FIFTH FIVE-YEAR REVIEW REPORT FOR ENTERPRISE AVENUE SUPERFUND SITE PHILADELPHIA COUNTY, PENNSYLVANIA



FEBRUARY 2017

Prepared by

U.S. Environmental Protection Agency Region 3 Philadelphia, Pennsylvania

Karen Melvin, Director **Hazardous Site Cleanup Division** U.S. EPA, Region 3

FEB 24 2017

Date

Table of Contents

LIST OF ABBREVIATIONS & ACRONYMS	95
I. INTRODUCTION	
Site Background	
FIVE-YEAR REVIEW SUMMARY FORM	
II. RESPONSE ACTION SUMMARY	
Basis for Response Actions and Actions Taken	
Status of Implementation	
Additional Response Actions	
Institutional Control Review	
Operation & Maintenance	
III. PROGRESS SINCE THE LAST REVIEW	
IV. FIVE-YEAR REVIEW PROCESS	
Community Notification, Involvement & Site Interviews	
Data Review	
Site Inspection	
V. TECHNICAL ASSESSMENT	
QUESTION A: Is the remedy functioning as intended by the decision documents?	10
QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels and remedial action	on objectives
used at the time of the remedy selection still valid?	10
QUESTION C: Has any other information come to light that could call into question the protection	ctiveness of the
remedy?	1
VI. ISSUES/RECOMMENDATIONS	1
VII. PROTECTIVENESS STATEMENT	17
VIII. NEXT REVIEW	1
APPENDIX A – REFERENCE LIST	
APPENDIX B - SITE CHRONOLOGY	B-
APPENDIX C - SITE MAP	
APPENDIX D - PRESS NOTICE	D-
APPENDIX E - SITE INSPECTION CHECKLIST	
APPENDIX F - SITE INSPECTION PHOTOS	F-
APPENDIX G - INTERVIEW FORMS	G-
APPENDIX H - GROUNDWATER DATA FROM NON-CERCLA CLEANUP ACTION	H-

I. INTRODUCTION

The purpose of a five-year review (FYR) is to evaluate the implementation and performance of a remedy to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The U.S. Environmental Protection Agency (EPA) is preparing this FYR pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 121, consistent with the National Contingency Plan (NCP) (40 Code of Federal Regulations (CFR) Section 300.430(f)(4)(ii)), and considering EPA policy.

This is the fifth FYR for the Enterprise Avenue Superfund site (the Site). The triggering action for this policy review is the completion date of the previous FYR. The FYR has been prepared because hazardous substances, pollutants or contaminants remain at the Site above levels that allow for unlimited use and unrestricted exposure. This FYR evaluates the protectiveness of the Selected Remedy addressing the stock piled soil as described in the 1984 Record of Decision (ROD).

The FYR was led by representatives from the EPA Region 3, with assistance provided by an EPA contractor, the Pennsylvania Department of Environmental Protection (PADEP), and Philadelphia Division of Aviation (DOA) staff. The review began on April 14, 2016.

Site Background

The Site consists of approximately 57 acres of land at the Philadelphia International Airport in Philadelphia, Pennsylvania that was utilized by the City of Philadelphia (the City) for disposal of incinerator residue and fly ash between 1971 and 1976 (see Figure 1 and Appendix C). Also during that time period, drums containing industrial and chemical hazardous wastes were illegally disposed of at the Site by other unknown parties. Runway 8-26 was later constructed on top of a portion of the Site. This runway is primarily used for commuter flights.

LIST OF ABBREVIATIONS & ACRONYMS

AOC Administrative Order by Consent

ARAR Applicable or Relevant and Appropriate Requirement

CERCLA Comprehensive Environmental Response, Compensation and Liability Act

CFR Code of Federal Regulations

CIC Community Involvement Coordinator DOA Philadelphia Division of Aviation

EPA United States Environmental Protection Agency
FAA United States Federal Aviation Administration

FONSI Finding of No Significant Impact

FYR Five-Year Review
IC Institutional Control
KIA Key Indicator Analysis

MCL Maximum Contaminant Level
MNA Monitored Natural Attenuation
NCP National Contingency Plan

NEPA National Environmental Policy Act

NPL National Priorities List O&M Operation and Maintenance

OU Operable Unit

PADEP Pennsylvania Department of Environmental Protection

PCE Tetrachloroethylene

PRP Potentially Responsible Party
PWD Philadelphia Water Department
RAO Remedial Action Objective


RCRA Resource Conservation and Recovery Act

ROD Record of Decision

RPM Remedial Project Manager SSA Sole Source Aquifer TCE Trichloroethylene

VOC Volatile Organic Compound

Figure 1: Site Map



Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site.

FIVE-YEAR REVIEW SUMMARY FORM

Site Name: Enterpr	ise Avenue			
EPA ID: PAD98	30552913			
Region: 3	State: PA	City/County: Philadelphia/Philadelphia		
NPL Status: Deleted				
Multiple OUs? No	Has the Yes	e site achieved construction completion?		
Lead agency: EPA				
Author name: Andrew	v Haneiko, with addit	ional support provided by Skeo		
Author affiliation: EPA	A Region 3			
Review period: 4/14/20	16 – 3/26/2017			
Date of site inspection:	7/20/2016			
Type of review: Policy				
Review number: 5				
Triggering action date: 3/26/2012				
Due date (five years after triggering action date): 3/26/2017				

II. RESPONSE ACTION SUMMARY

Basis for Response Actions and Actions Taken

In response to the discovery of the illegal disposal of drums, the City performed exploratory excavations in January 1979 and identified the presence of approximately 1,700 drums. The majority of these drums were broken and fragmented. Based on the results of soil and waste sample analytical data, the drums contained paint sludges, solvents, oils, resins, metal finishing waste, and solid inorganic wastes. The City performed initial response actions in 1982, including excavation of all contaminated soil and buried drums; offsite disposal of all drummed waste material; offsite disposal of about 226,000 gallons of contaminated water; and offsite disposal of 21,350 tons of contaminated soils. An additional 17,800 tons of contaminated soils were staged on the Site in two stockpiles following the initial response action by the City. Appendix B provides a chronology of activities at the Site.

The onsite soil stockpiles were contaminated with organic compounds. The larger pile, consisting of 11,700 tons, was contaminated primarily with trichloroethylene (TCE), tetrachloroethylene (PCE) and 1,1,1-trichloroethane. The smaller pile, consisting of 6,100 tons, was contaminated primarily with toluene, benzene and ethylbenzene. EPA identified a potential unacceptable risk to human health via direct contact (dermal contact, ingestion or inhalation) for the contaminated soil stockpiles. In addition, EPA identified a potential unacceptable risk to the environment if contaminants from the soil stockpiles leached into the groundwater.

EPA listed the Site on the National Priorities List (NPL) on September 8, 1983. EPA signed a ROD on May 10, 1984 to document the Selected Remedy and address the contaminated soil stockpiles. The Selected Remedy in the 1984 ROD consisted of the following components:

- · Resampling and analysis of the stockpiled soils in 100-cubic-yard lots for key indicator parameters;
- Onsite containment of soils that do not exceed established parameter limits;
- Offsite disposal of soils that exceed established parameter limits at a Resource Conservation and Recovery Act (RCRA) approved facility;
- Grading, completion of a clay cap and cover, and vegetation of the Site.

The 1984 ROD generally described the objective of the remedy but did not provide specific remedial action objectives (RAOs). The general objective of the 1984 ROD was to "provide adequate protection of public health, welfare, and the environment." The 1984 ROD stated that the Selected Remedy "effectively mitigates and minimizes damage to and provides adequate protection of public health, welfare, and the environment."

The 1984 ROD established a key indicator analysis (KIA) to determine whether each 100-cubic-yard soil lot could remain onsite (see Table 1). Limits for organics were based on 75 times the maximum background level. The limits for metals were based on the Extraction Procedure Toxicity Test. If any of the limits in Table 1 were exceeded in a 100-cubic-yard soil lot, the lot was sent offsite for disposal at an approved RCRA landfill. If the limits were not exceeded, the soil lot remained onsite.

Table 1: Soil Cleanup Goals

Soil Contaminant	ROD Cleanup Goal (milligrams per kilogram)
Total organic halogens	25
Benzene	12
Toluene	15
Ethylbenzene	15
Arsenic	5
Barium	100
Cadmium	1
Chromium	5
Lead	5
Mercury	0.2
Selenium	I
Silver	5

The 1984 ROD stated that contamination at the Site was limited to the soil stockpiles. Therefore, the Selected Remedy addressed the stockpiled soils only. Results of groundwater and surface water sampling at that time did not indicate an impact to these media from the Site and no response actions were selected for surface water or groundwater. The 1984 ROD stated that a low-permeability layer consisting of silty clay, found under the Site, generally restricts contaminant movement into the deep water-bearing zone. However, the 1984 ROD recognized the potential for contaminants to leach into the deep water-bearing zone. The potential impact to that zone was expected to be mitigated by the Selected Remedy.

Status of Implementation

The City implemented the Selected Remedy from August 1984 through March 1985. In accordance with the 1984 ROD, the contaminated soils were sampled for key indicator parameters (see Table 1). Soils exceeding any key indicator parameter were sent offsite for disposal at an approved RCRA landfill. Soils not exceeding any key indicator parameters remained onsite. The portion of each soil stockpile that remained onsite was graded, covered with 9 to 12 inches of clay, covered with topsoil and seeded. The soil stockpiles that remained onsite and were capped are hereinafter referred to as the "capped area". The area where drums and other waste were disposed illegally is hereinafter referred to as the "former landfill". EPA deleted the Site from the NPL on March 7, 1986.

Additional Response Actions

Additional response actions were taken at the Site after its deletion from the NPL but were not components of the Selected Remedy. Therefore, the following response actions are not included in this FYR's protectiveness determination and are summarized below for informational purposes.

In 1986 and 1987, the City monitored the groundwater from nine wells along the perimeter of the former landfill as a requirement by the Pennsylvania Department of Environmental Resources (PADER, now the PADEP). Several volatile organic compounds (VOCs) were detected above Maximum Contaminant Levels (MCLs) at that time.

For a short period of time in the late 1980's, the Philadelphia Water Department (PWD) used the Site as a staging area for a sludge-to-compost project. PADER required the removal of the sludge in 1990 and the former landfill was subsequently regraded with an additional two to three feet of soil.

In 1994, the City received approval from the U.S. Federal Aviation Administration (FAA) for construction of a 5,000-foot-long commuter runway, Runway 8-26, part of which would be located over the capped area and former landfill. In order for the City to obtain federal funding for this project, EPA conducted an environmental review in accordance with the National Environmental Policy Act (NEPA). Additionally, because the project is located within the recharge zone boundaries of a designated Sole Source Aquifer (SSA) by the Safe Drinking Water Act (42 U.S.C. § 300h-2), EPA evaluated the groundwater impacts from this project.

As a result of the NEPA review, special conditions were established and EPA supported a Mitigated Finding of No Significant Impact (FONSI) in a letter dated September 16, 1994 to FAA, primarily to prevent potential impacts to the SSA. The special conditions in the Mitigated FONSI included provisions to: 1) dewater the former landfill, 2) cap the former landfill, and 3) develop a groundwater mitigation and monitoring plan.

The City dewatered the former landfill and installed a geosynthetic cap in September 1997. To dewater the former landfill, 150 extraction wells were installed and approximately seven million gallons of water were removed and discharged to the PWD Southwest Water Pollution Control Plant. During this period of time, the City installed a 30-foot high surcharge pile to accelerate the natural compaction of the soil and allow for the timely completion of Runway 8-26. The former landfill currently sits beneath a clay cap, a geosynthetic cap, approximately 30 feet of fill material and an airport runway. Groundwater monitoring was also required prior to, during, and after construction of the runway, from 1994 through 1999. Monitoring well locations are shown on Figure H-1 in Appendix H.

During the construction of the runway, the City identified two separate areas with elevated levels of benzene and VOCs adjacent to the former landfill. As a result, over 500 tons of soil were excavated from two separate areas and disposed offsite based on the Pennsylvania Land Recycling and Environmental Remediation Standards Act (PA Act 2) soil cleanup criteria for benzene of 800 µg/kg.

Additionally, groundwater contamination was identified during the above actions. Groundwater remediation and monitoring is currently being conducted in accordance with a June 5, 2002 Administrative Order on Consent for Removal Action (Docket Number III-2001-0007-DC) between the City and EPA. The City agreed to continue extraction and treatment of contaminated groundwater until the groundwater is restored to MCLs. At the City's


request, EPA modified the AOC in 2008 to allow the groundwater treatment system to be shut down for an evaluation of monitored natural attenuation (MNA) to address contaminated groundwater. The groundwater treatment system has remained shut down since September 2008 and the evaluation of MNA and alternative remedial technologies is currently ongoing. Groundwater monitoring data is included in Appendix H for reference purposes.

Institutional Control Review

The 1984 ROD did not require institutional controls (ICs) at the Site. However, restrictions are in place at the airport that help ensure the long-term protectiveness of the Selected Remedy. The first restriction is zoning. Currently, the Enterprise Avenue Site is zoned, "Least Restricted Industrial District" limiting the Site to industrial activities. (see The Philadelphia Code § 14-509(1)(a-u)) The prohibited uses include hotels, libraries, and public museums. (see The Philadelphia Code § 14-509(2)(a-d)) In 2012 the City re-zoned all of the Philadelphia International Airport including Runway 8-26 for "Airport Use" only. If there is a use change, Philadelphia City Council would have to approve an ordinance to re-zone the Philadelphia International Airport. The second restriction deals with funding. If the airport property is not used for airport purposes the federal funds provided from the Secretary of Transportation to the City would need to be returned to the federal government. (see 49 U.S.C. § 47107(c)(2)(B)(I) & (iii) and 49 U.S.C.§ 47107(d)). See Figure 2.

Considering that an excess of thirty feet of soil was placed onto the capped area and former landfill to accommodate adequate runway slope as well as the existing and reasonably expected future land use of the airport, EPA believes that no additional ICs are needed at the Site to ensure the long-term protectiveness of the Selected Remedy.

Figure 2: Institutional Control Map



Operation & Maintenance

The 1984 ROD stated that the City would assume full responsibility for operation and maintenance (O&M) of the remedy, including inspection of the Site and maintenance of the vegetated cover. As required by FAA regulations, the runway area over the capped area and former landfill is maintained by regular mowing as well as by filling and grading of surface holes made by wildlife. The portion of the capped area adjacent to and under Fort Mifflin Road is mowed as part of regular roadway maintenance. The northern edge of the capped area, which is on the wastewater treatment plant area, is maintained by the City; wastewater treatment plant employees visually monitor that area on a regular basis.

III. PROGRESS SINCE THE LAST REVIEW

This section includes the protectiveness determinations and statements from the previous FYR as well as the recommendations from the previous FYR and the current status of those recommendations.

Table 2: Protectiveness Determination from the 2012 FYR

Protectiveness Determination	Protectiveness Statement
Protective	The remedy is protective of human health and the environment. The remedial action specified in the 1984 Record of Decision was successfully implemented and has eliminated exposure to contaminated soils at the site.

There were no issues and recommendations identified in the previous FYR.

IV. FIVE-YEAR REVIEW PROCESS

Appendix A lists documents reviewed during this FYR.

Community Notification, Involvement & Site Interviews

A public notice was made available by placing an ad in the Delaware County Daily Times, January 20, 2017, stating that a FYR was underway and inviting the public to submit any comments to EPA. Appendix D provides a copy of the public notice. This Report will be made available at the Site's information repository, located at EPA Region 3, 1650 Arch Street, Philadelphia, PA 19103-2029, and online at www.epa.gov/superfund/search-superfund-five-year-reviews.

During the FYR process, interviews were conducted with the Philadelphia International Airport Planning and Environmental Services Manager and the PWD Wastewater Treatment Plant Manager to document any perceived problems or successes with the remedy that has been implemented to date. The results of these interviews are summarized below. Appendix G provides the interview forms.

- Philadelphia Airport's Planning and Environmental Services Manager is satisfied with the cleanup project. The Airport continues to sample monitoring wells in accordance with the modified AOC. The Airport has regular communication with EPA.
- The Wastewater Treatment Plants Manager and Assistant Manager are aware of the Site. The PWD
 erected a guardrail and fence 3-4 years ago to prevent trespassing and illegal dumping.

Data Review

There is no monitoring data to review with respect to the Selected Remedy. The City continues to monitor groundwater pursuant to the modified AOC, which is not part of the Selected Remedy and therefore is not subject to this policy FYR. Appendix H provides groundwater monitoring data for 1995 through 2016 for informational purposes.

Site Inspection

The site inspection took place on July 20, 2016. In attendance were William Geiger, EPA's RPM for the Site at the time; Ellen Davies, PADEP Project Manager; Raymond Scheinfeld, Philadelphia International Airport's Planning and Environmental Services Manager; Melissa Shinbein, Philadelphia International Airport Environmental Engineer; and Amanda Goyne and Hagai Nassau, Skeo (EPA's FYR contractor). The purpose of the inspection was to assess the protectiveness of the remedy. For a full list of site inspection activities, see the Site Inspection Checklist in Appendix E. Site photographs are provided in Appendix F.

Site inspection participants met at the Philadelphia International Airport Authority office at 1 International Plaza, Suite 100. Participants discussed Site history and current Site status. Participants then traveled by car to restricted areas of the airport and viewed the capped area and former landfill area, including Runway 8-26, surrounding infield areas and adjacent wetlands. The capped area and former landfill area were in good condition. A portion of the capped area extends outside the airport property, under Fort Mifflin Road and onto the City's Southwest Water Pollution Control Plant. Participants accessed the Southwest Water Pollution Control Plant area to view the capped area and several groundwater monitoring wells.

The airport is highly secured with a fence and other security measures. The Southwest Water Pollution Control Plant area is also secured with a fence. Illegal dumping took place at the wastewater treatment plant area prior to erection of the fence. The Philadelphia International Airport's Planning and Environmental Services Manager, stated that the wastewater treatment plant's fence posts do not penetrate the cap because the cap is about 8-10 feet below the fence.

V. TECHNICAL ASSESSMENT

QUESTION A: Is the remedy functioning as intended by the decision documents?

The Selected Remedy in the 1984 ROD was offsite disposal of soils that exceeded defined parameters, and onsite containment and capping of remaining soils to prevent leaching of any residual contamination into groundwater. A geosynthetic cap was later installed as part of the construction of Runway 8-26. The capped area installed as a component of the Selected Remedy and the geosynthetic cap installed during runway construction prevent contact with contaminated soil and reduce leaching of residual contamination from the former landfill.

Fences and security measures at the airport and wastewater treatment plant area also prevent exposure to soil contamination and protect the cap.

Philadelphia International Airport maintains the runways and grassy areas to a high standard, in keeping with FAA requirements.

Considering the existing and reasonably expected future land use of the airport, EPA believes the ICs are adequate to ensure the long-term protectiveness of the Selected Remedy.

The City continues to monitor groundwater pursuant to the modified AOC, which was not part of the Selected Remedy and is therefore not subject to this policy FYR. The Site is within the recharge boundary zone of the Coastal Plain SSA in New Jersey, which is classified as a source of drinking water for central and southern New Jersey. There are no drinking water intakes downstream from any potential discharge from the Site, according to EPA's recent discussion with the City. In addition, no drinking water wells are impacted by the groundwater contamination.

QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels and remedial action objectives used at the time of the remedy selection still valid?

All contaminated soil at the Site was either disposed of offsite or capped in place. In addition, the geosynthetic cap, the 30 feet of additional cover material, the fences and airport security restrict access to most of the capped area. The cleanup levels established by the KIA in the 1984 ROD differ from current EPA practice of performing a baseline risk assessment. However, changes in toxicity data and cleanup levels do not affect the remedy's protectiveness.

No other exposure assumptions have changed since the 1984 ROD. The capped area is still used as airport and wastewater treatment plant property. The airport's Capacity Enhancement Plan includes plans to extend Runway 8-26 about 2,000 feet to the east to accommodate larger aircraft; however, there are no near-term plans to

implement this extension. EPA will stay in communication with the airport's environmental staff to ensure that any construction activity does not negatively impact the Selected Remedy.

Although no RAOs were identified in the 1984 ROD, the general objective to "provide adequate protection of public health, welfare, and the environment," is still valid and has been achieved by the Selected Remedy.

Groundwater contamination has been identified at the Site. Exposure to contaminated groundwater is a new potential exposure route. However, there are no drinking water intakes downstream from any potential discharge from the Site, according to EPA's recent discussion with the City. In addition, no drinking water wells are impacted by the groundwater contamination. The City continues to monitor groundwater pursuant to the modified AOC and additional response actions to return the groundwater to beneficial reuse are currently being evaluated.

QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy?

No other information has come to light that calls into question the protectiveness of the Selected Remedy.

VI. ISSUES/RECOMMENDATIONS

OU(s) without Issues/Recommendations Identified in the FYR:
Sitewide

This FYR did not identify any issues and recommendations.

VII. PROTECTIVENESS STATEMENT

Protectiveness Determination:

Protective

Protectiveness Statement:

The Selected Remedy is protective of human health and the environment. All contaminated soil at the Site was either disposed of offsite or capped. The capped area installed as a component of the Selected Remedy and the geosynthetic cap installed during runway construction prevent direct contact with contaminated soil and reduce leaching of residual contamination from the former landfill. Fences and security measures at the airport and wastewater treatment plant area also prevent exposure to soil contamination and protect the capped area and former landfill.

VIII. NEXT REVIEW

The next FYR Report for the Enterprise Avenue Superfund site will be conducted five years from the completion date of this review.

APPENDIX A - REFERENCE LIST

EPA. May 10, 1984. Record of Decision: Enterprise Avenue Site. https://semspub.epa.gov/work/03/449729.pdf.

EPA. December 31, 1985. Notice of Intent to Delete Sites from the National Priorities List. https://semspub.epa.gov/work/03/900053.pdf.

EPA. March 26, 2012. Fourth Five-Year Review Report for Enterprise Avenue Landfill Superfund Site. https://semspub.epa.gov/work/03/2136782.pdf.

APPENDIX B – SITE CHRONOLOGY

Table B-1: Site Chronology

Event	Date
Based on reports of illegal drum dumping, City conducted investigation	January 1979
City conducted study of landfill	1979 – 1982
City conducted initial remedial work	March – November 1982
EPA listed Site on Superfund program's National Priorities List (NPL)	September 8, 1983
EPA completed feasibility study for stockpiled soils	February 1984
EPA issued Site's Record of Decision (ROD)	May 10, 1984
City's contractor mobilized to start construction	July 23, 1984
City completed all on-site work, including final grading and seeding	March 22, 1985
EPA deleted Site from NPL	March 7, 1986
EPA recommended mitigated Finding of No Significant Impact for the	September 16, 1994
construction of a new commuter runway, Runway 8-26, partially located	
over the top of the landfill	
Airport started Runway 8-26 construction activities	September 1995
City excavated contaminated soil	September 26 – October 4, 1996
City activated groundwater pump-and-treat system	April 1997
EPA issued Site's first FYR Report	July 14, 1997
Airport completed installation of landfill geosynthetic cap as part of a	September 1997
National Environmental Policy Act review	September 1997
Airport completed Runway 8-26 construction	December 3,1999
EPA issued AOC for groundwater remediation	June 5, 2002
EPA signed Site's second FYR Report	September 18, 2002
EPA signed Site's third FYR Report	March 29, 2007
EPA modified 2002 AOC to include evaluation of monitored natural	September 12, 2008
attenuation for groundwater remediation	September 12, 2008
EPA signed Site's fourth FYR Report	March 26, 2012

APPENDIX C - SITE MAP




Figure C-1: Site Vicinity Map

Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site.

EPA REVIEWS CLEANUPEnterprise Ave Superfund Site

The U.S. Environmental Protection Agency (EPA) is conducting a Five-Year Review of the Enterprise Avenue Superfund Site located in southwest Philadelphia. EPA inspects sites regularly to ensure that cleanups conducted remain fully protective of public health and the environment. This site's cleanup construction was completed in 1997, with several Five-Year Reviews following. The site was removed from the National Priorities List of the nation's most hazardous waste sites in 1986. EPA's most recent Five-Year Review in 2012 determined that the remedy continues to be protective in the long-term. Results of the current Five-Year Review will be available to the public by April 2017.

To access results of the review (starting April 2017):

http://epa.gov/5yr

To learn detailed site and contact information:

http://go.usa.gov/x9YN7

To ask questions or provide site-related information:

Contact: Andrew Haneiko Phone: 215-814-3162

Email: haneiko.andrew@epa.gov

Protecting human health and the environment

APPENDIX E - SITE INSPECTION CHECKLIST

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST				
I. SITE INI	FORMATION			
Site Name: Enterprise Avenue Date of Inspection: 07/20/2016				
Location and Region: Philadelphia PA, Region 3	EPA ID: PAD980552913			
Agency, Office or Company Leading the Five-Year Review: EPA Region 3	Weather/Temperature: clear, abou	t 75°F		
Remedy Includes: (Check all that apply) Landfill cover/containment Access controls Institutional controls Groundwater pump and treatment Surface water collection and treatment Other:	☐ Monitored natural attenuation ☐ Groundwater containment ☐ Vertical barrier walls			
Attachments:	☐ Site map attached			
II. INTERVIEWS	(check all that apply)			
1. O&M Site Manager Raymond Scheinfeld Name Airport Planning & Environmental Date Interviewed at site at office by phone Phone:				
Problems, suggestions Report attached: see Appendix G				
2. O&M Staff Name Title Interviewed at site at office by phone Problems/suggestions Report attached: Problems/suggestions Report attached:				

3.	Local Regulatory Authorities and Response Agencies (i.e., state and tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices). Fill in all that apply.				
	Agency Contact Name Problems/suggestions Re	Title eport attached:	Date	Phone No.	
	AgencyName Problems/suggestions Re	Title eport attached:	Date	Phone No.	
	Agency Contact Name Problems/suggestions Re	Title eport attached:	Date	Phone No.	
	Agency Contact Name Problems/suggestions Re	Title eport attached:	Date	Phone No.	
	Agency Contact Name Problems/suggestions Re	Title port attached:		Phone No.	
4.	Other Interviews (optional) Report attached: see Appendix G				
Mary El	len Senss, Wastewater Treatr	nent Manager – Opera	tions; Mohammad Ibrahi	im, Assistant Plan	nt Manager
	III. ON-SITE DOCU	MENTS AND RECO	RDS VERIFIED (chec	k all that apply)	
1.	O&M Documents				
	O&M manual	Readily available	☐ Up to date	⊠ N	J/A
	☐ As-built drawings	Readily available	☐ Up to date	\boxtimes N	I/A
	☐ Maintenance logs	Readily available	☐ Up to date	⊠ N	J/A
	Remarks:				
2.	Site-Specific Health and S	Safety Plan	Readily available	☐ Up to date	⊠ N/A
	Contingency plan/emerg	gency response plan	Readily available	Up to date	⊠ N/A
	Remarks:				
3.	O&M and OSHA Trainin	g Records	Readily available	Up to date	⊠ N/A
	Remarks:				

4.	Permits and Service Agree	ments			
	☐ Air discharge permit		Readily available	Up to date	N/A
	☐ Effluent discharge		Readily available	Up to date	N/A
	☐ Waste disposal, POTW		Readily available	Up to date	N/A
	Other permits:		Readily available	Up to date	N/A
	Remarks:				
5.	Gas Generation Records		Readily available	Up to date	⊠ N/A
	Remarks:				
6.	Settlement Monument Reco	ords	Readily available	Up to date	⊠ N/A
	Remarks:				
7.	Groundwater Monitoring F		Readily available	Up to date	□ N/A
	Remarks:				
8.	Leachate Extraction Record		Readily available	Up to date	⊠ N/A
	Remarks:				
9.	Discharge Compliance Reco				
	Air	Readily available	☐ Up to date	\boxtimes N	I/A
	☐ Water (effluent)	Readily available	☐ Up to date ☐ N/A		I/A
	Remarks:				
10.	Daily Access/Security Logs		Readily available	☐ Up to date	□ N/A
	Remarks: Most of capped are	a is located within hi	ghly secured airport.		
		IV. O&M (COSTS		
1.	O&M Organization				
	☐ State in-house		Contractor for state		
			Contractor for PRP		
	Federal facility in-house		Contractor for Federal	facility	

2.	O&M Cost Reco	rds			
	Readily available		Up to date		
	□ Funding mecha	inism/agreement in place	∪navailable		
	Original O&M cos	t estimate: Brea	kdown attached		
		Total annual cost by y	ear for review perio	od if available	
	From:	To:	:	☐ Breakdown attached	
	Date	Date	Total cost		
	From:	То:	<u> </u>	☐ Breakdown attached	
	Date	Date	Total cost		
	From:	To:	/// 1000	☐ Breakdown attached	
	Date	Date	Total cost		
	From:	To:	W	☐ Breakdown attached	
	Date	Date	Total cost		
	From:	То:		☐ Breakdown attached	
	Date	Date	Total cost		
3.	Unanticipated or U	Jnusually High O&M Cos	ts during Review	Period	
	Describe costs and a	reasons:			
	V. ACCES	S AND INSTITUTIONAL	L CONTROLS	☑ Applicable ☐ N/A	
A. I	A. Fencing				
1.	Fencing Damaged ☐ Location shown on site map ☐ Gates secured ☐ N/A				
	Remarks: Airport is fenced and highly secured. Wastewater treatment plant is fenced.				
В. С	Other Access Restrictio	ns			
1.	Signs and Other Se	ecurity Measures	Location	shown on site map N/A	
	Remarks: "No Trespassing" signs on fences at airport and wastewater treatment plant.				

Implementation and Enforcement Site conditions imply ICs not properly implemented Site conditions imply ICs not being fully enforced Type of monitoring (e.g., self-reporting, drive by): Frequency: Responsible party/agency:	☐ Yes ☐ Yes	No □ N/A No □ N/A		
Site conditions imply ICs not being fully enforced Type of monitoring (e.g., self-reporting, drive by): Frequency:				
Type of monitoring (e.g., self-reporting, drive by): Frequency:	Yes	⊠ No □ N/A		
Frequency:				
Deconcible party/agangur				
Service Continue of Continue o				
Contact	-	-		
Name Title	Date	Phone no.		
Reporting is up to date	☐ Yes	□ No □N/A		
Reports are verified by the lead agency	☐ Yes	□ No □ N/A		
Specific requirements in deed or decision documents have be	een met Yes	□ No □ N/A		
Violations have been reported	☐ Yes	☐ No N/A		
Other problems or suggestions: Report attached				
2. Adequacy	Cs are inadequate	⊠ N/A		
D. General				
 Vandalism/Trespassing	**			
2. Land Use Changes On Site N/A				
Remarks: Airport may extend runway 8-26 at some point. No changes anticipated at wastewater treatment plant area.				
3. Land Use Changes Off Site				
VI. GENERAL SITE COND	ITIONS			
A. Roads Applicable N/A				
Roads Damaged				
B. Other Site Conditions				
Remarks:				
VII. LANDFILL COVERS 🖂 A	Applicable N/A			
A. Landfill Surface				
3.00 _ 0.095 312 milesh 100 Suprassocia k	an 🕅 Settlen	nent not evident		
Arial extent:	Depth:			
Remarks:	Бериі			
Remarks: B. Other Site Conditions Remarks:	Applicable N/A	nent not evident		

2.	Cracks	Location shown on site map	☐ Cracking not evident
	Lengths:	Widths:	Depths:
	Remarks:		
3.	Erosion	Location shown on site map	□ Erosion not evident
	Arial extent:		Depth:
	Remarks:		
4.	Holes	Location shown on site map	
	Arial extent:		Depth:
	Remarks:		
5.	Vegetative Cover	⊠ Grass	Cover properly established
	No signs of stress	☐ Trees/shrubs (indicate size and loc	ations on a diagram)
	Remarks:		
6.	Alternative Cover (e.g., ar		⊠ N/A
	Remarks:		
7.	Bulges	Location shown on site map	Bulges not evident
	Arial extent:		Height:
	Remarks:		
8.	Wet Areas/Water Damage	Wet areas/water dama;	ge not evident
	☐ Wet areas	Location shown on site	e map Arial extent:
	Ponding	Location shown on site	e map Arial extent:
	Seeps	Location shown on site	e map Arial extent:
	☐ Soft subgrade	Location shown on site	e map Arial extent:
	Remarks:		
9.	Slope Instability	Slides	Location shown on site map
	No evidence of slope ins ■ No evidence of slope ins No ev	tability	
	Arial extent:		
	Remarks:		
B. Bene	ches	ble N/A	
(Horizontally constructed mou order to slow down the velocit	nds of earth placed across a steep landfi y of surface runoff and intercept and con	Il side slope to interrupt the slope in newy the runoff to a lined channel.)
1.	Flows Bypass Bench	Location shown on site map	N/A or okay
	Remarks:		
2.	Bench Breached	Location shown on site map [N/A or okay
	Remarks:	10 10	
3.	Bench Overtopped	Location shown on site map [☐ N/A or okay
	Remarks:		

C. Le	tdown Channels	Applicable 🔲	N/A		
(Channel lined with erosion control mats, riprap, grout bags or gabions that descend down the steep side slope of the cover and will allow the runoff water collected by the benches to move off of the landfill cover without creating erosion gullies.)					
1.	Settlement (Low spots)	Location shows	n on site map	☐ No	evidence of settlement
	Arial extent:			Depth:	
	Remarks:				
2.	Material Degradation	Location shows	n on site map	□ No	evidence of degradation
	Material type:			Arial e	xtent:
	Remarks:				
3.	Erosion	Location shows	n on site map	☐ No	evidence of erosion
	Arial extent:			Depth:	
	Remarks:				
4.	Undercutting	☐ Location shown	on site map	☐ No	evidence of undercutting
	Arial extent:			Depth:	
	Remarks:				
5.	Obstructions	Type:		☐ No	obstructions
	Location shown on site map Arial extent:				
	Size:				
	Remarks:				
6.	Excessive Vegetative Gro	owth Ty	ype:		
	☐ No evidence of excessive growth				
	☐ Vegetation in channels	does not obstruct flov	V		
	Location shown on site	map A	rial extent:		
	Remarks:				
D. Co	ver Penetrations [Applicable 🛛 N	N/A		
1.	Gas Vents	☐ Active		Pass	ive
	Properly secured/locked	d Functioning	☐ Routinely sa	ampled	Good condition
	☐ Evidence of leakage at	penetration	☐ Needs main	tenance	□ N/A
	Remarks:				
2.	Gas Monitoring Probes				
	☐ Properly secured/locked	H Functioning	☐ Routinely sa	ampled	Good condition
	☐ Evidence of leakage at	penetration	☐ Needs main	tenance	□ N/A
	Remarks:				

3.	Monitoring Wells (within su	rface area of landfill)	
	Properly secured/locked	☐ Functioning	☐ Routinely sampled	Good condition
	Evidence of leakage at pe	enetration	☐ Needs maintenance	□ N/A
	Remarks:			
4.	Extraction Wells Leachate			
	Properly secured/locked	☐ Functioning	☐ Routinely sampled	Good condition
	☐ Evidence of leakage at pe	enetration	☐ Needs maintenance	□ N/A
	Remarks:			
5.	Settlement Monuments	Located	☐ Routinely surveyed	□ N/A
	Remarks:			
E. Ga	as Collection and Treatment	☐ Applicable	N/A	
1.	Gas Treatment Facilities			
	Flaring	☐ Thermal destru	ction	Collection for reuse
	Good condition	☐ Needs maintena	ance	
<u> </u>	Remarks:			
2.	Gas Collection Wells, Manif	folds and Piping		
	Good condition	☐ Needs maintena	ance	
	Remarks:			
3.	Gas Monitoring Facilities (e.	.g., gas monitoring o	f adjacent homes or buildir	ıgs)
	☐ Good condition	☐ Needs maintena	ance N/A	
	Remarks:			
F. Co	over Drainage Layer	☐ Applicable	⊠ N/A	
1.	Outlet Pipes Inspected	☐ Functioning	□ N/A	
	Remarks:			
2.	Outlet Rock Inspected	☐ Functioning	□ N/A	
	Remarks:			
G. De	etention/Sedimentation Ponds			
1.	Siltation Area exte	ent: D	Depth:	□ N/A
	Siltation not evident			
	Remarks:			
2.	Erosion Area exte	ent: D	Depth:	
	Erosion not evident			
	Remarks:			
3.	Outlet Works	oning		□ N/A
	Remarks:			~×.

4.	Dam 🔲 I	Functioning	□ N/A
	Remarks:		
н. ғ	Retaining Walls	☐ Applicable ☐ N/A	
1.	Deformations	Location shown on site map	Deformation not evident
	Horizontal displacement:	Vertical disp	placement:
	Rotational displacement: _		
	Remarks:		
2.	Degradation	Location shown on site map	Degradation not evident
	Remarks:		
I. Pe	erimeter Ditches/Off-Site Di	scharge Applicable	⊠ N/A
1.	Siltation	Location shown on site map	Siltation not evident
	Area extent:		Depth:
	Remarks:		
2.	Vegetative Growth	Location shown on site map	□ N/A
	☐ Vegetation does not im	pede flow	
	Area extent:		Type:
	Remarks:		
3.	Erosion	Location shown on site map	Erosion not evident
	Area extent:		Depth:
	Remarks:		
4.	Discharge Structure	☐ Functioning	□ N/A
	Remarks:		
VIII	VERTICAL BARRIER W	VALLS Applicable	⊠ N/A
1.	Settlement	Location shown on site map	Settlement not evident
	Area extent:		Depth:
	Remarks:		
2.	Performance Monitoring	Type of monitoring:	
	Performance not monit	ored	
	Frequency:		☐ Evidence of breaching
	Head differential:		
	Remarks:		
IX.	GROUNDWATER/SURFA	CE WATER REMEDIES	icable 🛛 N/A
A. (Groundwater Extraction We	ells, Pumps and Pipelines	Applicable N/A
1.	Pumps, Wellhead Plumb	ing and Electrical	
	Good condition	All required wells properly operating	☐ Needs maintenance ☐ N/A
	Remarks:		

2.	Extraction System Pi	pelines, Valves, Valve Bo	oxes and Other Appurtena	ances
	Good condition	☐ Needs maintenance		
	Remarks:			
3.	Spare Parts and Equ	ipment		
	Readily available	Good condition	Requires upgrade	☐ Needs to be provided
	Remarks:			
B. Su	rface Water Collection	Structures, Pumps and	Pipelines	ble N/A
1.	Collection Structures	s, Pumps and Electrical		
	Good condition	☐ Needs maintenance		
	Remarks:			
2.	Surface Water Collec	ction System Pipelines, V	alves, Valve Boxes and O	ther Appurtenances
	Good condition	☐ Needs maintenance		
	Remarks:			
3.	Spare Parts and Equ	ipment		
	Readily available	Good condition	Requires upgrade	☐ Needs to be provided
	Remarks:			
C. Tr	reatment System] N/A	
C. Tr	reatment System		TX	
	reatment System	Applicable)	oremediation
	reatment System Treatment Train (che	Applicable) aration 🔲 Bi	oremediation
	Treatment Train (che	Applicable ceck components that apply Oil/water sep) aration 🔲 Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters:	Applicable ceck components that apply Oil/water sep) aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters:	Applicable ceck components that apply Oil/water sep Carbon adsor) aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che	Applicable ceck components that apply Oil/water sep Carbon adsor	aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others:	Applicable cck components that apply Oil/water sep Carbon adsor	aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Good condition Sampling ports pro	Applicable cck components that apply Oil/water sep Carbon adsor lation agent, flocculent): Needs mainte	enance	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Good condition Sampling ports pro	Applicable cck components that apply Oil/water sep Carbon adsor ation agent, flocculent): Needs mainted perly marked and function ance log displayed and up	enance	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others: Good condition Sampling ports pro Sampling/maintena Equipment properl	Applicable cck components that apply Oil/water sep Carbon adsor ation agent, flocculent): Needs mainted perly marked and function ance log displayed and up	aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others: Good condition Sampling ports pro Sampling/maintena Equipment properl Quantity of ground Quantity of surface	Applicable ck components that apply Oil/water sep Carbon adsor ation agent, flocculent): Needs mainted perly marked and function ance log displayed and up y identified water treated annually: water treated annually:	aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others: Good condition Sampling ports pro Sampling/maintena Equipment properl Quantity of ground Quantity of surface	Applicable ck components that apply Oil/water sep Carbon adsor ation agent, flocculent): Needs mainted perly marked and function ance log displayed and up y identified water treated annually: water treated annually:	aration Bi	oremediation
	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others: Good condition Sampling ports pro Sampling/maintena Equipment properl Quantity of ground Quantity of surface Remarks:	Applicable ck components that apply Oil/water sep Carbon adsor lation agent, flocculent): Needs mainted operly marked and function ance log displayed and up y identified lwater treated annually:	aration Bi	oremediation
1.	Treatment Train (che Metals removal Air stripping Filters: Additive (e.g., che Others: Good condition Sampling ports pro Sampling/maintena Equipment properl Quantity of ground Quantity of surface Remarks:	Applicable ck components that apply Oil/water sep Carbon adsor ation agent, flocculent): Needs mainted perly marked and function ance log displayed and up y identified water treated annually: water treated annually:	aration Bi	oremediation

3.	Tanks, Vaul	lts, Storage Vessel	s		
	□ N/A	Good condition	Proper	secondary containment	☐ Needs maintenance
	Remarks:				
4.		tructure and App			
	□ N/A	☐ Goo		☐ Needs maintenance	
	Remarks:				
5.	Treatment l	Building(s)			
	□ N/A	☐ Goo doorwa	od condition (esp. re ys)	oof and	☐ Needs repair
	☐ Chemica	ls and equipment p	roperly stored		
	Remarks:				
6.		Wells (pump and			
	Properly	secured/locked	☐ Functioning	Routinely sampled	Good condition
	01-14		☐ Needs mainte		□ N/A
D. Me	onitoring Data				
1.	Monitoring	Data			
	☐ Is routine	ely submitted on tir	ne	☐ Is of acceptable qua	ality
2.	Monitoring	Data Suggests:			
	Groundw	vater plume is effec	ctively contained	Contaminant concer	ntrations are declining
E. M		ural Attenuation			
1.	Monitoring	Wells (natural atte			<u>~</u>
	☐ Properly	secured/locked	☐ Function	ing Routinely samp	oled Good condition
	☐ All requi	red wells located	☐ Needs m	aintenance	□ N/A
	Remarks:				

X. OTHER REMEDIES

If there are remedies applied at the site and not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is designed to accomplish (e.g., to contain contaminant plume, minimize infiltration and gas emissions).

The Selected Remedy in the 1984 ROD was offsite disposal of soils that exceeded defined parameters, and onsite containment and capping of remaining soils to prevent leaching of any residual contamination into groundwater. A geosynthetic cap was later installed as part of the construction of Runway 8-26. The capped area installed as a component of the Selected Remedy and the geosynthetic cap installed during runway construction prevent contact with contaminated soil and reduce leaching of residual contamination from the landfill. However, some leaching of contamination into groundwater may be occurring. The City continues to monitor groundwater pursuant to the modified AOC. No drinking water wells are impacted by the groundwater contamination.

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy. Philadelphia International Airport maintains the runway and grassy areas to a high standard, in keeping with FAA requirements.

C. Early Indicators of Potential Remedy Problems

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs that suggest that the protectiveness of the remedy may be compromised in the future.

None.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

None identified.

Site inspection attendees:

William Geiger, EPA RPM at time of site inspection

Ellen Davies, PADEP Project Manager

Raymond Scheinfeld, Philadelphia International Airport, Airport Planning and Environmental Services manager Melissa Shinbein, Philadelphia International Airport, Environmental Engineer

Amanda Govne, Skeo

Hagai Nassau, Skeo

APPENDIX F - SITE INSPECTION PHOTOS



Looking east from Runway 8-26 capped area



Looking west toward airport terminal from Runway 8-26 capped area



Vegetated runway infield capped area north of Runway 8-26



Vegetated runway infield capped area south of Runway 8-26




Runway 8-26



Inactive extraction well EW-1 exterior



Inactive extraction well EW-1 interior



Northern edge of capped area on wastewater treatment plant area and Fort Mifflin Road



Sign on fence surrounding airport area



Runway 8-26 viewed from airport control tower

APPENDIX G – INTERVIEW FORMS

	INTERVIEW DOCUM	MENTATION FORM	
	individual interviewed for tetailed summary of the interv		the attached
Raymond Scheinfeld Name	Airport Planning & Environmental Services Manager Title/Position	City of Philadelphia Organization	November 22, 2016 Date
Mary Ellen Senss Name	Wastewater Treatment Manager- Operations Title/Position	City of Philadelphia- Water Department Organization	November 22, 2016 Date
Mohammad Ibrahim Name	Assistant Plant Manager- Southwest Plant Title/Position	City of Philadelphia- Water Department Organization	November 22, 2016 Date
Name	Title/Position	Organization	Date
Name	Title/Position	Organization	Date
Name	Title/Position	Organization	Date

INTERVIEW RECORD EPA ID No.: PAD980552913 Site Name: Enterprise Avenue Date: Subject: Five Year Review Time: Outgoing Incoming Visit Other Telephone Type: Location of Visit: Philadelphia International Airport Plaza Bldg Contact Made By: Organization: US EPA Title: Community Involvement Name: Kimberly Scharl Coordinator Individual Contacted: Organization: City of Title: Airport Planning & Name: Raymond Scheinfeld Philadelphia **Environmental Services Manager** Street Address: Philadelphia International Airport Telephone No: 215-906-7604 City, State, Zip: Philadelphia, PA 19153 Fax No: 215-937-5576 E-Mail Address: Raymond.scheinfeld@phl.org

Summary of Conversation

- What is your overall impression of the project? (general sentiment)
 The project was well done and the clean-up effort was protective of human health and the environment.
- Have there been routine communications or activities (site visits, inspections, reporting, activities, etc.) conducted by your office regarding the site? If so, please give purpose and results.

Yes. Management is fully aware of what is going on at the site, although it is no longer mentioned in the press. There is regular communication with EPA. Wells were last tested in May/ June, 2016, and a report of the tests was submitted to EPA.

- Have there been any complaints, violations, or other incidents related to the site requiring a
 response by your office? If so, please give details of the events and results of responses.
 None noted.
- 4. Do you have any concerns related to the site? No concerns.
- 5. Do you feel the Record of Decision is still effective in protecting human health and the environment?

Yes.

	INTERVIE	W RECOR	D	
Site Name: Enterprise Avenue			EPA ID No.:	PAD980552913
Subject: Five Year Review			Time:	Date:
Type: Telephone <u>Vi</u> Location of Visit: City of Philad	<u>sit</u> Other lelphia Southwest Tre	atment Plant	Incoming	Outgoing
300	Contact	Made By:	234	
Name: Kimberly Scharl	Title: Communit	y Involvement	Organization	: US EPA
	Individual	Contacted:		
Name: Mary Ellen Senss/ Mohammad Ibrahim	Title: Wastewate Manager- Opera Plant Manager		Organization Philadelphia	: City of Water Department
Telephone No: 215-685-6258 Fax No: 215-685-6207 E-Mail Address: Maryellen.sens	ss@phila.gov	Street Address: City, State, Zip:		
	Summary Of	Conversation		

 Are you familiar with the Enterprise Avenue Superfund site (part of which is located on your property)?

Yes

- Are you aware of any concerns regarding the site or its operation and administration? Security could still be a concern. Employees of the southwest plan monitor the fence from time to time to ensure there are no trespassers.
- 3. Are you aware of any events, incidents, or activities at the site such as trespassing or emergency response?

None recently. We put a guardrail and fence up approximately 3 to 4 years ago to protect the area from trespassing and illegal dumping.

- 4. Do you have any comments, suggestions, or recommendations regarding the site's management or operation?
 - No. We met with police to see if there was anything else that could be done regarding security. It is a remote area, so there were limited options.
- Do you perform operation and maintenance of the portion of the site that is located on your property?No.
- 6. Our latest 5-year review shows the remedy now in place is working. Do you have an opinion as to anything we should currently be doing?

No, I can't think of anything that could be done that would affect their portion of the property.

APPENDIX H - GROUNDWATER DATA FROM NON-CERCLA CLEANUP ACTION

Figure H-1: Well Location Map




Table H-1: Selected Volatile Organic Compounds in Well LF-2, 1995 to 2016

1	-				-			-			-		-			D	ate Samp	ied				-10					_		-			_		-			_	-		-	-		
DEATILES (191)	595	6:95	7/95	A-93	515	11/95	811	11/96	3/97	6/97	5.97	12:97	398	6/58	551	12/95	199	11/99	5:00	11/00	5 01	11/01	4:02	12:02	9:03	3.04	5:04	305	10.05	4:06	10 04	508	6:09	11/05	£10	3/14	2.14	11/14	215	515	E/15 1	11.15	2:16
nyi Chloride	520	580	620	4000	660	1,300	1,430	3 600	1,500	1,100	640	1,400.	1,000	640.7	640	5503	390	360,7	MOUD	10	6300	230	229/D	5000	5800	econd	6600	4500	370	460	6500	1,750	7.420	1,390	2500	1 200	1 200	1702	170	40	U	u	U
DCE	31	1,0000	1 0000	5000	500U	36	6	514	160	147	703	84	1,0000	1,0000	80	0000	29.1	500U	15	100	75	11	9.5			_					-		10	6	4	2	ti	U	1	U	ti	U	U
DCE	13,000	13,000	12,000	10,000	17,000	9,000	7,100	14,000	32,000	6,400	15,000	13,000	14,000	11,000	9,200	6,600	9.200	6,000	5,1000	140	5,7000	2 0000	2,9000	4 4000	3,40204	2,00330	3 4070	3,905,0	1,600	3,700	3,1000	3,697	4.149	2,287	1885	u	U	u	U	U	U	U	U
DCE	650	850	850.6	760	\$40	1 600	560	3,300	3,000	1,400	1,500	1,100,0	1,100	4101	820	5602	200	460.7	310,0	10	450,0	240	1900	350.0	3100	36030	4000	3300	190	360	1300	675	640	522	770	440	940	779	800.0	970	760	5.50	850
lorobenzene	4,500	4,400	4,300	# 100	4,500	5,500	1,400	6,300	11,000	3,100	5,500	6,400	5,700	4 400	4.000	3,200	3,600	2,900	2,0000	55	2,7000	1,4000	1,5000	2,2000	2,6000	1,3000	2,8000	2,7000	3,300	2,700	50080	1,020	5,500	4 870	6820	1,500	6,600	7,600	1,300	9.900	7,100 1	700	\$ 100 F
DCE	140	180,0	200	1702	180.5	140		140	120	56	1103	1203	1004	89	71	170./	77.3					1.002.17				-	-				-		204	7.02	215	45	54	33	34	77	U	11	12
DCB	7,300	1 100	3,200	2,500	3,200	2,500		7,300	7,900	770	2 900	2,300	2,400	2,100	1,500	0000	1,500		-						-						-	-	109	106	100	110	330	31	42	27	U	16	23
2 DCB	1 500	2 300	2 300	1.700	2 100	1 500		1.600	2 000	570	1 700	1.700	1.700	1 400		5000								_									155	370	281	54	62	- 6		· ·	. U	u	· W

145 - 14ct Sampled - Net Analyzed

U - Not Detected

J - Estended Concentration D - Dilution Required

Table H-2: Selected Volatile Organic Compounds in Well LF-3, 1995 to 2016

								111											Date 54	ampled		17			100											0.5			W								
VOLATILES (pg/l	5/95	4:55	7/95	8	95	5/95	11/95	8/96	11/9	5 3/1	17 6	6/97	1/27	12/97	298	6/14	9:50	12/98	3/99	11/9	5:00	0 11	100	5/01 1	1/01	4/02	12/02	8:03	3/04	9/04	3/05	10/05	4/06	10/06	5/00	6/09	11/09	#/10	3/14	B/10	11/14	2/15	515	8115	11/15	2/1	6 5
/smyl Chlorode	500	34		10	740	690	470	. 5	. 10	w.	10.	100	200	690	350	160	140	23	0 13	10 1	10 17	100	900	3100	140	180	160	120	86	85	5.7	47	19	13	7	11		,		1	1	1	,	tu			,
,1 DCE	2	50	0 100	U	62U	500	500	56	15	w.	tou	100	2,1	500	29.	184	34	7	4 3	5.5	13	9.0	52	5.7		3,1								-	-	10	14				4	U		- 0	2		1
-2 DCE	1,100	.96	0 12	10	300	1,600	800	3	4	12	2,1	1,1	640	1,300	820	440	140	19	9 3	15	13	20 2	500	370	400	46	63	8.0	40	45	49	38	20	17		. 5	1	.16	1		4 3	U	U	U	U		0
Senzene	140	10	0 1	10	140	130	150	3	4	27	12	3,1	170	220	110	46.	214	7	J 10	a)	W	64	13	76		73	12	13	9	12	12	10	9	11	45	145	126	45	4	31	1 2	33	34	63	U	6	4
Chlorobensene	1,000	77	0 0	10	000	1,100	770		1	15	16	2.1	370	770	730	510	300	48	J 1	54	16	14	170	5200	440	27	40	1800	130	77	41	39	55	14080	.000	1,490	1,320	064	1 90	2 000	1,000	1,100	770	1.500	540	1 20	10
,3 DCB	38	33	4	14	373	437	339			7.5	24	100	10	15	14,	14	- 11		, ,	4.	1		-	-			1400	-		-		-				31	26		7	7	2 1	13	- 5	u			0
,4 DCB	640	56	0 2	0	680	740	540	-		22	21	4./	160	220	266	420	230	_ 5	4 5	57					-	E	257	-	_							. 24	24				7 1		12	V		1	5
1.2 DCB	380	34	0 3	roi .	360	400	290			11	11	2.4	97	160	220	250	140	3	4 1	35				-	- 1		- 1		-		-			1		351	234	93		1	d if	1 3		U		4	2

NS • Not Sampled

- Not Analyzed U - Not Detected

J = Estimated Concentration D = Dilution Required

Table II-3: Selected Volatile Organic Compounds in Well LF-4, 1995 to 2016

	_				_														Date for	empled .															_								,			16 2.16
VOLATILES (199)	1/95	6-91	7/95	0/93	5 9/	95 1	11/95	1/14	11/94	3/91	6.9	7 9	97 12	9.7	3/58	6/22	1/11	12:51	3/99	11/21	5.00	11/00	8.01	11:01	102	12.02	9103	3.04	3.04	3/05	10.05	4:04	10:04	5.08	6.01	11:01	1/10	2/16	0.1	11/16	2.11	5/15	8-15	1111	4	2.10
Veryl Chloride	190	400	420	45		AC.	363	150	10.0	524	1 11	1	26 2	20	76	(4)	101	82	1,2	151	120	104	12:1	10	170		-	-										1	10	10	12	1	v	10	1	4
1.1 DCT	. 1	100	160	24	4 1	OU.	101	40	tou	120	1 3		14 5	out	153	1015	101	100	121	100	TCU	7014	100	12.5	150													1	. 4	100	747	1	1 12	14	1 1	5
	E00	715	789	6.11	4 7	24	235	101	21	103	4 10	1	10	27	23	12	2.5	32	154	100	1335	103	(0.0	13.5	100													. 9	1 8	N 100	M	1	1 3	16	1	8 2
llentene	130	650	160	18	1	10	262	93			- 05	5	6.8	47	221	13	8.2	30	10	(1)	-100	100	70.5	200	2.2													31	77	¥ 8	14	- 1		1	1	9
Chlorobenzene	815	360	1,600	193	17	153	690	41	17	- 7	11	1 1	95 1	20	7.0	10	72	34	17	4,	77	37	10	- 4														1,000	N	1 15	790	971	10	- 17	1	6 31
1,1 DCB	25	330	43	- 59	4	67	523	- 1	41	- 3	1 4		6.7	50	3.1	74	10.5	1167	1 67																			. 0	. 14	1 10	75	41	1 12	18	1	6
1,4.008	500	110	611	- 44	1	20	550	+	11	- 8	1	1	#/	61	40	357	115	2.1	(1)												1								,	16	12		N	"	1	5
12008	280	340	350	31	1 1	165	270		+3	- 1		4	40	22	21	12	11.		- 40																				14	10	14		10	1,		15

Table H-4: Selected Volatile Organic Compounds in Well LF-5, 1995 to 2016

																																				Date !	Sampled										
DLATELS 1-99	5.51	611	7.9	1 41	11 1	91	11:55	£ 14	110	4 2	1.97	6.97	3.97	12:97	3.34	6.91	171	12/11	1.71	11.91	5.0	0 110	0 5	11	121	102	2.02	103	194	104	1.01	10:01	8.06	13:04	5.01	1.03	11.03	8.10	3.14	2.14	11:14	2:15	515	4:0	11:15	2 14	2.17
- ITHOUGH				1				100		1								- 3			١.						- 4	-												10	10				No.	16	1
t DCE	50.5	211	- 50			71	11.	54	10	1	101	1011	104	100	151	121	3.	100	100	1 100	10				94	101										70.0	10	10	1	10	16	14	1	No.	140	ly:	1
7 DCE	34.5	20	- 9	1	10	74	41.4	10	10	1	101	200	74.1	5.1	4/	2.	150	7.	1.3	1		0	4 1	1	84	1000	113						1			30	111		- 3	160	145	145	. 3	10	165	14	1 1
lenzenie	24	12	3	4	10 0	141	14	1.00	. 3	1	3/	1.5	12	21.	10	12	121	11	16.			4	7	4	2	Link			- 1		- 1	- 1	- 8					31		15	145	16	. 3	14	15	16	1
Morsbenzene	96	36	- 2	1	(5)	7	11	1.0		4	111	13	(1)	184	12	116	1.	7.6	- 0	ij (I	1	4	16		2.8	112	310	1	- 1		- 1	- 1				(17)	- 0	27	53	tc.	140	*7	47	10	140	160	4
3 DCB	219	- 51	- 51	4 3	d	19	Ot/		. 10		110	110	1261	100	100	1.111	10	101	100										_							96	1.	71	11	145	145	×.	14	14	162	- 46	4 '
,1 000 ,4 000	4.7	- 1		4	1-1	1.	- 1		10	1	11).	110	14	2.1	101	1913	100	753	100		1	1	1	1		1		- 1	- 1	- 1						10	- 10	71.	- 11	100	150	36,	- 1	140	*	- 19	1 1
2 DCH	1.2	14		1		214	14			n.	4.	1311	314		7.33	6.1	- Hts		4							0.15	- 510										7	- 2	- 11	No.	145	24.	1.0	16	:N5	. 14	-

Fig. - No. 2 (Let Append) - No. 2 (Let Append) - No. 2 (Let Append) - Extracted (Conservation) (1 - 2) (2 - 2) (Region)

Table H-5: Selected Volatile Organic Compounds in Well LF-6, 1995 to 2016

	-	_	-	-	-	_	-	$\overline{}$										$\overline{}$	1				20.0	0-24	0.00000	12.75	100			201 19	3,45,903,14	8391	25000	0.000		(9)33	0 028	32 3	200	3/14	75265020	2/15		2000		2/15	5
KATILES (191)	5:95	6/25	779	5 87	15 9/	15 11	195 8	135 1	1/96	3/97	6/97	9/97	12/97	3/98	5/98 9/	98 12	198 3.19	9 11/9	5.00	111	00 5/	01 1	1/01	402	12/02	9.03	3.04	900	4 3	95	10/05	405	10.04	5.01	6/09	11/01	.81	10	3/14	2/14	11/14	2/15	5/15	8715	11/15	2/15	- 0
-				T	T			Т																										2000													-
/ Chloride	143	51,			No.	ng S	154	13	*20	145	52	450	1 500	66	11 4		600 12	3 1 80	14	ad 1	pu		7.30	argul.				2	601 3	0.7	998D	1011	1141	- 60	ii,		n)	21.0						-			-
DCE	30	11.	ti.	9	N.	200	24	25	100	21	TEU	250	500	100	100 5	GU 25	0.7 10	259	1 70	1	ob:	toul	10	100					-						- 0		nu	·U	-	_==			-		-	-	+
DCE	3.			1	W.	20	14	50	90	4.000	9.)	420	4460	63	7.1 4		380 (1	162	11.05		21	754	10	Tou	1.9000	1.7	-	4	72	9,000	90000	150	(0.5)	730	311		111	10				55-55		-	-	-	-
teve	63			2	11 0	6.	3.2	357	5,1	47	6.	47	41.	22	10	11)	26.	4 40	19	7.1	11	11	4	4.1		- 12		12	19	33	20-	4.	4	- 3	- 31	1	10	to				-	-		-		-
robenzene	50	33	401	N.	20	20%	Tip	590	125	1.0x/	1002	250	1120	100	tico.	6.1 25	igu ir	250	25		÷4	17010	0.7	104	12.		4	4	1.	/101	4.9	3.0	11/	10			14,1	10	-			-	-			-	+
DCH	\$11	10	4 0	U.	117	26	10		100	100	100)	300	MH	f(0)0		GL2 1	(0.) 10	U.		-						-		-	_		-				- 1		10	TLA	-	_		-	-			-	-
DCH .	41.	10	1				10		160	fou	100	töb	TOU	ter	120/1	D./	10 10	0																	33		195	S10	_			-	1	-	-		+
DCB	TO.	1	1	U	.0		10		Total .	1	teu	icu	4.	±01.	1511	6	20 0	1																	(1)	9	3U	110							1	1	1

- Not Appropriat

U = Not (Selected)

J = Estimated Concentration

() = Estimated Concentration

() = Estimated Regulation

Table 11-6: Selected Volatile Organic Compounds in Well LF-7, 1995 to 2016

	1		100																Da	ate Sar	nple d													*								1,000		
DLATILIS (40	5/95	6/95	7/95	1/95	9.795	11/95	796 1	1/95	3/97 6.	97 97	97 12	2/97 2/	18 6.5	8 9/98	12/98	199 1	1/55	5.00	11/00	501	11/0	4.6	12	02	103	3/04	9.04	3/95	10/05	470E	10/06	5708	6.09	6-09 DUS	11/09	8/10	3/14	11/14	2/15	5/15	IJ/15	11/15	2/10	5
radiosis de		-	-				-				-				40	*500	100	100	1000	480		1		+	-			-		-	-	-	- 11	1		10						*		
yl Chieride	11.0	11	1.2	10	***	- 1	100	100	100 1	10011-1	-	100	-	200	1.7	1001	110.00	1,00	74.62	1.30	1					-	71.0	10.5	-		1	100												
DCE	10	115	213	10		10	SU	100	100 1	100	Du	1001	ou to	U 500	100	tou.	100	100	100	1.04	4	S 1	20	-	-	-			-	-	1	-	- 16	- 33	2 23	19		-			-		_	-
DCE	10	112	311	11.	0	4	JU.	10.3	100	0.7	7.4	tour	10	2 500		160	10	*50	No.	161	0.0	1	U								-		(4)	e ti	1 10	16						-		-
nzene	.196	**	5 75	2.9	12	· r	25	21	1.4	40	12	15	19	0 60	1	4.	24	27	10.		0.	1	cu -	-	-	_					-		7		1	1 1						17		-
lorobenzene	93	111	0.5	116	20	10	32	tou	33	120	35	104	9. 10	0 450	16	20	1.	100	170	10	0.3	- 1	W.	-	44				-	-	-	-	(4)	1 10	11	11	-		-	-		-		-
DOB	10	11	20		211	180		100	27	100	97	1,19	6. 11	U 15	34	0.82	-	-	1133		-		-	-	-			-			-	-	14	1	1	1	-	-		-				-
DCB	140	15	1 3	31	20	10		4.	110	430	45	19	35	6.	150	1.					-	-	1		-				-		1	-	- 1		1	1	-			§ =				-
ben	3.	1		36	201	10		10	24	14	10	100 1	04 11	U 09	10.3	1500							1										3.5	1		0 15	1.1						-	

tistana pred () = tastiste (tell (= Eatmate (C) = entail () = Double Heatmat

Table H-7: Selected Volatile Organic Compounds in Well LF-8, 1995 to 2016

VOLATRES (Hg/l)	5/95	6/	5 7	95	5.95	9/95	11/95	8/94	11/9	34	7 6	21	9/97	12/97	3/9-8	6/53	9/9	8 12	2/98	3/99	11/96	5.00	110	00 1	.01	11/01	402	12.02	9/01	104	1.04	3/05	10.05	4.06	10/0	26 1	5.08 8	64 DUS	6/09	11/09	- Britis	3/1	trt	4 11/	14 7	/15	5/15	6/15	11/15	2/16	5/1
ryf Chloride	1 30	tel.	71	20	21.5	20	71		0	19	500.0	10	10.57	0.23	- 5	-	2	250	0.42	10		-	to l	10	510	500	50.0	10	100	- ,	- 10	10	201			71		117	-					-	-						-
DCE		11.5	25.5	21.4	20	25	25		- 0	0.1	500	71.4	- 11.6	.11,	- 1	4	14	93.0	113	10		1	tick	116	54.6	SOL	500	12.	-						-	1	- 1	-	1		1	6	1		-						1
DCE		933	73.5	711	- 214	21	- 25		-0	1/	SOL	31.1	0.57	0.23	- 1		100	30	TU	310	1		ri (30.6	860	500	50.4	350	166	4.	1.62	4	10	1	6	11.4	10	11.0	- 61				1			-	-				+
ntene		154	20	71.	\$1.5	20	6.12	-	1 2	00	6.4	82	60	97			4.5	76	42.0	1020			8	22	54.	86	265	1300	90	7.	11		4.0		1	15	75.5	114				71				-	-				1
Recobenzene	120	43	45	40	42	38	190		. 1	20	590	150	630	130	- 66	61	90	480 6	6700	620	14	0 46	00 10	ecci	67	620	1-1000	11.0	5000	yeer	- Decir	2101	9900	1 6	01 127	vict.	87.7	88.5				1	-	-	-	- +					1
DOCE	- 5	7	20	201	0.3.4	10	0.9	-		3	EDG.	+	- 1	- 2	9		2	251	7		(6)	1	1		500	5014	501	= "	-		1		1	1	-	-	-						1			-					1
4 DCB		3	111	112	1.3	10			3	6J	423	- 6	- 0	15	. 1		10	50	122	- 8		2	4		50	4.014	11.4											-					1		-	1		- 1			1
2 DCB	4 1	141	211	20	753	21	1		1	4	Sect	Unit		- 4			1	253.	- 1	- 2	0.8			161	- 1	101	100					1	-	-	1	-				1	1		+	-	1	-	-			-	+

Table H-8: Selected Volatile Organic Compounds in Well LF-9, 1995 to 2016

VOLATEES (PG/)	_																	Date 5.	ampleid																		1								
	5/95	6/95	7/95	8.95	9/5	15 11	95 8	96 11	1796	3.97	697	9.97	12/97	3/98	6.08	9.94	12/98	Date 5.	11/99	5/00	11/00	501	11/01	4/02	12/02	8-03	3.04	9/04	3.05	10/05	4.06	10/05	5/08	5.09	11/09	8/10	3/14	8/14	11/14	2/15	5/15	8/15	11/15	2/16	5/1
yl Chloride	11,	71			10	dil	11.1		251	70	20	0.15	71.	10	to	11	10	10	10	n.	11	ti	11	1				1 2	-		-	-		11			-								+
DCE	10	9 9	1	1.		71.7	306		251.4	11.1	20	71.0	(41)	10	11	- 33	110	10	10	10,	- 51	1 11	11	11					-	-	1 2		1	11	1 .	1 1									10
DCE	*1.	11	1	V.	14	714	0.57		254	16	216	10.1	10	10	11	- 11	713	10	160	11,	t t	11	11	11	-					100	-	-		ti	1	1		12:							
ttene	- 3	4	1	A	4	4	7.4		550	- 14	34	130	58		- 2		1100	0.63	0.50	0.1	0.5	11	1)	3				-					-	11		1	-						- /	-	
probenzene	0.53	10.75	0	2	1	- 51	- 1	-	3.4	6.27	0.64	0.17	- 7	0.33	0.72	0.3	1.0	02.0	0.30	11.	0.1	11	0	1 1	1			-	-					1	1	1 1			- 10		-	-		-	
DCB	11.	1	1	1	1	10	0.14		535	114	- 251	10	10		- 11	- 11	11.5	11.4	113	11.	11	1 1	1 10	1 1	1					=	=			11	11	4								8	
DCB	10	11	1			10	0.14		-00	-14	- 33	*1.0	713	- 40	11,	- 31	10	10	0.13	- 11	- 11	11	1	11	1	-	-	-						Ti.	1 1	1			-	-					

in fact Analyzed 3) in fact Detected 3 in Extremetad Concentration 3 in Outron Required

⁻ fact Analyzed
U = fact Defected
U = Estimated Concentration
D = Obtaion Regured