

7.6.4

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W. R. GRACE  
ADMINISTRATIVE RECORD

W. R. Grace & Company  
ACTON ENVIRONMENTAL PROGRAM  
QUARTERLY REPORT ON  
AQUIFER RESTORATION

JULY 1985

WRG 003

1394 F

GRACE

James F. Murphy, Jr.  
Assistant Vice President  
Polyfibron Division

W. R. Grace & Co.  
55 Hayden Avenue  
Lexington, Mass. 02173

(617) 861-6600

July 9, 1985


Mr. John R. Moebes  
U.S. Environmental Protection Agency  
Region 1  
J. F. Kennedy Federal Building  
Room 1903  
Boston, Massachusetts 02203

Mr. Edmond G. Benoit  
The Commonwealth of Massachusetts  
Department of Environmental  
Quality Engineering  
Central Region  
75 Grove Street  
Worcester, Massachusetts 01605

Dear Messrs. Moebes and Benoit:

Enclosed is the Supplemental Aquifer Restoration Report as required  
by the "Addendum to Final Report on Aquifer Restoration Program".

Very truly yours,

  
James F. Murphy, Jr.

JFM, JR/mlr

cc: H. I. Fox - Sierra Club, Washington, D.c.  
O. M. Favorito - Grace/Cambridge  
K. E. Wenger - EPA/Boston  
B. J. Murphy, Jr. - Town of Acton  
John MacLeod - Acton Water District  
Steven Anderson - Palmer & Dodge

NOTICE: If the film image  
is less clear than this  
notice, it is due to the  
quality of the document  
being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1395

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

1. SUMMARY

The aquifer restoration system at the W. R. Grace & Co. Acton facility has been operating since March 22, 1985. This first quarterly report describes operations, hydraulic monitoring, contaminant modeling, and new field work that has been undertaken.

Hydraulically, the system is operating as planned. The groundwater elevations that have been measured show that levels within the influence of the pumping wells are still dropping. Even though these absolute levels have yet to stabilize, the shape of the contours as of June 11/12 showed that the size and shape of the planned containment area was being achieved.

Sampling and analysis for volatile organics have shown a decrease with time in the tower influent that is expected to continue. More work will be required to determine the precise location of the emergence of contaminated groundwater up into Fort Pond Brook. Additional well points in Fort Pond Brook and a sampling well are recommended to clarify the presence of contamination at the farthest downstream sampling point.

More field work by Grace northeast of the Secondary Lagoon is not recommended at this time. It is also concluded that existing monitoring locations and sampling schedules in the Mass. Broken Stone Pit are sufficient.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1396

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1397

## 2. INTRODUCTION

### System Description

The aquifer restoration system at the W.R. Grace & Co. Acton Facility was constructed and tested in the winter of 1984-1985 and placed into operation on March 22, 1985.

The system consists of seven pumping wells at five locations (two wells are paired) all discharging to a packed tower air stripper. The pumping wells are designed both to recover the groundwater under the site for treatment and to provide hydraulic containment (ie to prevent off-site migration of contaminated water by creating a depressed zone in the groundwater table). The air stripper is designed to remove volatile organic compounds from the groundwater. The treated water is discharged from the tower to Sinking Pond and infiltrates through the pond bottom back into the aquifer. Some of this treated water is recovered and recycled through the treatment system, while the balance moves southward either to the Assabet River or to the two pumping wells described below.

Two previously existing pumping wells (WRG-3 and RP-1) are also operating on the site. RP-1 protects the Assabet Well Field by pumping contaminated groundwater from the fractured bedrock. It discharges, through its own small packed tower air stripper, to the WRG-3 well casing. WRG-3 pumpage is partly used in the Daramic battery separator plant; the remainder is discharged directly to Sinking Pond.

The entire Aquifer Restoration System is shown in Figures 2-1 and 2-2. Characteristics of the pumping wells are summarized in Table 2-1.

### Startup and System Operation

The system was first activated on March 22, 1985. All wells, except for the WLF well, have been operating with few exceptions since that time. A flow record of the Aquifer Restoration wells is presented in Table 2-2.

The WLF well, though operable, has not been run since startup because of its proximity to an off-site landfill owned by Agway Inc. which was reported to be formerly used for disposal of agricultural chemicals. DEQE advised Grace and CDM of this potential problem in January 1985. Independent studies are currently being planned by others to determine if contaminants from this landfill have reached the groundwater. If it can be demonstrated that contaminants have not reached the groundwater under this landfill, then the WLF well can be activated. Meanwhile, groundwater elevation contours which are generated periodically as part of the Aquifer Restoration Monitoring program are studied to ensure that the containment zone developed by the pumping wells does not include the Agway landfill. The flow from the pumping system was reduced in mid-May to reduce the head in Sinking Pond, and thus to reduce the eastward component of the gradient in the vicinity of the Agway landfill. Head readings did not clearly show the Agway landfill to be coming within the combined area of influence of the Grace pumping system, but the developing gradients appeared to justify

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1398




FIGURE 2-1

AQUIFER RESTORATION WELL LOCATIONS

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD




FIGURE 2-2

AQUIFER RESTORATION WELL LOCATIONS

6

WRG 003

1399

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

TABLE 2-1

W.R. GRACE & COMPANY, ACTON FACILITY  
AQUIFER RESTORATION PROGRAM

KEY CHARACTERISTICS OF PUMPING WELLS

WELL	REFERENCE ELEV	DEPTH TO SCREEN (FT BELOW REF EL)	
		TOP	BOTTOM
NLBR	182.76	94	104
NLGP	182.91	72	87
SLBR	180.92	129	139
SLGP	181.88	92	112
ELF	197.35	60.6	100.6
RLF	147.01	32	41
WLF	198.24	93.4	111.4
WRG-3	NA	45	60
RP-1	NA	78	88

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1400

TABLE 2-2

MR GRACE--AQUIFER RESTORATION PUMPING WELL FLOWS--ALL FLOWS IN GPM (PRESSURE-PSI)									
DATE	MLF	ELF	RLF	NLBR	NLGP	SLBR	SLGP	TOTAL AIR FLOW	WRG-3
29-Mar-85	0	25	0	37	5	38	330	435	336
03-Apr-85	0	22	16	37	5	39	300	419	
05-Apr-85	0	25	15.5	37	5	26.5	300	409	295 ELF 15 TO 25
12-Apr-85	0	25	15.2	36	5	27	300	408.2	290 ELF 20 TO 27
19-Apr-85	0	27	5	37	5	39	300	413	290
22-Apr-85	0	47	21	43	12	0	380	503	
26-Apr-85	0	25	15	38	5	39	300	422	308 ELF NO GAGE
03-May-85	0	25	14	35	5	39	310	428	299 ELF NO GAGE
10-May-85	0	25	14.8	36	5	40	270	390.8	290 ELF NO GAGE
17-May-85	0	25	14.5	36	5	40	270	390.5	292 ELF NO GAGE
24-May-85	0	25 (55)	14.5 (106)	35.5 (46)	5 (95)	40 (27)	182 (44)	302	299 ELF NO GAGE
31-May-85	0	32.5 (56)	14.2 (108)	35.5 (46)	5 (87)	40.5 (27)	200 (44)	327.7	290
07-Jun-85	0	33.5 (59)	14.2 (108)	35.8 (46)	5 (88)	40.5 (27)	190 (45)	319	299
14-Jun-85	0	24.7 (69)	14.2 (109)	35.8 (47)	5 (90)	37 (28)	190 (42)	306.7	303 ELF REDUCED TO 20.8 (72)
20-Jun-85	0	17.5 (76)	14.2 (109)	35.6 (47)	5 (93)	37 (27)	225 (41)	334.3	290 NLGP NO GAGE
28-Jun-85	0	34.5 (58)	7 (110)	35.5 (48)	5 (101)	40.8 (30)	260 (31)	382.8	ELF REDUCED TO 10 (80) 299 RESTARTED 6/27 AFTER 1 DAY POWER OUTAGE ELF WIDE OPEN

8

WRG 003

M.R. GRACE  
ADMINISTRATIVE RECORDNOTICE: If the film image  
is less clear than this  
notice, it is due to the  
quality of the document  
being filmed.

1401



NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1402

this precautionary measure. Data presented in Section 3 show that the Agway landfill is not within the influence of the Grace pumping system.

Each well is equipped with a low level cutoff switch which automatically shuts the pump off when a preset low water level is sensed in the well casing. The ELF, RLF and NLGP wells have experienced shutdowns due to low water level. Their discharges have been reduced to enable continuous operation. The ELF well was further throttled in mid-June to reduce possible loadings of acetone and MEK to the air stripper (details explained in Section 3).

As predicted before startup, high levels of dissolved iron were in the raw water entering the stripper. It soon became apparent that this iron could, upon oxidation during the air stripping process, result in the formation of sufficient iron precipitate within the tower to coat the packing. Such fouling might ultimately affect the efficiency of the treatment process. This problem did occur after about eight months of operation at the small air stripper associated with the RP-1 recovery well. In early 1985, that tower became completely plugged with iron deposits. The RP-1 tower media were replaced and the tower was returned to service.

To date, the amount of iron precipitate in the full-scale tower is not threatening the operating efficiency; however, bench scale testing has been performed to develop a method of cleaning the tower before the accumulation becomes serious. To date, muriatic acid and hydrogen peroxide, each in weak solution, have been effective in cleaning media placed in a 6-inch diameter test column. The neutral pH residue after hydrogen peroxide cleaning makes peroxide the more attractive alternative for further study.

Iron or other material precipitating in the ELF discharge line plugged the pressure sensing ports in that well's orifice meter after about 1 month of operation. The gage and a short length of piping was cleaned and placed back in service in late May. That gage has since shown normal readings. The NLGP gage has recently started to indicate anomalous readings. That problem has not yet been diagnosed.

Other minor problems have developed during the last three months' operation. All well controls are housed in buried concrete vaults. Small amounts of rainfall leaking through the vault covers and small piping leaks that develop from time to time result in puddling of water within the vault and high humidity. A few small holes drilled in the concrete vault floors solved that problem. Minor repairs were also done to the control panel and conduit supports in Building No. 10 (adjacent to the full-scale stripping tower); this building houses the power supply, main breakers and status light panel for the Aquifer Restoration System). A few minor electrical system faults, including an undiagnosed control anomaly which could possibly cause problems for future operations, have not yet been repaired.

Immediately upon startup of the aquifer restoration pumping and treatment system, foaming was observed in the sump to which the air stripping tower discharges. That foaming has abated, but a sample was taken for semi-volatile analysis (acid/base/neutral extractable organics) on April 12, 1985. The goal of this sample was to identify the cause of the foaming and

to determine any nonvolatile compounds in the discharge. No priority pollutants were found, but the library search tentatively identified the following compounds:

<u>Compound</u>	<u>Estimated Concentration (ug/l)</u>	<u>Spectral Match</u>
Ethyloxirane	64	Poor
1-methyl-1,2,4-Triazole	14	Poor
1,1'-oxybisbutane	14	Good
1,4-cyclohexanedione	30	Poor
Trans-1,2-cyclobutane-dicarbonitrile	8	Poor

Four of these peaks, as shown above, were not judged by the analyst to have a good match to any compound on the EPA/NIH/NBS mass spectral data base. None of the five compounds is listed on the Merck Index of 10,000 chemicals, indicating that they have little, if any, commercial, industrial, or medicinal use. Toxicological data are not available, and it is not known whether these substances are natural or man-made.

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1403

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

M.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1404

### 3. RESULTS OF MONITORING

The data on heads, flows, and concentrations of contaminants are summarized in this section.

#### A. Groundwater Flow

The groundwater head measurements made to date are listed in Table 3-1. In addition to the required full round during June, earlier readings were made on selected wells during March and April. One purpose of these early readings was to observe any tendency for groundwater beneath the Agway site to come under the influence of the Grace pumping system. These early readings showed a marginal possibility of that behavior occurring. The best way to reduce that possibility was to reduce the head in Sinking Pond. Therefore, the Southern Lagoon Gravel Pack Well, which pumps most of the water through the aquifer restoration treatment system to the pond, was cut back from about 300 gpm to 200 gpm.

The flow field inferred from the heads shown in Table 3-1 is shown on Figure 3-1. For comparison, the predicted flow field is shown on Figure 3-2 (a reproduction of Figure 6.2, Vol. III, "Final Report on the Aquifer Restoration Program," June 1984). Comparison of actual and predicted flow fields reveals that overall, the two flow fields are quite similar. The inactive status of the Western Landfill well causes some differences in that vicinity. Absolute elevations vary somewhat between the prediction and the field data, but the shape of the contours, which governs flow directions, is as expected.

Those monitoring wells that have water level readings from more than one occasion have shown a tendency for water elevations to decrease with time, indicating that equilibrium has not been established. As time passes and the contours/cones of depression become stable, the absolute water levels are expected to be closer to the predicted water levels.

#### B. Water Quality Data

The available data on volatile organics are tabulated and discussed here under four categories:

1. Performance of Aquifer Restoration System
2. Protection of Assabet Well Field
3. Fort Pond Brook
4. Laws Brook Well Field

1. Aquifer Restoration System. In this category of data are the monitoring wells intended to check overall system performance, the Grace pumping wells installed in the fall of 1984, and those samples associated with the air stripping tower and Sinking Pond. Data for these wells are summarized on Table 3-2.

Levels of contamination in the tower influent are already decreasing as shown in Figure 3-3.

TABLE 3-1

W.R.GRACE, ACTON FACILITY, GROUNDWATER ELEVATION SUMMARY PAGE 1/3

WELL NO.	* REF. EL **	WATER ELEVATION			
		3/29/85	4/3/85	4/12/85 4/16/85	6/11/85 6/12/85
A-2E	* 132.70 **				122.85
A4-78	* 134.98 **				126.19
A5-78	* 132.32 **				126.73
A6-78	* 138.55 **				127.53
A8-78	* 141.28 **				130.90
AR-1	* 139.91 **				125.96
AR-2	* 137.38 **				125.69
AR-3	* 153.96 **		141.04		140.80
AR-4	* 171.72 **		140.11		139.73
AR-5	* 199.31 **				136.38
AR-6	* 199.67 **				141.14
AR-7	* 202.70 **				147.64
AR-8	* 141.39 **		133.85		132.72
AR-9	* 187.84 **	140.55	140.47	140.30	139.53
AR-10	* 191.68 **	139.42			138.58
AR-11	* 141.37 **	134.84	134.93		134.32
AR-12	* 141.45 **	124.06	124.06		123.44
AR-13	* 142.75 **				131.32
AR-14	* 152.31 **		128.54		128.27
AR-15	* 160.93 **		136.64		136.55
AR-16DP(A)	* 137.46 **				129.92
AR-16SH(B)	* 137.53 **				129.46
AR-17DP(B)	* 145.09 **				131.36
AR-17SH(A)	* 143.01 **				131.01
AR-18	* 185.47 **	137.75	137.55		136.35
AR-19DP(B)PZ	* 184.22 **	138.70	138.68		138.02
AR-19SH(A)PZ	* 184.92 **	135.65	136.47		136.01
AR-20	* 147.72 **	129.46	129.30		128.84
AR-20A	* 147.80 **	134.45	134.29		133.27
AR-21	* 197.80 **	129.41	129.14	129.02	128.77
AR-21A	* 197.61 **	129.52	128.69	128.43	128.31
AR-21B	* 197.71 **	136.39	136.30	136.13	135.59
AR-22	* 148.47 **		114.15		114.85
AR-23	* 165.99 **		136.22		135.13
AR-23A	* 165.81 **		136.33		135.22
AR-23B	* 165.53 **		136.10		135.02
ASS. RIV. (HIGH ST)	* **		126.94		
B-1	* 178.28 **	140.25	138.93		138.07
B-2	* 178.03 **	140.17	140.24		139.90
B-3	* 168.28 **	138.18	138.24		138.01
B-4	* 168.06 **	139.88	139.83		139.49
B-6	* 139.13 **			125.52	124.20
B-7	* 137.43 **				123.45
B-10	* 197.04 **		139.87		139.25
BD-1	* 195.90 **	140.00	139.78		138.53
BD-2	* 195.91 **	140.03	139.83		138.64
BL-1	* 177.42 **	138.47	138.08		136.88
BSL-1	* 178.67 **		140.99		139.99
CLF-1	* 151.24 **		126.30		125.96
CLF-2P1(C)	* 131.78 **		125.51		124.70
CLF-2P2(B)	* 129.81 **		125.00		124.39

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1405

12

WATER ELEVATION

WELL NO.	* REF. EL **	3/29/85	4/3/85	4/12/85 4/16/85	6/11/85 6/12/85
CLF-2P3(A)	* 131.65 **		124.19		123.62
CLF-3P1(A)	* 132.10 **		125.24		123.12
CLF-3P2(B)	* 133.23 **		124.84		123.28
CLF-3P3(C)	* 133.25 **		124.86		124.24
EL-3	* 174.74 **	139.40	139.27		138.73
ELF-OBS	* 197.97 **	134.75	134.72		135.67
G-1	* 201.75 **				140.74
G-2	* 198.31 **	138.15	138.08		137.34
G-3	* 192.13 **				139.04
J-2P	* 139.30 **				123.45
J-3P	* 135.70 **				122.67
LF-1	* 192.96 **				138.25
LF-2	* 195.01 **		137.74		136.79
LF-3	* 202.10 **		141.11		140.64
LF-4	* 199.42 **	137.81	137.76		138.14
LF-5	* 199.64 **	137.13	137.92		137.00
LF-5A	* 199.74 **	137.88	137.84		137.12
LF-5B	* 198.55 **	138.14	137.94		137.22
LF-5C	* 197.90 **	138.06	137.98		137.24
LF-6N	* 198.21 **	131.91	131.63		131.54
LF-6C	* 198.62 **	134.85	134.70		134.37
LF-6S	* 198.62 **	137.00	136.93		136.29
LF-7	* 194.94 **			138.28	137.67
LF-8	* 195.76 **			137.72	137.64
NL-1	* 142.12 **	137.19	137.08		136.10
NL-2	* 140.32 **				137.40
PT-1	* 135.54 **				122.30
PT-2	* 134.58 **				< 123.58
PT-2A	* 134.58 **				DRY
PT-3	* 138.57 **				123.75
PT-4	* 135.90 **				122.65
PT-5	* 137.25 **				122.76
PT-9	* 134.65 **				124.72
PT-10	* 135.23 **				124.54
PT-11	* 133.33 **				124.73
PT-12	* 153.54 **				141.06
R-1	* 155.98 **			127.61	127.08
R-2	* 138.94 **			123.93	123.38
R-2A	* 138.86 **			121.74	120.93
R-3	* 146.53 **			126.86	126.04
R-4	* 139.11 **			132.70	132.29
R-4A	* 140.59 **			134.17	133.80
R-5	* 139.02 **			126.54	125.72
SL-5	* 191.41 **				< 141.29
SL-9	* 181.61 **		139.82		139.02
TCA-1	* 183.62 **		139.39		138.01
TF-1	* 194.58 **	138.74			137.78
TF-2	* 195.01 **	138.78			137.76
TW-2-78	* 151.61 **			139.26	139.08
UNA-1	* 143.57 **			126.70	125.94
UNA-2	* 138.39 **			129.66	129.12

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1406

13

WATER ELEVATION

WELL NO.	* REF. EL **	WATER ELEVATION			
		3/29/85	4/3/85	4/12/85 4/16/85	6/11/85 6/12/85
UNA-3	* 154.79 **			132.32	131.93
UNA-5	* 157.75 **				136.78
WLF-OBS	* 199.15 **	137.19	137.20		136.72
WRG-1-DW	* 146.18 **				134.49
WRG-2-CW	* 146.83 **				134.44
73-3	* 130.96 **			126.39	124.22
73-4	* 138.11 **				134.11
73-6	* 134.20 **			134.20	129.26
73-7	* 134.65 **				127.68
77-1	* 132.09 **				123.95
77-2	* 133.63 **				125.89
77-3	* 134.26 **				128.64
78-3	* 133.29 **				126.00
9-78	* 137.00 **				125.67
NLBR	* 182.76 **		131.43		130.63
WLF	* 198.24 **		136.77		136.35
ELF	* 197.35 **		97.63		132.28
RLF	* 147.01 **		111.84		112.21
SLGP	* 181.88 **				128.82
SLBR	* 180.92 **		130.20		130.04
SINKING POND	* NA **	143.27	143.53	143.70	143.41
-----					
BARCAD WELLS	* **				
AR-18B	* 185.47 **	131.53	131.49		130.78
AR-19B	* 183.93 **	136.77	137.95		134.73
LF-7B-SH	* 194.91 **			137.90	137.62
LF-7B-DP	* 194.91 **			137.10	137.19
LF-8B	* 194.74 **			135.54	134.80
R-3B1	* 146.53 **				126.01

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1407

14

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1408




Figure 3-1  
GROUND WATER ELEVATION  
CONTOURS ON JUNE 11/12, 1985

15

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1409




Figure 3-2  
PREDICTED GROUND WATER  
ELEVATION CONTOURS WITH ALL  
RESTORATION WELLS PUMPING

16



NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

Table 3-2

WR GRACE ACTION  
 AQUIFER RESTORATION PROGRAM--VOA DATA  
 PERFORMANCE OF AQUIFER RESTORATION SYSTEM

DATE	LOC.	REF NO	V-chl	VDC	1,2-DCEa	Benz	Tol	etbz	xylene	DL
28-Mar-85	AR-21	1547		10		30				10
12-Apr-85	AR-21	1573				200				10
28-Mar-85	AR-21A	1546		30						10
17-Apr-85	AR-21A	1577		60						10
11-Apr-85	AR-9B1	1556								10
11-Apr-85	AR-9P	1555								10
28-Mar-85	ASBRIV-DN	1543								1
17-Apr-85	ASBRIV-DN	1579								1
28-Mar-85	ASBRIV-UP	1542								1
17-Apr-85	ASBRIV-UP	1578								1
26-Apr-85	ELF	1591				700	1000	70	50	10
24-May-85	ELF	1647			110	840	1700	130	50	10
29-Mar-85	ISP	1550						36		10
09-Apr-85	ISP	1552								10
12-Apr-85	ISP	1567								10
26-Apr-85	ISP	1584								10
03-May-85	ISP	1599					10		40	10
10-May-85	ISP	1603								10
17-May-85	ISP	1631								10
24-May-85	ISP	1641						20		10
03-May-85	ISP-10X1	1600								10
19-Apr-85	ISPU	1581								10
26-Apr-85	NLBR	1593		1800						10
24-May-85	NLBR	1646		2000		30				10
26-Apr-85	NLGP	1592		1200						10
24-May-85	NLGP	1645		1300						10
26-Apr-85	RLF	1590								10
24-May-85	RLF	1648								10
26-Apr-85	SLBR	1589	1600	1300		40	20	80	40	10
24-May-85	SLBR	1644		2200		70			60	10
26-Apr-85	SLGP	1588		560		110		1300	70	10
24-May-85	SLGP	1643		730		90	30	730	120	10
29-Mar-85	TOW-EF	1549						120		10
26-Apr-85	TOW-EF	1583								10
10-May-85	TOW-EF	1602				20	10	30		10
17-May-85	TOW-EF	1630						20		10
24-May-85	TOW-EF	1640								10
29-Mar-85	TOW-IN	1548	460	950		170	150	1100		10
09-Apr-85	TOW-IN	1551	1200	1100		100	50	1200		10
12-Apr-85	TOW-IN	1566	890	800		110	50	1100		10
19-Apr-85	TOW-IN	1580	580	590		90	40	730		10
26-Apr-85	TOW-IN	1582	430	920		180	140	1150	160	10
03-May-85	TOW-IN	1598	260	960		140	110	760	110	10
10-May-85	TOW-IN	1601		830		130	100	730	100	10
17-May-85	TOW-IN	1629		670		100	80	430	130	10
24-May-85	TOW-IN	1639	60	640		40	20	50	40	10

NOTE: ALL CONCENTRATIONS IN PPB

LEGEND  
 V chl=Vinyl Chloride  
 VDC=1,1 Dichloroethylene  
 1,2-DCEa=1,2-Dichloroethane  
 etbz=Ethylbenzene  
 xylene=Total Xylenes  
 Benz=Benzene  
 Tol=Toluene

W.R. GRACE  
 ADMINISTRATIVE RECORD

WRG 003

14 10

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1411




Figure 3-3

18

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1412

The data on tower effluent quality show that removal of volatiles has been consistently above 95%. Of greater importance is the quality of water entering Sinking Pond, after mixing with the WRG-3 discharge and further stripping in the cascade channel. Of the nine samples collected, six have been below detection limits for all priority pollutant VOC's. The sample on March 29 showed 36 ppb ethylbenzene, but was taken not at the entrance to Sinking Pond itself but at the upstream end of the "stilling basin" that separates the cascade from the pond itself. On May 3, a sample taken at the inlet to Sinking Pond showed 10 ppb toluene and 40 ppb of total xylenes (not a priority pollutant). A sample taken on May 3 from the pond, 10 ft away from the inlet and 1 ft deep, contained no detectable volatile organics. Later samples from the inlet to the pond have shown no detectable volatile organics, except for a May 24 sample which was reported as containing 140 ppb trichloroethylene and 20 ppb ethylbenzene. This sample was questioned with the laboratory because, on the same day, the undiluted tower effluent was reported BDL (below detection limits). Moreover, the May 24 reports of trichloroethylene in this and two other samples are the first reports of this compound in any sample since system startup. The laboratory's records showed that, at the same time these samples were run, samples from another site with extremely high concentrations of volatiles were being run in the same room. Cross-contamination via vapor transfer between open bottles is quite likely. CAA, the analytical laboratory, reported the above observations when questioned, and has prepared a letter documenting this likely contamination. Because of this situation, none of the samples with TCE reported appear in Table 3-2. The laboratory analyzed duplicates that had not been opened earlier for all three samples and detected no TCE.

Other items of interest on Table 3-2 include:

- o Two samples of the Assabet River downstream of the site have shown no contamination
  - o VDC is being collected primarily by the Northern Lagoon Gravel Pack and Bedrock and the Southern Lagoon Gravel Pack and Bedrock pumping wells. Vinyl chloride appears primarily in the Southern Lagoon Bedrock pumping well.
  - o Ethylbenzene appears primarily in the Southern Lagoon Gravel Pack pumping well
  - o Other monitoring wells required for quarterly sampling have been sampled, but laboratory reports are not expected until late July. These are, for the most part, outlying wells where changes would not be expected yet.
2. Protection of Assabet Well Field. This part of the aquifer restoration system, consisting of the pumping wells WRG-3 and RP-1 (the "bedrock pumping well"), has been operating since early 1984. Monitoring of this part of the system is achieved primarily through the R-series monitoring wells in and near the fractured upper bedrock. Monitoring of the Assabet well field itself is achieved by sampling Assabet 1 and 2 and several monitoring wells with the prefix "PT". Data are shown on

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1413

Table 3-3. Plots of actual and predicted time trends for RP-1 and Assabet 2 are shown in Figure 3-4. Progress toward cleanup appears to be as expected. WRG-3 monthly samples for the past year have mostly been below detection limits. The need to pump this well at its present rate is therefore being reevaluated.

3. Fort Pond Brook. Well points (1 1/2" diameter) were driven through the brook bottom at the locations shown in Figure 3-5. Screened intervals are shown in Table 3-4, together with the head difference between the subsurface and the brook surface water. Gradients in five of the six samplers were upward toward the brook on the day of sampling. FP-4 showed a slight downward gradient. FP-4 is near an active gravel washing operation that may alter the gradients in that vicinity. Samples were collected from the well points and the adjacent surface waters on May 29. Results of analyses for volatile organics are shown on Table 3-5. FP-1 and FP-5 have been resampled to verify the results shown. There has not been enough time to fully interpret these data.

In order to ascertain a more complete understanding of the presence of VDC in the vicinity of FP-5, W. R. Grace plans to conduct additional investigations in Fort Pond Brook. These investigations will include: (a) resampling and analysis of both the groundwater and surface waters at FP-1 through FP-5, (b) installation of 2 or 3 additional well points into the stream sediments downstream of FP-5, (c) installation of a monitoring well next to FP-5 into the aquifer below the level of the streambed sediments (10 to 15 feet below the streambed) to sample and analyze the groundwater at that location, and (d) collection and analysis of sample(s) of the streambed sediments for volatile organics, particle size, gradation, and organic carbon.

4. Laws Brook Well Field. Existing monitoring wells and production wells in the vicinity of the Laws Brook Well Field were sampled by CDM, accompanied by Larry Dayian of the Acton Water District, on May 14. Locations are shown on Figure 3-6, and results on Table 3-6. No volatile organic compounds were detected in any of the samples (detection limit = 1 ppb).

#### C. Analytical Quality Control/Quality Assurance

The standard procedures developed for the Consent Decree and Administrative Order were used to generate the water quality data in this report, including precautions to collect and preserve representative samples, chain-of-custody protocols, and furnishing blind replicates and trip blanks to laboratories. All VOA data presented earlier in this report were furnished by Cambridge Analytical Associates, using Method 624. The ERCO analytical laboratory was used for quality control. Table 3-7 shows all of the intralab and interlab comparisons. Some anomalies appeared and have been/are being investigated. For example, ERCO routinely analyzes for several non-priority pollutants. In the samples of stripping tower effluent collected on May 10, ERCO reported the presence of acetone and 2-butanone (methyl ethyl ketone, or MEK). CDM requested CAA to review the records for the comparative sample for evidence of these two compounds; CAA reported that peaks for these compounds were absent in that sample's chromatogram.

Table 3-3

WR GRACE ACTON  
 AQUIFER RESTORATION PROGRAM—VDA DATA  
 PROTECTION OF ASSABET WELL FIELD

DATE	LOC.	REF NO	V-chl	VDC	1,1,1-TCEa	Benz	TetCethy	Tol	etbz	xylene	DL
27-Mar-85	AIRSTP	1536									10
11-Apr-85	AIRSTP	1557									10
28-Mar-85	ASB-ONE	1544		9	70						1
30-Apr-85	ASB-ONE	1596		11	70						1
28-Mar-85	ASB-TWO	1545		17							1
30-Apr-85	ASB-TWO	1597		22							1
27-Mar-85	B5-B4	1528		110							10
11-Apr-85	B5-B4	1563		120							10
27-Mar-85	B6-B5	1527		1200							10
11-Apr-85	B6-B5	1562	580	980							10
24-May-85	B6-B5	1655		1100		40					10
27-Mar-85	R-1P	1525		60							10
11-Apr-85	R-1P	1560		70							10
27-Mar-85	R-2A	1530									10
11-Apr-85	R-2A	1565									10
27-Mar-85	R-2P	1529		60							10
11-Apr-85	R-2P	1564		20							10
27-Mar-85	R-3B1	1526									10
11-Apr-85	R-3B1	1561									10
24-May-85	R-3B1	1654						20			10
27-Mar-85	R-3P	1533					360				10
12-Apr-85	R-3P	1570									10
27-Mar-85	R-4	1532		90							10
12-Apr-85	R-4	1571		40							10
27-Mar-85	R-5	1531		1100							10
12-Apr-85	R-5	1572	570	680		30					10
27-Mar-85	RP-1	1535		260							10
11-Apr-85	RP-1	1558		450							10
27-Mar-85	WRG-3	1534		30							10
11-Apr-85	WRG-3	1559									10

NOTE: ALL CONCENTRATIONS IN PPB

LEGEND


V chl=Vinyl Chloride  
 VDC=1,1 Dichloroethylene  
 1,1,1-TCEa=1,1,1 Trichloroethane  
 TetCethy=Tetrachloroethylene  
 etbz=Ethylbenzene  
 xylene=Total Xylenes  
 Benz=Benzene  
 Tol=Toluene

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.


W.R.GRACE  
 ADMINISTRATIVE RECORD

WRG 003

14 14



**LEGEND:**  
 ○ MEASURED CONCENTRATIONS



**Figure 3-4**  
**TREND OF MEASURED AND PREDICTED VOC**

22

**WRG 003**

M.R.GRACE  
 ADMINISTRATIVE RECORD

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

1415

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1416




FIGURE 3-5

WELL POINT LOCATIONS IN FORT POND BROOK

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1417




Figure 3-6  
SAMPLING POINTS NEAR LAWS  
BROOK WELL FIELD

24



NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

TABLE 3-4  
WELL POINTS IN FORT POND BROOK

	FP-1	FP-2	FP-3	FP-4	FP-5	FP-6
Screened Interval (ft. below streambed)	1.5-3.5	2.03-4.03	1.43-3.43	1.05-3.05	2.34-4.34	2.7-4.7
Difference in Water Level Between Piezometer and Adjacent Brook Water on 5/29/85 (ft)	0.06 up	0.04 up	0.03 up	0.02 down	0.11 up	0.13 up

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1418

25

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

TABLE 3-5  
 WATER QUALITY DATA FOR MAY 29, 1985  
 WITHIN AND BENEATH FORT POND BROOK

Location	Water Source	1,1-Dichloroethylene (VDC)	Toluene	Total Xylenes	Other
FP-1	Surface	ND	ND	ND	ND
FP-1	Ground	ND (ND)	ND (ND)	ND (ND)	ND (ND)
FP-2	Surface	ND	2	1	ND
FP-2	Ground	ND	ND	ND	ND
FP-3	Surface	ND	ND	ND	ND
FP-3	Ground	ND	ND	ND	ND
FP-4	Surface	ND	ND	ND	ND
FP-4	Ground	ND *	1*	ND *	ND *
FP-5	Surface	ND	ND	ND	ND
FP-5	Ground	8 (3)	ND (ND)	ND (ND)	ND (ND)
FP-6	Surface	ND	ND	ND	ND
FP-6	Ground	ND	ND	ND	ND

All Results in ug/l (ppb)  
 Detection Limit 1 ug/l  
 ND = Not Detected  
 \* Duplicate was ND for all VOC  
 ( ) = Repeat sample on July 3

W.R.GRACE  
 ADMINISTRATIVE RECORD

WRG 003

14 19

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1420

Table 3-6

WR GRACE ACTON  
AQUIFER RESTORATION PROGRAM--VOA DATA LAWS BROOK WELL FIELD SAMPLING

DATE	LOC.	REF NO	V-chl	VDC	Benz	Tol	etbz	xylene	DL
14-May-85	8	1624							1
14-May-85	A	1620							1
14-May-85	B	1622							1
14-May-85	C-109	1627							1
14-May-85	CW	1626							1
14-May-85	D	1623							1
14-May-85	D-131	1628							1
14-May-85	LB-1	1625							1
14-May-85	LBRW	1621							1
14-May-85	SWF	1619							1

VOLATILE ORGANIC PRIORITY  
POLLUTANTS NOT FOUND  
ABOVE 1PPB DETECTION LIMIT

NOTE: ALL CONCENTRATIONS IN PPB

LEGEND

V chl=Vinyl Chloride  
VDC=1,1 Dichloroethylene  
etbz=Ethylbenzene  
xylene=Total Xylenes  
Benz=Benzene  
Tol=Toluene

C-109 = Duplicate of Christofferson Well Sample  
CW = Christofferson Well  
D-131 = Field Blank  
LBRW = Laws Brook Well  
SWF = Scribner Well

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

A review of the other ERCO analyses in Table 3-7 showed no reports of acetone or MEK. Samples from the inlet to Sinking Pond were collected in triplicate in June 1985, and were submitted to CAA, ERCO, and CDM laboratories in an effort to clarify whether false positives or false negatives are occurring. Pending these results, to reduce the possible problem raised by ketones, the flow from the Eastern landfill well has been reduced.

Table 3-8 shows the results of field blanks. No false positives are indicated.

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1421

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

TABLE 3-7

NR GRACE ACTON  
AQUIFER RESTORATION PROGRAM--VOLATILE ORGANIC DUPLICATE ANALYSES

DATE	LOC.	REF NO	V-chl	ACE	VDC	1,1-DCEa	1,2-DCEa	2-BUT	1,1,1-TCEa	1,2-DCP	Benz	TetCethy	Tol	etbz	xylene	DL
27-Mar-85	C-102	1537														10
27-Mar-85	AIRSTRP	1536														10
27-Mar-85	C-103	1540 E			55											2-25
27-Mar-85	AIRSTRP	1539 E			47						3					2-25
09-Apr-85	C-104	1553	600		1700						50		20	1200		10
09-Apr-85	TOW-IN	1551	1200		1100						100		50	1200		10
12-Apr-85	C-105	1568														10
12-Apr-85	ISP	1567														10
12-Apr-85	C-106	1575 E														2-25
12-Apr-85	ISP	1574 E											24			2-25
26-Apr-85	C-107	1594			2300											10
26-Apr-85	MLBR	1593			1800											10
10-May-85	C-108	1606														10
10-May-85	TOW-EF	1602									20		10	20	10	10
10-May-85	C-109	1608 E	7.0	51	37		2.2	16			20		10	30		10
10-May-85	TOW-EF	1607 E	6.0	70	34		2.5	24			6.6					2-25
17-May-85	C-110	1633														10
17-May-85	TOW-EF	1630												20		10
24-May-85	C-111	1649														10
24-May-85	RLF	1648														10
24-May-85	C-112	1651 E	16		41	4.7					14	5.4				2-25
24-May-85	RLF	1650 E	13		41	4.3					12	4.5				2-25

NOTE: ALL CONCENTRATIONS IN PPB  
REF NO'S APPENDED WITH \*E\* INDICATE ANALYSES PERFORMED BY ERCO

LEGEND  
V chl=Vinyl Chloride  
VDC=1,1 Dichloroethylene  
1,1,1-TCEa=1,1,1 Trichloroethane  
TetCethy=Tetrachloroethylene  
etbz=Ethylbenzene  
xylene=Total Xylenes  
Benz=Benzene  
Tol=Toluene  
ACE=Acetone  
2-BUT=2-Butanone  
1,2-DCEa=1,2-Dichloroethane  
1,1-DCEa=1,1-Dichloroethane  
1,2-DCP=1,2-Dichloropropane

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1422

29

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

TABLE 3-8

MR GRACE ACTON  
AQUIFER RESTORATION PROGRAM--VOLATILE ORGANIC ANALYSES OF TRIP BLANKS

DATE	LOC.	REF NO	V-chl	ACE	VDC	1,1-DCEa	1,2-DCEa	2-BUT	1,1,1-TCEa	1,2-DCP	Benz	TetCethy	Tol	etbz	xylene	DL
24-May-85	D-113	1652														2-25
27-Mar-85	D-123	1538														1
03-Apr-85	D-124	1541														2-25
09-Apr-85	D-125	1554														1
12-Apr-85	D-126	1569														10
12-Apr-85	D-127	1576														2-25
26-Apr-85	D-128	1595														10
10-May-85	D-129	1605														10
10-May-85	D-130	1609														2-25
17-May-85	D-132	1634														10
24-May-85	D-134	1653														10

VOLATILE ORGANIC PRIORITY POLLUTANTS

NOT FOUND ABOVE DETECTION LIMITS

NOTE: ALL CONCENTRATIONS IN PPB

LEGEND

- V chl=Vinyl Chloride
- VDC=1,1 Dichloroethylene
- 1,1-TCEa=1,1,1 Trichloroethane
- etCethy=Tetrachloroethylene
- etbz=Ethylbenzene
- xylene=Total Xylenes
- Benz=Benzene
- Tol=Toluene
- ACE=Acetone
- 2-BUT=2-Butanone
- 1,2-DCEa=1,2-Dichloroethane
- 1,1-DCEa=1,1-Dichloroethane
- 1,2-DCP=1,2-Dichloropropane

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1423

30

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R.GRACE  
ADMINISTRATIVE RECORD

WRG 003

1424

#### 4. RECOMMENDATIONS

##### A. Site Closure

The numerical model's prediction of aquifer cleanup rates is based on the assumption that the waste sites have been closed. This assumption is not valid at present. On the one hand, this fact should cause no immediate environmental concern because the active leachate sources are hydraulically contained by the aquifer restoration system. On the other hand, continuing leachate production retards the rate of cleanup of the aquifer. Moreover, the continued introduction of oxygen-demanding materials into the aquifer will cause anoxic conditions and, consequently, dissolved iron, to persist in the groundwater. The oxidation of this iron in the stripping tower will require continued maintenance to remove scale from the packing. For these reasons it is recommended that the actions of all parties related to site closure be completed in a timely manner.

##### B. Continued Operation

The aquifer restoration system is fulfilling its expectations. Continued operation and, if possible, speedy resolution by DEQE of the Western Land-fill Well issue are recommended.

##### C. Fort Pond Brook

The data from beneath and within Fort Pond Brook, presented here, address the agreement in the October 1984 "addendum" to determine "the location of the identified VDC plume discharge to Fort Pond Brook." Some resampling and other work as outlined in Section 3.B.3 (Fort Pond Brook) to clarify this issue is planned. Given the fact that VDC was found at FP-1 in the brook water at very low stream flow in the autumn of 1984, it would appear that the plume emerges adjacent to the Grace property upstream of FP-1. Additional groundwater sampling will have to be done upstream of FP-1 to determine this point.

##### D. Field Studies North of Secondary Lagoon

The following field data are now available:

- o Well point FP-5 showed 8 and 3 ug/l of VDC, respectively, on two sampling dates. The adjacent surface water in the brook was below detection limits of 1 ppb for VDC.
- o Eight wells in and near the Laws Brook Well Field, sampled on May 14, were below detection limits of 1 ppb for VOC's. For the pathways from the Secondary Lagoon hypothesized by GZA to be valid, at least "LB-1" and "8" would be expected to show contamination.
- o The measured water level elevations of AR-9, AR-10, G-3, and SL-9 are consistent with the predicted contours for that area. Thus, the CDM aquifer model has been further validated for the area in question.

31

NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W.R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1425

In addition, as we have pointed out before, several serious flaws exist in the arguments that have been put forth by the Acton Water District and its consultant, GZA. Included in these flaws are the following:

- o GZA's March 1985 report failed to take into account the slow vertical migration through the layered glacial deposits under the lagoon. This movement is one of the reasons why CDM does not believe that northward lagoon of contamination exceeded about 200 feet. Two-dimensional modeling, ignoring vertical movement and resistance thereto, is inappropriate near a groundwater divide where vertical flow predominates.
- o GZA's report hypothesized that a reason for the discrepancy between its conclusions and those of CDM was that CDM did not inject particles in the northern part of the Secondary Lagoon in the contaminant transport model. CDM had refuted this idea in a meeting with GZA and the government parties on August 16, 1984. As stated at that meeting and at the meeting on March 28, 1985, particles were injected along the north shore and other places in the northern part of the lagoon during calibration runs. Outputs are shown in Figures 4-1 and 4-2. Contaminant distributions are slightly different, but the maximum distance travelled north still does not exceed 200 feet in 17 years.
- o At the March 28 meeting, GZA presented a modeled location for the present groundwater divide showing it to be approximately beneath the northern shore of the Secondary Lagoon. Also on the figure was CDM's modeled location for the divide. GZA acknowledged at the meeting that the CDM divide was more consistent with field data than the GZA divide, thus revealing a bias toward northward flow in the GZA model structure.

In summary, we believe that the existing data, together with the CDM modeling results that place those data in perspective, show the unlikelihood that materials from the Secondary Lagoon are responsible for any problems in the AWD wells to the north. The finding of 8 and 3 ppb VDC at FP-5 is the only evidence of a possible plume in that area. Any such plume is probably at barely detectable concentrations (given the lack of detection of VOC's at eight wells in and near the Laws Brook Well Field). As stated previously, additional work, as outlined in Section 3.B.3 (Fort Pond Brook), is planned to clarify this issue. On this basis, no additional field work northeast of the Secondary Lagoon is warranted.

#### E. Mass Broken Stone Pit

The principal function of monitoring wells in the Mass Broken Stone Pit is to verify that the expected flow patterns and contaminant flushing are occurring. Review of the actual flow field indicates the sufficiency of existing wells AR-3, AR-15, B-5 and B-9 for this purpose. All levels of these multilevel wells undergo periodic sampling and analysis for volatile organics.



NOTICE: If the film image is less clear than this notice, it is due to the quality of the document being filmed.

W. R. GRACE  
ADMINISTRATIVE RECORD

WRG 003

1426 L




Figure 4-2

PARTICLE CLOUD FOR CONTAMINATION ENTERING  
NORTHEASTERN PART OF SECONDARY LAGOON

33