



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region 1

5 Post Office Square, Suite 100

Boston, MA 02109-3912

Memorandum

DATE: February 18, 2022

SUBJ: 12/3/2021 inspection of Upper Harbor sediment caps, NBHSS

FROM: D. Dickerson, RPM

To: site file

DAVID DICKERSON

Digitally signed by DAVID  
DICKERSON

Date: 2022.02.18 08:13:36 -05'00'

This memo documents the visual shoreline inspection of all Upper Harbor (UH) sediment caps, performed by D. Dickerson and N. Burgo on 12/3/2021. Courtney Cohen from the City of New Bedford also participated in some of the inspections. The inspections took place between approximately one hour before and one hour after an extreme low tide at 12:30 pm that day, since only the intertidal portions of the caps can be seen visually. Note that one cap, 0-711, is completely subtidal and thus could not be seen. At another UH cap, L-114, only a very small portion of the cap was seen at the extreme low tide during the inspection (see Figure 17 below). Bathymetric surveys performed in fall 2021 captured the subtidal conditions/elevations of all the UH sediment caps; the only issue noted was at the L-014 cap (see action items below).

Figure 1 below shows the locations of the seven UH sediment caps installed in 2020. North to south, these caps are: 0-711, Crib, L-014, L-114, pilot CDF shoreline, Cogg-East and Cogg-West. Note that a small, stone-only eighth UH sediment cap, located between the pilot CDF shoreline cap and the Cogg-West cap, was installed in 2015 as part of the Parcel 265 intertidal remedial action. This small cap was visible on this inspection due to the extreme low tide (Figure 22). Not shown on Figure 1 is the Aerovox sediment cap (just to the north of the Figure 1 boundary) that was also inspected on 12/3/2021.

Figures 2 through 26 below are photos of these caps running north to south taken during the inspection.

Based on this inspection the UH sediment caps appear to be in good shape. However, four action items were noted:

- 1 - At one small (~5 sf) area closer to the landward boundary of the **Crib cap**, the armor stone was missing and the underlying sand layer was visible (Figure 11). Armor stone needs to be placed within this area.
- 2 – At the **L-014 cap**, stone displacement along the seaward edge of the cap may have occurred, possibly from wave energy during the prolonged pre-Halloween nor'easter (Figure 16).
- 3 – At the pilot CDF shoreline cap, remove dredging-related cable/turnbuckle/shackle remaining on the armor-stone near the former Area C dock area.
- 4 – Also at the pilot CDF shoreline cap, remove an empty blue plastic drum near North Dock.

All of these action items except #2 (L-014 cap) have been addressed. As part of the spring 2022 topsoil repair at West Zone 4, additional armor stone will be placed at the L-014 cap to smooth the surface and edges of the cap. This will allow any future erosion/displacement of the stone surface to be readily visible.



Figure 2:  
Aerovox cap  
looking south  
from the  
northern edge.  
The boom in the  
background is  
from the  
Aerovox 21E  
work.




Figure 1:  
 ← 0-711 cap  
 ← Crib cap  
 ← L-014 cap  
 ← L-114 cap  
 ← Pilot CDF shoreline cap  
 ← Parcel 265 stone cap  
 ← Cogg-W and Cogg-E caps



Figure 3:  
**Aerovox cap**  
looking south  
showing  
“capacitor  
cove.” Titleist  
building in  
background.



Figure 4:  
**Aerovox cap**  
looking east  
showing the  
North Trench  
storm drain  
(plugged as part  
of 21E cleanup).



Figure 5:  
**Aerovox cap**  
looking north  
showing the  
North Trench  
outfall.




Figure 6:  
**Aerovox cap**  
looking south.  
The 5-gallon  
bucket is a  
cement anchor  
for the 21E silt  
curtain.



Figure 7:  
**Aerovox cap**  
showing the  
plugged South  
Trench outfall.




Figure 8:  
**Aerovox cap,**  
looking south.  
Ponded runoff  
is due to the  
storm drains  
and scuppers  
being plugged  
for the 21E  
cleanup. (Water  
gets pumped  
through an on-  
site treatment  
plant prior to  
discharge to the  
City sanitary  
sewer.)



Figure 9:  
**Aerovox cap**, southern E/W leg, looking east. Note the serrated pattern at the lower edge of the bank armor stone.



Figure 10:  
**Crib cap** looking north. White stake in middle is a stormwater outfall (see Figure 12).



Figure 11:  
**Crib cap**  
showing the  
small area in  
need of armor  
stone.



Figure 12: **Crib cap**  
looking SE  
showing storm  
drain outfall.



Figure 13: **Crib cap.** Looking west along northern edge of the cap.



Figure 14: **L-014 cap** looking south. Bare soil is WZ-4 backfill waiting to be planted as saltmarsh in spring 2022 (after replacement of topsoil lost in October 2021 nor'easter).





Figure 15:  
**L-014 cap**  
looking SE.  
Swale in  
foreground was  
installed as part  
of WZ-4  
restoration.



Figure 16:  
**L-014 cap**,  
looking north.

Potential  
displacement  
areas from  
October 2021  
nor'easter.



Figure 17:  
**L-114 cap**,  
looking north.  
Only a small  
area of  
emerging armor  
stone can be  
seen at extreme  
low tide.



Figure 18:  
**Pilot CDF  
shoreline cap**,  
southern end,  
looking north.  
Parcel 265  
saltmarsh  
replanting in  
fore-ground.



Figure 19:  
**Pilot CDF  
shoreline cap,**  
looking north.



Figure 20:  
**Pilot CDF  
shoreline cap,**  
looking south.



Figure 21:  
**Pilot CDF  
shoreline  
cap.**  
Northern  
E/W leg  
looking west.



Figure 22:  
**Parcel 265  
stone cap**  
looking NE.



Figure 23:  
**Cogg-West cap** looking east along bridge embankment. City storm drain in foreground.



Figure 24:  
**Cogg-West cap** looking NW. Bridge opening in foreground.



Figure 25:  
**Cogg-East cap** looking east. Bridge opening in fore-ground.



Figure 26:  
**Cogg-East cap**, eastern end, looking north.