



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Region 1

5 Post Office Square, Suite 100

Boston, MA 02109-3912

Memorandum

DATE: December 8, 2023

SUBJ: 11/13/2023 inspection of Upper Harbor sediment caps, NBHSS

FROM: David Dickerson, Remedial Project Manager

To: Site file (7.5)

DAVID

DICKERSON

Digitally signed by
DAVID DICKERSON

Date: 2023.12.08
10:21:52 -05'00'

This memo documents the visual shoreline inspection of all Upper Harbor (UH) sediment caps performed by D. Dickerson and N. Burgo on 11/13/2023. The inspections took place between approximately one hour before and one hour after a 0.1 ft low tide at 1:15 pm that day, since only the intertidal portions of the caps can be seen visually. Two caps, 0-711 and L-114, were completely subtidal and thus could not be seen. At the Parcel 265 cap, only the very top of one stone of the cap could be seen (Figure 21). Bathymetric and topographic surveys performed earlier in fall 2023 will augment this visual feature inspection.

Figure 1 below shows the locations of the seven UH sediment caps installed in 2020. North to south, these caps are: 0-711, Crib, L-014, L-114, pilot CDF shoreline, Cogg-East and Cogg-West. Also shown on Figure 1 is the Aerovox sediment cap constructed in 2018 and the Parcel 265 cap installed in 2016 as part of the subtidal dredging operations in that area.

Figures 2 through 25 below are photos of these caps running north to south taken during this inspection.

Based on this inspection the UH sediment caps continue to appear in good shape with only two action items required (the first of which is a placeholder from previous cap inspections):

- At the crib cap, when implementing the ongoing West Zone 2/3 remedial action, a low-ground-pressure small excavator or similar machine will be used to create a more uniform, smoother (less undulating) stone surface. This will aid in visually detecting potential stone displacement moving forward during O&M to minimize the need for topographic/bathymetric surveys during O&M. Additional stone may be added if necessary to help create this uniform, smoother surface.
- At the crib cap and pilot CDF shoreline cap, a few very small areas (most <1 ft² each) were observed where the sand layer of the cap was not completely covered with armor stone (see Figures 11, 12 and 18). At these areas armor stone will need to be placed (or relocated from visible high spots) to ensure the underlying sand cap is well protected against wave-based erosional forces. The action item above for crib cap smoothing is expected to address these areas for that cap, such that only limited stone placement will be required at the pilot CDF shoreline cap. The few areas at the pilot CDF shoreline cap requiring this minor stone placement are along the east-facing portion of that cap.




Figure 1

- Aerovox Cap
- O-711 Cap
- Crib Cap
- L-014 Cap
- L-114 Cap
- Pilot CDF Shoreline Cap
- Parcel 265 Cap
- Cogg-E and Cogg-W Caps



Figure 2:
Aerovox Cap:
 Looking NE showing “capacitor cove.” The lower edge of the larger armor stone on the river bank can be seen where it meets the smaller armor stone of the flatter portions of the cap.



Figure 3:
Aerovox Cap:
Looking west
showing the as-
built condition of
the recently
completed
(summer 2023)
North Trench
drainage grating.



Figure 4:
Aerovox Cap:
Looking south
showing the
South Trench
discharge
structure in
foreground.
Emergent salt
grass noted in
previous
inspections
remains near the
outfall (the void
spaces in the
armor stone are
likely filling in
with silt from the
drainage
discharge).



Figure 5:
Aerovox Cap:
Small birds
(possibly Snow
Buntings -
*Plectrophenax
nivalis*)
observed along
the N/S bank of
the cap.



Figure 6:
**Aerovox
Cap:** looking
north
showing a
serrated
pattern at the
waterline in
some areas.



Figure 7:
**Aerovox
Cap:**
Looking
northeast
showing the
southern
section of the
cap and the
abutting
Hadley Street
storm drain



Figure 8:
Crib Cap:
Looking
north.



Figure 9:
Crib Cap:
Looking
northeast
showing area
near a drainage
outfall
(possibly
defunct).



Figure 10:
Crib Cap:
Looking
southwest
showing the
northern edge of
the cap.
The southern
edge of the
ongoing WZ2/3
shoreline
excavation can
be seen in the
background.



Figure 11:
Crib Cap:
Looking west
showing an area
needing
additional armor
stone at the
northwestern
end of the cap.



Figure 12:
Crib Cap:
showing a very
small area
needing
additional armor
stone.



Figure 13:
L-014 Cap:
Looking north.



Figure 14:
L-014 Cap:
Looking south showing area where original topsoil from the abutting WZ4 restoration washed into the armor stone (WZ4 topsoil was subsequently replaced).



Figure 15:
L-014 Cap:
Looking west
showing the
drainage swale
where original
WZ4 topsoil was
likely discharged
onto the cap.



Figure 16:
**Pilot CDF Shore-
line Cap** (the
rocky surface
seaward of the
Sawyer Street
facility). Aerial
view looking west
at low tide.

Photo: Ed Pepin



Figure 17:
**Pilot CDF Shore-
line Cap:** looking
northeast showing
the southern edge
of the cap. Toe of
slope remains
well defined.



Figure 18:
**Pilot CDF Shore-
line Cap:** showing
area with thin armor
stone layer and
some exposed sand
isolation layer.



Figure 19:
**Pilot CDF Shore-
line Cap:** looking
east.



Figure 20:
**Pilot CDF Shore-
line Cap:** looking
west showing the
northern edge of
the cap.



Figure 21:
Parcel 265 Cap:
looking east. Only
the very top of one
stone was showing
at the time of the
inspection.




Figure 22:
**Cogg-West
Cap:** looking
southeast.



Figure 23:
**Cogg-East
Cap:** looking
east showing
the western
edge of the cap
at the
Coggeshall St
bridge opening.
Cap armor
stone also
shown in
background.



Figure 24:
**Cogg-East
Cap:** looking
northeast.



Figure 25:
**Cogg-East
Cap:** looking
north showing
the eastern end
of the cap.

END