

Kevin Mooney Senior Project Manager GE Aerospace

1 Plastics Ave. Pittsfield, MA 01201

T (413) 553-6610 kevin.mooney@ge.com

Via Electronic Mail

January 03, 2025

Mr. Joshua Fontaine U.S. Environmental Protection Agency, New England Region Five Post Office Square Suite 100 Boston, MA 02109

Re: GE-Pittsfield/Housatonic River Site Rest of River (GECD850) Rising Pond Dam - 2024 Penstock Investigations – Material Identification Testing

Dear Mr. Fontaine:

On December 19, 2024, GE submitted the 2024 Penstock Investigations End-of-Year Report, prepared by our consultants at GZA GeoEnvironmental, Inc. (GZA), which described the 2024 investigations of the penstock at Rising Pond Dam. That report noted that samples of the apparent interior penstock coating had been collected and submitted to a laboratory for material identification testing. The results of that testing have now been received and are attached. The results show that the sampled materials consist of "iron oxide rust, presumably from some type of mild steel due to the presence of manganese and no chromium, nickel, or other type of steel alloy additive." GZA understands this to mean that there is no coating inside the penstock, and that the sampled materials are likely rust flakes from corrosion of the steel penstock.

Please let me know if you have any questions about these testing results.

Very truly yours,

Kevin G. Mooney Senior Project Manager

Attachment

Cc: (via electronic mail) Dean Tagliaferro, EPA John Kilborn, EPA Alexander Carli-Dorsey, EPA Christopher Ferry, ASRC Federal Thomas Czelusniak, HDR Inc. Scott Campbell, Taconic Ridge Environmental Izabella Zapisek, Taconic Ridge Environmental Emily Caruso, MassDCR, Office of Dam Safety Michael Gorski, MassDEP Tamara Cardona-Marek, MassDEP Ben Guidi, MassDEP Michelle Craddock, MassDEP Jeffrey Mickelson, MassDEP Mark Tisa, MassDFW Eve Schluter, MassDFW Betsy Harper, MA AG Traci lott, CT DEEP Susan Peterson, CT DEEP Graham Stevens, CT DEEP Carol Papp, CT DEEP Lori DiBella, CT AG Whitney Behr, USFWS Mark Barash, US DOI Katie Zarada, NOAA James McGrath, City of Pittsfield Andrew Cambi, City of Pittsfield Michael Coakley, PEDA Melissa Provencher, BRPC Smitty Pignatelli, Town of Lenox R. Christopher Brittain, Town of Lee Town Manager, Great Barrington Town Administrator, Stockbridge Town Administrator, Sheffield Jim Wilusz, Tri Town Health Dept. Lance Hauer, GE Andrew Thomas, GE Matthew Calacone, GE Jonathan Andrews and Seth Krause, GZA James Bieke, Counsel for GE Public Information Repository at David M. Hunt Library in Falls Village, CT **GE Internal Repository**





Accreditation# 98218

December 27, 2024

GZA GeoEnvironmental, Inc.

MicroVision Labs Project #: 17006 GZA GeoEnvironmental Project #: 19896.50 GZA GeoEnvironmental Project Name: Rising Pond Dam Penstock Report Analyst: T. Wozmak

Scope of Work:

This report covers the methods and findings of the unknown material identification that MicroVision Laboratories, Inc. conducted on two (2) samples from project number 19896.50. The purpose of the analysis was to examine the sample material by SEM/EDS to identify the elemental composition of the solids. The results presented in this report relate only to the samples examined and as received.

Equipment:

Scanning Electron Microscopy (SEM) Energy Dispersive X-Ray Spectroscopy (EDS)

Methods:

MicroVision Labs is accredited to the ISO/IEC 17025:2017 standard. This analysis follows our in-house SOP #MVL01 (Scanning Electron Microscopy/Energy Dispersive X-Ray Spectroscopy [SEM/EDS] Analysis). This method is listed on our certificate of accreditation and has been validated.

Representative portions of the solid materials were sectioned and affixed to aluminum analysis stubs using double-sided conductive tape. Images were taken at various magnifications and EDS data was collected.

Findings:

Sample: 01 – Sta. 40, 4 o'clock (blue cap)



The SEM image above shows the sample material and the location where the EDS data was collected (yellow box). The elemental composition was predominantly iron and oxygen with lower to trace concentrations of carbon, manganese, silicon, calcium, nitrogen, aluminum, magnesium, potassium, sulfur, phosphorus, and sodium. The material was brittle, multilayered, flakey, and had a reddish color to it. These properties along with the elemental composition detected in the material suggests that this sample is composed of rust flakes, presumably from a mild steel due to the presence of manganese and no chromium, nickel, or other type of steel additive.

The mass percentages of each element detected in this sample are listed in the table below.

01 - Sta. 40, 4 o'clock (blue cap)									
Element	Mass Norm.[%]	abs. error [%](1 sigma)	rel. error [%](1 sigma)						
Iron	47.98	1.03	2.04						
Oxygen	33.20	1.49	4.24						
Carbon	10.27	0.55	5.05						
Manganese	2.74	0.07	2.36						
Silicon	1.80	0.06	3.23						
Calcium	1.28	0.03	2.36						
Nitrogen	1.08	0.06	5.48						
Aluminium	0.77	0.04	4.49						
Magnesium	0.24	0.02	7.51						
Potassium	0.22	0.01	5.12						
Sulfur	0.21	0.01	5.31						
Phosphorus	0.12	0.01	8.28						
Sodium	0.10	0.02	16.36						
	100								

ISO/IEC 17025:2017 Accredited

Page.



The SEM image above shows the sample material and the location where the EDS data was collected (yellow box). The elemental composition was also predominantly iron and oxygen with lower to trace concentrations of carbon, manganese, silicon, calcium, aluminum, magnesium, potassium, sodium, titanium, sulfur, and phosphorus. The material was brittle, multilayered, flakey, and had a reddish color to it. These properties along with the elemental composition detected in the material suggests that this sample is composed of rust flakes, presumably from a mild steel due to the presence of manganese and no chromium, nickel, or other type of steel additive.

The mass percentages of each element detected in this sample are listed in the table below.

02 - Sta. 55, 8 o'cl	ock (white cap)		
Element	Mass Norm.[%]	abs. error [%](1 sigma)	rel. error [%](1 sigma)
Iron	37.28	0.59	1.56
Oxygen	35.49	1.56	4.30
Carbon	11.99	0.62	5.05
Manganese	6.64	0.11	1.62
Silicon	2.90	0.08	2.72
Calcium	2.34	0.04	1.62
Aluminium	1.61	0.06	3.57
Magnesium	0.55	0.03	5.03
Potassium	0.39	0.01	2.50
Sodium	0.39	0.03	8.34
Titanium	0.15	0.01	5.24
Sulfur	0.14	0.01	4.72
Phosphorus	0.14	0.01	5.19
	100		

ISO/IEC 17025:2017 Accredited

Summary:

Sample 01 – Sta. 40, 4 o'clock (blue cap) and sample 02 – Sta. 55, 8 o'clock (white cap) were analyzed by SEM with EDS to determine their elemental compositions. Both samples are iron oxide rust, presumably from some type of mild steel due to the presence of manganese and no chromium, nickel, or other type of steel alloy additive.

Please let us know if you have any questions or if there is anything else we can do for you.

Sincerely,

Tyler Wozmak

Tyler Wozmak Analytical Microscopist

Reviewed by: JHK



ISO/IEC 17025:2017 Accredited

				Ch	ain	Of C	usto	dy		MicroVis	sion Labs	s Job#:	17	001	2
MICROVISION					Client	t Inform	ation	-		Project Information					
			Client: (GZA GeoE	nvironme	ntal, Inc.				Project Name: Rising Pond Dam Penstock					
			Billing Address: 249 Vanderbilt Avenue						Project Location: Great Barrington, MA						
			Norwood, MA 02062						Project Number: 19896.50 Project Manager: Seth Krause PO#:						
CLABS, INC.			Phone: (781) 278-5793												
			Email: seth.krause@gza.com												
	ate	w													
Sample ID	Collected D	Sampler' Initials	Coal Ash Tes	Lead Paint Chips Analysi	SEM/EDS	Micro-FTIR	X-Ray Imagin	Micro-XRF	PLM/Light Microscopy	Soot ID	Unknown Material ID	Polished Cro Section	Membrane Autopsy	Particle Siz Analysis	Other
) 01 - Sta. 40, 4 o'clock (blue cap)	11/19/24	SK									Х				
2) 02 - Sta. 55, 8 o'clock (white cap)	11/19/24	SK									X				
3)						nicke h									
4)															
5)									-				and option		
6)						1									
7)															
8)	-								-				-		
9)			-				A			-			-		
10)															
Relinquished By: Date/Ti	me	Rece	eived E	By Da	te/Tim	ę				Turn Ar	ound T	ime an	d Note	S:	
Seth Krause 12 18 2024 XI				6100	0 12	-192	Samples are from the inside of a 14-ft diameter steel penstock pipe The samples are flakes from the inside of the pipe. Possible steel pipe material or possible pipe coating of unkonwn material.								
List any known Hazardous Material	s:	Un	knowr	ı											
Analytical Report Requested:	(YES	s)1	NO		Minust	alan Lab		a lac			100				
)			187 B Phone	illerica F e 978-25	sion Lab Road, Ch 0-9909	Fax 97	es, Inc. rd, MA 78-250-9	01824 9901						