Five-Year Review Report

Third Five-Year Review Report for Piper Aircraft Corp./Vero Beach Water and Sewer Department Site FLD004054284

> Vero Beach Indian River County, Florida

> > May 2014

United States Environmental Protection Agency Region 4 Atlanta, Georgia

Approved by: Franklin E. Hill, Director Superfund Division

Date: 4



191

Third Five-Year Review Report for Piper Aircraft Corp./Vero Beach Water & Sewer Department 2926 Piper Drive Vero Beach Indian River County, Florida

| List of A | Acronyms | 3 |
|-----------------|--|------|
| Executi | ve Summary | 4 |
| Five-Ye | ear Review Summary Form | 5 |
| 1.0 Intr | oduction | 8 |
| 2.0 Site | Chronology | . 10 |
| 3.0 Bac | kground | . 11 |
| 31 | Physical Characteristics | 11 |
| 3.2 | LAND AND RESOURCE USE | . 11 |
| 3.3 | HISTORY OF CONTAMINATION | . 14 |
| 3.4 | Initial Response | . 14 |
| 3.5 | BASIS FOR TAKING ACTION | . 14 |
| 4.0 Ren | nedial Actions | . 16 |
| 4.1 | Remedy Selection | . 16 |
| 4.2 | Remedy Implementation | . 17 |
| 4.3 | OPERATION AND MAINTENANCE (O&M) | . 18 |
| 5.0 Pro | gress since the Last Five-Year Review | . 19 |
| 6.0 Five | e-Year Review Process | . 21 |
| 6.1 | Administrative Components | . 21 |
| 6.2 | COMMUNITY INVOLVEMENT | . 21 |
| 6.3 | DOCUMENT REVIEW | . 21 |
| 6.4 | DATA REVIEW | . 26 |
| 6.5 | SITE INSPECTION | . 29 |
| 6.6 | INTERVIEWS | . 29 |
| 7.0 Tec | hnical Assessment | . 31 |
| 7.1 | QUESTION A: IS THE REMEDY FUNCTIONING AS INTENDED BY THE DECISION | |
| | DOCUMENTS? | . 31 |
| 7.2 | QUESTION B: ARE THE EXPOSURE ASSUMPTIONS, TOXICITY DATA, CLEANUP LEVELS A REMEDIAL ACTION OBJECTIVES (RAOS) USED AT THE TIME OF REMEDY SELECTION | ND |
| 7.2 | STILL VALID? | . 31 |
| 1.3 | QUESTION C: HAS ANY OTHER INFORMATION COME TO LIGHT THAT COULD CALL INTO OUESTION THE PROTECTIVENESS OF THE REMEDY? | 22 |
| 7 4 | QUESTION THE PROTECTIVENESS OF THE REMEDY (| . 55 |
| , . | | 21 |
| 0.0 1550 | | . 34 |
| 9.0 Rec | ommendations and Follow-up Actions | . 35 |
| 10.0 Pr | otectiveness Statement | . 36 |

| 11.0 Next Review | |
|--|-----|
| Appendix A: List of Documents Reviewed | |
| Appendix B: Press Notice | B-1 |
| Appendix C: Interview Forms | C-1 |
| Appendix D: Site Inspection Checklist | D-1 |
| Appendix E: Photographs from Site Inspection Visit | E-1 |
| Appendix F: Map from Remedial Investigation | F-1 |
| Appendix G: Analytical Data for Ground Water | G-1 |
| Appendix H. Monitoring Well Concentrations | H-1 |

Tables

| Table 1: Chronology of Site Events | |
|--|--|
| Table 2: Ground Water Contaminant of Concern (COC) Cleanup Goals | |
| Table 3: Annual O&M Costs | |
| Table 4: Progress on Recommendations from the 2009 FYR | |
| Table 5: Previous and Current ARARs for Ground Water COCs | |
| Table 6: Institutional Control (IC) Summary Table | |
| Table 7: Vapor Intrusion Screening-Level Assessment | |
| Table 8: Current Site Issues | |
| Table 9: Recommendations to Address Current Site Issues | |
| | |

Figures

| Figure 1: Site Location Map | 12 |
|---|----|
| Figure 2: Detailed Site Map | 13 |
| Figure 3: Florida Ground Water Delineated Area Map | 25 |
| Figure 4. TCE Concentrations, Well MW-4S | 26 |
| Figure 5. 1,2-DCE Concentrations, Wells MW-4S and MW-16 | 27 |
| Figure 6. Vinyl Chloride Concentrations in Wells with MCL Exceedances | 28 |

List of Acronyms

| ARAR | Applicable or Relevant and Appropriate Requirement |
|---------|--|
| CERCLA | Comprehensive Environmental Response, Compensation and Liability Act |
| CIC | Community Involvement Coordinator |
| CFR | Code of Federal Regulations |
| COC | Contaminant of Concern |
| 1,2-DCE | cis-1,2-Dichloroethene |
| EPA | United States Environmental Protection Agency |
| ESD | Explanation of Significant Differences |
| FDEP | Florida Department of Environmental Protection |
| FDER | Florida Department of Environmental Regulation |
| FYR | Five-Year Review |
| IC | Institutional Control |
| MCL | Maximum Contaminant Level |
| μg/L | micrograms per liter |
| MW | Monitoring Well |
| NCP | National Oil and Hazardous Substances Pollution Contingency Plan |
| NPL | National Priorities List |
| O&M | Operation and Maintenance |
| OU | Operable Unit |
| PRP | Potentially Responsible Party |
| RA | Remedial Action |
| RAO | Remedial Action Objective |
| RD | Remedial Design |
| RI/FS | Remedial Investigation/Feasibility Study |
| ROD | Record of Decision |
| RPM | Remedial Project Manager |
| TCE | Trichloroethene |
| UST | Underground Storage Tank |
| UVB | Unterdruck-Verdampfer-Brunnen |
| VBWSD | Vero Beach Water & Sewer Department |
| VISL | Vapor Intrusion Screening Level |
| VOC | Volatile Organic Compound |

Executive Summary

The Piper Aircraft Corp./Vero Beach Water & Sewer Department Superfund site (the Site) is located near the eastern coast of central Florida, in the City of Vero Beach, Indian River County. Ground water beneath the Site is contaminated primarily by volatile organic compounds (VOCs), trichloroethene (TCE) and its degradation products, cis-1, 2-dichlorothene (1,2-DCE), 1, 1dichloroethene and vinyl chloride. The contamination came from an underground storage tank (UST) leaking TCE. The surrounding area is primarily commercial and industrial properties.

The United States Environmental Protection Agency (EPA) addressed the Site as one Operable Unit (OU). EPA approved a remedy for the Site in a Record of Decision (ROD) signed on December 23, 1993. The remedy includes ex-situ treatment of ground water and institutional controls.

The ROD did not specifically spell out remedial action objectives (RAOs), but states that ground water treatment is intended to protect human health and the environment by reducing or preventing further migration of the contaminated ground water and by reducing the contaminant concentrations in ground water until the concentrations are less than or equal to the performance standards.

The remedial actions continue to operate and function as designed, though the contaminant levels are not yet below maximum contaminant levels (MCLs). The ground water treatment system continues to function as designed, but the potentially responsible party (PRP), has begun exploring opportunities for optimization to expedite cleanup, such as bioremediation. The Site's institutional controls have been established and are sufficient for preventing exposure to contaminated ground water.

The potential for vapor intrusion exists at the site, but no vapor intrusion assessment had been completed during the last five-year period. During this five-year review (FYR), the first level screening was completed using the most recent EPA vapor intrusion screening level (VISL) calculator and the maximum contaminant concentrations detected in December 2013. The results indicate the December 2013 concentrations do not exceed EPA's acceptable risk levels for commercial use. EPA and the PRPs are still considering additional methods to more precisely determine any potential vapor intrusion risk posed to the workers at the Site. Florida Department of Environmental Protection (FDEP) has also requested a direct-push technology system installation in Building #4 to optimize remedial efforts and ensure that cleanup eliminated all source materials.

The remedy currently protects human health and the environment, because exposure to contaminated ground water is prevented through the implementation of institutional controls and the first level screening of vapor intrusion indicated that current contaminant levels are within an acceptable risk range. However, in order for the remedy to be protective in the long term, a site-specific vapor intrusion assessment may still be needed to ensure protectiveness since the contaminant concentrations tend to fluctuate.

Five-Year Review Summary Form

| SITE IDENTIFICATION | | | | | | |
|--|----------|--|-----------------------|---|--|--|
| Site Name: | Piper Ai | Piper Aircraft Corp./Vero Beach Water & Sewer Department | | | | |
| EPA ID: | FLD004 | 054284 | | | | |
| Region: 4 | | State: Fl | L | City/County: Vero Beach/Indian River County | | |
| | | | Sľ | TE STATUS | | |
| NPL Status: | Final | | | | | |
| Multiple OUs No | ? | | Has the Yes | e site achieved construction completion? | | |
| | | | REV | IEW STATUS | | |
| Lead agency: EPA If "Other Federal Agency" selected above, enter Agency name: N/A | | | | | | |
| Author name: Ryan Burdge and Sarah Alfano (Reviewed by EPA) | | | | | | |
| Author affiliation: Skeo Solutions | | | | | | |
| Review period: 10/2013 – 5/2014 | | | | | | |
| Date of site inspection: 1/7/2014 | | | | | | |
| Type of review: Policy | | | | | | |
| Review number: 3 | | | | | | |
| Triggering action date: 05/05/2009 | | | | | | |
| Due date (five years after triggering action date): 05/05/2014 | | | | | | |

Five-Year Review Summary Form (continued)

Issues/Recommendations

Issues and Recommendations Identified in the Five-Year Review:

| OU 1: Click here | Issue Category: F | Remedy Performar | ice | | | |
|----------------------------------|--|-----------------------|--------------------|----------------|--|--|
| to enter text. | Issue: The PRPs assessment. | or intrusion | | | | |
| | Recommendation: Conduct a site-specific vapor intrusion assessment in accordance with the most recent EPA vapor intrusion guidance. | | | | | |
| Affect Current Protectiveness | Affect Future Protectiveness | Implementing Party | Oversight Party | Milestone Date | | |
| No | Yes | PRP | EPA | 5/12/2015 | | |

| Sitewide Protectiveness Statement | | | | |
|--|---|--|--|--|
| Protectiveness Determination: Short-term Protective | Addendum Due Date (if applicable): N/A | | | |
| Protectiveness Statement: | | | | |

Protectiveness Statement:

The remedy currently protects human health and the environment, because exposure to contaminated ground water is prevented through the implementation of institutional controls and the first level screening of vapor intrusion indicated that current contaminant levels are within an acceptable risk range. However, in order for the remedy to be protective in the long term, a site-specific vapor intrusion assessment may still be needed to ensure protectiveness since the contaminant concentrations tend to fluctuate.

Five-Year Review Summary Form (continued)

Environmental Indicators

-Current human exposures at this site are under control. -Contaminated ground water migration is under control.

Are Necessary Institutional Controls in Place?

All 🗌 Some 🗌 None

Has EPA Designated the Site as Sitewide Ready for Anticipated Use?

🛛 Yes 🗌 No

Has the Site Been Put into Reuse?

Yes INO (Site remains in continued industrial use by Piper Aircraft)

Third Five-Year Review Report for Piper Aircraft Corp./Vero Beach Water and Sewer Department Superfund Site

1.0 Introduction

The purpose of a five-year review (FYR) is to evaluate the implementation and performance of a remedy in order to determine if the remedy will continue to be protective of human health and the environment. FYR reports document FYR methods, findings and conclusions. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The United States Environmental Protection Agency (EPA) prepares FYRs pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) Section 121 and the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). CERCLA Section 121 states:

If the President selects a remedial action that results in any hazardous substances, pollutants, or contaminants remaining at the site, the President shall review such remedial action no less often than each 5 years after the initiation of such remedial action to assure that human health and the environment are being protected by the remedial action being implemented. In addition, if upon such review it is the judgment of the President that action is appropriate at such site in accordance with section [104] or [106], the President shall take or require such action. The President shall report to the Congress a list of facilities for which such review is required, the results of all such reviews, and any actions taken as a result of such reviews.

EPA interpreted this requirement further in the NCP, 40 Code of Federal Regulations (CFR) Section 300.430(f)(4)(ii), which states:

If a remedial action is selected that results in hazardous substances, pollutants, or contaminants remaining at the site above levels that allow for unlimited use and unrestricted exposure, the lead agency shall review such action no less often than every five years after initiation of the selected remedial action.

Skeo Solutions, an EPA Region 4 contractor, conducted the FYR and prepared this report regarding the remedy implemented at the Piper Aircraft Corp./Vero Beach Water and Sewer Department Superfund site (the Site) in Vero Beach, Indian River County, Florida. EPA Region 4's contractor conducted this FYR from October 2013 to May 2014. EPA is the lead agency for developing and implementing the remedy for the potentially responsible party (PRP) financed cleanup at the Site. FDEP, as the support agency representing the State of Florida, has reviewed all supporting documentation and provided input to EPA during the FYR process.

This is the third FYR for the Site. The triggering action for this policy review is the previous FYR, signed on May 5, 2009. The FYR is required due to the fact that hazardous substances, pollutants or contaminants remain at the Site above levels that allow for unlimited use and unrestricted exposure. The Site consists of one operable unit (OU), which is addressed in this FYR report.

2.0 Site Chronology

Table 1 lists the dates of important events for the Site.

Table 1: Chronology of Site Events

| Event | Date | |
|--|--------------------|--|
| Piper Aircraft Corporation (Piper Aircraft) installed a trichloroethene (TCE) tank | 1975 | |
| and supply system on site | | |
| Vero Beach Water & Sewer Department (VBWSD) detected TCE in municipal | October 1978 | |
| supply well, CVB-15 | | |
| City of Vero Beach and Piper Aircraft developed pump & treat system under | March 1979 | |
| Florida Department of Environmental Regulation (FDER) oversight | | |
| Site operators installed a dewatering well | August 1, 1980 | |
| Piper Aircraft signed Consent Agreement for remediation of TCE. Pump-and- | October 1981 | |
| treat system operations began. | | |
| FDEP began preliminary assessment | October 1, 1984 | |
| EPA proposed the Site to the National Priorities List (NPL) | June 10, 1986 | |
| Piper Aircraft removed the underground storage tank (UST) and contaminated | June 1989 | |
| soil in the spill area, treated the soil, and returned it to the excavated area | | |
| EPA finalized the Site on the NPL | February 21, 1990 | |
| EPA notified Piper Aircraft of potential liability and necessary investigative | October 21, 1991 | |
| activities at the Site | | |
| EPA-lead remedial investigation/feasibility study (RI/FS) and risk assessment | April 29, 1992 | |
| began | | |
| EPA conducted an ecological risk assessment and human health risk assessment | July 15, 1993 | |
| EPA-lead RI/FS concluded and EPA signed a Record of Decision (ROD) | December 23, 1993 | |
| EPA began remedial design (RD) | September 22, 1994 | |
| EPA-lead RD concluded and Piper began RD for an improved ground water | December 11, 1995 | |
| remediation system | | |
| Piper Aircraft signed a Consent Decree with EPA to implement the selected | July 16, 1996 | |
| remedy | | |
| Piper Aircraft completed RD and began remedial action | September 30, 1997 | |
| Piper Aircraft completed installation of in-situ vertical circulation systems (UVB | January 23, 1998 | |
| wells) | | |
| Piper Aircraft completed UVB well development | January 26, 1998 | |
| EPA issued the Preliminary Close-Out Report | September 21, 1998 | |
| Piper Aircraft concluded remedial action and began developing a Long-Term | March 3, 2000 | |
| Response Action | | |
| EPA signed the first FYR report | May 13, 2004 | |
| Piper Aircraft submitted an initial proposal for a Bioremediation Pilot Study | May 27, 2004 | |
| Hurricane Frances forced the UVB wells to shut down | September 3, 2004 | |
| Hurricane Jeanne forced the UVB wells to shut down | October 29, 2004 | |
| Piper Aircraft submitted a revised proposal for a Bioremediation Pilot Study | September 23, 2005 | |
| Hurricane Wilma forced the UVB-1A well to shut down | October 2005 | |
| Piper Aircraft submitted Bioremediation Pilot Study Phase One Activities Report | May 1, 2008 | |
| Piper Aircraft submitted Bioremediation Pilot Study Phase Two Activities | January 30, 2009 | |
| Report (Revised) | • | |
| EPA signed the second FYR report | May 5, 2009 | |
| EPA issued an Explanation of Significant Differences (ESD) to the 1993 ROD | September 28, 2009 | |

3.0 Background

3.1 Physical Characteristics

The approximately 80-acre Site is located at 2926 Piper Drive, in the City of Vero Beach, Indian River County, Florida, about five miles from the Atlantic Ocean (Figure 1). The Indian River is approximately two miles east of the Site. The property includes several buildings used for manufacturing of general aviation aircraft and aircraft parts, storage, training and administrative purposes (Figure 2).

A trichloroethene (TCE) underground storage tank (UST) located on the Site property since 1975 contaminated site ground water. The UST and surrounding soils were excavated and removed in 1989. The Site spans one property parcel (3239340000400000001.0), but the contaminated ground water plume historically extended beyond this parcel boundary to the southeast. The City of Vero Beach (the City) operates a municipal well field in the area, and the Vero Beach Water Supply Well CVB-15 is located across Aviation Boulevard, 300 feet downgradient from the southern boundary of the Site (Figure 2). The City detected TCE contamination in CVB-15 in October 1978.

Due to well CVB-15 influence, ground water at the Site flows toward that well. The surficial aquifer beneath the Site exists in a layered sequence of permeable, silty sands and clay aquitards. As a result, the surficial aquifer exists under semi-confined water table to semi-artesian conditions. The surficial aquifer within the vicinity of the Site has an average depth of eight feet below surface and a saturated thickness of approximately 87 feet.

3.2 Land and Resource Use

Several buildings compose the Piper Aircraft, Inc. complex. The company uses these buildings for manufacturing and assembly of general aviation aircraft and aircraft parts, painting, storage, training and administrative purposes. Manufacturing operations at the facility are ongoing. The surrounding areas are zoned for commercial, industrial and residential use, and the land use is not expected to change.

Vero Beach Water & Sewer Department (VBWSD) provides potable water as well as sewage treatment and disposal for residents of Vero Beach. The Site lies on the southeastern section of the municipal well field. Municipal supply well CVB -15 is the closest downgradient municipal well in the plume. The operation of this well is continuous, with the exception of down time for routine maintenance or at the request of Piper Aircraft. The well operation also fluctuates depending on water demands of the City. The City treats all water pumped for potable water sources to acceptable levels before releasing it into the distribution system.





Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site.

Figure 2: Detailed Site Map



Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site.

3.3 History of Contamination

In October 1978, VBWSD detected TCE in municipal water well CVB-15, located 1,050 feet southeast and downgradient of Piper Aircraft's 5,000-gallon TCE storage tank. In October 1978, samples of shallow ground water adjacent to the UST revealed a TCE concentration of 39,000 micrograms per liter (μ g/L). Investigations by the City and Piper Aircraft determined that TCE leaked from a malfunctioning fitting on the UST. Investigations could not determine the duration and rate of leakage.

3.4 Initial Response

Promptly after VBWSD detected TCE in CVB-15 and traced it back to the Piper Aircraft tank, VBWSD discontinued use of well CVB-15 and Piper Aircraft removed the TCE from the UST. Six months later, the City developed two other wells, CVB-19 and CVB-20, to replace non-operational CVB-15. CVB-15 is now used as needed.

In March 1979, VBWSD and Piper Aircraft, with assistance from FDEP, installed a sixinch diameter ground water extraction well adjacent to the tank site for remediation at the source area. The pumping rate was approximately 200 gallons per minute. Extracted water was discharged via a mile-long pipeline to a spray-header assembly installed across a flood control canal. Between April 1981 and February 1992, the extraction well removed approximately 1,162 pounds of contaminants.

In October 1981, Piper Aircraft signed a Consent Agreement with FDEP for continuing the remediation of the TCE contamination levels via ground water extraction. On June 10, 1986, EPA proposed the Site for inclusion on the National Priorities List (NPL), and by March 1988, EPA completed a site inspection.

Piper Aircraft removed the TCE storage tank and excavated soil to a depth of 14 feet below land surface in June 1989. A total of 740 cubic yards of TCE-contaminated soils were landfarmed, an above-ground remediation technology for soils that reduces concentrations of petroleum constituents through biodegradation.

3.5 Basis for Taking Action

EPA finalized the Site on the NPL on February 21, 1990 and conducted a removal assessment in October 1991. EPA began the remedial investigation/feasibility study (RI/FS) on August 3, 1992, and collected 34 ground water samples. Investigations found TCE and its degradation products, cis-1,2-dichlorothene (1,2-DCE), 1,1-dichloroethene and vinyl chloride, in the ground water beneath the Site.

The baseline risk assessment indicated a cumulative potential residential carcinogenic risk level of 1.1×10^{-3} . The two media pathways responsible for this risk level are ground water and air. The ground water risk (3.9×10^{-4}) is due to the presence of vinyl chloride.

The air pathway risk (6.8×10^{-4}) is due to the presence of 1,1- dichloroethene near the spray treatment nozzle. The exposure to surface water and sediments and the ingestion of fish did not produce unacceptable risk levels.

Several contaminant levels exceeded federal maximum contaminant levels (MCLs) and warranted remediation, including TCE, cis-1,2-dichloroethene, 1,1-dichloroethene, and vinyl chloride.

4.0 Remedial Actions

In accordance with CERCLA and the NCP, the overriding goals for any remedial action are protection of human health and the environment and compliance with applicable or relevant and appropriate requirements (ARARs). A number of remedial alternatives were considered for the Site, and final selection was made based on an evaluation of each alternative against nine evaluation criteria that are specified in Section 300.430(e) (9) (iii) of the NCP. The nine criteria are:

- 1. Overall Protection of Human Health and the Environment.
- 2. Compliance with ARARs.
- 3. Long-Term Effectiveness and Permanence.
- 4. Reduction of Toxicity, Mobility or Volume through Treatment.
- 5. Short-Term Effectiveness.
- 6. Implementability.
- 7. Cost.
- 8. State Acceptance.
- 9. Community Acceptance.

4.1 Remedy Selection

EPA issued the Record of Decision (ROD) for the Site on December 23, 1993, selecting a remedy for contaminated ground water.

The ROD did not specifically spell out remedial action objectives, but Section 10.1 of the ROD states:

The ground water treatment component of the selected remedy will protect human health and the environment by reducing or preventing further migration of the contaminated ground water and by reducing the contaminant concentrations in ground water until the concentrations are less than or equal to the performance standards. Compliance with MCLs will be protective at this site. The long-term cancer risk associated with possible ingestion of the ground water will be reduced to within EPA's acceptable risk range of 1×10^{-4} and 1×10^{-6} and the non-carcinogenic risk would be reduced to the EPA goal of 1.

EPA selected ex-situ treatment of ground water with surface water discharge as the remedy for the Site. The remedy components included:

- Ground water withdrawal using extraction wells.
- Treatment of ground water via air stripping.
- Discharge of treated effluent to surface water.
- If necessary, treatment of air emissions.

Table 2 presents the cleanup goals specified in the 1993 ROD.

| Ground Water COC | ROD Cleanup Goal (µg/L) |
|--------------------|-------------------------|
| TCE | 3.0 |
| 1,2-DCE | 70.0 |
| 1,1-dichloroethene | 7.0 |
| Vinyl chloride | 1.0 |

Table 2: Ground Water Contaminant of Concern (COC) Cleanup Goals

EPA issued an Explanation of Significant Differences (ESD) in 2009 to document the approval of an alternate treatment technology and to require institutional controls to restrict ground water use. The alternate treatment technology consists of a proprietary inwell aeration and stripping system, called an Unterdruck-Verdampfer-Brunnen (UVB) vacuum vaporizing well system. The UVB system pumps contaminated water from the ground, treats the water with an air stripper just below the ground surface at the location of the well, and then pumps the treated water back into the ground at that same location.

4.2 Remedy Implementation

EPA began the remedial design (RD) process on September 22, 1994. Piper Aircraft entered into a consent decree with EPA on November 7, 1995, requiring Piper Aircraft to complete the RD and implement the selected remedy.

The PRP-led RD and focused feasibility study concluded in June 1997, and Piper Aircraft requested that EPA approve the use of the UVB system. EPA agreed to the PRP-proposed alternate technology approach, and Piper incorporated the UVB wells into the RD. The RD phase concluded on September 30, 1997. Piper Aircraft initiated the UVB system in January 1998.

EPA approved another system improvement project engineered in 2001, because well UVB-1 had not recovered significant quantities of contaminated ground water to date. The PRPs constructed well UVB-1A over a monitored "hot spot" of residual contamination near monitoring well 14 (MW-14). A redeveloped well UVB-1 would remove soft iron deposits from the deeper screen section and accept treated effluent originating from well UVB-1A. An aboveground aeration system replaced UVB-2 in November 2001.

With the approval of EPA in 2007, Piper Aircraft has begun investigations to determine if bioremediation would expedite ground water remediation with special regard to treatment of the TCE source area. A proposal to move forward with implementation is currently under review with EPA considering the possibility of adding a second component to address the persistent vinyl chloride contamination.

4.3 **Operation and Maintenance (O&M)**

Two recovery wells, have been in operation since December 1998. Since July 2001, well UVB-1A has replaced UVB-1 as a contaminant recovery well and UVB-1 is used as a return well for treated ground water effluent.

During the past five years, the recovery wells have operated continuously with the exception of brief periods of down time due to system maintenance. During the 3rd and 4th quarters of 2010, well UVB-1A did not operate due to repairs/replacement of the aerator blower and motor assemblies. Well UVB-1A also did not operate continuously during the 3rd quarter 2011 due to system repairs and well redevelopment. Well UVB-2 did not operate during the 2nd quarter 2012 due to well redevelopment and pump replacement.

Piper personnel collect influent and effluent samples from the recovery wells on a quarterly basis with the results presented in quarterly UVB systems operation reports. An independent laboratory analyzes samples for volatile organic compounds (VOCs). Piper personnel collect ground water level measurements semi-annually and collect ground water samples from select wells either semi-annually or annually for VOC analysis by an independent laboratory. The quarterly reports present the results of these data.

Piper Aircraft inspects the monitoring wells weekly as part of routine facility maintenance. Staff also replace and repair remedial components on a timely as-needed basis.

The ROD estimated that O&M could cost \$155,125 per year. Actual O&M expenses during the past five years appear in Table 4 below. Because O&M is performed by Piper Aircraft personnel, the costs below are for expenditures only and do not account for electricity expenses or labor. The actual O&M costs are presented in Table 3. For a more detailed breakdown of expenditures, refer to Appendix I.

| Year | Actual Costs | | |
|------|--------------|--|--|
| 2009 | \$39,000 | | |
| 2010 | \$24,000 | | |
| 2011 | \$11,000 | | |
| 2012 | \$9,000 | | |
| 2013 | \$7,000 | | |

Table 3: Annual O&M Costs

5.0 Progress since the Last Five-Year Review

The protectiveness statement from the 2009 FYR for the Site stated the following:

The remedy at the Piper Aircraft Vero Beach Site is protective of human health and the environment in the short-term because contaminated ground water is not being used for potable purposes without prior treatment, the treatment system is operating as expected, the newly identified benzene is found along the axis of the plume and can be treated by the remediation system, and Institutional Controls are in place. However, in order for the remedy to be protective in the long-term, the following actions are needed: review historic solvent usage areas to determine if there is another source area, evaluate the vapor intrusion pathway, and modify the ROD to include the requirement of Institutional Controls and document the changes in the treated water discharge. Although the remedy is protective, it may not be the most effective means of attaining cleanup goals and is therefore, being re-evaluated through the implementation of a bioremediation pilot study.

The 2009 FYR included nine issues and recommendations. This report summarizes each recommendation and its status below.

| Recommendations | Party Responsible | Milestone Date | Action Taken and Outcome | Date of Action |
|--|----------------------|-------------------|--|-------------------|
| Continue analyzing ground water samples for benzene | Piper Aircraft | 5/1/14 | Piper Aircraft has continued monitoring for benzene during the past five years. In summary, based on the lack of recent detections of benzene in ground water at the Site above MCLs, residual soil contamination, if any, does not appear to be acting as a continuing source of benzene contamination in ground water. See section 6.4 for more information. | Ongoing |
| Use direct-push technology to conduct an investigation to select the best location for an additional monitoring well east of MW-20 | Piper Aircraft | 5/1/10 | As noted by the 1992-1993 remedial investigation documents, remedial workers installed three temporary monitoring wells, TW-04, TW-05 and TW-06, east of the Site during Phase III of the remedial investigations at two depths, 40 feet below land surface and 80 feet below land surface. See Appendix F for related map. These wells did not detect COCs above MCLs. | 3/26/2009 |

Table 4: Progress on Recommendations from the 2009 FYR

| Recommendations | Party Responsible | Milestone Date | Action Taken and Outcome | Date of Action |
|---|----------------------|-------------------|---|-------------------|
| Use direct-push technology (mini drill rig) to conduct additional investigation inside the building(s) | Piper Aircraft | 5/1/10 | Piper Aircraft considered potential actions, but found that installing a mini drill rig would not be financially or structurally feasible. The FDEP representative noted during the site inspection that a system installation in Building #4 might be helpful and feasible. No installation actions occurred during this FYR period. EPA, FDEP and Piper Aircraft are currently working together to determine the best course of action for conducting additional source investigations. | 3/26/2009 |
| Review historic solvent use/storage areas and perform assessment where appropriate | Piper Aircraft | 5/1/10 | Piper Aircraft performed an in-house search for records and documents regarding historic solvent use, but did not find anything that would warrant additional assessment. | 3/26/2009 |
| Conduct vapor intrusion evaluation | Piper Aircraft | 5/1/11 | Piper Aircraft will conduct a vapor intrusion assessment and is reviewing indoor air-sampling reports to see if historic or recent reports have detected VOCs. | Ongoing |
| Modify the ROD to require institutional controls in the form of Florida Ground Water Delineation Area | EPA | 5/1/10 | EPA issued an ESD on September 28, 2009, to require institutional controls in the form of a Florida Ground Water Delineated Area until all COCs meet MCLs. | 9/28/2009 |
| Modify the ROD to document the change in the way treated water is discharged | EPA | 5/1/10 | EPA documented the change in treatment and discharge in an ESD on September 28, 2009. | 9/28/2009 |
| Continue implementation of bioremediation pilot study | Piper Aircraft | 5/1/14 | Piper Aircraft conducted the first two phases of a pilot study to employ bioremediation at the Site. The company's investigations suggested that Piper Aircraft use the maintenance yard as the location for further pilot studies. Piper Aircraft submitted this proposal to EPA in January 2009. | 1/30/2009 |
| Reduce sampling frequency from semi- annually to annually for the following wells: MW-2(89), MW4(1), MW-4(D), MW-6(S), MW-6(0), MW-7, MW- 10, MW-11, MW-12, MW-14(S), MW-15, MW-18 | Piper Aircraft | 5/1/10 | Piper Aircraft implemented the suggested reduced sampling frequency, but has not updated the O&M plan to reflect these changes. | 6/2009 |

6.0 Five-Year Review Process

6.1 Administrative Components

EPA Region 4 initiated the FYR in October 2013 and scheduled its completion for May 2014. The EPA remedial project manager (RPM) Shelby Johnston led the EPA site review team, which also included the EPA site attorney Elisa Roberts, the EPA community involvement coordinator (CIC) L'Tonya Spencer and contractor support provided to EPA by Skeo Solutions. The review schedule established consisted of the following activities:

- Community notification.
- Document review.
- Data collection and review.
- Site inspection.
- Local interviews.
- FYR Report development and review.

6.2 Community Involvement

In January 2014, EPA published a public notice in the *Vero Beach News Weekly* newspaper announcing the commencement of the FYR process for the Site, providing contact information for Shelby Johnston and L'Tonya Spencer and inviting community participation. The press notice is available in Appendix B. No one contacted EPA as a result of the advertisement.

EPA will make the final FYR Report available to the public. Upon completion of the FYR, EPA will place copies of the document in the designated site information repository: Indian River County Main Library, located at 1600 21st Street, Vero Beach, Florida, 32960.

6.3 Document Review

ARARs Review

CERCLA Section 121(d)(1) requires that Superfund remedial actions attain "a degree of cleanup of hazardous substance, pollutants, and contaminants released into the environment and of control of further release at a minimum which assures protection of human health and the environment." The remedial action must achieve a level of cleanup that at least attains those requirements that are legally applicable or relevant and appropriate.

• Applicable requirements are those cleanup standards, standards of control, and other substantive requirements, criteria, or limitations promulgated under federal environmental or state environmental or facility siting laws that specifically

address a hazardous substance, remedial action, location, or other circumstance found at a CERCLA site.

- Relevant and appropriate requirements are those standards that, while not "applicable," address problems or situations sufficiently similar to those encountered at the CERCLA site that their use is well suited to the particular site. Only those state standards that are more stringent than federal requirements may be applicable or relevant and appropriate.
- To-Be-Considered criteria are non-promulgated advisories and guidance that are not legally binding, but should be considered in determining the necessary remedial action. For example, To-Be-Considered criteria may be particularly useful in determining health-based levels where no ARARs exist or in developing the appropriate method for conducting a remedial action.

Chemical-specific ARARs are health- or risk-based numerical values or methodologies which, when applied to site-specific conditions, result in the establishment of numerical values. These values establish an acceptable amount or concentration of a chemical that may remain in, or discharged to, the ambient environment. Examples of chemicalspecific ARARs include MCLs under the federal Safe Drinking Water Act and ambient water quality criteria enumerated under the federal Clean Water Act.

Action-specific ARARs are technology- or activity-based requirements or limits on actions taken with respect to a particular hazardous substance. These requirements are triggered by a particular remedial activity, such as discharge of contaminated ground water or in-situ remediation.

Location-specific ARARs are restrictions on hazardous substances or the conduct of the response activities solely based on their location in a special geographic area. Examples include restrictions on activities in wetlands, sensitive habitats and historic places.

Remedial actions are required to comply with the chemical-specific ARARs identified in the ROD. In performing the Five-Year Review for compliance with ARARs, only those ARARs that address the protectiveness of the remedy are reviewed.

Ground Water ARARs

According to the 1993 ROD, the ground water ARARs are the National Primary Drinking Water Standards and Florida Drinking Water Standards. The Florida Primary Drinking Water Standards are the same as the Federal Primary Drinking Water Standards, except for TCE and vinyl chloride. The Florida standards are more stringent than the federal standards for those two contaminants, and are therefore considered the ARARs. As shown in Table 5, drinking water standards have not changed since the remedy selection.

| COCs ^a | 1993 ROD MCL ^b (μg/L) | Current (2013) MCL ^c (µg/L) | ARAR Changes | | | |
|--------------------|--|--|--------------|--|--|--|
| TCE | 3.0 ^d | 3.0 ^d | None | | | |
| 1,1-dichloroethene | 7.0 | 7.0 | None | | | |
| 1,2-DCE | 70.0 | 70.0 | None | | | |
| Vinyl chloride | 1.0 ^e | 1.0 ^e | None | | | |

Table 5: Previous and Current ARARs for Ground Water COCs

a. COCs as identified in the site's 1993 remedial investigation.

b. The 1993 ROD listed both the current federal and Florida Maximum Contamination Levels (MCLs) as ground water ARARs. The ARAR values listed in this column are the more stringent values of the two MCL values.

c. This review examined both the current federal and Florida MCLs. The ARAR value listed is the more stringent of the two MCL values. The source for the National Primary and Secondary Drinking Water Maximum Contamination Levels (MCLs) is <u>http://water.epa.gov/drink/contaminants/index.cfm</u> (accessed on 12/2/2013). State standards are based on Florida State Primary Drinking Water MCLs:

http://www.dep.state.fl.us/water/drinkingwater/vol_con.htm (accessed on 12/2/2013).

d. The less stringent federal MCL for TCE is 5.0 micrograms per liter ($\mu g/L$).

e. The less stringent federal MCL for vinyl chloride is 2.0 micrograms per liter (μ g/L).

Surface Water

The 2009 ESD modified the ground water remedy to omit the surface water discharge component. Therefore, there are no current surface water ARARs.

Soil ARARs

The 1993 ROD did not establish soil ARARs.

Institutional Control Review

By issuing the ESD in 2009, EPA required institutional controls in the form of the Florida Ground Water Delineated Area designation. FDEP and the water management district monitor well construction and require all users within the area to connect to the city water system for potable water. The ROD stated that in 1989, Piper removed contaminated soil surrounding an UST, with oversight by the Florida Department of Environmental Regulation (now FDEP) According to EPA's 1992 confirmatory soil sampling, there was no indication of any remaining soil contamination; therefore, land use controls are not necessary. Table 6 lists the institutional controls associated with the Site. Figure 3 shows the relevant Florida Delineated Ground Water Area.

| Area of Interest – Site-Wide (Parcel: 3239340000400000001.0) | | | | | | | |
|---|---------------|---|----------------------------|--|---|--|--|
| Media | ICs Needed | ICs Called for in the Decision Documents | Impacted Parcel(s) | IC Objective | Instrument in Place | | |
| Ground Water | Yes | Yes, 2009 ESD document required institutional controls in the form of a ground water delineated area as part of the ground water remedy. | 32393400004 000000001.0 | Restrict installation of ground water wells and ground water use. | The Site and a buffer zone around the perimeter are located within a Florida Delineated Ground Water Area, in which well placement is restricted. ¹ | | |
| 1. Florida's ground water delineation information is available online at: | | | | | | | |
| http://www.dep.state.fl.us/water/ground water/delineate.htm. | | | | | | | |

Table 6: Institutional Control (IC) Summary Table



Figure 3: Florida Ground Water Delineated Area Map

Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site.

6.4 Data Review

Ground Water

Piper Aircraft personnel collect ground water samples from select wells either semiannually or annually for VOC analysis. Piper Aircraft personnel also collect samples of influent and effluent from the treatment system on a quarterly basis for VOC analysis.

The data review included quarterly reports dated June 2009 through December 2013. During this period, detected concentrations of TCE, 1,2-DCE, vinyl chloride and benzene exceeded current MCLs in one or more samples. Concentrations of 1,1-dichloroethene did not exceed its MCL in any sampling event during the evaluation period.

Appendix G also presents a summary of ground water analytical data for those wells that had at least one COC concentration above the applicable cleanup goal. Appendix H includes a map of well concentrations.

TCE

During the evaluation period, only one monitoring well (MW-4S) contained TCE at or above the cleanup goal of 3 μ g/L. TCE concentrations in MW-4S exceeded the cleanup goal in every sampling event during the evaluation period. MW-4S is located in the outer maintenance yard, approximately 250 feet downgradient of the former underground storage tank that historically contained TCE. Figure 4 illustrates the concentrations of TCE in MW-4S.



Figure 4. TCE Concentrations, Well MW-4S

The cause of the increase in TCE concentrations in MW-4S in December 2010 and June 2011 is unknown; however, it does appear to correlate with the lowest recorded ground water levels during the evaluation period. It should also be noted that pumping well

UVB-1, which is located in close proximity to MW-4S, did not operate during the third and fourth quarter of 2010 due to blower unit replacement. MW-4S may have been experiencing rebound conditions during December 2010 and June 2011. TCE was not detected in any of the influent samples (UVB-1A or UVB-2) during the evaluation period.

1,2-DCE

During the evaluation period, two monitoring wells (MW-4S and MW-16) had 1,2-DCE concentrations at or above the cleanup goal of 70 μ g/L. MW-4S is located in the outer maintenance yard, approximately 250 feet downgradient of the former UST that historically contained TCE. MW-16 is located within Building 5, downgradient of MW-4S. Figure 5 illustrates the concentrations of 1,2-DCE in MW-4S and MW-16 during the evaluation period. Concentrations of 1,2-DCE in MW-4S spiked in 2010 and 2011 and have since declined in the past four sampling evens.



Figure 5. 1,2-DCE Concentrations, Wells MW-4S and MW-16

1,2-DCE was detected in both of the influent samples (UVB-1A or UVB-2) during the evaluation period at concentrations below the cleanup goal. The maximum detected influent concentration of 1,2-DCE was $36.3 \mu g/L$ in UVB-2 in March 2011.

Vinyl Chloride

During the evaluation period, vinyl chloride was detected above the cleanup goal of 1 μ g/L in twelve different wells. Figure 6 illustrates the concentrations of vinyl chloride in those wells where concentrations exceeded the cleanup goal at least once during the evaluation period. The maximum detected concentration of vinyl chloride was 62.5 μ g/L in MW-23-I2 in June 2010. Vinyl chloride was also detected above the cleanup goal for the first time in deeper well MW-23D at a concentration of 2.6 μ g/L during the December 2012 sampling event. In general, vinyl chloride concentrations at the Site have fluctuated over time with no apparent trends.



Figure 6. Vinyl Chloride Concentrations in Wells with MCL Exceedances

Vinyl chloride has also been detected above cleanup goals in the influent samples. The maximum detected concentration of vinyl chloride in UVB-1A is $3.7 \ \mu g/L$ (June 2009). Vinyl chloride has not been detected in UVB-1A in recent sampling events (December 2012 and June 2013). The maximum detected concentration of vinyl chloride in UVB-2 is 75.4 $\mu g/L$ (March 2011). Vinyl chloride was detected at 19.4 $\mu g/L$ and 14.7 during the two most recent sampling events at UVB-2 (October and December 2013, respectively).

Benzene

Although not a COC, samples are tested for benzene. The June 2011 sample from MW-1 exceeded the federal MCL for benzene (5 μ g/L). In addition, three samples from MW-1 contained benzene above the state MCL (1 μ g/L) in the December 2011, June 2012 and June 2013 sampling event. Benzene was not detected in MW-1 in the December 2013 sampling event.

City of Vero Beach Municipal Supply Well

1,2-DCE and vinyl chloride were detected in CVB-15 during the evaluation period; however, only vinyl chloride exceeded its cleanup goal. 1,1-dichloroethene and TCE were not detected in CVB-15 during any of the sampling events conducted during the evaluation period.

The concentrations of COCs in this well have been reduced since the original sampling in 1979. During the current evaluation period, concentrations of 1,2-DCE have fluctuated between non-detect and a maximum detection of $33.1 \,\mu$ g/L in December 2012. Concentrations of vinyl chloride have fluctuated between non-detect and a maximum detection of 6 μ g/L in June 2010.

6.5 Site Inspection

The FYR site inspection occurred on January 7, 2014. The attendees were:

- John Sykes III, FDEP, Environmental Specialist III
- John Ten Eyck, VBWSD Assistant Director
- Todd Wegenast, Piper Aircraft, Senior Environmental Health and Safety Manager
- Lars Persson, Piper Aircraft, Professional Geologist
- Ryan Burdge and Sarah Alfano, Skeo Solutions, EPA contractors

Shelby Johnston, EPA RPM, Samantha Urquhart-Foster, EPA RPM, and L'Tonya Spencer, EPA CIC, were unable to attend the site inspection. Piper Aircraft staff members John Bowman and Tony Cotrell attended portions of the site inspection and site tour. The site inspection checklist is included in Appendix D of this FYR report. Photographs from the site inspection are located in Appendix E.

During the initial part of the site inspection, on-site participants and Shelby Johnston (by telephone) met in a conference room to discuss the Site's remedial components and the status of the 2009 FYR recommendations. Then site inspection participants proceeded by foot to tour the manufacturing and storage buildings for the purposes of inspecting the pumping and monitoring wells. All indoor and maintenance yard remedial components appeared secure, in good condition and clearly labeled. Piper Aircraft staff also pointed out various geoprobe locations and components from Phase 1 and Phase 2 of the bioremediation project. FDEP representative John Sykes III noted during the inspection that Building #4 seemed large enough to accommodate equipment needed for subsurface investigations requested in the 2009 FYR. Outdoor monitoring well components appeared secure, in good condition and clearly labeled. City well CVB-15 appeared to be in good condition and Vero Beach representative John Ten Eyck did not voice concerns during the site inspection.

On January 7, 2014, Skeo Solutions staff visited the designated site information repository, Indian River County Main Library, as part of the site inspection. Contractors found site-related documents, including recent FYRs, the ROD and ESD as well as other remedial documents.

6.6 Interviews

The FYR process included interviews with parties affected by the Site, including the current landowners and regulatory agencies involved in Site activities or aware of the Site. The purpose was to document the perceived status of the Site and any perceived problems or successes with the phases of the remedy implemented to date. All of the interviews took place over email or phone after the site inspection. The section below summarizes the interview results. Appendix C provides the complete interviews.

Samantha Urquhart-Foster

Ms. Urquhart-Foster, EPA remedial project manager for the Site, believes the pump and treatment system appears to be effective at reducing contaminant concentrations in ground water, with the exception of MW-4S. The surrounding community relies on municipal water and therefore the contaminated ground water is not consumed by nearby residents.

Todd Wegenast

Mr. Todd Wegenast, Piper Aircraft, Inc. Senior Environmental Health and Safety Manager, believes the current remedial system is adequate for the protection of human health and the environment while not posing an undue financial burden on Piper Aircraft. He stated that Piper Aircraft and the City of Vero Beach have worked well together and that there have been no impacts on the surrounding community. He hopes to work with EPA and FDEP to close the project within the next five years.

John Ten Eyck

Mr. John Ten Eyck, VBWSD Assistant Director, has been involved with the cleanup since 1978 and stated he is well informed about the project. He reviews Piper Aircraft's sampling reports on a regular basis and feels confident in the status of the cleanup.

Resident #1

Resident #1 was unaware of the Site and is interested in learning more about the cleanup and current status.

Resident #2

Resident #2 is aware of the Site and is concerned about its impact on the area. He understands the City water serving the community is no contaminated.

7.0 Technical Assessment

7.1 Question A: Is the remedy functioning as intended by the decision documents?

The remedial actions continue to operate and function as designed. Contaminant concentrations have decreased over the years, but using current UVB technology, it may be difficult to bring all contaminant levels below MCLs within a reasonable time frame. Bioremediation is being considered to accelerate the cleanup.

O&M activities have maintained the effectiveness of the remedial actions as expected. Piper Aircraft inspects remedial components on an as-needed or weekly basis and makes repairs and replacements in a prompt manner. Over the past five years, Piper Aircraft has decreased the sampling frequency of several wells that consistently had contaminant levels below the MCL.

In September 2009, EPA issued an ESD to require institutional controls in the form of a Florida Ground Water Delineated Area until all COCs meet MCLs. FDEP and the water management district monitor well construction and require all users within the area to connect to the city water system for potable water. These institutional controls are sufficient and in place to prevent exposure to contaminated ground water.

7.2 Question B: Are the exposure assumptions, toxicity data, cleanup levels and remedial action objectives (RAOs) used at the time of remedy selection still valid?

Ground water cleanup goals are based on ARARs, all of which have remained the same. There have been no changes to exposure assumptions, toxicity data or RAOs that would call into question the ground water cleanup goals. Both on-site and off-site land use has remained the same over the past five years and site stakeholders do not anticipate those land uses to change.

During the last FYR, EPA recommended that Piper Aircraft perform a vapor intrusion evaluation to ensure that vapor intrusion is not an issue for workers within the on-site manufacturing buildings; Piper Aircraft has not yet performed an evaluation. EPA recently issued additional guidance recommending the use of multiple lines of evidence to evaluate the vapor intrusion pathway because this pathway is influenced by many variables, including the geology and hydrogeology of a site, building characteristics and seasonal changes.

For this FYR, the maximum contaminant concentrations detected in December 2013 were entered into the most recent EPA vapor intrusion screening level (VISL) calculator, integrating the most recent toxicity data (Table 7). The VISL calculator provides conservative estimates of risk and noncancer hazards, because the predicted indoor air concentrations are empirically based using conservative "generic" attenuation factors. These factors reflect worst-case conditions and do not take into account any site-specific conditions such as site soil strata, depth to water table, and building properties that may reduce the transport of vapors from ground water through the soil column. The calculator

was run to estimate indoor air risks using a ground water temperature of 25 degrees Celsius for the State of Florida, obtained from EPA's vapor intrusion guidance.¹ Monitoring data from shallow and intermediate ground water wells located near buildings were used to evaluate on-site worker exposure and hypothetical residential exposure.

The results indicate the December 2013 concentrations do not exceed EPA's acceptable risk levels for commercial land use. However, inputting the TCE concentrations in MW-4S for December 2009 through December 2011 caused exceedance of the VISL for acceptable noncancer Hazard Index of 1.0 for commercial land use during that time (Appendix G). EPA and the PRPs are still considering additional methods to more precisely determine any vapor intrusion risks posed to workers at the Site. One method currently being considered would include addition of the vinyl chloride and TCE to the analytes routinely monitored as a requirement for the personnel monitoring by the industrial hygiene standards. This type of sampling method would allow the concise analysis of what vapor if any the workers are being exposed to that may be attributed to the plume below the building.

| СОС | Maximum Ground Water Concentration in December 2013 | Ground Water Target Level | Calculated Indoor Air Concentration ^a | Vapor Intrusion Carcinogenic Risk | Vapor Intrusion Hazard | | | |
|--|---|------------------------------------|--|--|------------------------------|--|--|--|
| Commercial Scen | Commercial Scenario | | | | | | | |
| TCE | 21.7 µg/L (MW-4S) | 7.4 μg/L | $8.33 \mu g/m^3$ | 2.9x10 ⁻⁶ | 0.99 | | | |
| Vinyl chloride | 14.7 μg/L (UVB-2) | 2.5 μg/L | $17.4 \mu g/m^3$ | 6.0x10 ⁻⁶ | 0.38 | | | |
| Residential Scenario* | | | | | | | | |
| TCE | 21.7 μg/L (MW-4S) | 1.1 µg/L | $8.33 \mu g/m^3$ | 2.0×10^{-5} | 4.2 | | | |
| Vinyl chloride | 14.7 μg/L (UVB-2) | 0.14 µg/L | $17.4 \mu g/m^3$ | 1.0x10 ⁻⁴ | 0.16 | | | |
| a. EPA Vapor Intrusion Screening Level Calculator, June 2013 (<u>http://www.epa.gov/oswer/vaporintrusion/documents/VISL-Calculator.xlsm</u>) b. Bold indicates exceedance of EPA's acceptable risk. *The Residential scenario was evaluated for the future possible risk to residential inhabitants although the plant is expected to | | | | | | | | |

| Table 7. | Vanor | Intrusion | Screening_ | [evel / | Assessment |
|----------|-------|---------------|------------|----------|---------------|
| Table /. | vapor | 11111 1151011 | Screening- | | 1996991116111 |

The ground water monitoring plan does not include analysis for the presence of 1,4dioxane, a compound that is commonly used in industry as a stabilizer for chlorinated solvents. EPA will determine if additional sampling is necessary to determine if 1,4dioxane is present at the Site. Due to the institutional controls in place at the Site, the potential presence of 1,4-dioxane is not believed to affect human health and the environment.

¹ User's Guide for Evaluating Subsurface Vapor Intrusion into Buildings. The EPA's Office of Emergency and Remedial Response. February 2004 <u>http://www.epa.gov/oswer/riskassessment/airmodel/pdf/2004_0222_3phase_users_guide.pdf</u>.

7.3 Question C: Has any other information come to light that could call into question the protectiveness of the remedy?

There do not appear to be any new ecological risks associated with site use or site cleanup. There have not been any impacts from natural disasters noted since the hurricanes in 2003 and 2004.

7.4 Technical Assessment Summary

The remedial actions continue to operate and function as designed, though cleanup efforts have not lowered contaminant levels below MCLs. In general, contaminant levels have been going down since remedial actions began, but vinyl chloride levels consistently remain above the MCL at several monitoring wells. Using UVB technology, it may be difficult to bring all contaminant levels below MCLs within a reasonable period. Piper Aircraft has been investigating the use of bioremediation technologies to reduce remaining contaminant levels and will work with EPA and FDEP to implement these technologies. FDEP has also requested a direct-push technology system installation in Building #4 to optimize remedial efforts and ensure that cleanup eliminated all source materials. The Site's institutional controls are sufficient and in place to prevent exposure to contaminated ground water.

During the second FYR, EPA recommended that Piper Aircraft perform a vapor intrusion assessment, but Piper Aircraft has not performed an evaluation to ensure protectiveness. Further assessment may be needed to provide multiple lines of evidence to conclude that vapor intrusion is not posing unacceptable risk to on-site workers.

8.0 Issues

Table 8 summarizes the current site issues.

Table 8: Current Site Issues

| Issue | Affects Current Protectiveness? | Affects Future Protectiveness? |
|---|------------------------------------|-----------------------------------|
| The PRPs have not completed a site-specific vapor | No | Yes |
| intrusion assessment. | | |

9.0 Recommendations and Follow-up Actions

Table 9 provides recommendations to address the current site issues.

Table 9: Recommendations to Address Current Site Issues

| Issue | Recommendation / Follow-Up Action | Party Responsible | Oversight Agency | Milestone Date | Affects Protectiveness? | |
|-----------------|--------------------------------------|----------------------|---------------------|-------------------|----------------------------|--------|
| | | _ | | | Current | Future |
| The PRPs have | Conduct a site-specific | | | | | |
| not completed a | vapor intrusion assessment | | | | | |
| site-specific | in accordance with the | PRP | EPA | 05/12/2015 | No | Yes |
| vapor intrusion | most recent EPA vapor | | | | | |
| assessment. | intrusion guidance. | | | | | |
10.0 Protectiveness Statement

The remedy currently protects human health and the environment, because exposure to contaminated ground water is prevented through the implementation of institutional controls and the first level screening of vapor intrusion indicated that current contaminant levels are within an acceptable risk range. However, in order for the remedy to be protective in the long term, a site-specific vapor intrusion assessment may still be needed to ensure protectiveness since the contaminant concentrations tend to fluctuate.

11.0 Next Review

The next FYR will be due within five years of the signature/approval date of this FYR.

Appendix A: List of Documents Reviewed

Bio-Remediation Pilot Study, Phase Two Activities Report (Revised) for Piper Aircraft NPL Site – Piper Aircraft, Inc. Vero Beach, Florida. January 30, 2009.

Explanation of Significant Difference for Piper Aircraft/Vero Beach Water and Sewer Superfund Site. Vero Beach, Florida. September 28, 2009.

Final Construction Report for New Piper Aircraft, Inc. Superfund Site. Vero Beach, Florida. Prepared for New Piper Aircraft, Inc. December 4, 1998.

First Five-Year Review Report for Piper Aircraft Superfund Site. Vero Beach, Indian River County, Florida. May 13, 2004.

Notice to Property Owners of City of Vero Beach. FDEP. November 18, 2011.

NPL Site Narrative for Piper Aircraft/Vero Beach Water & Sewer. http://www.epa.gov/superfund/sites/nplsnl/n0400512.pdf. Accessed October 1, 2013.

Piper Aircraft – Vero Beach Water & Sewer, Piper Drive and Aviation Boulevard, HWC #026. Site Summary. FDEP. No Date Available.

Piper Aircraft Corp./Vero Beach Water and Sewer Dept. Region 4 Site Summary Profile. <u>http://www.epa.gov/region4/superfund/sites/npl/florida/piperacfl.html</u>. Accessed on October 1, 2013.

Proposed Plan Fact Sheet for the Explanation of Significant Differences to the Record of Decision for the Piper Aircraft/Vero Beach Water and Sewer Superfund Site. July 23, 2009.

Record of Decision. Piper Aircraft Corp./Vero Beach Water & Sewer Department. EPA ID: FLD004054284. OU 01. Vero Beach, FL. December 23, 1993.

Second Five-Year Review Report for Piper Aircraft Corp./ Vero Beach Water & Sewer Department Site. EPA ID: FLD004054284. Vero Beach, Indian River County, Florida. May 5, 2009.

Superfund Site Progress Profile for Piper Aircraft Corp./ Vero Beach Water & Sewer Department. <u>http://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0400512</u>. Accessed October 1, 2013.

U.S. Environmental Protection Agency Remedial Investigation. Piper Aircraft Vero Beach, Florida. 1992/1993.

O&M Reports

Eleventh Year, Second Quarter and June 2009 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Eleventh Year, Third Quarter and September 2009 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Eleventh Year, Fourth Quarter and December 2009 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Twelfth Year, First Quarter and March 2010 Operating Report. Piper Aircraft NPL Site- Piper Aircraft, Inc. Vero Beach, Florida.

Twelfth Year, Second Quarter and June 2010 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Twelfth Year, Third Quarter and September 2010 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Twelfth Year, Fourth Quarter and December 2010 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Thirteenth Year, First Quarter and March 2011 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida

Thirteenth Year, Second Quarter and June 2011 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Thirteenth Year, Third Quarter and September 2011 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Thirteenth Year, Fourth Quarter and December 2012 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fourteenth Year, First Quarter and March 2012 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fourteenth Year, Second Quarter and June 2012 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fourteenth Year, Third Quarter and September 2012 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fourteenth Year, Fourth Quarter and December 2013 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida Fifteenth Year, First Quarter and March 2013 Operating Report. Piper Aircraft NPL Site- Piper Aircraft, Inc. Vero Beach, Florida.

Fifteenth Year, Second Quarter and June 2013 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fifteenth Year, Third Quarter and September 2013 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Fifteenth Year, Fourth Quarter and December 2013 Operating Report. Piper Aircraft NPL Site-Piper Aircraft, Inc. Vero Beach, Florida.

Appendix B: Press Notice



The U.S. Environmental Protection Agency, Region 4 Announces a Five-Year Review for the Piper Aircraft Corp./Vero Beach Water & Sewer Department Superfund Site, Vero Beach, Indian River County, Florida

Purpose/Objective: EPA is conducting a Five-Year Review of the remedy for the Piper Aircraft Corp./Vero Beach Water & Sewer Department Superfund site (the Site) in Vero Beach, Florida. The purpose of the Five-Year Review is to make sure the selected cleanup actions effectively protect human health and the environment.

Site Background: The 80-acre Site is located on Piper Drive next to the Vero Beach municipal airport in east-central Florida. In 1975, Piper Aircraft Corporation began storing trichloroethene (TCE), a volatile organic compound (VOC), in an underground storage tank on site. A leak from the storage tank affected soils and a public well across the street from the Site. The City of Vero Beach discontinued use of the well. In 1989, cleanup crews removed the underground storage tank and dug up contaminated soil. Investigations showed the ground water was still contaminated with TCE and its degradation products. In 1990, EPA listed the Site on the Superfund program's National Priorities List (NPL).

Cleanup Actions: EPA selected a remedy to address contaminated ground water in the Site's December 1993 Record of Decision (ROD). It included extraction and treatment of ground water contaminated with VOCs. The selected remedy calls for remediation to continue until monitoring shows aquifer contaminant levels meet cleanup goals and ground water discharge meets surface water standards. EPA updated the remedy in 2009, including institutional controls and use of an in-well aeration/stripping system for more efficient ground water treatment.

Five-Year Review Schedule: The National Contingency Plan requires review of remedial actions that result in any hazardous substances, pollutants or contaminants remaining at the Site above levels that allow for unlimited use and unrestricted exposure every five years to ensure the protection of human health and the environment. The fourth Five-Year Review for the Site will be completed by May 2014.

EPA Invites Community Participation in the Five-Year Review Process: EPA is conducting this Five-Year Review to evaluate the effectiveness of the Site's remedy and to ensure that the remedy remains protective of human health and the environment. As part of the Five-Year Review process, EPA staff is available to answer any questions about the Site. Community

members who have questions about the Site or the Five-Year Review process, or who would like to participate in a community interview, are asked to contact:

| Samantha Urquhart-Foster, EPA Remedial Project Manager | L'Tonya Spencer, EPA |
|--|-----------------------|
| Community Involvement Coordinator | |
| Phone: (404) 562-8760 | Phone: (404) 562-8463 |
| (877) 178-3752 (toll-free) | |
| Email: <u>urquhart-foster.samantha@epa.gov</u> | Email: |
| spencer.latonya@epa.gov | |

Mailing Address: U.S. EPA Region 4, 61 Forsyth Street, S.W., 11th Floor, Atlanta, GA 30303-8960

Additional information is available at the Site's local document repository, located at Indian River County Main Library, 1600 21st Street, Vero Beach, Florida, 32960, and online at: <u>http://www.epa.gov/region4/superfund/sites/npl/florida/piperacfl.html</u>.

Appendix C: Interview Forms

Piper Aircraft Corp./Vero Beach Water & Sewer Department Superfund Site Five-Year Review Interview Questions

| Site Name: | Piper Air | craft Corp./Ve | ro Beach Water & | EPA ID No.: | FLD004054284 |
|----------------------|----------------|----------------------|----------------------|--------------------|--------------|
| | Sewer Der | <u>partment</u> | | | |
| Interviewer N | ame: <u>Sa</u> | arah Alfano | Affiliation: | <u>Skeo Soluti</u> | ons |
| Subject Name | : <u>Samar</u> | <u>ntha</u> | Affiliation: | EPA Regior | <u>n 4</u> |
| Urquhart-Fos | ter | | | | |
| Subject Conta | ict Inform | ation: <u>404-56</u> | 2-8760; Urquhart-Fos | ter.Samantha | @epa.gov |
| Interview For | mat: | Email | | | _ |

Interview Category: Remedial Project Manager (RPM)

1. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

The operation of the pump and treatment system appears to be effective at reducing contaminant concentrations in ground water. Over the past five years, concentrations of contaminants have generally decreased in all of the wells except for monitoring well MW-4(S). Piper conducts operations, maintenance and sampling activities as scheduled and/or needed. The property is in current use as an airplane manufacturing facility, which provides jobs to local residents.

2. What have been the effects of this Site on the surrounding community, if any?

The property is in current use as an airplane manufacturing facility, which has provided jobs to local residents. The surrounding community relies on municipal water and therefore the contaminated ground water is not consumed by nearby residents. I am not aware of the Site impacting the surrounding community negatively in recent years.

3. Are you aware of any complaints or inquiries regarding site-related environmental issues or remedial activities since the implementation of the cleanup?

I have not been involved with the Site since the beginning of the cleanup. However, in the past five years, only one individual has expressed concerns about how the Site impacted his former business which was located near the facility at the time the contamination was discovered in the ground water, three decades ago.

4. What is your assessment of the current performance of the remedy in place at the Site?

With the exception of the area of monitoring well MW-4(S), the remedy appears to be effective at decreasing contaminant concentrations throughout the contaminated ground water plume.

5. Are you comfortable with the status of the institutional controls at the Site? If not, what are the associated outstanding issues?

Yes

6. Are you aware of any community concerns regarding the Site or the operation and management of its remedy? If so, please provide details.

No. I am not aware of any community concerns regarding the current operations and management of the remedy. The only community member that has contacted EPA in recent years was discussed in response to question 3.

7. Do you have any comments, suggestions or recommendations regarding the management or operation of the Site's remedy?

No.

| Piper Aircraft Corp./Vero Beach Water | & Sewer De | epartment Superfund Site |
|---|--------------|---------------------------------|
| Site Name: <u>Piper Aircraft Corp./Vero Beach</u> | n Water & | EPA ID No.: <u>FLD004054284</u> |
| <u>Sewer Department</u> | | |
| Interviewer Name: <u>Sarah Alfano</u> | Affiliation: | Skeo Solutions |
| Subject Name: <u>John Ten Eyck</u> | Affiliation: | City of Vero Beach |
| Subject Contact Information: <u>JTenEyck@co</u> | vb.org | |
| Interview Format: Email | | |

Interview Category: Local Government

-

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date? Yes. I have been involved with the site since 1978.

2. Do you feel well-informed regarding the Site's activities and remedial progress? If not, how might EPA convey site-related information in the future?

Yes. The quarterly and annual reports submitted by Piper Aircraft provide the data necessary to assess the progress of the remediation.

- 3. Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing? N/A
- 4. Are you aware of any changes to state laws or local regulations that might affect the protectiveness of the Site's remedy? No.
- 5. Are you aware of any changes in projected land use(s) at the Site? No
- 6. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future? The City of Vero Beach Water & Sewer Department has been kept adequately informed. Reports, such as those currently being provided, and notices received by email are adequate for providing future information. Delivery of reports by electronic means could replace the current system of paper reports, if EPA so desired.
- 7. Do you have any comments, suggestions or recommendations regarding the project? The remediation process has proceeded at a rate that is satisfactory to the City.

| Site Name: | Piper Air | craft Corp./Vero | Beach Water & | EPA ID No.: | FLD004054284 |
|----------------------|------------------|--------------------|-------------------------|--------------------|--------------|
| | Sewer De | <u>partment</u> | | | |
| Interviewer N | ame: <u>Sa</u> | <u>arah Alfano</u> | Affiliation: | <u>Skeo Soluti</u> | ons |
| Subject Name | : Todd | Wegenast | Affiliation: | Piper Aircr | aft, Inc. |
| Subject Conta | ct Inform | ation: Todd.weg | <u>genast@piper.com</u> | | |
| Interview For | mat: | Email | | | |

Interview Category: Potentially Responsible Parties (PRPs)

- What is your overall impression of the remedial activities at the Site?
 I believe the current system is adequate for the protection of human health and the environment, while not posing an undue financial burden on Piper Aircraft. This system has proven to be fairly effective at lowering the contaminant levels and reducing the size of the plume.
- 2. What have been the effects of this Site on the surrounding community, if any? There have been no effects to the surrounding community to my knowledge. Piper Aircraft and the City of Vero Beach have worked well together.
- 3. What is your assessment of the current performance of the remedy in place at the Site? As stated above. I believe the current remedy in place is effective and with the current institutional controls, a solid plan.
- Are you aware of any complaints or inquiries regarding environmental issues or the remedial action from residents since implementation of the cleanup? I am not aware of any complaints or other issues.
- Do you feel well-informed regarding the Site's activities and remedial progress? If not, how might EPA convey site-related information in the future?

 I believe I am well informed and my staff is very knowledgeable of the remediation activities.
- 6. Do you have any comments, suggestions or recommendations regarding the management or operation of the Site's remedy?
 Dimen Aircreft will work with the EPA and EDEP to answer adequate protection of human

Piper Aircraft will work with the EPA and FDEP to ensure adequate protection of human health and the environment with a goal of closing the project within the next five years.

Appendix D: Site Inspection Checklist

| FIVE-YEAR REVIEW SITE | INSPECTION CHECKLIST |
|---|--|
| | |
| I. SITE INF | ORMATION |
| Site Name: Piper Aircraft Corp./Vero Beach Water & Sewer Department | Date of Inspection: January 7, 2014 |
| Location and Region: Vero Beach, Florida; Region 4 | EPA ID: FLD004054284 |
| Agency, Office or Company Leading the Five-Year Review: US EPA, Region 4 | Weather/Temperature: sunny and chilly |
| Remedy Includes: (Check all that apply) Landfill cover/containment Access controls Institutional controls Ground water pump and treatment Surface water collection and treatment Other: | Monitored natural attenuation Ground water containment Vertical barrier walls |
| Attachments: Inspection team roster attached (se | e Section 6.5) 🛛 Site map attached (see Figure 2) |
| II. INTERVIEWS | (check all that apply) |
| 1. O&M Site Manager <u>Todd Wegenast</u> Name Interviewed at site at office by email Problems suggestions Report attached: See Appen | Senior Environmental Health and Safety Manager01/10/2014 DateTitleDate |
| 2. O&M Staff | / / |
| Name Interviewed at site at office by phone F Problems/suggestions Report attached: | Title Date Phone: |
| 3. Local Regulatory Authorities and Response A response office, police department, office of pul recorder of deeds, or other city and county office. | Agencies (i.e., state and tribal offices, emergency blic health or environmental health, zoning office, es). Fill in all that apply. |
| Agency <u>FDEP</u> Contact <u>John Sykes III</u> <u>Environment</u> Name <u>III Hazardou</u> <u>Cleanup Sec</u> Titlo | al Specialist(850) 245-8960s WasteDatePhone No.tion |
| Problems/suggestions Report attached: See 2 | Appendix C. |
| Agency <u>City of Vero Beach Water & Sewer De</u> Contact <u>John Ten Eyck</u> Name <u>As</u> <u>Di</u> Tit | partment sistant <u>1/10/2014</u> (772) 978-5205 rector Date Phone No. le |
| Problems/suggestions Report attached: See A | Appendix C. |
| 4. Other Interviews (optional) Report attache | d: |
| | |

| | III. ON-SITE DOCUMENTS AND RECO | RDS VERIFIED (chec | k all that apply) | |
|-----|---|---|---|-----------|
| 1. | O&M Documents | | | |
| | O&M manual Readily available | Up to date | N/A | |
| | As-built drawings Readily available | Up to date | N/A | |
| | Maintenance logs Readily available | Up to date | N/A | |
| | Remarks: Piper Aircraft staff replace and repair re | emedial components as no | eeded in a timely manner. | |
| 2. | Site-Specific Health and Safety Plan | 🔀 Readily available | \square Up to date \square N/A | A |
| | Contingency plan/emergency response plan | Readily available | \square Up to date \square N/A | A |
| | Remarks: <u>Piper Aircraft has a detailed safety plan</u> with the current remedial actions, there is no sepa components. | for the facility, but due t rate portion for precautio | o the low risk associated ns dealing with remedial | |
| 3. | O&M and OSHA Training Records | Readily available | \Box Up to date \boxtimes N/A | ł |
| | Remarks: | | | |
| 4. | Permits and Service Agreements | | | |
| | Air discharge permit | Readily available | \Box Up to date \Box N/A | A |
| | Effluent discharge | Readily available | \Box Up to date \Box N/A | A |
| | 🔀 Waste disposal, POTW | Readily available | \Box Up to date \Box N/A | A |
| | Other permits: | Readily available | Up to date N/A | A |
| | Remarks: | | | |
| 5. | Gas Generation Records | Readily available | \Box Up to date \boxtimes N/A | A |
| | Remarks: | | | |
| 6. | Settlement Monument Records | Readily available | \Box Up to date \boxtimes N/A | A |
| | Remarks: | | | |
| 7. | Ground Water Monitoring Records | Readily available | \square Up to date \square N/A | ł |
| | Remarks: | | | |
| 8. | Leachate Extraction Records | Readily available | \Box Up to date \boxtimes N/A | ł |
| | Remarks: | | | |
| 9. | Discharge Compliance Records | | | |
| | Air Readily available | Up to date | N/A | |
| | Water (effluent) Readily available | Up to date | □ N/A | |
| ļ | Remarks: | | | |
| 10. | Daily Access/Security Logs | Readily available | \square Up to date \square N/A | ł |
| | Remarks: <u>Piper Aircraft has a security checkpoint</u> are gated and secure. | t when entering the visito | r's building. Other entranc | <u>es</u> |
| | IV. 0&M | COSTS | | |

| - | | | | |
|---------|------------------------------|--|-----------------------|---------------------------------------|
| 1. | O&M Organization | | | |
| | State in-house | | Contractor fo | or state |
| | PRP in-house | | Contractor fo | or PRP |
| | Federal facility in- | -house | Contractor fo | or Federal facility |
| | | | | |
| 2. | O&M Cost Records | | | |
| | 🔀 Readily available | | | |
| | Funding mechanis | sm/agreement in place | Unavailable | |
| | Original O&M cost es | stimate: 🗌 Brea | kdown attached | |
| | | Total annual cost by y | ear for review perio | od if available |
| | From: <u>mm/dd/yyyy</u> | To: <u>mm/dd/yyyy</u> | | Breakdown attached |
| | Date | Date | Total cost | |
| | From: <u>mm/dd/yyyy</u> | To: <u>mm/dd/yyyy</u> | | Breakdown attached |
| | Date | Date | Total cost | |
| | From: <u>mm/dd/yyyy</u> | To: mm/dd/yyyy | | Breakdown attached |
| | Date | Date | Total cost | |
| | From: <u>mm/dd/yyyy</u> | To: mm/dd/yyyy | | Breakdown attached |
| | Date | Date | Total cost | |
| | From: <u>mm/dd/yyyy</u> | To: <u>mm/dd/yyyy</u> | | Breakdown attached |
| | Date | Date | Total cost | |
| 3. | Unanticipated or Uni | usually High O&M Co | sts during Review | Period |
| | Describe costs and rea | sons: | | |
| | V. ACCESS A | AND INSTITUTIONA | L CONTROLS | Applicable N/A |
| A. Fen | icing | | | |
| 1. | Fencing Damaged | Location shown | on site map | Gates secured N/A |
| | Remarks: | | | |
| B. Oth | er Access Restrictions | | | |
| 1. | Signs and Other Secu | rity Measures | Location | n shown on site map N/A |
| | Remarks: <u>Piper Aircra</u> | ft has a security fence and ther entrances are gated | round the facility ar | nd requires checking in when entering |
| C In a | titutional Controls (IC) | | and secure. | |
| U. Inst | inunonal Controls (ICs | s) | | |

| 1. | Implementation and Enf | orcement | | |
|-------------|--|---|---|---|
| | Site conditions imply ICs | not properly implemented | Yes | 🛛 No 🗌 N/A |
| | Site conditions imply ICs | not being fully enforced | Yes | 🛛 No 🗌 N/A |
| | Type of monitoring (e.g., s <u>Piper Aircraft staff. The S</u> sufficient well-constructio | self-reporting, drive by): <u>Remedial componentiate</u> ite is located within a Florida Ground Water n standards through permitting requirements | ents are che Delineated s apply to th | cked at least weekly by l Area so strict and he area. |
| | Frequency: | | | |
| | Responsible party/agency: | Piper Aircraft, Inc. | | |
| | Contact <u>Todd Wegenas</u> | t Senior Environmental Health and Safety Manager | 01/07/20 | <u>14</u> (772) 299-2476 |
| | Name | Title | Date | Phone no. |
| | Reporting is up to date | | 🛛 Yes | □ No □ N/A |
| | Reports are verified by the | e lead agency | Yes Yes | No N/A |
| | Specific requirements in d | eed or decision documents have been met | 🛛 Yes | No N/A |
| | Violations have been repo | rted | Yes | No N/A |
| | Other problems or suggest | ions: 🔲 Report attached | | |
| | | | | |
| 2. | Adequacy ICs Remarks: <u>A 2009 ESD cal</u> <u>Area.</u> | are adequate ICs are inactional controls and the Site is in | dequate 1 a Florida (| N/A Ground Water Delineated |
| D. G | | | | |
| 1. | Vandalism/Trespassing Remarks: | Location shown on site map X N | o vandalisr | n evident |
| 2. | Land Use Changes On S | ite 🛛 N/A | | |
| 2 | | • | | |
| 3. | Land Use Changes Off S | ite 🖄 N/A | | |
| | Remarks: | | | |
| | | VI. GENERAL SHE CONDITIONS | | |
| A. R | oads 🖂 Applicable | | | |
| 1. | Roads Damaged | \Box Location shown on site map \Box Ro | bads adequa | nte 🗌 N/A |
| | Remarks: | | | |
| B. O | ther Site Conditions | | | |
| | Remarks: | | | |
| | VII. LA | ANDFILL COVERS Applicable | e 🛛 N/A | |
| A. La | andfill Surface | | | |

| 1. | Settlement (low spots) | Location shown on site map | Settlement not evident |
|--------|--|--|---|
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 2. | Cracks | Location shown on site map | Cracking not evident |
| | Lengths: | Widths: | Depths: |
| | Remarks: | | |
| 3. | Erosion | Location shown on site map | Erosion not evident |
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 4. | Holes | Location shown on site map | Holes not evident |
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 5. | Vegetative Cover | Grass | Cover properly established |
| | No signs of stress | Trees/shrubs (indicate size and lo | cations on a diagram) |
| | Remarks: | | |
| 6. | Alternative Cover (e.g., a | armored rock, concrete) | N/A |
| | Remarks: | | |
| 7. | Bulges | Location shown on site map | Bulges not evident |
| | Arial extent: | | Height: |
| | Remarks: | | |
| 8. | Wet Areas/Water Damag | ge 🗌 Wet areas/water damage not e | vident |
| | Wet areas | Location shown on site map | Arial extent: |
| | Ponding | Location shown on site map | Arial extent: |
| | Seeps | Location shown on site map | Arial extent: |
| | Soft subgrade | Location shown on site map | Arial extent: |
| | Remarks: | | |
| 9. | Slope Instability | Slides | Location shown on site map |
| | No evidence of slope ir | ıstability | |
| | Arial extent: | | |
| | Remarks: | | |
| B. Bei | nches Applic | cable 🕅 N/A | |
| | (Horizontally constructed mo order to slow down the veloc | ounds of earth placed across a steep land ity of surface runoff and intercept and c | fill side slope to interrupt the slope in onvey the runoff to a lined channel.) |
| 1. | Flows Bypass Bench | Location shown on site map | N/A or okay |
| | Remarks: | | |

| 2. | Bench Breached | Location shown on site map | N/A or okay |
|------|--|---|--|
| | Remarks: | | |
| 3. | Bench Overtopped | Location shown on site map | \square N/A or okay |
| | Remarks: | | |
| C. L | etdown Channels | Applicable 🛛 N/A | |
| | (Channel lined with erosion slope of the cover and will a cover without creating erosion | control mats, riprap, grout bags or gab llow the runoff water collected by the on gullies.) | ions that descend down the steep side benches to move off of the landfill |
| 1. | Settlement (Low spots) | Location shown on site map | No evidence of settlement |
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 2. | Material Degradation | Location shown on site map | No evidence of degradation |
| | Material type: | | Arial extent: |
| | Remarks: | | |
| 3. | Erosion | Location shown on site map | No evidence of erosion |
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 4. | Undercutting | Location shown on site map | No evidence of undercutting |
| | Arial extent: | | Depth: |
| | Remarks: | | |
| 5. | Obstructions | Туре: | No obstructions |
| | Location shown on site | e map Arial extent: | _ |
| | Size: | | |
| | Remarks: | | |
| 6. | Excessive Vegetative Gr | owth Type: | |
| | No evidence of excess | ive growth | |
| | Uegetation in channels | does not obstruct flow | |
| | Location shown on site | e map Arial extent: | _ |
| | Remarks: | | |
| D. C | over Penetrations | Applicable 🛛 N/A | |
| 1. | Gas Vents | Active | Passive |
| | Properly secured/Locked | Functioning Routinely | sampled Good condition |
| | Evidence of leakage at | penetration | intenance N/A |
| | Remarks: | | |

| 2. | Gas Monitoring Probes | | | |
|--------|------------------------------|------------------------|-----------------------------|----------------------|
| | Properly secured/Locked | Functioning | Routinely sampled | Good condition |
| | Evidence of leakage at pe | enetration | Needs maintenance | N/A |
| | Remarks: | | | |
| 3. | Monitoring Wells (within sur | rface area of landfill |) | |
| | Properly secured/Locked | Functioning | Routinely sampled | Good condition |
| | Evidence of leakage at pe | enetration | Needs maintenance | N/A |
| | Remarks: | | | |
| 4. | Extraction Wells Leachate | | | |
| | Properly secured/Locked | Functioning | Routinely sampled | Good condition |
| | Evidence of leakage at pe | enetration | Needs maintenance | N/A |
| | Remarks: | | | |
| 5. | Settlement Monuments | Located | Routinely surveyed | N/A |
| | Remarks: | | | |
| E. Gas | S Collection and Treatment | Applicable | X/A | |
| 1. | Gas Treatment Facilities | | | |
| | ☐ Flaring | Thermal destru | iction | Collection for reuse |
| | Good condition | Needs mainten | ance | |
| | Remarks: | | | |
| 2. | Gas Collection Wells, Manif | olds and Piping | | |
| | Good condition | Needs mainten | ance | |
| | Remarks: | | | |
| 3. | Gas Monitoring Facilities (e | .g., gas monitoring o | of adjacent homes or buildi | ings) |
| | Good condition | Needs mainten | ance 🗌 N/A | 1 |
| | Remarks: | | | |
| F. Cov | ver Drainage Layer | | e 🛛 N/A | |
| 1. | Outlet Pipes Inspected | Functioning | N/A | |
| | Remarks: | | | |
| 2. | Outlet Rock Inspected | Functioning | N/A | |
| | Remarks: | | | |
| G. Det | ention/Sedimentation Ponds | | e 🖂 N/A | |

| 1. | Siltation | Area extent: | Depth: | N/A |
|---|---|---|---|--|
| | Siltation not evid | ent | | |
| | Remarks: | | | |
| 2. | Erosion | Area extent: | Depth: | - |
| | Erosion not evide | ent | | |
| | Remarks: | | | |
| 3. | Outlet Works | Functioning | | N/A |
| | Remarks: | | | |
| 4. | Dam | Functioning | | □ N/A |
| | Remarks: | | | |
| H. R | etaining Walls | | N/A | |
| 1. | Deformations | Location she | own on site map | Deformation not evident |
| | Horizontal displacen | nent: | Vertical dis | splacement: |
| | Rotational displacem | nent: | | |
| | Remarks: | | | |
| 2. | Degradation | Location she | own on site map | Degradation not evident |
| | Remarks: | | | |
| I Do | rimator Ditabos/Off S | ta Diashanas | □ Applicable | |
| 1. 10 | Timeter Ditches/OII-5 | lie Discharge | | N/A |
| 1. 10 | Siltation | | own on site map | Siltation not evident |
| 1. 10 | Siltation Area extent: | Location sho | own on site map | Siltation not evident Depth: |
| 1. 10 | Siltation Area extent: Remarks: | Location sho | own on site map | Siltation not evident Depth: |
| 1. 1 c 1. 2. | Siltation Area extent: Remarks: Vegetative Growth | | own on site map | N/A Siltation not evident Depth: N/A |
| 1. 1. 1. 2. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does | Location sho | own on site map | Siltation not evident Depth: N/A |
| 1. 1. 1. 2. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does a Area extent: | Location sho | own on site map | Siltation not evident Depth: N/A Type: |
| 1. 2. | Siltation Area extent: Remarks: Vegetative Growth Uvegetation does not be a constructed of the sectent: Area extent: Remarks: | Location sho | own on site map | N/A Siltation not evident Depth: N/A Type: |
| 1. 1. 2. 3. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does Area extent: Remarks: Erosion | Location sho | Down on site map Down on site map Down on site map Down on site map | Siltation not evident Depth: N/A Type: Erosion not evident |
| 1. 2. 3. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does Area extent: Remarks: Erosion Area extent: | Location sho Location sho not impede flow | own on site map | Siltation not evident Depth: N/A Type: Erosion not evident Depth: |
| 1. 1. 2. 3. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does Area extent: Remarks: Erosion Area extent: Remarks: | Location sho Location sho not impede flow | own on site map | Siltation not evident Depth: N/A Type: Erosion not evident Depth: |
| 1. 1. 2. 3. 4. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does Area extent: Remarks: Erosion Area extent: Remarks: Erosion Area extent: Discharge Structure | Location sho Location sho not impede flow Location sho Location sho Location sho | own on site map | N/A □ Siltation not evident Depth: □ N/A Type: □ Erosion not evident Depth: □ N/A |
| 1. 1. 2. 3. 4. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does not be a standard of the | Location sho Location sho | own on site map | N/A □ Siltation not evident Depth: □ N/A Type: □ Erosion not evident Depth: □ N/A |
| 1. 10 1. 2. 3. 4. VIII. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does not be a stand of the stand of t | Location sho Location sho not impede flow Location sho Location sho ER WALLS | Image: Applicable Image: Applicable | N/A □ Siltation not evident Depth: □ N/A Type: □ Erosion not evident Depth: □ N/A |
| 1. 10 1. 2. 3. 4. VIII. 1. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does not be a structure Area extent: Remarks: Erosion Area extent: Remarks: Discharge Structure Remarks: VERTICAL BARRI Settlement | Location sho Location sho Location sho Location sho Location sho ER WALLS Location sho | Image: Applicable pwn on site map pwn on site map pwn on site map Image: Applicable pwn on site map | N/A □ Siltation not evident Depth: □ N/A Type: □ Erosion not evident Depth: □ N/A □ N/A □ N/A □ Settlement not evident |
| 1. 1. 2. 3. 4. 1. | Siltation Area extent: Remarks: Vegetative Growth Vegetation does not be a structure Area extent: Remarks: Erosion Area extent: Remarks: Discharge Structure Remarks: VERTICAL BARRI Settlement Area extent: | Location she Location she Location she Location she Location she ER WALLS Location she | Image: Applicable own on site map own on site map own on site map Image: Applicable own on site map | N/A □ Siltation not evident Depth: □ N/A Type: □ Erosion not evident Depth: □ N/A □ N/A □ N/A □ N/A □ N/A □ Settlement not evident Depth: □ Settlement not evident Depth: |

| 2. | Performance Monitoring Type of monitoring: | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|
| | Performance not monitored | | | | | | | | | |
| | Frequency: Evidence of breaching | | | | | | | | | |
| | Head differential: | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| IX. C | IX. GROUND WATER/SURFACE WATER REMEDIES Applicable N/A | | | | | | | | | |
| A. Ground Water Extraction Wells, Pumps and Pipelines Applicable N/A | | | | | | | | | | |
| 1. | Pumps, Wellhead Plumbing and Electrical | | | | | | | | | |
| | \boxtimes Good condition \boxtimes All required wells properly operating \square Needs maintenance \square N/A | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 2. | Extraction System Pipelines, Valves, Valve Boxes and Other Appurtenances | | | | | | | | | |
| | \square Good condition \square Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 3. | Spare Parts and Equipment | | | | | | | | | |
| | Readily available Good condition Requires upgrade Needs to be provided | | | | | | | | | |
| | Remarks: Piper Aircraft performs all remedial component repair and replacement as needed. | | | | | | | | | |
| B. Sı | urface Water Collection Structures, Pumps and Pipelines | | | | | | | | | |
| 1. | Collection Structures, Pumps and Electrical | | | | | | | | | |
| | Good condition Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 2. | Surface Water Collection System Pipelines, Valves, Valve Boxes and Other Appurtenances | | | | | | | | | |
| | Good condition Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 3. | Spare Parts and Equipment | | | | | | | | | |
| | Readily available Good condition Requires upgrade Needs to be provided | | | | | | | | | |
| ļ | Remarks: | | | | | | | | | |
| С. Т | reatment System 🛛 Applicable 🗌 N/A | | | | | | | | | |

| 1. | Treatment Train (check components that apply) | | | | | | | | | |
|------|---|--|--|--|--|--|--|--|--|--|
| | ☐ Metals removal ☐ Oil/water separation ⊠ Bioremediation | | | | | | | | | |
| | Air stripping Carbon adsorbers | | | | | | | | | |
| | Filters: | | | | | | | | | |
| | Additive (e.g., chelation agent, flocculent): | | | | | | | | | |
| | ⊠ Others: | | | | | | | | | |
| | Good condition | | | | | | | | | |
| | Sampling ports properly marked and functional | | | | | | | | | |
| | Sampling/maintenance log displayed and up to date | | | | | | | | | |
| | Equipment properly identified | | | | | | | | | |
| | Quantity of ground water treated annually: <u>Average of 2,649,937 gallons per year (18 quarters</u> considered for UVB-1 and UVB-2). | | | | | | | | | |
| | Quantity of surface water treated annually: | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 2. | Electrical Enclosures and Panels (properly rated and functional) | | | | | | | | | |
| | \square N/A \square Good condition \square Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 3. | Tanks, Vaults, Storage Vessels | | | | | | | | | |
| | \square N/A \square Good condition \square Proper secondary containment \square Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 4. | Discharge Structure and Appurtenances | | | | | | | | | |
| | \square N/A \square Good condition \square Needs maintenance | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 5. | Treatment Building(s) | | | | | | | | | |
| | \square N/A \square Good condition (esp. roof and doorways) \square Needs repair | | | | | | | | | |
| | Chemicals and equipment properly stored | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| 6. | Monitoring Wells (pump and treatment remedy) | | | | | | | | | |
| | \square Properly secured/Locked \square Functioning \square Routinely sampled \square Good condition | | | | | | | | | |
| | All required wells located Needs maintenance N/A | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| D. M | onitoring Data | | | | | | | | | |
| 1. | Monitoring Data | | | | | | | | | |
| | \boxtimes Is routinely submitted on time \boxtimes Is of acceptable quality | | | | | | | | | |

| 2. | Monitoring Data Suggests: | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|--|
| | Ground water plume is effectively contained Contaminant concentrations are declining | | | | | | | | | |
| E. M | E. Monitored Natural Attenuation | | | | | | | | | |
| 1. | Monitoring Wells (natural attenuation remedy) | | | | | | | | | |
| | Properly secured/Locked Functioning Routinely sampled Good condition | | | | | | | | | |
| | All required wells located Needs maintenance N/A | | | | | | | | | |
| | Remarks: | | | | | | | | | |
| | X. OTHER REMEDIES | | | | | | | | | |
| If ther nature | e are remedies applied at the site and not covered above, attach an inspection sheet describing the physical and condition of any facility associated with the remedy. An example would be soil vapor extraction. | | | | | | | | | |
| | XI. OVERALL OBSERVATIONS | | | | | | | | | |
| А. | Implementation of the Remedy | | | | | | | | | |
| В. | Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is designed to accomplish (e.g., to contain contaminant plume, minimize infiltration and gas emissions). The remedy is functioning and contaminant concentrations have declined. It is uncertain whether the treatment system will achieve remediation goals, so Piper Aircraft has been exploring bioremediation. Piper Aircraft submitted a plan to EPA to begin bioremediation and is waiting for a response. Adequacy of O&M | | | | | | | | | |
| | Describe issues and observations related to the implementation and scope of O&M procedures. In | | | | | | | | | |
| | particular, discuss their relationship to the current and long-term protectiveness of the remedy. | | | | | | | | | |
| | <u>Own activities are adequate. Piper Aircrait makes repairs and replacements in a timely and responsible</u> manner. The sampling for the LIVB wells and other monitoring wells is sufficient. If Piper Aircraft begins | | | | | | | | | |
| | bioremediation, additional Q&M activities will be required. | | | | | | | | | |
| C. | Early Indicators of Potential Remedy Problems | | | | | | | | | |
| | Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs that suggest that the protectiveness of the remedy may be compromised | | | | | | | | | |
| | in the future. | | | | | | | | | |
| D. | Opportunities for Optimization | | | | | | | | | |
| | Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy. None noted. | | | | | | | | | |

Appendix E: Photographs from Site Inspection Visit



UVB-2 and sump pump to monitoring well outside of Piper Aircraft facility



Former location of TCE storage tank, current injection point for UVB-2



The inner maintenance area, home to several remedial components and surrounded by manufacturing buildings



MW-2 within the inner maintenance area



Looking across Aviation Boulevard, viewing Piper looking northwest from CVB-15



Indoor MW-16



Indoor MW-17



Outdoor well cluster near Aviation Boulevard



Shops across Aviation Boulevard from Piper Aircraft facilities



Outdoor UVB-1A



Appendix F: Map from Remedial Investigation

Appendix G: Analytical Data for Ground Water

| | | Jun | -09 | | Dec-09 | | | | |
|------------|---------|-------------|--------|------|---------|-------------|-------|------|--|
| | 1,1-DCE | cis-1,2-DCE | TCE | VC | 1,1-DCE | cis-1,2-DCE | TCE | VC | |
| MCL | 7 | 70 | 3 | 1 | 7 | 70 | 3 | 1 | |
| MW-4S | <0.54 | 23 | 13.7 | 0.45 | <1.1 | 168 | 28.6 | 1.3 | |
| MW-5 | <0.54 | 1.7 | 2.8 | <0.3 | <0.54 | 0.59 | 1.9 | <0.3 | |
| MW-16 | 1.8 | 141 | <0.64 | 14.1 | 1.7 | 71.8 | 0.44 | 12.4 | |
| MW-17 | <0.54 | 2.7 | 0.33 | <0.3 | <0.54 | 11.1 | 0.36 | 1.4 | |
| MW-18 | <0.54 | 2 | <0.32 | <0.3 | NS | NS | NS | NS | |
| MW-19 | <0.54 | 2.1 | <0.32 | 2.5 | <0.54 | 1.3 | <0.32 | 1.7 | |
| MW-20 | <0.54 | 0.25 | <0.32 | <0.3 | <0.54 | 3.4 | <0.32 | 4 | |
| MW-22S | <0.54 | 1.6 | <0.32 | 4.2 | <0.54 | 2.3 | <0.32 | 8.6 | |
| MW-23S | <0.54 | 1 | < 0.32 | 0.81 | <0.54 | 6.8 | <0.32 | 19.9 | |
| MW-23D | <0.54 | 1.7 | <0.32 | <0.3 | <0.54 | 2.3 | <0.32 | 0.54 | |
| MW-23l1 | <0.54 | 4.5 | <0.32 | 3.5 | <0.54 | 6.6 | <0.32 | 23.3 | |
| MW-2312 | <0.54 | 4.5 | <0.32 | 38.9 | <0.54 | 3.1 | <0.32 | 19.3 | |
| CVB-15 | <0.54 | 25.7 | < 0.32 | 5 | <0.54 | 21.3 | <0.32 | 5.7 | |
| UVB-1A (I) | <0.54 | 12.6 | <0.32 | 3.7 | NS | NS | NS | NS | |
| UVB-2 (I) | <0.54 | 15.9 | <0.32 | 49.7 | <0.54 | 14.8 | <0.32 | 42.9 | |

Ground Water Analytical Results for Wells Reporting at Least One MCL Exceedance June 2009 through December 2013

Notes

< indicates not detected at stated detection limit

NS - Not Sampled

MCL - Maximum Contaminant Level; Lower of the Federal or State MCL

Bold text/gray shading indicates the detected concentration meets or exceeds MCL

All concentrations reported in micrograms per liter (ug/L)

| | | Jun- | 10 | | Dec-10 | | | | |
|------------|---------|-------------|-------|-------|---------|-------------|-------|-------|--|
| | 1,1-DCE | cis-1,2-DCE | TCE | VC | 1,1-DCE | cis-1,2-DCE | TCE | VC | |
| MCL | 7 | 70 | 3 | 1 | 7 | 70 | 3 | 1 | |
| MW-4S | 0.51 | 82.2 | 33.2 | 1.3 | 0.99 | 512 | 70.6 | 5.4 | |
| MW-5 | <0.29 | 0.35 | 1.4 | <0.28 | <0.23 | 8.1 | 1.3 | <0.22 | |
| MW-16 | 1.6 | 84.5 | 0.35 | 22.2 | 1.4 | 47.1 | 0.31 | 13.7 | |
| MW-17 | <0.29 | 2.9 | <0.24 | <0.28 | <0.23 | 1.4 | <0.26 | <0.22 | |
| MW-18 | <0.29 | 0.6 | <0.24 | <0.28 | NS | NS | NS | NS | |
| MW-19 | <0.29 | 2.5 | <0.24 | 2 | <0.23 | 1.8 | <0.26 | 2.1 | |
| MW-20 | <0.29 | <0.32 | <0.24 | <0.28 | <0.23 | 0.5 | <0.26 | 0.67 | |
| MW-22S | <0.29 | 2.8 | <0.24 | 1.4 | <0.23 | 5 | <0.26 | 13.7 | |
| MW-23S | <0.29 | 2.4 | <0.24 | 5.9 | <0.23 | 5.4 | <0.26 | 13.8 | |
| MW-23D | <0.29 | 1.8 | <0.24 | <0.28 | <0.23 | 1.2 | <0.26 | <0.22 | |
| MW-2311 | <0.29 | 1.4 | <0.24 | 2.6 | <0.23 | 3 | <0.26 | 7.8 | |
| MW-2312 | <0.29 | 10.6 | 0.26 | 62.5 | <0.23 | 0.29 | <0.26 | 1.3 | |
| CVB-15 | <0.29 | 22.1 | <0.24 | 6 | <0.23 | 16.9 | <0.26 | 3.3 | |
| UVB-1A (I) | <0.29 | 1 | <0.24 | 0.38 | NS | NS | NS | NS | |
| UVB-2 (I) | NS | NS | NS | NS | <0.23 | 14.8 | <0.26 | 35.2 | |

Ground Water Analytical Results for Wells Reporting at Least One MCL Exceedance June 2009 through December 2013

Notes

< indicates not detecte

NS - Not Sampled

MCL - Maximum Conta

Bold text/gray shading

| | | Jun | -11 | | Dec-11 | | | |
|------------|---------|-------------|-------|-------|---------|-------------|-------|-------|
| | 1,1-DCE | cis-1,2-DCE | TCE | VC | 1,1-DCE | cis-1,2-DCE | TCE | VC |
| MCL | 7 | 70 | 3 | 1 | 7 | 70 | 3 | 1 |
| MW-4S | <2.3 | 615 | 64.6 | 15.7 | 0.55 | 142 | 25.8 | 4.8 |
| MW-5 | <0.23 | 17.5 | 1.1 | <0.22 | <0.23 | 3.7 | 1.3 | 1.1 |
| MW-16 | 0.32 | 22.4 | <0.26 | 21.4 | 0.63 | 26.7 | 0.28 | 25.3 |
| MW-17 | <0.23 | 2 | <0.26 | <0.22 | <0.23 | 2.3 | <0.26 | <0.22 |
| MW-18 | <0.23 | <0.26 | <0.26 | <0.22 | NS | NS | NS | NS |
| MW-19 | <0.23 | 3.1 | <0.26 | 1.5 | <0.23 | 3.2 | <0.26 | 0.58 |
| MW-20 | <0.23 | <0.26 | <0.26 | <0.22 | <0.23 | 1.6 | <0.26 | 2.8 |
| MW-22S | <0.23 | 3.1 | <0.26 | 0.78 | <0.23 | 0.96 | <0.26 | 2 |
| MW-23S | <0.23 | 7.9 | <0.26 | <0.22 | <0.23 | 4.2 | <0.26 | 3.9 |
| MW-23D | <0.23 | 1.8 | <0.26 | 0.47 | <0.23 | 1.3 | <0.26 | <0.22 |
| MW-2311 | <0.23 | 8.9 | <0.26 | 23 | <0.23 | 5.2 | <0.26 | 4.9 |
| MW-2312 | <0.23 | 4.8 | <0.26 | 18.6 | 0.34 | 20.4 | <0.26 | 51.9 |
| CVB-15 | <0.23 | 14.5 | <0.26 | 5 | <0.23 | <0.26 | <0.26 | <0.22 |
| UVB-1A (I) | <0.23 | 3.4 | <0.26 | 1.9 | <0.23 | 1.2 | <0.26 | 0.51 |
| UVB-2 (I) | <0.23 | 20.3 | <0.26 | 52.2 | <0.23 | 2.8 | <0.26 | 6 |

Ground Water Analytical Results for Wells Reporting at Least One MCL Exceedance

June 2009 through December 2013

Notes

< indicates not detecte

NS - Not Sampled

MCL - Maximum Conta

Bold text/gray shading

| | | Jun | Dec-12 | | | | | |
|------------|---------|-------------|--------|-------|---------|-------------|-------|-------|
| | 1,1-DCE | cis-1,2-DCE | TCE | VC | 1,1-DCE | cis-1,2-DCE | TCE | VC |
| MCL | 7 | 70 | 3 | 1 | 7 | 70 | 3 | 1 |
| MW-4S | <0.23 | 43.3 | 19 | 0.45 | <0.2 | 37 | 15.5 | <0.44 |
| MW-5 | <0.23 | 4.4 | 1.8 | <0.22 | <0.2 | 2 | 1.4 | <0.44 |
| MW-16 | <0.23 | 16.7 | <0.26 | 22.3 | <0.2 | 4.4 | <0.31 | 5.5 |
| MW-17 | <0.23 | 3.1 | 0.31 | <0.22 | <0.2 | 1.6 | <0.31 | <0.44 |
| MW-18 | <0.23 | 1.7 | <0.26 | <0.22 | NS | NS | NS | NS |
| MW-19 | <0.23 | 2.5 | <0.26 | 0.88 | <0.2 | 0.73 | <0.31 | <0.44 |
| MW-20 | <0.23 | 1 | <0.26 | 0.87 | <0.2 | 8.1 | <0.31 | 11.4 |
| MW-22S | <0.23 | 2 | <0.26 | 4.1 | <0.2 | 1.8 | <0.31 | 0.82 |
| MW-23S | <0.23 | 2 | <0.26 | 1.7 | <0.2 | 3.4 | <0.31 | 1.7 |
| MW-23D | <0.23 | 0.38 | <0.26 | <0.22 | <0.2 | 3.3 | <0.31 | 2.6 |
| MW-2311 | <0.23 | 1.4 | <0.26 | 2.9 | <0.2 | 3.4 | <0.31 | 1.8 |
| MW-2312 | <0.23 | 12 | <0.26 | 10.1 | <0.2 | 3.6 | <0.31 | <0.44 |
| CVB-15 | <0.23 | <0.26 | <0.26 | <0.22 | <0.2 | 33.1 | <0.31 | 5.8 |
| UVB-1A (I) | <0.23 | 0.81 | <0.26 | 0.28 | <0.2 | <0.24 | <0.31 | <0.44 |
| UVB-2 (I) | NS | NS | NS | NS | <0.2 | 14.3 | <0.31 | 47.9 |

Ground Water Analytical Results for Wells Reporting at Least One MCL Exceedance

June 2009 through December 2013

Notes

< indicates not detecte

NS - Not Sampled

MCL - Maximum Conta

Bold text/gray shading

| | | Jun | -13 | | Dec-13 | | | |
|------------|---------|-------------|-------|-------|---------|-------------|--------|-------|
| | 1,1-DCE | cis-1,2-DCE | TCE | VC | 1,1-DCE | cis-1,2-DCE | TCE | VC |
| MCL | 7 | 70 | 3 | 1 | 7 | 70 | 3 | 1 |
| MW-4S | 0.21 | 91 | 20.7 | 1 | <0.2 | 51.7 | 21.7 | 0.69 |
| MW-5 | <0.2 | <0.24 | 1.3 | <0.44 | <0.2 | 0.27 | 1.6 | <0.44 |
| MW-16 | <0.2 | 6.7 | <0.31 | 7.6 | <0.2 | 1.6 | <0.31 | 6.3 |
| MW-17 | <0.2 | 3.1 | <0.31 | <0.44 | <0.2 | 2.7 | <0.31 | <0.44 |
| MW-18 | <0.2 | 0.39 | <0.31 | <0.44 | NS | NS | NS | NS |
| MW-19 | <0.2 | 1.6 | <0.31 | <0.44 | <0.2 | 2 | <0.31 | 0.83 |
| MW-20 | <0.2 | <0.24 | <0.31 | <0.44 | <0.2 | 0.73 | <0.31 | 0.8 |
| MW-225 | <0.2 | 2.1 | <0.31 | 1.3 | <0.2 | 0.63 | <0.31 | 0.67 |
| MW-23S | <0.2 | 0.71 | <0.31 | 1.1 | <0.2 | 2.3 | <0.31 | 1.5 |
| MW-23D | <0.2 | 0.89 | <0.31 | <0.44 | <0.2 | 0.68 | <0.31 | <0.44 |
| MW-2311 | <0.2 | 0.69 | <0.31 | <0.44 | <0.2 | 0.64 | <0.31 | 0.46 |
| MW-2312 | <0.2 | 3 | <0.31 | 4.8 | <0.2 | 0.39 | <0.31 | 1.3 |
| CVB-15 | <0.2 | 21.2 | <0.31 | 4.6 | <0.2 | 21.2 | <0.31 | 4.7 |
| UVB-1A (I) | <0.2 | 0.64 | <0.31 | <0.44 | <0.2 | 0.52 | < 0.31 | <0.44 |
| UVB-2 (I) | <0.2 | 6.1 | <0.31 | 15.3 | <0.2 | 4.9 | < 0.31 | 14.7 |

Ground Water Analytical Results for Wells Reporting at Least One MCL Exceedance June 2009 through December 2013

Notes

< indicates not detecte

NS - Not Sampled

MCL - Maximum Conte

Bold text/gray shading



Appendix H. Monitoring Well Concentrations

Appendix I. O&M Costs

Piper Aircraft, Inc.

| J/E | DocNum | Acct | Date | Per. | Year | Desc | Amount |
|-----|----------|-------|------------|------|--------|---|----------|
| GAJ | 30000530 | 22481 | 12/31/2013 | 12 | 2013 F | Reclass PRT4-5900 (Supplier 00620) (ACCUTEST LABORATORIES SOUTHEAST, INC) | 2,407.50 |
| GAJ | 30000530 | 22481 | 12/31/2013 | 12 | 2013 F | Reclass PRT4-6090 (Supplier 00620) (ACCUTEST LABORATORIES SOUTHEAST, INC) | 507.50 |
| GAJ | 30000530 | 22481 | 12/31/2013 | 12 | 2013 F | Reclass PRT4-6129 (Supplier 00620) (ACCUTEST LABORATORIES SOUTHEAST, INC) | 3,507.50 |
| GAJ | 30000530 | 22481 | 12/31/2013 | 12 | 2013 F | Reclass PRT4-6333 (Supplier 00620) (ACCUTEST LABORATORIES SOUTHEAST, INC) | 407.50 |
| GAJ | 30000530 | 22481 | 12/31/2013 | 12 | 2013 F | Reclass PRT4-6344 and APR3-47090 (Supplier 30609) (RUBBER & ACCESSORIES INC.) | 517.88 |

2013 Total (Audited Financials) 7,347.88

2013 Additional 2,882.98

2013 Grand Total 10,230.86

| J/E | DocNum | Acct | Date | Per. | Year | Desc | Amount |
|-----|----------|-------|------------|------|----------------|--|----------|
| MPP | 20008365 | 22481 | 01/10/2012 | 1 | 2012 ACCUTES | T LABORATORIES SOUTHEAS | 2,407.50 |
| MPP | 20008957 | 22481 | 04/09/2012 | 4 | 2012 ACCUTES | T LABORATORIES SOUTHEAS | 207.50 |
| GAJ | 20000253 | 22481 | 06/29/2012 | 6 | 2012 Reclass E | PO2-346 (BARNEY'S PUMPS, INC) | 1,207.00 |
| GAJ | 20000263 | 22481 | 06/29/2012 | 6 | 2012 Reclass P | RT4-5450 (RUBBER & ACCESSORIES INC.) | 228.00 |
| MAP | 20009546 | 22481 | 07/10/2012 | 7 | 2012 ACCUTES | T LABORATORIES SOUTHEAS | 3,307.50 |
| GAJ | 20000302 | 22481 | 08/24/2012 | 8 | 2012 Reclass F | RT4-5570 & PRT4-5578 (RAINFOREST IRRIGATION) | 1,210.00 |
| MPP | 20010159 | 22481 | 10/05/2012 | 10 | 2012 ACCUTES | T LABORATORIES SOUTHEAS | 407.50 |

2012 Total (Audited Financials) 8,975.00

2012 Additional 245.09

2012 Grand Total 9,220.09

| J/E | DocNum | Acct | Date | Per. | Year | Desc | Amount |
|-----|----------|-------|------------|------|------------------|---------------------|----------|
| MPP | 10008823 | 22481 | 01/07/2011 | 1 | 2011 ACCUTEST LA | BORATORIES SOUTHEAS | 2,207.50 |
| MPP | 10008946 | 22481 | 02/02/2011 | 2 | 2011 BARNEY'S PU | MPS, INC | 497.22 |
| MPP | 10009787 | 22481 | 04/08/2011 | 4 | 2011 ACCUTEST LA | BORATORIES SOUTHEAS | 615.00 |
| MCR | 10000961 | 22481 | 07/01/2011 | 6 | 2011 CROSBY, RUT | Н | 51.20 |
| MPP | 10010786 | 22481 | 06/13/2011 | 6 | 2011 RUBBER & AC | CESSORIES INC. | 470.88 |
| MPP | 10011191 | 22481 | 07/05/2011 | 7 | 2011 GHC SPECIAL | TY BRANDS, INC. DBA | 175.22 |
| MPP | 10011312 | 22481 | 07/08/2011 | 7 | 2001 ACCUTEST LA | BORATORIES SOUTHEAS | 3,507.50 |
| MAP | 10007969 | 22481 | 09/08/2011 | 9 | 2011 EPA HAZARD | US SUBSTANCE SUPERF | 2,067.06 |

| MPP | 10013294 | 22481 | 10/07/2011 | 10 | 2011 ACCUTEST LABORATORIES SOUTHEAS | 407.50 |
|-----|----------|-------|------------|----|-------------------------------------|--------|
| MPP | 10013296 | 22481 | 10/25/2011 | 10 | 2011 BARNEY'S PUMPS, INC | 411.84 |
| MPP | 10013778 | 22481 | 12/07/2011 | 12 | 2011 RUBBER & ACCESSORIES INC. | 485.36 |

2011 Total 10,896.28

| J/E | DocNum | Acct | Date | Per. | Year Desc | Amount |
|-----|----------|-------|------------|------|---|-----------|
| MPP | 90003241 | 22481 | 12/15/2009 | 1 | 2010 PRODUCT RECOVERY MANAGEMENT | 329.56 |
| MPP | 90003458 | 22481 | 01/27/2010 | 1 | 2010 BARNEY'S PUMPS, INC | 468.24 |
| CDT | 90000272 | 22481 | 02/15/2010 | 2 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 207.50 |
| MAP | 90002660 | 22481 | 11/05/2009 | 2 | 2010 INDIAN RIVER ARMATURE | 422.65 |
| MPP | 90003538 | 22481 | 01/08/2010 | 2 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 2,115.00 |
| MAP | 90003668 | 22481 | 04/06/2010 | 5 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 407.50 |
| MAP | 90005076 | 22481 | 04/06/2010 | 6 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 407.50 |
| APC | 90000034 | 22481 | 07/21/2010 | 7 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 407.50 |
| MPP | 90005882 | 22481 | 08/05/2010 | 8 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 3,407.50 |
| MAP | 90004687 | 22481 | 09/15/2010 | 9 | 2010 EPA HAZARDOUS SUBSTANCE SUPERFUND | 15,421.27 |
| MPP | 90006881 | 22481 | 11/05/2010 | 11 | 2010 ACCUTEST LABORATORIES SOUTHEAST, INC | 257.50 |
| MPP | 90007102 | 22481 | 12/07/2010 | 12 | 2010 RUBBER & ACCESSORIES INC. | 447.77 |

2010 Total 24,299.49

| J/E | DocNum | Acct | Date | Per. | Year | Desc | Amount |
|-----|----------|-------|------------|------|--------|--------------------------------|-----------|
| MPP | 90000094 | 22481 | 12/08/2008 | 1 | 2009 H | HOMELAND IRRIGATION CENTER | 48.57 |
| MPP | 90000116 | 22481 | 01/06/2009 | 1 | 2009 A | ACCUTEST LABORATORIES SOUTHEAS | 4,557.50 |
| MPP | 90000363 | 22481 | 02/04/2009 | 2 | 2009 0 | DFFICE PRODUCTS & SERVICES INC | 16.67 |
| MPP | 90000944 | 22481 | 04/07/2009 | 4 | 2009 E | BARNEY'S PUMPS, INC | 438.11 |
| MCR | 90000142 | 22481 | 04/30/2009 | 5 | 2009 0 | CROSBY, RUTH | 11.69 |
| MPP | 90001112 | 22481 | 04/06/2009 | 5 | 2009 A | ACCUTEST LABORATORIES SOUTHEAS | 407.51 |
| MPP | 90001413 | 22481 | 06/09/2009 | 6 | 2009 F | RUBBER & ACCESSORIES INC. | 624.02 |
| MCR | 90000206 | 22481 | 06/29/2009 | 6 | 2009 0 | CROSBY, RUTH | 30.20 |
| MPP | 90001961 | 22481 | 07/20/2009 | 9 | 2009 A | ACCUTEST LABORATORIES SOUTHEAS | 3,607.50 |
| MCR | 90000306 | 22481 | 10/02/2009 | 10 | 2009 L | JS ENVIRONMENTAL PROTECTION AG | 28,121.85 |
| MPP | 90002710 | 22481 | 11/05/2009 | 11 | 2009 A | ACCUTEST LABORATORIES SOUTHEAS | 207.50 |
| MPP | 90003036 | 22481 | 11/17/2009 | 12 | 2009 A | ACCUTEST LABORATORIES SOUTHEAS | 207.50 |
| MPP | 90002960 | 22481 | 11/30/2009 | 12 | 2009 F | RUBBER & ACCESSORIES INC. | 312.02 |
| MCR | 90000437 | 22481 | 12/31/2009 | 12 | 2009 0 | CROSBY, RUTH | 27.10 |

2009 Total 38,617.74
| J/E | DocNum | Acct | Date | Per. | Year Desc | Amount |
|-------------|----------|-------|------------|------|-------------------------------------|-----------|
| MPP | 80006721 | 22481 | 01/08/2008 | 1 | 2008 ACCUTEST LABORATORIES SOUTHEAS | 4,427.50 |
| MPP | 80007036 | 22481 | 01/14/2008 | 2 | 2008 GLOBAL ENVIRONMENTAL ENGINEERI | 3,575.00 |
| MCR | 80000878 | 22481 | 02/22/2008 | 2 | 2008 CROSBY, RUTH | 48.14 |
| MPP | 80008689 | 22481 | 04/04/2008 | 4 | 2008 AMERICAN DRILLING SERVICES, IN | 20,887.60 |
| MPP | 80008734 | 22481 | 03/26/2008 | 4 | 2008 HARBOR BRANCH ENVIRONMENTAL | 2,931.00 |
| MCR | 80001156 | 22481 | 05/29/2008 | 6 | 2008 PRODUCT RECOVERY MANAGEMENT | 319.29 |
| MPP | 80009504 | 22481 | 05/23/2008 | 6 | 2008 GLOBAL ENVIRONMENTAL ENGINEERI | 1,100.00 |
| MPP | 80009594 | 22481 | 05/29/2008 | 6 | 2008 RUBBER & ACCESSORIES INC. | 577.80 |
| MCR | 80001202 | 22481 | 06/17/2008 | 6 | 2008 BARKER, ROY | 21.43 |
| MCR | 80001206 | 22481 | 06/20/2008 | 6 | 2008 DEPARTMENT OF BUSINESS AND | 125.00 |
| MPP | 80009842 | 22481 | 06/12/2008 | 6 | 2008 A-1 METAL SUPPLY CORPORATION | 322.22 |
| MCR | 80001245 | 22481 | 06/27/2008 | 7 | 2008 CROSBY, RUTH | 41.40 |
| MPP | 80010937 | 22481 | 08/07/2008 | 8 | 2008 ACCUTEST LABORATORIES SOUTHEAS | 4,687.50 |
| NPP | 80011444 | 22481 | 09/12/2008 | 9 | 2008 BARNEY'S PUMPS, INC | 547.19 |
| ICR | 80001507 | 22481 | 09/27/2008 | 9 | 2008 CROSBY, RUTH | 20.91 |
| IPP | 80012351 | 22481 | 10/30/2008 | 11 | 2008 ACCUTEST LABORATORIES SOUTHEAS | 527.50 |
| ICR | 80001626 | 22481 | 11/12/2008 | 11 | 2008 EPA HAZARDOUS SUBSTANCES SUPER | 3,064.36 |
| I PP | 80012691 | 22481 | 11/24/2008 | 12 | 2008 GRAINGER | 196.17 |
| IPP | 80012732 | 22481 | 12/03/2008 | 12 | 2008 PARK'S RENTAL INC VERO BEACH | 189.00 |
| I CR | 80001702 | 22481 | 12/19/2008 | 12 | 2008 CROSBY, RUTH | 64.27 |
| MPP | 80013067 | 22481 | 11/24/2008 | 12 | 2008 LOWE'S COMPANIES INC | 86.88 |

2008 Total 43,760.16