

**SIXTH FIVE-YEAR REVIEW REPORT
FOR
SOUTH VALLEY SUPERFUND SITE
ALBUQUERQUE, BERNALILLO COUNTY, NEW MEXICO**



March 25, 2020



**Prepared by
U.S. Environmental Protection Agency
Region 6
DALLAS, TEXAS**

**SIXTH FIVE-YEAR REVIEW REPORT
SOUTH VALLEY SUPERFUND SITE
EPA ID#: NMD980745558
ALBUQUERQUE, BERNALILLO COUNTY, NEW MEXICO**

This memorandum documents the U.S. Environmental Protection Agency's performance, determinations, and approval of the South Valley Superfund Site (Site) sixth five-year review under Section 121(c) of the Comprehensive Environmental Response, Compensation, and Liability Act, 42 U.S. Code Section 9621(c), as provided in the attached Sixth Five-Year Review Report.

Summary of the Sixth Five-Year Review Report

The U.S. Environmental Protection Agency Region 6 (EPA) has conducted the Sixth Five-Year Review (FYR) of the remedial actions (RA)s implemented at the South Valley Superfund Site (Site) in Albuquerque, Bernalillo County, New Mexico. The purpose of this Sixth FYR was to determine whether the selected remedies for the Site continue to protect human health and the environment. The Site involves two potentially responsible parties (PRP)s, Univar USA, Inc. (Univar) and General Electric Aviation (GEA). This FYR covers the 5-year period starting on July 15, 2015.

This FYR for the Site was performed through a review of the Record of Decisions (ROD)s, Explanation of Significant Differences (ESD)s; other historic site documents; site inspections performed on October 21-22, 2019, at Univar and GEA facilities; interviews with stakeholders; and a review of data collected at the Site during the previous review periods.

The South Valley Site includes two industrial source facilities and is composed of six operable units (OUs). The facilities, GEA and Univar, were for the manufacturing of various aircraft parts and used for various industrial and commercial purposes, respectively:

- OU 01 – The Record of Decision (ROD) was signed on March 22, 1985, with no identified PRP, and consists of the City of Albuquerque municipal wells, San Jose 6 (SJ-6) and San Jose 3 (SJ-3) which were contaminated with volatile organic compounds (VOC)s. The Remedial Action Objective (RAO) was to eliminate the threat to human health posed by potentially introducing contaminants from SJ-6 and SJ-3 wells into the City of Albuquerque drinking water supply. This was accomplished by replacing municipal wells SJ-6 and SJ-3 with the Burton #4 well which was completed in April 1987.

On June 5, 2017, EPA submitted a letter to the New Mexico Environment Department (NMED) requesting comments to the proposal to commence with deletion of OU 01 from the National Priorities List (NPL). On August 11, 2017, NMED submitted a letter to EPA concurring with the proposal to commence with the deletion procedures for OU 01. On June 13, 2018, EPA issued a deletion docket to commence with the deletion of OU 01. EPA completed the deletion of OU 01 from the NPL on September 23, 2019. There are no hazardous substances remaining at OU1 above levels that allow for unlimited use/unrestricted exposure (UU/UE) so therefore, OU1 will not be included in FYRs going forward.

- OU 02 – The ROD was signed on September 30, 1988 for which GEA is the PRP, with a remedial goal of eliminating conduit(s) for contaminant migration from the shallow to intermediate aquifers. The RAO was accomplished by plugging and abandoning municipal wells SJ-6 and SJ-3 and other shallow wells, restricting ground water use, and implementing a ground water monitoring program. GEA submitted a letter to EPA requesting they commence with the deletion procedures for OU 02 on April 7, 2017. On August 11, 2017, NMED provided concurrence to EPA regarding GEA's request. EPA issued a deletion docket on June 13, 2018 and on September 23, 2019, EPA completed the deletion of OU 02 from the NPL. There are no hazardous substances remaining at OU 02 above levels that allow for unlimited use/unrestricted exposure (UU/UE) so therefore, OU 02 will not be included in FYRs going forward.

- OU 03 – The ROD for the Edmunds Street Ground Water Plume (Univar) was signed on June 28, 1988. The RAO included reducing the concentrations in ground water of site-related VOCs to acceptable levels (aquifer restoration) via a pump-treat-injection system. A ground water recovery system was initiated in April 1992 and a vapor recovery system was initiated in November 1999. The recovery systems for ground water and vapor were shut off in September 2006 and November 2006, respectively. Subsequent monitoring has shown that the ground water and vapor extraction systems reduced the dissolved chlorinated VOC concentrations to levels below and compliant with Applicable or Relevant and Appropriate Requirements (ARARs) as defined in the ROD. On June 10, 2014, EPA approved Univar’s request to close OU 03 for VOCs.

EPA approved Univar’s recommended actions regarding the further investigation of 1,4-dioxane as a contaminant of concern (COC). Univar submitted a Human Health Risk Evaluation (HHRE) that evaluated potential human health risks and defined site-specific risk-based cleanup goals. In addition to continually monitoring ground water, Univar proposed additional monitoring wells to delineate and identify the migration of the existing 1,4-dioxane plume. A remedial work plan was submitted to EPA and NMED for review and was approved on July 22, 2016. A ground water recovery, treatment, and injection system for the removal of 1,4-dioxane was installed and became operational on March 5, 2018. The ground water treatment system continues to operate to achieve the site 1,4-dioxane clean-up goals.

- OU 04 – The ROD for the Edmunds Street Source Control (to address the potential vadose zone contamination) was signed on March 30, 1989. Univar, the PRP, was required to locate the source of the solvent contamination by investigating the soil around a pit on their property. The investigation found that no additional action was necessary in the vadose zone. The ROD specified No Further Action.
- OU 05 – The ROD was signed on September 30, 1988. GEA is the PRP for this OU. The GEA Shallow Zone consists of the unsaturated and saturated portion of the shallow zone aquifer at the GEA facility. The RAO for this OU is to remediate the shallow zone ground water plume and eliminate source materials via enhanced dewatering, soil flushing, and soil vapor extraction techniques. GEA installed shallow ground water recovery systems on both the North Plant 83 and South Plant 83 Areas. Both ground water recovery system operations began in May 1994. The ground water treatment system at this OU was completely shut down in July 2010. Compliance ground water monitoring was completed on September 22, 2014. GEA requested closure of OU 05, stating that all requirements in the Administrative Order, dated July 3, 1989, had been fulfilled.

All wells and infrastructure associated with the OU 05 ground water treatment system were plugged and abandoned or removed as approved by EPA. GEA submitted a letter to EPA requesting that they commence with the deletion procedures for OU 05 on April 7, 2017. On August 11, 2017, NMED provided concurrence to EPA regarding GEA’s request. EPA issued a deletion docket on June 13, 2018 and on September 23, 2019, EPA completed the deletion of OU 05 from the NPL.

- OU 06 – The ROD was signed on September 30, 1988. GEA is the PRP for this OU. The GEA Deep Zone for OU 06 refers to the deep aquifer beneath the GEA facility. The RAO is to hydraulically contain the ground water plume to protect the City of Albuquerque’s water supply wells from being impacted and to reduce the concentrations of site-related VOCs in ground water to acceptable levels (aquifer restoration). The ground water remediation system at this OU began operation in March 1996. Remedial activities performed at OU 06 have hydraulically contained and reduced the overall volume and mass of the plume. A pumping and injection regimen is being implemented to address residual contaminants in the Deep Zone ground water plume.

Based on the information available during this Sixth FYR, the following determinations were made for the selected remedies for the OUs at the South Valley Superfund Site:

OU 03 - The remedy is protective of human health and the environment.

OU 04 -The remedy is protective of human health and the environment.

OU 05 - The remedy is protective of human health and the environment.

OU 06 - The remedy is protective of human health and the environment.

The remedial actions at OU 03, OU 04, OU 05, and OU6 are protective.

Environmental Indicators

Human Exposure Status: Under Control

Contaminated Ground Water Status: Under Control

Site-Wide Ready for Reuse: Yes

Actions Needed

The following actions must be taken for the remedy to be protective: None

Determination

I have determined that the remedy for Operable Units 3, 4, 5, and 6 at the South Valley Superfund Site is protective.

WREN STENGER
Digitally signed by WREN STENGER
DN: cn=U.S. Government, ou=Environmental Protection
Agency, cn=WRENSTENGER,
0.9.2342.19200300.100.1.1=68001003651787
Date: 2020.03.25 16:23:40 -05'00'

Wren Stenger
Director, Superfund and Emergency Management Division
U.S. Environmental Protection Agency Region 6

Date

CONCURRENCES

**SIXTH FIVE-YEAR REVIEW REPORT
SOUTH VALLEY SUPERFUND SITE
EPA ID#: NMD980745558
ALBUQUERQUE, BERNALILLO COUNTY, NEW MEXICO**

**MICHAEL
HEBERT**

Digitally signed by MICHAEL HEBERT
DN: c=US, o=U.S. Government,
ou=Environmental Protection Agency,
cn=MICHAEL HEBERT,
0.9.2342.19200300.100.1.1=68001003655443
Date: 2020.03.25 11:14:04 -05'00'

Michael Hebert
Remedial Project Manager

Date

**BLAKE
ATKINS**

Digitally signed by BLAKE ATKINS
DN: c=US, o=U.S. Government,
ou=Environmental Protection Agency,
cn=BLAKE ATKINS,
0.9.2342.19200300.100.1.1=68001003652741
Date: 2020.03.25 12:23:53 -05'00'

Blake Atkins
Chief, Louisiana/New Mexico/Oklahoma Section

Date

JOHN MEYER

Digitally signed by JOHN MEYER
DN: c=US, o=U.S. Government,
ou=Environmental Protection Agency,
cn=JOHN MEYER,
0.9.2342.19200300.100.1.1=68001003655626
Date: 2020.03.25 11:54:38 -05'00'

John C. Meyer
Chief, Superfund Remedial Branch

Date

(see attached email concurrence)

Leonard Schilling
Attorney, Office of Regional Counsel

3 – 18 - 20
Date

(see attached email concurrence)

I-Jung Chiang
Chief, Superfund Branch, Office of Regional Counsel

3 – 23 -20
Date

From: [Schilling, Leonard](#)
To: [Hebert, Michael](#)
Subject: RE: 0611/06R8 - South Valley - Five Year Review Report for concurrence
Date: Wednesday, March 18, 2020 10:04:15 AM

I concur

From: Hebert, Michael <hebert.michael@epa.gov>
Sent: Monday, March 16, 2020 9:17 AM
To: Schilling, Leonard <Schilling.Leonard@epa.gov>
Subject: 0611/06R8 - South Valley - Five Year Review Report for concurrence

E-Version of Draft South Valley Five Year Review Report

Sent for remote concurrence due to COVID-19 optional situational flexiplace.

Thanks, Hebert

From: [Travis, Pamela](#)
To: [Hebert, Michael](#)
Subject: RE: 0611/06R8 - South Valley Five Year Review Report- for concurrence
Date: Monday, March 23, 2020 5:29:15 PM

Please accept this e-mail as my concurrence on the South Valley Five Year Review Report.

From: Hebert, Michael <hebert.michael@epa.gov>
Sent: Monday, March 23, 2020 2:44 PM
To: Travis, Pamela <Travis.Pamela@epa.gov>
Subject: 0611/06R8 - South Valley Five Year Review Report- for concurrence

E-Version of Draft South Valley Five Year Review Report

Sent for remote concurrence due to COVID-19 optional situational flexiplace.

Thanks, Hebert

ISSUES/RECOMMENDATIONS
SIXTH FIVE-YEAR REVIEW REPORT
SOUTH VALLEY SUPERFUND SITE
EPA ID#: NMD980745558
ALBUQUERQUE, BERNALILLO COUNTY, NEW MEXICO

None

Table of Contents

| | |
|---|-----|
| LIST OF ABBREVIATIONS & ACRONYMS..... | 9 |
| I. INTRODUCTION | 10 |
| FIVE-YEAR REVIEW SUMMARY FORM..... | 11 |
| II. . RESPONSE ACTION SUMMARY | 11 |
| Status of Implementation | 14 |
| OU 03 Univar Ground Water Plume..... | 15 |
| OU 05 Shallow Zone Aquifer | 15 |
| OU 06 Deep Zone Aquifer..... | 16 |
| IC Summary Table | 16 |
| III. . PROGRESS SINCE THE LAST REVIEW | 18 |
| IV. . FIVE-YEAR REVIEW PROCESS..... | 20 |
| Community Notification, Involvement & Site Interviews | 20 |
| Data Review | 21 |
| OU 03 Ground Water Flow..... | 21 |
| OU 03 Univar Ground Water Plume..... | 21 |
| OU 06 Deep Zone Analytical Results | 24 |
| Deep-Shallow Zone (DS) (4900 to 4840 feet amsl)..... | 24 |
| Deep-Intermediate zone (DI) (4840 to 4790 feet amsl) | 24 |
| Deep-Intermediate & Deep-Deep Zone (DD) (4790 to 4660 feet amsl)..... | 25 |
| Deep-Low-Permeability Zone (DLPZ) (4660 to 4600 feet amsl)..... | 25 |
| Below-Deep-Low-Permeability Zone (BDLPZ) (4600 to 4500 feet amsl)..... | 25 |
| OU 06 VOC Mass Removal..... | 26 |
| Site Inspection..... | 27 |
| V. TECHNICAL ASSESSMENT..... | 28 |
| QUESTION A: Is the remedy functioning as intended by the decision documents? | 28 |
| QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid?..... | 29 |
| QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy?..... | 29 |
| VI. ISSUES/RECOMMENDATIONS..... | 29 |
| OTHER FINDINGS..... | 30 |
| VII. TECTIVENESS STATEMENT | 31 |
| VIII. NEXT REVIEW..... | 32 |
| APPENDIX A – REFERENCE LIST..... | 32 |
| APPENDIX B – ADDITIONAL SITE INFORMATION | 45 |
| Status of Implementation | 53 |
| Remedy Operation and Maintenance at OU 03..... | 53 |
| APPENDIX C –TABLES AND FIGURES | 55 |
| APPENDIX D – INTERVIEWS..... | 74 |
| APPENDIX E – SITE INSPECTION CHECKLIST | 86 |
| APPENDIX F – SITE INSPECTION PHOTOS..... | 117 |
| APPENDIX G – NEWSPAPER AFFIDAVIT OF PUBLICATION..... | 132 |

Tables

Table C-1: Operable Units Summary for South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 56

Table C-2: Comparison of OU 03 ARARS to Current Standards For Drinking and Ground Water, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 57

Table C-3: Comparison of OU 05 and OU 06 ARARS to Current Standards For Drinking and Ground Water, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 58

Table C-4: OU 03 Concentrations of 1,4-Dioxane in Samples Collected from the Ground Water Treatment System Influent, Effluent, and Recovery Wells Univar USA Inc., South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 59

Table C-5: OU 06 Deep Zone Ground Water Remediation System Performance and Compliance Monitoring Plan Taken from GEA Table 1 Annual and Semi-Annual Reports - July 2015 through June 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 61

Figures

Figure C-1: Operational Units OU 02, OU 05, and OU 06, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico 63

Figure C-2: OU 03 Well Locations and Distribution of 1,4- Dioxane at Univar South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico 64

Figure C-3: GEA Well Locations for Deep Zone Remediation System (OU 06), South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico 65

Figure C-4: GEA Well Locations and Distribution of 1,4-Dioxane in Shallow Aquifer January 2016 through April 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico 66

Figure C-5: Univar Potentiometric Surface Elevation – April 3, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 67

Figure C-6: Univar Potentiometric Surface Elevation – May 14, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 68

Figure C-7: Univar Potentiometric Surface Elevation – August 23, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 69

Figure C-8: Univar Potentiometric Surface Elevation – October 4, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 70

Figure C-9: Univar Potentiometric Surface Elevation – November 6, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 71

Figure C-10: Univar Potentiometric Surface Elevation – February 6, 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 72

Figure C-11: Univar Potentiometric Surface Elevation – April 16, 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico..... 73

LIST OF ABBREVIATIONS & ACRONYMS

| | |
|--------|---|
| ARAR | Applicable or Relevant and Appropriate Requirement |
| CERCLA | Comprehensive Environmental Response, Compensation, and Liability Act |
| COPC | Contaminant of Potential Concern |
| EPA | United States Environmental Protection Agency |
| FYR | Five-Year Review |
| GRTIS | Ground Water Recovery and Injection System |
| GWPS | Ground Water Protection Standards |
| GWQB | Ground Water Quality Bureau |
| ICs | Institutional Controls |
| MCL | Maximum Contaminant Level |
| NCP | National Oil and Hazardous Substances Pollution Contingency Plan |
| NMED | New Mexico Environment Department |
| NMWQCC | New Mexico Water Quality Control Commission |
| NPL | National Priorities List |
| OU | Operable Unit |
| O&M | Operation and Maintenance |
| PRP | Potentially Responsible Party |
| RA | Remedial Action |
| RAO | Remedial Action Objectives |
| RAP | Remedial Action Plan |
| RI/FS | Remedial Investigation and Feasibility Study |
| ROD | Record of Decision |
| RPM | Remedial Project Manager |
| SOS | Superfund Oversight Section |
| VOCs | Volatile Organic Compounds |

I. INTRODUCTION

The purpose of a Five-Year Review (FYR) is to evaluate the implementation and performance of a remedy in order to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings, and conclusions of reviews are documented in five-year review reports such as this one. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The U.S. Environmental Protection Agency (EPA) is preparing this five-year review pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 121, consistent with the National Contingency Plan (NCP)(40 CFR Section 300.430(f)(4)(ii)), and considering EPA policy.

This is the sixth FYR for the South Valley Superfund Site. The triggering action for this statutory review is the completion date of the previous FYR. This FYR has been prepared due to the fact that hazardous substances, pollutants, or contaminants remain at the site above levels that allow for unlimited use and unrestricted exposure (UU/UE).

The Site consists of six Operating Units (OUs). OU 01 and OU 02 will not be included in this or future FYRs because there are no contaminants remaining on site above levels that allow for UU/UE. OUs 3, 4, 5 and 6 are included in this FYR.

- OU 03 addresses: Univar ground water
- OU 04 addresses: Univar Edmunds street source control (vadose zone)
- OU 05 addresses: General Electric Aviation (GEA) groundwater, shallow zone
- OU 06 addresses: GEA groundwater, deep zone

OUs are further summarized in **Table C-1, Appendix C** and in greater detail in the data review and technical assessment sections of this FYR.

The South Valley Superfund Site Five-Year Review was led Mr. Bill Pearson and Mr. Angelo Ortelli, of the New Mexico Environment Department (NMED), Ground Water Quality Bureau (GWQB), Superfund Oversight Section (SOS) and Michael Hebert (EPA). Participants for the Site inspection included: Ms. Katy Brantingham, Associate Vice President, Arcadis US, Inc.; Ms. Julie Einerson, Owner, Genesis Environmental, Safety, and Health, LLC.; John Billiard, Technical Services Director, Axis Group, Inc. The potential responsible parties were notified of the initiation of the five-year review. The review began on 8/26/2019.

Site Background

The South Valley Site is in an industrial area in the southern portion of Albuquerque, New Mexico, one-half mile west of the Albuquerque International Airport; one-half mile east of the Rio Grande; close to the intersection of South Broadway and Woodward Road. Historical and current land use surrounding the Site is primarily industrial, with some residential use to the north of the site.

One portion of the South Valley Site is known as the Univar Site (**Appendix C, Figure C-1**). The Univar site has been utilized by multiple companies as a distribution facility for dry ice, chlorine, ammonia gas, and other industrial chemicals since 1965. Since 1985, Univar has remained the only active company on the Site. Univar purchased the property from AmeriGas in June 1988. The contamination identified in this designated portion is addressed in OU 03 and OU 04.

The other portion of the Site is known as the former Air Force Plant 83 Site (also referred to as the General Electric Aviation (GEA) Site). The Plant 83 consisted of two facilities: North Plant 83 Area, located north of Woodward Road, which was demolished in October 1997; and South Plant 83 Area, located south of Woodward Road, which was demolished in May 2011 (**Appendix C, Figure C-1**). Both facilities have been used for manufacturing purposes since the 1950's, first by Eidel Manufacturing; followed by the Atomic Energy Commission through its contractor,

American Car Foundry; followed by the U.S. Air Force through its contractors at General Electric; and finally, by General Electric Aviation (GEA) as facility owner since 1984. The contamination identified in this designated portion of the Site is addressed in OU 03, OU 05, and OU 06.

FIVE-YEAR REVIEW SUMMARY FORM

| SITE IDENTIFICATION | | |
|---|--|---|
| Site Name: South Valley | | |
| EPA ID: NMD980745558 | | |
| Region: 6 | State: NM | City/County: Albuquerque/Bernalillo. |
| SITE STATUS | | |
| NPL Status: Final | | |
| Multiple OUs? Yes | Has the site achieved construction completion? Yes | |
| REVIEW STATUS | | |
| Lead agency: EPA <i>[If "Other Federal Agency", enter Agency name]:</i> | | |
| Author name (Federal or State Project Manager): Michael Hebert, Remedial Project Manager | | |
| Author affiliation: EPA Region 6 | | |
| Review period: 8/30/2019 to 7/3/2020 | | |
| Date of site inspection: 10/21-22/2019 | | |
| Type of review: Statutory | | |
| Review number: 6 | | |
| Triggering action date: 7/3/2015 | | |
| Due date (five years after triggering action date): 7/3/2020 | | |

II. RESPONSE ACTION SUMMARY

Basis for Taking Action

In 1978, the City of Albuquerque detected low levels of VOCs in municipal wells SJ-3 and SJ-6 which prompted their removal (both plugged and abandoned) and the subsequent installation of a replacement well, Burton #4 (OU 01). In 1981, the EPA and NMED designated a one square mile area around SJ-6 as a Superfund Site which was added to the National Priorities List (NPL).

OU 03

Initial investigations starting in 1978 through the early 1980's resulted in the discovery of a plume of contaminated groundwater starting at the Univar site and extending to the east. Various VOCs were detected in the first groundwater zone at the site. During site characterization, the following hazardous substances were detected in ground water: acetone, carbon tetrachloride, chloroform, 1,2-Dichloroethane (1,2-DCA), trans-1,2- Dichloroethene (trans-1,2-DCE), 1,1- Dichloroethene (1,1-DCE), methylene chloride, tetrachloroethene (PCE), trichloroethene (TCE) and 1,1,1-Trichloroethane (TCA). This operable unit was solely concerned with groundwater ingestion being the route of exposure.

OU 04

As a result of the detection of contaminated groundwater which initiated OU3, subsequent investigations were performed in the 1980's to determine the source of the groundwater contamination. Various VOCs (i.e., Tetrachloroethene, 1,1-Dichloroethene) were detected in soils at the site, but the highest concentrations of soil contamination was found at the water table interface which indicated most of the contamination had migrated to the groundwater. OU4 considered three primary routes of exposure: direct contact, ingestion of contaminated soils, and inhalation.

OU 05 and OU 06

Initial investigations on the GEA property were conducted in 1984 and 1985. A second investigation was conducted in 1987 and 1988. VOCs in ground water were detected as high as 112 micrograms per liter ($\mu\text{g/L}$) for DCA, 55 $\mu\text{g/L}$ for DCE, 30 $\mu\text{g/L}$ for 1,2-DCA, 64 $\mu\text{g/L}$ for TCE, 28 $\mu\text{g/L}$ for PCE, and 2.6 $\mu\text{g/L}$ for vinyl chloride. Low concentrations of VOCs were detected in soils. These operable units were concerned with groundwater ingestion being the route of exposure.

Descriptions of the Site hydrology as it pertains to the Operable Units, including the Shallow Zone Aquifer and the Deep Zone Aquifer are provided in **Appendix B**.

Appendix C, Table C-1 lists the issues and basis for taking action, the remedial actions (RA), implementation status, and the actions proposed for each Operating Unit (OU) associated with the South Valley superfund Site.

Response Actions

OU 01 Municipal Wells

A Record of Decision (ROD) for OU 01 was signed on March 22, 1985. The remedy included in the ROD was to replace city water supply wells, San Jose #3 & #6.

RAOs described in the ROD include:

- Provide a new water supply well to replace the capacity of the contaminated well San Jose No. 6.

OU 02 Institutional Controls

A ROD for OU 02 was signed on September 30, 1988. The remedy components selected in the ROD included:

- Plug SJ #3 & #6 wells plus any private wells that might be a conduit from shallow to intermediate aquifers;
- Groundwater monitoring; and
- Access restrictions.

RAOs selected in the ROD include:

- Eliminate potential conduits for shallow groundwater contamination to migrate to lower groundwater zones.
- Restrict the usage of groundwater at or near the site.

OU 03 Univar Ground Water Plume

The ROD for OU 03, issued in June 1988, was to address ground water contamination. The ROD stated that although there were no current users of the ground water within the contaminated plume area, the movement of the plume could impact a major well field for the City of Albuquerque water supply.

OU 03 includes monitoring of ground water, treated water, and ambient air to ensure the effectiveness of the remedy. The risks were assessed according to the Maximum Contaminant Levels (MCLs), set forth under the Safe Drinking Water Act and New Mexico Water Quality Control Commission (NMWQCC) Regulations (New Mexico Administrative Code [NMAC]) (**Table C-2, Appendix C**).

An Explanation of Significant Differences was issued on September 26, 2006, which changed the cleanup goal for PCE from 20 µg/l to 5.0 µg/l. This change did not require a change in the design or operation of the remediation system as the existing remediation system was designed to remediate PCE in groundwater to 5.0 µg/l.

OU 04 Vadose Zone

The ROD for OU4, issued in March 1989, was to address the source of groundwater contamination. The Univar OU 04 soil investigation for potential COCs in the vadose zone determined that the soils did not pose a risk to human health and the environment. The ROD issued in 1989 specified No Further Action.

The OU 04 ROD did include a provision to determine if after groundwater remedial action, whether the soil gases would pose any threat to human health and the environment. A Soil Vapor Extraction (SVE) system was implemented and completed which resulted in non-detect soil vapor concentrations for all VOCs. Thus, it was determined that the soil gases did not pose a threat to human health or the environment.

OU 05 Shallow Zone Aquifer and OU 06 Deep Zone Aquifer

The Former Plant 83/General Electric ROD was signed on September 30, 1988, and covered OU 05 and OU 06. At GEA, the 1988 ROD documented the presence of VOCs and metals in soil and ground water samples collected at the Site. A comprehensive assessment was completed and confirmed that metals concentrations in ground water were not significantly above ARARs. Metals were removed as COCs for OU 05 and OU 06.

The remedy selected in the 1988 ROD, addressed VOCs in soil and in two distinct aquifer zones, later designated as the shallow zone and the deep zone aquifers (note: the deep zone aquifer includes both the intermediate and shallow zones described in the ROD). A list of COCs was not provided in the ROD but three COCs were identified due to their carcinogenic effects: 1,1-DCE, isophorone, and PCE. The shallow and deep ground water zones up to 160 ft bgs required remediation based on risk calculations. Requirements and standards specified in the NMWQCC Regulations had a prominent role in the listing of this site (**Table C-3, Appendix C**).

As part of the site characterization, soil cleanup levels (i.e. action levels) were established for VOCs that were detected in the vadose zone. The VOCs detected in the soil did not pose a threat to human health, however they could dissolve and migrate from the vadose zone to the shallow zone aquifer.

The 1988 ROD required the following response actions:

OU 05:

- Further characterization of the lateral extent of VOCs in the vadose zone and the lateral extent of VOCs in the shallow zone aquifer through the installation of additional monitoring wells;
- Extraction of VOC soil vapors from the vadose zone in Hazardous Waste Storage Areas 1, 3, and 4, at the north end of the North Plant 83 Area and south end of the South Plant 83 Area. Treatment of the extracted soil vapors via vapor-phase activated carbon;
- Extraction and treatment of ground water in the shallow zone aquifer (at a depth of approximately 30 ft bgs) via liquid-phase activated carbon; continue treatment until contaminant concentrations decrease below state and federal regulatory standards; and

OU 06:

- Extraction and treatment of ground water in the deep zone aquifer (at a depth of approximately 160 ft bgs) via air stripping and liquid-phase activated carbon; continue treatment until the contaminant concentrations decrease below state and federal regulatory standards.

Remedial goals selected in the ROD for OU5 included:

- remediating shallow zone groundwater, and
- eliminating source materials via enhanced dewatering, soil flushing, and SVE.

Remedial goals selected in the ROD for OU6 included:

- remediating deep zone groundwater.

An Explanation of Significant Differences was issued on October 16, 2006, which changed the cleanup goal for PCE from 20 µg/l to 5.0 µg/l. This change did not require a change in the design or operation of the remediation system as the existing remediation system was designed to remediate PCE in groundwater to 5.0 µg/l.

Status of Implementation

Remedy implementation activities were conducted during this Sixth Five-Year Review period at OU 03, OU 05, and OU 06 pursuant to the requirements of the South Valley Superfund Site ROD(s) and the decision documents referenced in **Appendix A**.

OU 01

The OU 1 remedy was addressed when the Burton 4 municipal well was installed to replace the use of contaminated City of Albuquerque supply wells, SJ-3 and SJ-6. OU 01 RA objectives were achieved in April 1987. OU 01 was deleted from the NPL on September 23, 2019. OU1 will not be included in this FYR because no hazardous substances remain in this OU above levels that allow for UU/UE.

OU 02

The OU2 remedial action was implemented by plugging and abandonment of several wells that were identified as potential contamination conduits to the shallow and deep ground water zones. Both SJ-3 and SJ-6 municipal wells that contained low levels of VOCs were plugged and abandoned. Ground water use and access restrictions were enforced through the New Mexico Office of State Engineers (NMOSE). OU 02 included the establishment of a monitoring well network containing 23 wells downgradient and north/east of the Site, in the vicinity of SJ-6 (completed between 1990 and 1992). The monitoring program at OU 02 was transferred to OU 06 in 1996, making all OU 02 activities complete except for the associated institutional controls, which remain in place and are considered part of OU 06 per the OU 06 ROD (see below). OU 02 RA objectives were achieved in 1994. OU 02

was deleted from the NPL on September 23, 2019. OU 02 will not be included in this FYR because no hazardous substances remain in this OU above levels that allow for UU/UE.

OU 03 Univar Ground Water Plume

The selected RA was implemented in accordance with the 1990 Consent Decree and the design described in the Remedial Action Plan (RAP) and Remedial Design Report. A ground water monitoring plan to determine the effectiveness of the RAs was also included in the RAP. The RA consisted of the containment and collection of the contaminated ground water using an extraction well system, treatment of the recovered ground water through packed tower aeration and return of the treated water to the aquifer through infiltration galleries. The RAP recovery wells were installed in 1989 and the treatment unit was constructed during the first quarter of 1990. The treatment system was fully operational by the end of 1990. Vadose zone treatment (originally intended for OU 04 remediation) was initiated in 1999 by Univar to improve the efficiency of the extraction system for VOCs in ground water within OU 03. The dissolved chlorinated VOC concentrations were reduced to below ARARs as defined in the ROD, and EPA approved Univar's request for a partial closure of OU 03 for VOCs on June 10, 2014 (Refer to **Appendix B** for additional details).

In November 2009, the EPA required Univar, pursuant to Section XVI(D) of the Univar Consent Decree (CIV 90-0291SC), to evaluate 1,4-Dioxane and to ensure that the 1,4-Dioxane does not pose a threat to human health and the environment. In early 2014, after the collection of groundwater data, a Human Health Risk Evaluation (HHRE) was completed by Univar to evaluate potential human health risks and define site-specific risk-based cleanup goals associated with 1,4-dioxane contamination. The cleanup goals for on-site ground water at Univar was set at 29 micrograms per liter ($\mu\text{g/L}$) or less and off-site ground water (properties not owned by Univar) to 6.7 $\mu\text{g/L}$ or less. On July 27, 2016, EPA and NMED approved Univar's Remedial Work Plan to continue monitoring 1,4-dioxane and to remediate ground water with a treatment system for OU 03. Two recovery wells (RW-05 and RW-06) and three injection wells (IW-01, IW-02, and IW-03) were installed for OU 03 in accordance with the Univar Well Installation Report dated April 27, 2017, and a ground water monitoring program was initiated. Operation of the groundwater recovery system was initiated in March 2018.

OU 05 Shallow Zone Aquifer

The shallow zone ground water remediation system started in May of 1994, which included 30 monitoring wells, eight extraction wells, one injection well, and a ground water treatment system. The remediation system extracted ground water from eight extraction wells. The ground water treatment system at OU 05 was shut down in July 2010. Compliance ground water monitoring and extraction well data from the North Plant 83 indicated all VOCs were below ARARs for at least eight consecutive quarters. EPA approved closure of all wells on the North Plant 83 Area on May 31, 2011. All wells and infrastructure associated with the OU 05 ground water treatment system were plugged and abandoned or removed after remedial and monitoring activities were completed. On November 1, 2011, GEA requested formal closure of the Operable Unit 05 (OU 05) North Plant 83 Area shallow zone ground water remediation system. GEA recorded a Declaration of Restrictive Covenants for the South Plant 83 Area with the Bernalillo County Clerk's Office on September 16, 2014. The restrictive covenant limits property uses and establishes ground water use restrictions and soil engineering controls. GEA requested closure of the OU 05 ROD on September 22, 2014, stating that they had satisfactorily completed all requirements of the Administrative Order dated July 3, 1989.

On April 7, 2017, GEA requested that EPA commence with NPL deletion procedures for OU 05. Remedial Action Closeout Reports for OU 01, dated April 11, 2017, and OU 02 and OU 05, dated January 17, 2018, detailed the completion of the remedial action objectives and goals for the OUs and fulfilled the NPL deletion procedural requirements. OU 05 was determined complete and deleted from the NPL on September 23, 2019. No O&M tasks

were implemented during this FYR period for OU 05. The history and progression of remedy implementations that were completed at OU 05 are documented in previous FYR reports and summarized in the Remedial Action Closeout Report that is Referenced in **Appendix A**.

OU 06 Deep Zone Aquifer

The deep zone aquifer is designated as the aquifer encountered at the site below an elevation of 4,900 ft above mean sea level (amsl). In the 1988 OU 06 ROD, this aquifer is further subdivided for purposes of reference into the intermediate and the deep zones. EPA adopted the five intervals to describe the Deep Zone Aquifer:

- Deep-shallow zone (DS) -4900 to 4840 feet amsl
- Deep-Intermediate zone (DI) - 4840 to 4790 feet amsl
- Deep-Intermediate & Deep-Deep Zone (DD) -4790 to 4660
- Deep-Low-Permeability Zone (DLPZ)- 4660 to 4600 feet amsl
- Below-Deep-Low-Permeability Zone (BDLPZ)- 4600 to 4500 feet amsl

Ground water is encountered at an elevation of approximately 4,900 ft amsl, which corresponds to depths of approximately 49-115 ft bgs. The deep zone ground water remediation system remediates ground water from a 240-ft interval (4,600 to 4,840 ft amsl).

The remediation system began operating in April 1996 and included monitoring wells, extraction wells, injection wells, and a ground water treatment system to remove VOCs from the extracted ground water to concentrations below the ARARs (

Figure C-3, Appendix C). The deep zone ground water remediation system operates by extracting ground water from three to four large diameter extraction wells and conveying it via a dual-walled pipe to the treatment system located on the northwest intersection of Woodward Road and the Albuquerque Metropolitan Arroyo Flood Control Association (AMAFCA) South Diversion Channel. The dual-walled pipe is located within a larger pipe to mitigate a potential for a leak to the subsurface. The extracted ground water is conveyed to the treatment plant via separate pipelines into the influent tank. Phosphate (AquaMag™) is added to the water to prevent scaling of minerals during treatment and injection. AquaMag™ is approved for use in drinking water and drinking water supply aquifers.

IC Summary

In 1988, the State of New Mexico's Engineers Office restricted access to groundwater in and near the site due to the presence of organic contaminants in excess of drinking water standards. All wells drilled in New Mexico must receive a permit from the Engineers Office and thus, are subject to the restrictions employed in 1988.

Upon cessation of manufacturing operations at the GEA South Plant 83 in October 2010, investigations were performed to determine if there was any contamination underneath the buildings. Due to hexavalent chromium and semi-volatile organic compound contamination, GEA performed a removal action in 2011. The area was backfilled with clean fill and capped with concrete. GEA filed a deed restriction in 2014 which identified the areas where contamination exceeded industrial soil screening levels. GEA performs property maintenance inspections to determine the integrity of the capped removal area.

Table 1: Summary of Planned and/or Implemented ICs

| Media, engineered controls, and areas that do not support UU/UE based on current conditions | ICs Needed | ICs Called for in the Decision Documents | Impacted Parcel(s) | IC Objective | Title of IC Instrument Implemented and Date (or planned) |
|--|-------------------|---|--|--|---|
| Ground Water | Yes | Yes | The New Mexico State Engineer designated an area that encompasses the entire South Valley Superfund Site | Restrict use and access to the shallow ground water aquifer to protect the public from potentially contaminated water. | Press Release in 1988 from the New Mexico Office of the State Engineer. |
| Ground Water/Soil | Yes | No | Former South Plant 83, GEA (OU 05) | Restrict ground water use/restricts specific areas from excavation. | Declaration of Restrictive Covenants, September 16, 2014 |

III. PROGRESS SINCE THE LAST REVIEW

This section includes the protectiveness determinations and statements from the last five-year review, as well as the recommendations from the last five-year review and the current status of those recommendations.

Table 2: Protectiveness Determinations/Statements from the 2015 FYR

| OU # | Protectiveness Determination | Protectiveness Statement |
|-----------|------------------------------|---|
| 01 | Protective | The remedy is protective of human health and the environment. |
| 02 | Protective | The remedy is protective of human health and the environment. |
| 03 | Short-term Protective | The remedy currently protects human health and the environment, because the remedy consisting of ground water recovery and treatment functioned as designed. However, in order for the remedy to be protective in the long-term, the presence of 1,4-dioxane in ground water should be evaluated. |
| 04 | Protective | The remedy is protective of human health and the environment. |
| 05 | Protective | The remedy is protective of human health and the environment. |
| 06 | Short-term Protective | The remedy currently protects human health and the environment, because the remedy consisting of water recovery and treatment functioned as designed. However, in order for the remedy to be protective in the long-term, the following actions need to be taken: (1) coordinate with NMED regarding the recent increase of MTBE concentrations; and (2) evaluate and address the TCE and 1,1-DCE concentration increases at a water level elevation of 4,500 to 4,600 ft-amsl. |
| Sitewide* | Short-term Protective | The remedial actions at OU 01, OU 02, OU 04, and OU 05 are protective. The remedial actions at OU 03 and OU 06 are protective in the short-term. However, for OU 03 and OU 06, the recommendations and follow-up actions identified in this FYR process should be addressed to ensure the long-term remedy will remain protective of human health and the environment. |

***Please note:** An incorrect (typographical error) sitewide protectiveness determination was reported in the 2015 FYR. The sitewide protectiveness determination must represent the least protective of the OUs. As can be seen above, the least protective of the OUs has a protectiveness determination of “Short-term Protective”, therefore the sitewide determination should be “Short-term Protective”.

Table 3: Status of Recommendations from the 2015 FYR

| OU # | Issue | Recommendations | Current Status | Current Implementation Status Description* | Completion Date (if applicable) |
|-------------|---|--|-----------------------|--|--|
| 02 | Status of OU 02 remedial requirements | Determine if OU 02 remedial requirements have been achieved or define the monitoring well network and sample frequency for that network of wells associated with OU 02. | Completed | General Electric addressed the status of the OU 02 remedial requirements in a RA Report for OU 02 – All requirements were met. | 1/17/2018 |
| 03 | 1,4-Dioxane- This compound is known to have been used as a stabilizer in solvent at Univar. Its presence above certain levels could affect the future protectiveness of the ground water remedy at OU 03 at this facility. While the quantitative and qualitative risk data for this compound are still in development, a path forward for evaluation should be determined for this compound. | Continue sampling for this compound at OU 03 (Univar). In addition, an evaluation should be performed to determine if additional remedial activities are needed. Proposed monitoring wells should be installed and a remedial action plan developed upon completion of well installations and ground water monitoring. | Completed | On July 22, 2016, Arcadis U.S., Inc on behalf of Univar Solutions USA, Inc. submitted an approved Remedial Work Plan for 1,4-Dioxane in ground water at OU 03. On March 5, 2018, Univar installed and began operation of a recovery, treatment, and injection system (advanced oxidation process) with 1,4-dioxane risk-based cleanup goals of 29 micrograms/L (µg/L) for on-site ground water and 6.7 µg/L for off-site ground water. | 7/27/2016 |
| 06 | 1,1-DCA in Sentinel Well P83-19U. | Evaluate the detection of 1,1-DCA since 2012 in sentinel well P83-19U. | Completed | In the Fifth FYR (July 2015), sentinel monitoring well P83-19U was mentioned as having detectable concentrations of 1,1-DCA (2.3 µg/L) below its ARAR of 25 µg/L. Continued monitoring is warranted. | 3/14/2016 |

IV. FIVE-YEAR REVIEW PROCESS

Community Notification, Involvement & Site Interviews

A public notice was made available by a newspaper posting in the Albuquerque Journal, on September 6, 2019, stating that there was a five-year review and inviting the public to submit any comments to the U.S. EPA. The results of the review and the report will be made available at the following Site information repositories:

Zimmerman Library
Government Information Dept.
University of New Mexico
Albuquerque, NM 87131
505.277.9100

New Mexico Environment Department
Ground Water Quality Bureau
1190 St. Francis Drive, Suite N2300
Santa Fe, NM 87502-5469

During the FYR process, interviews were conducted to document successes and any problems with the remedy that had been implemented to date. Interview records are included in **Appendix D**. The results of these interviews are summarized below.

Interview participants included community members, site contract engineers, consultants, managers, and County representatives. Three community members contacted declined to provide a response. In general, participants agreed that the project continues to progress and is beneficial to the environment. Cleanup activities at the site have not disrupted the nearby community. However, a community representative expressed that some residents are unsatisfied with how contamination cleanup has been addressed and they would like to be better informed about the status of cleanup activities at the South Valley Superfund Site. According to the County, trespassing and illegal dumping continues to be a problem at the Site.

Some interviewees expressed concern for potential human health exposures to hazardous chemicals from the site. They indicated that community members have expressed concerns specifically related to the future development of portions of the South Valley superfund site property. Participants suggested that future development projects could disproportionately pose health risks to the low income and minority populations living nearby. Interviewees also expressed concerns that future development in the area would exclude the local community and benefit only commercial or industrial land use.

Site consultants, contractors, and managers indicated that ARARs have been achieved at three Operable Units and portions of the site have been successfully completed and deleted. Participants explained that the partial NPL deletion of OUs at the Site are beneficial to the community and make the property viable for future use. The remedies implemented have been successful in reducing concentrations of VOCs in the ground water. ARARs in the Deep Ground Water (OU 06) are expected to be achieved with the continued operation of the Remediation System. The remedy implemented at the Site continues to be protective of human health and the environment. Concentrations of 1,4-dioxane are being successfully addressed to at least achieve the onsite and offsite standards of 29 µg/L and 6.7 µg/L, respectively. The treatment system has successfully removed approximately 6 pounds of 1,4-dioxane from the ground water.

Univar and GEA have completed operation and maintenance activities at the site including, rehabilitating extraction wells to improve efficiency and installing additional wells to better address VOCs in the ground water. Difficulties at the Site include the natural bacteria growth and accumulation that occurs when the injection/extraction system is shut down. During this time, well screen intervals become clogged. Well rehabilitation, following system shutdowns, has been costly and in some cases has caused the equipment to fail. The system is periodically shutdown

to improve capture and removal of contaminants in the ground water. Operators are present at the Site at least five days per week and remain on-call daily to address any problems that arise (OU 06). System operation remains costly and the treatment program has achieved asymptotic levels of contaminant removal. At the Univar (OU 03) site, the system is operated remotely and monitored daily. Biweekly site visits are conducted to visually inspect the condition and components of the treatment system.

Data Review

The Site data generated and reviewed during this Sixth FYR period were ground water elevation levels and analytical results for the ground water samples collected at OU 03 and OU 06. As stated previously, all remedial activities associated with OU 04, and OU 05 have been fulfilled and additional data beyond site inspection and IC maintenance were not collected. The data collection and monitoring activities completed during this FYR period satisfy the requirements set forth in decision documents and operation, maintenance and monitoring plans referenced in **Appendix A**.

OU 03 Ground Water Flow

Ground water consistently flows in east to southeast direction across the Site. When the OU 03 treatment system started in March 5, 2018, mounding was observed northwest of the active recovery wells and (partially) near the infiltration gallery. The mounding is influenced by the treated ground water being discharged into the injection well network. A ground water cone of depression was also observed around the recovery wells in response to ground water extractions. As of October 3, 2018, all treated ground water is discharged into the infiltration gallery. The ground water mound observed near the active injection wells started to dissipate and mounding increased near the infiltration gallery (

Figure C-11, **Appendix C**). The cone of depression remains around the recovery wells as the treatment system continues to operate. Despite these influences to ground water beneath the Site, flow continues in a southeasterly direction. Potentiometric surface elevation contour maps are depicted in **Figure C-5** through

Figure C-11, Appendix C.

OU 03 Univar Ground Water Plume

Univar evaluated the existing monitoring well network and submitted the Remedial Work Plan to address 1,4-dioxane contamination in the ground water on May 13, 2016. After EPA approved the Remedial Work Plan on July 22, 2016, additional wells were installed to complete the lateral delineation of the plume. A final well installation report, detailing the completion of two new recovery wells, three injection wells, and the redevelopment of existing wells was provided on April 27, 2017. Univar installed and began operating an Advance Oxidation Treatment System and the ground water recovery and injection system (GRTIS) on March 5, 2018. The treatment system was designed to treat 1,4-dioxane contaminated ground water to a concentration of less than 6.7 µg/L.

The ground water system at OU 03 encompasses recovery wells (RW-02, RW-05, RW-06, and GM-27) and the treated water is injected above the water table via injection wells (VE-4, VE-6, IW-01, IW-02, IW-03) and the infiltration gallery. Depth to ground water was measured periodically during 2018 and quarterly in 2019. Ground water is sampled at least semi-annually using low-flow procedures and/or HydraSleeve™ samplers at the following monitoring wells: GM-02, GM-09S, GM-11S, GM-14S, GM-15S, GM-21, GM-25, GM-26, GM-29, GM-30, RW-04, and I-01 (**Figure C-2, Appendix C**). Samples were collected via a submersible pump using low flow methods and/or hydraSleeve™ samplers. The results discussed herein are depicted in **Figure C-4, Appendix C**.

Operation and maintenance (O&M) activities at OU 03 were conducted, at a minimum, on a bi-weekly schedule during this FYR period. O&M activities were completed in accordance with the Univar Operation, Maintenance and Monitoring Manual (July 31, 2018). The O&M activities implemented were not limited to the inspection and monitoring of GRTIS system components including, tanks and piping, flow rates, and recovery well pressures. Performance sampling and treatment process monitoring activities were also completed to assess the system for optimization. Univar samples the 1,4-dioxane concentrations in the ground water influent and effluent to assess the operational performance of the GRTIS. The performance monitoring results from the Univar Annual 2019 Remediation Report are provided in **Table C-4, Appendix C**.

The system initially operated by conveying treated ground water from the remediation system into the upgradient injection wells. Treated ground water was re-injected into the potentially impacted vadose zone to flush out any 1,4-dioxane contamination. Flow rates were adjusted down and eventually suspended in October 2018, after 1,4-dioxane concentrations decreased. Treated ground water has since been redirected and pumped to the infiltration gallery. Concentrations of 1,4-dioxane gradually rebounded after the shift, facilitating increased contaminant removal from the ground water near GM-27, RW-05, and RW-06. Due to the low concentrations of 1,4-dioxane in samples collected from recovery well RW-2 (near or less than 1.0 µg/L reporting limit), RW-2 operation was suspended. RW-2 is now incorporated into the ground water monitoring program. The ground water monitoring schedule is evaluated and modified annually as needed. Remedy implementation to address 1,4-dioxane and VOCs at OU 03 are further detailed in **Appendix B**.

Since the startup of the GRTIS, considerable progress has been made toward achieving the onsite cleanup goal of 29 µg/L and offsite cleanup goal of 6.7 µg/L for 1,4-dioxane, in the shallow aquifer at the Univar site. The post treatment data described herein includes annual concentration ranges for 2018 and 2019. Data collected during January 22-28, 2016 and April 25-27, 2017 was used to establish pre-remedial, baseline concentrations. The sitewide baseline ground water monitoring results, according to the Univar 2016 Remedial Work Plan, indicated that as many as 20 samples exceeded off-site cleanup goals. The maximum (pre GRTIS startup) concentration was 187 µg/L in a GM-27 duplicate grab sample that was collected.

Concentrations of 1,4-dioxane in onsite upgradient monitoring well GM-09S decreased from 65.4 µg/L in January 2016, to non-detect in the ground water grab samples collected in October 2018 and then increased above onsite cleanup levels of 29 µg/L in April 2019 (43.3 µg/L). Onsite well GM-02 remains below cleanup levels and has steadily decreased from 3.6 µg/L in January 2016, to non-detect in 2019. Similar increasing and decreasing trends were observed in offsite wells since GRTIS operations started.

Offsite cleanup levels of 6.7 µg/L were exceeded in the 2019 hydraSleeve™ samples collected in one downgradient well (GM-29, located east of highway I-25). In January 2016, concentrations from hydraSleeve™ samples were 23.6 µg/L at GM-29 and, by October 2018, were non-detect. In April 2019, concentrations were still reduced overall but had increased to 8.7 µg/L at GM-29.

Remedial goals were achieved in the downgradient offsite well GM-15S by May 2018, and an increase from non-detect to 4.4 µg/L was observed in the hydraSleeve™ samples from April 2019. Concentrations of 1,4-dioxane persist in the other nearby, downgradient offsite wells located east of the I-25 (RW-04, GM-14S, and GM-30; hydraSleeve™ samples). Concentrations were relatively steady since baseline sampling events in 2016 and 2017. The GRTIS capture area is not yet estimated to extend downgradient and east of I-25, where remedial progress remains comparatively slow.

Grab samples from offsite monitoring wells GM-25, GM-26, and I-01 (west of I-25) are all below offsite cleanup goals and have remained relatively steady since baseline sampling. Notable remedial progress has been observed at offsite well GM-21. Baseline 1,4-dioxane concentrations were 143 µg/L (hydraSleeve™ sample) in 2016 and 98.6 µg/L (grab sample) in 2017. Concentrations dramatically decreased to non-detect and 8.4 µg/L in 2018 and cleanup

goals were achieved at GM-21 by April 2019. Progress is slower, but remedial goals have been achieved in the GM-11S well. 1,4-dioxane concentrations decreased from 6.1 µg/L in 2017 to 1.9 µg/L in 2019.

Recovery wells were also sampled monthly, and then quarterly, after the startup of the remedial system. The ground water recovery well network consists of RW-02, RW-05, RW-06, and GM-27. Concentrations of 1,4-dioxane in the recovery wells decreased significantly within two years of GRTIS startup and then remained relatively stable during the period of injection well operation, indicating that flushing of the vadose zone is occurring and that clean water is being successfully captured by the recovery wells.

Concentrations of 1,4-dioxane have remained relatively stable and below cleanup goals in the recovery wells since startup, except for at GM-27, which has shown remedial progress. Recovery well GM-27 historically contained maximum concentrations of 1,4-dioxane (199 µg/L in August 2015 and 102 µg/L in April 2017). The onsite cleanup goals were achieved at GM-27 three months after the GRTIS started in March 2018. Concentrations were as low as 4.1 µg/L in August 2018. Steady increases above offsite remedial goals were observed at GM-27 until 2019, when concentrations stabilized between 28.7 µg/L in February and 24.9 µg/L in April. The initial decreasing trends followed by significant increases observed in the recovery wells at the site coincide with the temporary cessation of treated (clean) ground water discharges into the injection wells IW-1, IW-2, IW-3 and VE-06 on October 3, 2018. Univar recovery well data since GRTIS startup, including the ground water influent and effluent 1,4-dioxane concentrations, is summarized in **Table C-4, Appendix C**.

The GRTIS system operated 99.9% of the time from November through April 2019. Approximately 2.7 pounds of 1,4-dioxane was removed from 40,269,827 gallons of extracted ground water (February 23, 2018 through April 29, 2019). Since March 2018, the combined extracted ground water flow rate has been approximately 65 gallons per minute (gpm). Recovery well flow rates were approximately 25 gpm at RW-05 and RW-06 and 15 gpm at GM-27, with slight fluctuations occurring over time. The mass of 1,4-dioxane that has been removed is estimated to be 2.7 pounds during November 2018 through April 2019. Progress toward achieving offsite and onsite cleanup goals is expected to continue to improve with the continuous operation of the GRTIS.

OU 06 (Deep Zone Aquifer)

Ground Water Level Monitoring

In 2008, the City of Albuquerque terminated pumping operations from municipal supply well Miles-01. Since that time, ground water levels within the Site have steadily risen. During this FYR, ground water elevations have continued to rise on average three to ten feet, depending on the well location and type of well. The ground water flow direction has also changed from a northeasterly direction to a more east-southeasterly direction. Ground water elevations were calculated using ground water measurements from monitoring, injection, and extraction wells. GEA continues to monitor changes in total head fluctuations to identify any influences this may have on the remedial system.

During this FYR period the OU 06 treatment plant operated continuously. Operations were only halted to address system malfunctions, complete maintenance activities, or to implement system optimization measures. According to the GEA Annual Reports from 2015 through 2019, system repairs that were completed included, and were not limited to, replacing and semi-annually back-flushing the activated carbon in two vessels, replacing an air compressor in the treatment plant, and installing a Programmable Logic Controller.

Improvements that have been made to the remediation system include the installation of two extraction wells, EW-005 (December 2014) and EW-006 (January 2015) to target concentrations of 1,1-DCE, TCE, and PCE that persist in monitoring well P83-09D. Injection well IW-636 was replaced with IW-636R in January 2015. The well became operational by June 2015. Until November 15, 2017, the remediation system used four operating extraction wells to capture impacted ground water for subsequent treatment and injection. GEA submitted a plan to implement an

alternate extraction remedy that included transitioning from continuous extraction from four extraction wells (EW003R, EW-004, EW-005, and EW-006) to pulse-pumping, to better address the residual contamination in the Deep Zone Aquifer. The pump was replaced at EW-004 after it failed in March 2019, and the well was fully operational by April.

Since July 24, 2018, the Deep Zone Remediation System has been running three extraction wells, a VOC removal treatment system, a redundant treatment via liquid-phase granular activated carbon, and 11 injection wells (to return treated water to the Deep Zone Aquifer).

Currently, pulse-pumping is ongoing within OU 06. GEA started quarterly monitoring of VOCs in the combined influent. GEA continues to evaluate alternatives to the long-term optimization of the system to achieve RAOs. Complete O&M records are provided in the GEA Annual Reports referenced in **Appendix A**. Overall, the system is functioning as designed. Most of the VOCs have been successfully reduced at OU 06, and mass removal has consequently slowed, reaching asymptotic levels of contaminant removal. A summary of the Performance and Compliance Monitoring schedule for each well at OU 06 is provided in **Appendix C, Table C-5**.

OU 06 Deep Zone Analytical Results

Monthly compliance sampling of treatment system effluent during this FYR demonstrated that VOC concentrations were non-detect before treated ground water was injected back into the aquifer.

The ground water data reviewed herein references the OU 06 COCs and the ARARs in **Appendix C, Table C-3**. The data review covers samples collected in 49 monitoring wells/ ports and 6 extraction wells. The review is organized by samples that were collected in the five designated aquifer zones: DS, DI, DD, DLPZ, and BDLPZ.

Deep-Shallow Zone (DS) (4900 to 4840 feet amsl)

Well data used to represent water quality in the DS zone is obtained from the following monitoring wells/ ports: WB-01(1) and WB-05(1). Samples collected at WB-01(1) were non-detect for all COCs. TCE was the only VOC detected in WB-05(1). Maximum concentrations, below ARARS, were 2.7 µg/L in October 2015 and, in 2019, were decreased to 1.4 µg/L. A MTBE concentration of 3.7 µg/L was detected in WB-05(1) in 2016 and has remained relatively steady in 2019. Note that WB-05(1) is most influenced by extraction well EW-003R (discussed below).

Deep-Intermediate zone (DI) (4840 to 4790 feet amsl)

Well data used to represent water quality in the DI zone is obtained from the following monitoring wells/ ports: P83-07D, P83-09D, P83-19U (sentinel well), P83-22S, P83-29S, WB-01(2), WB-02(1), WB-04(1), WB-05(2), and WB-07(1). Monitoring wells P83-07D, P83-22S, P83-29S, WB-02(1), and WB-07(1) were non-detect for all COCs during this FYR period. ARARs were exceeded in P83-09D for PCE and 1,1 DCE in 2017 and 2018. TCE concentrations have remained above ARARs at P83-09D since 2017.

The cleanup level for PCE is based on the MCL which is 5 µg/L. PCE increased in well P83-09D from 1.5 µg/L in 2015 to 7.4 µg/L in April 2018. PCE concentrations decreased to 4.7 µg/L in 2019. Similarly, TCE concentrations increased from 3.2 µg/L in 2015 to 16 µg/L in 2018 and subsequently decreased to 9.9 µg/L in 2019. Concentrations in WB-05(2) persist below ARARs for PCE (ranging from 1.2 µg/L in 2019 to 1.7 µg/L in 2016) and TCE (ranging from 1.3 µg/L in 2015 to 3.5 µg/L in 2016).

1,1-DCE exceeded ARARs in P83-09D in 2017 through 2018, with concentrations at 6.8 µg/L in January 2018. In 2019, 1,1-DCE was below ARARs (4.1 µg/L). Similar rising and falling trends below ARARs occurred for 1,1-DCA and 1,2-DCA at this well during the same time period and likely coincide with the extraction and pumping activities implemented at EW-003R (discussed in the following sections).

Only 1,1-DCA was detected below ARARs (ranging from 1.2 µg/L to 2.8 µg/L) at sentinel monitoring well P83-19U from 2015 to 2018 (and a single detection of 2.0 µg/L at P83-29S in 2015). Samples collected at P83-19U exhibited non-detects for all COCs by October 2018. In the Fifth FYR (July 2015), sentinel monitoring well P83-19U was mentioned as having detectable concentrations of 1,1-DCA (2.3 µg/L) below its ARAR of 25 µg/L. Discussions with EPA and GEA concerning detections in the sentinel well, could not identify the source of the 1,1-DCA. One possible source discussed included a former landfill located adjacent to P83-19U.

MTBE was detected at WB-05(1) at concentrations ranging from 1.9 µg/L in 2015 to 3.7 µg/L in 2017. MTBE was non-detect at well P83-09D in 2016 and continued to show gradual increases to 6.4 µg/L in 2019.

Deep-Intermediate & Deep-Deep Zone (DD) (4790 to 4660 feet amsl)

Well data used to represent water quality in the DD zone of the aquifer was obtained from the following monitoring wells/ports: P83-19M (sentinel well), P83-22M, P83-22D, P83-26M, P83-26D, WB-01(3), WB-01(4), WB-01(5), WB-02(2), WB-04(2), WB-04(3), WB-05(3), WB-05(4), WB-07(2), WB-07(3), and WB-07(4). ARARs were briefly exceeded during this FYR period at WB-01(03) and WB-01(4), however, in 2019, all COCs in the DD zone were below ARARs.

Trace PCE was detected in West Bay wells WB-05(4), WB-01(5), WB-01(4), and WB-01(3). PCE detections at WB-01(3) and WB-05(4) were reduced in 2019 from respective highs of 2.1 µg/L (April 2018) and 1.5 µg/L (January 2018). All other wells containing PCE were reduced to non-detect by at least 2017. TCE concentrations at WB-01(03) increased from 2.6 µg/L in 2015 to above ARARs (5.5 µg/L) in April 2018 and, by 2019, concentrations decreased again to 2.8 µg/L. TCE concentrations at WB-01(05) steadily decreased from 2.4 µg/L in 2015 to non-detect in 2018. Except for WB-01(03), TCE was non-detect in all DD well samples in 2019.

In 2015, 1,1 DCE was above ARARs (6.4 µg/L) at WB-01(4), however, non-detect concentrations were achieved by 2016. 1,1-DCE detections steadily increased at WB-05(4) from 1.7 µg/L in 2017 to above ARARs in 2018. Concentrations reached a high of 8.3 µg/L in July 2018 and in 2019 were decreased to just below ARARs. Trace detections for 1,1-DCE and 1,1-DCA were also reported in WB-01(3) during this FYR period.

Chloroform was detected at WB-01(4) at concentrations ranging from 1.6 (2018) to 11 µg/L (April 2016) and were non-detect by April 2018 (the ARAR for chloroform is 80 µg/L). Chloroform was not detected at any other location during the FYR period. Trace detections of MTBE were only at WB-01(3) from April 2018 to January 2019. All other DD zone monitoring wells (P83-19M-sentinel well, P83-22M, P83-22D P83-26M P83-26D WB-02(2) WB-07(4) WB-04(2) WB-04(3) WB-07(2) WB-07(3) and WB-07(4)) were non-detect for all COCs during this FYR period.

Deep-Low-Permeability Zone (DLPZ) (4660 to 4600 feet amsl)

Well data used to represent water quality in the DLPZ is obtained from the following sample locations at monitor wells/ports: P83-19LR, WB-01(6), WB-02(3), WB-04(4), and WB-05(5). Well samples collected at P83-19LR, WB-01(6), and WB-02(3) were non-detect for all COCs during this FYR period.

Trace PCE (1 µg/L) was detected at WB-05(5) only in October 2015. TCE was detected below ARARs at WB-04(4). Concentrations gradually increased from initial detections in 2016 to a high of 2.2 µg/L in January 2019 and, by April 2019, were non-detect. According to the 2014-2015 GEA Annual Report, 1,1-DCE at WB-05(5) was detected above ARARs, ranging from 5.2 µg/L to 7.1 µg/L. Beginning in 2016, concentrations were decreased to below ARARs (ranging from 2 µg/L to 3.3 µg/L in 2019). 1,1-DCA was also detected consistently below ARARs at WB-05(5) throughout the FYR period and at WB-04(4) from 2018 through January 2019.

Below-Deep-Low-Permeability Zone (BDLPZ) (4600 to 4500 feet amsl)

Well data used to represent water quality in the BDLPZ is obtained from samples collected at the following monitoring wells/ports: WB-02(4), WB-02(5), WB-04(5), WB-04(6), WB-05(6), P83-19D-2, P83-22D-2,

WB-07(5), and P83-30D-2 (sentinel well). PCE decreased at WB-04(5) from 14 µg/L in July 2015 to non-detect in 2018. Concentrations (2.3 µg/L in 2015) at WB-02(4) were also non-detect by 2017. TCE decreased significantly in both WB-04(5) and WB-02(4) and persists at concentrations below ARARs. High TCE concentrations at WB-04(5) were 31 µg/L at the start of the FYR period and in 2019 were reduced to 1.4 µg/L.

Decreasing trends from above ARARS (15µg/L in 2015) to non-detect in 2019 were also indicated in WB-04(5) for 1,1-DCE. Detections of 1,1-DCA and 1,2-DCA were reduced to non-detect at WB-04(5) beginning in 2017 and 2018, respectively. In WB-02(4), concentrations of 1,1-DCE (1.2 µg/L) and 1,1-DCA (1.5 µg/L) continue to persist at low levels in 2019. Note that WB-02(4) and WB-04(5) are in an area that is most influenced by extraction activities at EW-004. All other samples collected at wells within the BDLPZ were non-detect for all COCs.

Extraction Wells

In 2015, extraction wells EW-005 and EW-006 were installed to improve contaminant extraction. At the beginning of this FYR period, extraction wells EW-003R, EW-004, EW-005, and EW-006 were operational (**Figure C-3, Appendix C**). PCE was only detected in EW-006 in 2015 (2.5 µg/L) and 2016 (1.8 µg/L) and remained non-detect in all extraction wells thereafter. TCE was detected above ARARs (6.4 µg/L) only in 2015 at EW-006 and decreased to 1.4 µg/L in 2019. TCE was detected at a concentration of 1.3 µg/L at EW-003R and 1.0 µg/L at EW-004 at the beginning of the FYR period. Concentrations returned to non-detect in both wells by 2017 and 2016, respectively.

Non-detect levels of 1,1-DCA and 1,1-DCE were achieved in all extraction wells by 2018. Only EW-003R, EW-005, and EW-006 had detections below ARARs at the start of the FYR period, with highest detections of 1,1-DCE (3.7 µg/L) and 1,1-DCA (4.2 µg/L) at EW-006.

OU 06 VOC Mass Removal

GEA calculated total VOC mass removal based on treated ground water extraction volumes and the average total VOC concentrations removed. GEA's assessment is a combined total sum of detectable VOC concentrations for 1,1-DCA, 1,1-DCE, 1,2-DCA, PCE, and TCE. Approximately 17.6 lbs. of VOCs were removed from approximately 989 million gallons of extracted and treated ground water via the Deep Zone Remediation System from August 2015 through June 2019. Since April 1996, 7.7 billion gallons of ground water has been treated and an accumulative VOC mass of 1,568.5 lbs. has been removed. VOC mass removal was improved in 2015 in the 4600 to 4570 aquifer depth intervals, following the installation of two extraction wells. Mass removal was 9.1 lbs. from 2015 to 2016, compared to 4.8lbs from 2014 to 2015. VOC mass removal in the subsequent years was 6.1 lbs. (2016 to 2017), 4.2 lbs. (2017 to 2018), and 0.0 lbs. (2018 to 2019). Since April of 2018, progress in VOC mass removal has led to asymptotic conditions at the site. Complete mass removal data since the startup of the remedial system in 1996 is provided in Table 4 of GE Annual Reports for the Ground Water Remediation System (Reports from 2015 through 2019 are referenced in **Appendix A**).

OU 06 Summary

During the last (Fifth) FYR period, 1,1-DCA was detected at low levels (from 1.2 µg/L to 2.3 µg/L – below cleanup level of 25 µg/l) in three sentinel wells (P83-19U, P83-19M and P83-30D2) located east and down-gradient of the deep zone remediation system and the capture zone. These wells are monitored to determine if contaminants in the Deep Zone are migrating. P83-30D2 samples never exhibited VOC detections and it had been over 10 years since VOCs were detected in samples collected from the other two wells. Analytical results for P83-19U continued to show 1,1-DCA at levels as high as 3.3 µg/L in October 2013. During this FYR period, concentrations in P83-19U ranged from 1.2 µg/L to 2.8 µg/L. Samples collected at P83-19U exhibited non-detects by October 2018. All detections were below the ARAR of 25 µg/L. P83-19M and P83-30D2 were non-detect for all COCs during this FYR.

Significant progress has been made during this FYR period to capture and treat residual contamination in OU 06. Monitoring wells with detectable concentrations of VOCs have remained the same or declined, with only TCE being detected above ARARs in P83-09D at the end of this FYR period. The installation of extraction wells

EW-005 and EW-006 enhanced extraction rates and VOC capture in the Deep Zone Aquifer. The success of remedy implementations at OU 06 has led to the attainment of asymptotic conditions; consequently, in 2018 through 2019, 241 million gallons were extracted, and an estimated zero pounds of VOCs were removed. GEA continues to explore cost effective remedy enhancements to further improve the removal of residual contaminants in the ground water at the Site.

Site Inspection

The inspection of the Site was conducted on October 21, 2019 at Univar and October 22, 2019 at GEA. The South Valley Superfund Site Five-Year site inspections were led Mr. Bill Pearson and Mr. Angelo Ortelli, of the New Mexico Environment Department (NMED), Ground Water Quality Bureau (GWQB), Superfund Oversight Section (SOS). Participants for the Site inspection at Univar included: Ms. Katy Brantingham, Associate Vice President, Arcadis US, Inc. Participants at GEA included: Ms. Julie Einerson, Owner, Genesis Environmental, Safety, and Health, LLC.; John Billiard, Technical Services Director, and Leonard Stockton, Senior Engineer, Axis Group, Inc. The purpose of the inspection was to assess the current condition of the remedy components and monitoring network.

GEA Inspection

The site inspection team discussed the treatment system and treatment system components for the OU 06 Deep Zone Aquifer Remediation system. Equipment and components associated with remedial systems appeared to be in good working order. The remediation treatment buildings are located within a secure, fenced area. All hazardous materials on-site are properly stored. All pertinent documents were on-site, readily available, and up-to-date.

The former GEA South Plant (OU 05) was inspected. All monitoring and production wells have been plugged and abandoned. Cement caps were installed over all of the soil contamination removal areas. Concrete flooring from the former production buildings, storm water drainage channels, and cement caps, are all that remain. Weeds and sapling tree growth is being managed.

At the GEA North Plant (OU 05), all monitoring and extraction wells have been plugged and abandoned and the infrastructure has been removed. The roads and sidewalks appear to be maintained in good condition. Both Plants (North and South) are presently listed for sale.

The inspection team inspected several monitoring wells (WB-01, WB-04, WB-05, P83-09D) and extraction wells (EW-003R, EW-004, EW-005). All monitoring, extraction and injection wells were locked and secure from vandalism or theft.

Univar Inspection

The general appearance of OU 03 is in excellent condition and well maintained. Equipment associated with the remedial system (advanced oxidation) appeared to be well serviced and maintained. The remediation treatment buildings and many of the wells are located within a fenced secure area. All wells were locked and secure. The wells located outside of the fenced secure area were locked and secure from vandalism and theft. All hazardous materials on-site are properly stored. All exterior security fences were in excellent condition. All pertinent documents were on-site, readily available and up to date. All treated water from the advance oxidation system is being discharged to the infiltration gallery.

The areas associated with OU 03 and OU 06 continue to be plagued by illegal dumping, mostly of household items and construction debris. Dumping activities do not appear to have affected access to wells in either OU.

V. TECHNICAL ASSESSMENT

QUESTION A: Is the remedy functioning as intended by the decision documents? Yes

Question A Summary:

The review of documents, monitoring data, and the results of the site inspection indicates that the remedy components are functioning as intended at OU 03 and OU 06. Remedial action goals and objectives have been achieved at OU 01, OU 02, OU 04 and OU 05. OU 01, OU 02, and OU 05 have been deleted from the NPL for the Site. The following briefly describes the remedial action status at OUs 03, 04, 05 and 06.

OU 03 Univar

The remedial systems at OU 03 (Univar) have decreased the concentrations of VOCs to below the ARARs. The RA has achieved the requirements of the ROD signed on June 28, 1988 and the Consent Decree dated March 27, 1990. The concentrations of COCs (excluding 1,4-dioxane) were less than the clean-up goals for at least eight consecutive sampling events before ground water sampling and treatment was discontinued. On June 10, 2014, EPA approved Univar's request to close OU 03 for VOCs, except for 1,4-dioxane.

On November 19, 2009, EPA notified Univar to evaluate the occurrence of 1,4-dioxane in various wells and determine if it posed a threat to human health and the environment. On January 14, 2010, EPA approved the planned evaluation of 1,4-dioxane in ground water and approved a Remedial Work Plan to address 1,4-dioxane in ground water, on July 22, 2016. On March 5, 2018, Univar began the remediation of 1,4-dioxane in ground water and continues to operate the treatment plant and extraction/injection system as designed. The advance oxidation process, along with the flushing of the vadose zone with treated water, has resulted in a significant reduction (< 12 months) in 1,4-dioxane ground water concentrations. Continued operation of the treatment system is needed to remove additional residual 1,4-dioxane from groundwater.

OU 04 Univar

The ROD for OU4, issued in March 1989, was to address the source of groundwater contamination. The Univar OU 04 soil investigation for potential COCs in the vadose zone determined that the soils did not pose a risk to human health and the environment. The ROD issued in 1989 specified No Further Action.

The OU4 ROD did include a provision to determine if after groundwater remedial action, whether the soil gases would pose any threat to human health and the environment. A Soil Vapor Extraction (SVE) system was implemented and completed, which resulted in non-detect soil vapor concentrations for all VOCs. Thus, it was determined that the soil gases did not pose a threat to human health or the environment.

OU 05 – GEA Shallow Zone

All remedial actions have been completed concerning OU 05. GEA filed a deed restriction in 2014 which identified the areas where soil contamination exceeded industrial soil screening levels. GEA performs property maintenance inspections to determine the integrity of the capped removal area.

OU 06 GEA Deep Zone

The remedial system at OU 06 (the deep zone aquifer at GEA) has reduced the mass and volume of contaminants in the deep zone aquifer and the plume is contained and stable. The remedy continues to operate and function as designed. The deep zone ground water plume has been reduced to one small area near monitoring well P83-09D, with concentrations of TCE above ARARs. All other VOCs are below ARARs. The ground water treatment system effectively treats extracted ground water for reinjection back into the aquifer. The Deep Zone pump and treat system

has reached a state of asymptotic remediation efficiency. GEA continues to pulse-pump extraction wells to improve extraction efficiencies. They are also exploring remedy enhancements to address the remaining VOC contamination.

QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid? Yes

Question B Summary:

The selected remedies for the South Valley Site were selected to eliminate the VOCs within the Site soils and to restore ground water under and near the Site to levels below State and Federal regulatory standards.

To Be Considered (TBCs) requirements identified within the RODs have been revised or changed since the last FYR. New Mexico Water Quality Control Commission (WQCC) Ground Water standards (20.6.2.3103 NMAC) were revised in December 2018, but did not change the Site clean-up goals as listed in **Table C-2** and **Table C-3, Appendix C**. Exposure pathways; land use, health receptors and routes of exposure, ecological receptors and routes of exposure, newly identified contaminants or source areas, toxic byproducts or changes in site conditions, have not changed or been revised since the last FYR. Toxicity factors for COCs and contaminant characteristics have not changed in any way to change or impede the protectiveness of the remedies since the last FYR.

Progress toward meeting RAOs has advanced as anticipated.

- OU 03 – OU 03 is progressing as expected towards meeting restoration of the groundwater with no issues affecting remedy protectiveness.
- OU 04 – OU 04 has met the objective to ensure that the soils and soil vapor do not pose a risk to human health and the environment and there are no issues affecting remedy protectiveness.
- OU 05 – OU 05 has met the objective to restore the groundwater and to ensure the soils do not pose a risk to human health and the environment, and there are no issues affecting remedy protectiveness.
- OU 06 – OU 06 is progressing as expected towards meeting restoration of the groundwater, with no issues affecting remedy protectiveness.

QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy? No

No other information has come to light that could affect the protectiveness of the remedies. There are no additional risks or previously unidentified risks that could affect performance or protectiveness of the identified remedies.

VI. ISSUES/RECOMMENDATIONS

| Issues/Recommendations |
|---|
| OU(s) without Issues/Recommendations Identified in the Five-Year Review: |
| <i>OU 03, OU 04, OU 05, OU 06</i> |

OTHER FINDINGS

In addition, the following are recommendations that were identified during the FYR, but do not affect current and/or future protectiveness:

- Increase the frequency of public updates and dissemination of information concerning the progress of the remedy at the Site. In addition, communication of GEA's continued commitment to complete the cleanup of the OUs for which they are responsible, should alleviate concerns that cleanup will be impacted by GEA closing the facility in Albuquerque.
- A public meeting was held on December 11, 2018 to discuss the completion and deletion of OU 01, OU 02 and OU 05. Public notices were published in the local paper and paper notices were mailed out to individuals on the mailing list. During this time, an information session was held where remedial progress at the site was communicated and individuals were able to ask questions and express concerns. Additional public meetings will be scheduled in the future as needed to ensure the public remains up-to date.
- Monitoring results from OU 06 indicate that the system has reached asymptotic contaminant levels. Remedy optimization should be explored to improve removal of remaining VOC contamination.
- Re-evaluate the need for a deed restriction on OU 05, given the significant amount of contaminated soil removed.

VII. PROTECTIVENESS STATEMENT

| Protectiveness Statement(s) | |
|---|--|
| <i>Operable Unit:</i> OU 03 | <i>Protectiveness Determination:</i> Protective |
| <i>Protectiveness Statement:</i> The remedy is protective of human health and the environment. | |

| Protectiveness Statement(s) | |
|---|--|
| <i>Operable Unit:</i> OU 04 | <i>Protectiveness Determination:</i> Protective |
| <i>Protectiveness Statement:</i> The remedy is protective of human health and the environment. | |

| Protectiveness Statement(s) | |
|---|--|
| <i>Operable Unit:</i> OU 05 | <i>Protectiveness Determination:</i> Protective |
| <i>Protectiveness Statement:</i> The remedy is protective of human health and the environment. | |

| Protectiveness Statement(s) | |
|---|--|
| <i>Operable Unit:</i> OU 06 | <i>Protectiveness Determination:</i> Protective |
| <i>Protectiveness Statement:</i> The remedy is protective of human health and the environment. | |

| Sitewide Protectiveness Statement | |
|--|--|
| <i>Protectiveness Determination:</i> Protective | |
| <i>Protectiveness Statement:</i> The remedial actions at OU 03, OU 04, OU 05, and OU 06 are protective. | |

VIII. NEXT REVIEW

The next five-year review report for the South Valley Superfund Site is required five years from the completion date of this review.

APPENDIX A – REFERENCE LIST

Reference List

Aestus. 2006a. 2005-2006 Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Ground water Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site, Albuquerque, New Mexico. 15 August.

Aestus. 2006b. 2005-2006 Annual Report and Semi-Annual Quality Assurance Report Deep Zone Ground water Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site, Albuquerque, New Mexico. 15 August.

Aestus. 2006c. Letter Proposing Changes to the October Sample Event GE/Plant 83 Superfund Site, Albuquerque, New Mexico. 18 September.

American Ground-Water Consultants. 1983. Hydrogeology of the AmeriGas Property, Albuquerque, New Mexico: Prepared for Counsel to AmeriGas, Inc., Valley Forge Pennsylvania.

ARCADIS. 2005a. Third Five-Year Review of Remedial Actions, Univar USA, Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. 2 September.

ARCADIS. 2005b. Letter Report to Mr. Gregg Lyssy, U.S. Environmental Protection Agency Regarding Installation of Two Additional Ground water Monitoring Wells and Abandonment of Two Ground water Monitoring Wells Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. 21 December.

ARCADIS. 2006a. 2006 Annual Progress Report for Remedial Actions, Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. 14 July.

ARCADIS. 2006b. Work Plan to Optimize the Future Remedial Activities, Univar USA, Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. 7 September.

ARCADIS. 2007. February 2007 Quarterly Sampling of Ground water Monitoring Wells Univar USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. 19 March.

ARCADIS. 2008. Letter Summarizing the 5 December 2007, Meeting with EPA. 28 January.

ARCADIS. 2010a. Letter from Ms. Kathryn Brantingham of ARCADIS to Mr. Michael Hebert of EPA, in Response to EPA Letter Regarding 1,4-Dioxane. 7 January.

ARCADIS. 2010b. October 2009. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 15 January.

ARCADIS. 2010c. January 2010. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 5 April.

ARCADIS. 2010d. April 2010. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 21 July.

ARCADIS. 2010e. July 2010. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 22 September.

ARCADIS. 2011. October 2010. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 17 January.

ARCADIS. 2011. February 2011. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 3 May.

ARCADIS. 2011. April 2011. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 7 July.

ARCADIS. 2011. July 2011. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 3 October.

ARCADIS. 2011. Letter from Ms. Kathryn Brantingham of ARCADIS on behalf of Univar detailing proposed investigation actions for 1,4-Dioxane. 4 October.

ARCADIS. 2012. October 2011. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 12 January.

ARCADIS. 2012. February 2012 8-Hour Pumping Tests and March 2012 Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 29 May.

ARCADIS. 2012. Work Plan for Extended Pump Test and Treatment Pilot Study for 1,4-Dioxane. 31 May.

ARCADIS. 2013. December 2012. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 18 January.

ARCADIS. 2013. February 2013. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 15 April.

ARCADIS. 2013. Extended Pump Test and Treatment Study Final Report. 24 June.

ARCADIS. 2013. June 2013. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 21 August.

ARCADIS. 2013. Human Health Risk Evaluation for 1,4-Dioxane. 18 October.

ARCADIS. 2013. September 2013. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 19 November.

ARCADIS. 2013. November 2013. Quarterly Sampling of Ground water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 19 December.

ARCADIS. 2014. Human Health Risk Evaluation for 1,4-Dioxane. Revised. 17 January.

ARCADIS. 2014. Monitoring Well Drilling and Installation and Ground Water Monitoring Network Work Plan. 24 January.

ARCADIS. 2014. Letter from Katy Brantingham of ARCADIS on behalf of Univar submits Notice of Completion of Consent Decree Requirements for Constituents of Concern (VOCs). Does not include 1,4-Dioxane. 2 June.

ARCADIS. 2014. July 2014. Quarterly Sampling of Ground Water Monitoring Wells, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 3 October.

ARCADIS. 2015. Monitoring Well Drilling and Installation Report, Univar USA, Inc, 3301 Edmunds Street, Albuquerque, New Mexico. 2 September.

ARCADIS. 2016. Remedial Work Plan, For 1,4-Dioxane In Groundwater Univar USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. July 22.

ARCADIS. 2017. Well Installation, Univar, USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. April 27.

ARCADIS. 2017. Groundwater Monitoring Activities, Univar USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. July 13.

ARCADIS. 2018a. Treatment System Construction Report for 1,4-Dioxane in Groundwater. Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. July 31.

ARCADIS. 2018b. Operation, Monitoring, And Maintenance Manual Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. July 31.

ARCADIS. 2018c. 2018 Remediation Progress Report, For Remedial Actions at Operable Unit 3 of the South Valley Superfund Site in Albuquerque, New Mexico. December 7.

ARCADIS. 2019a. Field Sampling Plan, For 1,4 Dioxane in Groundwater Treatment Project. Univar USA Inc. 3301 Edmunds Street Albuquerque, New Mexico. 23 April.

ARCADIS. 2019b. 2019 Annual Remediation Progress Report, For Remedial Actions at Operable Unit 3 of the South Valley Superfund Site in Albuquerque, New Mexico. June 26.

Axis Group, Inc. (Axis). 2007a. 2006-2007 Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2007b. 2006-2007 Annual Report and Semi-Annual Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2007c. Request to Terminate North Plant 83 Operations. Shallow Zone Groundwater Remediation System. 11 September.

Axis. 2007d. Approval Letter to Terminate North Plant 83 Operations Shallow Zone Groundwater Remediation System. 5 November.

Axis. 2008a. Letter Work Plan to Optimize the Deep Zone Groundwater Remediation System. 2 April. Axis. 2008b. 2007-2008 Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2008c. 2007-2008 Annual Report and Semi-Annual Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2008d. Performance and Compliance Monitoring Plan Revision 2008 Deep Zone and Shallow Zone Groundwater Remediation Systems Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 21 October.

Axis. 2009a. Transmittal Updated 2/17/09 - Performance and Compliance Monitoring Plan - Revision 2008 Deep Zone and Shallow Zone Groundwater Remediation Systems Former Air Force Plant 83/General Electric Aviation Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 17 February.

Axis. 2009b. Follow-Up to Conference Call Shallow Zone Groundwater Extraction Well and SEW-10 and Monitoring Well SW-08. 13 April.

Axis. 2009c. 2008-2009 Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2009d. 2008-2009 Annual Report and Semi-Annual Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2009e. Request to Implement Closure Plan North Plant 83 Area Wells Former Plant 83/GE Operable Unit Albuquerque, New Mexico. 10 November.

Axis. 2010a. 2009 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2010b. 2009 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2010c. Work Plan to Conduct a Chemical Injection Remediation Program, Shallow Zone Aquifer SW-08 and SEW-05 Areas Former Plant 83/GE Operable Unit, South Valley Superfund Site. 15 March.

Axis. 2010. 2009-2010. Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2010. 2009-2010. Annual Report and Semi-Annual Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2011. 2010-2011. Annual Report and Semi-Annual Quality Assurance Report Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2011. 2010-2011. Annual Report and Semi-Annual Quality Assurance Report Deep Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2012. 2011-2012. Annual Report and Semi-Annual Quality Assurance Report Deep Zone and Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2013. 2012-2013. Annual Report and Semi-Annual Quality Assurance Report Deep Zone and Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2014a. Fourth Revision, Performance Monitoring Compliance Program. 16 April.

Axis. 2014b. 2013-2014. Annual Report and Semi-Annual Quality Assurance Report Deep Zone and Shallow Zone Groundwater Remediation System Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August.

Axis. 2014c. Axis on behalf of GEA submitted Work Plan to Optimize the Deep Zone Remediation System, Operable Unit 06. 25 August.

Axis. 2015a. 2015 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report, Deep Zone Groundwater Remediation System, Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2015b. 2014-2015 Annual Report and Semi-Annual Quality Assurance Report, Deep Zone Groundwater Remediation System, Shallow Zone Groundwater Remediation System Closure (South Plant 83 Area), Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August

Axis. 2016a. 2016 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report, Deep Zone Groundwater Remediation System, Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2016b. 2015-2016 Annual Report and Semi-Annual Quality Assurance Report, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August

Axis. 2017a. 2017 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report, Deep Zone Groundwater Remediation System, Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2017b. 2016-2017 Annual Report and Semi-Annual Quality Assurance Report, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August

Axis. 2017c. Remedial Action Report, San Jose 6 Operable Unit, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 11 April

Axis. 2017d. Notification of Intention to Modify Deep Zone Groundwater Remediation System Retraction Rates, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 23 October

Axis. 2018a. 2018 Semi-Annual Report, Third and Fourth Quarters-Quality Assurance Report, Deep Zone Groundwater Remediation System, Former Air Force Plant 83/General Electric Operable Unit South Valley Superfund Site Albuquerque, New Mexico. 15 February.

Axis. 2018b. 2017-2018 Annual Report and Semi-Annual Quality Assurance Report, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August

Axis. 2019a. Revised Request for Authorization to Plug and Abandon Monitoring Wells, Operable Unit 6, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 2 May

Axis. 2019b. 2018-2019 Annual Report and Semi-Annual Quality Assurance Report, Former Air Force Plant 83/General Electric Operable Unit, South Valley Superfund Site Albuquerque, New Mexico. 15 August

Billiard, John. 2010. Distribution of Charts for Concentrations of Volatile Organic Compounds in Samples Collected from Monitoring and Extraction Wells Associated with the Deep Zone Aquifer Treatment System. Electronic Communication. 3 and 4 March.

Canonie Environmental Services, Corp. (Canonie). 1993a. Remedial Design Plan, Shallow Zone Ground Water Extraction and Treatment System, Plant 83/General Electric Operable Unit, South Valley Superfund Site, Albuquerque, New Mexico, General Electric Aircraft Engines, Albuquerque, New Mexico. July.

Canonie. 1993b. Proposed Cleanup Goals Volatile Organic Compounds in Soil General Electric Aircraft Engines Plant 83/GE Operable Unit. April.

Canonie. 1994. System Monitoring Plan, Appendix B of the Remedial Design Plan, Shallow Zone Ground Water Extraction and Treatment System General Electric Aircraft Engines, Albuquerque, New Mexico. Revised. 26 April.

Canonie. 1995. Deep Zone Groundwater Remediation System, 100% Design Report, Volumes 1, 2, 3, and 4. June.

D'Appolonia Waste Management Services. 1983. Geophysical Survey of Van Waters & Rogers Inc. Facility, Albuquerque, New Mexico. 24 March.

D'Appolonia Waste Management Services. 1984. Evaluation of Soil and Water Contamination at the AmeriGas Property, South Valley, Albuquerque, New Mexico (Final Report). Prepared for Counsel to Van Waters & Rogers Inc. (Univar Corporation), Seattle, Washington.

DBS&A 2010. Daniel B Stevens & Associates (DBS&A) submitted to EPA a Sump Investigation Work Plan for the GEA Manufacturing Plant closure. 9 December.

DBS&A 2011. Sump Inspection and Investigation Report. 4 August.

DBS&A 2012. Final Closure Report, GE Aviation Manufacturing Plant. 18 June.

(United States) Environmental Protection Agency (EPA). 1984. Final Focused Feasibility Study, South Valley Hazardous Waste Site, Albuquerque, New Mexico. 25 July.

EPA. 1985. Record of Decision for South Valley Operable Unit 01; EPA/ROD/R06-85/006. 22 March.

EPA. 1988a. Remedial Investigation Report, SJ-6 Superfund Site, South Valley Area, Albuquerque, New Mexico. May.

EPA. 1988b. ROD for South Valley Site Edmunds Street Ground Water OU. 28 June.

EPA. 1988c. Feasibility Study Report, SJ-6 Superfund Site, South Valley Area, Albuquerque, New Mexico. June.

EPA. 1988d. ROD for San Jose 6 (SJ 6) Superfund Site, Albuquerque, New Mexico. 30 September.

EPA. 1988e. ROD for Former Air Force Plant 83/General Electric Superfund Site, Albuquerque, New Mexico. 30 September.

EPA. 1989a. ROD Edmunds Street Property Source Control, South Valley Superfund Site. 30 March.

EPA. 1989b. Administrative Order, South Valley Superfund Site, Docket Number CERCLA 6-16-89 (Former Air Force Plant 83/General Electric Operable Unit). 16 June.

EPA. 1990a. Consent Decree in the Matter of the United States of America versus Univar Corporation. Entered on Docket on 27 March.

EPA. 1991. Unilateral Administrative Order to Chevron USA, Inc.; Phillips Pipe Line Company; Texaco Pipeline Inc.; and West Emerald Pipeline Corporation. October.

EPA. 2001. "Comprehensive Five-Year Review Guidance." EPA 540-R-01-007. June.

EPA. 2005. Approval of the Third Five-Year Review at the South Valley Superfund Site for Edmunds Street OU 3, General Electric Aircraft Engines OU 02, General Electric Aircraft Engines OU 05, and General Electric Aircraft Engine OU 06. 26 September.

EPA. 2006a. EPA Letter Regarding Proposed Changes to the October Sampling Event, Former Air Force Plant 83/General Electric Operable Unit at the South Valley Superfund Site, Albuquerque, New Mexico. 22 September.0

EPA. 2006b. Letter from Mr. Bret Kendrick of EPA, to Mr. George Sylvester of Univar USA, Inc. regarding the Work Plan to Optimize Future Remedial Activities for the Edmunds Street Ground Water OU at the South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. 22 September.

EPA. 2006c. Explanation of Significant Differences, South Valley Superfund Site Edmunds Street Ground Water OU, Albuquerque, Bernalillo County, New Mexico. 26 September.

EPA. 2006d. Explanation of Significant Differences, South Valley Superfund Site Former Air Force Plant 83/General Electric Operable Unit Albuquerque, Bernalillo County, New Mexico. 13 October.

EPA. 2006e. Electronic communication from Mr. Bret Kendrick of EPA Region 6 to Ms. Katy Brantingham of ARCADIS, Regarding Approval with Changes of the Work Plan for Optimization of Remedial Activities. 18 October.

EPA. 2007a. Electronic Communication from EPA to GEA Regarding Conditions Approval for Plugging and Abandoning Wells P83-08M and P83-08D. 2 March.

EPA. 2007b. EPA Letter Regarding GEA's Request to Terminate the North Plant 83 Portion of the Shallow Zone Ground Water Remediation System, Former Air Force Plant 83/General Electric Operable Unit at the South Valley Superfund Site, Albuquerque, New Mexico. 24 October.

EPA. 2007c. EPA Letter Regarding Response to the EPA Approval Letter to Terminate North Plant 83 Operations Shallow Zone Ground Water Remediation System, Former Air Force Plant 83/General Electric Operable Unit at the South Valley Superfund Site, Albuquerque, New Mexico. 13 November.

EPA. 2008. Letter from Mr. Bret Kendricks of EPA to Mr. George Sylvester of Univar, USA, Inc. in Response to the Summary of the December 5, 2007 Meeting Regarding the Edmunds Street Ground Water Operable Unit at the South Valley Superfund Site, Albuquerque, New Mexico. 30 January.

EPA. 2009a. 9 April 2009 Conference Call/13 April 2009 Letter - Follow-Up Shallow Zone Extraction Well SEW-IO and Monitoring Well SW-08, South Valley Superfund Site, Albuquerque, New Mexico. EPA and NMED Approval. 22 April.

EPA. 2009b. Letter from Mr. Michael Hebert of EPA to Mr. George Sylvester of Univar USA, Inc., Regarding Initiation by EPA of the Five-Year Review Process. 19 November.

EPA. 2009c. Letter from Mr. Michael Hebert of EPA to Mr. George Sylvester of Univar USA, Inc., Regarding Requirement for Sampling for 1,4-Dioxane. 19 November.

EPA. 2009d. Letter from Mr. Michael Hebert of EPA to Mr. Dana Beaulieu of GE Transportation Regarding Initiation by EPA of the Five-Year Review Process. 19 November.

EPA. 2010a. Letter from Mr. Michael Hebert of EPA to Univar approving proposed activities for the evaluation of 1,4-Dioxane. 14 January

EPA 2010b. Letter from Mr. Michael Hebert to GEA approving the plugging and abandonment of all off-site monitoring and extraction wells related to the North Plant 83 Shallow Zone. 4 March

EPA 2010c. Letter from Mr. Michael Hebert of EPA to GEA approval to conduct Chemical Injection Remediation Program. 1 June.

EPA 2010d. Letter from Mr. Michael Hebert of EPA to GEA requesting a future plan description related to the planned closure of GEA Manufacturing Plant Operations. 12 July.

EPA 2011a. Letter from Mr. Michael Hebert of EPA to GEA stating all recommendations pertaining to GEA as described in the Fourth FYR have been addressed. 23 March.

EPA 2011b. Letter from Mr. Michael Hebert of EPA to GEA approving the request to abandon remaining wells and close the North Plant 83 Shallow Zone System. 31 May.

EPA. 2011c. Letter from Mr. Michael Hebert of EPA to Univar requiring an evaluation of current monitoring network is adequate to determine extent of 1,4-Dioxane. 14 July.

EPA. 2011d. Letter from Mr. Michael Hebert of EPA to GEA approving Work Plan for Remediation of Hazardous Materials East and West Tank Line. 21 October.

EPA. 2011e. Letter from Mr. Michael Hebert of EPA to Univar approving Site conceptual model and proposed investigation activities for 1,4-Dioxane. 21 November.

EPA 2012. Letter from Mr. Michael Hebert of EPA to GEA approving the Final Closure Report, GEA Manufacturing Plant. 2 November.

EPA 2013. Letter from Mr. Michael Hebert of EPA to GEA approving of Closure of the South Plant 83 Remediation System and other unused monitoring wells. 13 February.

EPA. 2014a. Letter from Mr. Michael Hebert of EPA to Univar approves the Revised Human Health Risk Evaluation for 1,4-Dioxane. 18 March

EPA. 2014b. Letter from Mr. Michael Hebert of EPA to Univar approving the Revised Well Installation and Monitoring Network Work Plan. 23 April.

EPA. 2014c. Letter from Mr. Michael Hebert of EPA to Univar approving completion of Consent Decree. 10 June.

EPA. 2015. Community Involvement Plan – South Valley. 1 April.

EPA. 2017. Letter from Mr. Michael Hebert of EPA to GEA acknowledgement for Request to Modify Extraction Rates at Deep Zone Groundwater Remediation System. 30 October

EPA. 2018a. Memorandum from Mr. Michael Hebert of EPA acknowledgement of completion and Approval of Operable Unit 1. 17 January

EPA. 2018b. Memorandum from Mr. Michael Hebert of EPA acknowledgement of completion and Approval of Operable Unit 2 and Operable Unit 5. 17 January

EPA. 2018c. Letter from Mr. Derek Ragon of EPA to NMED, Deletion Docket: South Valley Superfund Site. 13 June

EPA. 2019a. Letter from Mr. Michael Hebert of EPA to GEA approval of Field Sampling Plan. 24 April

EPA. 2019b. Publication in Federal Register - Partial Deletion of Operable Units 1, 2, and 5, South Valley Superfund Site Albuquerque, New Mexico. 23 September

General Electric Aviation (GEA). 2007. Letter to EPA Regarding Update on 1,4-Dioxane Sampling Results at Former Plant 83/General Electric Operable Unit, South Valley Superfund Site. 5 July.

GEA. 2009. Shallow Zone Groundwater Extraction and Monitoring Well Status, Former Plant 83/GE Operable Unit Albuquerque, New Mexico. 22 January.

GEA 2010. Letter from Mr. Dana Beaulieu of GEA to EPA outlining planned site investigations of the GEA Manufacturing Plant. 3 August.

GEA 2010. Letter from Mr. Oscar Lackey of GEA requesting an optimization review of the Deep Zone Monitoring Network. 19 August.

GEA 2011. Letter from Mr. Dana Beaulieu of GEA to EPA responding to recommendation in the Fourth Five Year Review. 26 January.

GEA 2011, Letter Report from GEA to EPA, Chemical Injection Remediation Final Report including all related groundwater monitoring data and Request to Close OU 05. 9 March.

GEA 2011. Letter Mr. Dana Beaulieu of GEA to EPA requesting to abandon remaining wells and close North Plant 83 Shallow Zone System. 9 May.

GEA 2011. Work Plan for Remediation of Hazardous Materials East and West Tank Line Area. 12 October.

GEA 2011. GEA submits Final Report and Request for Closure of North Plant 83 Shallow Zone. 1 November.

GEA 2011. East West Tank Line Ground Water Sampling and Flow Field Sampling Plan. 4 November.

GEA 2013. Final Report for Closure of the South Plant 83 Remediation System and other unused monitoring wells. 28 May.

GEA 2014. GEA files Declaration of Restrictive Covenants for the former GEA Manufacturing Facility with the Bernalillo County Clerk. 16 September.

GEA 2014. Letter from Randall McAlister of GEA to EPA, Request for Closure Former Plant 83/GE Operable Unit 05. 22 September.

GEA 2017. Letter from Randall McAlister of GEA to EPA, Request for Partial Delisting of San Jose 6 Operable Unit 02 and Former Plant 83/GE Operable Unit 05. 7 April.

Geraghty & Miller, Inc. (G&M). 1985. Source Control Investigation at 3301 Edmunds Street, S.F., Albuquerque, New Mexico.

G&M. 1989a. Remedial Investigation Report, 3301 Edmunds Street Site, S.E., Albuquerque, New Mexico. January.

G&M. 1989b. Feasibility Study Report, 3301 Edmunds Street Site, Albuquerque, New Mexico, January.

G&M. 1990a. Remedial Design Report, Ground water Remediation Project, 3301 Edmunds Street Site, Albuquerque, New Mexico. April.

G&M. 1990c. Remedial Action Plan, 3301 Edmunds Street Site, Albuquerque, New Mexico. September.

G&M. 1995. Five Year Review of Remedial Actions at the Van Waters & Rogers Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. 8 November.

Harding Lawson Associates, Inc. (HLA). 1989. Public Health Evaluation, Van Waters & Rogers Inc., Edmunds Street Site, Albuquerque, New Mexico. 20 January.

HLA. 2000. Revised Performance and Compliance Monitoring Plan, Plant 83/General Electric Operable Unit, South Valley Superfund Site, Albuquerque, New Mexico. July.

Hydrometrics and Geosciences Consultants Limited (H+GCL). 1993a. Plant 83 Plume Delineation program, Deep Zone Hydrogeologic Data Evaluation Report, Document Control No. BOT01520.DOC.

H+GCL. 1993b. Plant 83 Plume Delineation Program, Groundwater Flow Model, Draft Report. 18 August.

ISOTEC 2010. Report from ISOTEC detailing field activities related to the chemical Injection Remediation Program at OU 05. 9 September.

New Mexico Administrative Code. Various Dates. Title 20, Chapter 6, Water Quality, Part 2, Ground and Surface Water Protection.

NMED. 2007. Discharge Permit Renewal, DP-1065, General Electric Aviation. 11 May.

NMED 2012 Groundwater Discharge Plan Renewal, DP-1065, General Electric Aviation. 12 September.

NMED 2017. NMED Concurrence with General Electric Request and EPA Proposal to Commence Delisting Procedures for OU 01, OU 02 and OU 05. 11 August.

Smith Environmental Technology, Corp. (formerly Canonie). 1996. Performance and Compliance Monitoring Plan, Plant 83/General Electric Operable Unit, South Valley Superfund Site, Albuquerque, New Mexico. May.

Stetson Engineers, Inc. 2001. Memorandum Regarding Water Quality Sampling Results, for New Mexico South Valley Superfund Site, Plant 83/GE Deep Zone Groundwater Treatment System. 1 December.

Underground Resources Management. 1982. Hydrogeologic Investigation in the Vicinity of a Chemical Handling Facility, Albuquerque, New Mexico.

Water Equipment Services, Inc. 2005. Second Five-year Review Report for Former Plant 83/General Electric Operable Unit South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico. Prepared in concert with U.S. EPA Region 6 and New Mexico Environment Department. 15 September.

APPENDIX B – ADDITIONAL SITE INFORMATION

SITE CHRONOLOGY

South Valley Superfund Site

| Date | Event |
|--|---|
| 1978 | Volatile organic compounds were detected in City of Albuquerque wells from the San Jose and Miles municipal well fields. In subsequent sampling, contamination persisted in wells SJ-3 and SJ-6 (in the San Jose well field) whereas the impact in well Miles-1 (in the Miles well field) was not confirmed and it was returned to service. |
| 1981 | As pre-National Priorities List responses, the City of Albuquerque took Albuquerque municipal wells SJ-3 and SJ-6 off-line. |
| September 8, 1983 | The South Valley Site is placed on the National Priorities List. |
| March 22, 1985 | The Record of Decision for OU 01 was signed. |
| September 28, 2005 | Approval of the FYR memorandum for the Site. |
| August 26, 2010 | Fourth Five Year Review completed for the South Valley Superfund Site. First Site wide FYR initiated by EPA. |
| January 31, 2013 | South Valley Superfund Site Open House updating the Public on cleanup progress. |
| Univar – Edmunds Street OUs (OU 03 and OU 04) | |
| June 28, 1988 | OU 03 - Record of Decision for the Edmunds Street Ground Water OU is signed. |
| January 1989 | Submittal of the Remedial Investigation and Feasibility Study reports to EPA and NMED. |
| 30 March 1989 | OU 04 – the Record of Decision for the Edmunds Street Property Source Control is signed. |
| March 27, 1990 | The Consent Decree in the Matter of the United States of America versus Univar Corporation was entered on docket. |
| September 7, 1990 | The Remedial Action Plan for OU 03 was submitted to the EPA and NMED. |
| 1990 | The construction of the ground water remedy at OU 03 was completed. |
| September 10, 1990 through January 14, 1991 | The ground water system for OU 03 startup program was conducted. |
| November 8, 1995 | First FYR for Univar completed |
| March 1996 | EPA and NMED verbally approve modifications to the ground water monitoring plan, including use of Columbia Analytical Services, lower reporting limits, and elimination of analysis for benzene, toluene, ethylbenzene, totalxylene and 1, 2- dichloroethane. |
| March 1998 | two ground water monitoring wells installed, one as a replacement well (GM-22R) and one new well (GM-25) |
| November 1998 | vapor extraction system for OU 04 installed |
| July 16, 1999 | air quality permit for the vapor extraction system obtained |
| August 1999 | pilot study for the vapor extraction system begins |
| September 14, 2000 | Second FYR for Univar completed |

| Date | Event |
|--------------------|---|
| October 2000 | installation of additional vapor extraction system wells for full system build out completed |
| July 15, 2003 | City of Albuquerque Environmental Health Department approved discontinuing compliance monitoring for the vapor extraction system (OU 04) |
| October 7, 2004 | Univar received authorization from EPA (Mr. Terry Roundtree) in an electronic communication to discontinue semi-annual sampling of the treatment unit influent and effluent and ground water monitoring wells and to reduce the number of ground water monitoring wells monitored annually. |
| January 31, 2005 | EPA submitted letter to Univar requesting the installation of deeper wells |
| August 2005 | deeper wells GM-27 and GM-28 installed |
| September 2, 2005 | Third FYR for Univar completed |
| September 7, 2006 | ARCADIS on behalf of Univar submitted a work plan to optimize future remedial activities. |
| October 18, 2006 | EPA approved changes to the optimization plan for remedial activities |
| September 29, 2006 | vapor extraction system was shut down |
| November 3, 2006 | ground water treatment system was shut down |
| December 5, 2007 | Discussion between EPA and Univar regarding the results of the optimization study and revision of the remedial actions |
| January 30, 2008 | EPA and NMED approve revised remedial action |
| November 19, 2009 | Letter from EPA notifying Univar that they started the FYR for the South Valley Superfund site and alleviating concerns that Univar should perform this review consistent with the Consent Decree. |
| November 19, 2009 | letter from EPA to Univar requiring evaluation for 1,4-Dioxane |
| January 7, 2010 | letter from ARCADIS on behalf of Univar to EPA outlining activities for the evaluation of 1,4-Dioxane |
| January 14, 2010 | letter from EPA to Univar approving proposed activities for the evaluation of 1,4-Dioxane |
| July 14, 2011 | letter from EPA to Univar requiring an evaluation of current monitoring network adequacy for use in determining extent of 1,4-Dioxane |
| October 4, 2011 | letter from ARCADIS on behalf of Univar detailing proposed investigation actions for 1,4-Dioxane |
| November 21, 2011 | letter from EPA to Univar approving proposed investigation activities for 1,4-Dioxane |
| February, 2012 | ARCADIS on behalf of Univar performs 8-hour pump test |
| May 29, 2012 | ARCADIS on behalf of Univar submits report on 8-hour pump test |
| May 31, 2012 | ARCADIS on behalf of Univar submits work plan for additional actions which include an extended pump test and treatment pilot study for 1,4-Dioxane |
| June 13, 2012 | letter from EPA to Univar approving extended pump test and treatment study for 1,4-Dioxane |
| Aug-Nov, 2012 | ARCADIS extended pump test and treatment study for 1,4-Dioxane |
| June 24, 2013 | ARCADIS on behalf of Univar submits report on extended pump test and treatment study |
| October 18, 2013 | ARCADIS on behalf of Univar submits a Human Health Risk Evaluation for 1,4-Dioxane |
| January 17, 2014 | ARCADIS on behalf of Univar submits Revised Human Health Risk Evaluation of 1,4-Dioxane |

| Date | Event |
|--|--|
| January 24, 2014 | ARCADIS on behalf of Univar submits Monitoring Well Drilling and Installation and Ground Water Monitoring Network Work Plan |
| March 18, 2014 | letter from EPA to Univar approves the Revised Human Health Risk Evaluation for 1,4-Dioxane |
| March 19, 2014 | ARCADIS on behalf of Univar submits the Revised Well Installation and Monitoring Network Work Plan |
| April 23, 2014 | letter from EPA to Univar approving the Revised Well Installation and Monitoring Network Work Plan |
| June 2, 2014 | ARCADIS on behalf of Univar submits Notice of Completion of Consent Decree Requirements for Constituents of Concern (VOCs). Does not include 1,4-Dioxane |
| June 10, 2014 | letter from EPA to Univar approving completion of Consent Decree requirements |
| May 13, 2016 | Submittal of Remedial Work Plan for 1,4-Dioxane in Ground Water – 3301 Edmunds Street Site |
| June 10, 2016 | EPA comments to Remedial Work Plan for 1,4-Dioxane in Ground Water – 3301 Edmunds Street Site |
| July 22, 2016 | Submittal of revised Remedial Work Plan for 1,4-Dioxane in Ground Water – 3301 Edmunds Street Site |
| July 27, 2016 | EPA approves to Remedial Work Plan for 1,4-Dioxane in Ground Water – 3301 Edmunds Street Site |
| April 27, 2017 | Final Proposed Remedial System Well Installation Report - 3301 Edmunds Street Site |
| July 13, 2017 | April 2017 Groundwater Monitoring Activities - 3301 Edmunds Street Site |
| October 27, 2017 | DESIGN DRAWINGS - 1,4-Dioxane GROUNDWATER PROJECT - UNIVAR USA INCORPORATED |
| July 31, 2018 | Univar submittal of OM&M Manual for 1,4-Dioxane in Groundwater Treatment Project |
| July 31, 2018 | Univar submittal of Treatment System Construction Report for 1,4-Dioxane in Groundwater Treatment Project |
| April 23, 2019 | Univar submittal of Field Sampling Plan for 1,4-Dioxane in Groundwater Treatment Project |
| April 24, 2019 | EPA Approval of Field Sampling Plan for 1,4-Dioxane in Groundwater Treatment Project |
| June 12, 2019 | Univar submittal of Field Sampling Plan – For 1,4-Dioxane in Groundwater Treatment Project |
| September 1, 2019 | Letter – Univar USA, Inc. name changed to Univar Solutions USA, Inc. |
| GEA – Plant 83/GE OUs (OU 02, OU 05, and OU 06) | |
| 1988 | Remedial Investigation/Feasibility Study completed |
| September 30, 1988 | Record of Decision for OU 02, the vicinity of SJ-6 signed |
| September 30, 1988 | Record of Decision for shallow soil and ground water (OU 05) and deep ground water (OU 06) signed |
| June 16, 1989 | Administrative Order in the Matter of General Electric Company, South Valley Superfund Site was entered on docket |
| 1991 | remedial design start for OU 05 soil vapor extraction system |
| 1992 | remedial design start for OU 05 shallow ground water remediation system |
| 1992 | remedial design completed for OU 05 soil vapor extraction system |
| June 1992 | start of the remedial action for the shallow soils |

| Date | Event |
|--------------------|--|
| 1994 | remedial design started for the deep zone ground water remediation system |
| 1993 | final closeout report for OU 05 soil vapor extraction system completed |
| 1993 | remedial design completed for OU 05 shallow ground water remediation system |
| May 1994 | remedial action starts for the shallow ground water remediation system |
| 1995 | remedial design completed for deep zone ground water remediation system |
| April 1996 | dedication ceremony for deep zone ground water remediation system, full time operation begins |
| September 2000 | First FYR for GEA completed |
| 2001 | Optimization No. 1 for the deep zone ground water remediation system |
| September 15, 2005 | Second FYR for GEA completed |
| August 15, 2006 | 2005-2006 annual reports for the shallow and deep aquifer remediation systems submitted |
| September 18, 2006 | GEA, through their contractor, submits proposed changes to the October 2006 sampling |
| October 26, 2006 | Explanation of Significant Difference stipulates new Maximum Contaminant Level/applicable or relevant and appropriate requirement for tetrachloroethylene at 5 microgram per liter |
| February 23, 2007 | EPA notification that 2 wells, P83-08D and P83-08M, need to be plugged and abandoned |
| March 2, 2007 | EPA receives request for Comfort Letter for the owner of Duke City Distributing Co. property |
| March 2, 2007 | EPA approves to the request to plug and abandon P83-08D and P83-08M |
| March 9, 2007 | EPA provides Comfort Letter to the owner of neighboring property |
| March 16, 2007 | GEA contractor proposal to plug and abandon P83-08D and P83-08M |
| April 4, 2007 | EPA approval to plug and abandon wells P83-08D and P83-08M |
| April 18, 2007 | EPA approves changes to the April 2007 sampling event |
| May 11, 2007 | NMED approves the renewal of the ground water discharge permit DP_1065 |
| July 5, 2007 | GEA provided EPA results for 1,4-Dioxane |
| August 15, 2007 | GEA submits the 2006-2007 annual reports for the shallow and deep aquifer remediation systems |
| September 11, 2007 | GEA submits request to terminate operation of North Plant – shallow zone treatment |
| October 24, 2007 | EPA conditionally approves GEA's request to terminate operations at the North Plant shallow zone treatment system |
| November 5, 2007 | GEA response to EPA's conditions approval |
| November 13, 2007 | EPA approves the changes proposed on 5 November |
| October 31, 2007 | operations of the shallow zone ground water treatment system for North Plant terminated |
| April 2, 2008 | GEA submits work plan to optimize the deep zone system |
| August 15, 2008 | GEA submits 2007-2008 annual reports for the shallow and deep aquifer remediation systems |
| October 17, 2008 | 1,1-dichloroethene in sample collected from well SEW-05 in North Plant 83 Area exceeds the applicable or relevant and appropriate requirement |

| Date | Event |
|-------------------|--|
| October 21, 2008 | GEA submits 2008 revision of the performance and compliance monitoring plan for both the shallow and deep zones treatment systems |
| November 24, 2008 | extraction well SEW-05 within the North Plant treatment system is brought back into operation |
| August, 2009 | GEA informs EPA that Manufacturing Plant Operations will cease in late 2010. |
| October 2009 | Operations at the North Plant 83 Area ceased |
| November 10, 2009 | GEA requests to plug and abandon North Plant 83 wells |
| November 19, 2009 | Letter from EPA notifying GEA that they started the FYR for the South Valley Superfund site and alleviating concerns that GEA should perform this review consistent with the Administrative Order. |
| November 19, 2009 | Letter from EPA to GEA regarding sampling for 1,4-Dioxane. |
| March 4, 2010 | Letter from EPA to GEA approving the plugging and abandonment of all off-site monitoring and extraction wells related to the North Plant 83 shallow zone. |
| March 15, 2010 | Axis submits Work Plan to EPA to conduct a chemical injection remediation program in the shallow zone aquifer SW-08 and SEW-05 areas |
| June 1, 2010 | Letter from EPA to GEA approval to conduct chemical injection remediation program |
| July 12, 2010 | Letter from EPA to GEA requesting a plan detailing the investigations related to the closure of GEA manufacturing facility operations |
| August 3, 2010 | GEA response to EPA's request for plans outlining GEA's planned investigations of GEA manufacturing facility |
| August 19, 2010 | GEA requests a review of the deep zone monitoring network |
| September 1, 2010 | ISOTEC on behalf of GEA submitted a report detailing field activities related to the chemical injection remediation program |
| September 9, 2010 | Letter from EPA to GEA requesting a work plan that outlines investigation activities related to the closure of GEA manufacturing facilities |
| October 19, 2010 | EPA approves modifications to the deep zone monitoring program |
| December 9, 2010 | DBS&A on behalf of GEA submits a Sump Investigation Work Plan related to the GEA manufacturing facility closure |
| January 26, 2011 | GEA letter to EPA - response to recommendations in the Fourth FYR |
| March 9, 2011 | GEA submits Chemical Injection Remediation Program Final Report and Request to Close North and South Plant 83 |
| March 16, 2011 | GEA submits additional responses to recommendations in the Fourth FYR |
| March 23, 2011 | EPA letter to GEA - acknowledging GEA has addressed all recommendations pertaining to GEA in the Fourth FYR |
| May 9, 2011 | GEA letter to EPA - request to abandon wells and close North Plant 83 Shallow Zone System |
| May 31, 2011 | EPA letter to GEA - approves the request to abandon wells and close the North Plant 83 shallow zone system |
| August 4, 2011 | DBS&A on behalf of GEA submits Sump Inspection and Investigation Report |
| October 12, 2011 | GEA submits Work Plan for Remediation of Hazardous Materials East and West Tank Line Area |
| October 19, 2011 | GEA letter to EPA outlining ground water sampling in the east west tank line area |

| Date | Event |
|--------------------|--|
| October 21, 2011 | EPA letter to GEA approving Work Plan for Remediation of Hazardous Materials East and West Tank Line |
| October 25, 2011 | EPA letter approves ground water sampling in the east west tank line area. |
| November 1, 2011 | GEA submits letter to EPA Final Report and Request for Closure North Plant 83 Shallow Zone |
| November 4, 2011 | GEA submits East West Tank Line Ground Water Sampling and Flow Field Sampling Plan. |
| November 28, 2011 | EPA letter to GEA - approval of Final Closure Report North Plant 83 Shallow Zone |
| June 18, 2012 | DBS&A on behalf of GEA submits Final Report GEA Manufacturing Facility |
| August 15, 2012 | GEA submits to EPA - report, requests closure of the South Plant 83 Shallow Zone |
| September 12, 2012 | State of New Mexico Ground Water Discharge Plan Renewal (DP-1065) approved |
| October 17, 2012 | GEA submits Revised Final Report GEA Manufacturing Facility. |
| November 2, 2012 | EPA letter to GEA - approval of Final Closure GEA Manufacturing Facility |
| February 13, 2013 | EPA letter to GEA - approval of closure of the South Plant 83 remediation system and other unused monitoring wells |
| May 28, 2013 | GEA submits Final Report for Closure of the South Plant 83 Remediation System |
| April 1, 2014 | GEA submits to EPA - Draft Declaration of Restrictive Covenants that outlines the Institutional Controls for the Former GEA Manufacturing Facility |
| April 16, 2014 | Axis on behalf of GEA submits to EPA - the fourth revision of the Performance Monitoring Compliance Program. |
| August 25, 2014 | Axis on behalf of GEA submits to EPA - Work Plan to Optimize the Deep Zone Remediation System, Operable Unit 06 |
| August 27, 2014 | EPA acknowledges Work Plan to Optimize Deep Zone Remediation System and has no further comments. |
| September 16, 2014 | GEA files Declaration of Restrictive Covenants for the former GEA Manufacturing Facility with the Bernalillo County Clerk |
| September 22, 2014 | GEA letter to EPA - Request for Closure Former Plant 83/GE Operable Unit 05 |
| August 5, 2015 | Sunport Blvd Public Hearing |
| February 22, 2016 | GEA response to 5th FYR report issue concerning 1,1 DCA in Well P83-09U |
| April 7, 2017 | GEA Request for Partial Deletion |
| April 11, 2017 | Submittal of 2017 Remedial Action Report – San Jose 6 Operable Unit |
| June 5, 2017 | EPA requesting comments to GEA Deletion Request |
| August 11, 2017 | NMED Concurrence Letter to EPA for Deletion of OU 01, OU 02, and OU 05 |
| October 23, 2017 | Axis group notification of intention to modify Deep Zone groundwater remediation system extraction rates |
| October 30, 2017 | EPA acknowledgment for request to modify extraction rates for the Deep Zone ground water remediation system |
| January 17, 2018 | EPA approval of the OU 02/ OU 05 remedial action report |

| Date | Event |
|--------------------|---|
| May 25, 2018 | Maps of South Valley NPL Site OU 01, OU 02, and OU 05, proposed for partial deletion |
| June 13, 2018 | EPA Deletion Docket: South Valley Superfund Site |
| January 15, 2019 | Letter from Mayor of Albuquerque, NM State Representative and NM State Senators – Partial Deletion of Superfund Site |
| March 5, 2019 | EPA response to Mayor of Albuquerque, NM State Rep and NM State Senator letter |
| March 28, 2019 | NMED response to NM State Rep and NM State Senator letter |
| May 2, 2019 | GEA to EPA – Revised request to Plug and Abandon Monitoring Wells P-1, P-2 and P-3 |
| June 6, 2019 | Letter (Second) from NM State Representative and NM State Senators – Partial Deletion of Superfund Site |
| July 10, 2019 | NMED letter to Esther Abeyta, NM State Representative and NM State Senators – Partial Deletion of OU 01, OU 02, and OU 05 |
| July 15, 2019 | EPA Re-opens Public Comment Period for Partial Deletion of OU 01, OU 02, and OU 05 |
| July 19, 2019 | EPA response (Second) to NM State Rep and NM State Senator letter |
| August 26, 2019 | Letter (Third) from NM State Representative and NM State Senators – Partial Deletion of Superfund Site |
| September 6, 2019 | EPA response (Third) to NM State Rep and NM State Senator letter |
| September 23, 2019 | EPA Announces the Deletion of OU 01, OU 02, and OU 05 in Federal Register |

Additional Site Information

Hydrology

The hydrogeologic units encountered at the Site are described in the paragraphs below. Ground water is located in the Santa Fe Group Aquifer. The remediation at Univar, OU 03, is limited to the shallow portion of the aquifer while at General Electric Aviation (GEA), OUs 05 and 06, because the impact extends deeper within the formation, the remediation addresses different depth horizons that were divided by convention into the shallow zone aquifer and the deep zone aquifer. The deep zone aquifer includes both the intermediate zone and deep zone referred to in the 1988 ROD for OU 03). OU 05 addresses impacts to the shallow zone aquifer located proximate to the South Plant 83 and North Plant 83 Areas and a portion of the San Jose residential neighborhood, located just north of North Plant 83 Area. OU 06 addresses impacts to portions of the deep zone aquifer found east of the Plant 83 facilities, south of Woodward Road and east of South Broadway. Descriptions of the shallow zone and deep zone aquifers are provided below as outlined in the Second FYR for GEA.

Shallow Zone Aquifer

By convention, the shallow zone aquifer refers to ground water that is above the relatively continuous silty clay layer and/or above an elevation of 4,900 feet (ft) above mean sea level (amsl). In the North Plant 83 Area, there is a continuous silty clay layer underneath the aquifer. Accordingly, the shallow zone aquifer ground water is primarily perched. Perched ground water does not have a uniform flow direction, but rather flows in directions dictated by the undulating surface of the underlying silty clay layer. In the South Plant 83 Area, the silty clay layer underneath the aquifer is not continuous. Hence, the ground water generally flows west to east. The shallow zone formation consists of layers of coarse-grained sands, silty sands, clays, and silty clays. This shallow zone aquifer generally extends to a depth of approximately 20-25 ft below ground surface (bgs). The shallow zone formation is underlain by a relatively continuous silty clay layer, except at the south end of South Plant 83 where it is absent or does not provide hydraulic separation from the deep zone aquifer.

Deep Zone Aquifer

By convention, the deep zone aquifer refers to the aquifer below an elevation of 4,900 ft amsl. The following text summarily describes the deep zone aquifer geology. The geology consists of unconsolidated alluvial units of the older Santa Fe Group. These sediments (down to approximately 4,300 ft amsl) are primarily ancestral Rio Grande-related, braided fluvial deposits and contain lenticular deposits of finer grained, relatively lower conductivity sands, silts, and clays. Sediments within the upper 600-700 ft of the deep zone aquifer (the area where ground water is being remediated) are characterized by high proportions of sands and gravels that form extensive and locally high conductivity units across the site. Discontinuous silts and clays are present within this interval and may limit the downward rate of contaminant movement in the vertical direction. Note that these silts and clays form confining layers in upper portions of the aquifer, but these confining layers are not laterally extensive. There is no evidence of a laterally extensive confining layer east of the Albuquerque Metropolitan Arroyo and Flood Control Authority (AMAFCA) South Diversion Channel, in the area of interest.

Status of Implementation

OU 03

Although the ROD for OU 03 required the implementation of a ground water remedy, Univar enhanced the effectiveness of the ground water remediation system for OU 03 by installing a soil vapor extraction system (VES) to address vadose zone contamination.

The original design of the recovery well system was based on modeling of different ground water remediation scenarios. Ground water extraction wells RW-01, RW-02, RW-03, and RW-04 were installed in October and November 1989 at the locations shown on **Figure C-2, Appendix C**. These recovery wells were completed at depths of 155, 166, 180, and 200 ft bgs, respectively, in the intermediate aquifer.

The operating requirements for the remedial system were identified during development of the ARARs as part of the remedial investigation and feasibility study (RI/FS). The cleanup goals for the ground water impacted by site-related VOCs are defined as the EPA's MCL and NMWQCC standards (**Appendix C, Table C-2**). The ground water and air discharge concentrations from the treatment unit are to meet the ground water discharge criteria specified by the NMWQCC and the air discharge criteria specified by the Albuquerque Environmental Health Department.

The VES was originally installed to address contamination in the vadose zone (OU 04) at the Edmunds Street Source Control and to improve the removal of VOCs from the ground water, although it was not required by the ROD. The VES consists of a self-contained extraction blower, vapor-liquid separator (knockout pot), controls, valves, and piping. The system had a maximum throughput of approximately 450 standard cubic feet per minute and was locked inside of a wheel-mounted trailer located in the southeast corner of the Univar property. Further details on the testing and operation of this system are provided in the Third FYR report. The VES was turned off after cleanup goals were achieved on September 29, 2006.

Approximately 850 million gallons of ground water were treated from June 4, 1990 to April 30, 2006. The ground water remedial system was shut off on November 3, 2006. Subsequent compliance monitoring showed that the ground water and vapor extraction systems reduced the dissolved chlorinated VOC concentrations to levels below ARARs as defined in the ROD. On June 10, 2014, EPA approved Univar's request for a partial closure of OU 03 for VOCs.

Remedy Operation and Maintenance at OU 03

On June 10, 2014, EPA approved Univar's request to close OU 03 for VOCs only. During this FYR period, O&M activities targeted 1,4-dioxane contamination.

VOCs

The ground water treatment system for OU 03 began operation June 4, 1990. Long-term Operations and Maintenance (O&M) of the remedial system had been conducted since system startup in January 1991 through November 2006. All routine O&M of the remedial system was performed as specified in the RAP. Monitoring of the ground water remedial system during the sixteenth year of operation (September 1990 through May, 2006) was conducted to assess the overall effectiveness of the treatment unit and as specified in RAP. The combined remedial system includes the recovery wells, ground water treatment unit, infiltration gallery, VES, and associated equipment.

On September 7, 2006, ARCADIS submitted, on behalf of Univar, a work plan to optimize remedial activities as only PCE was being detected at maximum concentrations of 12 µg/L (MCL of 5 µg/L). In addition, the remedial system had reached an asymptotic recovery rate of less than 1 pound of VOCs per year. EPA approved the work plan which consisted of shutting down the ground water remediation system and the VES the week of November 3, 2006 and continue semi-annual ground water monitoring. On January 30, 2008, EPA and NMED approved revisions to the RAs which kept the remedial systems turned off and continued ground water measurements and sampling to monitor VOC levels. Subsequent ground water monitoring showed that the ground water remediation system and the VES reduced the chlorinated VOC concentrations to levels below ARARs.

1,4-Dioxane

On June 16, 2004, EPA requested that Univar sample and analyze ground water for 1,4-dioxane to determine if the compound was present. On November 19, 2009, following several years of monitoring, EPA notified Univar that they are required to sample for 1,4-dioxane, a probable human carcinogen, as part of the ground water monitoring program pursuant to Section XVI(D) of the Univar Consent Decree. Univar was to evaluate the occurrence of 1,4-dioxane and determine if it poses a threat to human health and the environment. On January 7, 2010, Univar submitted a work plan to further evaluate the presents of 1,4-dioxane in ground water, develop a conceptual site model (CSM), conduct a risk assessment, and propose a schedule to perform ground water sampling from 24 wells previously used for the treatment and extraction of VOCs. On January 14, 2010, EPA approved Univar's recommended approach to further investigation of 1,4-dioxane as a contaminant of concern (COC).

On March 18, 2014, EPA approved a Human Health Risk Evaluation (HHRE) submitted by Univar that evaluated potential human health risks and defined site-specific, risk-based cleanup goals. In addition, Univar evaluated the monitoring well network and submitted a work plan for the installation of additional monitoring wells to aid in the delineation and to monitor the migration of 1,4-dioxane impacted ground water.

APPENDIX C –TABLES AND FIGURES

Table C-1: Operable Units Summary for South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico.

| Operable Unit | Issue | Remedial Action | Current Status | Proposed Action |
|----------------------|--|--|--|--|
| OU 01 | Municipal wells contaminated with volatile organic compounds (VOCs) | Wells were plugged and abandoned, a replacement well installed | Completed in 1987 | Deleted from the NPL on September 23, 2019 |
| OU 02 | Remedial goal to eliminate/prevent migration of contaminants from shallow to intermediate aquifers | Wells were plugged and abandoned, new and replacement well installed; restrict ground water use; ground water monitoring | Completed in 2019 | Deleted from the NPL on September 23, 2019 |
| OU 03 | Reduce ground water related VOCs to acceptable levels | Pump-treat-injection system | EPA approved partial completion for VOCs; Continue pump-treat-injection system for 1,4-dioxane | Continue pump-treat-injection system for 1,4-dioxane |
| OU 04 | Soil vadose zone investigation for potential solvent contamination | Investigation found no evidence of contamination | Completed in 1988 | ROD specified No Further Action |
| OU 05 | Remediating shallow zone ground water and eliminating source materials | Pump-treat-injection system, enhanced dewatering, soil flushing, and soil vapor extraction | Completed in 2014 | Deleted from the NPL on September 23, 2019 |
| OU 06 | Hydraulically contain plume to protect water supply wells and reduce the concentrations of VOCs to acceptable levels | Pump-treat-injection system | Continue pump-treat-injection system | Continue pump-treat-injection system for Site related VOCs |

Table C-2: Comparison of OU 03 ARARS to Current Standards For Drinking and Ground Water, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico.

| Constituent | Cleanup Goal from ROD or ESD Micrograms per Liter (µg/L) | | Current Standards*** (µg/L) | |
|--------------------------|---|-----------|--------------------------------|-----------------------|
| | Concentration | Source | MCL | NMWQCC (12/8/2018) |
| Acetone | NS** | NS | NS | NS |
| Carbon tetrachloride | 5 | MCL | 5 | 5 |
| Chloroform | 100 | NMWQCC | NS | 100 |
| 1,2-dichloroethane | 5 | MCL | 5 | 5 |
| Trans-1,2-dichloroethene | 70 | MCL | 100 | 100 |
| 1,1-dichloroethene | 5 | NMWQCC | 7 | 7 |
| Methylene chloride | 100 | NMWQCC | NS | 5 |
| Tetrachloroethene | 5* | MCL | 5 | 5 |
| 1,1,1-trichloroethene | 60 | NMWQCC | 200 | 200 |
| Trichloroethene | 5 | MCL | 5 | 5 |
| 1,4-Dioxane (Offsite) | 6.7 | HHRE***** | NS | NS |
| 1,4-Dioxane (Onsite) | 29 | HHRE***** | NS | NS |

* The initial ARAR for tetrachloroethene was set as 20 µg/L, based on NMWQCC standards (based on New Mexico Administrative Code, various dates); this ARAR was modified in a 2006 Explanation of Significant Differences (EPA 2006a) to reflect the MCL of 5 µg/L promulgated in 1992.

** No Standard

*** NMWQCC standards effective December 21, 2018.

***** Human Health Risk Evaluation completed by Univar USA, Inc., March 6, 2014.

Table C-3: Comparison of OU 05 and 06 ARARS to Current Standards For Drinking and Ground Water, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico.

| Constituent | Cleanup Goal Micrograms per Liter (µg/L) | Current Standards (µg/L) | |
|----------------------------------|--|--------------------------|-----------|
| | | MCL | NMWQCC*** |
| 1,1,1-Trichloroethane | 60 | 200 | 200 |
| 1,1,2,2-Tetrachloroethane | 10 | -- | 10 |
| 1,1,2-Trichloroethane | 5 | 5 | 5 |
| 1,1-Dichloroethane | 25 | -- | 25 |
| 1,1-Dichloroethene | 5 | 7 | 7 |
| 1,2-Dichloroethane | 5 | 5 | 5 |
| 1,2-Dichloropropane | 5 | 5 | 5 |
| Benzene | 5 | 5 | 5 |
| Bromoform | 80 | 80* | -- |
| Carbon tetrachloride | 5 | 5 | 5 |
| Chlorobenzene | 80 | 100 | -- |
| Chloroform | 80 | 80* | 100 |
| Chloromethane | 2,300,000 | -- | -- |
| Dibromochloromethane | 80 | 80* | -- |
| Dichlorobromomethane | 80 | 80* | -- |
| Ethylbenzene | 700 | 700 | 700 |
| Ethylene dibromide | 0.05 | 0.05 | 0.05 |
| Methyl tertiary butyl ether | 100 | -- | 100 |
| Methylene chloride | 5 | 5 | 5 |
| Tetrachloroethene | 5** | 5 | 5 |
| Toluene | 750 | 1,000 | 1000 |
| <i>trans</i> -1,2-Dichloroethene | 100 | 100 | 100 |
| Trichloroethene | 5 | 5 | 5 |
| Vinyl chloride | 1 | 2 | 2 |
| Xylenes (total) | 620 | 10,000 | 620 |

* 80 micrograms per liter is the MCL for Total trihalomethanes.

** The initial ARAR for tetrachloroethene was set as 20 µg/L, based on NMWQCC standards (based on New Mexico Administrative Code, various dates); this ARAR was modified in a 2006 Explanation of Significant Differences (EPA 2006a) to reflect the MCL of 5 µg/L promulgated in 1992.

Note: Dashes (--) indicate no drinking water or ground water standard.

*** NMWQCC standards effective December 21, 2018

Table C-4: OU 03 Concentrations of 1,4-Dioxane in Samples Collected from the Groundwater Treatment System Influent, Effluent, and Recovery Wells Univar USA Inc., South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico.

| Reproduced from Univar 2019 Annual Report, Table 5 | | | Analyte Method Units Sample Type | 1,4-Dioxane 8260BSIM µg/L |
|---|-------------|--------------------|---|---------------------------------|
| Location ID | Sample Date | Sample ID | | |
| INFLUENT | 2/23/2018 | INF-01-02232018 | P | 17.0 |
| INFLUENT | 2/23/2018 | INF-02-02232018 | P | 17.0 |
| INFLUENT | 2/23/2018 | INF-03-02232018 | P | 16.0 |
| INFLUENT | 3/6/2018 | INF-01-03062018 | P | 12.4 |
| INFLUENT | 3/21/2018 | INF-01-03212018 | P | 8.0 |
| INFLUENT | 3/27/2018 | INFLU-01-03272018 | P | 3.5 |
| INFLUENT | 4/4/2018 | INFU-01-04042018 | P | 7.5 |
| INFLUENT | 5/15/2018 | INFL05151810IS | P | 6.2 |
| INFLUENT | 8/22/2018 | INFLU-082218 | P | 7.3 |
| INFLUENT | 11/5/2018 | INFL-110518-3IS | P | 7.1 |
| INFLUENT | 2/7/2019 | INFL-020719-3IS | P | 12.2 |
| INFLUENT | 4/18/2019 | INFL-041819-15IS | P | 11.2 |
| EFFLUENT | 2/23/2018 | EFF-01-02232018 | P | < 1.0 |
| EFFLUENT | 2/23/2018 | EFF-01-02232018-FD | FD | < 1.0 |
| EFFLUENT | 2/23/2018 | EFF-02-02232018 | P | < 1.0 |
| EFFLUENT | 2/23/2018 | EFF-03-02232018 | P | < 1.0 |
| EFFLUENT | 3/6/2018 | EFF-01-03062018 | P | < 1.0 |
| EFFLUENT | 3/12/2018 | EFF-01-030122018 | P | < 1.0 |
| EFFLUENT | 3/21/2018 | EFF-01-03212018 | P | < 1.0 |
| EFFLUENT | 3/27/2018 | EFF-01-03272018 | P | < 1.0 |
| EFFLUENT | 4/4/2018 | EFF-01-04042018 | P | < 1.0 |
| EFFLUENT | 5/15/2018 | EFFL05151811IS | P | < 1.0 |
| EFFLUENT | 8/22/2018 | EFFLU-082218 | P | < 1.0 |
| EFFLUENT | 11/5/2018 | EFFL-110518-4IS | P | < 1.0 |
| EFFLUENT | 2/7/2019 | EFFL-020719-4IS | P | < 1.0 |
| EFFLUENT | 4/18/2019 | EFFL-041819-16IS | P | < 1.0 |
| GM-27 | 3/6/2018 | GM-27-03062018 | P | 32.2 |
| GM-27 | 3/6/2018 | GM-27-03062018D | FD | 32.6 |
| GM-27 | 4/4/2018 | GM-27-04042018 | P | 9.8 |
| GM-27 | 5/15/2018 | GM2705161814IS | FD | 4.4 |
| GM-27 | 5/15/2018 | GM2705161813IS | P | 4.3 |
| GM-27 | 8/22/2018 | GM-27-082218 | P | 4.1 |
| GM-27 | 10/2/2018 | GM2710021801FD | FD | 9.4 |
| GM-27 | 10/2/2018 | GM2710021802IS | P | 9.3 |
| GM-27 | 11/5/2018 | GM-27-110518-6IS | P | 11.5 |
| GM-27 | 11/5/2018 | GM-27-110518-7FD | FD | 11.8 |
| GM-27 | 2/7/2019 | GM27-020719-6IS | P | 28.7 |
| GM-27 | 2/7/2019 | GM27-020719-7FD | FD | 27.1 |
| GM-27 | 4/18/2019 | GM27-041819-17IS | P | 24.9 |

| Reproduced from Univar 2019 Annual Report, Table 5 | | | Analyte Method Units | 1,4-Dioxane 8260BSIM µg/L |
|---|-------------|------------------|----------------------------|---------------------------------|
| Location ID | Sample Date | Sample ID | Sample Type | |
| RW-02 | 3/6/2018 | RW-02-03062018 | P | 1.7 |
| RW-02 | 5/15/2018 | RW020515188IS | P | < 1.0 |
| RW-02 | 8/22/2018 | RW-02-082218 | P | < 1.0 |
| RW-02 | 10/2/2018 | RW021002105IS | P | 1.3 |
| RW-02 | 11/5/2018 | RW-02-110518-1IS | P | 1.6 |
| RW-02 | 2/7/2019 | RW02-020719-1IS | P | 1.2 |
| RW-02 | 4/17/2019 | RW02-041719-10IS | P | 1.3 |
| RW-05 | 3/6/2018 | RW-05-03062018 | P | 3.9 |
| RW-05 | 4/4/2018 | RW-05-04042018 | P | 3.9 |
| RW-05 | 5/15/2018 | RW050515189IS | P | 3.9 |
| RW-05 | 8/22/2018 | RW-05-082218 | P | 4.2 |
| RW-05 | 10/2/2018 | RW0510021804IS | P | 5.1 |
| RW-05 | 11/5/2018 | RW-05-110518-2IS | P | 3.6 |
| RW-05 | 2/7/2019 | RW05-020719-2IS | P | 3.7 |
| RW-05 | 4/17/2019 | RW05-041719-7IS | P | 3.7 |
| RW-06 | 3/6/2018 | RW-06-03062018 | P | 11.6 |
| RW-06 | 4/4/2018 | RW-06-04042018 | P | 8.9 |
| RW-06 | 5/15/2018 | RW0605151812IS | P | 7.8 |
| RW-06 | 8/22/2018 | RW-06-082218 | P | 10 |
| RW-06 | 8/22/2018 | DUP-01-082218 | FD | 10.6 |
| RW-06 | 10/2/2018 | RW0610021803IS | P | 10.7 |
| RW-06 | 11/5/2018 | RW-06-110518-5IS | P | 8.2 |
| RW-06 | 2/7/2019 | RW06-020719-5IS | P | 13.5 |
| RW-06 | 4/17/2019 | RW06-041719-9IS | P | 10.8 |

Notes:

Bold = Detection above groundwater treatment goal

µg/L = micrograms per liter

P = Primary/Parent Sample

FD = Field Duplicate

-- = not analyzed

<1.0 = Below Laboratory Reporting Levels

On-site groundwater treatment goal = 29 µg/L

Off-site groundwater treatment goal = 6.7 µg/L

Table C-5: OU 06 Deep Zone Groundwater Remediation System Performance and Compliance Monitoring Plan Taken from GEA Table 1 Annual and Semi-Annual Reports - July 2015 through June 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico.

| Former Air Force Plant 83/General Electric Operable Unit - Albuquerque, New Mexico Ground Water Quality Monitoring | | | | | | | | | |
|--|---------------------------------|-------------|------------------|---|----------------|----------------|--|-----------|-----------|
| Annual | Semi-annual | | Semi-annual | Semi-annual | | | Monthly Treatment System Compliance Sampling | | |
| Monitoring Wells | Extraction and Monitoring Wells | | Monitoring Wells | Extraction, Injection, and Monitoring wells | | | Sample Port SP-425 | | |
| P83-22S | EW-001 | P83-22D-2 | SJ6-02D | D-01 | IW-631 | P83-22 cluster | 7/1/2015 | 12/2/2016 | 7/2/2018 |
| P83-22M | EW-002 | P83-30D-2 | SJ6-07D | D-02 | IW-633 | P83-23 cluster | 8/5/2015 | 1/5/2017 | 8/1/2018 |
| P83-22D | EW-003R | WB-01 (1-6) | SJ6-08D | D-03 | IW-634 | P83-24 cluster | 9/2/2015 | 2/1/2017 | 9/4/2018 |
| P83-26M | EW-004 | WB-02 (1-5) | SJ6-10D | EW-001 | IW-635R | P83-25 cluster | 10/5/2015 | 3/2/2017 | 10/1/2018 |
| P83-26D | P83-07D | WB-04 (3-6) | | EW-002 | IW-636 | P83-26 cluster | 11/5/2015 | 4/3/2017 | 11/1/2018 |
| P83-29S | P83-09D | WB-05 (1-6) | | EW-003R | IW-637R | P83-27 cluster | 12/1/2015 | 5/1/2017 | 12/3/2018 |
| WB-04 (1-2, 10-12) | P83-19D-2 | | | EW-004 | IW-638R | P83-28 cluster | 1/20/2016 | 6/1/2017 | 1/2/2019 |
| WB-07 (1-5) | P83-19LR | | | HL-02 | IW-639 | P83-29 cluster | 2/1/2016 | 7/3/2017 | 2/1/2019 |
| | P83-19M | | | HL-05 | IW-640 | P83-30D-2 | 3/1/2016 | 8/1/2017 | 3/1/2019 |
| | P83-19U | | | I-03 | IW-641 | P83-31 cluster | 4/1/2016 | 9/1/2017 | 4/2/2019 |
| | | | | I-04 | IW-642 | SJ6-01D | 5/5/2016 | 10/2/2017 | 5/1/2019 |
| | | | | I-06 | P83-07D | WB-01 (1-6) | 6/1/2016 | 11/8/2017 | 6/4/2019 |
| | | | | | P83-09D | WB-02 (1-8) | 7/1/2016 | 12/1/2017 | |
| | | | | | P83-10D | WB-04 (1-7) | 8/1/2016 | | |
| | | | | | P83-11D | WB-05 (1-9) | 9/1/2016 | | |
| | | | | | P83-19 cluster | WB-06 (1-8) | 10/3/2016 | | |
| | | | | | P83-21 cluster | WB-07 (1-5) | 11/1/2016 | | |

Notes:

1. This table reflects modifications to the sampling program based on the EPAs correspondence dated 10-19-10 regarding agency approval of monitoring program modifications.
2. Number in parentheses in Westbay™ well designations refers to screen/port number.
3. The treatment system compliance samples are collected at the effluent line to the injection header (SP-425).

P = Piezometer
D, LR, and D-2 = Deep interval within deep zone aquifer M = Middle interval within deep zone aquifer
S and U = Shallow interval within deep zone aquifer

(This page is intentionally left blank)

Figure C-1: Operational Units OU 02, OU 05, and OU 06, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico



Figure C-2: OU 03 Well Locations and Distribution of 1,4-dioxane at Univar South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-4: GEA Well Locations and Distribution of 1,4-dioxane in Shallow Aquifer January 2016 through April 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-5: Univar Potentiometric Surface Elevation – April 3, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-6: Univar Potentiometric Surface Elevation – May 14, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-7: Univar Potentiometric Surface Elevation – August 23, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-8: Univar Potentiometric Surface Elevation – October 4, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-9: Univar Potentiometric Surface Elevation – November 6, 2018, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico




Figure C-10: Univar Potentiometric Surface Elevation – February 6, 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico





Figure C-11: Univar Potentiometric Surface Elevation – April 16, 2019, South Valley Superfund Site, Albuquerque, Bernalillo County, New Mexico



APPENDIX D – INTERVIEWS

| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
|--|--|--|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: November 4, 2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode 6SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: william.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Katy Brantingham | Title: Associate VP | Organization: Arcadis U.S., Inc. (Lead Project Consultant) |
| Telephone No: 602.797.4523 E-Mail Address: katy.brantingham@arcadis.com | Street Address: 410 N. 44 th Street, Suite 1000 City, State, Zip: Phoenix, AZ 85008 | |
| Survey Questions | | |
| 1. What is your overall impression of the project? (general sentiment) | | |
| <i>Very Good. Open and cooperative communication between all parties</i> | | |
| 2. Is the remedy functioning as expected? How well is the remedy performing? | | |
| <i>The USEPA and NMED issued a notice of completion dated 6/10/14 that acknowledged Univar USA Inc. (Univar) had completed all the requirements of the Consent Decree as they relate to the Constituents of Concern in ground water with the exception of 1,4-dioxane.</i> | | |
| <i>During this 5-year review period (2016-2020), the remedy was modified to treat 1,4-dioxane. The objective of the groundwater recovery, treatment, and injection system (GRTIS) is to reduce 1,4-dioxane concentrations in on-site (Univar property) groundwater to 29 micrograms per liter (µg/L) or less and off-site groundwater (properties not owned by Univar) to 6.7 µg/L or less (Arcadis 2016a). This objective is being achieved by recovering groundwater impacted with 1,4-dioxane and pumping it to the treatment system (advance oxidation process), treating the 1,4-dioxane in the recovery water and reinjecting the treated water upgradient of the recovery area to flush the potentially impacted vadose zone and reduce the groundwater remediation timeframe. The treatment system treats 1,4-dioxane to a concentration less than 6.7 µg/L.</i> | | |
| <i>The modified system was started on March 5, 2018. Monitoring and maintenance is on-going. Since startup, the system has operated 99.9 percent of the time and the total volume of extracted groundwater treated by the GRTIS from February 23, 2018 through October 2, 2019 was 57,171,964 gallons and 6 pounds of 1,4-dioxane was removed from the extracted groundwater.</i> | | |

The following documents were submitted:

- Arcadis. 2016. Remedial Work Plan For 1,4-Dioxane In Groundwater Univar USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. July 22.
- Arcadis. 2017. Well Installation Univar USA Inc. 3301 Edmunds Street Site, Albuquerque, New Mexico. April 27.
- Arcadis. 2018a. Treatment System Construction Report for 1,4-Dioxane in Groundwater. Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. July 31.
- Arcadis. 2018b. Operation, Monitoring, And Maintenance Manual Univar USA Inc. 3301 Edmunds Street Site Albuquerque, New Mexico. July 31.
- Arcadis. 2018c. Field Sampling Plan. Univar USA Inc. 3301 Edmunds Street Albuquerque, New Mexico. July 31.
- Arcadis. 2018d. 2018 Remediation Progress Report, For Remedial Actions at Operable Unit 3 of the South Valley Superfund Site in Albuquerque, New Mexico. December 7.
- Arcadis. 2019. 2019 Annual Remediation Progress Report, For Remedial Actions at Operable Unit 3 of the South Valley Superfund Site in Albuquerque, New Mexico. June 26.

3. What does the monitoring data show? Are there any trends that show contaminant levels are decreasing?

The recovery well network has effectively captured the treated water from the injection wells as demonstrated by the potentiometric surface elevation contours and concentrations of 1,4-dioxane in the recovery wells and nearby monitoring wells. 1,4-Dioxane concentrations in the recovery wells decreased significantly within two months of system startup and then remained relatively stable during the period of injection well operation indicating that flushing of the vadose zone had occurred and clean water was breaking through to the recovery wells. 1,4-Dioxane concentrations in recovery wells (RW-05, RW-06, and GM-27), spiked after the cessation of recharge in injection wells IW-1, IW-2, IW-3 and VE-06 in October 2018, but have a decreasing trend throughout the first two quarterly sampling events. 1,4-Dioxane concentrations in downgradient groundwater monitoring wells east of Interstate 25 (I-25) (GM-15S, GM-29, and GM-30) have decreased overall but have not decreased significantly since the start-up of the GRTIS.

4. Is there a continuous on-site O&M presence? If so, please describe staff and activities. If there is not a continuous on-site presence, describe staff and frequency of site inspections and activities.

Univar Solutions USA Inc. (Univar Solutions) still operates at the facility so there are personnel and security at the facility. Maintenance and monitoring of the GRTIS is conducted by Arcadis and includes remote system monitoring, biweekly OM&M site visits, monthly process monitoring, and quarterly GRTIS performance sampling. These were conducted in accordance with the Remedial Work Plan. The GRTIS is adjusted based on the OM&M conducted at the Site to optimize performance. Depths to groundwater is conducted quarterly and groundwater monitoring is conducted semiannually.

During the biweekly OM&M site visits, the general system condition is checked by visually inspecting mechanical and electrical components of the system, tanks, equipment, and associated piping for leaks, cracks, chips, exterior corrosion, or other damage, and performing preventative maintenance on equipment components in accordance with manufacturer's recommendations. During each OM&M visit the following information was collected using a tablet to ensure GRTIS was running at optimal performance:

- Groundwater recovery flow rates, totalizer flow readings, groundwater level if

possible, and pressure at each recovery well.

- *Injection flow rate, totalizer readings, groundwater level if possible, and pressure at each injection well and infiltration gallery.*
- *Water-level data from dedicated pressure transducers in operating recovery and injection wells.*
- *System readings including electric meter, tank levels, flow rates, volumes, temperatures, and pressures throughout the treatment units.*

5. Have there been any significant changes in the O&M requirements, maintenance schedules, or sampling routines in the last five years? If so, do they affect the protectiveness or effectiveness of the remedy? Please describe changes and impacts.

None since the system was modified.

6. Have there been unexpected O&M difficulties or costs at the site since the last five years? If so, please give details.

None since the system was modified.

7. Have there been opportunities to optimize O&M, or sampling efforts? Please describe changes and resultant or desired cost savings or improved efficiency.

None since the system was modified.

8. Do you have any comments, suggestions, or recommendations regarding the project?

Due to increasing concentrations of 1,4-dioxane in monitoring well GM-9S, this well will be converted to a groundwater recovery well and vapor extraction wells VE-2 and VE-3 will be converted to injection wells to optimize the system. Continued operation and optimization of the GRTIS is recommended until 1,4-dioxane groundwater concentrations are reduced to less than the 29 µg/L on-site cleanup goal and the 6.7 µg/L off-site cleanup goal. Maintenance and monitoring will continue as approved in the Remedial Work Plan.

| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
|---|--|--------------------------|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: October 29, 2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode 6SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: william.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Julie Einerson | Title: GE Contract Environmental Manager | Organization: |
| Telephone No: (505) 440-2905 E-Mail Address: julie.einerson@ge.com | Street Address: City, State, Zip: | |
| Survey Questions | | |
| <p>1. What is your overall impression of the project? (general sentiment) <i>My impression is that the SVSS project is well managed and continues to progress toward completion. The partial deletion of three Operable Units (OUs 1, 2, and 5) is very positive for the community and in the ability to return the properties to viable use. OU 6 is the last operable unit managed by GE and is on track to achieving the goal of reaching ARARs in the groundwater in the very near future.</i></p> <p>2. Is the remedy functioning as expected? How well is the remedy performing? <i>Yes, only one monitoring well has contaminants that remain above ARARs. The water entering the Treatment Plant System is clean with no detectable contaminants. We've reached the end of the viable use of the pump and treat remedy.</i></p> <p>3. What does the monitoring data show? Are there any trends that show contaminant levels are decreasing? <i>Yes, as stated in the previous question the system has reached its optimal usefulness and has essentially eliminated the plume of contamination it was originally designed to address. This is shown in that no contaminants above ARARs have been detected in the five of the six extraction wells for at least 10 years. One extraction well (EW-006) has had no VOCs above ARARs for two years. Only two conventional monitoring wells have VOCs above ARARs at this time.</i></p> <p>4. Is there a continuous on-site O&M presence? If so, please describe staff and activities. If there is not a continuous on-site presence, describe staff and frequency of site inspections and activities. <i>There is continuous on-site presence, operators man the Treatment Plant operations 5 days a week and are on call at night and over weekends in case any system issues arise. The Treatment Plant is programmed to auto-dial the operators if any alarms through the system occur so they can respond as necessary.</i></p> | | |

5. Have there been any significant changes in the O&M requirements, maintenance schedules, or sampling routines in the last five years? If so, do they affect the protectiveness or effectiveness of the remedy? Please describe changes and impacts.

There have not been any changes in the maintenance schedules or sampling routines in the past five years.

The O&M requirements have been adjusted as needed to shut off pumping in extraction wells to "shock" the aquifer to assist in more efficient removal of the remaining contaminants. This has proven very effective in that in the previous Five-Year Report five wells had contaminants above ARARs. Today only two conventional wells have contaminants above ARARs.

6. Have there been unexpected O&M difficulties or costs at the site since the last five years? If so, please give details.

Yes, as a result of the adjustments to the pumping regimes discussed in Q5, extraction well EW-003R, which had been shut down for several months to pulse the aquifer, had a pump/motor failure within 3 months of returning to service. In rehabilitating the well, it was determined that the shutdown of the well had caused significant bacterial growth in the well which clogged the screen. This bacterial growth of an iron reducing bacteria caused a breach in the well screen allowing sediment to infiltrate the well. It also caused the pump/motor to over-work due to pumping the sediment and difficulty pumping water through the bacterial clogged screen, ultimately causing the failure of the pump/motor. The rehabilitation of this well cost \$115K and system downtime. The lesson take-away is that once the system is shut-down there will be no turning it back on. Injection and extraction wells will be lost for use.

7. Have there been opportunities to optimize O&M, or sampling efforts? Please describe changes and resultant or desired cost savings or improved efficiency.

The system optimization was responded to in previous questions. There are no cost savings, the system has reached asymptotic levels of contaminant removal and is extremely costly to continue to operate for the benefit of removing contaminants that have been below ARARs in extraction wells for the past 13 years. The annual operational costs at an average of \$1.3M per year for the past 4 years for groundwater below ARAR's in extraction wells is an extremely poor use of resources from a sustainability standpoint, i.e. electrical use, and financially for tax payer funded expenditures.

8. Do you have any comments, suggestions, or recommendations regarding the project?

Yes, it's time to shut the system down.

| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
|--|--|------------------------------|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: 10/29/2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode 6SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: william.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: John W. Billiard, PE | Title: Principal Engineer | Organization: Axis Group Inc |
| Telephone No: (303) 332-5757 E-Mail Address: jwb@axisgroupinc.com | Street Address: 5374 E. Otero Dr. City, State, Zip: Centennial, CO 80122 | |
| Survey Questions | | |
| <p>1. What is your overall impression of the project? (general sentiment):</p> <p><i>The project continues to progress toward completion. Three Operable Units (OUs 1, 2, and 5) are already complete, and have been delisted. OU 6 is on track to achieving its goals of reaching ARARs in the ground water. OU 6 is managed by GE.</i></p> <p>2. Is the remedy functioning as expected? How well is the remedy performing?</p> <p><i>OU 6 (Deep Ground water) is functioning as designed. Ground water level and quality data collected to date demonstrates capture, containment, treatment, and reinjection of treated water back to the aquifer and that overall, the system has been and continues to be protective of human health and the environment. To date, about 7.8 billion gallons of ground water have been extracted, treated to non-detect levels, and returned to the aquifer for beneficial use.</i></p> <p>3. What does the monitoring data show? Are there any trends that show contaminant levels are decreasing?</p> <p><i>The OU 6 (Deep Ground water), ground water data indicate levels of dissolved VOCs in ground water are decreasing. At this point, only two ground water sample wells indicate dissolved VOCs in ground water at a level barely above ARARs.</i></p> <p>4. Is there a continuous on-site O&M presence? If so, please describe staff and activities. If there is not a continuous on-site presence, describe staff and frequency of site inspections and activities.</p> <p><i>The OU 6 (Deep Ground water) remediation system operates on a continuous basis (i.e. 24/7/365). Two engineers currently work at the OU 6 remediation system during normal working hours, five days a week all year. When the operators are not physically at the site, an automated system will alert them via telephone call if the remediation system requires attention. When necessary, one of the operators will return to the site and attend to the remediation system as required outside of normal work hours (evenings and weekends).</i></p> | | |

5. Have there been any significant changes in the O&M requirements, maintenance schedules, or sampling routines in the last five years? If so, do they affect the protectiveness or effectiveness of the remedy? Please describe changes and impacts.

The Deep Zone Ground water Remediation System has been and continues to be protective of human health and the environment. Minor modifications to the ground water sample program have been made for efficiency and after discussions with the regulatory agencies. Based on ground water data, the ground water extraction and injection systems have been modified to improve the efficiency of the overall system.

6. Have there been unexpected O&M difficulties or costs at the site since the last five years? If so, please give details.

O&M difficulties at the Deep Zone Ground water Remediation System include having to rehabilitate an extraction well after the well was turned off for about six months. Well rehabilitation is very costly and time consuming.

7. Have there been opportunities to optimize O&M, or sampling efforts? Please describe changes and resultant or desired cost savings or improved efficiency.

Extraction wells were added to the overall system to address dissolved VOCs in the groundwater at specific areas. When needed, extraction and injection wells are rehabilitated to improve efficiency. In addition, extraction wells are turned off and then restarted at different times to improve extraction efficiency.

Note that when an extraction or injection well is turned off for a relatively lengthy time (months or longer) naturally occurring bacteria grow and clog the screen interval requiring well rehabilitation prior to restarting extraction or injection. This is very important when considering long term changes such as a shut down. Should the Deep Zone Groundwater System be turned off for a month or longer, it will likely require very significant and costly work to restart the system due to the loss of extraction and injection well capacity.

8. Do you have any comments, suggestions, or recommendations regarding the project?

The Deep Zone Groundwater Treatment System has effectively remediated the San Jose Aquifer. The Deep Zone Groundwater Treatment System extracts, treats, and injects over 20 million gallons per month of virtually clean water. Data from only two monitoring wells in over 60 sampling wells indicate dissolved VOCs above ARARs. In other words, the San Jose Aquifer remediation (OU 6) is effectively complete.

| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
|--|---|--|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: November 1, 2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: William.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Todd Burt | Title: Senior Vice President | Organization: Bohannon Huston Inc. |
| Telephone No: 505-823-1000 E-Mail Address: tburt@bhinc.com | | Street Address: 7500 Jefferson St, NE City, State, Zip: Albuquerque, NM 87109 |
| Survey Questions | | |
| <p>1. What is your general impression of the work conducted at the South Valley Superfund Site? <i>The work is being handled in a professional manner. The site is kept clean and in working order.</i></p> <p>2. What effects have site cleanup operation efforts had on the surrounding community/area? <i>Based on conversations with the staff, the groundwater contamination is being reduced and efforts to protect the groundwater resource appear beneficial. The staff have also worked to clean up “dumped” trash in the area and have contacted the County or City to assist with these activities.</i></p> <p>3. Are you aware of any community concerns regarding the South Valley Superfund Site? If so, please give details. <i>No.</i></p> <p>4. Are you aware of any complaints, incidents, or activities at the site in the past five years such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. <i>No.</i></p> <p>5. Do you feel well informed about the site’s activities and progress? If not, please indicate how you would like to be informed about site activities – for example by e-mail, regular mail, fact sheets, meetings, etc. <i>Yes. Communication from staff on-site has been thorough and responsive.</i></p> <p>6. Do you have any comments, suggestions, or recommendations regarding the site’s management or operation? <i>The facility remains in good condition and clean. The operations are overseen consistently and the staff are professional.</i></p> | | |

| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
|--|---|--|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: 11/7/2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: William.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Rodrigo Eichwald | Title: Engineering Manager | Organization: Bernalillo County |
| Telephone No: 505-848-1574 E-Mail Address: rleichwald@berncogov | Street Address: 2400 Broadway SE City, State, Zip: ABQ, NM 87120 | |
| Survey Questions | | |
| <p>1. What is your general impression of the work conducted at the South Valley Superfund Site? The work being done to clean up the area is impressive.</p> <p>2. What effects have site cleanup operation efforts had on the surrounding community/area? It has allowed the Sunport Blvd Extension Project to move forward.</p> <p>3. Are you aware of any community concerns regarding the South Valley Superfund Site? If so, please give details. Yes, the community thinks incorrectly that the site has not been cleaned up and they won't let the sins of the past go.</p> <p>4. Are you aware of any complaints, incidents, or activities at the site in the past five years such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. I'm not aware of any.</p> <p>5. Do you feel well informed about the site's activities and progress? If not, please indicate how you would like to be informed about site activities – for example by e-mail, regular mail, fact sheets, meetings, etc. Yes.</p> <p>6. Do you have any comments, suggestions, or recommendations regarding the site's management or operation? No, the Axis group is doing a fantastic job with their remediation.</p> | | |

| | | |
|---|--|--|
| SUPERFUND FIVE-YEAR REVIEW SITE SURVEY | | |
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: November 7, 2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode 6SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: William.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Brian Lopez | Title: Construction Manager | Organization: Bernalillo County |
| Telephone No: 505-848-1525 E-Mail Address: bjlopez@bernco.gov | Street Address: 2400 Broadway City, State, Zip: Albuquerque, NM, 87102 | |
| Survey Questions | | |
| <p>1. What is your general impression of the work conducted at the South Valley Superfund Site? The work being performed is being handled in a thoughtful manner to the surrounding areas and is beneficial to the environment.</p> <p>2. What effects have site cleanup operation efforts had on the surrounding community/area? The site cleanup operation has been performed in a discrete manor so the efforts have had no negative effects.</p> <p>3. Are you aware of any community concerns regarding the South Valley Superfund Site? If so, please give details. Comments received in the past concerning the site have been residents wanting a safe distance from potential chemical accidents, explosions and release of hazardous chemicals. Development in the area is being persued for financial gains at the expense of the health and well being of the many low income, minority residents in the San Jose and Mountain View communities. Projects in the area are implemented for the sole purpose of enhancing the industrial use of business in the northern area.</p> <p>4. Are you aware of any complaints, incidents, or activities at the site in the past five years such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. The county is aware of constant trespassing where illegal dumping occurs on a regular basis.</p> <p>5. Do you feel well informed about the site's activities and progress? If not, please indicate how you would like to be informed about site activities – for example by e-mail, regular mail, fact sheets, meetings, etc. Yes, I feel I will informed about he site.</p> <p>6. Do you have any comments, suggestions, or recommendations regarding the site's management or operation? I do not have any additional comments.</p> | | |

SUPERFUND FIVE-YEAR REVIEW SITE SURVEY

| | | |
|--|---|---|
| Site Name: South Valley Superfund Site | | EPA ID No.: NMD980745558 |
| Location: Albuquerque, Bernalillo County, New Mexico | | Date: November 19, 2019 |
| Contact Made By: | | |
| Name: Michael Hebert | Title: Remedial Project Manager | Organization: U.S. EPA |
| Telephone No.: (214) 665-8315 E-Mail: hebert.michael@epa.gov | Street Address: 1201 Elm Street, Suite 500, Mailcode SEDRL City, State, Zip: Dallas, Texas 75270 | |
| Name: Bill Pearson | Title: State Project Manager | Organization: NMED |
| Telephone: (505) 827-0039 E-Mail: William.pearson@state.nm.us | Street Address: 1190 St. Francis Drive City, State, Zip: Santa Fe, New Mexico 87505 | |
| Individual Contacted: | | |
| Name: Frances Armijo | Title: | Organization: <i>South Broadway Neighborhood Association</i> |
| Telephone No: 505-247-8798 | | Street Address: 915 Williams St. SE |
| E-Mail Address: | | City, State, Zip: Albuquerque, NM 87102 |
| Survey Questions | | |
| <p>1. What is your general impression of the work conducted at the South Valley Superfund Site? <i>Not doing enough about the pollution problem (air, water) to make he community safe.</i></p> <p>2. What effects have site cleanup operation efforts had on the surrounding community/area? <i>Not sure.</i></p> <p>3. Are you aware of any community concerns regarding the South Valley Superfund Site? If so, please give details. <i>Yes, concerned about air quality issues in San Jose and adjacent communities.</i></p> <p>4. Are you aware of any complaints, incidents, or activities at the site in the past five years such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details. <i>NO.</i></p> <p>5. Do you feel well informed about the site’s activities and progress? If not, please indicate how you would like to be informed about site activities – for example by e-mail, regular mail, fact sheets, meetings, etc. <i>NO. I get all my information from Esther Abeyta concerning the SV Site. As a community organization I would like to be more informed about issues and events concerning the SV Site. Please add my organization, South Broadway Neighborhood Association, to your mailing/emailing list.</i></p> <p><i>South Broadway Neighborhood Association C/O Frances Armijo 915 Williams St. SE Albuquerque, NM 87102 505-247-8798</i></p> <p>6. Do you have any comments, suggestions, or recommendations regarding the site’s management or operation? <i>NO.</i></p> | | |

APPENDIX E – SITE INSPECTION CHECKLIST

| I. SITE INFORMATION | |
|---|--|
| Site name: South Valley Superfund Site - GEA | Date of inspection: October 22, 2019 |
| Location and Region: Albuquerque, New Mexico | EPA ID: NMD980745558 |
| Agency, office, or company leading the five-year review: EPA Region 6 | Weather/temperature: Sunny, Calm, 50s |
| Remedy Includes: (Check all that apply) <ul style="list-style-type: none"> <input type="checkbox"/> Landfill cover/containment <input checked="" type="checkbox"/> Access controls <input checked="" type="checkbox"/> Institutional controls <input checked="" type="checkbox"/> Ground water pump and treatment <input type="checkbox"/> Surface water collection and treatment Other _____ _____ _____ | |
| Attachments: <input checked="" type="checkbox"/> Inspection team roster attached <input type="checkbox"/> Site map attached | |
| II. INTERVIEWS (Check all that apply) | |
| 1. O&M site manager <u>John Billiard</u> <u>Technical Director</u> <u>10/22/2019</u> <div style="display: flex; justify-content: space-around; font-size: small;"> Name Title Date </div> Interviewed <input checked="" type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. <u>(303) 332-5757</u> Problems, suggestions; <input checked="" type="checkbox"/> Report attached <input type="checkbox"/> Survey form attached to report; interview at site as well. | |
| 2. O&M staff <u>Leonard Stockton Jr.</u> <u>Senior Engineer</u> <u>10/22/2019</u> <div style="display: flex; justify-content: space-around; font-size: small;"> Name Title Date </div> Interviewed <input type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. <u>(505) 247-3919</u> Problems, suggestions; <input type="checkbox"/> Report attached | |

3. **Local regulatory authorities and response agencies** (i.e., State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.) Fill in all that apply.

Agency County of Bernalillo

Contact Brian Lopez Construction Section Manager 10/12/2019 (505) 848-1525

Name Title Date Phone no.

Problems; suggestions; Report attached

Agency

Contact

Name Title Date Phone no.

Problems; suggestions; Report attached

Agency

Contact

Name Title Date Phone no.

Problems; suggestions; Report attached

4. **Other interviews (optional)** Report attached.

Ester and Steven Abeyta, San Jose Neighborhood Residents

Katy Brantingham, ARCADIS, Inc.

Julie Einerson, GEA Albuquerque

Todd Burt, Bohannon & Huston

III. ON-SITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)

1. O&M Documents

O&M manual Readily available Up to date N/A

As-built drawings Readily available Up to date N/A

Maintenance logs Readily available Up to date N/A

Remarks

2. Site-Specific Health and Safety Plan Readily available Up to date N/A

Contingency plan/emergency response plan Readily available Up to date N/A

Remarks HASP 2014 and PCMP 2014

| | | | | |
|--|--|--|--|---|
| 3. | O&M and OSHA Training Records | <input checked="" type="checkbox"/> Readily available | <input checked="" type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| Remarks <u>Leonard Stockton and Louis Keating (Both on file at treatment plant office)</u> | | | | |
| 4. | Permits and Service Agreements | | | |
| | <input type="checkbox"/> Air discharge permit | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| | <input checked="" type="checkbox"/> Effluent discharge | <input checked="" type="checkbox"/> Readily available | <input checked="" type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| | <input type="checkbox"/> Waste disposal, POTW | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| | <input type="checkbox"/> Other permits | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| Remarks <u>Ground Water Discharge Plan DP 1625, December 18, 2017.</u> | | | | |
| 5. | Gas Generation Records | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| Remarks _____ | | | | |
| 6. | Settlement Monument Records | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| Remarks _____ | | | | |
| 7. | Ground water Monitoring Records | <input checked="" type="checkbox"/> Readily available | <input checked="" type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| Remarks <u>Annual and Semi-Annual Reports</u> | | | | |
| 8. | Leachate Extraction Records | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| Remarks _____ | | | | |
| 9. | Discharge Compliance Records | | | |
| | <input type="checkbox"/> Air | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| | <input checked="" type="checkbox"/> Water (effluent) | <input checked="" type="checkbox"/> Readily available | <input checked="" type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| Remarks <u>Records Provided Monthly</u> | | | | |
| 10. | Daily Access/Security Logs | <input checked="" type="checkbox"/> Readily available | <input checked="" type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| Remarks <u>Sign in Sheet hanging by the Treatment Building Office</u> | | | | |
| IV. O&M COSTS | | | | |
| 1. | O&M Organization | | | |
| | <input type="checkbox"/> State in-house | <input type="checkbox"/> Contractor for State | | |
| | <input type="checkbox"/> PRP in-house | <input checked="" type="checkbox"/> Contractor for PRP | | |
| | <input type="checkbox"/> Federal Facility in-house | <input type="checkbox"/> Contractor for Federal Facility | | |
| | <input type="checkbox"/> Other _____ | | | |

| | | | |
|---|----------|--|---|
| 2. O&M Cost Records | | | |
| <input checked="" type="checkbox"/> Readily available | | <input checked="" type="checkbox"/> Up to date | |
| <input type="checkbox"/> Funding mechanism/agreement in place | | | |
| Original O&M cost estimate _____ | | <input type="checkbox"/> Breakdown attached | |
| Total annual cost by year for review period if available | | | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| 3. Unanticipated or Unusually High O&M Costs During Review Period | | | |
| Describe costs and reasons: _____ | | | |
| V. ACCESS AND INSTITUTIONAL CONTROLS <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | | | |
| A. Fencing | | | |
| 1. Fencing damaged <input type="checkbox"/> Location shown on site map | | <input checked="" type="checkbox"/> Gates secured <input type="checkbox"/> N/A | |
| Remarks <u>Deep Zone Aquifer Treatment System: Treatment building is surrounded by a security fence; it is 9-ft high and consists of an 8-ft high chain-link fabric and three strands of barbed-wire supported by 45-degree extensions. Access is controlled by the plant personnel. All wells are outside of the fenced area but they are secured, extraction wells at the deep zone aquifer being also equipped with alarm systems after vandalism affected system operation. Access at the deep zone aquifer controlled by the Contractor.</u> | | | |
| B. Other Access Restrictions | | | |
| 1. Signs and other security measures <input type="checkbox"/> Location shown on site map | | <input checked="" type="checkbox"/> N/A | |
| Remarks _____ | | | |
| C. Institutional Controls (ICs) | | | |

| | | | |
|---|--|--|---|
| 1. Implementation and enforcement | | | |
| Site conditions imply ICs not properly implemented | | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A |
| Site conditions imply ICs not being fully enforced | | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A |
| Type of monitoring (e.g., self-reporting, drive by) <u>Reporting by other entities to EPA; New Mexico Office of the State Engineers (NMOSE) drilling restrictions; ground water discharge permit</u> | | | |
| Frequency <u>monthly reporting of discharged volumes, quarterly sampling for ground water permit</u> | | | |
| Responsible party/agency <u>GEA; EPA; NMED</u> | | | |
| Contact _____ | | | |
| | Name | Title | Date Phone no. |
| Reporting is up-to-date | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Reports are verified by the lead agency | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Specific requirements in deed or decision documents have been met | | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| Violations have been reported | | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> N/A |
| Other problems or suggestions: | <u>Report attached</u> | | |
| <u>EPA region 6 receives periodic report from entities covered by the Unilateral Order. NMOSE restricts issuing permits for drilling vicinity of the Site. NMED issued permit for ground water discharges</u> | | | |
| 2. Adequacy | <input checked="" type="checkbox"/> ICs are adequate | <input type="checkbox"/> ICs are inadequate | <input type="checkbox"/> N/A |
| Remarks _____ | | | |
| D. General | | | |
| 1. Vandalism/trespassing | <u>Location shown on site map</u> <input checked="" type="checkbox"/> No vandalism evident | | |
| Remarks _____ | | | |
| 2. Land use changes on site | <input checked="" type="checkbox"/> N/A | | |
| Remarks _____ | | | |
| 3. Land use changes off site | <input checked="" type="checkbox"/> N/A | | |
| Remarks _____ | | | |
| VI. GENERAL SITE CONDITIONS | | | |
| A. Roads | <input checked="" type="checkbox"/> Applicable | <input type="checkbox"/> N/A | |

| | | | |
|--|---|---|---|
| 1. Roads damaged | <input type="checkbox"/> Location shown on site map | <input checked="" type="checkbox"/> Roads adequate | <input type="checkbox"/> N/A |
| Remarks _____ | | | |
| B. Other Site Conditions | | | |
| Remarks <u>The site's general appearance was excellent and well maintained.</u> | | | |
| VII. LANDFILL COVERS <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | | |
| A. Landfill Surface | | | |
| 1. Settlement (Low spots) | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Settlement not evident | |
| Areal extent _____ | Depth _____ | | |
| Remarks _____ | | | |
| 2. Cracks | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Cracking not evident | |
| Lengths _____ | Widths _____ | Depths _____ | |
| Remarks _____ | | | |
| 3. Erosion | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Erosion not evident | |
| Areal extent _____ | Depth _____ | | |
| Remarks _____ | | | |
| 4. Holes | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Holes not evident | |
| Areal extent _____ | Depth _____ | | |
| Remarks _____ | | | |
| 5. Vegetative Cover | <input type="checkbox"/> Grass | <input type="checkbox"/> Cover properly established | <input type="checkbox"/> No signs of stress |
| <input type="checkbox"/> Trees/Shrubs (indicate size and locations on a diagram) | | | |
| Remarks _____ | | | |
| 6. Alternative Cover (armored rock, concrete, etc.) | <input type="checkbox"/> N/A | | |
| Remarks _____ | | | |
| 7. Bulges | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Bulges not evident | |
| Areal extent _____ | Height _____ | | |
| Remarks _____ | | | |

| | | |
|--|---|--|
| 8. Wet Areas/Water Damage <input type="checkbox"/> Wet areas/water damage not evident | | |
| <input type="checkbox"/> Wet areas | <input type="checkbox"/> Location shown on site map | Areal extent _____ |
| <input type="checkbox"/> Ponding | <input type="checkbox"/> Location shown on site map | Areal extent _____ |
| <input type="checkbox"/> Seeps | <input type="checkbox"/> Location shown on site map | Areal extent _____ |
| <input type="checkbox"/> Soft subgrade | <input type="checkbox"/> Location shown on site map | Areal extent _____ |
| Remarks _____ | | |
| _____ | | |
| 9. Slope Instability <input type="checkbox"/> Slides <input type="checkbox"/> Location shown on site map <input type="checkbox"/> No evidence of slope instability | | |
| Areal extent _____ | | |
| Remarks _____ | | |
| _____ | | |
| B. Benches <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | |
| (Horizontally constructed mounds of earth placed across a steep landfill side slope to interrupt the slope in order to slow down the velocity of surface runoff and intercept and convey the runoff to a lined channel.) | | |
| 1. Flows Bypass Bench | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> N/A or okay |
| Remarks _____ | | |
| _____ | | |
| 2. Bench Breached | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> N/A or okay |
| Remarks _____ | | |
| _____ | | |
| 3. Bench Overtopped | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> N/A or okay |
| Remarks _____ | | |
| _____ | | |
| C. Letdown Channels <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | |
| (Channel lined with erosion control mats, riprap, grout bags, or gabions that descend down the steep side slope of the cover and will allow the runoff water collected by the benches to move off of the landfill cover without creating erosion gullies.) | | |
| 1. Settlement | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> No evidence of settlement |
| Areal extent _____ Depth _____ | | |
| Remarks _____ | | |
| _____ | | |

| | | | |
|-----------------------|---|------------------------------|-------------------------------|
| 2. | Material Degradation | _ Location shown on site map | _ No evidence of degradation |
| | Material type _____ | Areal extent _____ | |
| | Remarks _____ | | |
| <hr/> | | | |
| 3. | Erosion | _ Location shown on site map | _ No evidence of erosion |
| | Areal extent _____ | Depth _____ | |
| | Remarks _____ | | |
| <hr/> | | | |
| 4. | Undercutting | _ Location shown on site map | _ No evidence of undercutting |
| | Areal extent _____ | Depth _____ | |
| | Remarks _____ | | |
| <hr/> | | | |
| 5. | Obstructions | Type _____ | _ No obstructions |
| | _ Location shown on site map | Areal extent _____ | |
| | Size _____ | | |
| | Remarks _____ | | |
| <hr/> | | | |
| 6. | Excessive Vegetative Growth | Type _____ | |
| | _ No evidence of excessive growth | | |
| | _ Vegetation in channels does not obstruct flow | | |
| | _ Location shown on site map | Areal extent _____ | |
| | Remarks _____ | | |
| <hr/> | | | |
| D. Cover Penetrations | | _ Applicable | <u>X</u> N/A |
| <hr/> | | | |
| 1. | Gas Vents | _ Active | _ Passive |
| | _ Properly secured/locked | _ Functioning | _ Routinely sampled |
| | _ Evidence of leakage at penetration | _ Good condition | |
| | _ Needs Maintenance | | |
| | _ N/A | | |
| | Remarks _____ | | |
| <hr/> | | | |
| 2. | Gas Monitoring Probes | | |
| | _ Properly secured/locked | _ Functioning | _ Routinely sampled |
| | _ Evidence of leakage at penetration | _ Needs Maintenance | _ N/A |
| | Remarks _____ | | |
| <hr/> | | | |

| | | |
|--|---|---|
| 3. Monitoring Wells (within surface area of landfill) | | |
| <input type="checkbox"/> Properly secured/locked | <input type="checkbox"/> Functioning | <input type="checkbox"/> Routinely sampled |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Evidence of leakage at penetration | <input type="checkbox"/> Needs Maintenance |
| <input type="checkbox"/> N/A | Remarks _____ | |
| 4. Leachate Extraction Wells | | |
| <input type="checkbox"/> Properly secured/locked | <input type="checkbox"/> Functioning | <input type="checkbox"/> Routinely sampled |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Evidence of leakage at penetration | <input type="checkbox"/> Needs Maintenance |
| <input type="checkbox"/> N/A | Remarks _____ | |
| 5. Settlement Monuments | | |
| <input type="checkbox"/> Located | <input type="checkbox"/> Routinely surveyed | <input type="checkbox"/> N/A |
| Remarks _____ | | |
| E. Gas Collection and Treatment | | |
| <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A | |
| 1. Gas Treatment Facilities | | |
| <input type="checkbox"/> Flaring | <input type="checkbox"/> Thermal destruction | <input type="checkbox"/> Collection for reuse |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | | |
| 2. Gas Collection Wells, Manifolds and Piping | | |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | | |
| 3. Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings) | | |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | <input type="checkbox"/> N/A |
| Remarks _____ | | |
| F. Cover Drainage Layer | | |
| <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A | |
| 1. Outlet Pipes Inspected | | |
| <input type="checkbox"/> Functioning | <input type="checkbox"/> N/A | |
| Remarks _____ | | |
| 2. Outlet Rock Inspected | | |
| <input type="checkbox"/> Functioning | <input type="checkbox"/> N/A | |
| Remarks _____ | | |
| G. Detention/Sedimentation Ponds | | |
| <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A | |

| | | | |
|---|--|---|--|
| 1. | Siltation | Areal extent _____ | Depth _____ |
| | <input type="checkbox"/> N/A | | <input type="checkbox"/> Siltation not evident |
| Remarks _____ | | | |
| 2. | Erosion | Areal extent _____ | Depth _____ |
| | <input type="checkbox"/> Erosion not evident | | |
| Remarks _____ | | | |
| 3. | Outlet Works | <input type="checkbox"/> Functioning | <input type="checkbox"/> N/A |
| Remarks _____ | | | |
| 4. | Dam | <input type="checkbox"/> Functioning | <input type="checkbox"/> N/A |
| Remarks _____ | | | |
| H. Retaining Walls | | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |
| 1. | Deformations | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Deformation not evident |
| | Horizontal displacement _____ | Vertical displacement _____ | |
| | Rotational displacement _____ | | |
| Remarks _____ | | | |
| 2. | Degradation | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Degradation not evident |
| Remarks _____ | | | |
| I. Perimeter Ditches/Off-Site Discharge | | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |
| 1. | Siltation | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Siltation not evident |
| | Areal extent _____ | Depth _____ | |
| Remarks _____ | | | |
| 2. | Vegetative Growth | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> N/A |
| | <input type="checkbox"/> Vegetation does not impede flow | | |
| | Areal extent _____ | Type _____ | |
| Remarks _____ | | | |

| | | | |
|--|---|---|---|
| 3. | Erosion | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Erosion not evident |
| Areal extent _____ Depth _____ | | | |
| Remarks _____ | | | |
| 4. | Discharge Structure | <input type="checkbox"/> Functioning | <input type="checkbox"/> N/A |
| Remarks _____ | | | |
| VIII. VERTICAL BARRIER WALLS <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | | |
| 1. | Settlement | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> Settlement not evident |
| Areal extent _____ Depth _____ | | | |
| Remarks _____ | | | |
| 2. | Performance Monitoring | Type of monitoring _____ | |
| <input type="checkbox"/> Performance not monitored Frequency _____ <input type="checkbox"/> Evidence of breaching | | | |
| Head differential _____ | | | |
| Remarks _____ | | | |
| IX. GROUND WATER/SURFACE WATER REMEDIES <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | | | |
| A. Ground water Extraction Wells, Pumps, and Pipelines <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | | | |
| 1. | Pumps, Wellhead Plumbing, and Electrical | | |
| <input checked="" type="checkbox"/> Good condition <input checked="" type="checkbox"/> All required wells properly operating <input type="checkbox"/> Needs Maintenance <input type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| 2. | Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances | | |
| <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance | | | |
| Remarks _____ | | | |
| 3. | Spare Parts and Equipment | | |
| <input checked="" type="checkbox"/> Readily available <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Requires upgrade <input type="checkbox"/> Needs to be provided | | | |
| Remarks _____ | | | |
| B. Surface Water Collection Structures, Pumps, and Pipelines <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | | |

| |
|--|
| <p>1. Collection Structures, Pumps, and Electrical</p> <p><input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> |
| <p>2. Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances</p> <p><input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> |
| <p>3. Spare Parts and Equipment</p> <p><input type="checkbox"/> Readily available <input type="checkbox"/> Good condition <input type="checkbox"/> Requires upgrade <input type="checkbox"/> Needs to be provided</p> <p>Remarks _____</p> |
| <p>C. Treatment System <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A</p> |
| <p>1. Treatment Train (Check components that apply)</p> <p><input type="checkbox"/> Metals removal <input type="checkbox"/> Oil/water separation <input type="checkbox"/> Bioremediation</p> <p><input checked="" type="checkbox"/> Air stripping <input checked="" type="checkbox"/> Carbon adsorbers</p> <p><input checked="" type="checkbox"/> Filters _____</p> <p><input checked="" type="checkbox"/> Additive (e.g., chelation agent, flocculent) <u>AquaMag and pH control</u></p> <p>Others _____</p> <p><input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p><input checked="" type="checkbox"/> Sampling ports properly marked and functional</p> <p><input checked="" type="checkbox"/> Sampling/maintenance log displayed and up to date</p> <p><input checked="" type="checkbox"/> Equipment properly identified</p> <p><input checked="" type="checkbox"/> Quantity of ground water treated annually <u>See Report</u></p> <p><input type="checkbox"/> Quantity of surface water treated annually _____</p> <p>Remarks _____</p> |
| <p>2. Electrical Enclosures and Panels (properly rated and functional)</p> <p><input type="checkbox"/> N/A <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> |

| | | | | | |
|--|--|---|---|--|--|
| 3. | Tanks, Vaults, Storage Vessels | <input type="checkbox"/> N/A | <input checked="" type="checkbox"/> Good condition | <input type="checkbox"/> Proper secondary containment | <input type="checkbox"/> Needs Maintenance |
| Remarks _____ | | | | | |
| 4. | Discharge Structure and Appurtenances | <input type="checkbox"/> N/A | <input checked="" type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | | | | | |
| 5. | Treatment Building(s) | <input type="checkbox"/> N/A | <input checked="" type="checkbox"/> Good condition (esp. roof and doorways) | <input type="checkbox"/> Needs repair | |
| <input type="checkbox"/> Chemicals and equipment properly stored | | | | | |
| Remarks _____ | | | | | |
| 6. | Monitoring Wells (pump and treatment remedy) | <input checked="" type="checkbox"/> Properly secured/locked | <input checked="" type="checkbox"/> Functioning | <input checked="" type="checkbox"/> Routinely sampled | <input checked="" type="checkbox"/> Good condition |
| <input checked="" type="checkbox"/> All required wells located | | | | | |
| | | | | <input type="checkbox"/> Needs Maintenance | <input type="checkbox"/> N/A |
| Remarks _____ | | | | | |
| D. Monitoring Data | | <input checked="" type="checkbox"/> Applicable | | <input type="checkbox"/> N/A | |
| 1. | Monitoring Data | <input checked="" type="checkbox"/> Is routinely submitted on time | | <input checked="" type="checkbox"/> Is of acceptable quality | |
| 2. | Monitoring data suggests: | <input checked="" type="checkbox"/> Ground water plume is effectively contained | | | |
| | | <input checked="" type="checkbox"/> Contaminant concentrations are declining | | | |
| D. Monitored Natural Attenuation | | <input checked="" type="checkbox"/> Applicable | | <input type="checkbox"/> N/A | |

| | |
|---|---|
| 1. | Monitoring Wells (natural attenuation remedy) |
| <input type="checkbox"/> | Properly secured/locked |
| <input type="checkbox"/> | Functioning |
| <input type="checkbox"/> | Routinely sampled |
| <input type="checkbox"/> | Good condition |
| <input type="checkbox"/> | All required wells located |
| <input type="checkbox"/> | Needs Maintenance |
| <input type="checkbox"/> | N/A |
| Remarks _____ | |
| X. OTHER REMEDIES | |
| If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction. | |
| XI. OVERALL OBSERVATIONS | |
| A. Implementation of the Remedy | |
| Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.). <u>Remedy functioned as designed.</u> | |
| B. Adequacy of O&M | |
| Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy. <u>Current O&M activities for wells are adequate.</u> | |
| C. Early Indicators of Potential Remedy Problems | |
| Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future. <u>There are no early indicators of potential remedy failure.</u> | |
| D. Opportunities for Optimization | |

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

See Five-Year Review report.

| I. SITE INFORMATION | |
|---|---|
| Site name: South Valley Superfund Site - Univar | Date of inspection: October 21, 2019 |
| Location and Region: Albuquerque, New Mexico | EPA ID: NMD980745558 |
| Agency, office, or company leading the five-year review: EPA Region 6 | Weather/temperature: Calm and sunny |
| Remedy Includes: (Check all that apply) <ul style="list-style-type: none"> <input type="checkbox"/> Landfill cover/containment <input checked="" type="checkbox"/> Access controls <input checked="" type="checkbox"/> Institutional controls <input checked="" type="checkbox"/> Ground water pump and treatment <input type="checkbox"/> Surface water collection and treatment Other _____ _____ _____ | |
| Attachments: <input checked="" type="checkbox"/> Inspection team roster attached <input type="checkbox"/> Site map attached | |
| II. INTERVIEWS (Check all that apply) | |
| 1. O&M site manager <u>Katy Brantingham</u> <u>ARCADIS Project Manager</u> <u>10-21-2019</u> <div style="display: flex; justify-content: space-around; margin-left: 40px;"> Name Title Date </div> Interviewed <input checked="" type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. <u>(480) 229-6004</u> Problems, suggestions; <input checked="" type="checkbox"/> Report attached Survey form attached to report; interview at site as well. | |
| 2. O&M staff <u>None at Site</u> _____ <u>NA</u> _____ <div style="display: flex; justify-content: space-around; margin-left: 40px;"> Name Title Date </div> Interviewed <input type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. _____ Problems, suggestions; <input type="checkbox"/> Report attached | |

3. **Local regulatory authorities and response agencies** (i.e., State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.) Fill in all that apply.

Agency County of Bernalillo

Contact Brian Lopez Construction Section Manager 12/12/2014 (505) 848-1525

Name Title Date Phone no.

Problems; suggestions; Report attached

Agency _____

Contact _____

Name Title Date Phone no.

Problems; suggestions; Report attached

Agency _____

Contact _____

Name Title Date Phone no.

Problems; suggestions; Report attached

4. **Other interviews** (optional) Report attached.

Ester and Steven Abeyta, San Jose Neighborhood Residents

John Billiard, Axis Group, Inc.

Julie Einerson, GEA

Todd Burt, Bohannon & Huston

III. ON-SITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)

1. O&M Documents

O&M manual Readily available Up to date N/A

As-built drawings Readily available Up to date N/A

Maintenance logs Readily available Up to date N/A

Remarks _____

2. **Site-Specific Health and Safety Plan** Readily available Up to date N/A

Contingency plan/emergency response plan Readily available Up to date N/A

Remarks _____

3. **O&M and OSHA Training Records** Readily available Up to date N/A

Remarks Kept with ARCADIS, records are up to date.

| | | | |
|--|--|-------------------------------------|---|
| 4. Permits and Service Agreements | | | |
| <input type="checkbox"/> Air discharge permit | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| <input type="checkbox"/> Effluent discharge | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| <input type="checkbox"/> Waste disposal, POTW | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| <input type="checkbox"/> Other permits _____ | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| Remarks <u>State Engineer Permit for extraction wells and Plant facility water supply well.</u> | | | |
| 5. Gas Generation Records <input type="checkbox"/> Readily available <input type="checkbox"/> Up to date <input checked="" type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| 6. Settlement Monument Records <input type="checkbox"/> Readily available <input type="checkbox"/> Up to date <input checked="" type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| 7. Ground water Monitoring Records <input type="checkbox"/> Readily available <input type="checkbox"/> Up to date <input checked="" type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| 8. Leachate Extraction Records <input type="checkbox"/> Readily available <input type="checkbox"/> Up to date <input checked="" type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| 9. Discharge Compliance Records | | | |
| <input checked="" type="checkbox"/> Air | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input type="checkbox"/> N/A |
| <input type="checkbox"/> Water (effluent) | <input type="checkbox"/> Readily available | <input type="checkbox"/> Up to date | <input checked="" type="checkbox"/> N/A |
| Remarks <u>Obtained for VES from City of Albuquerque. system terminated in 2005. Permit Terminated.</u> | | | |
| 10. Daily Access/Security Logs <input checked="" type="checkbox"/> Readily available <input checked="" type="checkbox"/> Up to date <input type="checkbox"/> N/A | | | |
| Remarks _____ | | | |
| IV. O&M COSTS | | | |
| 1. O&M Organization | | | |
| <input type="checkbox"/> State in-house | <input type="checkbox"/> Contractor for State | | |
| <input type="checkbox"/> PRP in-house | <input checked="" type="checkbox"/> Contractor for PRP | | |
| <input type="checkbox"/> Federal Facility in-house | <input type="checkbox"/> Contractor for Federal Facility | | |
| <input type="checkbox"/> Other _____ | | | |

| | | | |
|---|----------|--|---|
| 2. O&M Cost Records | | | |
| <input checked="" type="checkbox"/> Readily available <input checked="" type="checkbox"/> Up to date | | | |
| <input type="checkbox"/> Funding mechanism/agreement in place | | | |
| Original O&M cost estimate _____ | | <input type="checkbox"/> Breakdown attached | |
| Total annual cost by year for review period if available | | | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| From _____ | To _____ | _____ | <input type="checkbox"/> Breakdown attached |
| Date | Date | Total cost | |
| 3. Unanticipated or Unusually High O&M Costs During Review Period | | | |
| Describe costs and reasons: | | | |
| <u>None</u> | | | |
| V. ACCESS AND INSTITUTIONAL CONTROLS <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | | | |
| A. Fencing | | | |
| 1. Fencing damaged <input type="checkbox"/> Location shown on site map | | <input checked="" type="checkbox"/> Gates secured <input type="checkbox"/> N/A | |
| Remarks _____ Perimeter security fence has been installed | | | |
| B. Other Access Restrictions | | | |
| 1. <input checked="" type="checkbox"/> Signs and other security measures | | <input type="checkbox"/> Location shown on site map <input type="checkbox"/> N/A | |
| Remarks _____ No signs placed on fences to identify facility for security purposes; surveillance cameras have been installed. | | | |
| C. Institutional Controls (ICs) | | | |

1. Implementation and enforcement
 Site conditions imply ICs not properly implemented Yes No N/A
 Site conditions imply ICs not being fully enforced Yes No N/A

Type of monitoring (e.g., self-reporting, drive by)

Frequency

Responsible party/agency

Contact _____

| Name | Title | Date | Phone no. |
|------|-------|------|-----------|
|------|-------|------|-----------|

Reporting is up-to-date Yes No N/A

Reports are verified by the lead agency Yes No N/A

Specific requirements in deed or decision documents have been met Yes No N/A

Violations have been reported Yes No N/A

Other problems or suggestions: Report attached

2. Adequacy ICs are adequate ICs are inadequate N/A

Remarks _____

D. General

1. Vandalism/trespassing Location shown on site map No vandalism evident
 Remarks Off-site areas around monitoring wells, lots of dumping, mostly construction debris and household items.

2. Land use changes on site N/A

Remarks _____

| |
|--|
| 3. Land use changes off site <input type="checkbox"/> N/A |
| Remarks <u>Parcel of land to north of Plant contains three monitoring wells has change ownership. no access at this time but not a problem with remedy. wells not currently sampled.</u> |
| VI. GENERAL SITE CONDITIONS |
| A. Roads <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A |
| 1. Roads damaged <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Roads adequate <input type="checkbox"/> N/A |
| Remarks _____ |
| B. Other Site Conditions |
| Remarks <u>See D. 1.</u> |
| VII. LANDFILL COVERS <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A |
| A. Landfill Surface |
| 1. Settlement (Low spots) <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Settlement not evident |
| Areal extent _____ Depth _____ |
| Remarks _____ |
| 2. Cracks <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Cracking not evident |
| Lengths _____ Widths _____ Depths _____ |
| Remarks _____ |
| 3. Erosion <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Erosion not evident |
| Areal extent _____ Depth _____ |
| Remarks _____ |
| 4. Holes <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Holes not evident |
| Areal extent _____ Depth _____ |
| Remarks _____ |
| 5. Vegetative Cover <input type="checkbox"/> Grass <input type="checkbox"/> Cover properly established <input type="checkbox"/> No signs of stress |
| <input type="checkbox"/> Trees/Shrubs (indicate size and locations on a diagram) |
| Remarks _____ |

| | | |
|--|--|---|
| 6. | Alternative Cover (armored rock, concrete, etc.) | <input type="checkbox"/> N/A |
| Remarks _____ _____ | | |
| 7. | Bulges | <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Bulges not evident |
| Areal extent _____ Height _____ | | |
| Remarks _____ _____ | | |
| 8. | Wet Areas/Water Damage | <input type="checkbox"/> Wet areas/water damage not evident |
| <input type="checkbox"/> | Wet areas | <input type="checkbox"/> Location shown on site map Areal extent _____ |
| <input type="checkbox"/> | Ponding | <input type="checkbox"/> Location shown on site map Areal extent _____ |
| <input type="checkbox"/> | Seeps | <input type="checkbox"/> Location shown on site map Areal extent _____ |
| <input type="checkbox"/> | Soft subgrade | <input type="checkbox"/> Location shown on site map Areal extent _____ |
| Remarks _____ _____ | | |
| 9. | Slope Instability | <input type="checkbox"/> Slides <input type="checkbox"/> Location shown on site map <input type="checkbox"/> No evidence of slope instability |
| Areal extent _____ | | |
| Remarks _____ _____ | | |
| B. Benches <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | | |
| (Horizontally constructed mounds of earth placed across a steep landfill side slope to interrupt the slope in order to slow down the velocity of surface runoff and intercept and convey the runoff to a lined channel.) | | |
| 1. | Flows Bypass Bench | <input type="checkbox"/> Location shown on site map <input type="checkbox"/> N/A or okay |
| Remarks _____ _____ | | |
| 2. | Bench Breached | <input type="checkbox"/> Location shown on site map <input type="checkbox"/> N/A or okay |
| Remarks _____ _____ | | |
| 3. | Bench Overtopped | <input type="checkbox"/> Location shown on site map <input type="checkbox"/> N/A or okay |
| Remarks _____ _____ | | |

| | | | |
|--|--|---|--|
| C. Letdown Channels | | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |
| (Channel lined with erosion control mats, riprap, grout bags, or gabions that descend down the steep side slope of the cover and will allow the runoff water collected by the benches to move off of the landfill cover without creating erosion gullies.) | | | |
| 1. | Settlement | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> No evidence of settlement |
| | Areal extent _____ | Depth _____ | |
| | Remarks _____ | | |
| | _____ | | |
| 2. | Material Degradation | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> No evidence of degradation |
| | Material type _____ | Areal extent _____ | |
| | Remarks _____ | | |
| | _____ | | |
| 3. | Erosion | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> No evidence of erosion |
| | Areal extent _____ | Depth _____ | |
| | Remarks _____ | | |
| | _____ | | |
| 4. | Undercutting | <input type="checkbox"/> Location shown on site map | <input type="checkbox"/> No evidence of undercutting |
| | Areal extent _____ | Depth _____ | |
| | Remarks _____ | | |
| | _____ | | |
| 5. | Obstructions | Type _____ | <input type="checkbox"/> No obstructions |
| | <input type="checkbox"/> Location shown on site map | Areal extent _____ | |
| | Size _____ | | |
| | Remarks _____ | | |
| | _____ | | |
| 6. | Excessive Vegetative Growth | Type _____ | |
| | <input type="checkbox"/> No evidence of excessive growth | | |
| | <input type="checkbox"/> Vegetation in channels does not obstruct flow | | |
| | <input type="checkbox"/> Location shown on site map | Areal extent _____ | |
| | Remarks _____ | | |
| | _____ | | |
| D. Cover Penetrations | | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |

| | | |
|---|--|---|
| 2. Gas Collection Wells, Manifolds and Piping | | |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | | |
| _____ | | |
| 3. Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings) | | |
| <input type="checkbox"/> Good condition | <input type="checkbox"/> Needs Maintenance | <input type="checkbox"/> N/A |
| Remarks _____ | | |
| _____ | | |
| F. Cover Drainage Layer | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |
| 1. Outlet Pipes Inspected <input type="checkbox"/> Functioning <input type="checkbox"/> N/A | | |
| Remarks _____ | | |
| _____ | | |
| 2. Outlet Rock Inspected <input type="checkbox"/> Functioning <input type="checkbox"/> N/A | | |
| Remarks _____ | | |
| _____ | | |
| G. Detention/Sedimentation Ponds | <input type="checkbox"/> Applicable | <input checked="" type="checkbox"/> N/A |
| 1. Siltation Areal extent _____ Depth _____ | | |
| <input type="checkbox"/> N/A | <input type="checkbox"/> Siltation not evident | |
| Remarks _____ | | |
| _____ | | |
| 2. Erosion Areal extent _____ Depth _____ | | |
| <input type="checkbox"/> Erosion not evident | | |
| Remarks _____ | | |
| _____ | | |
| 3. Outlet Works <input type="checkbox"/> Functioning <input type="checkbox"/> N/A | | |
| Remarks _____ | | |
| _____ | | |
| 4. Dam <input type="checkbox"/> Functioning <input type="checkbox"/> N/A | | |
| Remarks _____ | | |
| _____ | | |

| | | | | |
|---|---|--|---|--|
| H. Retaining Walls | | | <input type="checkbox"/> _Applicable | <input checked="" type="checkbox"/> _N/A |
| 1. | Deformations | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _Deformation not evident | |
| | Horizontal displacement | _____ | Vertical displacement | _____ |
| | Rotational displacement | _____ | | |
| | Remarks | _____ | | |
| | _____ | | | |
| 2. | Degradation | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _Degradation not evident | |
| | Remarks | _____ | | |
| | _____ | | | |
| I. Perimeter Ditches/Off-Site Discharge | | | <input type="checkbox"/> _Applicable | <input checked="" type="checkbox"/> _N/A |
| 1. | Siltation | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _Siltation not evident | |
| | Areal extent | _____ | Depth | _____ |
| | Remarks | _____ | | |
| | _____ | | | |
| 2. | Vegetative Growth | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _N/A | |
| | <input type="checkbox"/> _Vegetation does not impede flow | | | |
| | Areal extent | _____ | Type | _____ |
| | Remarks | _____ | | |
| | _____ | | | |
| 3. | Erosion | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _Erosion not evident | |
| | Areal extent | _____ | Depth | _____ |
| | Remarks | _____ | | |
| | _____ | | | |
| 4. | Discharge Structure | <input type="checkbox"/> _Functioning | <input type="checkbox"/> _N/A | |
| | Remarks | _____ | | |
| | _____ | | | |
| VIII. VERTICAL BARRIER WALLS | | | <input type="checkbox"/> _Applicable | <input checked="" type="checkbox"/> _N/A |
| 1. | Settlement | <input type="checkbox"/> _Location shown on site map | <input type="checkbox"/> _Settlement not evident | |
| | Areal extent | _____ | Depth | _____ |
| | Remarks | _____ | | |
| | _____ | | | |

| | |
|--|--------------------------|
| 2. Performance Monitoring | Type of monitoring _____ |
| _Performance not monitored Frequency _____ _Evidence of breaching Head differential _____ | |
| Remarks _____ | |
| _____ | |
| IX. GROUND WATER/SURFACE WATER REMEDIES <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | |
| A. Ground water Extraction Wells, Pumps, and Pipelines <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | |
| 1. Pumps, Wellhead Plumbing, and Electrical | |
| <input checked="" type="checkbox"/> Good condition <input checked="" type="checkbox"/> All required wells properly operating <input type="checkbox"/> Needs Maintenance <input type="checkbox"/> N/A | |
| Remarks _____ | |
| _____ | |
| 2. Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances | |
| <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance | |
| Remarks <u>VES Unit removed, piping and wells still in place; portion of wells and piping used in 1,4-Dioxane water treatment system, VES terminated in 2005.</u> | |
| 3. Spare Parts and Equipment | |
| <input checked="" type="checkbox"/> Readily available <input type="checkbox"/> Good condition <input type="checkbox"/> Requires upgrade <input type="checkbox"/> Needs to be provided | |
| Remarks _____ | |
| B. Surface Water Collection Structures, Pumps, and Pipelines <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A | |
| 1. Collection Structures, Pumps, and Electrical | |
| <input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | |
| _____ | |
| 2. Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances | |
| <input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance | |
| Remarks _____ | |
| _____ | |
| 3. Spare Parts and Equipment | |
| <input type="checkbox"/> Readily available <input type="checkbox"/> Good condition <input type="checkbox"/> Requires upgrade <input type="checkbox"/> Needs to be provided | |
| Remarks _____ | |
| _____ | |
| C. Treatment System <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A | |

| |
|--|
| <p>1. Treatment Train (Check components that apply)</p> <p><input type="checkbox"/> Metals removal <input type="checkbox"/> Oil/water separation <input type="checkbox"/> Bioremediation</p> <p><input type="checkbox"/> Air stripping <input type="checkbox"/> Carbon adsorbers</p> <p><input type="checkbox"/> Filters _____</p> <p><input type="checkbox"/> Additive (e.g., chelation agent, flocculent) _____</p> <p><input checked="" type="checkbox"/> Others <input type="checkbox"/> 1,4-dioxane removal by Advanced Oxidation method.</p> <p><input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p><input checked="" type="checkbox"/> Sampling ports properly marked and functional</p> <p><input checked="" type="checkbox"/> Sampling/maintenance log displayed and up to date</p> <p><input checked="" type="checkbox"/> Equipment properly identified</p> <p><input type="checkbox"/> Quantity of ground water treated annually _____</p> <p><input type="checkbox"/> Quantity of surface water treated annually _____</p> <p>Remarks _____</p> <p>_____</p> <p>_____</p> |
| <p>2. Electrical Enclosures and Panels (properly rated and functional)</p> <p><input type="checkbox"/> N/A <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> <p>_____</p> <p>_____</p> |
| <p>3. Tanks, Vaults, Storage Vessels</p> <p><input type="checkbox"/> N/A <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Proper secondary containment <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> <p>_____</p> <p>_____</p> |
| <p>4. Discharge Structure and Appurtenances</p> <p><input type="checkbox"/> N/A <input checked="" type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance</p> <p>Remarks _____</p> <p>_____</p> <p>_____</p> |
| <p>5. Treatment Building(s)</p> <p><input type="checkbox"/> N/A <input checked="" type="checkbox"/> Good condition (esp. roof and doorways) <input type="checkbox"/> Needs repair</p> <p><input checked="" type="checkbox"/> Chemicals and equipment properly stored</p> <p>Remarks _____</p> <p>_____</p> <p>_____</p> |

| |
|--|
| 6. Monitoring Wells (pump and treatment remedy) |
| <input checked="" type="checkbox"/> Properly secured/locked <input checked="" type="checkbox"/> Functioning <input checked="" type="checkbox"/> Routinely sampled <input checked="" type="checkbox"/> Good condition |
| <input checked="" type="checkbox"/> All required wells located <input type="checkbox"/> Needs Maintenance <input type="checkbox"/> N/A |
| Remarks _____ _____ |
| D. Monitoring Data |
| 1. Monitoring Data |
| <input checked="" type="checkbox"/> Is routinely submitted on time <input checked="" type="checkbox"/> Is of acceptable quality |
| 2. Monitoring data suggests: |
| <input checked="" type="checkbox"/> Ground water plume is effectively contained <input checked="" type="checkbox"/> Contaminant concentrations are declining |
| E. Monitored Natural Attenuation |
| 1. Monitoring Wells (natural attenuation remedy) |
| <input type="checkbox"/> Properly secured/locked |
| <input type="checkbox"/> Functioning |
| <input type="checkbox"/> Routinely sampled |
| <input type="checkbox"/> Good condition |
| <input type="checkbox"/> All required wells located |
| <input type="checkbox"/> Needs Maintenance |
| <input type="checkbox"/> N/A |
| Remarks _____ _____ |
| X. OTHER REMEDIES |
| If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction. |
| XI. OVERALL OBSERVATIONS |
| A. Implementation of the Remedy |
| Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.). |
| <input type="checkbox"/> Remedy functioned as designed. _____ _____ _____ |

| |
|---|
| <p>B. Adequacy of O&M</p> |
| <p>Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.</p> <p>_____ Current O&M activities are adequate. _____</p> <p>_____</p> <p>_____</p> |
| <p>C. Early Indicators of Potential Remedy Problems</p> |
| <p>Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.</p> <p>_____ There are no early indicators of potential remedy failure. _____</p> <p>_____</p> <p>_____</p> |
| <p>D. Opportunities for Optimization</p> |
| <p>Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy. _____ See Five-Year Review Report _____</p> <p>_____</p> <p>_____</p> |

APPENDIX F – SITE INSPECTION PHOTOS



Photograph No. 1

Site: South Valley Superfund Site

Description: OU 03, Outside Treatment Buildings looking North.



Photograph No. 2 Site: South Valley Superfund
Description: OU 03, Extraction Wells Influent and effluent from Old Treatment Building.



Photograph No. 3 Site: South Valley Superfund
Description: OU 03, New 1,4-dioxane Advanced Oxidation Treatment Building.



Photograph No. 4

Site: South Valley Superfund

Description: OU 03, Equalization Tank and sand filter unit in Treatment Building.



Photograph No. 5

Site: South Valley Superfund

Description: OU 03, UV Oxidation Unit and Hydrogen Peroxide tank in Treatment Building.



Photograph No. 6

Site: South Valley Superfund

Description: OU 03, Area of VES Treatment Unit – removed. Piping still in place.



Photograph No. 7

Site: South Valley Superfund


Description: OU 03, Area east of fenced area; extraction, injection and monitoring wells.



Photograph No. 8

Site: South Valley Superfund


Description: OU 03, Area east of I-25; Monitoring wells in distance.




Photograph No. 9

Site: South Valley Superfund

Description: OU 03, Area west of I-25; Railroad spur area of trash dumping.



Photograph No. 10 Site: South Valley Superfund
 Description: OU 06, Geographical Overview. Squares– Extraction wells; Circles - Injection wells.



Photograph No. 11 Site: South Valley Superfund
 Description: OU 06, Water Treatment Plant Overview.



Photograph No. 12

Site: South Valley Superfund

Description: OU 06, Influent water lines from Extraction wells.



Photograph No. 13

Site: South Valley Superfund

Description: OU 06, Influent water lines from Extraction wells



Photograph No. 14

Site: South Valley Superfund

Description: OU 06, Influent Equalization Tank.



Photograph No. 15

Site: South Valley Superfund

Description: OU 06, Air Stripper towers (2)



Photograph No. 16

Site: South Valley Superfund

Description: OU 06, Carbon Prefilters (3).



Photograph No. 17

Site: South Valley Superfund

Description: OU 06, Liquid Phase Carbon Absorbers (2).



Photograph No. 18

Site: South Valley Superfund

Description: OU 06, Effluent Surge Tank after Carbon Filters.



Photograph No. 19 Site: South Valley Superfund
Description: OU 06, Injection Pumps and Filters. Treated Water is pumped to Injection Wells.



Photograph No. 20 Site: South Valley Superfund
Description: OU 05, Monitoring Well – WB-01 looking northwest at Chevron Facilities.



Photograph No. 21

Site: South Valley Superfund

Description: OU 05, South Plant 83 Area; Concrete Cap, Institutional Control

APPENDIX G – NEWSPAPER AFFIDAVIT OF PUBLICATION



PUBLIC NOTICE

**U.S. EPA Region 6
South Valley Superfund Site
Five Year Review
September 2019**

The United States Environmental Protection Agency (EPA) and the New Mexico Environment Department (NMED) are conducting the sixth five-year review of the South Valley Superfund Site (Site) in Bernalillo County, New Mexico. The review is required by law under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) to assure that human health and the environment are being protected by the remedial actions taken at the Site.


The Site includes two properties: General Electric Aviation where manufacturing occurred and Univar which was used for various industrial and commercial purposes. The Site is approximately 1-square-mile located at the intersection of Broadway Blvd. and Woodward Rd in the South Valley of Albuquerque, NM. The Site is composed of six operable units with a ground water contamination plume containing volatile organic compounds (VOC's) at concentrations greater than EPA drinking wa.

AFFIDAVIT OF PUBLICATION STATE OF NEW MEXICO

County of Bernalillo SS

Elise Rodriguez, the undersigned, on oath states that she is an authorized Representative of The Albuquerque Journal, and that this newspaper is duly qualified to publish legal notices or advertisements within the meaning of Section 3, Chapter 167, Session Laws of 1937, and that payment therefor has been made or assessed as court cost; that the notice, copy of which hereto attached, was published in said paper in the regular daily edition, for 1 time(s) on the following date(s):

09/06/2019



OFFICIAL SEAL
Susan Ramirez
NOTARY PUBLIC - STATE OF NEW MEXICO

My Commission Expires: 2/15/2023
[Signature]

Sworn and subscribed before me, a Notary Public, in and for the County of Bernalillo and State of New Mexico this

6 day of September of 2019

PRICE \$134.02

Statement to come at the end of month.

ACCOUNT NUMBER 1007595

fer standards or maximum contaminant levels. The presence of VOC's in ground water is a result of past releases from manufacturing operations and chemical distribution. The Site treatment system consists of a ground water extraction, treatment, and re-inject systems. Contaminated ground water is located within the shallow and deep aquifer zones.

The review will summarize the past five years of the remedial activities and evaluate if the remedy continues to protect public health and the environment. This five-year review is scheduled for completion by September 2020 and the report will be made available to the public at the Site's information repositories.

Zimmerman Library
Government Information Dept.
University of New Mexico
Albuquerque, NM 87131
505.277.9100

**New Mexico Environment
Department**
Ground Water Quality Bureau
1190 St. Francis Drive, Suite
N2300
Santa Fe, NM 87502-5469

The EPA seeks the public's input for this five-year review.

If you have any questions, issues or concerns regarding this Superfund Site, please contact the EPA project manager, Mike Hebert at 214.665.8315 or 1.800.533.3508 (toll free) or by email at hebert.michael@epa.gov. You may also contact the NMED project manager, Bill Pearson, at 505.827.0039 or by email at william.pearson@state.nm.us.

Additional information about the South Valley Superfund Site is available at the site repositories or at <https://cumulis.epa.gov/supercpad/CurSites/cs/linfo.cfm?id=0600881&mspp=med>

Journal: September 6, 2019



AVISO PÚBLICO

Región 6 de la EPA de EE. UU. Sitio del Superfondo de South Valley Revisión de cinco años Septiembre 2019

La Agencia de Protección Ambiental de los Estados Unidos (EPA, por sus siglas en inglés) y el Departamento de Medio Ambiente de Nuevo México (NMED, por sus siglas en inglés) están llevando a cabo la sexta revisión de cinco años del Sitio del Superfondo de South Valley (Sitio) en el condado de Bernalillo, Nuevo México. La ley exige la revisión bajo la autoridad de la Ley Integral de Respuesta, Compensación y Responsabilidad Ambiental (CERCLA) para garantizar que la salud humana y el medio ambiente estén protegidos por las medidas correctivas tomadas en el Sitio.

El Sitio incluye dos propiedades: General Electric Aviation donde se produjo la fabricación y Univar, que se utilizó para diversos fines industriales y comerciales. El sitio de aproximadamente 1 milla cuadrada está ubicado en la intersección de Broadway Blvd. y Woodward Rd en South Valley, Albuquerque, NM. El sitio está compuesto por seis unidades operables con una pluma de contaminación de agua subterránea que contiene compuestos orgánicos volátiles (COV) en concentraciones mayores a los estándares de agua potable de la EPA o niveles máximos de contaminantes. La presencia de COV en el agua subterránea es el resultado de emisiones anteriores de operaciones de fabricación y distribución de productos químicos. El sistema de tratamiento del sitio consiste en una extracción de agua subterránea, tratamiento y sistemas de reinyección. El agua subterránea contaminada se encuentra dentro de zonas de acuíferos poco profundos y acuíferos profundos.


AFFIDAVIT OF PUBLICATION

STATE OF NEW MEXICO

County of Bernalillo SS

Elise Rodriguez, the undersigned, on oath states that she is an authorized Representative of The Albuquerque Journal, and that this newspaper is duly qualified to publish legal notices or advertisements within the meaning of Section 3, Chapter 167, Session Laws of 1937, and that payment therefore has been made of assessed as court cost; that the notice, copy of which hereto attached, was published in said paper in the regular daily edition, for 1 time(s) on the following date(s):

09/06/2019



[Signature]

[Signature]

Sworn and subscribed before me, a Notary Public, in and for the County of Bernalillo and State of New Mexico this 6 day of September of 2019

PRICE \$154.56

Statement to come at the end of month.

ACCOUNT NUMBER 1007595

La revisión resumirá los últimos cinco años de las actividades correctivas y evaluará si el remedio continúa protegiendo la salud pública y el medio ambiente. Esta revisión de cinco años está programada para finalizar en septiembre de 2020 y el informe se pondrá a disposición del público en los repositorios de información del Sitio.

Biblioteca Zimmerman
Departamento de Información del Gobierno
Universidad de Nuevo México
Albuquerque, NM 87131
505.277.9100

Departamento de Medio Ambiente de Nuevo México
Oficina de Calidad de Aguas Subterráneas
1190 St. Francis Drive, Suite N2300
Santa Fe, NM 87502-5469

La EPA busca comentarios del público para esta revisión de cinco años.

Si tiene alguna pregunta, problema o inquietud con respecto a este Sitio del Superfondo, comuníquese con el gerente del proyecto de la EPA, Mike Hebert, al 214.685.8315 o al 1.800.533.3508 (llamada gratuita) o por correo electrónico en hebert.michael@epa.gov. También puede comunicarse con el gerente del proyecto de NMED, Bill Pearson, al 505.827.0039 o por correo electrónico en william.pearson@state.nm.us.

Hay disponible información adicional sobre el Sitio del Superfondo de South Valley en los repositorios del sitio o en <https://cumulis.epa.gov/supercpad/CurSites/csinfo.cfm?id=0600881&mssp=med>

Journal: September 6, 2019