FOURTH FIVE-YEAR REVIEW REPORT FOR HOMESTAKE MINING COMPANY SUPERFUND SITE CIBOLA COUNTY, NEW MEXICO



SEPTEMBER 2016





2008 2016

Prepared by

U.S. Environmental Protection Agency Region 6 Dallas, Texas

FOURTH FIVE-YEAR REVIEW REPORT HOMESTAKE MINING COMPANY SUPERFUND SITE EPA ID#: NMD007860935 CIBOLA COUNTY, NEW MEXICO

This memorandum documents the U.S. Environmental Protection Agency's (EPA's) performance, determinations and approval of the Homestake Mining Company Superfund site (Site) fourth Five-Year Review under Section 121 (e) of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), 42 U.S. Code Section 9621 (c), as provided in the attached Fourth Five-Year Review Report.

Summary of the Fourth Five-Year Review Report

The Site consists of three project areas called operable units (OUs). OU1 is identified as tailings seepage contamination of groundwater aquifers; OU2 is identified as long-term tailings stabilization, surface reclamation, and site closure; and OU3 is identified as radon concentrations in the neighboring subdivisions. The Site's remedy for OU1 and OU2 consists of long-term remedial actions, including a groundwater collection and injection system, reverse osmosis (RO) and zeolite treatment of contaminated groundwater, long-term stabilization of a large tailings pile (LTP) and a small tailings pile (STP), surface reclamation, monitoring and institutional controls. The Site's potentially responsible party (PRP) Homestake Mining Company (HMC) is implementing groundwater restoration activities as well as mill decommissioning and reclamation at the Site under the Nuclear Regulatory Commission's (NRC's) authority for license termination. EPA has not issued Records of Decision (RODs) for cleanup activities for OU1 and OU2. In 1989, EPA issued a no action ROD for OU3 (radon contamination) in neighboring subdivisions. Due to community concerns, EPA conducted additional investigations between 2010 and 2014 to support a supplemental human health risk assessment (HHRA) for the residential areas outside the facility's licensed boundary.

The groundwater collection and injection system is containing the highest contaminant concentrations within a defined collection area, primarily within the facility's licensed boundary. The system is also reducing contaminant concentrations in groundwater beyond the facility's licensed boundary. Residents in the neighboring subdivision utilize the public water supply extended to them pursuant to a 1983 CERCLA Consent Decree or have been given the option to connect to public water. An Institutional Control in the form of a health advisory is in place to caution current and future owners and private wells users about potential contamination. Contaminated soil at the former mill was excavated and disposed of in the LTP within the facility's licensed boundary. The mill was decontaminated, demolished and parts were buried in place or placed in the LTP. A final radon barrier and erosion protection cover were constructed on the sides of the LTP. Interim soil covers were constructed on the top of the LTP and on the STP. Radon mitigation systems and soil/debris removal efforts in the residential areas mitigated exposures to unacceptable levels of contaminants. Exposures to contamination are currently controlled.

EPA is currently reviewing historic information related to the cleanup being conducted at the Site under the NRC's authority. EPA is conducting the review to determine whether the established background levels, and subsequently the NRC-approved site cleanup levels, are appropriate under the CERCLA remedial investigation/feasibility (RI/FS) equivalency process. As part of the CERCLA equivalency process, EPA is also performing a groundwater assessment that includes sampling and geophysical investigation at the Site. Once the assessment is complete, EPA will follow the CERCLA process to complete a RI/FS, Proposed Plan and a ROD for OU1 and OU2.

Groundwater restoration under the New Mexico Water Quality Control Commission (NMWQCC) regulations (e.g. 20.6.2.4103 NMAC) require the achievement of site standards at any place of withdrawal for present or reasonable foreseeable future use, not just at point of compliance (POC) well locations. Also, according to EPA's "Guidance for Evaluating Completion of Groundwater Restoration Remedial Actions (OSWER 9355.0-129, November 2013)", groundwater remediation levels generally should be attained throughout the contaminant plume.

Human Exposure Status: Under Control

Contaminated Groundwater Status: Under Control

Actions Needed

The following actions must be taken for the remedy to be protective over the long term: complete review of EPA CERCLA equivalency including assessment of groundwater and issue RODs for OU1 and OU2; update the timeframe estimate for groundwater restoration based on current operating conditions and data; include an estimate of the time needed for groundwater restoration of those areas outside the facility's licensed boundary in addition to the areas downgradient of the source areas; investigate the source of the elevated uranium in the HMC supply wells in the San Andres aquifer to determine if pumping from the San Andres wells is drawing contamination into the deeper aquifer.

Determination

I have determined that the remedy for the Homestake Mining Company Superfund site is short-term protective. This Five-Year Review Report specifies the actions that need to be taken for the remedy to be protective over the long term.

Carl E. Edlund, P.E.

Director, Superfund Division

U.S. Environmental Protection Agency Region 6

Date

and realling high of postality grade through the block of grade and

CONCURRENCES

FOURTH FIVE-YEAR REVIEW REPORT HOMESTAKE MINING SUPERFUND SITE EPA ID#: NMD007860935 CIBOLA COUNTY, NEW MEXICO

Sai Appriji		7/28/16
Sairam Appaji Remedial Project Manager		Date
2		
Blu 7 to		8/4/16
Blake Atkins		Date
Chief, LA/NM/OK Section	1	
	1	* 18 ⁰ %
John Myer		8/5/16
John C. Meyer		Date
Chief, Superfund Remedial Branch		
Pamela Travis Attorney, Office of Regional Counsel		07/28/2016 Date
CHOOL B		08/08/11
Mark A. Peycke		08/09/16 Date
Chief, Superfund Branch, Office of Regional Co	ounsel	
× 90		
Pamela Phillips		Date
Deputy Director, Superfund Division		

ISSUES/RECOMMENDATIONS

FOURTH FIVE-YEAR REVIEW REPORT HOMESTAKE MINING COMPANY SUPERFUND SITE EPA ID#: NMD007860935 CIBOLA COUNTY, NEW MEXICO

Issues and Recommendations Identified in the Five-Year Review:

OU(s): OU1 and	Issue Category: Other			
OU2	Issue: Although remediation is underway under NRC authority, there is no EPA Record of Decision (ROD) in place for OU1 and OU2.			
	Recommendation: Complete EPA reassessment of background groundwater and complete the CERCLA equivalency analysis including issuance of a ROD for OU1 and OU2.			
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date
No	Yes	EPA	EPA	9/30/2018

OU(s): OU1	Issue Category: Re	medy Performance		
	Issue: The 2012 Updated Corrective Action Program (CAP) estimated active groundwater restoration to be complete by 2020; however, the estimate was based on groundwater modeling, observed results from present operating conditions and predicted future operating conditions. Several operating conditions have changed since the groundwater modeling was conducted, including discontinuation of land treatment and active flushing of the LTP as well as an increase in the operating capacity of the water treatment systems. In addition, groundwater modeling estimated the time for POC wells to achieve constituent of concern (COC) groundwater protection standards; modeling did not predict COC concentrations for any other areas, including those areas outside the facility's licensed boundary.			
	Recommendation : Update the timeframe estimate for groundwater restoration based on current operating conditions and data. Include an estimate of the time needed for groundwater restoration of those areas outside the facility's licensed boundary in addition to the areas downgradient of the source areas.			
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date
No	Yes	PRP	EPA	9/27/2017

OU(s): OU1	Issue Category: Re	Issue Category: Remedy Performance		
	Issue: The source of the uranium exceedance in the San Andres supply wells at the Site is unclear.			es supply wells at
	Recommendation: Investigate the source of the elevated uranium in the HMC supply wells to determine if pumping from the San Andres wells is drawing site contamination into the deeper aquifer.			
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date
No	Yes	PRP	EPA	9/27/2017

Table of Contents

LIST OF ABBREVIATIONS & ACRONYMS	9
I. INTRODUCTION	10
FIVE-YEAR REVIEW SUMMARY FORM	11
II. RESPONSE ACTION SUMMARY	11
BASIS FOR TAKING ACTION RESPONSE ACTIONS STATUS OF IMPLEMENTATION INSTITUTIONAL CONTROL REVIEW SYSTEMS OPERATIONS/OPERATION & MAINTENANCE (O&M)	12 14 18
III. PROGRESS SINCE THE LAST REVIEW	
IV. FIVE-YEAR REVIEW PROCESS	
COMMUNITY NOTIFICATION, INVOLVEMENT & SITE INTERVIEWS	25
V. TECHNICAL ASSESSMENT	30
QUESTION A: Is the remedy functioning as intended by the decision documents?	DIAL ACTION 33 N THE
VI. ISSUES/RECOMMENDATIONS	35
OTHER FINDINGS	36
VII. PROTECTIVENESS STATEMENT	37
VIII. NEXT REVIEW	38
APPENDIX A – REFERENCE LIST	A-1
APPENDIX B – SITE MAPS	B-1
APPENDIX C – SITE CHRONOLOGY	
APPENDIX D – SITE BACKGROUND	D-1
D.1 PHYSICAL CHARACTERISTICS. D.2 LAND AND RESOURCE USE. D.3 HISTORY OF CONTAMINATION D.4 INITIAL RESPONSE.	D-1 D-2
APPENDIX E – PRESS NOTICE	E-1
APPENDIX F – INTERVIEW FORMS	F-1
APPENDIX G -DETAILED DATA ANALYSIS	G-1
APPENDIX H –SITE INSPECTION CHECKLIST	
APPENDIX I –SITE INSPECTION PHOTOS	I-1
APPENDIX J – TOXICITY REVIEW TABLE	
APPENDIX K – ARARS REVIEW	K-1

Tables

Table 1: Constituent of Concern (COC) by Media	11
Table 2: Site Groundwater Protection Standards	
Table 3: Summary of Planned and/or Implemented Institutional Controls (ICs)	19
Table 4: Protectiveness Determinations/Statements from the 2011 FYR	20
Table 5: Status of Recommendations from the 2011 FYR	21
Table G-1: Exceedances of Site Standards for COCs by Aquifer, 2014	G-1
Table G-2: Quantities of Constituents Collected	G-2
Figures	
Figure B-1: Site Location Map	
Figure B-2: Detailed Site Map	
Figure B-3: Parcels Map	
Figure B-4: Injection and Collection Well Map	
Figure G-1: Groundwater Flow Direction - Alluvial Aquifer	
Figure G-2: Groundwater Flow Direction - Upper Chinle Aquifer	
Figure G-3: Groundwater Flow Direction - Middle Chinle Aquifer	
Figure G-4: Groundwater Flow Direction - Lower Chinle Aquifer	
Figure G-5: Groundwater Flow Direction - San Andres Aquifer	
Figure G-6: Selenium Concentrations in the Alluvial Aquifer - 1999	
Figure G-7: Selenium Concentrations in the Alluvial Aquifer - 2014	
Figure G-8: Uranium Concentrations in the Alluvial Aquifer - 1999	
Figure G-9: Uranium Concentrations in the Alluvial Aquifer - 2014	
Figure G-10: Uranium Concentrations in the Upper Chinle Aquifer - 1999	
Figure G-11: Uranium Concentrations in the Upper Chinle Aquifer - 2014	
Figure G-12: Uranium Concentrations in the Middle Chinle Aquifer - 1999	
Figure G-13: Uranium Concentrations in the Middle Chinle Aquifer - 2014	
Figure G-14: Uranium Concentrations in the Lower Chinle Aquifer - 1999	
Figure G-15: Uranium Concentrations in the Lower Chinle Aquifer - 2014	
Figure G-16: Uranium Concentrations at POC Well S4	
Figure G-17: Uranium Concentrations at POC Well D1	
Figure G-18: Molybdenum Concentrations at POC Well S4	
Figure G-19: Molybdenum Concentrations at POC Well D1	
Figure G-20: Molybdenum Concentrations at POC Wells X	
Figure G-21: Uranium Concentrations at POC Wells CE2 and CE8	
Figure G-22: Molybdenum Concentrations at POC Wells CE2 and CE8	
Figure G-23: Uranium Concentrations in Tailings Solution, 2000	
Figure G-24: Uranium Concentrations in Tailings Solution, 2014	
Figure G-25: Locations of 2014 Soil/Debris Removal Actions	
Figure G-26: Radon Monitoring Locations	
Figure G-27: Radon in Private Well Water	G-29

LIST OF ABBREVIATIONS & ACRONYMS

ARAR Applicable or Relevant and Appropriate Requirement ATSDR Agency for Toxic Substances and Disease Registry

BVDA Bluewater Valley Downstream Alliance

CAP Corrective Action Program

CERCLA Comprehensive Environmental Response, Compensation and Liability Act

CFR Code of Federal Regulations

CIC Community Involvement Coordinator

cm Centimeter

COC Constituent of Concern DOE Department of Energy

dpm/cm² Disintegrations per Minute per Square Centimeter

EPA U.S. Environmental Protection Agency

FYR Five-Year Review gpm Gallons per Minute IC Institutional Control LTP Large Tailings Pile

HHRA Human Health Risk Assessment HMC Homestake Mining Company MCL Maximum Contaminant Level

mg/l Milligram per Liter mg/kg Milligram per Kilogram

mg/kg-day Milligram per Kilogram per Day mg/m³ Milligram per Cubic Meter

mrem/yr Millirem per Year

NCP National Contingency Plan

NMED New Mexico Environment Department

NMWQCC New Mexico Water Quality Control Commission

NPL National Priorities List

NRC Nuclear Regulatory Commission
O&M Operation and Maintenance

OU Operable Unit pCi/g Picocurie per Gram pCi/L Picocurie per Liter

pCi/m²s Picocurie per square meter per second

POC Point of Compliance

PRP Potentially Responsible Party RAO Remedial Action Objective

RO Reverse Osmosis ROD Record of Decision

RPM Remedial Project Manager RSL Regional Screening Level STP Small Tailings Pile

TDS Total Dissolved Solids

TEDE Total Effective Dose Equivalent

TPP Tripolyphosphate

UU/UE Unlimited Use/Unrestricted Exposure

I. INTRODUCTION

The purpose of a Five-Year Review (FYR) is to evaluate the implementation and performance of a remedy to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The U.S. Environmental Protection Agency (EPA) is preparing this FYR pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) Section 121, consistent with the National Contingency Plan (NCP)(40 Code of Federal Regulations (CFR) Section 300.430(f)(4)(ii)), and considering EPA policy.

This is the fourth FYR for the Homestake Mining Company Superfund site (Site). The triggering action for this policy review is the completion of the previous FYR on September 27, 2011. The FYR has been prepared because hazardous substances, pollutants or contaminants remain at the site above levels that allow for unlimited use and unrestricted exposure (UU/UE).

The Site consists of three operable units (OUs). OU1 addresses groundwater restoration; OU2 addresses long-term tailings stabilization, surface reclamation and site closure; and OU3 addresses radon concentrations in the neighboring subdivisions. This FYR report addresses all site OUs.

The FYR was led by Sairam Appaji, EPA Remedial Project Manager (RPM), with contractor support provided by Skeo Solutions. Participants also included Stephen Harper, EPA Community Involvement Coordinator (CIC) and Angelo Ortelli, New Mexico Environment Department (NMED). Homestake Mining Company (HMC), the potentially responsible party (PRP), was notified of the initiation of the FYR. The review began on November 13, 2015.

Appendix A includes a list of documents reviewed as part of this FYR.

Site Background

The Site is located in a rural area of Cibola County, New Mexico, about 5.5 miles north of the village of Milan (Appendix B, Figure B-1). The Site includes HMC's former uranium mill, groundwater contaminated by site-related wastes and radon contamination in neighboring residential subdivisions. The uranium mill operated between 1958 and 1990. It was decommissioned and demolished between 1993 and 1995 as part of the mill site reclamation work required under Nuclear Regulatory Commission (NRC) Source Materials License No. SUA-1471 (License SUA-1471). The only current operations at the Site are related to the operation and maintenance (O&M) of the NRC-required Corrective Action Program (CAP) for groundwater restoration. The facility currently consists of two former tailings impoundments (referred to as the large and small tailings piles), a groundwater collection and injection system, a reverse osmosis (RO) water treatment facility, pilot and full-scale zeolite water treatment systems, two lined collection ponds, three lined evaporation ponds, a groundwater collection system for areas outside the facility's licensed boundary and associated equipment and structures (Appendix B, Figure B-2). Seepage from the tailings piles has resulted in contamination of the underlying groundwater aquifers with radiological and non-radiological contaminants. The aquifers are known locally as the San Mateo alluvial aquifer and the Upper, Middle and Lower Chinle aquifers.

HMC owns land in and around the former mill and leases much of it for livestock grazing. The major land use south and west of the facility's licensed boundary is residential development in the Pleasant Valley Estates, Murray Acres, Broadview Acres, Valle Verde and Felice Acres subdivisions. Since the previous FYR, a shed company began operations east of the facility's licensed boundary. Future land use is expected to be consistent with current use.

Appendix C includes a site chronology. Appendix D contains additional background information about the Site, including geology and history of contamination.

FIVE-YEAR REVIEW SUMMARY FORM

SITE IDENTIFICATION			
Site Name: Homestake	Mining Company		
EPA ID: NMD00786093	35		
Region: 6	State: NM	City/County: Grants/Cibola County	
	SI	TE STATUS	
NPL Status: Final			
Multiple OUs? Yes	Has the Yes	site achieved construction completion?	
	REV	TEW STATUS	
Lead agency: EPA			
Author name: Sairam Appaji, with additional support provided by Skeo Solutions			
Author affiliation: EPA Region 6			
Review period: 11/13/20	015 – 9/27/2016		
Date of site inspection: 1/12/2016			
Type of review: Policy			
Review number: 4			
Triggering action date: 9/27/2011			
Due date (five years afte	er triggering action d	ate): 9/27/2016	

II. RESPONSE ACTION SUMMARY

Basis for Taking Action

The basis for taking action at the Site includes detections of the following constituents in the specified media:

Table 1: Constituent of Concern (COC) by Media

Groundwater ^a	Soil	Uranium Mill Tailings
Uranium	Radium-226	Radon-222 Emissions
Selenium	Thorium-230	
Molybdenum		
Vanadium		
Radium-226 and Radium-228		
Thorium-230		
Sulfate		
Chloride		
Nitrate		

Groundwatera	Soil	Uranium Mill Tailings
Total Dissolved Solids (TDS)		
Notes:		

The initial response at the Site addressed exposure of neighboring residents to groundwater contaminated with radiological and non-radiological constituents. Additional response actions at the Site addressed exposure to Radon-222 (commonly referred to as radon) in nearby homes and radiological constituents in residential soil, discrete items that contained radioactive contamination including pipe, rocks and petrified wood. Other potential historical exposure sources at the Site included uranium byproducts, contaminated surface soil, buildings, equipment and radon emissions to ambient air from the tailings piles.

Response Actions

Documents that detail the remedial decisions for the Site include NRC License SUA-1471, originally issued to HMC in 1957 by the Atomic Energy Commission; a 1993 NRC-approved Decommissioning and Reclamation Plan (DRP); a 1989 NRC-approved groundwater CAP, updated in 2006 and 2012; NMED-approved Discharge Permits DP-200 and DP-725; and the 1989 EPA Record of Decision (ROD) for OU3.

Pursuant to the 1983 Consent Decree, HMC financed the extension of the Village of Milan's municipal water supply to then-existing residences of the subdivisions and made payments to the Village of Milan for the residents' water usage over a period of ten years. The extension of the water supply was completed in 1985.

Pursuant to the 2009 Memorandum of Agreement (MOA) with NMED, HMC agreed to provide hookups to Milan's municipal water supply to additional residents.

NRC is addressing remedial activities at the Site under mill tailings regulations in 10 Code of Federal Regulations (CFR) 40, Appendix A, as amended, which conform with EPA standards in 40 CFR 192.

HMC completed updates to the DRP and groundwater CAP during this FYR period. NRC, EPA, NMED and the community provided comments and NRC is currently performing review of additional information that Homestake has provided in support of the CAP and DRP.

OU1 – Groundwater Restoration

HMC is implementing the groundwater restoration program under NRC License SUA-1471, a groundwater CAP, and NMED Discharge Permit DP-200. In September 2014, NMED issued to HMC a renewal and modification of Discharge Permit DP-200. The modification of DP-200 subsumed the conditions and requirements of DP-725, which previously regulated discharges to the collection and evaporation ponds. Therefore, NMED terminated Discharge Permit DP-725 in October 2014.

License SUA-1471 and the groundwater CAP defined general remedial action objectives (RAOs) for groundwater restoration, as follows:

- Remediate groundwater to levels stipulated in License SUA-1471 and NMED Discharge Permit DP-200.
- Dewater the large tailings pile (LTP) to remove this area as a continuing source of groundwater contamination.

¹ Site Summary on the NRC website: http://www.nrc.gov/info-finder/decommissioning/uranium/is-homestake.pdf.

Groundwater COCs identified in the 2012 Updated CAP, which states "At the time of placement [in the LTP], concentrations of the 10 COCs in tailings pore water in the LTP were elevated."

² NRC is currently reviewing the 2012 Updated CAP. In the interim, HMC is implementing the groundwater restoration program as outlined in the 2012 Updated CAP.

Prevent the consumption of contaminated groundwater by residents in the nearby subdivisions.

Remedy selection at the Site has been based on the procedures specified by NRC, NMED and the 1983 Consent Decree. The groundwater CAP drives the groundwater remedy for the Site with NRC, NMED and EPA providing approval and oversight.

The major components of the groundwater remedy include:

- Dewatering the LTP to remove contaminated groundwater and control the source area of the groundwater contamination.
- Provisions for an alternate and permanent water supply for nearby subdivision residents; financing of the cost of residents' water use for ten years (1985 through the end of 1994).
- Operation of a groundwater collection and injection system to reverse groundwater flow back toward the
 collection wells next to the tailings piles; treatment of the collected groundwater by RO and zeolite for reinjection or evaporation.

Groundwater cleanup standards are established by both NRC (License SUA-1471) and NMED (DP-200). In July 2006, the NRC issued Amendment 39 to License SUA-1471, which revised the list of groundwater protection standards. Table 2 lists the 2006 standards, which are still current. These standards have also been incorporated into NMED Discharge Permit DP-200 and the 2012 Updated CAP.

Table 2: Site Groundwater Protection Standards

Constituent	Alluvial Aquifer	Chinle Mixing Zone	Upper Chinle Non-Mixing Zone	Middle Chinle Non-Mixing Zone	Lower Chinle Non-Mixing Zone
Uranium	0.16 mg/L ^a	0.18 mg/L ^a	0.09 mg/L ^a	0.07 mg/L ^a	0.03 mg/L
Selenium	0.32 mg/L ^a	0.14 mg/L ^a	0.06 mg/L ^a	0.07 mg/L ^a	0.32 mg/L ^a
Molybdenum	0.1 mg/L	0.1 mg/L	0.1 mg/L	0.1 mg/L	0.1 mg/L
Radium-226 and	5.0 pCi/L	NR^b	NR^b	NR^b	NR^b
Radium-228	_				
Thorium-230	0.3 pCi/L	NR ^b	NR ^b	NR ^b	NR ^b
Sulfate	1,500 mg/L ^a	1,750 mg/L ^a	914 mg/L ^a	857 mg/L ^a	2,000 mg/L ^a
Chloride	250 mg/L	250 mg/L	412 mg/L ^a	250 mg/L	634 mg/L ^a
TDS	2,734 mg/L ^a	3,140 mg/L ^a	2,010 mg/L ^a	1,560 mg/L ^a	4,140 mg/L ^a
Nitrate	12 mg/L ^a	15 mg/L ^a	NR ^b	NR ^b	NR ^b
Vanadium	0.02 mg/L	0.01 mg/L	0.01 mg/L	NR ^b	NR ^b

Notes:

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

License SUA-1471 defines the following RAOs for OU2:

- Limit radon emissions from the tailings impoundments.
- Remediate soil contamination that resulted from windblown tailings.

License SUA-1471 and the Decommissioning and Reclamation Plan define the following major components of the OU2 remedy:

- Decontamination of the mill facilities and equipment.
- Demolition of the mill facilities and equipment.

a) Values based on site-specific groundwater background concentrations

NR - Groundwater protection standards not required for constituents in this zone pCi/L - picocurie per liter

mg/L – milligram per liter

- Burial of contaminated debris and asbestos-containing materials in the out slope of the LTP.
- Burial of uncontaminated debris and equipment in pits on the mill site.
- Excavation of surface soils contaminated with windblown tailings and burial in the out slope of the LTP.
- Construction of a final radon barrier on the two tailings piles to minimize radon emissions and reduce erosion.

In April 2013, HMC submitted an update to its Decommissioning and Reclamation Plan for NRC review and approval. Review of the update is ongoing.

Soil cleanup criteria for OU2 were based on the NRC requirements in 10 CFR 40, Appendix A, Criterion 6, which are repeated in the EPA requirements specified in 40 CFR 192. These regulations include a cleanup standard for radium-226 in the top 15 centimeters (cm) of soil of 5 picocuries/gram (pCi/g) above background and 15 pCi/g above background for each 15-cm depth increment below the top 15 cm. The NRC-approved background level for radium-226 at the mill site was established as 5.5 pCi/g. Therefore, the radium-226 cleanup standards are 10.5 pCi/g for the top 15 cm of soil, 20.5 pCi/g for the next 15-cm depth increment, increasing by 15 pCi/g for each successive 15 cm of depth.

OU3 – Radon in Neighboring Subdivisions

EPA signed the OU3 ROD on September 27, 1989. Although elevated indoor radon concentrations were discovered in a few houses in the subdivisions near the Site, EPA determined that there was no definitive correlation between the radon concentrations and the proximity of those homes to the mill facility. The selected remedial action was no further action; therefore, there are no RAOs under CERCLA. However, the decision formalized in the ROD did not constitute a finding by EPA that adequate protection was achieved in the neighboring subdivisions. To address concerns raised by residents, EPA conducted additional evaluation of the neighborhoods between 2010 and 2014.

There is no identified cleanup standard for OU3. The EPA action level for radon in home air (4.0 picocuries per liter (pCi/L)) guided selection of homes for radon mitigation systems, installed in 2012.

The soil action level established for the 2014 removal action at residential properties was 3.5 pCi/g of radium-226, inclusive of background in outdoor soils (1.03 pCi/g to 1.67 pCi/g). The total effective dose equivalent (TEDE) was 15 millirem per year (mrem/yr) above background.

An NRC license condition required HMC to monitor outdoor radon and windblown particulate levels at the facility boundary to ensure that conditions in the subdivisions do not significantly change before final site closure. Under 10 CFR 20 (Standards for Protection Against Radiation) the concentration of radon is limited to 3 pCi/L above background at HMC's licensed boundary.

Status of Implementation

OU1 – Groundwater Restoration

In 1976, groundwater sampling by HMC identified a contaminant plume in the alluvial aquifer that originated from the LTP. The plume was moving off site to the south and west. As a result of these findings, HMC implemented a state-approved groundwater restoration program in 1977. The program included installation of a line of groundwater injection wells along the southern boundary between the LTP and the downgradient residences. The purpose of this line of injection wells was to create a hydraulic barrier that reversed the natural flow direction of the contaminated groundwater away from the residences and back toward the tailings piles; however, initial efforts may have induced downward migration of contaminants. Between 1977 and 1982, HMC also installed groundwater collection wells near the tailings piles and evaporation ponds. These wells would collect tailings seepage and retrieve groundwater that may have migrated from the pile.

In 1983, EPA placed the Site on the Superfund program's National Priorities List (NPL). That same year, HMC and EPA signed an Agreement and Stipulation (Consent Decree). The Consent Decree required HMC to provide an extension of the Village of Milan municipal water system to four residential subdivisions (Broadview Acres, Felice Acres, Murray Acres and Pleasant Valley Estates). The agreement required HMC to pay for residents' water for 10 years. HMC connected residences to the Village of Milan's water supply system in 1985 and paid for water use until the end of 1994. At the time, EPA did not require additional response actions to remediate groundwater because HMC was already implementing a state-approved plan.

In September 1989, HMC submitted a CAP for groundwater remediation to NRC. The program was approved by NRC in License Amendment No. 8, dated July 20, 1990, by adding the requirement for implementation of the CAP as License Condition 35. The groundwater restoration program was modified again in January 15, 1989, to incorporate the RO groundwater treatment system. In 2006 and following an evaluation of background water quality, NRC issued License Amendment No. 39 to establish a revised list of groundwater protection standards for Site groundwater. Since that time, HMC has performed several operating modifications or adjustments under the oversight of NMED and NRC, which are summarized in the site chronology (Appendix C). In 2012, HMC submitted an Updated CAP to NRC for review and approval. This document summarized the history of groundwater restoration at the Site, and combined relevant information from annual reports and license conditions into a single document. It also included potential revisions to the restoration strategy in efforts to meet EPA and NMED requirements. Review of the 2012 Updated CAP is currently ongoing by NRC.

The current program includes a groundwater collection and injection system for the San Mateo alluvial aquifer and the Upper and Middle Chinle aquifers; a tailings toe drain system; a pilot zeolite water treatment system on top of the LTP; an RO water treatment system; two collection ponds; and three evaporation ponds.

Deep-well supplied fresh water or treated water is injected into the San Mateo alluvial aquifer and the Upper and Middle Chinle aquifers to reverse the natural gradients and to flush contaminants from the contaminated portions of the aquifers. Modifications have been made as restoration has progressed, including discontinuing injection in some downgradient alluvial wells and expanding injection closer to the collection wells. Figure B-4 in Appendix B, originally included in the 2014 Annual Monitoring Report/Performance Review for Homestake's Grants Project Pursuant to NRC License SUA-1471 and Discharge Plan DP-200, shows the locations of the present injection and collection system.

Collected groundwater is pumped to the RO treatment plant with smaller volumes directed to the pilot zeolite treatment system or pumped directly into evaporation ponds. Treated water from the RO and zeolite systems is reinjected into the aquifers for plume control. Evaporation of water at the ponds is enhanced through spray misters; the spray misters operate on a seasonal basis and are shut down during the winter months.

Since the previous FYR, HMC upgraded the RO groundwater treatment system, which utilizes a lime-caustic pretreatment and clarification unit. Although the original system had a 600 gallon per minute (gpm) design capacity, it had been operating at less than 50 percent of its capacity due to limitations of its sand filtration unit. The expanded and upgraded RO system has the capacity to treat 1,200 gpm, doubling its capacity to treat groundwater. Upgrades to the system also included changing the filtration mechanism from sand filtration to microfiltration (using low pressure membranes) and installation of a new clarifier tank. The upgraded RO system began full-scale operation in February 2016.

HMC completed construction of a full-scale zeolite water treatment system on top of the LTP in 2016. The 1,200 gpm full-scale system was designed to supplement the existing 300 gpm pilot treatment system. Once complete, the two systems will be combined for a total design capacity of 1,500 gpm. The treated water from the zeolite treatment system will be used for plume control (as part of the injection/collection system) in the areas west and south of the facility's licensed boundary. To the extent possible and as site conditions allow, the treated water from zeolite will be used in lieu of fresh water for reinjection. The zeolite-based treatment system was in the testing phase in July 2016.

Downgradient of the facility's licensed boundary, groundwater remediation also included extraction of contaminated groundwater with land application treatment using four irrigation systems (a practice initially implemented in 2000). However, NMED prohibited use of the irrigation systems with a renewal/modification of DP-200 and the practice ended in 2012. Extracted groundwater is now treated using the upgraded RO and pilot zeolite treatment systems. Initially, the off-site groundwater restoration system consisted of 13 collection wells. By 2005, the off-site groundwater restoration system had expanded to 35 wells. Since the previous FYR, 550 wells, including injection and collection wells throughout the Site, were added to the program to expedite the cleanup process. This includes installation of 160 new alluvial wells in 2014.

HMC is also evaluating the efficacy of tripolyphosphate (TPP) injections as an additional mechanism for remediation. A TPP pilot test is underway that involves injection of TPP, or another phosphate source, into the alluvial aquifer inside the area of hydraulic control. The primary objective of the pilot testing is to evaluate the uranium immobilization efficacy of TPP in the alluvial aquifer and collect design parameters necessary for full-scale implementation. The most recent TPP injection occurred in August 2015.

The 2012 Updated CAP estimated active groundwater restoration to be complete by 2020; however, the estimate was based on groundwater modeling, results from present operating conditions and predicted future operation conditions. Several operating conditions have changed since the modeling was conducted, including discontinuation of land treatment and active flushing of the LTP, as well as an increase in the operating capacity of the water treatment systems. Based on these recent changes, this estimate should be revised based on current remedy components. The estimate should also clarify when groundwater outside the facility's licensed boundary will be restored.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

HMC decommissioned and dismantled the mill in the early 1990s, with some waste materials deposited in the LTP or buried next to the south side of the LTP. Following demolition of the mill facility, HMC removed soil contaminated by windblown tailings, ore storage and processing; HMC disposed of these materials in the LTP. HMC recontoured the LTP to improve long-term stability and to prepare for final closure. In 1994, HMC constructed a final radon barrier and erosion protection cover on the sides of the LTP as well as an interim radon cover on its top. In 1995, HMC constructed an interim radon cover on the portion of the small tailings pile (STP) not covered by evaporation pond 1. The placement of final radon barriers will not occur until groundwater restoration activities are complete.

In 2000, HMC began a tailings flushing program at the LTP. This program involved injection of water into the LTP and extraction via a large number of wells on the LTP. The program was a way to flush out contaminants in the tailings. Water collected by the wells was directed to the collection ponds or treated through the RO treatment system.

HMC conducted a pilot study in a portion of the LTP between December 2010 and May 2012 to evaluate the possibility of a rebound in contamination concentrations once the flushing program ends. Data from the study found that significant rebound was not expected. HMC ended the LTP flushing program in July 2015 and is currently collecting data to evaluate rebound.

The previous FYR also recommended re-evaluating stability of the LTP because a prior earthquake stability analysis had assumed unsaturated tailings. In 2010, the stability analyses were updated using the regional seismic parametric values, and the factors of safety under earthquake loading were well above minimums. Every year a third party independent, professional engineer (licensed in New Mexico) assesses the LTP conditions to ascertain that the 2010 analysis is still applicable to present conditions.

OU3 - Radon in Neighboring Subdivisions

EPA issued a no action ROD for OU3. However, residents in the neighboring subdivisions raised concerns that they had been exposed to unacceptable levels of radioactive contaminants through inhalation and ingestion. The residents alleged that the contaminants were transported into their homes through the spray mist from the evaporation pond associated with the groundwater remediation activities and through their use of contaminated groundwater for domestic uses (such as cooking, showering, washing, etc.). The residents were concerned about contaminants transported from the Site through the air or surface runoff to their backyards, and about consumption of produce in areas irrigated with contaminated groundwater and consumption of livestock meat from cattle exposed to contaminated grazing areas. To address these concerns, EPA conducted additional evaluation of the neighborhoods between 2010 and 2014 to gather data to support the development of a Human Health Risk Assessment (HHRA) for OU3. Data collection included:

- Screening, scanning and survey evaluation.
- Long-term indoor and outdoor radon exposure evaluation.
- Soil, produce and private well evaluation.

EPA evaluated the resulting data, conducted and finalized an HHRA in December 2014, and determined mitigation or removals, or both, were needed at several residential properties. These evaluations and removal efforts are summarized below.

Screening, Scanning and Survey Evaluation

Major components of the evaluation included radiation ground scans around 86 houses in the subdivisions south of the Site, collection of soil samples for analysis of radionuclides from areas with high scan readings, measurement of indoor exposure radiation levels (short term), and collection of wipe samples within select residences. EPA contractor Weston Solutions, Inc. conducted the work between September 2010 and May 2012. Weston Solutions, Inc. presented results of the investigation in the Removal Assessment Report for Homestake Mining Company, Grants, Cibola County, New Mexico, dated May 2012 (May 2012 Removal Assessment Report). Results are summarized in Section IV, Data Review, of this FYR.

Long-Term Indoor and Outdoor Radon Exposure Evaluation

EPA conducted long-term air radon monitoring at homes in the five subdivisions south and west of the Site and from homes in a background area. Results were presented in the Human Health Risk Assessment, Homestake Mining Co. Superfund Site, Cibola County, New Mexico, dated December 2014 (2014 HHRA), and are summarized in Section IV, Data Review, of this FYR.

Soil, Produce and Private Well Evaluation

EPA collected surface soil samples from the yards of each house with an access agreement. EPA also collected surface soil from the Site's three irrigation fields, two central pivot fields, evaporation pond banks and a background area. Surface soil samples were collected from four runs with the highest gamma radiation readings in the area between the evaporation ponds and the fence line. The samples were analyzed for metals and radionuclides.

EPA collected 10 samples of vegetables from various gardens in the subdivisions, 14 irrigation well water samples from private properties, and samples from the evaporation pond at the Site. Results are summarized in Section IV, Data Review, of this FYR.

Radon Mitigation and Removal Actions

Based on the long-term indoor and outdoor radon exposure evaluation, EPA determined that radon mitigation was warranted at 12 residential properties where radon in indoor air exceeded 4 pCi/L based on average annual

sampling. EPA installed mitigation systems in 11 homes³; one homeowner declined the mitigation effort. The source of high radon levels in these homes has not been identified. The HHRA found no significant difference between annual indoor radon levels in the five subdivisions and background levels. Installation of the mitigation systems was completed in 2012.

EPA determined that soil removal actions were warranted to address radioactive-contaminated soil at 16 properties. EPA identified two additional properties for removal of discrete items. The contaminated soil and other material found in the subdivisions were unrelated to Homestake Site. Removal actions at the properties were conducted between February and July 2014.

Institutional Control Review

Table 3 summarizes all institutional controls (ICs) for the Site, with additional OU-specific information below.

OU1 – Groundwater Restoration

Beginning in 2009, NMED requested the New Mexico Office of State Engineer (NM-OSE) to issue a health advisory to every person who applies for a well permit within the San Mateo Creek basin. The advisory cautions current and future owners and users of private wells within the San Mateo Creek basin that their well water could contain contaminant concentrations in excess of federal drinking water standards. The advisory was also published in two newspapers of general circulation in Cibola and McKinley counties. The NM-OSE Health Advisory is considered as an Information Device type of Institutional Control.

HMC also conducts an annual land use survey to meet annual license condition reporting requirements under License SUA-1471. This review includes an assessment of the five residential subdivisions south and west of the Site. The assessment determines whether occupied dwellings are using water service from the Village of Milan system for potable water consumption rather than private wells, particularly private domestic wells that are completed into the underlying shallow alluvial aquifer. If residences are not on the Village of Milan water supply, HMC will give the residences the opportunity to connect to the public water supply with HMC covering the cost of hookup. As of 2014, all residences in the subdivisions, except for one residence in Valle Verde, are connected to public water. The Valle Verde resident has declined the offer to connect to the Village of Milan water supply.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

HMC currently restricts access within its license boundary with a security fence and warning signs. The facility maintains security support services, security alarm systems and site entry controls. Once site reclamation is complete, HMC will maintain the site controls until transfer of title to the Department of Energy (DOE). Upon title transfer from HMC to the DOE, the DOE will assume custody of and responsibility for the Site in perpetuity for the licensed area. Restrictions will need to be implemented to prevent disturbance of soil, waste and any remedy components; to prevent unacceptable future use; and to prevent use of groundwater for potable purposes.

OU3 - Radon in Neighboring Subdivisions

Decision documents did not require institutional controls for OU3. However, annual radon flux measurements and radon monitoring at the fenceline of the HMC boundary is required under the facility's NRC license.

³ Radon mitigation systems consisted of single suction point active soil depressurization system with a radon-specific fan (RadonAway).

Table 3: Summary of Planned or Implemented Institutional Controls (ICs)

Media, engineered controls and areas that do not support UU/UE based on current conditions	ICs Needed	ICs Called for in the Decision Documents ^a	Impacted Parcel(s)	IC Objective	Title of IC Instrument Implemented and Date (or planned)
Groundwater	No	No	Parcels overlying the groundwater contaminant plumes	To caution current and future owners and users of private wells within the San Mateo Creek basin that their well water could contain contaminant concentrations in excess of federal drinking water standards	New Mexico Office of State Engineer Health Advisory (2009)
Groundwater	No	Yes ^b	Parcels overlying the groundwater contaminant plumes in the five neighboring residential neighborhoods	To determine whether current residents are using the public water supply for potable water consumption	Amendment 34 to SUA-1471 (approved 2002) requires submittal of a land-use survey on an annual basis
Groundwater, soil and waste within the NRC license boundary	Yes	No	Parcels within the NRC license boundary	To prevent disturbance of soil, waste and any remedy components; to prevent unacceptable future use; to prevent use of groundwater for potable purposes	Restrictive Covenants to be filed after EPA issues a ROD for OU1 and OU2 and full reclamation and closure of the Site.

Notes:

Systems Operations/Operation & Maintenance (O&M)

OU1 – Groundwater Restoration

License SUA-1471 and NMED Discharge Permit DP-200 stipulate O&M requirements for OU1. Several internal documents kept at the facility also outline O&M activities. The O&M activities include:

- Operation, maintenance and monitoring of the groundwater injection and collection wells, as well as associated piping.
- O&M of the RO treatment plant, zeolite treatment systems, collection ponds and evaporation ponds.
- Groundwater sampling and monitoring.
- Air monitoring.
- Maintenance of air monitoring stations and groundwater monitoring wells.

HMC personnel are at the Site daily during the week performing O&M activities. Daily and weekly inspections verify the condition of RO treatment plant and zeolite treatment system components. Monitoring of collected water is performed as a part of O&M. More than 5.8 billion gallons of groundwater have been extracted from the on-site collection system between 1978 and 2014. More than 1.1 million pounds of uranium have been removed from groundwater with subsequent treatment by the RO system. Total volume of groundwater collected and

a) EPA decision documents have not yet been issued for OU1 and OU2.

b) Required by reporting requirements under License SUA-1471.

quantities of constituents removed by the on-site contaminated groundwater collection and tailings dewatering systems from 1978 to 2014 are shown in Appendix G.

O&M also includes periodic monitoring of several hundred groundwater monitoring wells and continual O&M of dozens of collection and injection wells.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

NRC licensing requirements require HMC to conduct annual inspections of the tailings piles and pond dikes, and annual radon flux surveys for the tailings piles. The annual inspections include visual observations of the tops and outslopes of both tailing piles and of the dikes, slopes and liners of the evaporation ponds. The inspections also include review of piezometer readings, tailings collection well and tailings drainage sump collection rates, leak detection monitoring records for evaporation ponds 2 and 3, settlement monitoring survey data, pond level measurements and other data. Annual reports submitted to NRC, EPA and NMED document results of the inspections and the radon flux surveys.

O&M for OU2 also consisted of those activities associated with the tailings flushing program, which ceased operation in 2015.

OU3 - Radon in Neighboring Subdivisions

There is no current long-term O&M for OU3. Generally the radon mitigation systems are known to operate without any maintenance problems for many years before the motor in the unit wears out. EPA has installed these systems at other sites and have not experienced maintenance issues. The homeowners have been instructed to contact the installer for servicing any repairs beyond the warranty period.

III. PROGRESS SINCE THE LAST REVIEW

This section includes the protectiveness determinations and statements from the last FYR as well as the recommendations from the last FYR and the current status of those recommendations.

Table 4: Protectiveness Determinations/Statements from the 2011 FYR

OU#	Protectiveness Determination	Protectiveness Statement
1	Short-term Protective	Based on current information, the remedy at OU1 is protective of human health and
		the environment through the use of a groundwater collection and injection system at
		the Site and the use of a health advisory. The health advisory informs current and
		future residents of potential risks of drinking water standard exceedances in the use of
		water from private wells and minimizes the possibility of new wells being installed
		within the area of contamination, thus limiting the primary exposure pathway of
		ingestion. There is no evidence of current exposure from any media at this time.
2	Short-term Protective	Based on current information, the remedy at OU2 is protective of human health and
		the environment due to the stabilization of the tailings piles, surface reclamation and
		decommissioning of the mill. Soil contaminated by windblown tailings was excavated
		and disposed of in the LTP and the mill facility was decontaminated, demolished and
		parts were either buried in place or placed in the LTP. A radon barrier and erosion
		protection cover were constructed on the sides of the LTP, and an interim soil cover
		was constructed on its top and on the STP.
3	Protectiveness	Although the OU3 ROD called for no further action, EPA recognized the need to
	Deferred	monitor outdoor radon and windblown particulate levels south of the disposal area to
		ensure that conditions in the neighboring subdivisions remain protective until final
		site closure. Therefore, EPA continues to review outdoor radon monitoring and
		particulates data collected at the facility boundary. Also, in September 2010, EPA
		began collecting sample data to support the development of an HHRA, to include

OU#	Protectiveness Determination	Protectiveness Statement		
Sitewide	Protectiveness Deferred	indoor and outdoor radon samples. The sample collection will continue on a quarterly basis until November 2011. A HHRA is expected in spring 2012 which will provide information needed to support a determination of the protectiveness of the OU3 remedy. Therefore, the determination of protectiveness for OU3 is deferred until completion of the HHRA. The remedy, exclusive of OU3 at the Site, is protective of human health and the environment through the combined effects of HMC's ongoing groundwater remedial action with associated groundwater monitoring, and the dissemination of a health advisory through the State's well permitting process, which advises prospective well owners of the potential existence of groundwater exceeding drinking water standards.		

Table 5: Status of Recommendations from the 2011 FYR

OU#	Issue	Recommendation	Current Status	Current Implementation Status Description	Completion Date (if applicable)
1	Extraction of large quantities of water from the San Andres Formation and subsequent injection, primarily into the alluvial aquifer, has created localized areas with an artificial head difference of approximately 100 feet that, combined with the presence of faults and associated fracturing in the bedrock, increases the risk of downward migration of contaminants.	Minimize use of clean water and develop an alternate source, such as treatment of extracted groundwater, for use in injection into the alluvial and Chinle Formation aquifers remedy.	Ongoing	HMC continues to extract groundwater from the San Andres aquifer for injection into the alluvial and Chinle aquifers. HMC recently completed construction of the full-scale zeolite treatment system and completed expansion and upgrades to the RO treatment facility. Water treated with these alternative technologies is expected to significantly reduce reliance on San Andres water for injection.	NA
1	Rebound conditions are unknown in the tailings flushing program. The flushing program is also likely decreasing the stability of the LTP due to the increased saturation of the pore spaces. The earthquake stability analysis assumed unsaturated tailings and did not account for the increased percentage of fluid-filled pore space resulting from the relatively recent tailings flushing program.	Conduct a pilot study in a portion of the LTP to quantify possible contaminant concentration rebound effects and demonstrate that rebound will not occur once the flushing program has ended. The earthquake stability analysis should be reevaluated to account for the increased fluid-filled pore space resulting from the relatively recent tailings flushing program.	Completed	HMC conducted a pilot study in a portion of the LTP between December 2010 and May 2012 to evaluate the possibility of a rebound in contamination concentrations once the LTP flushing program ends. The study found that significant rebound of the contaminants was not expected. HMC discontinued the LTP tailings flushing program in 2015 and is collecting additional data to monitor actual rebound conditions at the Site. HMC re-evaluated the stability of the LTP in 2010 and found that the factors of safety under earthquake loading were well above minimums. Every year a	5/1/2012

OU#	Issue	Recommendation	Current Status	Current Implementation Status Description	Completion Date (if applicable)
		The protectiveness is dependent on a revised earthquake risk analysis.		third party independent, professional engineer assesses the LTP conditions to ascertain that the 2010 analysis is still applicable to present conditions.	
				The 2014 annual inspection results for the LTP, included in the 2014 Annual Report, noted that the "slope stability analysis of the LTP updated in 2010 is still valid for 2014; the stability parameters have not changed negatively during 2014 and are expected to gradually improve even more as the flushing program winds down and the LTP phreatic surface declines. The static and pseudo-static factors of safety remain well above the design minimum	
2	A persistent plume of elevated uranium contamination just south of the former mill site may be a remnant of the LTP contaminant plume and may continue to impact groundwater. In addition, an historic irrigation ditch established in the 1920s that ran through the future Homestake mill property, and presumably was backfilled to original grade during construction of the mill, may be serving as a preferential pathway for leached contaminants to groundwater.	Determine whether a remnant of the LTP contaminant plume is continuing to impact groundwater. Investigate the backfilled irrigation ditch that ran through the HMC property to determine whether it serves as a preferential pathway for the migration of leached contaminants to groundwater.	Considered But Not Implemented	values of 1.5 and 1.0, respectively." HMC provided a response, also included in the 2013 update to the Decommissioning and Reclamation Plan, that the historical record of the mill contains no information, coupled with subsequent mill site area reclamation and post-reclamation gamma surveys of the reclaimed area that indicated no radiological anomalies, to support the speculation that the old irrigation ditch plays any part in movement of contaminated groundwater on the HMC site. HMC further noted that the movement of uranium and other COCs in groundwater has been investigated for 35 years and remediation is making progress. A study of the ditch would not change the	4/1/2013
2	The east side slope of the STP/evaporation pond 1 had moderate to large furrows and the west side of the westernmost collection pond had	Provide some type of native vegetative cover or erosion protection cover to the east side slope of the STP/evaporation	Completed	groundwater restoration plan. HMC began repair of the outslope rills and placement of clean fill on the east outslopes to provide a wider crest road for increased safety of maintenance vehicles.	2/1/2015

OU#	Issue	Recommendation	Current Status	Current Implementation Status Description	Completion Date (if applicable)
	moderate furrows, both of which appeared to be the result of rainfall/erosion.	pond 1 and the west side of the westernmost collection pond to prevent erosion.		Currently, the earthen slopes on these structures are addressed on an as-needed basis to eliminate rills and rodent burrows; additional clean fill material is placed as needed to repair potential erosion areas. A seed mixture for native vegetative cover is currently being evaluated by HMC in conjunction with the local Natural Resources Conservation Department.	
3	Annual air monitoring reports in 2006-2010 indicate releases of radon outside the area covered by the NRC license, in concentrations exceeding EPA standards.	EPA is currently in the process of completing a radon survey and a determination of the radon source (if possible), and specific recommendations will be made upon completion of the survey. This information will be incorporated into an HHRA in the spring of 2012.	Completed	EPA completed a radon survey in 2012, which included screening and sampling of 86 residential properties south and west of the Site. Results were presented in the May 2012 Removal Assessment Report. Based on sampling results, radon mitigation systems were installed at 11 residential properties where radon in indoor air exceeded 4 pCi/L based on average annual sampling; however, the source of radon in these homes has not been identified. EPA also conducted removal actions at 18 properties with radiological contaminated soil/debris. EPA finalized the HHRA for OU3 in December 2014.	12/1/2014
3	The 2006-2010 annual air monitoring report indicates that releases of radon exceeded the annual average concentrations allowed under 40 CFR 192.02(b)(2).	EPA is currently in the process of completing a radon survey and a determination of the radon source (if possible), and specific recommendations will be made upon completion of the survey. This information will be incorporated into an HHRA in the spring of 2012.	Completed	Please see the OU3 status above.	12/1/2014
3	Radon air monitors along the Homestake fenceline have continuously recorded	EPA is currently in the process of completing a radon survey and a	Completed	Please see the OU3 status above.	12/1/2014

OU#	Issue	Recommendation	Current Status	Current Implementation Status Description	Completion Date (if applicable)
	outdoor ambient air	determination of the			
	radon concentrations	radon source (if			
	associated with cancer	possible), and			
	risk levels that are	specific			
	greater than EPA's	recommendations			
	acceptable cancer risk	will be made upon			
	range of 1 x 10 ⁻⁴	completion of the			
	to 1 x 10 ⁻⁶ , as published	survey. This			
	in the National	information will be			
	Contingency Plan.	incorporated into an			
		HHRA human			
		health risk			
		assessment in the			
		spring of 2012.			

IV. FIVE-YEAR REVIEW PROCESS

Community Notification, Involvement & Site Interviews

A public notice was made available by a newspaper posting in the *Cibola Beacon* on 12/15/2015, stating that there was a FYR and inviting the public to submit any comments to EPA. Appendix E includes a copy of the public notice. The results of the review and the report will be made available at the site information repository located at New Mexico State University, Grants Campus Library, at 1500 Third Street in Grants, New Mexico.

During the FYR process, interviews were conducted with representatives of the NMED and the PRP, as well as local residents, to document any perceived problems or successes with the remedy that has been implemented to date. The results of these interviews are summarized below. Appendix F includes interview summary forms.

NMED indicated that it has had extensive interaction with HMC throughout the permit renewal process for DP-200 and that HMC has been cooperative and responsive to NMED requests for information. NMED noted that HMC has met the requirements of DP-200 since renewal in 2014, and is in compliance with the permit conditions. NMED also noted that HMC has made a concerted effort to accelerate groundwater remediation at the Site, with construction of the upgraded RO water treatment plant and zeolite water treatment system. NMED is also aware of complaints and inquiries from local residents. These include, but are not limited to, concerns over the overall remedial strategy, over-pumping and use of the San Andres aquifer, potential cross-contamination of the San Andres aquifer (from overlying contaminated aquifers), use of zeolite as a viable treatment technology, flushing of the LTP, radon background and monitoring, and the approved groundwater background concentrations (remediation standards). NMED noted that a health advisory is in place, but the State of New Mexico does not have a mechanism in place to enforce the institutional control.

The PRP's O&M representative noted that HMC continues to make significant gains with regard to water remediation activities and that significant progress was made over the past five years. He stated that the current remedy is soundly based in science and is effective. The monitoring data over the past 15 years support the remediation efforts. COCs, including selenium, uranium and molybdenum, are showing significant reductions. New systems implemented in the past five years include the new zeolite water treatment system, an improved RO water treatment plant and expanded well field. He also noted that HMC is conducting a pilot study using TPP. These changes have a significantly positive effect on the protectiveness of the remedy, as they have enabled HMC to treat more contaminated water at a faster rate.

Local residents expressed concern over the progress of remediation at the Site, which has stretched nearly 40 years. HMC paid for public water for ten years, but the groundwater [for use with private wells] still is not clean. Residents cannot use their wells and now they have to pay for water. Some residents expressed interest in EPA taking more of a lead role at the Site. They noted that communication with NRC had been a problem in the past, but that EPA has communicated better with the residents in recent years. Some residents noted that the Site has had both financial and physical effects on the community. Property values are down. One resident noted that there is a high incidence of cancers in people living closest to the Site. Another resident had concerns over the recent residential yard soil cleanups, including the background values used and the completeness of the cleanup. There was also concern about the new treatment technologies at the Site, and whether any of the new work will make the plumes bigger.

Data Review

OU1 – Groundwater Restoration

The data reviewed for OU1 include analytical and water level data from monitoring, injection and collection wells, as originally presented in HMC's 2011 through 2014 Annual Monitoring Reports/Performance Reviews (annual reports). The current monitoring program consists of several hundred groundwater monitoring wells, most of which are located in the alluvial aquifer. Wells in the Upper, Middle and Lower Chinle Formation and the San Andres aquifer are also monitored. Sampling is conducted at least annually; however, some wells are sampled more frequently.

The 2014 annual report stated that over 120 million gallons of water was extracted from the Alluvial aquifer on-site and 56 million gallons were extracted off-site. Approximately 1.5 million gallons was extracted from the Upper Chinle Formation on-site in 2014 and 167,000 gallons were extracted off-site. An additional 38 million gallons was extracted from the Middle Chinle off-site in 2014. Contaminants removed from the Alluvial aquifer include 2.6 million pounds of sulfate, 11,000 pounds of uranium, 16,000 pounds of molybdenum and 643 pounds of selenium. Contaminants removed from the Upper Chinle include 71,000 pounds of sulfate, 342 pounds of uranium, 434 pounds of molybdenum and 9 pounds of selenium.

Groundwater monitoring is used to characterize the contaminant plumes, evaluate performance of the restoration strategies and demonstrate progress made in restoring groundwater to meet site standards. Uranium and selenium are the most widespread contaminants at the Site; therefore, the groundwater monitoring data review focuses on uranium and selenium concentrations and distributions within each aquifer unit.

Groundwater Flow

Water level elevation maps showing groundwater flow direction in the alluvial, Upper, Middle and Lower Chinle and the San Andres aquifers are included in Appendix G (Figures G-1 through G-5). Review of the maps shows that groundwater flow directions in the alluvial and Chinle aquifers have been altered by operation of the collection/injection system. The groundwater gradient in the alluvial and Upper Chinle aquifers south of the LTP has been reversed, with groundwater flowing back toward the collection wells, which is consistent with the intent of the collection/injection system.

Plume Characterization

Plume maps showing the distribution of selenium in the alluvial aquifer in 1999 and 2014 are included in Appendix G (Figures G-6 and G-7). Plume maps were not available between 1999 and 2014. The 2014 selenium plume map shows the main plume under the LTP has decreased in size and concentration compared to the 1999 plume. Selenium concentrations in 2014 do not exceed 5 mg/L, whereas the 1999 map shows an area with concentrations above 5 mg/L south of the LTP. An area southwest of Felice Areas, with elevated selenium concentrations in 1999, was also restored prior to 2014. The 2014 map shows that selenium has been restored to below the cleanup standard (0.32 mg/L) in all of the residential areas south and southwest of the Site. The 2014 map does show an area of elevated selenium concentrations (between 0.32-1 mg/L) east of Highway 605 that was

not detected in 1999. Injection/collection wells are located in this area to aid in restoration (Appendix B, Figure B-4).

Comparison of the 1999 and 2014 uranium plumes for the alluvial aquifer (Appendix G, Figures G-8 and G-9) indicates that the plume has decreased in size and concentration, although not to the same degree as selenium. The plume northwest of Valle Verde subdivision that was greater than the site standard (0.16 mg/L) has been pulled back about 1 mile to the east. The area greater than 10 mg/L was also reduced in 2014. The 2014 uranium plume patterns also show that the concentrations in southern Felice Acres have been reduced to below 1.0 mg/L, compared to levels up to 10 mg/L in 1999. The area with concentrations greater than 0.5 mg/L in southern Felice Acres is much smaller than in 1999; however, concentrations persist above the site standard (0.16 mg/L) in this residential area. HMC installed additional wells southwest of Felice Acres in 2014⁴; however, additional efforts may be needed to aid restoration of this area.

Plume maps showing the distribution of uranium in the Upper, Lower and Middle Chinle aquifers in 1999 and 2014 are included in Appendix G, Figures G-10 through G-15. The plumes in the Lower and Middle Chinle aquifers have generally decreased in size and magnitude, but uranium concentrations persist above the cleanup standard in the Broadview Acres, Felice Areas and west of the LTP in the Middle Chinle aquifer and southwest of Felice Areas in the Lower Chinle. The uranium plume in the Upper Chinle shows higher concentrations and a larger plume footprint under the LTP in 2014 than in 1999, possibly as a result of the tailings flushing program. The plume is well defined and is expected to be remediated with the current network of collection/injection wells.

Compliance with Site Standards

There are five Point of Compliance (POC) wells: S4, D1, and X in the alluvial aquifer and CE2 and CE8 in the Upper Chinle aquifer. These wells are sampled during annual and semi-annual sampling events. The site standards must be met at these locations to comply with the NRC license and to demonstrate that NRC groundwater restoration objectives have been met. Note that groundwater restoration under the New Mexico Water Quality Control Commission (NMWQCC) regulations (e.g. 20.6.2.4103 NMAC) requires the achievement of site standards at any place of withdrawal for present or reasonable foreseeable future use, not just at POC well locations. EPA guidance also indicates that groundwater remediation levels generally should be attained throughout the contaminant plume. However, this evaluation is limited to the five POC wells used to comply with the NRC license. There are no POC wells for the other aquifers. Key constituents of interest in the alluvial and Upper Chinle aquifers are sulfate, total dissolved solids (TDS), chloride, uranium, selenium and molybdenum.

The alluvial aquifer POC wells are west and south of the LTP and the STP. POC wells S4 and D1 exceeded the site standard for uranium and molybdenum during each of the last five years. POC well X did not exceed any site standards during the FYR period with the following exceptions: in 2011, POC well X exceeded the radium-226 standard in one sample, and in 2013, well X exceeded the molybdenum standard in two out of four sampling events. Concentration trend plots for each COC were provided in the 2014 annual report. Appendix G includes the uranium plots for POC wells S4 and D1 (Figures G-16 and G-17) and the molybdenum plots for POC wells S4, D1 and X (Figures G-18, G-19 and G-20, respectively). Uranium and molybdenum concentrations at well S4 have been decreasing or stable since 2004 and during this FYR period. Uranium and molybdenum concentrations at well D1 were decreasing or stable between 2000 and 2007, but spiked in 2008, and have been sporadic during this FYR period. Restoration in this area is ongoing.

The Upper Chinle aquifer POC wells are south of the LTP and STP. During the last five years, POC well CE2 exceeded the site standard for the mixing zone for uranium, molybdenum and selenium. POC well CE8 did not exceed any of the site standards. Appendix G includes uranium and molybdenum plots for CE2 and CE8 (Figure G-21 and G-22). POC well CE2 shows increasing uranium and molybdenum concentrations since 2000, which coincides with the start of pumping from this well in 1999. These increasing concentrations have continued during

⁴Wells installed in 2014 can be found in the October 2014 Status Report: Remediation Strategy and March 2015 Supplemental Information on Remedial Strategy.

this FYR. This increase is expected as it draws contaminated groundwater towards it. Restoration in this area is continuing.

Table G-1 in Appendix G provides a summary of the COCs that exceeded the site standards in 2014, the general locations of the exceedance for the alluvial aquifer as well as the other aquifers for which there were exceedances.

San Andres Aquifer Monitoring

The San Andres aquifer has been used as the source for fresh water injection into the alluvial and Chinle aquifers. As a result, HMC established a monitoring program for the San Andres aquifer and currently samples seven wells at least annually.

Sampling results from 2014 identified uranium in all but one of the San Andres aquifer wells monitored. Deep well 951R, located west of the LTP and west of the West Fault, reported a maximum detected concentration of 0.08 mg/L. This concentration exceeds the federal Safe Drinking Water Act maximum contaminant level (MCL) of 0.03 mg/L and is the highest level recorded in this well since sampling began at this well in 2012. Well 951R is a replacement well for well 951. In 2015, uranium also exceeded the MCL in wells 951R and 943. HMC should conduct further investigation to determine if pumping from the San Andres wells is drawing contamination down into the deeper aquifer. Under NMED's direction, HMC is currently conducting a well-integrity investigation of all seven San Andres wells. Interim reports regarding this investigation are currently under review by NMED.

The Department of Energy (DOE) completed a "Site Status Report on the Flow and Contaminant Transport in Vicinity of the Bluewater New Mexico, Disposal Site" in November 2014. The site status report indicates that uranium contamination in the San Andres aquifer has migrated eastward from the Bluewater site to the HMC site, and possibly that uranium-contaminated San Mateo Creek alluvial groundwater has migrated southward and impacted the northwestern-most municipal well (Milan Well #4) through vertical migration by pumping groundwater from the San Andres aquifer.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

The data review for OU2 evaluated the tailings flushing program for the LTP through the end of 2014. The review also considered data from inspections of the STP, LTP, pond dikes, slopes and evaporation ponds as well as the radon flux surveys, originally presented in the 2011 through 2014 annual reports.

Between 1995 through the end of 2014, 480 million gallons of water has been removed from the tailings via dewatering wells.⁵ Of that, 24 million gallons were pumped from the tailings in 2014. Contaminants removed from the tailings since dewatering began include 19.8 million pounds of sulfate, 76,000 pounds of uranium, 209,000 pounds of molybdenum and 710 pounds of selenium (Appendix G, Table G-2).⁶

Uranium is a key water quality parameter for the tailings solution. Appendix G, Figure G-23 shows uranium concentrations in the tailing solution in 2000, shortly after the start of the flushing program. Figure G-24 shows uranium concentrations in 2014. These figures show the decline in uranium concentrations with time.

The tailings flushing program ended in July 2015; however, data continue to be collected to evaluate potential rebound conditions, the results of which will be presented in future annual reports.

The 2014 annual inspection of the tailings piles and evaporation ponds found that they were in generally good condition and were being maintained within the operating limits of the NRC license and NMED permits and the

-

⁵ Tailings wells were installed in the LTP beginning in 1994 and wells were periodically added through 2014.

⁶ The 2014 Annual Report states that the quantity of constituents removed in 2014 was computed by multiplying the average concentration of a particular constituent for each source of water (groundwater, toe drains and tails collection) by the volume of water pumped for each during that year.

respective facility designs. A slump was observed in the fill under the pond liner of evaporation pond 1, along about 200 feet of the south inslope of the pond from the southeast corner westward. The slump at evaporation pond 1 should be protected against further displacement to protect the liner. During 2014, leaks in the liners for evaporation ponds 2 and 3 were also repaired.

Radon flux measurements for the LTP in October 2014 resulted in average flux of 20.95 picocuries per square meter per second (pCi/m²s), or slightly above the desired 20 pCi/m²s goal. As a result, HMC increased the interim cover in areas with flux monitoring locations where the measurements were higher than other areas of similar size. New measurements were made in November 2014. The addition of interim cover to these areas resulted in an average flux for the LTP of 19.70 pCi/m²s, below the goal. The measurements for the STP resulted in an average flux of 6.84 pCi/m²s. Radon flux measurements at the tailings piles in 2012 and 2013 were below the desired 20 pCi/m²s goal; data from 2011 were slightly above the goal at 20.96 pCi/m²s at the LTP. This also resulted in the installation of additional interim cover in 2011.

OU3 - Radon in Neighboring Subdivisions

The OU3 data review considered data from the May 2012 Removal Assessment Report, data from the December 2014 HHRA, prepared by EPA, and data from the December 2014 Removal Report for Morman Farms, Multiple Properties, Milan, Cibola County, New Mexico (2014 Removal Report), prepared by Weston for EPA.

Between October 2010 and December 2011, 885 indoor radon samples were collected from 79 houses in the five neighboring subdivisions and 28 houses in the background community of Bluewater Village. EPA selected Bluewater Village as the best available area to serve as background based on selection criteria documented in the 2014 HHRA. Results indicated that 11 of the 79 houses from the five subdivisions had average annual radon above the EPA 4 pCi/L recommended action guideline. The maximum detected result, excluding results from basements, was 7.2 pCi/L (from a home in Valle Verde subdivision). Three houses in the background area also exceeded the EPA recommended action guideline. The HHRA did not find a significant difference between the five subdivisions indoor radon levels and the background indoor radon levels. The average of indoor radon levels at the five subdivisions (1.86 pCi/L) was only slightly higher than the background average indoor radon level (1.57 pCi/L). Although the source of the elevated radon in homes was not identified, EPA elected to install radon mitigation systems in the homes with levels exceeding the EPA 4 pCi/L recommended action guideline. Ten of the 11 homes were mitigated through the Superfund removal program; one resident refused mitigation.

EPA also collected 751 outdoor long-term radon samples from several areas around the HMC facility, the five subdivisions and Bluewater Village (background area). One hundred twenty-two radon monitors were placed along the fenceline between the HMC property and the residential areas; 120 radon monitors were placed within the HMC property; 353 radon monitors were placed in the five subdivisions; and 156 monitors were placed in Bluewater Village (Appendix G, Figure G-26). The HHRA determined that statistical comparison between outdoor radon at the five subdivisions versus outdoor radon at the background area identified a statistically significant increase in the average at the five subdivisions over that in the background area. The average outdoor radon levels at the five subdivisions and the background area were 1.29 pCi/L and 0.46 pCi/L, respectively.

The HHRA determined that the average upgradient radon-222 gas levels (0.62 pCi/L) was higher than the downgradient air radon-222 levels (0.44 pCi/L) within the HMC facility boundaries. In contrast, total radon (radon-222 + thoron gas) measured at the downgradient air monitors within the HMC facility boundaries showed higher levels than the upgradient air total radon levels, indicating a potential nearby source of total radon, which EPA believes to be the LTP.

EPA collected surface soil samples from the yards of each house where an access agreement was granted. EPA also collected surface soil from the Site's three irrigation fields, two central pivot fields, evaporation pond banks and a background area. Surface soil samples were also collected from four runs with the highest gamma radiation readings in the area between the evaporation ponds and the fence line. The samples were analyzed for metals and

radionuclides. Summary statistics are found in the HHRA. The HHRA reviewed the data and concluded that soil results did not show that contamination had migrated from the evaporation ponds.

Results from the garden vegetable samples found that radium-226 and radium-228 were not detected. Potassium 40 was detected in the vegetable samples. Potassium 40 was also found in the soil samples and in the background soil at the same concentrations. Potassium 40 is not site related and is naturally found in soil and vegetation at the five neighboring subdivision areas.

EPA collected 14 irrigation well water samples from private properties. Figure G-27 in Appendix G presents the radon results for the 11 residences with private well water. A federal MCL for radon in groundwater has not been established; however the proposed MCL is 300 picocuries per liter (pCi/L) and the proposed alternative maximum contaminant level is 4,000 pCi/L. Five of the samples exceeded the proposed MCL. The HHRA concluded that the results indicate that well water is contaminated with radon gas and has the potential to contribute to indoor air radon levels in houses that use groundwater for domestic purposes. However, because the residences are connected to the Village of Milan water system the direct exposure pathway is incomplete for all but the one resident in Valle Verde who has refused connection to the public water supply. The HHRA also concluded that radon in private well water is contributing a relatively small amount of radon to indoor air based on the detected concentrations and the radon in groundwater to air transfer factor.⁷

The May 2012 Removal Assessment Report included the results of radiation ground scans around 86 houses in the subdivisions south of the Site, collection of soil samples for analysis of radionuclides from areas with high scan readings, measurement of indoor exposure radiation levels (short term), and collection of wipe samples within select residences.

Of the properties screened and sampled, the 2012 Removal Assessment Report concluded that 48 residential properties had outdoor levels above the Derived Concentration Guideline Level, which was a value calculated for each individual residence. Ten properties had discrete items that contained radioactive contamination, including pipe, rocks and petrified wood. Indoor scanning indicated that one home had an indoor total effective dose equivalent (TEDE) greater than the EPA risk-based action level of 15 mrem/yr, and five other residences had total combined outdoor and indoor doses above 15 mrem/yr. Analytical results from each of the 191 soil samples collected and analyzed for total uranium were less than the EPA Regional Screening Levels (RSLs) action level of 230 milligrams per kilogram (mg/kg). All 78 indoor-surface alpha-wipe sample results exhibited gross alpha concentrations less than the NRC action level of 20 disintegrations per minute per 100 square centimeters (20 dpm/100 cm²).

In April 2013, EPA re-evaluated the removal assessment data and compared to new background data to determine which properties were eligible for a removal action. The results identified 20 properties that were eligible for removal of contaminated soils and five properties that were eligible for discrete-items removals (2014 Removal Report). EPA added one other property to the removal list after discussions with the property owner. Of the eligible properties, three property owners declined the EPA offer for soils removal; two additional property owners were non-responsive; and three property owners declined discrete-items removals. Consequently, removal actions associated with 18 residential properties of soils (16 properties) and discrete items (2 properties) were conducted between February and July 2014. Figure G-25 of Appendix G shows the locations of the removals. Following removal actions, a Certified Health Physicist generated property status statements for each property verifying that the project cleanup levels (radium-226 in outdoor soils of less than 3.5 pCi/g inclusive of background; TEDE of less than 15 mrem/yr above background) were achieved. EPA mailed letters to the removal property owners with the results of removal actions at their respective properties.

⁷ The National Academy of Sciences (NAS 1999) recommends that EPA use 10,000 pCi/L in water to 1 pCi/L in air as the best estimate of the transfer of radon in drinking water to radon in indoor air (through showering, cooking and other household water uses).

Site Inspection

The site inspection took place on January 12, 2016. Participants included Sai Appaji, EPA; Angelo Ortelli, NMED; Jesse Toepfer and Bill Ferdinand, Barrick Gold (HMC); Treat Suomi and Johnny Zimmerman-Ward, Skeo Solutions. The purpose of the inspection was to assess the protectiveness of the remedy. Photographs taken during the site inspection and a completed checklist are in Appendix D and E, respectively.

The site inspection started at the on-site HMC offices, with Barrick Gold providing an overview of activities at the Site since the previous FYR. Site inspection participants then drove to the top of the LTP to get an overall view of the Site. From the south side of the tailings piles, site inspection participants viewed evaporation ponds 1 and 2, as well as the collection ponds and the RO treatment building. On top of the LTP, site inspection participants viewed the pilot zeolite system and the full-scale zeolite system, which was almost ready for full-scale operation at the time of the inspection. Contractors were working to complete plumbing connections during the site inspection. Piping and wells left over from the injection system were viewed on top of the LTP. Site inspection participants drove down the tailings pile and observed evaporation pond 3 north of the Site and the TPP injection area, including the associated shed and wells. Site inspection participants then toured the updated RO treatment building, including the new clarifier, equalization tanks, microfiltration units, and the old and new RO systems. Site inspection participants then drove on the STP to view evaporation ponds 1 and 2, and around the STP to observe the face of the pile. Participants also observed new well clusters on a locked access road south of the Site.

On January 12, 2016, Skeo Solutions staff visited the designated site repository, New Mexico State University, Grants Campus Library, as part of the site inspection. Documents, including monitoring reports, as recent as 2015 were available for the public to view on compact disc. Some older documents were available in paper.

V. TECHNICAL ASSESSMENT

QUESTION A: Is the remedy functioning as intended by the decision documents?

Question A Summary:

OU1 – Groundwater Restoration

Yes. The review of documents indicates that the groundwater restoration remedy is being implemented as intended. The primary documents that detail remedial decisions for OU1 are NRC License SUA-1471, the NRC-approved groundwater CAP and NMED groundwater discharge plans.

The groundwater restoration program currently includes an extensive groundwater collection and injection system, an RO water treatment facility, a zeolite-based water treatment system, two collection ponds and three evaporation ponds. Operation of the groundwater collection/injection system has been partially successful at restoring groundwater to the approved standards. Contaminants removed from the Alluvial aquifer include 2.6 million pounds of sulfate, 11,000 pounds of uranium, 16,000 pounds of molybdenum and 643 pounds of selenium. Contaminants removed from the Upper Chinle include 71,000 pounds of sulfate, 342 pounds of uranium, 434 pounds of molybdenum and 9 pounds of selenium. Monitoring data show that the flow of groundwater has been reversed from the injection wells and infiltration trenches at the facility boundary back toward the collection wells, as intended. The injection/collection system has helped contain the most highly contaminated groundwater within the collection area, which includes groundwater under the tailings piles, collection and evaporation ponds 1 and 2. Although contaminant levels have generally decreased over time, they still exceed the groundwater cleanup standards at the POC wells and in some portions of the alluvial and Chinle aquifers.

-

⁸ In 2001, HMC merged with Barrick Gold Corporation as a wholly-owned subsidiary (HHRA, 2014).

Contaminant levels remain above groundwater cleanup standards in the alluvial and Chinle aquifers outside the facility boundary and in residential neighborhoods. Injection/collection continues in areas where contaminant concentrations exceed cleanup standards. The uranium plume in the alluvial aquifer extends southwest of the Felice Acres development (Appendix G). New wells were added in this area in 2014; however, additional efforts may be needed to aid restoration efforts. Most residents in the developments south and southwest of the Site are connected to public water. The only exception is a resident in Valle Verde who declined to connect to the public water supply. HMC is working with property owners to plug and abandon private wells.

Sampling results from 2014 and 2015 identified uranium in San Andres well 951R as well as well 943 at a concentration that exceeds the uranium MCL. Groundwater protection standards for the San Andres aquifer have not been established. The source of the elevated uranium in the San Andres aquifer requires further investigation to determine if pumping from the San Andres wells is drawing contamination down into the deeper aquifer. The DOE's 2014 "Site Status Report on the Flow and Contaminant Transport in Vicinity of the Bluewater New Mexico Disposal Site" also indicates that uranium contamination in the San Andres aquifer has migrated eastward from the Bluewater site to the HMC site, and possibly that uranium-contaminated San Mateo Creek alluvial groundwater has migrated southward and impacted the northwestern-most municipal well (Milan Well #4) through vertical migration by pumping groundwater from the San Andres aquifer.

Since the previous FYR, HMC has discontinued land treatment of extracted groundwater. Off-site extracted groundwater is now treated through the RO or pilot zeolite treatment systems. HMC upgraded the RO treatment system to treat 1,200 gpm, doubling its capacity to treat groundwater. HMC also constructed a full-scale zeolite water treatment system, capable of treating 1,500 gpm. HMC now has the capacity to treat 2,700 gpm, which is significantly more than the original 300 gpm operating capacity of the older RO treatment system. Water treated with these alternative technologies is expected to reduce reliance on San Andres water for injection. Since the previous FYR, HMC added 550 wells, including injection and extraction wells, to the program in efforts to expedite the cleanup process.

The 2012 Updated CAP estimated active groundwater restoration to be complete by 2020; however, the estimate was based on groundwater modeling, results from present operating conditions and predicted future operation conditions. Several operating conditions have changed since the modeling was conducted, including discontinuation of land treatment and active flushing of the LTP, as well as an increase in the operating capacity of the water treatment systems. The modeling predicted when COC concentrations at the POC wells would be achieved; modeling did not predict COC concentrations for any other areas. Based on these recent changes, this estimate should be revised based on current remedy components.

The complexity of the OU1 remedial system requires daily O&M. HMC has full-time staff for that purpose. This level of O&M appears to be adequate to maintain the groundwater remedial system. HMC is exploring opportunities for optimization of the remedy and evaluating the efficacy of TPP injections as an alternative groundwater treatment technology.

Institutional controls for the Site currently include a NM-OSE Health Advisory issued to every person who applies for a well permit within an area inside the San Mateo Creek basin. HMC also conducts an annual land use survey to meet annual license condition reporting requirements under NRC License SUA-1471. Institutional controls (i.e. NM-OSE order for a moratorium on the permitting of new wells) are currently in place to caution residents from drinking contaminated groundwater.

An EPA ROD for groundwater restoration has not been issued for OU1. However, EPA is reviewing assessment and response actions taken under NRC and NMED authority to determine if they are functionally equivalent to the CERCLA cleanup process or if additional investigations or response actions are warranted. EPA is also reevaluating background concentrations for the alluvial and Chinle aquifers at the Site. After completing the analysis, EPA plans to issue a ROD for OU1.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

Yes. Several OU2 remedy components have been implemented as intended. The remaining components for final reclamation and closure, included in HMC's 2013 update to the Decommissioning and Reclamation Plan, are anticipated to be implemented once OU1 groundwater restoration is complete.

To date, HMC has decommissioned and dismantled the mill, with some waste materials and impacted soils deposited in the LTP. HMC recontoured the LTP, constructed a final radon barrier and erosion protection cover on its sides, and placed an interim radon cover on its top. HMC also constructed an interim radon cover on a portion of the STP. The covers appear to be functioning as designed. HMC conducts regular O&M of the OU2 remedy components to maintain effectiveness of the remedy and takes corrective action as needed. In 2014, these actions included additional interim cover on the LTP because of elevated radon flux measurements and repairs to the evaporation ponds due to liner leaks. HMC should determine the need for future corrective action for the slump at evaporation pond 1 to protect against further displacement and protect the pond's liner.

Between 2000 and 2015, HMC implemented a tailings flushing program to mobilize contaminant mass in the tailings piles with subsequent capture of the aqueous-phase contamination by the collection system. As of the end of 2014, HMC estimates that 76,000 pounds of uranium and other site contaminants have been removed from the tailings since dewatering began. HMC is collecting additional data to evaluate potential rebound now that the tailings flushing program has ceased.

Following approved closure of the LTP, NRC will implement institutional controls for the former mill facility. Following HMC's specific license termination, a custodial agency, DOE, will ensure continued long-term care, including monitoring and maintenance to protect the public health and safety, as required by 10 CFR 40.28.

An EPA ROD for OU2 cleanup has not been issued. However, EPA is currently evaluating NRC activities to determine whether they are functionally equivalent to the CERCLA cleanup process or if additional investigations or response actions are warranted. Once this analysis is complete, EPA plans to issue a ROD for OU2.

OU3 - Radon in Neighboring Subdivisions

EPA did not require a remedy for OU3 in the September 1989 ROD. However, EPA conducted additional evaluation of the neighboring subdivisions between 2010 and 2014. Data from the investigations were used to develop an HHRA and to identify residences where removal actions were necessary to protect human health.

Although the HHRA found no significant difference between the five subdivisions' annual indoor air radon levels and the background annual indoor air radon levels, EPA elected to install radon mitigation systems in 11 homes with radon levels above 4 pCi/L; one additional homeowner declined to have a mitigation system installed. The mitigation systems are operating as intended and have reduced indoor air radon concentrations in these homes to levels below the EPA 4 pCi/L recommended action guideline⁹.

EPA also conducted removal actions in 2014 to address radioactive-contaminated soil at 16 properties and radioactive discrete material at two additional properties. The removal actions successfully achieved cleanup levels. EPA determined that the radiological soil and debris was unrelated to the Site, but elected to conduct the removal actions to protect human health.

An O&M Plan for OU3 is not in place. Generally the radon mitigation systems are known to operate without any maintenance problems for many years before the motor in the unit wears out. EPA has installed these systems at other sites and have not experienced maintenance issues. The homeowners have been instructed to contact the installer for servicing any repairs beyond the warranty period.

32

⁹ Data presented in the Radon Mitigation Project Report, prepared by New Mexico Radon Services for Environmental Quality Management, Inc., dated September 2012

QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels and remedial action objectives (RAOs) used at the time of the remedy selection still valid?

OU1 – Groundwater Restoration

Radiological and some non-radiological contaminants in groundwater are regulated under NRC License SUA-1471 and under the New Mexico Water Quality Control Commission's groundwater restoration requirements (NMED Discharge Permit DP-200). Some of the current groundwater standards, including those for uranium in all but the Lower Chinle Non-Mixing Zone, are based on 95 percent Upper Tolerance Limits of background concentrations, which are higher than health risk-based levels and promulgated legal standards. After coordinating with EPA and NMED, NRC published an Environmental Assessment in May 2006 and a Finding of No Significant Impact in June 2006, and issued License Amendment 39 to NRC License SUA-1471 in July 2006 to document the revised list of groundwater standards. These groundwater protection standards have been incorporated into the NMED discharge permit and remain valid. When EPA issues a ROD for the OU1 remedy, this ROD will also include a complete list of applicable or relevant and appropriate requirements (ARARs) for the Site that will be evaluated during future FYRs.

Land use in OU1 has been primarily agricultural with some low density residential use. Since the previous FYR, a shed manufacturing company began operations across the street from the Site. Future land use is expected to be consistent with current use. No human health or ecological routes of exposure have changed and no new receptors have been identified that could affect the protectiveness of the remedy at OU1.

No new contaminants or contaminant sources were identified at OU1. No unanticipated toxic byproducts of the remedy have been identified at OU1.

Current toxicity values for groundwater COCs, sourced from the November 2015 RSL table (http://www.epa.gov/risk/risk-based-screening-table-generic-tables) and the Preliminary Remediation Goals (PRGs) for Radionuclides Table (https://epa-prgs.ornl.gov/radionuclides/download.html) are summarized in Appendix J. Since toxicity data for only three COCs were included in the previous FYR, changes in toxicity values for only these three COCs were reviewed. Since the previous FYR, the reference concentration for uranium has changed from 3 x 10⁻⁴ mg/m³ (milligrams per cubic meter) to a more stringent value of 4 x 10⁻⁵ mg/m³. This change does not affect the groundwater cleanup standards for uranium, which are primarily based on background. In addition, the inhalation pathway is not significant for uranium exposures from groundwater. Other contaminant characteristics have not changed in a way that would affect protectiveness of the remedy. Risk assessment methodologies have not changed in a way that could affect protectiveness of the remedy.

Significant progress toward meeting RAOs has been made during the past five years. Upgrades and expansion of the RO water treatment facility, startup of the full-scale zeolite-based treatment system and installation of hundreds of new injection/extraction wells are expected to expedite groundwater restoration to complete active restoration by 2020. However, as previously mentioned, this date of completion requires an update based on current conditions.

OU2 - Long-Term Tailings Stabilization, Surface Reclamation and Site Closure

The cleanup criteria for OU2 were based on the NRC requirements in 10 CFR 40, Appendix A, Criterion 6, which are repeated in the EPA requirements specified in 40 CFR 192. These regulations include a cleanup standard for radium-226 in the top 15 cm of soil of 10 pCi/g (5 pCi/g above background) and 20.5 pCi/g (15 pCi/g above background) for each 15-cm depth increment below the top 15 cm. The regulations have not changed; therefore, the cleanup standards remain valid.

The requirements in 10 CFR 40, Appendix A, Criterion 6 (6) were revised to include a benchmark dose criterion to address residual uranium and thorium during mill cleanups. Though the requirement does not apply to sites

with a previously-approved decommissioning plan, NRC has indicated that it would be applied to new areas of contamination. In the event that these areas are identified in the future, HMC will develop dose-based (radium-226 benchmark dose) cleanup criteria using appropriate methods. These criteria, if established, can be used to evaluate protectiveness in future FYRs.

When EPA issues a ROD for the OU2 remedy, this ROD will also include a complete list of ARARs for the Site that will be evaluated during future FYRs.

Land use at OU2 is expected to remain consistent with current use. Homestake owns substantial acreage around the licensed boundary and land use is not expected to significantly change in the near future. Following completion of groundwater restoration at the Site, remaining features will be decommissioned and closed in accordance with the 2013 update to the Decommissioning and Reclamation Plan. Final decommission and reclamation activities will include final closure of the LTP and STP, closure and demolition of the groundwater treatment systems, closure of the two collection ponds and three evaporation ponds, demolition of remaining site structures, reclamation of remaining contaminated soils, final surface contouring and topseeding, and installation of necessary security features (fencing, etc.). HMC currently anticipates full closure by 2022; however, this date is based on the anticipated completion of active groundwater restoration by 2020. This date may require revision based on current conditions.

No human health or ecological routes of exposure have changed and no new receptors have been identified that could affect the protectiveness of the remedy at OU2. No new contaminants or contaminant sources were identified at OU2 during the FYR period.

OU3 - Radon in Neighboring Subdivisions

EPA finalized an HHRA for OU3 in December 2014. The HHRA identified chemicals and radionuclides of potential concern, identified the pathways and routes of intake for contaminants, and quantitatively evaluated the potential excess lifetime cancer and non-cancer risk. The HHRA made the following conclusions:

- Indoor radon gas levels at the five subdivisions were similar to levels at the indoor radon background location
- Risk from outdoor radon gas was slightly higher at the five subdivisions than in the background area. Compared to indoor radon, the risk from outdoor radon is less.
- The excess cancer risk from direct and indirect exposure to soil (ingestion, inhalation, external and produce ingestion), excluding background, is estimated at 6 x 10⁻⁵ in site-related life-time cancer risk, which exceeds EPA's point-of-departure of 1 x 10⁻⁶ but is within EPA acceptable risk range (1 x 10⁻⁶ to 1 x 10⁻⁴).
- If raising cattle or poultry for domestic uses, the increase in excess cancer risk from indirect exposure to soil (i.e., ingestion of meat, ingestion of milk, ingestion of poultry and eggs, etc.) is within EPA acceptable risk range, except for ingestion of milk, which is slightly above the upper end of the risk range.
- If using well water for domestic consumption, the cancer risk (2.2 x 10⁻³) exceeds EPA's acceptable risk range of 1 x 10⁻⁶ to 1x 10⁻⁴. Risk from site-related contaminants in groundwater were not delineated in the risk assessment. Residences of the five subdivisions have been connected to the Milan municipal water supply system with one exception. This response action was taken to abate risks from exposure to contaminants in groundwater.
- The source of excess cancer risk is 1.3×10^{-3} from inhalation exposure to background sources and 5×10^{-4} from exposure to HMC sources. The level of risk presented by the HMC facility apart from background would generally indicate the need for long-term cleanup in the Superfund program because it exceeds EPA's acceptable risk range (1 x 10⁻⁶ to 1 x 10⁻⁴). Long-term cleanup is ongoing.

Although the source of the elevated radon in homes was not identified, EPA elected to install radon mitigation systems in the homes with levels exceeding the EPA 4 pCi/L recommended action guideline. This action level has not changed.

No human health or ecological routes of exposure have changed and no new receptors have been identified that could affect protectiveness of the remedy at OU3. No new contaminants or contaminant sources were identified at OU3 during the FYR period.

QUESTION C: Has any **other** information come to light that could call into question the protectiveness of the remedy?

EPA is currently evaluating the NRC activities to determine if they are functionally equivalent to CERCLA cleanup. This review is expected to determine the need to conduct an ecological risk assessment for the Site. EPA is also conducting a reassessment of the background groundwater quality for the alluvial and Chinle aquifers as part of this effort.

VI. ISSUES/RECOMMENDATIONS

Issues/Recommendations
OU(s) without Issues/Recommendations Identified in the FYR:
OU3

Issues and Recommendations Identified in the FYR:

OU(s): OU1 and	Issue Category: Other				
OU2	Issue: Although remediation is underway under NRC authority, there is no ROD in place for OU1 and OU2.				
	Recommendation: Complete EPA reassessment of background groundwater and complete the CERCLA equivalency analysis including issuance of a ROD for OU1 and OU2.				
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date	
No	Yes	EPA	EPA	9/30/2018	

OU(s): OU1	Issue Category: Remedy Performance
OU(s): OU1	Issue: The 2012 Updated CAP estimated active groundwater restoration to be complete by 2020; however, the estimate was based on groundwater modeling, observed results from present operating conditions and predicted future operating conditions. Several operating conditions have changed since the groundwater modeling was conducted, including discontinuation of land treatment and active flushing of the LTP as well as an increase in the operating capacity of the water treatment systems. In addition, groundwater modeling estimated the time for POC wells to achieve COC groundwater protection standards; modeling did not predict COC concentrations for any other areas, including those areas outside the facility's licensed boundary.
	Recommendation : Update the timeframe estimate for groundwater restoration based on current operating conditions and data. Include an estimate of the time

	needed for groundwater restoration of those areas outside the facility's licensed boundary in addition to the areas downgradient of the source areas.				
Affect Current Protectiveness	v e v				
No	Yes	EPA	9/27/2017		

OU(s): OU1	Issue Category: Remedy Performance				
	Issue: The source of the uranium exceedance in the San Andres supply wells at the Site is unclear.				
	Recommendation: Investigate the source of the elevated uranium in the HMC supply wells to determine if pumping from the San Andres wells is drawing site contamination into the deeper aquifer.				
Affect Current Protectiveness	Affect Future Party Oversight Party Milestone Date Protectiveness Responsible				
No	Yes	PRP	EPA	9/27/2017	

OTHER FINDINGS

In addition, the following are recommendations that were identified during the FYR but do not affect current and/or future protectiveness:

- Uranium concentrations persist above the site standard (0.16 mg/L) in southern Felice Acres in the alluvial aquifer. Although HMC installed additional wells southwest of Felice Acres in 2014, additional efforts may be needed to aid restoration of this area.
- HMC should determine the need for future corrective action for the slump at evaporation pond 1 to protect against further displacement and protect the pond's liner.

VII. PROTECTIVENESS STATEMENT

Protectiveness Statements

Operable Unit:Protectiveness Determination:Planned AddendumOU1Short-term ProtectiveCompletion Date:

Protectiveness Statement:

The OU1 remedy is currently protective of human health and the environment because: the groundwater collection/injection system is containing the highest contaminant concentrations within a defined collection area, primarily within the facility's licensed boundary; the system is also reducing contaminant concentrations in groundwater beyond the facility's licensed boundary; residents near the Site utilize the public water supply or have been given the option to connect to public water. An Institutional Control in the form of a health advisory is in place to caution current and future owners and users of private wells about potential contamination. In order for the remedy to be protective in the long term, the following actions need to be taken: Complete EPA reassessment of background groundwater and complete the CERCLA equivalency analysis including issuance of a ROD for OU1 and OU2. Update the timeframe estimate for groundwater restoration based on current operating conditions and data. Include an estimate of the time needed for groundwater restoration of those areas outside the facility's licensed boundary in addition to the areas downgradient of the source areas. Investigate the source of the elevated uranium in HMC supply wells in the San Andres aquifer to determine if pumping from the San Andres wells is drawing site contamination into the deeper aquifer.

Operable Unit:Protectiveness Determination:Planned AddendumOU2Short-term ProtectiveCompletion Date:
Click here to enter a date

Protectiveness Statement:

The OU2 remedy is currently protective of human health and the environment because soil contaminated by windblown tailings was excavated and disposed, the mill facility was decontaminated, demolished, and disposed of in the LTP. A final radon barrier and erosion protection cover were constructed on the sides of the LTP, and an interim soil cover was constructed on its top and on the small tailings pile resulting in exposures to contamination are being currently controlled. In order for the remedy to be protective in the long-term, complete the CERCLA equivalency analysis including issuance of a ROD for OU1 and OU2.

Operable Unit: Protectiveness Determination: Planned Addendum
OU3 Protective Completion Date:
Click here to enter a date

Protectiveness Statement:

The ROD issued for OU3 was a no action ROD. However, EPA conducted removal actions to address concerns identified during supplemental investigations conducted between 2010 and 2014. These removal actions are protective of human health and the environment. Radon mitigation systems and soil/debris removal efforts mitigated exposures to unacceptable levels of contaminants.

Sitewide Protectiveness Statement						
Protectiveness Determination: Short-term Protective		Planned Addendum Completion Date: Click here to enter a date				

Protectiveness Statement:

The remedy at the Site is currently protective of human health and the environment. The removal actions conducted at OU3 are protective of human health and the environment. However, in order for the remedy to be protective in the long-term, the actions identified in the OU1 and OU2 protectiveness statements need to be taken.

VIII. NEXT REVIEW

The next FYR report for the Homestake Mining Company Superfund site is required five years from the completion date of this review.

APPENDIX A - REFERENCE LIST

2011 Annual Monitoring Report/Performance Review for Homestake's Grants Project Pursuant to NRC License SUA-1471 and Discharge Plan DP-200. Prepared by Homestake Mining Company of California and Hydro-Engineering, LLC. March 2012.

2012 Annual Monitoring Report/Performance Review for Homestake's Grants Project Pursuant to NRC License SUA-1471 and Discharge Plan DP-200. Prepared by Homestake Mining Company of California and Hydro-Engineering, LLC. March 2013.

2013 Annual Monitoring Report/Performance Review for Homestake's Grants Project Pursuant to NRC License SUA-1471 and Discharge Plan DP-200. Prepared by Homestake Mining Company of California and Hydro-Engineering, LLC. March 2014.

2014 Annual Monitoring Report/Performance Review for Homestake's Grants Project Pursuant to NRC License SUA-1471 and Discharge Plan DP-200. Prepared by Homestake Mining Company of California and Hydro-Engineering, LLC. March 2015.

First Five-Year Review Report For Homestake Mining Company Superfund Site, Cibola County, New Mexico. Prepared by CH2M Hill for U.S. EPA Region 6. September 2001.

Decommissioning and Reclamation Plan Update 2013, SUA-1471, Homestake Grants Reclamation Project, Cibola County, New Mexico. Prepared by ARCARDIS U.S., Inc. for Homestake Mining Company of California. April 2013.

Discharge Permit DP-200, Homestake Mining Company of California Uranium Millsite. Prepared by New Mexico Environment Department, Groundwater Quality Bureau.

Grants Reclamation Project Updated Corrective Action Program (CAP). Prepared by Homestake Mining Company of California for the Nuclear Regulatory Commission. March 2012.

Homestake – Grants Uranium Recovery Facility, Site Summary from the NRC website: http://www.nrc.gov/info-finder/decommissioning/uranium/is-homestake.pdf

Human Health Risk Assessment, Homestake Mining Co. Superfund Site, Cibola County, New Mexico. Prepared by U.S. EPA. December 2014.

Record of Decision, Homestake Mining Company, Radon Operable Unit, Cibola County, New Mexico. Prepared by U.S. EPA Region 6. September 1989.

Removal Assessment Report for Homestake Mining Company, Grants, Cibola County, New Mexico. Prepared by Weston Solutions, Inc. for U.S. EPA Region 6. May 2012.

Removal Report for Mormon Farms, Multiple Properties, Milan, Cibola County, New Mexico. Prepared by Weston Solutions, Inc. for U.S. EPA Region 6. December 2014.

Risk Assessment of Radon in Drinking Water. Prepared by National Academy of Sciences. National Academy Press. Washington, DC. 1999.

Second Five-Year Review Report For Homestake Mining Company Superfund Site, Cibola County, New Mexico. Prepared by U.S. EPA Region 6. September 2006.

Third Five-Year Review Report For Homestake Mining Company Superfund Site, Cibola County, New Mexico. Prepared by U.S. EPA Region 6. September 2011.

APPENDIX B - SITE MAPS

Figure B-1: Site Location Map




Figure B-2: Detailed Site Map






Figure B-3: Parcels Map





Figure B-4: Injection and Collection Well Map (Source: 2014 Annual Monitoring Report/Performance Review)



APPENDIX C - SITE CHRONOLOGY

Event	Date		
Uranium mining mill operations began at the Site	1958		
The New Mexico State Engineers Office first observed groundwater	1961		
contamination near the Site			
New Mexico signed an agreement with the NRC authorizing the State to	1974		
regulate uranium milling activities under the Atomic Energy Act	-,		
A New Mexico Environment Improvement Division and EPA study	1974-1975		
determined that residential well water in one of the neighboring	157.137.6		
subdivisions showed elevated selenium levels			
NMED and HMC reached an agreement on a groundwater protection	August 1976		
plan, establishing a groundwater injection and collection system and an	Tagast 1970		
associated monitoring program, and providing bottled water for			
downgradient residents			
HMC implemented the groundwater protection plan; groundwater	1977		
remediation began with fresh-water injection into six alluvial wells on	17//		
the north side of Broadview Acres (OU1)			
HMC installed additional collection and injection wells, including those	1978-1982		
in Murray Acres and Broadview Acres ¹⁰	19/0-1982		
EPA proposed the Site for the Superfund program's NPL	December 30, 1982		
EPA listed the Site on the NPL	September 8, 1983		
EPA and HMC signed a Consent Decree requiring HMC to pay for an	November 29, 1983		
extension of the Village of Milan municipal water system to four			
residential subdivisions, and to pay for basic water services for the			
residences of these subdivisions for 10 years.	1001		
NMED approved groundwater discharge plan DP-200 (OU1)	1984		
HMC completed a Phase II Feasibility Study (FS) (OU1)	1986		
The Milan water supply was installed for Broadview Acres, Felice Acres,	1986		
Murray Acres and Pleasant Valley Estates subdivisions (OU1)			
New Mexico returned regulatory authority for uranium mills to NRC	1986		
EPA issued an Administrative Order on Consent to HMC to conduct a	June 30, 1987		
Remedial Investigation (RI)/FS for the Radon OU (OU3); HMC initiated			
the RI/FS			
HMC finished the RI/FS for the Radon OU (OU3); EPA issued a no	September 27, 1989		
further action Record of Decision (ROD) for OU3			
HMC submitted an Updated CAP for groundwater remediation to the	September 1989		
NRC (OU1)			
Uranium milling operations at the Site ceased	1990		
HMC constructed evaporation pond 1 on top of the STP (OU1)	1990		
HMC finished installation of a toe drainage system around the LTP	August 1992		
HMC began reclamation activities to clean up soils and decommission	1993		
the mill. HMC submitted a reclamation plan to NRC.			
EPA Region 6 and NRC sign a Memorandum of Understanding (MOU)	1993		
detailing each agency's responsibilities and authority at the Site			
HMC re-contoured the west side of the LTP (OU2)	1993		
EPA released HMC from the 1983 CD (OU1)	1994		
HMC re-contoured the east side of the LTP (OU2)	1994		
HMC completed demolition of the mill and surface reclamation activities	1995		
(OU2)	1993		
HMC began collection of lower concentration water for re-injection into	1995		
the higher concentration areas in the alluvial aquifer (OU1)	1993		
HMC tested dewatering of the LTP (OU2)	1995		
Third tested dewatering of the LTF (OU2)	1995		

_

¹⁰ Additional groundwater injection and collection wells have been added throughout the groundwater restoration effort and are not included further in this chronology. Please refer to the 2012 Updated CAP for history of the groundwater injection/collection systems at the Site.

Event	Date
HMC completed installation of the interim soil cover on the STP	October 1995
HMC began using evaporation pond 2 (OU1)	1996
HMC initiated fresh water injections in Upper Chinle well CW13 (OU1)	1996
EPA prepared a Preliminary Close-out Report	September 23, 1996
NRC approved the soil cleanup and mill reclamation (OU2)	1999
HMC added a reverse osmosis (RO) unit to treat water and produce RO	1999
product water for injection into the alluvial aquifer (OU1)	
HMC initiated the flushing program for the LTP (OU2)	2000
EPA approved the first FYR	September 27, 2001
HMC added 60 acres of irrigation area (OU1)	2002
HMC initiated fresh water injection in Section 28; fresh water injection	2002
into Upper Chinle well 944; fresh water injection into the alluvial aquifer east of Felice Areas and fresh water injection east of Broadview Acres	
(OU1)	
HMC added a second RO unit to the treatment plant to increase RO	2002
treatment capacity from 300 to 600 gallons per minute (OU2)	2002
HMC added a fresh water injection line west of the LTP and initiated	2003
fresh water injection into Section 3 (OU2)	2000
HMC added 24 acres of flood irrigation area in Section 33, injection lines	2004
in Section 3 and injection lines east of Broadview Acres and in southern	
Felice Acres (OU2)	
HMC expanded the groundwater collection and irrigation system (OU1)	2005
NMED approved revised site groundwater background concentrations for	2005
each aquifer unit (OU1)	
NMED sampled residential wells in nearby subdivisions based on	2005
recommendations from the Bluewater Valley Downstream Alliance	
(BVDA) (OU1)	
EPA issued the second FYR	September 26, 2006
HMC submitted the Updated CAP to NRC	December 2006
EPA completed the Remedy System Evaluation (RSE), a broad	December 2008
evaluation that considered the remedy goals, conceptual site model,	
aboveground and subsurface performance and site closure strategy. NMED issued a health advisory to limit groundwater exposure	2009
NMED and HMC reach a Memorandum of Agreement for HMC to	2009
provide additional water hook-ups to residents	200)
The Agency for Toxic Substances and Disease Registry (ATSDR) issued	June 2009
a Health Consultation Report	54.10 2 009
NMED approved discharge plan DP-725 and evaporation pond 3	2009
EPA began multi-media sampling effort in support of the human health	2010
risk assessment	
EPA issued an Addendum to the RSE	December 2010
EPA recommended NRC implement the RSE recommendations	March 2011
EPA issued a deficiency letter to NRC regarding HMC's non-compliance	2011
with radon standards and potential ARARs	
NMED granted temporary permission for land application of alluvial	2011
water in Section 28; temporary permission was denied for land	
application of alluvial water in Section 33 center pivot and Sections 33	
and 34 flood irrigation areas	F-1 2011
HMC completed repairs to the LTP and STP, damaged by July 2010	February 2011
storms, and replaced stormwater downdrains EPA issued the third FYR	Santambar 20, 2011
Meeting held with representatives of the NRC, EPA, NMED, DOE and	September 29, 2011 January 2012
HMC to discuss the RSE recommendations. NRC indicated that it did not	January 2012
plan to specifically require HMC to implement any of the	
recommendations. However, HMC would have to address some of the	
issues in the Updated CAP for the Site to demonstrate compliance with	

Event	Date
willingness to evaluate a number of the RSE recommendations to	
determine if remedial process efficiencies could be improved.	
EPA issued an Administrative Order on Consent to HMC	February 24, 2012
HMC submitted the Updated CAP to NRC, EPA and NMED for review	March 2012
and approval (OU1)	
HMC submitted a revised Decommissioning and Reclamation Plan to	2013
NRC for review and approval (OU2)	
EPA installed radon mitigation systems at 10 residential properties; one	2012
property owner whose residence was eligible for a system refused	
mitigation efforts (OU3)	
EPA conducted a soil/debris removal effort at 18 residential properties	2014
(OU3)	
EPA issued the final HHRA for OU3	December 2014

APPENDIX D - SITE BACKGROUND

D.1 Physical Characteristics

The Site includes a former uranium mill, portions of the underlying aquifers contaminated by site-related wastes (tailings) and contamination in neighboring residential subdivisions. HMC operated the mill from 1958 to 1990 before demolishing most of the mill facility in the early 1990s. Existing facility features include a small office and maintenance complex, small and large tailings piles, an RO water treatment facility, pilot and full-scale zeolite treatment systems, two wastewater collection ponds and three evaporation ponds. The LTP is unlined, covers about 215 acres, is 85 to 90 feet tall and contains about 20 million tons of tailings. The STP is also unlined and covers about 40 acres, is 25 feet tall and contains about 2 million tons of tailings. Evaporation pond 1 was constructed on top of the STP.

Five housing subdivisions are located south and southwest of the former mill. The nearest residence is located in Murray Acres and is about 0.6 miles from the center of either tailings pile.

The Site lies above the San Mateo alluvium, which is over 120 feet deep. The alluvium is generally sandy silt; however, two distinct sand and gravel horizons occur at the top and bottom of the unit. The lower sand and gravel horizon is relatively continuous throughout the area and is a source of water in the region. Directly under the alluvium is the Chinle Formation (with Upper and Lower members), composed primarily of shale and siltstone with three sandstone units. The Chinle Formation is underlain by the San Andres Limestone. The Chinle beds have been tilted up to ten degrees (generally to the northeast) and been extensively faulted in the site area due to uplift of the Zuni Mountains southwest of the Site. The natural groundwater flow in the alluvial aquifer is generally to the southwest, while flow direction in the bedrock aquifers is generally eastward (downdip) under natural conditions.

Surface drainage across the Site is predominantly directed to the southwest. Ponding occurs after significant precipitation, but this water either evaporates or infiltrates into the ground. The Site lies partially within the floodplain of the San Mateo Creek, which is part of the Rio Grande drainage basin. The Arroyo Del Puerto is an ephemeral tributary stream to the San Mateo Creek drainage, which is also ephemeral at their confluence. This confluence is about 10 miles north of the Site. San Mateo Creek has perennial flow at its headwaters on the north flank of Mount Taylor; intermittent flow over its middle reach, which is normally dry in the summer except for high rainfall events; and ephemeral in its lower reach where it meets Rio San Jose Creek near Milan. During peak runoff from snow melt in the late spring or during heavy summer and fall rain storms, flood waters pass through the Site and continue to the five residential subdivisions southwest of the Site.

D.2 Land and Resource Use

HMC owns land in and around the former mill property. HMC leases much of the land for livestock grazing. The area containing the evaporation ponds, groundwater treatment plant, tailings piles and office and maintenance complex is fenced to exclude grazing. Certain small areas in the southern and western portions of the Site boundary are seasonally used for livestock grazing.

The major land use south and southwest of the Site is residential development in the Pleasant Valley Estates, Murray Acres, Broadview Acres, Valle Verde and Felice Acres subdivisions. Several lots within these developments are vacant or contain horse barns, corrals or equipment storage. Some dwellings are vacant or have been permanently abandoned and are in disrepair. Most of these houses use the Milan municipal water supply. In 2012 one residence in Valle Verde was found to still be using water from a domestic well supply. The resident has refused offers to connect to the public water supply (2014 Annual Monitoring Report, HMC).

Future land use is expected to be consistent with current use. Although the New Mexico Office of the State Engineer issued a health advisory to prevent people from installing private wells, a future resident could install a well and use it for domestic purposes.

D.3 History of Contamination

Milling operations occurred at the Site between 1958 and 1990. Operations used an alkaline leach-caustic precipitation process to extract and concentrate uranium oxide from uranium ores. The milling process byproducts (waste) were placed in two tailings piles onsite (STP and LTP). The STP contains approximately 1.2 million tons of tailings from ore milled under contracts with the federal government. The LTP contains approximately 21 million tons of tailings from ore milled under both federal government and commercial contracts. Because the tailings piles were not constructed with engineered liners, they likely began leaking soon after milling operations began. Early FYR reports state that groundwater contamination was first identified in 1961; however, the source of this information could not be corroborated.

In the mid-1970s high levels of selenium were detected in residential wells completed in the alluvial aquifer, which prompted groundwater remedial activities. In addition to the tailings pile sources, soil contamination from uranium ore storage and windblown tailings continued until the OU2 soil cleanup was completed. It is possible that leaching of soil contaminants left in place continued to contaminate groundwater, because the soil cleanup standard was based on human-health risk rather than potential for contaminants to leach to groundwater; this may explain the area of persistent groundwater contamination south of the former mill site.

An important change in the remedial strategy occurred about 15 years ago when the tailings-flushing program began. As designed, this flushing has resulted in considerable mobilization of contaminant mass that would not otherwise be occurring. Injection of "clean" groundwater into impacted alluvial and Chinle Formation aquifers has been a major part of the OU1 remedial strategy. This has been done to help hydraulic control of the contaminant plumes; however, it has also diluted contaminant concentrations in samples from nearby monitoring wells, making it difficult to assess contaminant trends. Periodic movement and/or addition of injection lines has added to the difficulty in assessing trends.

D.4 Initial Response

The OU1 initial response was due to detection of elevated selenium in residential water supply wells southwest of the mill facility in 1976. The original groundwater remedy has been revised and expanded on HMC's initiative. The current system includes hundreds of monitoring, injection wells/infiltration lines and collection wells located over thousands of acres.

The decision to close the mill facility triggered the initial response for OU2. Cleanup of the mill facilities and contaminated soils was completed in 1995; however, final closure of the tailings piles has not occurred due to a change in remedial strategy from that presented in the original tailings piles closure plan. The original strategy was to dewater the LTP as much as possible, assure that at least 90 percent consolidation had occurred, and then construct the final radon cover. However, in 2000 the tailings flushing program began, which injected considerable quantities of water and, therefore, final closure of the LTP has been postponed. NRC is the lead agency overseeing cleanup. HMC follows the NRC closure process, approved pursuant to the NRC license. There have been no interim response actions.

APPENDIX E – PRESS NOTICE



Homestake Mining Company Superfund Site Public Notice U. S. Environmental Protection Agency, Region 6

December 2015

The U.S. Environmental Protection Agency Region 6 (EPA) will be conducting the fourth five-year review of remedy implementation and performance at the Homestake Mining Company Superfund site (Site) in Milan, Cibola County, New Mexico. The Site includes a former uranium mill, contaminated portions of the underlying groundwater aquifers and contamination in neighboring subdivisions. The land immediately south and west of the Site consists of residential developments. Land near the Site is also used for agricultural and livestock purposes. The groundwater remedial actions included source control, plume control, evaporation and reverse osmosis system. The five-year review will determine if the remedies are still protective of human health and the environment.

The five-year review is scheduled for completion in September 2016. The report will be made available to the public at the following local information repository:

New Mexico State University, Grants Campus Library 1500 Third Street Grants, New Mexico 87020 (505) 287-6639

Site status updates are available on the Internet at http://www.epa.gov/superfund/homestake-mining

All media inquiries should be directed to the EPA Press Office at (214) 665-2200

For more information about the Site, contact:

Sairam Appaji/Remedial Project Manager (214) 665-3126 or 1-800-533-3508 (toll-free) or by email at appaji.sairam@epa.gov

Stephen Harper/Community Involvement Coordinator (214) 665-2727 or 1-800-533-3508 (toll-free) or by email at harper.stephen@epa.gov

APPENDIX F – INTERVIEW FORMS

Homestake Mining Co. Superfund Site Five-Year Review Interview Form

Site Name: Homestake Mining Co. EPA ID No.: NMD007860935
Interviewer Name: Johnny Zimmerman- Affiliation: Skeo Solutions (EPA

Ward

Subject Name: Angelo Ortelli A

Kurt Vollbrecht

Affiliation: NMED

NMED Mining

Contractor)

Environmental Compliance

Section

Subject Contact Information: (505) 827-2866

Time: Date: <u>February 16, 2016</u>

Interview Location:

Interview Format (circle one): In Person Phone Mail Other Email

Interview Category: State Agency

1. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

HMC has been cooperative and responsive to NMED requests for information. HMC has met the requirements of DP-200 since renewal in 2014, and is in compliance with the permit conditions. HMC has made a concerted effort to accelerate groundwater remediation at the Site. HMC has significantly increased their reverse osmosis (RO) system capacity, and have completed pilot testing of a 300-gpm zeolite treatment system and are now planning to implement full-scale treatment at a 1500-gpm capacity. HMC has also drilled several new alluvial and Chinle aquifer wells to increase the extraction of contaminated groundwater from persistent plumes located southeast and west of the Large Tailings Pile (LTP).

2. What is your assessment of the current performance of the remedy in place at the Site?

Since renewal of DP-200 in 2014 HMC has addressed issues with pre-filtration of water entering the existing (Phase 1) 600-gpm RO system allowing that system to operate at full capacity for the first time since construction. Construction of an additional (Phase 2) 600-gpm RO system is complete and currently on-line. Construction of the 1200-gpm zeolite system is also nearly complete. Implementation of the increased RO capacity and use of zeolite treatment technology will result in effective acceleration of the remedy. With the increased treatment capacity, HMC was able to discontinue land application/irrigation of contaminated groundwater four years ago, and flushing of the LTP ended in July 2015.

3. Are you aware of any complaints or inquiries regarding site-related environmental issues or remedial activities from residents in the past five years?

There have been many complaints and inquiries from residents proximal to the Site. These include, but are not limited to concerns over the overall remedial strategy, over-pumping and use of the San Andres/Glorieta aquifer, potential cross-contamination of the San Andres/Glorieta aquifer (from overlying contaminated aquifers), use of zeolite as a viable treatment technology, flushing of the LTP, radon background and monitoring, and the approved groundwater background concentrations (remediation standards). These are just some of the key issues raised by the public.

4. Has your office conducted any site-related activities or communications in the past five years? If so, please describe the purpose and results of these activities.

NMED has had extensive interaction with HMC during the past five years. Prior to 2014 these communications were mostly related to the technical review of the remedy as a component of the renewal process for DP-200. Since approval of DP-200, NMED has had infrequent contact with HMC to insure the requirements of DP-200 are being met.

In addition, HMC's Closure Manager hosts conference calls with all agencies on the first Wednesday of each month to provide updates on remedial progress at the Site.

5. Are you aware of any changes to state laws that might affect the protectiveness of the Site's remedy?

No.

6. Are you comfortable with the status of the institutional controls at the Site? If not, what are the associated outstanding issues?

There is currently a health advisory in place (published in January 2009) that would limit the installation of private wells within the contaminated aquifers. However, the State of New Mexico has no mechanism to enforce institutional controls. As part of the efforts to address cross-contamination of the San Andres aquifer, HMC also completed the plugging and abandonment of the old Murray Acres Association Irrigation well (OSE Permit No. B-5) in December 2014.

7. Are you aware of any changes in projected land use(s) at the Site?

No.

8. Do you have any comments, suggestions or recommendations regarding the management or operation of the Site's remedy?

Over the past several years management of the ground water remedy has improved substantially. Continued movement in this direction is expected in the future.

Site Name: Homestake Mining Co. EPA ID No.: NMD007860935

Interviewer Name: <u>Johnny Zimmerman</u>. Affiliation: <u>Skeo Solutions (EPA</u>

Ward Contractor)

Subject Name: Resident 1 Affiliation: Affected Resident

Subject Contact Information:

Time: 1:00 P.M. Date: <u>January 12, 2016</u>

Interview Location: Kiva Café, Milan, NM

Interview Format (circle one): (In Person) Phone Mail Other:

Interview Category: Residents

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date?

I worked for Homestake off and on in the past. I saw the site in 1958 when operations began. In 1957 I worked for Kerr-McGee and saw Homestake go up and come down. Homestake was using mill solution for cleanup.

2. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

I have some real problems since it has taken 40 years and Homestake is nowhere near clean up. Even when "cleaned up" alluvial is not as clean as when I dug my well in 1964.

3. What have been the effects of this Site on the surrounding community, if any?

There have been a lot of problems. Half of the community that lived in subdivisions worked in uranium. It created friction with those who worked for Homestake and those who don't. We have meetings and EPA comes, we have pro-uranium and anti-uranium groups. I don't mind nuclear power.

4. Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing?

No.

5. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future?

Pretty well, they've had regular meetings and we understand EPA's position. We would prefer if they were in the front seat driving as opposed to the backseat, or not in the car at all as in the beginning. Many locals, including me, drilled our own wells and paid for it ourselves. Then Homestake put in community water and promised to pay for water for 10 years, after which we were supposed to be able to use our wells again. The cleanup has taken longer and we have to pay for potable water. It seems that in 1977 when Homestake got the new project manager, things flatlined. We would like to see the water cleaned up. We keep getting a pushed out date for that. I can't water my lawn because I don't want to pay for the water. We've been promised clean water for 40 years and it's still not done.

6. Do you own a private well in addition to or instead of accessing city/municipal water supplies? If so, for what purpose(s) is your private well used?

Yes, I have a private well, but I haven't used it in years. The state hydro told me it was ok to use outside, but after I watered apple trees, the leaves turned black, so I stopped using it. We also have a San Andres well which we use for irrigation, but it is picking up radionuclides and TDS that wasn't there in the past.

7. Do you have any comments, suggestions or recommendations regarding any aspects of the project?

Hurry up and get the job done. They currently have the Cadillac of all procedures and we wish they had started with this cleanup. Why hasn't this new cleanup been introduced before? It was enlightening to see the first site FYR to see what a big problem we had. We've had responses from EPA recently as it appears to be who's in driver's seat. We don't get responses from NRC in the same way.

EPA ID No.: NMD007860935 Site Name: Homestake Mining Co.

Interviewer Name: Johnny Zimmerman-Affiliation: **Skeo Solutions (EPA** Ward

Contractor)

Resident 2 **Subject Name:** Affiliation: **Affected Resident**

Subject Contact Information:

Time: 1:30 P.M. Date: **January 12, 2016**

Interview Location: Kiva Café, Milan, NM

In Person Phone **Interview Format (circle one):** Mail Other:

Interview Category: Residents

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date?

Yes, I have lived where I am since fall of 1978. Homestake had a pit where they were doing blasting about 11 years ago and I think it broke the seal on my deep, San Andres well. The water level changed from 200 to 80. The last time the well was sampled was in conjunction with the State, EPA and Homestake, there was no power at well, so they brought in a generator. And no one likely wants to go through the hassle again. We haven't used the well for about 10 years. Whenever they extended the water line to us, we tapped in. Not because the well was contaminated but because we were concerned Homestake would eventually screw it up. We intended to use the well for yard and trees, but we'll have to get it sampled. Last samples said it was fine. Two houses down from us has a San Andres well that is contaminated.

2. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

This has been going on for 40 years, or at least the contamination has been known for more than 40 years. The first 25 years of the program was not done in earnest, seemed to be a lot of window dressing and smoke screens. In the 1980s, the Homestake manager told him he was told to do as little, spend as little as possible. At the time I was the general manager for Kerr-McGee. We know that a lot of early work was poorly done; injections weren't deep enough. When they decided on injection and extraction, the wells drove the pollution further out. The geology is complex. The location of the Homestake Mill was picked for political reasons, to provide jobs and income for the county. It was a bad placement of a mill. They also made mistakes with their treatment process, they used carbonate leach, but it should've been an acid leach. The mill was labor intensive and used a split circuit to treat.

3. What have been the effects of this Site on the surrounding community, if any?

The word "devastation" is used a lot and may be overused. It's hard to say what property values would've been if there was no contamination. I think my place is worth less than half of what it would be without contamination. People living closest to the site (i.e., in Murray Acres) have a high incidence of cancers, which his likely related to the mill, but it's hard to prove. There have been financial and physical effects on the community.

4. Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing?

There have been a few incidents in the past. From other community members, we heard of a breach of impoundments that flowed through Murray Acres. There was also a dustup with an agricultural contractor regarding some cattle grazing.

5. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future?

In the last few years it has been much better. In the past, EPA's involvement was pretty low key. NRC has not been supportive or communicating well with us. We're ok with how EPA communications are going now.

6. Do you own a private well in addition to or instead of accessing city/municipal water supplies? If so, for what purpose(s) is your private well used?

Yes, see #1.

7. Do you have any comments, suggestions or recommendations regarding any aspects of the project?

In my honest opinion, they will never ever be able to clean the water to usable limits. You'll never get them down to drinking water standards and there will always be contamination in the alluvial. We're concerned Homestake will get a pass from NRC, it will be transferred to DOE, and then they'll realize, like Anaconda or Kerr-McGee, that isn't actually done. Alternatively, we could be bought out and moved. But where do you draw the line, who has been impacted enough, etc. We're doubtful we'd be bought out and moved. We'll keep paddling up a creek with a broken paddle and we'll do this again in 5 years. I think progress is being made, but it is slow. The government entities need to make Homestake pay for our water going forward. We were promised it would be cleaned up in 10 years, but it's not and we can't even grow gardens because we have to pay for water. It has destroyed the value of our belongings.

Site Name: Homestake Mining Co. EPA ID No.: NMD007860935

Interviewer Name: Johnny Zimmerman-**Affiliation: Skeo Solutions (EPA**

Contractor)

Ward **Subject Name:** Resident 3 Affiliation: **Affected Resident**

Subject Contact Information:

Time: 2:00 P.M. Date: **January 12, 2016**

Interview Location: Kiva Café, Milan, NM

In Person **Interview Format (circle one):** Phone Mail Other:

Interview Category: Residents

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date?

Yes, I know a good deal, but probably not everything as I moved to the area in January of 2001. I live 2 miles from the plant and about 1.5 miles from the ponds.

2. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

I have a background in psych and science and have worked with companies like GE/Westinghouse in the past with zirconium chemicals. When I was interested in the property I bought here, I was warned by others about potential contamination in the area. I researched Homestake on the EPA web site, which was my main source of information. I also asked around town. No one seemed to know a lot. What I read online was that only the alluvial was contaminated and it would be clean by 2003 and that contamination was only around the plant. Then there was not much going on until about 2005 when the company came back in. A realtor came to me and asked me to sell, but I didn't. Then someone came by and told me about an upcoming mining meeting. This was after that community meeting at the gym that got heated between the pro and anti- uranium folks. I participated in the meeting and since then it has been one huge disappointment after another. Additional aquifers are not contaminated and information has gone downhill, not just with Homestake. I joined BVDA and participated in other meetings and did a lot of online research. I did nuclear fuel chain research. Mining and the local issues are just the beginning of the spectrum as you get to nuclear weapons. Now no one knows how to dispose of waste. I was impressed with the information provided by the two men considering reopening the Mt. Taylor mine. They had considered many of the potential problems and issues we brought up. We have great reservations about reopening Mt. Taylor. Look at what happened at Three Mile Island, Chernobyl and Fukushima. Fukushima seems to have killed mining interest. Seems the problem is being chased instead of getting in front of it. Getting involved here has made me more aware of other issues. Other folks have been here much longer than me and done much more. I don't see myself as an adversary, but as a partner. I think they should see if it's possible to clean up this area before opening a new one.

3. What have been the effects of this Site on the surrounding community, if any?

It has divided us. Our properties are contaminated. I had soil removed from my property, but they didn't do a complete job. I had windblown sand against the fence, and they did the inside of the fence, but not the dune at the fence, so now it just blows back in. It took 2 years to get the yard cleanup started and 3 hours to clean yard. The background level area was moved and that affected the amount that was cleaned up. I'm concern that the point they picked had contaminated soils wash down from the valley and it provided a ponding area of sediments that had artificially high contamination.

4. Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing?

Haven't heard of any. In the past year, there has been drilling south of me and we've been suggesting they get monitoring wells out in front of the plume, so I'm not surprised to see that the plumes seem to be moving. We've found out Homestake is building a new reverse osmosis plant. This all shows that they are chasing after the plume. We're concerned they'll keep the numbers low, hand off the project to DOE and it will rebound. New strategies triggered by hearing previous plans didn't work. Seems like they've ramped up with the reverse osmosis and the zeolite. I think what they're doing could be making the plume bigger, although maybe weaker at the same time, and the pumping may suck water out of the tailings piles.

5. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future?

Meeting with Homestake and EPA was good and I was impressed with information presented at last meeting about Mt. Taylor.

6. Do you own a private well in addition to or instead of accessing city/municipal water supplies? If so, for what purpose(s) is your private well used?

Yes, I have a well that is inside my building but I don't use it. I think it is disconnected. I ran across a letter alerting the manager (who previously occupied my building) of the possible contamination of the well. I think the land is subsiding as the well casing is sticking out of the ground more than it used to.

7. Do you have any comments, suggestions or recommendations regarding any aspects of the project?

I think they need to keep trying to get ahead of the contamination and try to communicate better. New wells were new to me when I saw them drilling. Their location makes me realize that the contamination is now past my property and it's obviously moved beyond the hydraulic barrier and down Thunderbid Road. Homestake hired a public relations person, which was helpful. I had lots of respect for the Mt Taylor guys as they seemed even keeled. I see us as community partners with Homestake and I would like to see them step up operations as much as they can. They added evaporation pond 3, but it wasn't big enough. They keep chasing and need to get ahead of it. They should set up an operation that could be turned back on when DOE took over. What happens if it rebounds?

Site Name: Homestake Mining Co. EPA ID No.: NMD007860935

Interviewer Name: <u>Johnny Zimmerman-</u> Affiliation: <u>Skeo Solutions (EPA</u>

Contractor)

Subject Name: Resident 4 Affiliation: Affected Resident

Subject Contact Information:

Ward

Time: <u>1:30 P.M.</u> Date: <u>February 5, 2016</u>

Interview Format (circle one): In Person (Phone) Mail Other:

Interview Category: Residents

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date?

I am aware of the attempted cleanup activities; but there have been no successful cleanup activities to date.

2. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

This is a ludicrous question. They have been supposedly trying to clean this up for 40 years now and all they have done is dilute it. Even after the USGS folks told them flushing wasn't working and wasn't an appropriate method for cleanup, they continued to flush. We had to fight to get that USGS remedial evaluation study underway and they didn't heed it. This is probably one of the worst cleanups in the country.

3. What have been the effects of this Site on the surrounding community, if any?

According to EPA's own recent report, we've been exposed to way more than the acceptable radon risk in ambient air. Bulldozers scraped some contaminated soils back up on the pile and we were told the radon was cleaned up, but we found a lot of our houses were still very high in radon. We have lived with that for years. This is not just a problem for our generation, but also for future generations. Studies have shown it affects genes and successive generations. We're concerned about ours and future generations. It is a travesty that this is still going on. And this is just the air we're talking about, what about the years that kids played in tailings piles and families drank contaminated groundwater. We've been living in a soup of contamination.

4. Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing?

No.

5. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future?

Yes, they tell us what they're not doing and what they can't do. I want them to help us help them find a solution. We've done a lot as a community, such as hired experts, etc. We've helped them more than other communities have done and still they're telling us what can't be done.

6. Do you own a private well in addition to or instead of accessing city/municipal water supplies? If so, for what purpose(s) is your private well used?

Yes, it's used for irrigation. I can't drill a domestic, livestock or garden well because water I would drill into is contaminated.

7. Do you have any comments, suggestions or recommendations regarding any aspects of the project?

Yes, I think Sam Coleman and Ron Curry need to quit talking and start acting. We've listened to them and we get surveys and studies and reports and we get absolutely no action. Every minute there is no action people are breathing in a radon soup.

Site Name: Homestake Mining Co. EPA ID No.: NMD007860935 Affiliation:

Interviewer Name:

Subject Name: Jesse R. Toepfer

Subject Contact Information: 505.290.3067

Time: Date:

Interview Location:

Interview Format (circle one): Phone Other:(Email In Person Mail

HMC

Affiliation:

Interview Category: 0&M

1. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

Homestake continues to make strident gains with regard to its water remediation activities. I have a high degree of confidence that we are on the right track, and that we have made significant progress over the past 5 years.

2. What is your assessment of the current performance of the remedy in place at the Site?

I believe it is soundly based in science, and it is effective.

3. What are the findings from the monitoring data? What are the key trends in contaminant levels that are being documented over time at the Site?

The monitoring data over the past 15 years supports the remediation efforts. The constituents of concern (COCs), including selenium, uranium, and molybdenum, are showing significant reductions in accordance with the site's remediation strategy.

4. Is there a continuous on-site O&M presence? If so, please describe staff responsibilities and activities. Alternatively, please describe staff responsibilities and the frequency of site inspections and activities if there is not a continuous on-site O&M presence.

There is a continuous O&M presence. Homestake's staff and crew check the site's conveyance pipelines, evaporation ponds and water treatment systems multiple times a day. On the weekends, a crew technician is assigned "water watch," and is required to patrol the site, check on the water treatment systems and is "oncall" should any of those systems come offline. The site's environmental technicians are trained to perform a multitude of electromechanical activities necessary for the ongoing remediation efforts. Supervision of site activities is performed by the Closure Manager, the Project Superintendent and the Senior Engineer.

5. Have there been any significant changes in site O&M requirements, maintenance schedules or sampling routines since start-up or in the last five years? If so, do they affect the protectiveness or effectiveness of the remedy? Please describe changes and impacts.

Homestake has a few new systems that have been implemented over the past 5 years: a new zeolite water treatment system, an improved RO water treatment plant and an expanded well-field. Homestake is additionally pursuing a pilot study using Tripolyphosphate (TPP), but as this is still just a pilot study, it does not represent a commissioned system in actual service. The Homestake staff and crew have been trained to manage and operate these new systems, and where applicable, new procedures and maintenance requirements have been implemented. Sampling routines remain consistent with the requirements set forth in the NRC License and NMED Discharge Permit. These changes have a significantly positive effect on the protectiveness of the remedy as they have enabled Homestake to treat more impacted water at a faster rate.

6. Have there been unexpected O&M difficulties or costs at the Site since start-up or in the last five years? If so, please provide details.

No.

- 7. Have there been opportunities to optimize O&M activities or sampling efforts? Please describe changes and any resulting or desired cost savings or improved efficiencies.
 - Homestake continues to seek out ways to streamline and optimize its operations. Upgrades to the RO water treatment plant and well-field, as well as an on-going transition to computer-based monitoring and recording continue to have an increasingly positive effect on sampling efforts and O&M activities.
- 8. Do you have any comments, suggestions or recommendations regarding O&M activities and schedules at the Site?

Homestake continues to work with regulators to ensure the Sit is being remediated and managed in accordance with the NRC License and NMED Discharge Permit.

APPENDIX G -DETAILED DATA ANALYSIS

Table G-1: Exceedances of Site Standards for COCs by Aquifer, 2014

Aquifer	COCs with Exceedances	Location(s) of Exceedance				
	Sulfate	Area and of Walla Wards				
	Chloride	Area east of Valle Verde;				
	TDS	Area close to LTP and STP				
		Collection area near tailings;				
		Two wells in northern Felice Acres;				
	Uranium	Several wells in southern Felice Acres;				
		One well in Murray Acres				
Alluvial Aquifer	Selenium	Collection area near LTP and STP				
	z etement	Area near LTP and STP;				
	Molybdenum	Southeast of the STP;				
	17101y odeliain	Area in central Section 27 (west of LTP)				
		Area north and west of LTP;				
	Nitrate	Small area southeast of Valle Verde				
	Radium-226 and Radium-228	Immediately under the LTP				
	Thorium-230	Immediately under the LTP				
	Sulfate	Inimediately under the LTF				
		W. II				
	Chloride	Wells near or on the LTP				
-	TDS	1 7 777				
	Uranium	Area near the LTP and collection ponds				
		Four wells north and in Broadview and Felice Acre				
Upper Chinle	Selenium	Mixing zone near LTP and collection ponds;				
Aquifer		Two wells in non-mixing zone				
11401101		Several wells near the tailings and south of Collection				
	Molybdenum	ponds;				
		Two wells north of Broadview Acres				
	Nitrate	Two wells in the LTP area				
	Radium-226 and Radium-228	Few wells in western portion of LTP				
	Vanadium	One well near the LTP				
	Sulfate	Four wells in mixing zone area				
	Chloride	Three wells west of West Fault;				
	Chloride	One well in Murray Acres				
		Three wells in Felice Acres;				
	TDC	One well in Broadview Acres;				
	TDS	One well in Murray Acres;				
MC 141 - CL 1-1		Four wells west of West Fault				
Middle Chinle		Mixing zone wells in western portion of Felice Acre				
Aquifer	II	Non-mixing zone wells in western portion of				
	Uranium	Broadview Acres;				
		Several wells west of West Fault				
		Wells 481 and 493 in Felice Acres;				
	Selenium	Wells CW17, CW56, CW61, CW62, CW71 and CW				
		in mixing zone				
	Molybdenum	Several wells west of West Fault				
	Sulfate					
	Chloride	Far downgradient wells				
Lower Chinle	TDS					
Aquifer	100	Six wells located near the subcrop of the Lower Chir				
riquiror	Uranium	aquifer with the alluvial aquifer;				
	Gianium	Two non-mixing zone wells				
		I wo non-mixing zone wens				

Table G-2: Quantities of Constituents Collected (Source: 2014 Annual Monitoring Report)

TABLE 2.1-1. QUANTITIES OF CONSTITUENTS COLLECTED.

YEAR	SOURCE	TOTAL VOLUME PUMPED	SULFATE CONC.			UR ANIUM (U) CONC. AMT.		MOLYBDENUM (MO) CONC. AMT.		SELENIUM (SE) CONC. AMT.	
		(GAL)	(MG/L)	(LB)	(MG/L)	(LB)	(MG/L)	(LB)	(MG/L)	(LB)	
4070	e.w	275 700 22	5700	*200520	35	0004	40	0225	-		
1978 1979	G.W.	27670033 46371629	5200 5200	1200620 2012095	35 35	8081 13543	40 40	9236 15478	2	462 774	
1980	G.W.	39385860	5200	1708978	35	11503	40	13146	2	657	
1981	G.W.	91613183	5200	3975155	35	26756	40	30578	2	1529	
1982	G.W.	159848025	5200	6935910	35	46684	40	53353	2	2668	
1983	G.W.	167018540	5200	7247043	35	48778	40	55746	2	2787	
1984 1985	G.W.	203258522 194074421	5200 5200	8819519 8421015	35 35	59362 56680	40 40	67842 64777	2 2	3392 3239	
1986	G.W.	199326030	5200	8648886	35	58214	40	66530	2	3326	
1987	G.W.	180881740	5200	7848576	35	52827	40	60374	2	3019	
1988	G.W.	166460826	5200	7222843	35	48615	40	55560	2	2778	
1989	G.W.	175780800	5200	7627243	35	51 337	40	58671	2	2934	
1990	G.W.	164378919	5200	7132508 7441397	35	48007	40	54865	2	2743	
1991 1992	G.W.	171497720 128398849	5200 4925	5276234	35 27.2	50086 29134	40 35.9	57242 38419	1.60	2862 1718	
1992	TOE	8544670	12117	864006	53.2	3793	106.5	7595	1.73	123	
1993	G.W.	115795020	5011	4841203	28.1	27130	45.4	43885	1.47	1425	
1993	TOE	18357680	12117	1856262	53.2	8150	106.5	16315	1.73	265	
1994	G.W.	98294087	4423	3624762	26.0	21146	27.3	22349	1.42	1162	
1994	TOE	18337680	12117	1854240	53.2	8141	106.5	16299	1.73	264	
1995	G.W.	108306398	3256	2942827	16.1	14553	19.2	17355	1.65	1491	
1995 1995	TAILS	17711370 5905740	11 370 8191	1680500 403680	54.6 36.1	8069 1778	94.4 89.7	13952 4420	2.25 0.15	332	
1996	G.W.	122064160	3899	3967919	20.9	21225	26.8	27259	1.92	1950	
1996	TOE	15431810	11537	1484295	46.4	5970	105.0	13509	1.29	166	
1996	TAILS	9181390	9434	722129	40.2	3077	108.0	8236	0.18	14	
1997	G.W.	94465562	4955	3836678	26.9	20892	33.4	25887	3.17	2456	
1997	TOE	12029390	11094	1113808	41.8	419	100.0	10040	0.81	81	
1997 1998	G.W.	21292900 74459130	10284 5088	1827575 3161866	45.8 29.6	8139 18385	92.4 34.8	16420 21625	0.14 1.85	25 1151	
1998	TOE	10321780	9870	850257	42.5	3665	95.2	8203	0.73	63	
1999	G.W.	117752408	3363	3305027	16.6	16314	14.8	14545	2.06	2024	
1999	TOE	8809890	11560	849976	54.3	3993	106.0	7794	0.46	34	
1999	TAILS	120550	9420	9478	40.9	41	111.5	112	0.19	0	
2000	G.W.	146609842	3358	4108868	18.8	23004	20.6	25206	1.94	2374	
2000 2000	TOE	8032870 12446810	9734 9710	652590 1008685	58.6 37.8	3929 3927	118.0 127.0	7911 13193	0.34	23 31	
2000	G.W.	144925056	2770	3350438	19.6	23707	21.4	25884	1.65	1996	
2001	TOE	9606280	9935	796529	43.1	3455	95.7	7673	0.78	63	
2001	TAILS	31465370	8688	2281555	34.6	9086	89.2	23425	0.19	50	
2002	G.W.	201357360	2748	4618092	14.9	25040	16.7	28065	1.23	2067	
2002	TOE	17975520	9210	1381718	33.4	5011	88.7	13307	0.76	114	
2002	TAILS	17817840	7670	1140588	23.5	3495	40.8	6067	0.12	18	
2003 2003	G.W. TOE	177727419 28418871	2417 9457	3585168 2243048	13.8 35.6	20470 8444	15.5 78.9	22991 18714	0.73 4.35	1083 1032	
2003	TAILS	8890076	9800	727126	28.0	2078	92.0	6826	0.30	22	
2004	G.W.	154422720	2272	2931913	11.3	14633	16.6	21386	0.79	1017	
2004	TOE	26720928	8007	1787722	31.9	7115	67.6	15102	2.78	622	
2004	TAILS	44745696	6360	2377848	23.1	8637	60.9	22769	0.20	75	
2005	G.W.	130810679	2478	2705346	11.8	12883	15.5	16922	0.59	644	
2005	TOE	20704320	8228	1421784	43.5	7517	87.5	15120	2.63	454	
2005 2006	G.W.	45685786 132406109	4389 1990	1673497 2199072	18.7 9.6	7130 10609	56.3 14.3	21467 15802	0.18	69 807	
2006	TOE	20374782	7432	1263796	38.0	6462	76.2	12958	1.09	185	
2006	TAILS	43707760	4278	1560550	17.6	6420	51.9	18932	0.14	51	
2007	G.W.	137707200	2420	2781316	10.3	11838	16.7	19193	0.52	598	
2007	TOE	25037779	6829	1427024	31.9	6666	67.3	14063	1.20	251	
2007	TAILS	24561680	4130	846616	19.9	4079	61.1	12525	0.15	31	
2008	G.W. TOE	137145174	2672 7847	3058408	11.5	13163 6894	16.5 68.5	18886 14945	0.61	698	
2008 2008	TAILS	261 408 50 59 50 32 4	7847 4671	1711992 231968	31.6 16.0	6894 795	68.5 42.8	2126	1.58 0.24	345 12	
2009	G.W.	131564160	3145	3453318	15.5	17020	19.1	20660	0.85	933	
2009	TOE	27238830	7792	1771396	35.0	7957	69.9	15891	0.81	184	
2009	TAILS	29403070	3850	944782	13.7	3362	38.6	9472	0.24	59	
2010	G.W.	125785118	2793	2932099	12.9	13542	16.6	17427	0.64	672	
2010	TOE	18444330	6848	1054156	32.9	5065	52.1	8020	0.51	79	
2010	TAILS	12953960 132573855	3018	326287 3217590	9.4	1016	33.5	3622 24895	0.19	1361	
2011 2011	G.W. TOE	14777020	2908 6747	832101	14.4 29.9	15933 3688	22.5 53.2	6561	0.44	1361 54	
2011	TAILS	54713150	2887	1318308	10.5	4795	33.5	15297	0.18	82	
2012	G.W.	143304728	3070	3671785	13.4	16027	16.8	20093	0.62	742	
2012	TOE	12201316	6476	659465	26.8	2729	48.9	4980	0.43	44	
2012	TAILS	56486600	2632	1240823	8.9	4196	26.2	12352	0.17	80	
2013	G.W.	122813790	2793	286 2836	12.5	12813	16.2	16605	0.73	748	
2013	TOE	9211575	6453	496105	26.7	2053	53.3	4098	0.35	27	
2013 2014	G.W.	31489800 124070324	2448 2570	643368 2661212	7.5 11.4	1971 11805	23.6 15.8	6202 16361	0.12	652	
2014	TOE	9427490	5683	447149	21.2	1668	46.0	3619	0.03	12	
2014	TAILS	24487100	2788	569782	7.8	1594	27.1	5538	0.16	33	
		4,990,325,396		165,335,766		991,736		1,185,099		62,939	
IM G.W.											
JM G.W. JM TOE		383,857,031		28,499,920		120,851		256,667		4,816	
		383,857,031 481,305,602 5,855,488,029		28,499,920 19,854,647 213,690,333		120,851 75,615 1,188,202		256,667 209,002 1,650,768		4,816 710 68,465	

NOTE: Average concentrations for 1978 to 1991 were used in calculating the quantities of constituents removed. Concentrations from the collection wells have gradually decreased from 1978 through 1991.

G.W. = Ground water; TOE = Toe drains on edge of tailings; TAILS = Large tailings collection wells

6465.16 6467.94 • 6471.69 NOS MAP, SEE FIGURE 4.2-1C JARGE-TAILINGS-PILE (RECLAMATION IN PROGRESS) 154350 100 ACRE CENTER PIVOT OS MAP, SEE FIGURE 4.2-1A PLEASANT VALLEY ESTATES 1541500 MURRAY ACRES 6530.35 6542.69 6539.72 6528.65 6537.97 153950 VALLE VERDE 652717 6519.73 503.86 BROADVIEW ACRES FLOOD TRRIGATION 120 AC FLOOD 150 AC CENTER PIVET 6508.68 FELICE-ACRES 6459.76
174 AC
CENTER PIVOT
AND FLOOD IRRIGATION SOS MAP, SEE / FIGURE 4.2-10 6442.46 6473.67 6468.28 6477.02 6479.22 6475.41 6474.82 °6481.99 6453,75 6454.11 ALLUVIAL AQUIFER 475400 481400 487,400 489,400 SCALE: 1"=1600' C:\PROJECTS\ 2015-06 FIGURE 4.2-1. WATER-LEVEL ELEVATIONS OF 1600QAL14 DATE: 3/10/15 THE ALLUVIAL AQUIFER, FALL 2014, FT-MSL

Figure G-1: Groundwater Flow Direction – Alluvial Aquifer (Source: 2014 Annual Monitoring Report/Performance Review)

Figure G-2: Groundwater Flow Direction – Upper Chinle Aquifer (Source: 2014 Annual Monitoring Report/Performance Review)





Figure G-3: Groundwater Flow Direction – Middle Chinle Aquifer (Source: 2014 Annual Monitoring Report/Performance Review)



1545500 -1545500 COUNTY ROAD 63 26/2 LARGE-TAILINGS-PILE (RECLAMATION IN PROGRESS) € •3 6467.32 1543500 1543500 PLEASANT-VALLEY ESTATES 1541500 1541500 COUNTY ROAD 25 32¹33 MURRAY ACRES 27 26 26₁25 35 36 1539500 VALLE VERDE BROADVIEW ACRES -6480 1537500 153750 FELICE-ACRES 1535500 153550 --LEGEND--LOWER CHINLE WELLS ●6481.99 UNSATURATED ALLUVIUM SATURATED ALLUVIUM FIGURE 7.2-1 WATER LEVEL ELEVATIONS
OF THE LOWER CHINLE AQUIFER,
2014, FT-MSL

Figure G-4: Groundwater Flow Direction – Lower Chinle Aquifer (Source: 2014 Annual Monitoring Report/Performance Review)

6426.0 23 24 26/23 0//fbx LARGE-TAILINGS-PILE 1543500 1543500 1541500 CROSS SECTION LOCATION 32 33 29 28 1539500 VALLE VERDE BROADVIEW ACRES FELICE-ACRES --LEGEND--SAN ANDRES VELL SUBCROP OF SAN ANDRES SCALE: 1" = 1600' FIGURE 8.0-1. LOCATION OF SAN ANDRES WELLS AND WATER-LEVEL ELEVATION FOR THE SAN ANDRES AQUIFER, 2014, FT-MSL C:\PROJECTS\2015-06\
1600SAN bmw

DATE: 3/13/2015

Figure G-5: Groundwater Flow Direction – San Andres Aquifer (Source: 2014 Annual Monitoring Report/Performance Review)

Figure G-6: Selenium Concentrations in the Alluvial Aquifer - 1999 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-7: Selenium Concentrations in the Alluvial Aquifer - 2014 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-8: Uranium Concentrations in the Alluvial Aquifer - 1999 (Source: 2014 Annual Monitoring Report/Performance Review) LARGE-TAILINGS-PILE 1541500 1541500 153950 BROADVIEW ACRES FELICE-ACRES LEGEND ALLUVIAL AQUIFER SCALE: 1"=1600'
C:\PROJECTS\ 2015-08
HEATMAPQAL
DATE: 3/17/2015 FIGURE 1.1-10. ALLUVIAL URANIUM CONCENTRATIONS, 1999




Figure G-10: Uranium Concentrations in the Upper Chinle Aquifer - 1999 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-11: Uranium Concentrations in the Upper Chinle Aquifer - 2014 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-12: Uranium Concentrations in the Middle Chinle Aquifer - 1999 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-13: Uranium Concentrations in the Middle Chinle Aquifer - 2014 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-14: Uranium Concentrations in the Lower Chinle Aquifer - 1999 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-15: Uranium Concentrations in the Lower Chinle Aquifer - 2014 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-16: Uranium Concentrations at POC Well S4 (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 4.3-55. URANIUM CONCENTRATIONS FOR WELLS S2, S4, S12 AND SM.

Figure G-17: Uranium Concentrations at POC Well D1 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-18: Molybdenum Concentrations at POC Well S4 (Source: 2014 Annual Monitoring Report/Performance Review)




Figure G-19: Molybdenum Concentrations at POC Well D1 (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 4.3-91. MOLYBDENUM CONCENTRATIONS FOR WELLS B12, D1, S28 AND S38.

Figure G-20: Molybdenum Concentrations at POC Well X (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 4.3-94. MOLYBDENUM CONCENTRATIONS FOR WELLS K9, K10, K11 AND X.

Figure G-21: Uranium Concentrations at POCs CE2 and CE8 (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 5.3-12. URANIUM CONCENTRATIONS FOR MIXING ZONE WELLS 494, CE2, CE5, CE8, CE12, AND CW50

Figure G-22: Molybdenum Concentrations at POCs CE2 and CE8 (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 5.3-18. MOLYBDENUM CONCENTRATIONS FOR MIXING ZONE WELLS 494, CE2, CE5, CE8, CE12, AND CW50

Figure G-23: Uranium Concentrations in Tailings Solution, 2000 (Source: 2014 Annual Monitoring Report/Performance Review)




FIGURE 2.1-9, TAILINGS SOLUTION URANIUM CONCENTRATION, 2000




Figure G-24: Uranium Concentrations in Tailings Solution, 2014 (Source: 2014 Annual Monitoring Report/Performance Review)

FIGURE 2.1-12. TAILINGS SOLUTION URANIUM CONCENTRATION, 2014

PROJECTS\2015-06\DWG\UNAT_TAILS

SCALE: 1" = 500'




Figure G-25: Locations of 2014 Soil/Debris Removal Actions





Figure G-26: Radon Monitoring Locations (Source: 2014 HHRA)





APPENDIX H -SITE INSPECTION CHECKLIST

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST							
I. SITE INFORMATION							
Site Name: Homestake Mining Company Date of Inspection: 01/12/2016							
Location and Region: Cibola County, New Mexico/Region 6 EPA ID: NMD007860935							
Agency, Office or Company Leading the Five-Year Review: EPA Region 6	Weather/Temperature: 20s and clear						
Remedy Includes: (Check all that apply) Landfill cover/containment Monitored natural attenuation Access controls Ground water containment Institutional controls Vertical barrier walls Ground water pump and treatment Surface water collection and treatment Other:							
Attachments:	☐ Site map attached						
II. INTERVIEWS	(check all that apply)						
1. O&M Site Manager Name Interviewed at site at office by phone Please Problems, suggestions Report attached:	Title Date						
Name	Interviewed at site at office by phone Phone:						
	Agencies (i.e., state and tribal offices, emergency blic health or environmental health, zoning office, es). Fill in all that apply.						
Agency Contact Name Tit Problems/suggestions Report attached:							
AgencyNameTit Problems/suggestions Report attached:							
Agency Contact Name Tit Problems/suggestions Report attached:							
Agency Contact Name Tit Problems/suggestions \[\] Report attached:							

4.	Agency Contact Name Problems/suggestions Repor		Date	Phone No.	
1	III. ON-SITE DOCUME	ENTS AND RECO	RDS VERIFIED (chec	k all that apply)	
1.	O&M Documents	7 D 4:1:1-k1-	M Ha to dota	ПΝ	/ A
	_	Readily available	☐ Up to date	<u> </u>	/A
		Readily available	☐ Up to date	_	/A
		Readily available	☐ Up to date	∐ IN	/A
2.	Remarks: Site-Specific Health and Safe	aty Plan	Readily available	Up to date	□ N/A
2.	Contingency plan/emergen	·	Readily available	Up to date	□ N/A
	plan	icy response	Keadily available	⊠ op to date	17/21
	Remarks:				
3.	O&M and OSHA Training I	Records	Readily available	Up to date	N/A
	Remarks:				
4.	Permits and Service Agreem	nents			
	Air discharge permit		Readily available	Up to date	⊠ N/A
	☐ Effluent discharge		Readily available	Up to date	□ N/A
	☐ Waste disposal, POTW		Readily available	Up to date	⊠ N/A
	Other permits:		Readily available	Up to date	□ N/A
	Remarks:				
5.	Gas Generation Records		Readily available	Up to date	⊠ N/A
	Remarks:				
6.	Settlement Monument Reco	rds	Readily available	Up to date	⊠ N/A
	Remarks:				
7.	Ground Water Monitoring I	Records	Readily available	Up to date	□ N/A
	Remarks:				
8.	Leachate Extraction Record	ls	Readily available	Up to date	□ N/A
	Remarks:				
9.	Discharge Compliance Reco	rds			
	Air	Readily available	Up to date	□N	/A

	Water (effluent)	Readily availab	le Ul	p to date	□ N/A				
	Remarks:								
10.	Daily Access/Security	Logs	Readily ava	ailable 🔲 U	Up to date N/A				
	Remarks:								
	IV. O&M COSTS								
1.	O&M Organization								
	State in-house		Contractor for	r state					
	PRP in-house		Contractor for	r PRP					
	Federal facility in-ho	ouse	Contractor for	r Federal facili	ity				
2.	O&M Cost Records								
	Readily available		Up to date						
	☐ Funding mechanism	agreement in place	Unavailable						
	Original O&M cost estimate: Breakdown attached								
	Total annual cost by year for review period if available								
	From:	Го:		Breakde	own attached				
	Date	Date	Total cost						
	From:	Го:		Breakde	own attached				
	Date	Date	Total cost						
	From:	Го:		Breakde	own attached				
	Date	Date	Total cost						
	From:	Го:		Breakde	own attached				
	Date	Date	Total cost						
	From:	Го:		Breakde	own attached				
	Date	Date	Total cost						
3.	Unanticipated or Unusu	ally High O&M Costs	s during Review I	Period					
	Describe costs and reason	ns:							
	V. ACCESS AN	D INSTITUTIONAL	CONTROLS [>	Applicable	□ N/A				
A. Fen	cing								
1.	Fencing Damaged	Location shown o	n site map	Gates secured	⊠ N/A				
	Remarks:								
B. Oth	er Access Restrictions								
1.	Signs and Other Securit	ty Measures	☐ Location	shown on site	map N/A				
	Remarks: HMC property	includes an office build	ding, maintenance	storage buildi	ngs, water towers,				
	tailings piles, evaporation ponds, collection ponds and an RO water treatment plant. The office								

building and maintenance/storage buildings are surrounded by a chain-link fence which is unlocked	onl <u>y</u>							
during business hours. The remainder of the property is surrounded by barbed-wire fencing.								
C. Institutional Controls (ICs)								
1. Implementation and Enforcement								
Site conditions imply ICs not properly implemented	<u> </u>							
Site conditions imply ICs not being fully enforced								
Type of monitoring (e.g., self-reporting, drive by):								
Frequency:								
Responsible party/agency:								
Contact								
Name Title Date Phone no.								
Reporting is up to date	4							
Reports are verified by the lead agency	A							
Specific requirements in deed or decision documents have been met Yes No No	A							
Violations have been reported ☐ Yes ☐ No ☒ N/	A							
Other problems or suggestions: Report attached								
2. Adequacy ☐ ICs are adequate ☐ ICs are inadequate ☐ N/A								
Remarks: Institutional controls (ICs) are not yet in place within the NRC licensed boundary. There is an advisory for new well installations in the area. Under the IC put into place in 2009, NMED requires the New Mexico Office of the State Engineer to issue a health advisory to every person who applies for a well permit within the area referenced in the drinking water advisory; the advisory was published in two newspapers of general circulation in Cibola and McKinley counties. HMC is also required to conduct an annual land use survey to determine if properties are connected to public water or use private water supply.								
suppry.	t an							
D. General	t an							
	t an							
D. General 1. Vandalism/Trespassing ☐ Location shown on site map ☐ No vandalism evident	t an							
D. General 1. Vandalism/Trespassing ☐ Location shown on site map ☐ No vandalism evident Remarks:	t an							
D. General 1. Vandalism/Trespassing ☐ Location shown on site map ☐ No vandalism evident Remarks: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	t an							
D. General 1. Vandalism/Trespassing ☐ Location shown on site map ☐ No vandalism evident Remarks: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	t an							
D. General 1. Vandalism/Trespassing □ Location shown on site map □ No vandalism evident Remarks: □ N/A 2. Land Use Changes On Site □ N/A Remarks: □ N/A	t an							
D. General 1. Vandalism/Trespassing □ Location shown on site map □ No vandalism evident Remarks: □ N/A 2. Land Use Changes On Site □ N/A Remarks: □ N/A Remarks: □ N/A Remarks: New shed company across the street from the Site.	t an							
D. General 1. Vandalism/Trespassing □ Location shown on site map ⊠ No vandalism evident Remarks: □ □ □ N/A 2. Land Use Changes On Site ⊠ N/A Remarks: □ □ N/A 3. Land Use Changes Off Site □ N/A Remarks: New shed company across the street from the Site. VI. GENERAL SITE CONDITIONS A. Roads ☑ Applicable □ N/A	t an							
D. General 1. Vandalism/Trespassing □ Location shown on site map □ No vandalism evident Remarks: □ N/A 2. Land Use Changes On Site □ N/A Remarks: □ N/A 3. Land Use Changes Off Site □ N/A Remarks: New shed company across the street from the Site. VI. GENERAL SITE CONDITIONS A. Roads □ Applicable □ N/A	t an							
D. General 1. Vandalism/Trespassing Remarks: Location shown on site map No vandalism evident Remarks: 2. Land Use Changes On Site Remarks: N/A 3. Land Use Changes Off Site Remarks: New shed company across the street from the Site. VI. GENERAL SITE CONDITIONS A. Roads Applicable N/A 1. Roads Damaged Location shown on site map Roads adequate N/A	t an							

	VII. LANDFILL COVERS Applicable N/A					
A. Land	dfill Surface					
1.	Settlement (low spots)	Location shown on site map	Settlement not evident			
	Arial extent:		Depth:			
	Remarks:					
2.	Cracks	Location shown on site map	☐ Cracking not evident			
	Lengths:	Widths:	Depths:			
	Remarks:					
3.	Erosion	Location shown on site map	Erosion not evident			
	Arial extent:		Depth:			
	Remarks:					
4.	Holes	Location shown on site map				
	Arial extent:		Depth:			
	Remarks:					
5.	Vegetative Cover	⊠ Grass	Cover properly established			
	☐ No signs of stress	☐ Trees/shrubs (indicate size and loc	cations on a diagram)			
	Remarks: Site had snow on it at time of site inspection.					
6.	Alternative Cover (e.g., an	rmored rock, concrete)	□ N/A			
	Remarks: In good condition on slopes.					
7.	Bulges	Location shown on site map	Bulges not evident			
	Arial extent:		Height:			
	Remarks:					
8.	Wet Areas/Water	Wet areas/water damage not ev	vident			
Damag		Transformation and a second	A.S.I. and and			
	☐ Wet areas	Location shown on site map				
	☐ Ponding	Location shown on site map	Arial extent:			
	Seeps	Location shown on site map	Arial extent:			
	Soft subgrade	Location shown on site map	Arial extent:			
0	Remarks:	□ qr.i				
9.	Slope Instability	Slides	Location shown on site map			
	No evidence of slope in	stability				
	Arial extent:					
	Remarks:					
B. Beno	— 11					
		unds of earth placed across a steep land ty of surface runoff and intercept and co				

1.	Flows Bypass Bench	Location shown on site map	☐ N/A or okay
	Remarks:		
2.	Bench Breached	Location shown on site map	☐ N/A or okay
	Remarks:		
3.	Bench Overtopped	Location shown on site map	☐ N/A or okay
	Remarks:		
C. Letd	lown Channels	Applicable N/A	
S		ontrol mats, riprap, grout bags or gabic ow the runoff water collected by the boar gullies.)	
1.	Settlement (Low spots)	Location shown on site map	No evidence of settlement
	Arial extent:		Depth:
	Remarks:		
2.	Material Degradation	Location shown on site map	No evidence of degradation ■
	Material type:		Arial extent:
	Remarks:		
3.	Erosion	☐ Location shown on site map	No evidence of erosion
	Arial extent:		Depth:
	Remarks:		
4.	Undercutting	Location shown on site map	No evidence of undercutting
	Arial extent:		Depth:
	Remarks:		
5.	Obstructions	Type:	No obstructions ■
	Location shown on site	map Arial extent:	
	Size:		
	Remarks:		
6.	Excessive Vegetative Gro	wth Type:	
	No evidence of excessive	e growth	
	☐ Vegetation in channels of	loes not obstruct flow	
	Location shown on site	map Arial extent:	
	Remarks:		
D. Cove	er Penetrations	Applicable N/A	
1.	Gas Vents	Active	Passive
	☐ Properly secured/locked	☐ Functioning ☐ Routinely s	ampled Good condition
	Evidence of leakage at p	penetration Needs main	ntenance N/A

	Remarks:			
2.	Gas Monitoring Probes			
	Properly secured/locked	☐ Functioning	☐ Routinely sampled	Good condition
	Evidence of leakage at pe	enetration	☐ Needs maintenance	N/A
	Remarks:			
3.	Monitoring Wells (within su)	
	Properly secured/locked	☐ Functioning	☐ Routinely sampled	
	Evidence of leakage at pe	enetration	☐ Needs maintenance	□ N/A
	Remarks:			
4.	Extraction Wells Leachate			
	Properly secured/locked	☐ Functioning	☐ Routinely sampled	Good condition
	Evidence of leakage at pe	enetration	☐ Needs maintenance	□ N/A
	Remarks:			
5.	Settlement Monuments	Located	☐ Routinely surveyed	N/A
	Remarks:			
E. G	as Collection and Treatment	Applicable	⊠ N/A	
1.	Gas Treatment Facilities			
	☐ Flaring	☐ Thermal destru	ction	Collection for reuse
	Good condition	☐ Needs mainten	ance	
	Remarks:			
2.	Gas Collection Wells, Mani	folds and Piping		
	Good condition	Needs mainten	ance	
	Remarks:			
3.	Gas Monitoring Facilities (e	e.g., gas monitoring o	of adjacent homes or buildi	ngs)
	Good condition	Needs mainten	ance N/A	
	Remarks:			
F. Co	over Drainage Layer		N/A	
1.	Outlet Pipes Inspected		□ N/A	
	Remarks:			
2.	Outlet Rock Inspected	☐ Functioning	□ N/A	
	Remarks:			
G. D	etention/Sedimentation Ponds		N/A	
1.	Siltation Area ext	ent: I	Depth:	□ N/A
	Siltation not evident			
	Remarks:			

2.	Erosion Area e	xtent: Depth:	
	Erosion not evident		
	Remarks:		
3.	Outlet Works	nctioning	□ N/A
	Remarks:		
4.	Dam	nctioning	□ N/A
	Remarks:		
H. R	etaining Walls [Applicable N/A	
1.	Deformations	Location shown on site map	☐ Deformation not evident
	Horizontal displacement:	Vertical displa	acement:
	Rotational displacement:	<u> </u>	
	Remarks:		
2.	Degradation	Location shown on site map	Degradation not evident
	Remarks:		
I. Pei	rimeter Ditches/Off-Site Disc	harge	N/A
1.	Siltation	Location shown on site map	Siltation not evident
	Area extent:		Depth:
	Remarks:		
2.	Vegetative Growth	Location shown on site map	□ N/A
	☐ Vegetation does not impe	ede flow	
	Area extent:		Type:
	Remarks:		
3.	Erosion	Location shown on site map	Erosion not evident
	Area extent:		Depth:
	Remarks:		
4.	Discharge Structure	☐ Functioning	□ N/A
	Remarks:		
VIII.	VERTICAL BARRIER WA	LLS	N/A
1.	Settlement	Location shown on site map	Settlement not evident
	Area extent:		Depth:
	Remarks:		
2.	Performance Monitoring	Type of monitoring:	
	Performance not monitor	ed	
	Frequency:		Evidence of breaching
	Head differential:		

	Remarks:					
IX.	IX. GROUND WATER/SURFACE WATER REMEDIES Applicable N/A					
Α. (a. Ground Water Extraction Wells, Pumps and Pipelines					
1.	Pumps, Wellhead Plu	umbing and Electrical				
	☐ Good condition	☐ All required wells properly operating ☐ Needs maintenance ☐ N/A				
	Remarks:					
2.	Extraction System Pi	pelines, Valves, Valve Boxes and Other Appurtenances				
	☐ Good condition	☐ Needs maintenance				
	Remarks:					
3.	Spare Parts and Equ					
	Readily available					
		condition				
	Remarks:					
		Structures, Pumps and Pipelines ☐ Applicable ☒ N/A				
1.		s, Pumps and Electrical				
	Good condition	Needs maintenance				
	Remarks:					
2.	<u></u>	ction System Pipelines, Valves, Valve Boxes and Other Appurtenances				
	Good condition	Needs maintenance				
2	Remarks:					
3.	Spare Parts and Equ	<u></u>				
	Readily available	Good Requires upgrade Needs to be provided condition				
	Remarks:					
C. 7	Treatment System					
1.	Treatment Train (che	eck components that apply)				
	☐ Metals removal	☐ Oil/water separation ☐ Bioremediation				
	☐ Air stripping	Carbon adsorbers				
	Filters:					
	Additive (e.g., chel	lation agent, flocculent):				
	Others: Extraction wells, three evaporation ponds, two wastewater collection ponds, zeolite treatment and an RO treatment plant.					
	☐ Good condition	☐ Needs maintenance				
	☐ Sampling ports pro	perly marked and functional				
	Sampling/maintena	ance log displayed and up to date				
	Equipment properl	y identified				

	Quantity of ground water treated annually:						
	Quantity of surface water treated annually:						
	Remarks:						
2.	Electrical Enclosures and Panels (properly rated and functional)						
	□ N/A						
	Remarks:						
3.	Tanks, Vaults, Storage Vessels						
	☐ N/A ☐ Good ☐ Proper secondary containment ☐ Needs maintenance condition						
	Remarks:						
4.	Discharge Structure and Appurtenances						
	□ N/A □ Good □ Needs maintenance condition						
	Remarks:						
5.	Treatment Building(s)						
	N/A☐ Sood condition (esp. roof and doorways)☐ Needs repair doorways)						
	Chemicals and equipment properly stored						
	Remarks:						
6.	Monitoring Wells (pump and treatment remedy)						
	☐ Properly secured/locked ☐ ☐ Routinely sampled ☐ Good condition Functioning						
	☐ All required wells located ☐ Needs maintenance ☐ N/A						
	Remarks:						
D. Mo	nitoring Data						
1.	Monitoring Data						
	☐ Is routinely submitted on time ☐ Is of acceptable quality						
2.	Monitoring Data Suggests:						
	☐ Ground water plume is effectively ☐ Contaminant concentrations are declining contained						
	onitored Natural Attenuation Monitoring Wells (notural attenuation remodu)						
1.	Monitoring Wells (natural attenuation remedy) ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled ☐ Good condition						
	☐ All required wells located ☐ Needs maintenance ☐ N/A						
	Remarks:						
	X. OTHER REMEDIES						

If there are remedies applied at the site and not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is designed to accomplish (e.g., to contain contaminant plume, minimize infiltration and gas emissions).

The objective of the OU1 remedy is long-term remediation of tailings-contaminated groundwater. The objective of the OU2 remedy is long-term stabilization and closure of the tailings disposal area, including a land-cleanup program for wind-blown tailings. In the OU3 ROD, EPA stated no further action for this OU; however, EPA tested and cleaned up residential yards with contamination. With the new zeolite treatment system and an expanded RO system on line, the remedy will likely be functioning as intended by NRC and HMC. HMC has been actively seeking ways to enhance and speed up the rate of restoration of the contaminated groundwater. Other monitoring data is collected to verify that no airborne emissions are coming from the Site. The monitoring program shows that the Site is operating within the conditions of its NRC license and NMED permits.

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy. O&M is adequate.

C. Early Indicators of Potential Remedy Problems

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs that suggest that the protectiveness of the remedy may be compromised in the future.

None, if all new remedies are implemented at full scale.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy. None, once all new remedies implemented.

APPENDIX I –SITE INSPECTION PHOTOS



Signage at the HMC on-site office



Fencing and signage near the HMC office



Top of the LTP



Wells on top of the LTP



Full-scale zeolite treatment facility on top of the LTP



Platform for the full-scale zeolite treatment



Full-scale zeolite treatment system vents



Support building and tanks at the full-scale zeolite treatment system



Pilot zeolite treatment system tanks



Pits and piping for the pilot zeolite treatment system



View of evaporation ponds 1 and 2 on top of the STP



Rock and radon cover for the LTP



View of evaporation pond 1 from the LTP



View of the wastewater collection ponds



Evaporation pond 2



Evaporation pond 3



RO water treatment facility



Interior of the new RO treatment facility



New microfiltration units within the RO treatment system facility



TPP pilot test support building



TPP pilot test area

APPENDIX J - TOXICITY REVIEW TABLE

Table J-1: Changes in Toxicity Values for Groundwater COCs

Groundwater COC	Toxicity Data from the 2011 FYR ^a		Current 7	Change in Toxicity Since Last FYR	
COC	RfD ^c	RfC ^d	RfD	RfC	
	(mg/kg-day)e	$(mg/m^3)^f$	(mg/kg-day)e	$(mg/m^3)^f$	
Uranium	$3x10^{-3}$	$3x10^{-4}$	$3x10^{-3}$	$4x10^{-5 (g)}$	RfC decreased
Selenium	$5x10^{-3}$	$2x10^{-2}$	$5x10^{-3}$	$2x10^{-2}$	None
Molybdenum	NA	NA	5x10 ⁻³	NA	RfD listed
Radium-226 and	NA	NA	NA	NA	NA
Radium-228					
Thorium-230	NA	NA	NA	NA	NA
Sulfate	NA	NA	NA	NA	NA
Chloride	NA	NA	NA	NA	NA
TDS	NA	NA	NA	NA	NA
Nitrate	1.6	NA	1.6	NA	None

Notes:

- a) Source is Table 8 of the 2011 FYR
- b) Source is the November 2015 Regional Screening Level table, accessed March 3, 2016, available at: http://www.epa.gov/risk/risk-based-screening-table-generic-tables; Cancer slope factors and inhalation unit risk were not available for any of the COCs
- c) Reference Dose
- d) Reference Concentration
- e) mg/kg-day milligram per kilogram per day
- f) mg/m³ milligram per cubic meter
- g) Source is the ATSDR

Table J-2: Toxicity Values for Radionuclides of Concern

Isotope	Soil Ingestion Slope Factor (risk/pCi)	Adult Soil Ingestion Slope Factor (risk/pCi)	Water Ingestion Slope Factor (risk/pCi)	Food Ingestion Slope Factor (risk/pCi)	Inhalation Slope Factor (risk/pCi)	External Exposure Slope Factor (risk/year per pCi/g)
U-238	1.34E-10	4.66E-11	6.40E-11	8.66E-11	2.4E-08	1.24E-10
U-238+D	1.97E-10	5.62E-11	8.70E-11	1.21E-10	2.4E-08	1.19E-07
Th-230	1.66E-10	7.73E-11	9.14E-11	1.19E-10	3.4E-08	8.45E-10
Ra-226	6.77E-10	2.95E-10	3.85E-10	5.14E-10	2.8E-08	2.50E-08
Ra-228	1.98E-09	6.70E-10	1.04E-09	1.42E-09	4.4E-08	3.43E-11

APPENDIX K – ARARS REVIEW

ARARs Review

CERCLA Section 121(d)(1) requires that Superfund remedial actions attain "a degree of cleanup of hazardous substance, pollutants, and contaminants released into the environment and of control of further release at a minimum which assures protection of human health and the environment." The remedial action must achieve a level of cleanup that at least attains those requirements that are legally applicable or relevant and appropriate. In performing the FYR for compliance with ARARs, only those ARARs that address the protectiveness of the remedy are reviewed.

EPA has not issued decision documents for OU1 and OU2; therefore, detailed review of ARARs for these OUs is not applicable. It is expected that EPA will issue a ROD for these OUs by 2018, which include a comprehensive list of ARARs.

Appendix A of the OU3 ROD identified the following ARARs for OU3:

- 10 CFR Part 20, Standards for Protection Against Radiation.
- 10 CFR Part 40, Appendix A. Criteria Relating to the Operation of Uranium Mills and the Disposition of Tailings Wastes Produced by the Extraction or Concentration of Source Material from Ores Processed Primarily for Their Source Material Content.
- 40 CFR Part 192. Health and Environmental Protection Standards for Uranium and Thorium Mill Tailings.
- State of New Mexico ARARs.

These ARARs have not changed in a way that could affect protectiveness of the remedy.