FIFTH FIVE-YEAR REVIEW REPORT FOR SIKES DISPOSAL PITS SUPERFUND SITE HARRIS COUNTY, TEXAS



July 2016



Prepared by

U.S. Environmental Protection Agency Region 6 Dallas, Texas

FIFTH FIVE-YEAR REVIEW REPORT SIKES DISPOSAL PITS SUPERFUND SITE EPA ID NO. TXD980513956 HARRIS COUNTY, TEXAS

This memorandum documents the U.S. Environmental Protection Agency's (EPA's) performance, determinations, and approval of the Sikes Disposal Pits Superfund Site (Site or site) fifth five-year review (FYR) under Section 121(e) of the Comprehensive Environmental Response, Compensation, and Liability Act, Title 42 U.S. Code, Section 962I(c), as provided in the attached Fifth FYR Report.

Summary of the Fifth Five-Year Review Report

The site remedial actions included excavation of contaminated soil and sludge, on-site incineration of excavated soil and sludge, and on-site disposal of residue ash from the incineration. Contaminated surface water was collected and treated on-site. Institutional controls were put in place to prevent the use of contaminated groundwater while it naturally attenuates to within the 10⁻⁵ Human Health Criteria (HHC) that was established by the Record of Decision (ROD). The Site is in the Operations and Maintenance (O&M) phase, and the O&M is being conducted by the Texas Commission on Environmental Quality (TCEQ). This Fifth FYR Report includes a review of relevant decision documents, implementation documents, remedy performance documents, groundwater monitoring reports, and legal documents, and focuses on the data obtained during routine groundwater sampling and gauging. Further evaluation and assessment of site-specific information and sampling data are needed.

Human Exposure Status: Under Control Contaminated Groundwater Status: Under Control

Actions Needed

The following actions must be taken for the remedy to be protective over the long term:

- Conduct an assessment of the Maximum Contaminant Levels (MCLs) and the Human Health Criteria (HHC), and update the action levels as appropriate. Ensure that the laboratory detection limits are lower than updated cleanup levels.
- Perform the five-year sampling event to reassess indicator parameters per the O&M Plan (Shaw 2012b).
- Between each sampling event conducted at the Site, perform the data evaluation as described in the O&M Plan (Shaw 2012b), and include results of the evaluation in the annual reports. Evaluate data trends to adjust sampling frequency as appropriate, upon discussion and approval of the EPA and reevaluate attenuation timeframes.
- Conduct an assessment of detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life.
- Assess the need for sediment sampling, and if appropriate establish data quality objectives for sediment at the Site.
- Remove the fallen tree from the fenced enclosure for well GW-31 and repair the fence.

Determination

I have determined that the remedy for the Sikes Disposal Pits Superfund Site is protective of human health and the environment in the short-term and will be protective in the long-term if recommendations listed above are implemented.

Carl E. Edlund, P.E. Director, Superfund Division U.S. Environmental Protection Agency Region 6

9

CONCURRENCES

FIFTH FIVE-YEAR REVIEW REPORT SIKES DISPOSAL PITS SUPERFUND SITE EPA ID NO. TXD980513956 HARRIS COUNTY, TEXAS

Jalahhmi M. Iniam

Raji Jøsiam Remedial Project Manager

ancher Carlos A. Sanchez

Chief, Texas/Arkansas Section

John C. Meyer

Chief, Superfund Remedial Branch

- Josh C

Anne Foster Attorney, Office of Regional Counsel

Mark A. Peycke Chief, Superfund Branch, Office of Regional Counsel

M

Pamela Phillips Deputy Director, Superfund Division

<u>7-19-16</u> Date

7/20/16

7/20/16 Date

8125/116

Date

08/30/16 Date

ISSUES/RECOMMENDATIONS

FIFTH FIVE-YEAR REVIEW REPORT SIKES DISPOSAL PITS SUPERFUND SITE EPA ID NO. TXD980513956 HARRIS COUNTY, TEXAS

Issues and Recommendations Identified in the Five-Year Review:

OU(s): Sitewide	Issue Category: Remedy Performance						
	Issue: The 2012 Operation and Maintenance (O&M) Report (Shaw 2012b) states that action levels for contaminants of concern have been updated to reflect the lower value between the Maximum Contaminant Levels (MCLs) or Record of Decision specified Human Health Criteria (HHC). The exposure assumptions, toxicity data, and action levels used at the time of the remedy selection should be reassessed.						
Recommendation: Conduct an assessment of the MCLs and the HHC, update the action levels as appropriate. Ensure that the laboratory detec are lower than the updated cleanup levels.							
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMilestone Date						
No	Yes	ЕРА	ЕРА	5/1/2017			

OU(s):	Issue Category: Remedy Performance					
Sitewide	Issue: The O&M Plan contains provisions for semi-annual and annual sampling, in addition to a periodic reassessment of indicator parameters that is to take place "once every five years or whenever a statistically significant increase in the concentration of one or more indicator parameters has occurred" (Shaw 2012b). Semi-annual and annual sampling was conducted during the current review period as described in the O&M Plan (with the exception of a semi-annual event in 2012). However, during the Fourth five-year review (FYR) period and during the current FYR period, the reassessment of indicator parameters did not take place.					
	Recommendation: Perform the five-year sampling event to reassess indicator parameters per the O&M Plan (Shaw 2012b).					
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMileston					
No	Yes State EPA 5/1/2017					

OU(s):	Issue Category: Remedy Performance					
Sitewide	Issue: In addition to sampling frequency, the O&M Plan states that a data evaluation should take place between each sampling event, and states that "the purpose of the data evaluation is to determine the quality of groundwater beneath the site and to determine whether or not a statistically significant change has occurred in the groundwater since the last sampling event" (Shaw 2012b). The results of the statistical evaluation are to be reported in each Annual Report. During the current and Fourth FYR period, no statistical analysis has been conducted between sampling events conducted at the Site.					
	Recommendation: Between each sampling event conducted at the Site, perform the data evaluation as described in the O&M Plan (Shaw 2012b), and include results of the evaluation in the annual reports. Evaluate data trends to adjust sampling frequency as appropriate, upon discussion and approval of the EPA, and reevaluate attenuation timeframes.					
Affect Current Protectiveness	Affect Future Party Protectiveness Responsible Oversight Party Mileston					
No	Yes	State	EPA	5/1/2017		

OU(s): Sitewide	Issue Category: Remedy Performance						
	 Issue: The Fourth FYR recommended that an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life be conducted and also stated that data quality objectives for sediment should be set. There was no record of this assessment in the documents reviewed for the current FYR period. Recommendation: Conduct an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life. 						
							Affect Current Protectiveness
No	Yes	State	ЕРА	5/1/2017			

OU(s):	Issue Category: Monitoring					
Sitewide	Issue: The Fourth FYR stated that the appropriate criteria for setting appropriate data quality objectives and the evaluation of results of surface water and sediment samples is to be determined. The O&M plan (Shaw 2012) included surface water sampling. Based upon review of groundwater monitoring reports and other documents, it did not appear that sediment samples were collected during the review period or the data quality objectives were set for the sediment.					
	Recommendation: Assess the need for sediment sampling and if appropriate establish data quality objectives for sediment at the Site.					
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMilestone D					
No	Yes	EPA	EPA	5/1/2017		

OU(s):	Issue Category: Operations and Maintenance					
Sitewide	Issue: A tree was observed to have fallen on the fence for the well enclosure around GW-31 and a cross section support bar to the fence was disconnected.					
	Recommendation: Remove the fallen tree from the fenced enclosu GW-31 and repair the fence.					
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date		
No	Yes	State	EPA	5/1/2017		
Protectiveness No	Protectiveness Yes	Responsible State	Oversight Party EPA	Milestone Date		

.

FIFTH FIVE-YEAR REVIEW REPORT SIKES DISPOSAL PITS SUPERFUND SITE

TABLE OF CONTENTS

LIST C LIST C I. II. III. IV. V. V. VI.	DF TABLE DF ABBRI INTROD RESPON PROGRE FIVE-YE TECHNI ISSUES/I	ESiiEVIATIONS AND ACRONYMSiiiUCTION1SE ACTION SUMMARY4SS SINCE THE LAST REVIEW9AR REVIEW PROCESS15CAL ASSESSMENT19RECOMMENDATIONS22
	OTHER I	FINDINGS
VII. VIII.	PROTEC NEXT RI	TIVENESS STATEMENT
APPEN APPEN	IDIX A: IDIX B:	REFERENCE LIST SITE CHRONOLOGY TABLE P. 1. SITE CHRONOLOGY
APPEN	IDIX C:	SITE FIGURE FIGURE C-1: LOCATION MAP FIGURE C-2: SITE MAP FIGURE C-3: CONCENTRATION TRENDS FOR BERYLLIUM IN THE SHALLOW AQUIFER FIGURE C-4: CONCENTRATION TRENDS FOR LEAD IN THE SHALLOW AQUIFER FIGURE C-5: CONCENTRATION TRENDS FOR NICKEL IN THE SHALLOW AQUIFER FIGURE C-6: CONCENTRATION TRENDS FOR BENZENE IN THE SHALLOW AQUIFER FIGURE C-7: CONCENTRATION TRENDS FOR VINYL CHLORIDE IN THE SHALLOW AQUIFER
APPEN APPEN APPEN APPEN	IDIX D: IDIX E: IDIX F: IDIX G:	DEED NOTICE NOTICE TO THE PUBLIC REGARDING THE FIVE-YEAR REVIEW INTERVIEW FORM REGRESSION ANALYSIS FOR SELECT WELL-ANALYTE PAIRS TABLE G-1: SUMMARY STATISTICS AND TREND RESULTS FIGURES G-1 THROUGH G-16: GROUNDWATER TIME SERIES TREND PLOTS FOR SELECT ANALYTE-WELL PAIRS
APPEN APPEN APPEN	IDIX H: IDIX I: IDIX J:	SITE INSPECTION CHECKLIST SITE INSPECTION PHOTOGRAPHS APPLICABLE OR RELEVANT AND APPROPRIATE REQUIREMENT SUMMARY

LIST OF TABLES

N	umber	
	amour	

<u>Title</u>

- Table 1:
 Summary of Remedial Action Objectives and Applicable Criteria
- Table 2:
 Summary of Currently Applicable Site Criteria for Monitored Contaminants
- Table 3:
 Summary of Planned and/or Implemented Institutional Controls
- Table 4:
 Protectiveness Determination/Statement from the 2011 Five-Year Review

 Table 5:
 Status of Recommendation from the 2011 Five-Year Review

LIST OF ABBREVIATIONS AND ACRONYMS

ARAR	Applicable or relevant and appropriate requirement				
COC	Contaminant of concern				
DQO	Data quality objectives				
EPA EPS	U.S. Environmental Protection Agency East pond (surface water sample location name)				
FS FSP FYR	Feasibility study Field Sampling Plan Five-year review				
HHC	Human Health Criteria				
IC	Institutional control				
MCL mg/L μg/L	Maximum Contaminant Level Milligrams per liter Micrograms per liter				
O&M	Operations and maintenance				
ppm	Parts per million				
RA RAO RI ROD	Remedial action Remedial action objective Remedial Investigation Record of Decision				
SARA Site/site	Superfund Amendments and Reauthorization Act Sikes Disposal Pits Superfund Site				
TCEQ	Texas Commission on Environmental Quality				
VOC	Volatile organic compound				
WPS	West pond (surface water sample location name)				

(This page intentionally left blank)

I. INTRODUCTION

The purpose of a five-year review (FYR) is to evaluate the implementation and performance of a remedy in order to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings, and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The U.S. Environmental Protection Agency (EPA) is preparing this FYR pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act Section 121, consistent with the National Contingency Plan (40 Code of Federal Regulations Section 300.430[f][4][ii]), and considering EPA policy.

This is the Fifth FYR for the Sikes Disposal Pits Superfund Site (Site/site). The Record of Decision (ROD) was signed on September 18, 1986 (EPA 1986). The triggering action for this Policy/Pre-Superfund Amendments and Reauthorization Act (SARA) review is the completion date of the previous FYR. The FYR has been prepared due to the fact that hazardous substances, pollutants, or contaminants remain at the site above levels that allow for unlimited use and unrestricted exposure.

The Site consists of one (1) Operable Unit, which will be addressed in this FYR.

The Site FYR was led by Ms. Raji Josiam of the EPA, Remedial Project Manager for the Site. Mr. Lam Tran of the Texas Commission on Environmental Quality (TCEQ) assisted in the review as the representative for the support agency. The review began on 2/29/2016. References are included as Appendix A, and the Site Chronology is included in Appendix B. Appendix C includes a location map as Figure C-1, and a Site map as Figure C-2. Additional figures in Appendix C are discussed in Section IV.

Site Background

The Site is located on a 185-acre site approximately 2 miles southwest of Crosby, Harris County, Texas. The Site is bordered by U. S. Highway 90 on the south, the San Jacinto River and Love Marina on the west, and Jackson Bayou on the north (Appendix C, Figure C-1). Both Jackson Bayou and the San Jacinto River have designated beneficial uses for contact recreation and high aquatic life habitat by the TCEQ (Title 30 Texas Administrative Code [TAC] Chapter 307). In the past, the eastern portion of the Site was used by a honey farm to raise bees and harvest honey; this was not observed during the Site inspection. The Riverdale Subdivision is located approximately 500 feet southwest of the Site. An offroading park (Down South Offroad Park) is located within the Site on the north end (Appendix C, Figure C-2). The only features remaining that are related to the remedy include groundwater monitoring wells and access roads. Individual security fencing with a locked gate secures each monitoring well. Since completion of the remedy, vegetation has become reestablished (see Section 6.6 for a discussion of the site inspection). The majority of the Site is vacant, except for the Love Marina at the western side of the Site (EPA 2011).

From about 1961 until 1967, the Site was operated as an illegal open dump. As a result, a wide variety of wastes, including drums and bulk wastes, were disposed on-site. The wastes were primarily chemical wastes, such as benzene, phenols, olefinic compounds, and other organic solvents, that most likely originated from petrochemical companies operating in the surrounding area. Approximately 2,000, 55-gallon drums of waste and an indeterminable amount of bulk loads were discovered to have been disposed at the Site. The drums were dumped along the sides of roads and bulldozed into pits and low mounds, while the bulk loads were dumped and/or pumped into pits and low-lying areas. Hydrocarbon

odors from the Site became such a nuisance that local residents at the time complained to both President Lyndon Johnson and Congress. Much of the wastes were deposited into what was known as the main waste pit, which was surrounded by a dike. This dike was breached by flooding, which resulted in the transporting of wastes across a large low-lying area east of the main waste pit known as the overflow area (EPA 2011).

The Site is frequently inundated by floodwaters from the San Jacinto River. Surface water at the site ultimately drains to either the San Jacinto River or Jackson Bayou. A shallow aquifer, located within alluvial sand deposits ranging from 17 to 34 feet thick, underlies the site. Groundwater in the shallow aquifer flows from the east and northeast towards the southwest across the site. The shallow aquifer discharges into several ponds located at the Love Marina at the southwest portion of the site. A deeper aquifer is located approximately 65 feet below the shallow aquifer. Separated from these two aquifers by several hundred feet of clay are the deeper Chicot and Evangeline aquifers. These two aquifers supply much of the water supply for metropolitan Houston (EPA 2011).

FIVE-YEAR REVIEW SUMMARY FORM

SITE IDENTIFICATION						
Site Name: Sikes I	Disposal Pits	Superfun	d Site			
EPAID: TXD 9	80513956					
Region: 6	State: T2	K	City/County: Crosby/Harris County			
		SI	TE STATUS			
National Priorities Lis	t Status: Fi	nal				
Multiple Operable Un No	its (OUs)?	Has the Yes	site achieved construction completion?			
	REVIEW STATUS					
Lead agency: EPA (If "Other Federal Age	ncy," enter .	Agency na	ime):			
Author name (Federal	or State Pr	oject Mar	nager): Ms. Raji Josiam			
Author affiliation: EPA	A Region 6					
Review period: 2/29/20)16-4/15/2	016				
Date of site inspection:	Date of site inspection: 3/3/2016					
Type of review: Policy/Pre-SARA						
Review number: 5						
Triggering action date	: 9/28/20 11					
Due date (five years af	ter triggerin	g action d	ate): 9/28/2016			

II. RESPONSE ACTION SUMMARY

Basis for Taking Action

The purpose of the response actions conducted at the Site was to protect public health and welfare and the environment from releases or threatened releases of hazardous substances from the site. The major threats posed by the Site were direct human contact with sludge and contaminated soils, continued direct contamination of the upper aquifer, potential contamination of the lower aquifer, direct contact with contaminated surface waters, and releases of toxic volatile organic compounds into the air through uncontrolled disturbances of the waste (EPA 2011). The major contaminants of concern identified included chemical wastes, such as benzene, phenols, olefinic compounds, and other organic solvents, that most likely originated from petrochemical operations (Table 2).

Response Actions

The Record of Decision (ROD) selecting the remedial action for the Site was signed on 9/18/1986 (EPA 1986). The remedial action objectives (RAOs) developed for the Site, along with their associated, ROD-based criteria, are shown in Table 1.

Remedial Action Objective	ROD Criteria
Prevent human contact with	No direct contact with wastes containing greater than 100 parts
contaminated soil and wastes	per million (ppm) polynuclear aromatic hydrocarbons.
Minimize the impact of	Surface Water Quality Criteria: 0.1 milligrams per liter (mg/L)
contaminated runoff	benzene, 0.3 mg/L vinyl chloride, and 0.3 mg/L total phenols and
	metals, per Section 156.19.15.002 of the Texas Water Code.
Prevent human contact with	Surface Water Quality Criteria: 0.1 mg/L benzene, 0.3 mg/L
contaminated surface water	vinyl chloride, and 0.3 mg/L total phenols and metals, per Section
	156.19.15.002 of the Texas Water Code.
Minimize site-related degradation	Surface Water Quality Criteria: 0.1 mg/L benzene, 0.3 mg/L
of the San Jacinto River and	vinyl chloride, and 0.3 mg/L total phenols and metals; per Section
Jackson Bayou	156.19.15.002 of the Texas Water Code.
Prevent use of contaminated	Human Health Criteria (HHC) ¹ and current drinking water
groundwater in the upper aquifer	standards for the currently monitored contaminants ² .
Protect against contamination of	Existing background water quality in the lower aquifer.
the lower aquifer	
Prevent migration of wastes	Surface Water Quality Criteria: 0.1 mg/L benzene, 0.3 mg/L vinyl
offsite during flood events	chloride, and 0.3 mg/L total phenols and metals, per Section
	156.19.15.002 of the Texas Water Code.
Prevent use of groundwater (lower	Existing background water quality in the lower aquifer.
aquifer) contaminated above	
background	
Minimize the potential of any	Federal Ambient Air Standards at the Site boundary.
adverse air discharge	
Notes:	

Table 1: Summary of Remedial Action Objectives and Applicable Criteria

¹ – In the seventh revision of the O&M Plan, the contaminants of concern (COCs) values were compared to the lower value of the Maximum Contaminant Levels (MCLs) or ROD -specified HHCs (Shaw 2012b).

 2 – Monitored contaminants include beryllium, cadmium, total chromium, lead, mercury, nickel, thallium, methyl methacrylate (not listed in ROD, added in with the 2001 O&M Plan), styrene (not listed in ROD, added in with

the 2000 O&M Plan), benzene, chlorobenzene, chloroform, 1,2-dichloroethane, trans-1,2-dichloropropene, ethylbenzene, 1,1,2,2-tetrachloroethane, toluene, 1,1,2-trichloroethane, trichloroethene, and vinyl chloride.

Table 2 lists the currently monitored contaminants, along with list of lower value of MCLs or HHCs that the COCs values were compared to (CB&I 2015).

Contaminant	ROD-Specified 10 ⁻⁵ HHC (micrograms per liter [µg/L])	Current MCL ¹ (µg/L) (EPA 2011)	Lower Value of MCLs or HHCs (CB&I 2015) (µg/L)
Beryllium	0.037	4	0.037
Cadmium	10	5	5
Chromium (total)	50	100	50
Lead	50	15	15
Mercury	0.14	2	0.14
Nickel	13.4		13.4
Thallium	13	2	2
Methyl methacrylate ²	34,000		34,000 ³
Styrene ⁴	100	100	100
Benzene	6.6	5	5
Chlorobenzene	488	100	100
Chloroform	1.9	80	1.9
1,2-Dichloroethane	9.4	5	5
Trans-1,2-dichlorpropene	87		87
Ethylbenzene	1,400	700	700
1,1,2,2-Tetrachloroethane	1.7		1.7
Toluene	14,300	1,000	1,000
1,1,2-Trichloroethane	6	- 5	5
Trichloroethene	23	5	5
Vinyl Chloride	20	2	2

	Table 2: Summary	/ of HHCs a	nd MCLs	for Monitored	Contaminants
--	------------------	-------------	---------	---------------	--------------

Notes:

The lower of the HHC or the MCL are bolded.

¹ - MCLs listed in the Fourth FYR Report were checked against current MCLs, and there have been no updates for listed contaminants as of 11/2015 (EPA 2015b).

 2 - Included in the O&M Plan in 6/2001, but was not initially listed in the ROD.

³ - Listed in the 2015 Annual Report (CB&I 2015) as 34,000 milligrams per liter (mg/L); assumed to be a typo. ⁴ - Included in the O&M Plan in 12/2000, but was not initially listed in the ROD

The major components of the selected remedy included (EPA 2011):

• Excavation of soil and sludge containing more than 10 ppm of volatile organic compounds;

- On-site incineration of excavated soil and sludge;
- On-site disposal of residue ash from incineration;
- Backfilling of pits and excavated areas;

- Flood protection during remedial action;
- Collection and treatment of contaminated surface water;
- Prevent use of contaminated groundwater (through institutional controls [ICs]) while it naturally attenuates (through natural flushing) and;
- Monitoring of the upper and lower aquifers.

Status of Implementation

The remedial action (RA) was structured in two Phases, Phase A and Phase B. Phase A began in 10/1990, and consisted of preparing the Site for remediation and construction of treatment facilities. RA activities included mobilization to the Site, construction of an expanded security fence and establishing 24-hour security, general improvements such as construction of access roads, marking known contaminated areas, construction of flood protection structures, installation and testing of the incinerator and water treatment plant, installation of the air monitoring network, and installation of an on-site laboratory. Phase A activities were completed 80 days ahead of schedule on 1/24/1992 (EPA 2011).

Phase B began immediately after completion of Phase A, and consisted of Site remediation and monitoring activities. A trial incineration was conducted in early 1992, and excavation and incineration activities were completed on 6/11/1994. A total of 496,253 tons of contaminated soil and sludge were excavated and remediated. Also, approximately 350 million gallons of contaminated water were treated as part of the dewatering and storm water treatment process. The air monitoring network detected no levels of contaminants of concern (COCs) leaving the Site during remediation. All the ash from the incinerator was determined to be acceptable for use as backfill at the Site. The final inspection was conducted and the Final Certificate of Completion was issued in 12/1995 (EPA 2011).

Institutional Control Summary Table

Media, Engineered Controls, and Areas that Do Not Support Unlimited Use/Unrestricted Exposure Based on Current Conditions	ICs Called for in the Decision Documents ¹	Impacted Parcel(s)	IC Objective	Title of IC Instrument Implemented and Date (or planned)
Property of Mr. Richard O. Sikes	Yes	Mr. Sikes'	Prohibits use of shallow groundwater within the parcel(s) without approval of TCEQ, or before contaminants of concern no longer exist	Deed Notice (9/25/2001)
Property of Mr. Jim Love	Yes	Mr. Love's	Same as above	Deed Notice (9/25/2001)
Property of Mr. M.W. McClendon	Yes	Mr. McClendon's	Same as above	Deed Notice (9/25/2001)
Property designated previously belonging to Mr. William N. Parker	Yes	Mr. Parker's	Same as above	Not required
Property designated previously belonging to Mr. Larry Anderson	Yes	Mr. Anderson's	Same as above	Not required
Notes: IC = Institutional control. ¹ – These properties were was banned under "Institu Alternative (EPA 1986).	not specifically itional Consider	named in the RO ations" in the des	D; however, use of the t cription of the selected 1	Jpper Aquifer Remedial

Table 3: Summary of Planned and/or Implemented Institutional Controls

The deed notices are included as Appendix D of this report. During the FYR, no activities were observed that violated institutional controls (ICs). On 10/5/2015, TCEQ sent a letter to EPA stating that deed notices were not necessary for the Parker or Anderson properties (TCEQ 2015). This was based on quarterly monitoring conducted at the Site between 4/2013 and 7/2014 that showed groundwater sampling results that TCEQ believed to indicate that "the groundwater below the [Parker and Anderson]... properties is safe to drink and institutional controls are not necessary at this time" (TCEQ 2015). EPA concurred with TCEQ's assessment regarding deed notices on the Parker and Anderson properties on 10/19/2015 (EPA 2015a).

Systems Operations/Operations and Maintenance

The TCEQ is currently responsible for O&M activities at the Site, which includes semi-annual and annual groundwater and surface water sampling, maintenance of the access roads (to take place several days before each groundwater monitoring event), emergency inspections following significant flooding events,

and inspection of Site security features (including warning signs). These activities are specified by the O&M Plan last revised in 2012 (Shaw 2012b). The 2012 O&M Plan is version eight, which is to be effective through 8/31/2016 (CB&I 2013). Semi-annual sampling is to take place for wells GW-28 and GW-30, and surface water samples are to be collected from each of two ponds (east pond [EPS] and west pond [WPS]). Semi-annual sampling is to take place during the second half of the fiscal year, which runs September to August. Annual sampling events consist of collecting samples from six shallow monitoring wells (GW-15, GW-18, GW-19, GW-25, GW-28, and GW-30), from two deep monitoring wells (GW-31), and surface water samples are to be collected from each of the two ponds. Annual sampling is to take place during the first half of the fiscal year.

In addition to the semi-annual and annual groundwater sampling described in the O&M Plan (Shaw 2012b), groundwater is to be collected from all Site wells (GW-07, GW-15, GW-18, GW-19, GW-21, GW-23, GW-25, GW-27, GW-28, GW-29, GW-30, GW-31, GW-32, GW-33, GW-34, and GW-35) and from each of the two ponds every five years. This event will replace the routine annual and semi-annual sampling performed during that year. According to the O&M Plan, the first five-year sampling event was to be performed by 2016 (Shaw 2012b).

The O&M Plan describes the groundwater sampling frequency and analytical parameters to be tested, sampling procedures, analytical testing requirements, and data evaluation. The O&M Plan states that the Site-Specific Health and Safety Plan is readily available during all O&M activities and is typically kept inside work vehicles (Shaw 2012b).

The O&M Plan also contains provisions for re-evaluating baseline conditions and analytical parameters. The plan states that to verify the data quality objectives (DQOs) of the project are being achieved, a periodic reassessment of the indicator parameters is required; this is to occur every five years (as described above) or whenever a statistically significant increase of one of the indicator parameters has occurred (Shaw 2012b). During the Fifth FYR, it did not appear from the monitoring reports that the five-year indicator parameter reassessment had been conducted or that statistical analysis of data trends had been performed; this was also the case during the Fourth FYR. As part of the Fifth FYR, a statistical analysis of select analyte-well pairs was conducted by the EPA subcontractor. No significant increase in any indicator parameters was found (See Section IV).

During the current review period, a total of 11 groundwater monitoring events took place between 8/2012 and 6/2015 for which reports were available as of the date of this FYR (note that one event was only for one well, GW-27, in 8/2014). One groundwater monitoring event took place in 11/2015, but the annual report for this work will not be prepared until after the date of this report. However, the data from the 11/2015 event is included in this review. During the review period, annual sampling according to the 2012 O&M Plan took place five times (8/2012, 12/2012, 12/2013, 12/2014, and 11/2015), and semiannual sampling according to the 2012 O&M Plan took place three times (6/2013, 4/2014, and 6/2015). During the sampling events conducted in 4/2013, 2/2014, and 7/2014, groundwater samples were collected in support of data in order to determine if ICs were necessary for the Anderson and Parker properties (TCEQ 2015). In addition, wells SI-116 and INT-116 were sampled a number of times between 2013 and 2014. These wells are not included in the 2012 O&M Plan list of wells to be sampled, and it has since been determined that these wells are for the adjacent French Limited Superfund Site (FLTG 1995). It is unclear why these wells have been included in the groundwater monitoring program during the current review period. Surface water was collected from both EPS and WPS locations during all sampling events except for 2/2014 and 7/2014, and during the 8/2014 event where only one well was sampled.

Lastly, note that in the seventh revision of the O&M Plan, the COCs levels are being compared to the lower of the MCLs or ROD-specified HHCs (Shaw 2012b). See Table 1 and Table 2. EPA MCLs were

last updated in November 2015; values listed in Table 2 reflect current MCLs for listed COCs (EPA 2015b).

III. PROGRESS SINCE THE LAST REVIEW

OU No.	Protectiveness Determination	Protectiveness Statement
Sitewide	Protective	The remedy for the Sikes Disposal Pits Superfund Site is protective of human health and the environment in the short term, and will remain so provided the action items identified in this five- year review report are addressed.

 Table 4: Protectiveness Determination/Statement from the 2011 Five-Year Review

Table 5: Status of Recommendation from the 2011 Five-Year Review

				Over-	Original		Completion
OU		Recommendations/	Party	sight	Milestone	Current	Date (if
No.	Issue	Follow-Up Actions	Responsible	Party	Date	Status	applicable)
Site-	Some monitor well	Replace locks and signs as	TCEQ	EPA	2012	Ongoing	December
wide	locks are missing	needed to protect the					2012*
	or corroded, and	monitor wells. The access	-				* TCEQ
	some warning	gates should be secured to					indicated that
	signs are faded and	prevent unauthorized access					all locks and
	outdated (carried	to wells. The fences and					signs were
	over from the third	gates are required to restrict					replaced by
	five-year review).	access and prevent damage					December
		to or tampering with the					2012. During
		monitor wells, particularly					this site visit,
		in light of increased traffic					a few locks
		potentially associated with					and signs
		off-road biking activities					were further
		planned for the site.					identified to
							be replaced.
		-					See below for
							recommenda-
							tion
Site-	Waste drums are	Dispose any waste	TCEQ	EPA	2012	Ongoing	Annual*
wide	currently stored	contained in the drums					
	inside the security	associated with sampling					*TCEQ
	fence at wells	events, and implement a				-	indicated that
	GW-28/GW-29	program for disposition in a					the waste is
	(carried over from	timely manner of all wastes					disposed of
	the third five-year	generated as part of		1			once a year
	review).	sampling activities.					

				Over-	Original		Completion
OU		Recommendations/	Party	sight	Milestone	Current	Date (if
No.	Issue	Follow-Up Actions	Responsible	Party	Date	Status	applicable)
Site-	The O&M Plan,	The sampling frequency	TCEQ	EPA	2012	Addressed	See below
wide	last updated in	specified by the O&M Plan				in Next	for issue in
	2/2003, requires	should be implemented.				FYR	Fifth FYR.
	semi-annual	Based on the apparently					
	sampling of 6	relative stability of the					
	shallow wells and	contaminant plume, a					
	2 deep wells.	reduction in the frequency					
	During the fourth	of monitoring for less-					
	five-year review	affected wells included in			:		
	period, only three	the semi-annual program					
	sampling events	could be considered,					
	(12/2006 6/2007	perhaps to annual for the					
	(12/2000, 0/2007, 0.000)	next live-year review					
	anu 5/2011).	period. Due to detections of					
		above criteria, however, it is					
		recommended that sampling					
		of GW-28 GW-30 and the					
		ponds continue at the semi-					
		annual frequency					
		Statistical analysis of data					
		trends should be considered					
		to aid in setting the					
		appropriate monitoring					
		frequency and reevaluation					
		of attenuation timeframes					
		(ROD indicates a natural					
		attenuation timeframe of					
		less than 30 years). The					
		wells not included in a					
		revised semi-annual or					
		annual program should be					
		sampled at least once during					
		the five-year review period,					
		or if they are determined to					
		no longer be needed, they					
		should be properly					
		abandoned. Also, the					
		interim baseline event must					
		be implemented as required					
		m the O&M Plan, and the	,				
		O&M Plan must be updated					
		to document any changes in					
		the monitoring program.					

OU No.	Issue	Recommendations / Follow-Up Actions	Party Responsible	Oversight Party	Original Milestone Date	Current Status	Completion Date (if applicable)
Site- wide	Since the ROD was signed, MCLs have been established for several site contaminants that are lower than the human health criteria presented in the ROD (carried over from third five- year review).	The lower of the MCL or ROD specified human health criteria should be considered when determining when the groundwater at the site has achieved the remedial objective of protection of human health and restrictions on use of contaminated groundwater can be lifted.	TCEQ	EPA	2012	Addressed in Next FYR	See below for issue in Fifth FYR.

OU		Recommendations/	Party	Over- sight	Original Milestone	Current	Completio n Date (if
No.	Issue	Follow-Up Actions	Responsible	Party	Date	Status	applicable)
Site-	Site-related	Continue to monitor	TCEQ	EPA	2012	Addressed	See below
wide	contaminants of	contaminant				in Next	for issue in
	concern continue to be	concentrations in site				FYR	Fifth FYR.
	detected in site wells,	wells and the two					
	and have been detected	ponds, add procedures					
	in the east and west	for sampling of the two					
	ponds at the Love	ponds to the O&M					
	Marina, but no surface	Plan, and determine the					
	water criteria have been	appropriate criteria for					
	set for evaluating the	setting appropriate data					
	risk of exposure, and no	quality objectives and					
	sediment data have	the evaluation of results					
	been collected.	of surface water and					
		sediment samples.					
		Also, perform an					
		assessment of the					
		detections of site					
		contaminants above					
		Texas surface water					
		quality standards for the					
		protection of human					
		health and aquatic life.					

OU No.	Issue	Recommendations/ Follow-Up Actions	Party Responsible	Over- sight Party	Original Milestone Date	Current Status	Completion Date (if applicable)
Site-	Recent groundwater	Perform a	TCEQ	EPA	2012	Considered	See below
wide	data for benzene and	preliminary vapor				But Not	for
	vinyl chloride from	intrusion screening				Implemented	explanation
	two shallow wells	evaluation. The					-
	(GW-28 and GW-30)	purpose of this					

	exceed FPA's vapor	evaluation would be					
	intrusion screening	to assess the					
	levels (EDA 2015b)	notantial for					
	ICVCIS (EI A 20150).	migration of select					
		volatile organic					
		volatile organic					
		Compounds (VOCS)					
		from contaminated				:	
		groundwater and					
		potentially					
[]		contaminated soil	, 				
		vapor into current					
		and potential future					
		overlying					
		residential/industrial					
		buildings, and to					
		assess current and					
		future risk to					
		building occupants					
		from potential vapor					
		intrusion. To plan					
		this evaluation, refer					
		to the Interstate					
		Technology &					
		Regulatory Council					
		(ITRC 2007) and					
ļ		the EPA Vanor					
		Intrucion Guidance					
		(EDA 2015co)					
		(EFA 2013aa)					
0.1	Deedeetiere	Goundate the filling	TOPO	EDA	2012	Completed	10/10/2015
Site-	Deed notices	Complete the filing	ICEQ	EPA	2012	Completed	10/19/2015
wide	describing the site	or deed notices for					
	nazards are not in	the Parker and					
	place for all properties	Anderson					
	within the boundary of	properties.					
ļ	the site (carried over						
	from third five-year						
	review).						

- Fourth FYR Recommendations / Follow-Up Actions: Some monitor well locks are missing or corroded, and some warning signs are faded and outdated (carried over from the Third FYR). TCEQ indicated that all locks and signs were replaced by December 2012. During this site visit, a few locks and signs were further identified to be replaced.
 - o Fifth FYR Status
 - Warning signs around groundwater monitoring well enclosures should be replaced on wells GW-15, GW-18, GW-31, and GW-34.
 - Well casing locks should be replaced on wells GW-19 and GW-23.
 - Well identification should be replaced on wells GW-15 and GW-35.
- Fourth FYR Recommendations / Follow-Up Actions: Waste drums are currently stored inside the security fence at wells GW-28/GW-29 (carried over from the Third FYR)

- o Fifth FYR Status
 - During the Site inspection, one drum was noted in this area and contained approximately 10 gallons of purge water. TCEQ stated that waste is disposed of once per year.
- Fourth FYR Recommendations / Follow-Up Actions: The O&M Plan, last updated in 2/2003, requires semi-annual sampling of 6 shallow wells and 2 deep wells. During the Fourth FYR period, only three sampling events were performed (12/2006, 6/2007, and 3/2011).
 - o Fifth FYR Status
 - The O&M Plan was updated in 2012 (Shaw 2012b), and called for semi-annual, annual, and five-year sampling. Semi-annual sampling took place on 6/2013, 4/2014, and 6/2015; no semi-annual event took place in 2012, however. Annual sampling took place on 8/2012, 12/2012, 12/2013, 12/2014 and 11/2015, but the annual sampling event report for the 2015 event was not submitted as of the date of this report. Analytical results from the 11/2015 monitoring event were reviewed, however.
 - Statistical analysis of data trends was recommended under this Issue during the Fourth FYR. A statistical analysis took place during the Fifth FYR. See Section IV.
 - During the Fifth FYR, it did not appear from the monitoring reports that the fiveyear indicator parameter reassessment (interim baseline event, as recommended) had been conducted.
- Fourth FYR Recommendations / Follow-Up Actions: Since the ROD was signed, MCLs have been established for several site contaminants that are lower than the HHC presented in the ROD (carried over from Third FYR).
 - o Fifth FYR Status
 - The COCs levels have been compared to the lower of the MCLs or RODspecified HHCs (Shaw 2012b).
 - The ROD has not been amended in regard to action levels being based on the lower of the MCL or HHCs.
- Fourth FYR Recommendations / Follow-Up Actions: Site-related COCs continue to be detected in Site wells, and have been detected in the east and west ponds at the Love Marina, but no surface water criteria have been set for evaluating the risk of exposure, and no sediment data have been collected.
 - o Fifth FYR Status
 - Surface water samples were collected at regular intervals during the current review period.

- As recommended, surface water collection procedures are outlined in the O&M Plan (Shaw 2012b). COCs have not been detected in the East or West pond samples taken during the current review period.
- It does not appear that sediment data have been collected.
- As recommended, an "assessment of the detections of site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life" (EPA 2011) has not been conducted during the current review period.
- Fourth FYR Recommendations / Follow-Up Actions: Recent groundwater data for benzene and vinyl chloride from two shallow wells (GW-28 and GW-30) exceed EPA's generic vapor intrusion screening levels.
 - o Fifth FYR Status
 - During the Site inspection, TCEQ stated that a vapor assessment has not been conducted at the Site. There are no residential or industrial buildings at the site in the vicinity of these shallow wells and hence, vapor intrusion is not an issue at this time. If residential or industrial buildings are constructed in the area in the future, vapor intrusion in these buildings needs to be evaluated and addressed.
- Fourth FYR Recommendations / Follow-Up Actions: Deed notices describing the site hazards are not in place for all properties within the boundary of the Site (carried over from Third FYR).
 - o Fifth FYR Status

 As stated above, TCEQ sent a letter to EPA stating that deed notices were not necessary for the Parker or Anderson properties after review of the results of quarterly monitoring conducted at the Site between 4/2013 and 7/2014 (TCEQ 2015). EPA concurred with TCEQ's assessment regarding deed notices on the Parker and Anderson properties on 10/19/2015 (EPA 2015a).

IV. FIVE-YEAR REVIEW PROCESS

Community Notification, Involvement, and Site Interview

A public notice was published on 2/24/2016 in the *Highlands/Crosby Star Courier* announcing the FYR at the Site. A copy of this news release is provided in Appendix E. The results of this review and the report will be made available at the Site information repository located at the Crosby Branch Library, 135 Hare Road, Crosby, Texas 77532 (Phone 281-328-3535).

During the FYR process, interview forms were sent to various parties with association to the Site to document any perceived problems or successes with the remedy that has been implemented to date:

- Mr. Lam Tran, Project Manager, TCEQ Summarized below.
- Down South Offroad (Sikes New Property/Land Owner) Survey not returned. Hard copy provided on 3/2/2016; inquiry emailed on 3/9/2016, 3/16/2016, and 3/24/2016.
- Business Manager for Down South Offroad Survey not returned. Hard copy provided on 3/2/2016; inquiry emailed on 3/9/2016, 3/16/2016, and 3/24/2016.
- Love's Marina New Owner Survey not returned. Hard copy provided on 3/2/2016. TCEQ inquiry made on 3/31/2016.
- Love's Marina Site Manager Survey not returned. Hard copy provided on 3/2/2016. TCEQ inquiry made on 3/31/2016.
- Harris County Commissioner of Precinct 2 Survey not returned. Sent via email on 2/23/2016.
- Harris County Precinct 2 Infrastructure Director Survey not returned. Sent via email on 2/23/2016.
- Crosby Voluntary Fire Department Chief Survey not returned. Sent via email on 2/23/2016.
- Former Sikes Property/Land Owner Not available.
- Former Love's Marina Part-time Employee Not available.

The result of the returned interview is summarized below and the full form is included in Appendix F.

On 3/3/2016, Mr. Lam Tran of TCEQ returned an interview form sent by the EPA subcontractor on 2/17/2016. Mr. Tran stated that TCEQ conducted all tasks recommended by the Fourth FYR, specifically, that groundwater and surface water monitoring were conducted in accordance with the updated O&M Plan (Shaw 2012b). Mr. Tran noted that ownership of Love's Marina had changed during the review period, and that the new owner has been cooperative during the review period. He also noted that a customer of Down South Offroad called TCEQ and asked for information regarding the Site; he additionally noted that the new owner of this business has occasionally asked TCEQ when groundwater contamination at the Site will be detected below action levels. No other information regarding these inquiries was listed in the interview form. Vandalism to the fence and gate surrounding well GW-19 was noted in 6/2013; the fence and gate were repaired in 7/2013 according to Mr. Tran. Lastly, Mr. Tran recommended that wells at the Site that are not being sampled on a semi-annual basis should be plugged

and abandoned, although a rationale was not stated. See Appendix F.

Data Review

This FYR consisted of a review of relevant documents including groundwater monitoring data (see below), the ROD (EPA 1986), the current O&M Plan (Shaw 2012b), and IC documentation. Applicable cleanup standards were also reviewed (EPA 2015b).

Data collected since the previous FYR includes groundwater and surface water sampling analytical results. The ROD specified HHCs for the groundwater that must be met before groundwater beneath at the Site can be used. Until these criteria are met, there is a ban on the use of groundwater from the shallow and deep aquifers. As discussed above the COC levels have been compared to the lower of the MCLs or ROD-specified HHCs (Table 2). Analytical results discussed below are therefore compared to either MCLs or HHCs for monitored COCs, depending on the lower of the two values. See Table 2.

The last FYR was completed 8/2011. Groundwater samples were obtained annually between 2012 and 2015. Groundwater and surface water data are summarized below.

Metals in Shallow Wells

During the current review period, beryllium continued to be the most commonly detected COC in shallow wells at the Site. The beryllium was detected above the action level (HHC) of 0.037 μ g/L a total of 14 times in wells GW-15, GW-18, GW-19, GW-23, GW-27, GW-28, and GW-30. The highest concentration detected during this FYR period was 6.23 μ g/L in GW-27 during the July 14, 2014 sampling event. However, note that except for the 3/2011 groundwater monitoring event, the laboratory detection limit was above the beryllium action level for every sampling event during the current review period. Lead was detected above the action level (MCL) of 15 μ g/L one time each in wells GW-23 and GW-34, and nickel was detected above the action level (HHC) of 13.4 μ g/L 10 times in wells GW-15, GW-18, and GW-27. Concentration trends for beryllium, lead, and nickel are shown in Appendix C, Figure C-3 through Figure C-5, respectively. Note that for non-detect results, a concentration of one-half the detection limit was used as the data point for graphing purposes.

Metals in Deep Wells

During the current review period, no metals were detected above their action levels in any of the deep wells at the Site.

Volatile Organic Compounds (VOCs) in Shallow Wells

Well GW-30 was sampled eight times between 8/2012 and 11/2015. Benzene was detected above its 5 μ g/L action level a total of seven times in this well during the current review period. Vinyl chloride was detected in this well above its 2 μ g/L action level during every monitoring event. The only other well with VOC detections above action levels was well GW-28, with one detection each of benzene and vinyl chloride during the 8/2012 groundwater monitoring event. The action levels for both benzene and vinyl chloride are their MCLs. Concentration trends for benzene and vinyl chloride are shown in Appendix C, Figure C-6 and Figure C-7, respectively.

VOCs in Deep Wells

During the current review period, no VOCs were detected above their action levels in any of the deep wells at the Site.

Metals and VOCs in Surface Water

No metals or VOCs were detected above their action levels in either the East Pond or West Pond during the current review period. The vast majority of samples collected from these locations were below laboratory detection limits. However, chromium was detected at a concentration of 20 μ g/L (HHC action level is 50 μ g/L) in the East Pond during the 6/2015 groundwater monitoring event; however, it was not detected above the laboratory detection limit in the other eight samples collected during the review period. No other detected concentrations of note occurred in surface water samples collected during the review period.

Concentration Trend Analysis

The EPA subcontractor conducted a Mann-Kendall analysis for temporal trend (Gilbert 1987) for select analyte-well pairs with 4 or more samples and at least 1 detected concentration for data available from 12/2006 to 11/2015. Due to variations in method detection limits, all concentrations reported below the highest reported detection limit of the non-detect results were treated as ties for the Mann-Kendall test. Exact two-sided probabilities for the null distribution of the Mann-Kendall test were obtained from Hollander and Wolfe (1973). The test was evaluated at the 95% significance level for data sets with at least 10 samples, or the 90% significance level for data sets with fewer than 10 samples. All analyte-well pairs evaluated had a frequency of detection of at least 33%. Decreasing trends were noted for beryllium in wells GW-15 and GW-18; for benzene in wells GW-28 and GW-30; for trichloroethylene in well GW-28; and for vinyl chloride in wells GW-28 and GW-30. All other analyte-well pairs showed no significant trend. Appendix G contains the summary statistics and trend results, along with time series plots for the selected analyte-well pairs.

Purge Water Disposal

According to the Field Sampling Plan (FSP) (ECS 2013), purge water generated during sampling events is to "be collected in 55-gallon drums for subsequent testing and disposal" (ECS 2013). Specific analytical testing requirements and discharge criteria for purge water are not contained in the FSP (ECS 2013) or O&M Plan (Shaw 2012b). In 2011, two 55-gallon drums were noted near well GW-28; one was stated to be full, and the other was one-third full. These were to be managed for disposal at a later date (Shaw 2011). In 2012, one 55-gallon drum was noted in the enclosure for well GW-28. This was disposed of as solid waste through a Bill of Lading (Shaw 2012a), and was therefore empty. It is not clear where the purge water or second drum from 2011 were disposed. The 2013 Annual Report included a Uniform *Hazardous* Waste Manifest for purge water disposal (CB&I 2013). No waste manifest for purge water was included in the 2014 Annual Report (CB&I 2014), and the 2015 Annual Report included a *Non-Hazardous* Waste Manifest for purge water disposal (CB&I 2015).

Site Inspection

The inspection of the Site was conducted on 3/2/2016. In attendance were Ms. Raji Josiam, EPA; Mr. Lam Tran, TCEQ; and Ms. April Ballweg, EA Engineering, Science, and Technology, Inc., PBC. The purpose of the inspection was to assess the protectiveness of the remedy. The Site Inspection Checklist is included as Appendix H. Photographic documentation of the Site inspection is included as Appendix I.

The Site is under new ownership since the previous FYR. The new property owners have started a business identified as Down South Offroad (Photographs 27 and 28). This is an off-road motocross bike park with picnic areas and day camping type activities. During the Site visit, it appeared that various locations near monitoring wells appeared to have been used for the day camping and picnicking activities (Photographs 15 and 16). In addition, trash disposal barrels were staged throughout the property. The ROD does not specify any restrictions on land use, except for banning the use of groundwater in the upper aquifer on Site. However, the new property/business owner of Down South Offroad identified the desire to install a water supply well to allow for the rinsing of bikes after trail riding activities. This has not been explored with TCEQ or EPA, and this potential well installation is currently only in the preliminary stage.

Love Marina is under new ownership as determined during the Site visit (Photographs 45 and 47). Signage and property structures (Photographs 46 and 48) indicate activities at the marina include picnicking, fishing, swimming, boating, and camping.

The fence erected around the Site during the remedial action is mostly intact; however, the gate is showing more wear. All groundwater monitoring wells were checked during the Site inspection and appear to be in good condition with only minor maintenance items identified. Access is restricted to monitoring wells by individual perimeter fencing (see Photograph 2 as an example). The groundwater monitoring well fence gates were all found to be locked during Site visit. The well casing padlocks on GW-19 (Photograph 38) and GW-23 were missing or damaged beyond the point of use as observed during the Site visit. Warning signs are posted at most well locations (Photographs 2, 7, 6, 9, 17, 19, 22, 33, 37, 40, and 43), however, some were missing the yellow warning signs (Photographs 13, 30, and 31). In addition, some of the TCEQ phone number signs were faded or illegible (Photographs 3 and 13). The language on some Site signs is also outdated (citing Texas Natural Resource Conservation Commission instead of TCEQ; Photographs 6, 7, 29, and 40). Some well identifications were observed to be faded (Photograph 34 as example), while GW-35 was missing an identification completely due to heavy rusting of the well casing. One 55-gallon drum used for staging of purge water from sampling events was observed stored inside the fence at wells GW-28/GW-29 (Photographs 33, 35, and 36).

Vegetation around the monitor wells was observed to be under control (Photographs 2, 7, 9, 11, 13, 17, 19, 20, 33, 37, 40, and 43). Only wells GW-15/GW-31 (Photographs 29, 30, 31, and 32) had nearby vegetative growth at the fence line with a fallen tree observed leaning on the fence at GW-31. Site roads were in excellent condition (Photographs 1, 25, 26, and 45), except for the road to GW-15/GW-31, which requires 4-wheel drive to access the wells.

The honey farm behives that previously lined the road heading northwest from wells SI-116/INT-116 (Photograph 49) were not observed during this FYR. In addition, Well-A/GW-5 (Photograph 50) was observed during the Site visit and based on historical research, it was determined to be part of the French Limited Superfund Site well field and not associated with the Site (FLTG 1995). See Appendix C, Figure C-2.

V. TECHNICAL ASSESSMENT

Question A: Is the remedy functioning as intended by the decision documents?

Based on the data review, the Site inspection, and the interviews, it appears that the remedy selected in the ROD is functioning as intended. All remedy components defined in the ROD are complete except for ongoing natural flushing of the shallow groundwater. O&M is occurring, however there are some items identified in the O&M plan that have not taken place in the last five years.

Remedial Action Performance

- Based on the data review, the Site inspection, and the interviews, it appears that the remedy selected in the ROD is functioning as intended. All remedy components defined in the ROD are complete except for ongoing natural flushing of the shallow groundwater.
- As a result of the statistical analysis performed, it was found that there are no wells that show statistically significant increases in monitored parameters where exceedances of action levels are found. In addition, with the exception of wells GW-28 and GW-30, no VOCs have been detected above action levels in the remainder of Site wells since 2006. The metals beryllium, lead, and nickel are more widespread than VOCs in Site wells; however, there are a number of wells (GW-7, GW-21, GW-25, GW-33, and GW-35) where no metals exceedances above action levels have been found since approximately 2006.
- Opportunities exist to reduce costs of monitoring at the Site through reduction in the frequency of sampling for wells where VOCs and/or metals have not historically been detected above action levels. In wells where sampling has ceased, plugging and abandonment could potentially reduce costs in maintaining access to the wells (i.e., less subcontractor time on Site).

System Operations/Operation and Maintenance

- Site O&M includes semi-annual and annual groundwater and surface water sampling, maintenance of the access roads, emergency inspections following significant flooding events, and inspection of Site security features. In addition, groundwater from all Site wells and one surface water sample from each of the two ponds is to be collected every five years for reassessment of indicator parameters (Shaw 2012b).
 - Site O&M activities (i.e., mowing and Site road work) took place in 10/2013, 7/2014, 12/2014, and 6/2015 (CB&I 2014, CB&I 2015). Semi-annual sampling took place on 6/2013, 4/2014, and 6/2015; no semi-annual event took place in 2012. Annual sampling took place on 8/2012, 12/2012, 12/2013, 12/2014 and 11/2015 (CB&I 2015).
 - It did not appear from review of collected data that the 5-year sampling event took place during the current review period, although during the 12/2013 sampling event, groundwater and surface water was collected from the prescribed wells and surface water locations for this event (with the exception of wells GW-32 and GW-33). However, there was no discussion of the 5-year sampling event in the 2014 Annual Report (CB&I 2014).
 - During every sampling event conducted during the current review period except in 3/2011, the beryllium laboratory detection limit reported was above the action level.

- The Fourth FYR recommended that an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life be conducted. There was no record of this assessment in the documents reviewed for the current FYR period. This assessment is still needed and should be completed.
- No discussion of an emergency inspection following a significant flooding event was found during the review of the Annual Reports.
- The O&M Plan also contains provisions for conducting a statistical analysis of collected data (Shaw 2012b).
 - A statistical analysis did not take place during the Fourth FYR; however, the EPA subcontractor performed a Mann-Kendall regression analysis on select analyte-well pairs as part of the current FYR. As stated above, no significant increase in any indicator parameters was identified. Rather, where a statistically significant trend was observed, the trend was a decreasing one (See Section IV and Appendix G).
 - It should be noted that the current O&M Plan calls for a data evaluation "to determine whether or not a statistically significant change has occurred in the groundwater since the last sampling event" (Shaw 2012b). No such evaluation was completed during the current review period.

Implementation of Institutional Controls and Other Measures

• ICs are in place (Appendix D) and are effective in preventing exposure.

Question B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy section still valid?

The exposure assumptions, toxicity data, and RAOs used at the time of the remedy selection may no longer be valid. The potential for VI should be evaluated and the cleanup levels selected in the ROD may need to be changed to reflect more stringent MCLs.

Changes in Standards and To Be Considered

• Applicable or relevant and appropriate requirements (ARARs) for this Site were identified in the ROD dated 9/18/1986 (EPA 1986). This FYR included identification and evaluation of changes in these ARARs to determine whether such changes may affect the protectiveness of the selected remedy. No changes that would call into question the effectiveness of the remedy have occurred since the signing of the ROD. The ARAR summary is provided in Appendix J.

Changes in Toxicity and Other Contaminant Characteristics

• None.

Changes in Risk Assessment Methods

• There have been no changes that bear on the protectiveness of the selected remedy.

Changes in Exposure Pathways

- Vapor Intrusion was identified as a possibility during the Fourth FYR and preliminary screening suggested a VI study is needed. During the Site inspection, TCEQ stated that a vapor assessment has not been conducted at the Site. There are no residential or industrial buildings at the site in the vicinity of these shallow wells, and hence, vapor intrusion is not an issue at this time. If residential or industrial buildings are constructed in the area in the future, vapor intrusion in these buildings needs to be evaluated and addressed.
- In addition, no sediment sampling has taken place in the two surface water ponds at the Site as recommended during the Fourth FYR. COCs have not been detected in the East or West pond samples taken during the current review period. Further assessment is needed to determine the need for sediment sampling.

Expected Progress towards Meeting RAOs

- Construction for the remedy was completed in 1995.
- Site RAOs are being met.

Question C: Has any other information come to light that could call into question the protectiveness of the remedy?

• No other information has been identified that calls the protectiveness of the selected remedy into question.

VI. ISSUES/RECOMMENDATIONS

Issues and Recommendations Identified in the Five-Year Review:

OU(s): Sitewide	Issue Category: Re	medy Performance			
	Issue: The 2012 Op that action levels for lower value between Decision specified H toxicity data, and ac assessed.	peration and Maintena contaminants of con the Maximum Conta Iuman Health Criteria tion levels used at the	ance (O&M) Report (cern have been updat aminant Levels (MCL a (HHC). The exposu e time of the remedy s	Shaw 2012b) states ed to reflect the .s) or Record of ure assumptions, selection should be	
	Recommendation: and the Human Heal Ensure that the labor levels.	Conduct an assessme lth Criteria, and upda ratory detection limits	nt of the Maximum C te the action levels as s are lower than the u	Contaminant Levels appropriate. pdated cleanup	
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMilestone Date				
No Yes EPA EPA 5/1/2					

OU(s):	Issue Category: Re	medy Performance				
Sitewide	in addition to a periodic reassessment of indicator parameters that is to take place "once every five years or whenever a statistically significant increase in the concentration of one or more indicator parameters has occurred" (Shaw 2012b). Semi-annual and annual sampling was conducted during the current review period as described in the O&M Plan (with the exception of a semi-annual event in 2012). However, during the Fourth five-year review (FYR) period and during the current FYR period, the reassessment of indicator parameters did not take place.					
	r sampling event to re 2b).	eassess indicator				
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMilestone Date					
No	Yes	State	EPA	5/1/2017		

OU(s):	Issue Category: Re	medy Performance				
Sitewide	Issue: In addition to evaluation should ta purpose of the data of the site and to deterr occurred in the grou results of the statistic During the current a conducted between s	o sampling frequency ke place between eac evaluation is to detern nine whether or not a ndwater since the last cal evaluation are to b nd Fourth FYR perior sampling events cond	, the O&M Plan state h sampling event, and nine the quality of gr statistically significa t sampling event" (Sh be reported in each A d, no statistical analy ucted at the Site.	s that a data d states that "the oundwater beneath int change has naw 2012b). The nnual Report. sis has been		
Recommendation: Between each sampling event conducted at the Site, perf the data evaluation as described in the O&M Plan (Shaw 2012b), and include results of the evaluation in the annual reports. Evaluate data trends to adjust sampling frequency as appropriate, upon discussion and approval of the EPA reevaluate attenuation timeframes.						
Affect Current Protectiveness	Affect FuturePartyProtectivenessResponsibleOversight PartyMilestone Date					
No	Yes State EPA 5/1/2017					

OU(s): Sitewide	Issue Category: Remedy Performance Issue: The Fourth FYR recommended that an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life be conducted and also stated that data quality objectives for sediment should be set. There was no record of this assessment in the documents reviewed for the current FYR period.					
						Recommendation: Conduct an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life.
	Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date	
No	Yes	State	ЕРА	5/1/2017		

OU(s): Sitewide	Issue Category: Monitoring Issue: The Fourth FYR stated that the appropriate criteria for setting appropriate data quality objectives and the evaluation of results of surface water and sediment samples is to be determined. The O&M plan (Shaw 2012) included surface water sampling. Based upon review of groundwater monitoring reports and other documents, it did not appear that sediment samples were collected during the review period or the data quality objectives were set for the sediment.				
	Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date
No	Yes	ЕРА	EPA	5/1/2017	

OU(s): Sitewide	Issue Category: Operations and Maintenance Issue: A tree was observed to have fallen on the fence for the well enclosure around GW-31 and a cross section support bar to the fence was disconnected.					
						Recommendation: Remove the fallen tree from the fenced enclosure for well GW-31 and repair the fence.
	Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date	
No	Yes	State	EPA	5/1/2017		

OTHER FINDINGS

In addition, the following are recommendations that were identified during the FYR and may improve performance of the remedy, but do not affect current and/or future protectiveness:

- Warning signs around groundwater monitoring well enclosures should be replaced on wells GW-15, GW-18, GW-31, and GW-34.
- Well casing locks should be replaced on wells GW-19 and GW-23.
- Well identification should be replaced on wells GW-15 and GW-35.

- During the Site visit, the new property/business owner of Down South Offroad identified the desire to install a water supply well to allow for the rinsing of bikes after trail riding activities. This potential well installation is currently only in the preliminary stage and has not been formally explored with EPA or TCEQ. The ROD does not specify any restrictions on land use except for banning the use of groundwater in the upper aquifer on Site, therefore, an upper aquifer well may not be feasible.
- Groundwater from wells SI-116 and INT-116 was collected during 5 of the 12 sampling events conducted at the Site. These wells are part of the French Limited Superfund Site (FLTG 1995), and are not included in the Site well list as described in the O&M Plan (Shaw 2012b). For all future sampling events conducted at the Site, groundwater collection from wells S1-116 and INT-116 should be discontinued.
- Specific analytical testing requirements for disposal of purge water from groundwater sampling are not included in the FSP (ECS 2013) or O&M Plan (Shaw 2012b). Specific analytical testing requirements for purge water from groundwater sampling should be added to the FSP (ECS 2013) and/or O&M Plan (Shaw 2012b).
- Documentation of disposal of purge water from groundwater sampling during the current review period was inconsistent and incomplete. A consistent means to document the disposal of purge water from groundwater sampling should be determined, and this should be incorporated into the FSP (ECS 2013) and/or O&M Plan (Shaw 2012b).
- An opportunity exists to remove selected groundwater monitoring wells from the current monitoring program based on historical metals and VOC sample results below action levels in a number of Site wells. It should be determined if the removal of groundwater monitoring wells from the sampling program is appropriate, and if so, with EPA consensus, monitoring wells should be selected for removal and proper plugging and abandonment.
VII. PROTECTIVENESS STATEMENT

Sitewide Protectiveness Statement

Protectiveness Determination: Short-term Protective

Protectiveness Statement:

I have determined that the remedy for the Sikes Disposal Pits Superfund Site is protective of human health and the environment in the short-term and will be protective in the long-term if recommendations listed below are implemented:

- Conduct an assessment of the MCLs and the HHC, and update the action levels as appropriate. Ensure that the laboratory detection limits are lower than the updated cleanup levels.
- Perform the five-year sampling event to reassess indicator parameters per the O&M Plan (Shaw 2012b).
- Between each sampling event conducted at the Site, perform the data evaluation as described in the O&M Plan (Shaw 2012b), and include results of the evaluation in the annual reports. Evaluate data trends to adjust sampling frequency as appropriate, upon discussion and approval of the EPA and reevaluate attenuation timeframes.
- Conduct an assessment of the detections of Site contaminants above the Texas surface water quality standards for the protection of human health and aquatic life.
- Assess the need for sediment sampling and if appropriate establish data quality objectives for sediment at the Site.
- Remove the fallen tree from the fenced enclosure for well GW-31 and repair the fence.

VIII. NEXT REVIEW

The next FYR report for the Sikes Disposal Pits Superfund Site is required five years from the completion date of this review.

(This page intentionally left blank)

.

.

,

APPENDIX A

REFERENCE LIST

(This page intentionally left blank)

- CB&I. 2013. Annual Groundwater Monitoring Report, Fiscal Year 2013 (9/2012 8/2013), Sikes Disposal Pits Federal Superfund Site, Crosby, Harris County, Texas, Site Number SUP034. 8/29.
- CB&I. 2014. Annual Groundwater Monitoring Report, Fiscal Year 2014 (9/2013 8/2014), Sikes Disposal Pits Federal Superfund Site, Crosby, Harris County, Texas, Site Number SUP034. 8/28.
- CB&I. 2015. Annual Groundwater Monitoring Report, Fiscal Year 2015 (9/2014 8/2015), Sikes Disposal Pits Federal Superfund Site, Crosby, Harris County, Texas, Site Number SUP034. 8/18.
- Environmental Chemistry Services (ECS). 2013. Field Sampling Plan for Operations and Maintenance Activities, Sikes Disposal Pits Federal Superfund Site, Crosby, Harris County, Texas. Version 3.0. 6/21.
- U.S. Environmental Protection Agency (EPA). 1986. Record of Decision Remedial Alternative Selection: Sikes Disposal Pits Superfund Site, Crosby, Texas. 9/18.
- EPA. 2002. OSWER Draft Guidance for Evaluating the Vapor Intrusion to Indoor Air Pathway from Groundwater and Soils (Subsurface Vapor Intrusion Guidance). EPA530-D-02-004. 11/2002.
- EPA. 2011. Fourth Five-Year Review Report for the Sikes Disposal Pits Superfund Site, Crosby, Harris County, Texas. 9/28.
- EPA. 2015a. Electronic mail from Mr. Ruben Moya of the EPA to Mr. Lam Tran of TCEQ, regarding deed notices for the Parker and Anderson properties. 10/19.
- EPA. 2015b. Regional Screening Level (RSL) Summary Table (TR=1E-06, HQ=1). 11/2015.
- FLTG, Inc. (FLTG). 1995. French Ltd. Project Monthly Progress Report, Submitted to U.S. Environmental Protection Agency-Region 6 and Texas Natural Resource Conservation Commission. 12/1995.
- Gilbert, R.O. (Gilbert). 1987. *Statistical Methods for Environmental Pollution Monitoring*. New York: Van Nostrand Reinhold.
- Hollander, M., and D. A. Wolfe (Hollander and Wolfe). 1973. *Nonparametric Statistical Methods*. Wiley, New York.
- Interstate Technology and Regulatory Council (ITRC). 2007. Vapor Intrusion Pathway: A Practical Guideline. 1/2007.

- Shaw Environmental, Inc. (Shaw). 2011. Annual Groundwater Monitoring Report, Fiscal Year 2011 (9/2010 8/2011), Sikes Disposal Pits Federal Superfund Site, Crosby, Texas, LPST Number SUP034. 4/21.
- Shaw. 2012a. Semi-Annual Groundwater Monitoring Report, Fiscal Year 2012 (9/2011 8/2012), Sikes Disposal Pits Federal Superfund Site, Crosby, Texas, Site Number SUP034. 8/29.
- Shaw. 2012b. Operations and Maintenance Plan, Sikes Disposal Pits Superfund Site, Crosby, Texas, Site Number SUP034. 10/2.
- Texas Commission on Environmental Quality (TCEQ). 2015. Letter from Lam Tran, TCEQ Project Manager, to Ruben Moya, EPA Superfund Division, Region 6, Regarding Fourth Five Year Review of Sikes Disposal Pits Federal Superfund Site – deed notices for the Parker and Anderson properties. 10/5.

APPENDIX B

SITE CHRONOLOGY

(This page intentionally left blank)

SITE CHRONOLOGY

Table B-1: Site Chronology

Event	Date		
Site used as open dump	1961–1967		
U.S. Environmental Protection Agency (EPA) and Texas Water Development	1981		
Board (TWDB) begin site assessments			
Site proposed to EPA's National Priorities List	10/1981		
EPA and TWDB execute initial cooperative agreement making the TWDB the	6/1982		
lead agency for the project			
Remedial investigation/feasibility study (RI/FS) performed	5/1983 - 6/1986		
Site finalized on the National Priorities List	9/1983		
Record of Decision (ROD) signed	9/18/1986		
Remedial design (RD) completed	12/1988		
Remedial action (RA) contract awarded to IT-Davy	4/1990		
Notice to proceed issued for RA Phase	10/1990		
RA Phase A completed, and Phase B begins	1/1992		
Trial Burn of the incinerator conducted; State issues interim operating	4/1992		
conditions to allow remediation to begin			
Trial Burn Report is approved and production operating conditions are issued	8/1992		
Excavation of contaminated soils is completed	5/1994		
Incineration completed	6/1994		
Incineration demobilization is completed	8/1994		
Final inspection conducted	4/1995		
Final completion certificate issued	12/1995		
Final Closeout Report issued by EPA	5/1997		
First five-year review completed by EPA	4/1998		
Second five-year review completed by EPA	9/2001		
Continued semi-annual groundwater monitoring and well maintenance	10/1995 - present		
Operations and Maintenance Plan prepared for the Site by Daniel B. Stephens	2/2003		
and Associates, Inc.			
Third five-year review completed by EPA	9/2006		
Semi-annual groundwater sampling event	12/2006		
Semi-annual groundwater sampling event	6/2007, 7/2007		
Semi-annual groundwater sampling event	3/2011		
Annual groundwater sampling event	8/2012		
Operations and Maintenance Plan, Revision VIII, prepared for the Site by	10/2/2012		
Shaw Environmental, Inc.			
Annual groundwater sampling event	12/2012		
Quarterly groundwater sampling event for Institutional Control (IC) data	4/2013		
collection			
Semi-annual groundwater sampling event in addition to IC data collection	6/2013		
Annual groundwater sampling event in addition to IC data collection	12/2013		
Quarterly groundwater sampling event for IC data collection	2/2014		
Semi-annual groundwater sampling event in addition to IC data collection	4/2014		
Quarterly groundwater sampling event for IC data collection	7/2014		
Well GW-27 re-sampled per direction of TCEQ	8/2014		

Event	Date
Annual groundwater sampling event	12/2014
Semi-annual groundwater sampling event	6/2015
Texas Commission on Environmental Quality letter to EPA stating that ICs for groundwater beneath the Parker and Anderson properties are not believed to be necessary as a result of quarterly groundwater monitoring at the Site between 4/2013 and 7/2014	10/5/2015
Annual groundwater sampling event	11/2015
Submittal of the Fifth Five Year Report for the Site	4/2016

APPENDIX C

SITE FIGURES

(This page intentionally left blank)





Legend Image: Surface Water Sample Location Vell Type Image: Sikes Deep Well Image: Sikes Shallow Well Image: Sike Boundary Site Boundary





Fifth Five-Year Review Sikes Disposal Pits Federal Superfund Site Crosby, Harris County, Texas





Sikes Disposal Pits Superfund Site Harris County, Texas



Sikes Disposal Pits Superfund Site Harris County, Texas



Sikes Disposal Pits Superfund Site Harris County, Texas





APPENDIX D

DEED NOTICE

(This page intentionally left blank)

V357381

DEED NOTICE

10/12/01 300631572 V357381

\$23.00

STATE OF TEXAS COUNTY OF HARRIS

This Notice is filed pursuant to the rules of the Texas Natural Resource Conservation Commission (TNRCC) and affects the real property described in Exhibit A (Property).

This Notice is required for the following reasons:

As identified in reports on file with the TNRCC concerning the Sikes Disposal Pits Superfund Site, the shallow groundwater beneath the Property contains certain chemicals of concern that exceed the TNRCC-approved protective concentration levels. Use of this shallow groundwater for any purpose is prohibited unless otherwise approved in writing by the TNRCC or until such time as all the chemicals of concern no longer exceed their respective protective concentration levels. The shallow groundwater is continuing to be monitored in accordance with specific requirements of a TNRCC-approved plan unless or until the TNRCC makes any modifications to the plan.

For additional information, contact:

-

-

00

۴

U.

TNRCC Central Records 12100 Park 35 Circle, Building D Austin, Texas 78753 Mail: TNRCC - MC 199 P O Box 13087 Austin, Texas 78711-3087

As of the date of this Notice, the record owners of fee title to the Property are M. W. McClendon with an address of P.O. Box 66160, Houston, Texas 77266.

This Notice may be rendered of no further force or effect only by a release executed by the TNRCC or its successor agencies and filed in the same Real Property Records as those in which this Notice is filed.

By:

Executed this 25^{μ} day of September 2001.

David L. Davis

Assistant Director, Remediation Division Texas Natural Resource Conservation Commission J

STATE OF TEXAS COUNTY OF TRAVIS

BEFORE ME, on this the 25 day of September 2001, personally appeared David L. Davis, Assistant Director of the of the Remediation Division of the Texas Natural Resource Conservation Commission, known to me to be the person whose name is subscribed to the foregoing instrument, and he acknowledged to me that he executed the same for the purposes and in the capacity herein expressed.

GIVEN UNDER MY HAND AND SEAL OF OFFICE, this the 25^{+h} day of September 2001.

LARBARA ANIN DAYWOOD MY COM AUGUST 08, 2005

Bachara ann Daywoo Q Notary Public in and for the State of Texas County of Tre UIS

My Commission Expires: 8 - 8 - 0 5

Property Description

(Tract 5)

:

\$

FILE FOR RECORD 8:00 AM

OCT 1 2 2001

County Clerk, Harrie County, Texas

PAUL RAY SMITH

north line of Sirocka 6.7198 acre tract (Title By Linit Survey) (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed Records) with for the Harris County Deed Records, but also being the POINT OF BEGINNING;

Records, said point also being the POINT OF BEGINNING; THENCE 5 87-38-56 W, with the south line of the Humphrey Jackson Labor, Abstract A-37, the south line of the Humphrey Jackson Survey, Abstract A-37, the north line of the Reuben White Survey, Abstract A-34, the south line of said Sirocka 6.7198 acre tract, a distance of 1068.10 feet passing a 5/8" iron rod set in concrete (X = 3240024.87, Y = 764708.07) marking the southeast corner of a appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, a distance of 1092.87 feet passing a 5/8" iron rod set in concrete (X = 3240000.13, Y = 764708.06) marking the northwest corner of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed records) recorded in Volume 760, Page 61 of the Harris County Deed Records, and the northeast corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, in all a distance of 1302.32 feet to a 5/8" iron rod set in concrete (X = 3239790.85, Y = 764699.47) marking the southeast corner of a 19.500 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Fage 227 of the Harris County Deed Records, the southwest corner of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, also being in the north line of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, the centerline of a Southwestern Bell Telephone Easement (20.00 foot width) recorded in Volume 1377, Page 580 and also Volume 1398, Pages 633 and 634 of the Harris County Deed Records;

THENCE N 2-21-04 W, with the west line of said M.W. Mc Clendon 19.9997 acre tract, the east line of said 19.5090 acre tract, the west line of said appurtenant easement, a distance of 479.96 feet to a 5/8" iron rod set in concrete (X = 3239771.16, Y = 765179.02) marking the westerly corner of the M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code 176-90-1631 of the Harris County Official Public Records of Real Property, the West corner of a appurtenant easment (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, and the easterly corner of a 19.5090 acre tract conveyed to Richard O. and Nabel Sikes and recorded in Volume 1595, Page 227 of the

544-88-112



Harris County Deed Records;

THENCE N 57-09-41 W, with the west line of said M.W. Mc M.M. Clendon 19.9997 acre tract, east line of said 19.5090 acre tract, a distance of 612.66 feet to a 5/8" iron rod set in concrete (X = 3239256.41, Y = 765511.25) marking the northwest corner of the M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, the northeast corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume of the Harris County Official Fublic Factors of A 19.5090 acre tract property, the northeast corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records, the southwest corner of the William R. Parker Jr. 85.1628 acre tract recorded under File No. J-305647, Film Code No. 069-89-0811, and File No. J-226172, Film Code 064-85-0167 of the Harris County Official Public Records of Real Property, said point also being in the easterly right of way line of T. 4 N.O. Railroad (Southern Pacific Railroad), the north line of the Humphrey Jackson Labor, Abstract A-84, and the south line of the Humphrey Jackson League;

THENCE S \$1-49-24 E, with the north line of said M.W. Mc Clendon 19.9997 acre tract, the south line of the said William R. Parker Jr. 85.1628 acre tract, a distance of 509.27 feet passing a 5/8" iron rod set in concrete (X = 2339760.50, Y = 765438.82) marking the northwast corner of a appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, a distance of 570.29 feet passing a 5/8" iron rod set in concrete (X = 233820.90, Y = 765430.14) marking the northeast corner of a appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, a distance of appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, a distance of s98.85 feet passing a 5/8" iron rod set in concrete (X = 240146.12, Y = 765383.41) marking the centerline of a Southwestern Bell Telephone easement (20.00 foot width) recorded in Volume 1398, Page 633, and Volume 2846, Page 476 Southwestern Bell Telephone easement (20.00 foot width) recorded in Volume 1398, Page 633, and Volume 2846, Page 476 of the Harris County Deed Records, in all a distance of 1833.89 feet to a $5/8^{*}$ iron rod set in concrete (X = 3241071.65, Y = 765250.43) marking the northeast corner of the H.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Fublic Records of Real Property, the southeast corner of the William R. Parker Jr. 85.1628 acre tract recorded under File No. J-305647, Film Code No. 069-89-0811, and File No. J-226172, Film Code No. 064-85-0167 of the Harris County Official Fublic Records of Real Property, said point also being in the west line of the T.A. Ramsey & L.L. Anderson 41.6778 acre tract recorded in Volume 4968, Fage 298 of the Harris County Deed Records; of the Harris County Deed Records;

THENCE S 2-21-04 E, with the east line of the said M.W. Mc Clendon 19.9997 acre tract, and the west line of the said

N -٩.

In

.

PAUL RAY SMITH

Blel

T.A. Ramsey & L.L. Anderson 41.6778 acre tract, a disardination of the set o

NOTE 1: M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property is subject to a appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, and a Southwestern Bell Telephone easement (20.00 foot width) recorded in Volume 1398, Page 633, and Volume 2846, Page 476 of the Harris County Deed Records.

112

-00-

₩ 10 Note 2: All reference distances made to State Highway 90 such as the centerline station, offset 1t., and width are actual surface distances shown on State Highway 90 Right of Way Map dated July 1929. All distances shown in parenthesis are also surface distances.



v357383

DEED NOTICE

STATE OF TEXAS COUNTY OF HARRIS

10/12/01 300631574 V357383

\$47.00

5

This Notice is filed pursuant to the rules of the Texas Natural Resource Conservation Commission (TNRCC) and affects the real property described in Exhibit A (Property).

This Notice is required for the following reasons:

As identified in reports on file with the TNRCC concerning the Sikes Disposal Pits Superfund Site, the shallow groundwater beneath the Property contains certain chemicals of concern that exceed the TNRCC-approved protective concentration levels. Use of this shallow groundwater for any purpose is prohibited unless otherwise approved in writing by the TNRCC or until such time as all the chemicals of concern no longer exceed their respective protective concentration levels. The shallow groundwater is continuing to be monitored in accordance with specific requirements of a TNRCC-approved plan unless or until the TNRCC makes any modifications to the plan.

For additional information, contact:

TNRCC Central Records 12100 Park 35 Circle, Building D Austin, Texas 78753 Mail: TNRCC - MC 199 P O Box 13087 Austin, Texas 78711-3087

As of the date of this Notice, the record owners of fee title to the Property are Richard and Mabel Sikes with an address of 709 Sheldon Road, Houston, Texas 77530.

This Notice may be rendered of no further force or effect only by a release executed by the TNRCC or its successor agencies and filed in the same Real Property Records as those in which this Notice is filed.

Executed this 25^{H_1} day of September 2001.

By: David L. Davis

Assistant Director, Remediation Division Texas Natural Resource Conservation Commission

STATE OF TEXAS COUNTY OF TRAVIS

BEFORE ME, on this the $\frac{25^{++}}{2}$ day of September 2001, personally appeared David L. Davis, Assistant Director of the of the Remediation Division of the Texas Natural Resource Conservation Commission, known to me to be the person whose name is subscribed to the foregoing instrument, and he acknowledged to me that he executed the same for the purposes and in the capacity herein expressed.

GIVEN UNDER MY HAND AND SEAL OF OFFICE, this the 25⁴⁴ day of September 2001.

Barbara ann Daywood Notary Public in and for the State of Texas County of Jravis

BARBARA ANN DAYWOOD COMMISSION EXPRES AUGUST 08, 2005

My Commission Expires: 8-8-05-

5



••



÷

· · ·

.



in Volume 3085, Page 643 of the Harris County De recorded in Volume 760, Page 61 of the Marris Records;

114

12.2

THENCE S 87-38-56 W, with the south line of the Humphrey Jackson Labor, Abstract A-37, the south line of the Humphrey Jackson Survey, Abstract A-37, the north line of the Reuben White Survey, Abstract A-84, the south line of said M.W. Hc Clendon 19.9997 acre tract, the north line of said Sirocka 6.7198 acre tract, a distance of 1092.87 feet to a 5/8" iron rod set in concrete (X = 3240000.13, Y = 764708.06) marking the northwest corner of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed records) recorded in Volume 760, Page 61 of the Harris County Deed Records, and the northeast corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, and being in the south line of the M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property;

THENCE S 87-38-56 W, with the south line of the Humphrey Jackson Labor, Abstract A-84, the south line of the Humphrey Jackson Survey, Abstract A-37, the north line of a 17.5362 acre tract conveyed to Jim and Edna Love, the south line of M.W. Mc Clendon 19.9997 acre tract, a distance of 208.45 feet to a 5/8" iron rod set in concrete (X = 3239790.85, Y = 76459.47) marking the southeast corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records, the southwest corner of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, also being in the north line of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, said point also being located in the centerline of a Southwestern Bell Telephone Resement (20.00 foot width) recorded in Volume 1377, Page 580 and also Volume 1398, Pages 633 and 634 of the Harris County Deed Records, said point also being the POINT OF BEGINNING:

THENCE S 87-38-56 W, with the south line of the Humphrey Jackson Labor, Abstract λ -37, the south line of the Humphrey Jackson Survey, Abstract λ -37, the north line of the Reuben White Survey, Abstract λ -34, the south line of said 19.5090 acre tract, and the north line of said 17.5362 acre tract, a distance of 1781.24 feet passing a 5/8" iron rod set in concrete (X = 3238011.11, Y = 764626.40) marking the south line of a 19.5090 acre tract conveyed to Richard O. and Mabel

40 Sikes and recorded in Volume 1595, Page 227 of the Hard's County Deed Records, and the north line of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, in all a distance of 1930.33 feet to a point for corner (X = 3237862.14, Y = 764620.28) marking the southwest corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records, and \$45 Volume 1595, Page 227 of the Harris County Daed Records, and the northwest corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property;

بالبد سرموجيست جيدوا الدليوجيد ا

.. _

STERES TO

. RAY SMITH

4040 4646

THENCE N 2-21-04 W, with the west line of said 19.5090 acre tract, a distance of 151.70 feet to a point for corner (X = 3237855.92, Y = 764771.85) marking the northwest corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records, said point also being in the southerly right of way line of the T.4 N.O. Railroad (Southern Facific Railroad);

٧ -Ŧ

000

THENCE N 74-53-12 E, with the northerly line of said 19.5090 acrs tract, and the southerly right of way line of said T. & N.O. Railroad (Southern Pacific Railroad) a distance of 113.86 feet passing a 5/8" iron rod set in concrete (X = 3237965.84, X = 764801.54) marking the north line of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes recorded in Volume 1595, Page 227 of the Harris County Deed Records, and the southerly right of way line of T. & N.O. Railroad (Southern Pacific Railroad), in all a distance of 725.13 feet to a 5/8" iron rod set in concrete (X = 323855.97, Y = 764960.91) marking the northerly corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records, said point also being in the southerly right of way line of T. & N.O. Railroad (Southern Pacific Railroad), said point also being the Point of Curvature of a tangent curve in a northeasterly direction;

THENCE with the southeasterly right of way line of T. ϵ N.O. Railroad (Southern Pacific Railroad), and the northwesterly line of said 19.5090 acre tract continuing along a tangent curve to the left in a northeasterly direction (Central Angle = 22-52-50; Radius = 1575.26 feet; Chord = N 63-26-47 E, 624.89 feet) an arc distance of 629.06 feet to a 5/8" iron rod sat in concrete (X = 322614 94 X = 265240.26) marking rod set in concrete (X = 3239114.94, Y = 765240.26) marking the northerly corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes recorded in Volume 1595, Page 227 of the Harris County Deed Records, said point also being in the southeasterly right of way line of T. & N.O. Railroad (Southern Pacific Railroad);

THENCE N 37-59-38 W, with the westerly line of said 19.5090



acre tract, and the Northeasterly right of way line of TAM N.O. Railroad (Southern Pacific Railroad), a distance of M_{1} 99.99 feet to a $5/8^{m}$ iron rod set in concrete (X = M_{1} 3239053.39, Y = 765319.06) marking a northwesterly corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes recorded in Volume 1595, Page 227 of the Harris County Deed Records, and the southeasterly right of way line of T. & N.O. Railroad (Southern Pacific Railroad);

¹⁴€.

1144

00

THENCE with the southeasterly right of way line of the T. & N.O. Railroad (Southern Pacific Railroad), and the northwesterly line of said 19.5090 acre tract continuing along a tangent curve to the left in a northeasterly direction (Central Angle = 10-52-25; Radius = 1475.27 fact; Chord = N 46-34-10 E, 279.55 feet) an arc distance of 279.97 fact to a 5/8" iron rod sat in concrete (X = 3239256.41, Y = 765511.25) marking a northerly corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes recorded in Volume 1595, Page 227 of the Harris County Deed Records, said point also marking the northwesterly corner of M.W. Mc Clendon 19.997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, and the southwest corner of the William R. Parker Jr. 85.1628 acre tract recorded under File No. T-305647, Film Code No. 069-89-0811 of the Harris County Official Public Records of Real Property, said point also being in the southeasterly right of way line of the T. & N.O. Railroad (Southern Pacific Railroad), the north line of the Humphrey Jackson Labor, Abstract A-37, and the south line of the Humphrey Jackson League, Abstract A-37;

THENCE S 57-09-41 E, with the easterly line of said 19.5090 acre tract, and the westerly line of said M.W. Mc Clendon 19.9997 acre tract, a distance of 612.66 feet to a 5/8" iron rod set in concrete (X = 3239771.16, Y = 765179.02) marking the easterly corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes recorded in Volume 1595, Page 227 of the Harris County Deed Records, and the westerly corner of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property;

THENCE S 2-21-04 E, with the east line of said 19.5090 acre tract, and the west line of said M.W. Mc Clendon 19.9997 acre tract, a distance of 479.96 feet to the POINT OF BEGINNING, and containing a computed area of 19.5090 acres (849,814 square feet).

Note 1: 19.5090 acre tract is shown on IT/DMC Plat 1002-0021 dated 4-15-91.

Note 2: All reference distances made to State Highway 90, such as centerline station, offset 1t., and width are actual surface distances shown on State Highway 90 Right of Way Map

Plf. Site

_

Coordinate File Name: EDP-CS.CRD Luwest pt #: 1 Hisbert pt #: 2020 Nob # : 500500 Description: SIKES DISPOSAL PITS COORDINATE FILE FOR SCHOORFY SURVEY # of there. in point descr.: 10

	FROM	TYPE		SEARI	NĞ	DISTANCE	CT !	NC	RTHING]	LASTING
	ETART						948	7647	58.719	32413	245.453
	948	INV	\$ 87-	-49-24	W	155.433	615	7647	52,890	32410	092.075
	615	S.E.	S 37-	-38-56	W	1068.102	944	7647	05.074	32400	024.873
	615	S.S.	5 87.	-38-66	W	1092.868	913	7847	08.056	32400	000.128
	615	inv	\$ 87.	-2859	W	1302.321	901	7646	99.465	32397	790.851
	START						901	7646	89.465	32391	790.851
	901	5.5.	5 87.	-38-56	W	1781.236	984	7646	26.395	32380)11.114
	901	INV	S 87-	-38-56	W	1930.331	914	7646	20.279	S2378	362.144
	914	INV	N 2.	-21-04	W	151.699	935	7647	71.850	32378	355.921
L)	935	S.S.	N 74-	-53-12	E	113.856	985	7648	01.536	32379	965.839
÷.	935	INV	N 74-	-53-12	Е	725.128	934	7649	60.913	32385	55 5.96 9
÷.	RADIUS	5 POINT					. 904	7664	81.684	32381	145.253
-	DELTA:	:- 22-5	2 - 50 I	R= 15	75.	257 A=	629.061	Ç=	624.889	T=	318.778
Ő	P.C	P.T.			_						
W	934	INV	N 63-	-26-47	E	624.889	933	7652	40.260	32391	14.945
1 4-10 %	933	INV	N 37-	-59-38	W	29.991	932	7653	19.060	32390)53.391
₩	RADIUS	5 POINT					904	7664	81.684	32381	45.253
Ú.	DELTA	- 10-5	2-25 I	R= 14	7 5 .	266 A=	279.974	C=	279.554	T=	140,409
	P.C	P.T.									
	932	INV	N 46-	-34-10	T.	279.554	903	7655	11.247	32392	256.405
	903	INV	5 57-	-09-41	E	612.659	902	7651	79.017	32397	71.162
	902	INV	S 2-	-21-04	Ξ	479.956	901	7646	99.465	32397	790.851
							9 01	7646	99.465	32397	90.851
÷			<u>N</u> 0-	-0000	5	0.000	CLOSIN	g line Ce tra	VERSED		
	>10000	0000 Pi	RECISI	ION							
	AREA:	849	313.69	Squa	-	Feet 1	9.6090 /	Acres			

تعادد فاستعلم والتستنيس - • CAUT. ALL PROTECTION IS AFFORDED CHAIT UNDER THE TERMS OF THE PROPOSED POLICY. , RETEWART TITLE (L.). COMPANY ASSUMES NO LIABLITY FOR FRANCISCO CONTROL ON OWNERS IN THIS REPORT OR FOR VERSAL STATELIERT, ") COMPANY ASSUMES NO LIABLITY FOR FRANCISCO ON OWNERS IN THIS REPORT OR FOR VERSAL STATELIERT, ") COMPANY ASSUMES NO LIABLITY FOR FRANCISCO ON OWNERS IN THIS REPORT OR FOR VERSAL STATELIERT, ") COMPANY ASSUMES NO LIABLITY FOR FRANCISCO ON OWNERS OF THE SECOND WITHIN THE TELESCOVE THEORY OF THE CAUTALITY IN THE SECOND ON THE SECOND THE SECOND OF THE SECOND OF THE SECOND WITHIN THE TELESCOVE THEORY OF THE SECOND ON THE SECOND OF THE CONTROL OF THE SECOND OF THE CONTROL OF THE SECOND OF THE THEORY MALE OF THE SECOND OF THE CONTROL OF THE SECOND OF THE THEORY MALE OF THE SECOND OF THE THEORY ASSUMES THE SECOND OF THE SEC

.

nump. June 13. 1988 6 8:00		ASTR - RON ORR
	67	No. 881133790
EXAMINER:		
	TITLE REPORT	506-16-2640

APPLICANT: TBA

Ŧ;

4

4

٣

e

Ö,

ö

÷ ۴

In,

. . . .

1.61

Sanimation from: Records of STEVIART TITLE COMPARY Subject or Claims of premot accessing characteries in area and boundaring unpublishits for labor a praterial in converting with reports or new interviewments: unpublisher.

TITLE GOOD IN: RICHARD C. SIKES and wife, MABIL SIKES by virtue of Dated from ELIZABETH SIMBING MASTERSON, et al.datad Harch 1, 1947 recorded in Volume 1995 Page 227 of the Deed Records of Earris County, Texas.

CORRECT DESCRIPTION OF PROPERTY;

All that tract of land out of the SUMPEREY JACKSON LEAGUE AND LABOR containing Twenty (20) acres and described in Exhibit "A" attached.

SUBJECT TO:

DESTRICTIONS.

None of Record.

EASEMENTS AND RIGHTS OF WAY:

Subject to any casements, rights-of-way, roadways, encroachments, etc., which a survey or physical inspection of the premises might disclose.

MINERALS AND/OF ROYALTIES:

All the oil, gas and other minorals, the royalties, bonuses, rentals and all other rights in connection with same all of which are expressly excepted berefrom and not insured hereunder, as same are set forth in instrument recorded in Volume 1595, Fage 227 of the Deed Records of Marris County, Texas.

OTHER EXCEPTIONS:

. •

Subject to the terms, conditions and stipulations of any and all Lease Agreements, amendments and supplements thereto. existing with the tenants in possession, whether written or oral and whether recorded or unrecorded. ۰.

Subject property is subject to overflow from the flood waters of the San Jacinto Miver after extra heavy upstream rains.

Continued on next page

....

GF NO. 88113379D TITLE REPORT CONTINUATION

OTHER EXCEPTIONS CONTINUED:

Subject to the rights for Lateral Support of any and all easements, right of way, pipelines, roadways that cross subject property whether written or oral and whether recorded or unrecorded.

The company by this report does not insure against the exercise of power of competent governmental authority to declare the above described property to be contaminated with hazardous and/or toxic materials.

LIENS:

 \sim

τ

0 4

स स

Ó

-Ö-

4

*•**.**] ...

Ű

Note: We find no outstanding liens of record affecting the subject property. Inquiry should be made concerning the existence of any unrecorded lien or other indebtedness which could give rise to any security interest claim in the subject property.

MISCELLANEOUS:

We are to be furnished with a survey, complete with the correct metes and bounds description of the subject property made by a licensed Public Surveyor of the State of Texas, suitable to this Title Company. When same is submitted, it is to be returned to Examiner for inspection and approval.

The property covered herein is subject to the terms, conditions, provisions and stipulations of Ordinance \$85-1878 of the City of Eouston enacted October 23, 1985 pertaining to the platting and replatting of real property and the establishment of building set back lines within such boundaries. This is pointed out for information and is not intended to waive the provisions of any title policy issued which excludes from coverage loss or damage as a consequence of the exercise and enforcement or attempted enforcement of governmental police powers over land described therein.

There is pending in the 125th Judicial District Court of Harris County, Texas, Cause No. 8624307 action styled Richard Sikes vs. Jim Love Prior to closing, require said suit be released with prejudice.

C

.

Exhibit A "

Ľ

.

÷

The land above poforred to is situated in Harris County, Toxas, and is described by mates and bounds as follows, to-wit:

1440

0

17 17 10

*••£.

Twenty (20) acress of land, more or less, out of the Humphrey Jackson League and Labor, in Marris County, Texas, situated on the east bank of San Jacinto River, about eighteen miles northeast of the City of Houston, and described by metes and bounds as follows:

Beginning at a codar stump and pipe on the east bank of the San Jacinto River (from which a pagnolis tree marked "X" bears E, 56t deg, E, 53 ft. and a magnolis tree marked "X" bears S, 65t deg. E, 50 ft.) the south west corner of the Humphrey Jackson Labor;

Thence North along the east bank of the San Jacinto River about 240 ft. to the south right of way line of the Texas and Hew Orleans Railroad, 200 ft. south of the center of the track of said railroad for the north west corner;

Thence following the south right of way line of the said railroad in an east and morth direction, 1210 ft. parallel and 200 ft. south of the center of said railroad track, for corner;

Thence North and west along a jog in said right of way 100 ft. to a point 100 ft. from the center of the track of said railroad, for a corner;

Thence east and north 280 ft. along the south right of way line of said railroad, parallel and 100 ft. from the center of the track of said railroad, to a point, being the intersection of the north line of the Humphrey Jackson Labor, and the south right of way line of the Taxas and New Orleans Railroad, for corner;

Thence 3. 45 deg. E. 500/It. for a corner; Thence 3. 480 It. to the south line of the Humphray Jackson Labor for a corner;

- 1 -

Thence W. 1862.4 ft. to the place of beginning, containing twenty [20] seres of lund, hore or less, including a lake, known as Round or Tank Leke, and being the sume property conveyed by H. Masterson to W. A. Childress, et al, Trustees of the Houston Local Council Boy Scouts of America, the use of which land has been abandoned by said Heuston Local Council Boy beouts of America and was reconveyed by the Trustees there.f to the Estate of H. Masterson, deceased;

....

. . .

. ...


TEXAS WATER COMMISSION Sikes Disposal Pits Remedial Action Metes And Bounds Description 6.7198 Acres (292,713 square feet) Reuben White Survey, A-84 Harris County, Texas

A tract of land being 6.7198 acres (292,713 square feet) out of the Reuben White Survey, Abstract A-84, Harris County, Texas and being all of that 6.7198 acres Sirocka tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed Records) recorded in Volume 760, Page 61 of the Harris County Deed Racords, said tract being more particulary described by mates and bounds as follows with all bearings and coordinates referenced to the Texas Coordinate System (N.A.D. 1927) South Central Zone (all distances and acreages herein recited are grid and may be converted to surface by multiplying by the combined factor 1.00009):

1151

ģ

Ö

lî

.

BEGINNING at a 5/8" iron rod in concrete (X = 3241245.45, Y = 764758.72) set in the northerly right of way line of State Highway 90 (centerline station = 36+23.43, offset lt. = 110.00 feet) said point marking the northeast corner of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed Records) recorded in Voluma 760, Page 61 of the Harris County Deed Records, the southerly corner of the T.A. Ramsey & L.L. Anderson 41.6778 acre tract recorded in Volume 4968, Page 298 of the Harris County Deed Records, said corner also being located in the in the south line of the Humphrey Jackson Labor, Abstract A-37, and the north line of the Reuben White Survey, Abstract A-84;

THENCE S 67-00-43 W, with the northerly right of way line of State Highway 90 (offset lt. = 110.00 feet) and the southerly line of said Sirocka 6.7198 acre tract, a distance of 223.41 feet to a 5/8" iron rod set in concrete (X = 3241039.788, Y = 764671.47) marking the southerly corner of Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volumes 3085, Page 643 of the Harris County Deed Records) recorded in Volume 760, Page 61 of the Harris County Deed Records, said point also being in the northerly right of way line of State Highway 90 (centerline station = 36+23.43, offset lt. = 110.00 feet);

THENCE S 22-59-17 E, with the northerly right of way line of State Highway 90, and the southerly line of said Sirocka

PAUL RAY SMITH

southwest corner of the Sirocka 6.7198 acre tract files Limitation (Advarse Possession) by Richard O. and Maber are recorded in Volume 3085, Page 643 of the Harris County Dead Maber are souther and the southeastering corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, said point also being in the northerly line of a 20.2137 acre tract conveyed to Jim Love and recorded under File No. L-283655, Film Code No. 189-30-1254 of the Harris County Official Public Records of Real Property;

THENCE N 2-21-04 W, with the west line of said Sirocka 6.7198 acre tract and the east line of said 17.5362 acre tract, a distance of 363.89 feet to a 5/8 iron rod set in concrete (X = 3240000.13, Y = 764708.06) marking the northwest corner of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed Records) recorded in Volume 760, Page 61 of the Harris County Deed Records, also marking the northeast corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, said point being in the south line of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, the north line of the Reuben White Survey, Abstract A-34, the southerly line of the Humphrey Jackson Labor, Abstract A-37, Abstract A-37;

THENCE N 87-38-56 E, with the north line of said Sirocka 6.7198 acre tract, the south line of said M.W. Mc Clendon 19.9997 acre tract, the north line of the Reuben White Survey, Abstract A-84, the south line of the Humphrey Jackson Labor, Abstract A-37, the south line of the Humphrey Jackson Survey, Abstract A-37, a distance of 24.77 feet passing a 5/8" iron rod set in concrete (X= 3240024.87, Y = 764709.07) marking the southeast corner of a appurtenant easement (60.00 foot width) recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, in all a distance of 1092.87 feet to a 5/8"iron rod set in concrete (X = 3241092.08, Y = 764752.89) marking the southeast corner of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, in all a distance of 1092.87 feet to a 5/8"iron rod set in concrete (X = 3241092.08, Y = 764752.89) marking the southeast corner of M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, the southwest corner of the T.A. Ramsey & L.L. Anderson 41.6778 acre tract recorded in Volume 4968, Page 298 of the Harris County Deed Records, said point also being in the north line of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed

544-88-115

• • •



fall. foite

Coordinate File Name: SDP-CS.CRD Jeb # : 500600 Lovast 35 %: 1 Highest pt #: 2020 Description: SIKES DISPOSAL PITS COORDINATE FILE FOR BOUNDARY SURVEY # of chars. in point descr.: 10

NORTHING EASTING FROM TYPE BEARING DISTANCE ŤŌ -----764758.719 3241245.453 START 948 948 INV S 67-00-43 W 223.407 635 764671.470 3241039.788 3241051.503 INV 8 22-59-17 E 8 67-00-43 W 29.997 635 949 764643.855 INV 699.936 950 764370.503 3240407.151 949 950 INV N 22-59-17 W 69,994 951 764434.939 3240379.815 764351.359 3240182.799 951 INV S 67-00-43 W 214.012 952 INV 5 87-38-56 W 764344.472 764708.058 952 167.885 917 3240015.055 INV N 2-21-04 W 917 363.892 913 3240000.128 913 S.S. 764709.074 3240024,873 N 87-38-56 E 24,766 944 764752.890 N 87-38-56 E 913 INV 1092.868 615 3241092.075 615 INV N 87-49-24 E 153.488 948 764758.719 3241245.453 764758.719 3241245.453 948 N 0-00-00 E 0.000 CLOSING LINE 3016.479 DISTANCE TRAVERSED >10000000 PRECISION

6.7198 Acres

2

292713.24 Square Feet

0	AREA:
1	
٧.	
-	

IA

In

-

-

۵

Ö.

Ú

. *



V357382

DEED NOTICE

STATE OF TEXAS COUNTY OF HARRIS

10/12/01 300631573 V357382 * \$29.00

1

مرين بر

This Notice is filed pursuant to the rules of the Texas Natural Resource Conservation Commission (TNRCC) and affects the real property described in Exhibit A (Property).

This Notice is required for the following reasons:

As identified in reports on file with the TNRCC concerning the Sikes Disposal Pits Superfund Site, the shallow groundwater beneath the Property contains certain chemicals of concern that exceed the TNRCC-approved protective concentration levels. Use of this shallow groundwater for any purpose is prohibited unless otherwise approved in writing by the TNRCC or until such time as all the chemicals of concern no longer exceed their respective protective concentration levels. The shallow groundwater is continuing to be monitored in accordance with specific requirements of a TNRCC-approved plan unless or until the TNRCC makes any modifications to the plan.

For additional information, contact:

TNRCC Central Records 12100 Park 35 Circle, Building D Austin, Texas 78753 Mail: TNRCC - MC 199 P O Box 13087 Austin, Texas 78711-3087

As of the date of this Notice, the record owners of fee title to the Property are Jim and Edna Love with an address of \angle 211 Highway 90, Crosby, Texas 77532.

This Notice may be rendered of no further force or effect only by a release executed by the TNRCC or its successor agencies and filed in the same Real Property Records as those in which this Notice is filed.

By:

Executed this 25 th day of September 2001.

David L. Davis

Assistant Director, Remediation Division Texas Natural Resource Conservation Commission

STATE OF TEXAS COUNTY OF TRAVIS

BEFORE ME, on this the 25^{-h} day of September 2001, personally appeared David L. Davis, Assistant Director of the of the Remediation Division of the Texas Natural Resource Conservation Commission, known to me to be the person whose name is subscribed to the foregoing instrument, and he acknowledged to me that he executed the same for the purposes and in the capacity herein expressed.

GIVEN UNDER MY HAND AND SEAL OF OFFICE, this the 25^{+h} day of September 2001.

A DECKSTON OF THE OWNER OF BARBARA ANN DAWWOOD MY COMMISSION EDPRES AUGUST 08, 2005

Salbace ann Daywood Notary Public in and for the State of Texas County of Travis

My Commission Expires: 8-8-05

544-88-1125



TEXAS WATER COMMISSION Sikes Disposal Pits Remedial Action Metes And Bounds Description 17.5362 Acres (763,876 square feet) Reuben White Survey, A-84 Harris County, Texas

A tract of land being 17.5362 acres (763,876 square feat) out of the Reuben White Survey, Abstract A-84, Harris County, Texas and being all of that 17.5362 acre tract conveyed to Jim and Edna Love by deed recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property; said tract being more particulary described by metes and bounds as follows with all bearings and coordinates referenced to the Texas Coordinate System (N.A.D. 1927) South Central Zone (all distances and acreages herein recited are grid and may be converted to surface by multiplying by the combined factor 1.00009):

N 19

0

10

3

COMMENCING at a 5/8" iron rod in concrete (X = 3241245.45, Y = 764758.72) set in the northerly right of way line of State Highway 90 (centerline station = 36+23.43, offset 1t. = 110.00 feet) said point marking the northeast corner of the Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded in Volume 3085, Page 643 of the Harris County Deed Records) recorded in Volume 760, Page 61 of the Harris County Deed Records, the southerly corner of the T.A. Ramsey & L.L. Anderson 41.6778 acre tract recorded in Volume 4968, Page 298 of the Harris County Deed Records, said corner also being located in the in the south line of the Humphrey Jackson Labor, Abstract A-37, and the north line of the Reuben White Survey, Abstract A-84;

THENCE S 87-49-24 W, with the south line of the Humphrey Jackson Labor, Abstract A-84, the south line of the Rumphrey Jackson Survey, Abstract, A-84, the north line of the Rumphrey Muite Survey, Abstract A-37, south line of said T.A. Ramsey & L.L. Anderson 41.6778 acre tract, and the north line of said Sirocka 6.7198 acre tract, a distance of 153.49 feet to a $5/8^{\circ}$ iron rod set in concrete (X = 3241092.08, Y = 764752.89) marking the southwest corner of said T.A. Ramsey & L.L. Anderson 41.6778 acre tract recorded in Volume 4968, Page 298 of the Harris County Deed Records, the southeast corner of the M.W. Mc Clendon 19.9997 acre tract recorded under File No. G-838726, Film Code No. 176-90-1631 of the Harris County Official Public Records of Real Property, and being in the north line of Sirocka 6.7198 acre tract (Title By Limitation (Adverse Possession) by Richard O. and Mabel Sikes recorded

TX-D-83050



Official Public Records of Real Property, and also dairs in the southwest corner of a 17.5362 acre tract conveyed and and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property;

THENCE N 3-56-04 W, with the westerly line of said 17.5378 acre tract a distance of 15.62 feet to a point for corner (X = 3237953.99, Y = 764275.48) marking the westerly corner of a 17.5362 acre tract conveyed to Jim and Edna Lova and recorded under File No. K-371045, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property;

THENCE N 14-57-04 W, with the westerly line of said 17.5362 acre tract a distance of 152.02 feet passing a point for corner (X = 3237514.77, Y = 764422.35) in the centerline of a Southwestern Bell Telephone easement (20.00 feet in width) records in Volume 1377, Page 580 of the Harris County Deed Records, in all a distance of 356.87 feet to a point for corner (X = 3237861.92, Y = 764620.27) marking the northwest corner of a 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property, and also marking the southwest corner of a 19.5090 acre tract conveyed to Richard O. and Mabel Sikes and recorded in Volume 1595, Page 227 of the Harris County Deed Records;

N T T

4-00

4....,

ĽĎ.

THENCE N 87-38-56 E, with the north line of said 17.5362 acre tract, the south line of said 19.5090 acre tract, the north line of the Reuben White Survey, Abstract A-37, the south line of the Humphrey Jackson Labor, Abstract A-84, the south line of the Humphrey Jackson Survey, Abstract A-84, a distance of 149.10 feet passing a set $5/8^{\circ}$ iron rod set in concrete (X = 3238011.11, Y = 764626.40), a distance of 1930.33 feet passing a $5/8^{\circ}$ iron rod set in concrete (X = 3239790.85, Y = 764699.47) marking the southeast corner of a 19.5090 acre tract conveyed to Richard 0. and Mabel Sikes and recorded in Volume 1595, Fage 227 of the Harris County Deed Records, said point also being in the centerline of a Southwestern Bell Telephone easement (20.00 feet width) recorded in Volume 1377, Fage 580, Volume 1398, Fage 633, Volume 2846, Fage 476 of the Harris County Deed Records, in all a distance of 2139.79 feet to the POINT OF BEGINNING, containing a computed area of 17.5362 acres (763,876 square feet).

NOTE 1: 17.5362 acre tract conveyed to Jim and Edna Love and recorded under File No. K-371046, Film Code No. 036-71-1889 of the Harris County Official Public Records of Real Property is subject to an ingress and egress easement shown on Exhibit "A" of the Final Judgement, Cause No. 477,742 of the 157th District Court, Harris County, Texas. Said 17.5362 acre tract

TX-D-83052

		OF	Se.	
k	6/2	*	6	Å
(E .	PAUL	RAY	SMIT	H)
0		464		Ĵ
	-100			2

fl. linte

Coordinate File Name: SNP-C9.CRN Lowest pt #: 1 Highest pt #: 2020 Job # : 500600 Description: SIKES DISPOSAL PITS COORDINATE FILE FOR BOUNDARY SURVEY 4 of chars. in point descr.: 10

	FROM	type		3éarin	Ģ	DISTANCE	TC:	NORTHING	EASTING	•
	START						, 948	764758.719	3241245.453	****
	948	INV	S	87-49-24	W	153.488	615	764752.890	3241092.075	
	615	S.S.	Ş	37-38-56	W	1068.102	944	764709.074	3240024.873	
	615	INV	Ş	87-38-56	М	1092.868	913	764708.058	3240000,128	
	START						913	764708.058	3240000.128	
	913	INV	S	2-21-04	Z	363,892	917	764344.472	3240015,055	
	917	S.S.	S	87-38-56 1	W	1673.814	982	764275.808	\$238342.650	
11	917	INV	S	87-38-56 1	W	2061.503	916	764259.904	3237955.288	
(Ū	916	INV	N	3-56-04 1	H	15.619	915	764275.486	3237954.216	
-	9 15	S.S.	N	14-57-04	M	152.018,	974	764422.357	3237914.996	
H.	915	INV	N	14-57-04	W	358.874	914	764620.279	3237862.144	
ï	914	S.S.	N	87-38-56	E	149.095	984	764626,395	3238011.114	
in in	914	S.S.	N	87-33-56 1	E	1930.331	901	764699.465	3239790.551	
# #	914	INV	N	87-38-56	K	2139.785	\$13	764708.058	3240000.128	
ŵ							913	764708.058	3240000.128	
1			N	0-00-00	E	0.000	CLOSING	LINE		
V.						4937,673	DISTANC	E TRAVERSED		
۳.	>10000	00000	PREC	VISION						
Ŵ.	AREA:	76	3875	55 Square	8	Feet 17	7.5362 A	cres	. •	

1.19

TX-D-83054

LEVE PROPERTY 1

CALTTON. PROTECTION IS APPORDED ONLY LINDER THE TEAMS OF THE PROPOSED POLICY. STEWART TITLE GUARANTY COMPARY ASSUMES NO LABLITY FOR GRACHS DR OMISSIONS IN THIS REPORT OR FOR VERSAL STATEMENT. This is a case of a problemary caper made for use of Sinvert This Guaranty Company early, to desirate propersion of the incurance balance can be baund. If a capy of furthered to the perior to the Verbaction is to foolbate propersion of the necestary incurdings, is paint and correst requirements if any, and to the Methaction of the Company's tole search foom which and the Company may rely. More all the information semistive fuels from all the company's tole search foom which and the Company may rely. More all the information semistive fuels, or the absence of other information, company of a method series which is not disclosed person, the Company shall not be the failed in the statement of size of for any verbal statement relevant teachers to be stated, on state probably the company shall not be failed to the company's tole series of the teacher of the statement which is not disclosed person, the Company shall not be failed to which all the statement point of for any verbal statement relevant teachers. The Company shall not be failed to save the default undership to be capitary in terms of the statements and there the person of the period of the state is set of the statement of the teacher's the their internets the terms of the period of the state between the failed there are an interview to the terms of the period period of the state state of the statement of the statement

TITLE REPORT

GP NO. 88113379-8

• •

DATE: June 13, 1988 & 8:00 A.N. CLOSER: RON ORR

APPLICANT: TEA

.

Representation from: Recently of STREART TITLE COMPANY Subject to: Claims of present exception; distributions in area and boundaring: engoid bills for labor or subscript in connection with reports or new improvements; empoid tence.

TITLE GOOD IN: JIN LOVE and wife, EDNA LOVE by wirtue of Deed from GRACE D. HC COY dated August 11, 1982 recorded under Clerk's File No. X-371046 of the Real Property Records of Earris County, Texas.

CORRECT DESCRIPTION OF PROPERTY:

All that certain tract of land located in the Rouben White Survey, Abstract 84, in Earris County, Texas, containing 17.584 acres of land, more or less, and described in Exhibit "A" attached.

SUBJECT TO:

RESTRICTIONS:

None.of Record.

EASENERTS AND RIGETS OF WAY:

Subject to any easements, rights-of-way, roadways, encroachments, etc., which a survey or physical inspection of the premises might disclose.

Lasements granted to Southwestern Bell Telephone Company an reflected in instruments recorded in Volume B21, Page 28, Volume 2846, Page 476 and Volume 2849, Page 674 all of the Deed Records of Marris County, Taxas.

Unlocated pipeline right-of-way easement is favor of Nouston Gulf Gas Company as set forth in instrument recorded in Volume 815, Page 210 of the Deed Records of Marris County, Texas.

Subject to the sights of the General Public as to ingress and egress that passes through subject property as set forth in Final Judgement under Cause No. 477742 if the 157th Judicial District in the District Court of Harris County, Texas.

MINERALS AND/OR ROYALTIES:

Although there are no specific reservations of minerals on this property, all the oil, gas and other minerals, the royalties, Continued on next page

TX-D-83056

ىلى ^{تە}رەر

·· ,

1.58

GF NO. 88113379-8 TITLE REPORT CONTINUATION

:

MISCELLANFOLS CONTINUED: Abstract of Judgment filed May 26, 1981 in the amount of \$1,204.04 plus cost and interest, in favor of Montgomery Hard J Co., Inc., against Jim D. Love dbs Jim Love Sand Co., recorded under Clerk's File No. G-985030 of the Real Property Records of Espris County, Texas.

Abstract of Judgment filed Rovember 15, 1984 in the amount of \$228.50 plus cost and interest, in favor of L. A. Goodman, M. D., sgainst Edna L. Love, recorded under Elerk's File No. J-781802 of the Roal Property Records of Matrix County, Teras.

There is pending in the 125th Judicial District Court of Barris County, Texas, Cause No. 8624307 action styled Richard Sikes vs. Jim Love prior to closing, require said suit be released with projudice.

El. bit.

1

tract or parcel of land in the Morthwest corner of the MENDER WHITE LEASUE, Abstract No. 54, in Earris County, Texas, more particularly described as follows;

EXCLURING at an irun pipe at the Morthwest corner of the Router. White League, said pipe being located on the East hank of the San Jacinto River South 18 deg. 35' Mast 362.5 fest from the easter line of the 1. 4 R.O. HR a 12 inth magnolis marked "X" bears Forthwest 12.5 fest from said pipe;

THINCE South 12 dog. 41' Rest 350 foot to a stake on the East back of said Rivers . .

THERE South 1 deg. bo: West 15.62 feet to a stake on the East Back of said River marking the Southwest corner of the Tract herein described;

INFROM North 69 deg. 55' East 2001.69 feet along a line permissi with the North Line of said Render White League to an iron pipe at the Southeast corner of the Fract berein described and the Southwest corner of the Biroska Truct;

TRENCE North 0 deg. 05' West 355 feet to an iron pipe in the North line of Said League marking the Northeast corner of the Tract beyein described and the Northwest corner of said Sirocke Tract;

TREMCE South 89 deg. 55' West 2139.] fest along the North line of said Rethen White Leegers to the Plane of HENDMAING, and containing 17.58 acres of land.

RECORDERS MEMORANDUM AT THE TIME OF RECORDATION, THIS INSTRUMENT WAS FOUND TO BE INADEQUATE FOR THE BEST PHOTOGRAPHIC REPRODUCTION BECAUSE OF ILLEGIBILITY, CARBON OR PHOTO COPY, DISCOLORED PAPER, ETC.

Ð,

Lî,

FILE FOR RECORD 8:00 AM

OCT 1 2 2001

County Clerk, Hants County, Texas

NAY PROMISION RENEW WACH RESTRICTS WE SALE REVIEW, OR BUG OF THE DESCRIBED BEAR PROPERT BECARES OF COLOR OF RACE IS INVED NO UNERFORCEMENT WORKER FORCEMENT THE STATE OF TEXAS COLUMITY OF MARRIES (Under collip both to informative SFED) by The Names Segment as the data and at the fama impact homes by are not una day RECORDED, is no official Public Research of Real Property of Homes County, Toma on

OCT 1 2 2001

Buraly & Kuyman COUNTY CLERK HARRIE COUNTY, TEXAS

544-88-1136

.

4 1 1 1 1

APPENDIX E

NOTICE TO THE PUBLIC REGARDING THE FIVE-YEAR REVIEW

(This page intentionally left blank)

HIGHLANDS / CROSBY STAR COURIER

P.O. BOX 405 Highlands, TX. 77562 281-328-9605

PUBLISHER'S AFFIDAVIT

FEB 2 9 2016

STATE OF TEXAS

COUNTY OF HARRIS

Before me, the undersigned authority, on this day personally appeared <u>Ms.Julieta</u>, who being by me duly sworn, deposes and says that she is the <u>solitor</u> of the HIGHLANDS STAR CROSBY COURIER; that said newspaper is regularly published in Harris County, Texas and generally circulated in Harris County, Texas; and that the attached notice was published in said newspaper on the following dates, to wit:

	02-24-16
_	(Dates)
	(Signed)
Subscribed and sworn to me this the, 2016, to certify of office	24 day of which witness my hand and seal
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
MEI ING L. HOFFMAN MEI ING L. HOFFMAN MEI ING L. HOFFMAN Comm. Expires 02-05-2020 Notary ID 126400946	Notary Public in and for the State of Texas

(SEAL)

Mei Hoffman

Print or Type Name of Notary Public

My Commission Expires 02(05/2020)



ss. Rates are \$15.00 per column inch, 14 per word plus affidavit. We can give td. Please call or email for assistance. site: http://galenaparkisd.com/purchasing_currentbids. The Galena Park ISD reserves the right to reject any or all proposals."

a presentation of the second se

**APPENDIX F** 

**INTERVIEW FORM** 

(This page intentionally left blank)

SUPERFUND FIVE-YEAR REVIEW SITE SURVEY						
Site Name: Sikes Disposal Pits Superfund Site			EPA	EPA ID No.: TXD980513956		
Location: Crosby, Houston County, Texas			Dat	Date: March 3, 2016		
Contact Made By:						
Name: Raji Josiam	Title:	Title: Remedial Project Manager			Organization: U.S. EPA	
<b>Telephone No.:</b> 214-665-8529 <b>E-Mail:</b> Josiam.Raji@epa.gov	Street Address: 1445 Ross Avenue, Suite 1200 City, State, Zip: Dallas, Texas 75202					
Name: April Ballweg	Title: Project Manager			<b>Organization:</b> EA Engineering, Science, and Technology, Inc., PBC		
Telephone No.: 972-459-5019 E-Mail: <u>aballweg@eaest.com</u>	Street Address: 405 S. Highway 121 Bypass, Suite C-100 City, State, Zip: Lewisville, Texas 75067					
Individual Contacted:						
Name: Lam Tran		Title: Project Manager		r	Organization: TCEQ	
Telephone No.: E-Mail Address: 713-767-3	Street Address: 5425 Polk Street City, State, Zip: Houston, Texas 77023					
Survey Questions						

The purpose of the five-year review is to evaluate the implementation and performance of the remedy, and to confirm that human health and the environment continue to be protected by the remedial actions that have been performed at the site. This interview is being conducted as a part of the fifth five-year review for the Sikes Disposal Pits Superfund Site. Should you choose to respond, please return your survey form to April Ballweg at EA Engineering, Science, and Technology, Inc., PBC via e-mail or U.S. Postal Service by 11 March 2016. The scope of the review is from 2011 to the present.

1. What is your general impression of the work conducted at the site since the fourth Five-Year Review period (since September 2011)?

TCEQ conducted all tasks recommended by the fourth Five-Year Review. Primarily, the groundwater and surface water monitoring were conducted in accordance with the updated Operation and Maintenance Plan.

SUPERFUND FIVE-YEAR REVIEW SITE SURVEY				
Site Name: Sikes Disposal Pits Superfund Site	EPA ID No.: TXD980513956			
Location: Crosby, Houston County, Texas	Date: March 3, 2016			

2. From your perspective, what effects have site operations had on the surrounding community?

There has not been sufficient contact with the surrounding community to adequately comment. The Love's Marina, located southwest of the site, did change land ownership approximately in 2012 and the new marina operator has been cooperative during the fifth five-year review period.

3. During this review period, are you aware of any community concerns regarding the site or its operation and administration? If so, please provide details.

A customer of Down South Offroad, an on-site park for off-road motored vehicles, identified the site as a Superfund site and called TCEQ in 2015 for information. The new owner of the Love's Marina was aware of the Superfund site prior to the marina purchase and has occasionally asked TCEQ when the groundwater contamination will be detected below the action level.

^{4.} Are you aware of any events, incidents, or activities at the site during this review period, such as vandalism, trespassing, or emergency responses from local authorities? If so, please provide details.

The TCEQ conducted site visits approximately twice a year and vandalism was identified at monitoring well MW-19 in June 2013. The chain-link fence and gate was repaired in July 2013 to restore the security of the monitoring well.

SUPERFUND FIVE-YEAR REVIEW SITE SURVEY					
Site Name: Sikes Disposal Pits Superfund Site EPA ID No.: TXD980513956					
Location: Crosby, Houston County, Texas	Date: March 3, 2016				
<ul><li>5. Do you feel well informed about the site's activities and would like to be informed about the site activities – for e meetings, etc.</li><li>Yes</li></ul>	progress? If not, please indicate how you xample, by e-mail, regular mail, fact sheets,				
<ul> <li>6. Do you have any comments, suggestions, or recommendation?</li> <li>The TCEQ recommends that monitoring wells at the sistemi-annual basis should be plugged and abandoned.</li> </ul>	ations regarding the site's management or ite that are not being sampled on a				

**APPENDIX G** 

**REGRESSION ANALYSIS FOR SELECTED WELL-ANALYTE PAIRS** 

(This page intentionally left blank)

























GW-23



**GW-27** 



















**GW-28** 










**GW-34** 



#### TABLE G-1. SUMMARY STATISTICS AND TREND RESULTS

								Detected Results Summary			М	ann-Kendall T	'est		
Matuin	Wall	Analyta	Unita	Einst Exont	Lost Event	No. of	FOD	Minimum	Marimum	Maan	Madian	6D	Mann-Kendall	Two-Tailed P-	Mann-Kendall
Matrix	wen	Analyte	Units	First Event	Last Event	Results	FOD	Minimum	Maximum	Mean	Median	50	S	Value	Trend
GW	GW-15	Beryllium	mg/l	12/5/2006	12/11/2014	8	75%	0.00033	0.00309	0.00167	0.00189	0.000994	-17	0.05	Decreasing
GW	GW-15	Lead	mg/l	12/5/2006	12/11/2014	8	75%	0.00217	0.0358	0.0133	0.0107	0.0122	-13	0.14	NST
GW	GW-15	Nickel	mg/l	12/5/2006	12/11/2014	8	100%	0.00264	0.0171	0.00882	0.00663	0.00586	-4	0.72	NST
GW	GW-18	Beryllium	mg/l	12/5/2006	11/4/2015	12	67%	0.000259	0.00127	0.000827	0.000929	0.000418	-31	0.04	Decreasing
GW	GW-18	Lead	mg/l	12/5/2006	11/4/2015	12	75%	0.00104	0.0207	0.00637	0.00451	0.00632	-25	0.10	NST
GW	GW-18	Nickel	mg/l	12/5/2006	11/4/2015	12	92%	0.0148	0.028	0.0228	0.025	0.00509	14	0.38	NST
GW	GW-23	Lead	mg/l	6/13/2007	7/15/2014	6	67%	0.000329	0.035	0.0105	0.00326	0.0165	4	0.60	NST
GW	GW-27	Beryllium	mg/l	6/13/2007	8/11/2014	7	43%	0.00102	0.00623	0.00348	0.00319	0.00262	9	0.24	NST
GW	GW-27	Nickel	mg/l	6/13/2007	8/11/2014	7	71%	0.00103	0.0513	0.0157	0.00271	0.0218	9	0.24	NST
GW	GW-28	Benzene	mg/l	12/5/2006	11/4/2015	12	92%	0.00043	0.0794	0.014	0.00416	0.0245	-50	0.00	Decreasing
GW	GW-28	Beryllium	mg/l	12/5/2006	11/4/2015	12	33%	0.000623	0.00108	0.000838	0.000825	0.000188	6	0.74	NST
GW	GW-28	Trichloroethylene	mg/l	12/5/2006	11/4/2015	12	58%	0.00039	0.01	0.00257	0.0011	0.00351	-37	0.01	Decreasing
GW	GW-28	Vinyl chloride	mg/l	12/5/2006	11/4/2015	12	50%	0.00093	0.0125	0.00419	0.00195	0.00463	-31	0.04	Decreasing
GW	GW-30	Benzene	mg/l	12/5/2006	11/4/2015	12	100%	0.0048	0.22	0.0376	0.0174	0.0626	-41	0.01	Decreasing
GW	GW-30	Vinyl chloride	mg/l	12/5/2006	11/4/2015	12	100%	0.017	0.072	0.0418	0.0402	0.0186	-34	0.02	Decreasing
GW	GW-34	Lead	mg/l	6/12/2007	7/15/2014	6	67%	0.00338	0.0188	0.00807	0.00504	0.00727	-4	0.60	NST

Notes:

FOD = Frequency of detection.

GW = groundwater.

mg/l = milligrams per liter. NST = No significant trend.

SD = Standard deviation.

**APPENDIX H** 

SITE INSPECTION CHECKLIST

(This page intentionally left blank)

### FIVE-YEAR REVIEW SITE VISIT CHECKLIST

I. SITE INFORMATION						
Site Name: Sikes Disposal Pits	Superfund Site	<b>Date of Inspection:</b> 3/2	/2016			
Location and Region: Crosby, Ha	arris County, Texas	<b>EPA ID:</b> TXD980513956				
Agency, office, or company leading review: U.S. Environmental Protection Age	n <b>g the five-year</b> ency, Region 6	<b>Weather/temperature:</b> Clear skies with high of 70°F, winds SSE at ~ 13 mph.				
Remedy Includes:       (Check all the control of the con	at apply) ment ng around wells)	<ul> <li>Ground water pump and treatment</li> <li>Surface water collection and treatment</li> <li>Other (Natural flushing of ground water in upper aquifer)</li> </ul>				
Attachments: X Inspection t	eam roster attached	Site map attached (Fig	gure C-2 of report)			
Ш.	INTERVIEWS (Chec	ek all that apply)				
1. O&M Site Manager	<u>Marc Viola</u> <u>Proje</u> Name	<u>ct Manager, CB&amp;I</u> Title	Date			
Interviewed: by mail at Problems, suggestions: R publi	Interviewed: by mail at office by phone Phone no Problems, suggestions: Report attached <u>Received survey on 4 April 2016; authorization to</u> publish it not received, therefore not included in the FYR Report.					
2. O&M Staff						
	Name	Title	Date			
Interviewed: by mail at Problems, suggestions: R	office by phone by phone	Phone no				
<b>3. Local regulatory authorities and response agencies</b> (i.e.; State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.). Fill in all that apply.						
Contact Lam Tran	Project Manager	(7 ⁻	12) 767 2550			
Name	Title	Date	Phone no.			
Problems, suggestions: Report attached <u>Received on 28 March 2016</u>						
Agency						
Contact			<u>()</u>			
Name Problems, suggestions:	Title Report attached	Date Phone no.				

4. Other interviews (optional): Report attached to Five-Year Review Report							
Sikes Property Owner – No Survey Provided							
Love's Marina Owner – No Survey Provided							
Harris County Commission of Precinct 2 – No St	urvey Provided						
Harris County Precinct 2 Infrastructure Director	– No Survey Provided						
III. ON-SITE DOCUMENTS & RE	<b>CORDS VERIFIED</b> (Check all that apply)						
1. O&M Documents							
O&M manual (long term monitoring plan)	$\square$ Readily available $\square$ Up to date $\square$ N/A						
As-built drawings	Readily available $\square$ Up to date $\square$ N/A						
Maintenance logs	$\boxtimes$ Readily available $\boxtimes$ Up to date $\square$ N/A						
Remarks: Stored at local CB&I (TCEQ's subc	contractor) office						
2. Site-Specific Health and Safety Plan	$\boxtimes$ Readily available $\boxtimes$ Up to date $\square$ N/A						
Contingency plan/emergency response pla	an $\bigotimes$ Readily available $\bigotimes$ Up to date $\square$ N/A						
Remarks: <u>Team brought on-site during inspe</u>	ection; stored at local office for team subcontractor						
3. O&M and OSHA Training Records	$\square$ Readily available $\square$ Up to date $\square$ N/A						
Remarks: Staff required to maintain 8-hour OSH	A refresher courses annually						
4. Permits and Service Agreements							
Air discharge permit	$\square$ Readily available $\square$ Up to date $\square$ N/A						
Effluent discharge	$\square$ Readily available $\square$ Up to date $\square$ N/A						
Waste disposal, POTW	$\square Readily available \square Up to date \square N/A$						
Other permits	$\Box$ Readily available $\Box$ Up to date $\boxtimes$ N/A						
Remarks:							
5. Gas Generation Records	$\square$ Readily available $\square$ Up to date $\square$ N/A	•					
6. Settlement Monument Records	$\square Readily available \square Up to date \square N/A$						
7. Ground Water Monitoring Records	$\square$ Readily available $\square$ Up to date $\square$ N/A						
8. Leachate Extraction Records	$\square$ Readily available $\square$ Up to date $\square$ N/A						
9. Discharge Compliance Records							
Air	$\Box$ Readily available $\Box$ Up to date $\boxtimes$ N/A						
Water (effluent)	$\Box$ Readily available $\Box$ Up to date $\boxtimes$ N/A						
Remarks:							
10. Daily Access/Security Logs	$\Box$ Readily available $\Box$ Up to date $\boxtimes$ N/A						
Remarks:							

	IV. O&M COSTS						
1.	O&M Organization						
	State in-house Contractor for State PRP in-house						
	Contractor for PRP Other						
2.	O&M Cost Records (Not Available [N/A])						
	Readily available Up to date Funding mechanism/agreement in place						
	☐ Original O&M cost estimate ☐ Breakdown attached						
	Total annual cost by year for review period if available $(N/A)$						
	Date Date Total Cost						
	$\frac{Datc}{Datc} = \frac{10tar}{Cost}$ From N/A to N/A  S = Reakdown attached						
	From N/A to N/A $\$$ - Breakdown attached						
	From N/A to N/A \$ - Breakdown attached						
	From N/A to N/A \$ - Breakdown attached						
	From N/A to N/A \$ - Breakdown attached						
	Total Invoiced Amount:   N/A   -          Breakdown attached						
3.	Unanticipated or Unusually High O&M Costs During Review Period						
	N/A						
	V. ACCESS AND INSTITUTIONAL CONTROLS Applicable N/A						
A.	Fencing						
1.	<b>Fencing damaged</b> Location shown on site map Gates secured N/A						
	Remarks: Continue repairing on an as need basis; main gate showed damage of chain link fence						
	fabric which may allow trespasser access, however, gates and fencing around monitoring wells were						
	observed to be in good condition during the site visit.						
B.	Other Access Restrictions						
1.	Signs and other security measures Location shown on site map N/A						
	Remarks: TCEQ signs on perimeter fencing at each well location were observed; some signs faded or						
	missing information or identifying TNRCC, and in need of repair or replacement.						

C. Institutional Controls						
1. Implementation and enforcement						
Site conditions imply ICs not properly implemented $\Box$ Yes $\boxtimes$ No $\Box$ N/A						
Site conditions imply ICs not being fully enforced $\Box$ Yes $\boxtimes$ No $\square$ N/A						
Type of monitoring (e.g., self-reporting, drive by) Inspections during O&M site visits.						
Frequency Per the O&M Plan						
Responsible party/agency TCEQ						
Contact Lam Tran Project Manager 713-767-3559						
Name Title Date Phone no.						
Reporting is up-to-date						
Reports are verified by the lead agency Yes No N/A						
Specific requirements in deed or decision documents have been met $\Box$ Yes $\Box$ No $\Box$ N/A						
Violations have been reported						
Other problems or suggestions: Report attached						
2 A degree $\nabla$ ICs are adequate $\nabla$ ICs are inedequate $\nabla$ N/A						
<b>2.</b> Adequacy  It's are adequate  I to sate inadequate I to a provide the prov						
they do not cover the site in its entirety. On 10/5/2015, TCEO sent a letter to EPA stating that deed						
notices were not necessary for the Parker or Anderson properties based on quarterly groundwater results.						
EPA concurred with TCEQ's assessment regarding deed notices on the Parker and Anderson properties						
<u>on 10/19/2015.</u>						
D. General						
<b>1. Vandalism/trespassing</b> Location shown on site map No vandalism evident						
Remarks:						
2. Land use changes onsite N/A						
Remarks:						
3. Land use changes offsite X/A						
Remarks:						
VI. GENERAL SITE CONDITIONS						
A. Roads						
<b>1. Roads damaged</b> $\Box$ Location shown on site map $\boxtimes$ Roads adequate $\Box$ N/A						
Remarks:						
B. Other Site Conditions						
Remarks:						

	VII. LANDFILL	COVERS	Ap	plicable	N/A
А.	Landfill Surface				
1.	Settlement (Low spots) Areal extent Remarks:	Location show	n on site map Depth	Settlemen	t not evident
2.	Cracks Lengths Remarks:	Location show Widths	n on site map	Cracking Depths	not evident
3.	Erosion Areal extent Remarks:	Location show	n on site map Depth	Erosion no	ot evident
4.	Holes Areal extent Remarks:	Location show	n on site map Depth	Holes not	evident
5.	Vegetative Cover	Grass	Cover properly ( is on a diagram)	established	] No signs of stress
6.	Alternative Cover (arm Remarks:	ored rock, concrete,	, etc.) 🗌 N/A		
7.	Bulges Areal extent Remarks:	Location show	n on site map Depth	Bulges no	t evident
8.	Wet Areas/Water Dama Wet areas Ponding Seeps Soft subgrade Remarks:	age Wet are Locatio Locatio Locatio Locatio	eas/water damagon shown on site on shown on site on shown on site on shown on site on shown on site	e not evident map map map	Areal extent         Areal extent         Areal extent         Areal extent         Areal extent
9.	Slope Instability	] Slides 🗌 Loc e instability	cation shown on Areal extent	site map	

B.	Benches Applicable N/A (Horizontally constructed mounds of earth placed across a steep landfill side slope to interrupt the slope in order to slow down the velocity of surface runoff and intercept and convey the runoff to a lined channel.)
1.	Flows Bypass Bench Location shown on site map N/A or okay Remarks:
2.	Bench Breached   Icocation shown on site map   N/A or okay
	Kemarks:
3.	<b>Bench Overtopped</b> Location shown on site map N/A or okay
	Remarks:
C.	Letdown Channels Applicable N/A (Channel lined with erosion control mats, rip rap, grout bags, or gabions that descend down the steep side slope of the cover and will allow the runoff water collected by the benches to move off of the landfill cover without creating erosion gullies.)
1.	Settlement Dearth Location shown on site map No evidence of settlement
	Arear extent   Depth     Remarks:   Depth
2.	Material Degradation Location shown on site map No evidence of degradation
	Remarks:
3.	Erosion       Location shown on site map       No evidence of erosion         Areal extent       Depth
	Remarks:
4	<b>Undercutting D</b> Location shown on site map <b>D</b> No evidence of undercutting
т.	Areal extent     Depth
	Remarks:
5.	Obstructions Type
	Areal extent Size
	Remarks:
6.	Excessive Vegetative Growth Type
	Location shown on site map     Areal extent
	Remarks:
1	

D.	Cover Penetrations	Applicable	N/A	
1.	Gas Vents  Properly secured/locked  Evidence of leakage at Remarks:	Active Functioning penetration	<ul> <li>Passive</li> <li>Routinely sampled</li> <li>Needs O&amp;M</li> </ul>	Good condition N/A
2.	Gas Monitoring Probes  Properly secured/locke Evidence of leakage at Remarks:	d	<ul> <li>Routinely sampled</li> <li>Needs O&amp;M</li> </ul>	Good condition N/A
3.	Monitoring Wells (within Evidence of leakage at Remarks:	surface area of landfill) penetration	) Needs O&M	□ N/A
4.	Leachate Extraction Well <ul> <li>Properly secured/locke</li> <li>Evidence of leakage at</li> </ul>	s d	<ul> <li>Routinely sampled</li> <li>Needs O&amp;M</li> </ul>	Good condition N/A
5.	Settlement Monuments Remarks:	Located	Routinely surveyed	□ N/A
E.	Gas Collection and Treat	ment 🗌 Appli	cable 🛛 N/A	
1.	Gas Treatment Facilities       Flaring      Good condition      Remarks:	<ul><li>Thermal dest</li><li>Needs O&amp;M</li></ul>	ruction	Collection for reuse
2.	Gas Collection Wells, Mar Remarks:	nifolds, and Piping	Good condition	Needs O&M
3.	Gas Monitoring Facilities Good condition Remarks:	(e.g., gas monitoring o	of adjacent homes or buildi	ings)
F.	Cover Drainage Layer	Applicable	N/A	
1.	Outlet Pipes Inspected Remarks:	Functioning	N/A	
2				-
2.	Outlet Rock Inspected Remarks:	Functioning	N/A	

	1 Siltation Areal ex	tant Siza
	$\Box \mathbf{N} \mathbf{A}$	
		tion not evident
	Remarks:	
	<b>2. Erosion</b> Areal ex	tent Depth
	Erosion not evident	
	Remarks:	
3.	Outlet Works	Functioning N/A
	Remarks:	
4.	Dam	Functioning N/A
	Remarks.	
H.	Retaining Walls	$\square$ Applicable $\square$ N/A
1.	Deformations	Location shown on site map Deformation not evident
	Horizontal displacement	Vertical displacement
	Potational displacement	
	Rotational displacement	
2.	Degradation	Location shown on site map Degradation not evident
	Remarks:	
I.	Perimeter Ditches/Off-Site D	ischarge Applicable X/A
I. 1.	Perimeter Ditches/Off-Site D Siltation	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident
I. 1.	Perimeter Ditches/Off-Site D Siltation Areal extent	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth
I. 1.	Perimeter Ditches/Off-Site D Siltation Areal extent Remarks:	ischarge Applicable N/A Location shown on site map Siltation not evident Depth
I. 1.	Perimeter Ditches/Off-Site D Siltation Areal extent Remarks:	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth
I. 1. 2.	Perimeter Ditches/Off-Site D Siltation Areal extent Remarks: Vegetative Growth	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth
I. 1. 2.	Perimeter Ditches/Off-Site D         Siltation         Areal extent	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth       Depth         Location shown on site map       N/A         Image: N/A       Image: N/A
I. 1. 2.	Perimeter Ditches/Off-Site D         Siltation         Areal extent         Remarks:         Vegetative Growth         Vegetation does not imped         Areal extent	ischarge Applicable N/A  Location shown on site map Siltation not evident Depth Location shown on site map N/A le flow Type
I. 1. 2.	Perimeter Ditches/Off-Site D         Siltation         Areal extent         Remarks:         Vegetative Growth         Vegetation does not imped         Areal extent         Remarks:	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth
I. 1. 2.	Perimeter Ditches/Off-Site D         Siltation         Areal extent         Remarks:         Vegetative Growth         Vegetation does not imped         Areal extent         Remarks:	ischarge       Applicable       N/A         Location shown on site map       Siltation not evident         Depth
I. 1. 2.	Perimeter Ditches/Off-Site D         Siltation         Areal extent         Remarks:         Vegetative Growth         Vegetation does not imped         Areal extent         Remarks:         Erosion	ischarge Applicable N/A     Location shown on site map Siltation not evident     Depth
I. 1. 2. 3.	Perimeter Ditches/Off-Site D         Siltation         Areal extent	ischarge Applicable N/A   Location shown on site map Siltation not evident   Depth
I.         1.         2.         3.	Perimeter Ditches/Off-Site D         Siltation         Areal extent         Remarks:         Vegetative Growth         Vegetation does not imped         Areal extent         Remarks:         Erosion         Areal extent         Pareal extent         Pareal extent         Pareal extent         Pareal extent	ischarge Applicable N/A   Location shown on site map Siltation not evident   Depth Depth     Location shown on site map N/A   le flow Type     Uppe Depth     Location shown on site map Erosion not evident
I. 1. 2. 3.	Perimeter Ditches/Off-Site D         Siltation         Areal extent	ischarge Applicable N/A   Location shown on site map Siltation not evident   Depth Depth     Location shown on site map N/A   le flow Type     Use Location shown on site map Erosion not evident
I. 1. 2. 3.	Perimeter Ditches/Off-Site D         Siltation         Areal extent	ischarge Applicable N/A     Location shown on site map Siltation not evident     Depth     Location shown on site map     N/A     Image: Depth
I. 1. 2. 3.	Perimeter Ditches/Off-Site D   Siltation   Areal extent	ischarge Applicable N/A     Location shown on site map Siltation not evident     Depth

	VIII. VERTICAL BARRIER WALLS Applicable N/A
1.	Settlement <ul> <li>Location shown on site map</li> <li>Settlement not evident</li> </ul> Areal extent         Depth           Remarks:
2.	Performance Monitoring       Type of monitoring         Performance not monitored       Frequency       Evidence of breaching         Head differential
	IX. GROUND WATER/SURFACE WATER REMEDIES Applicable N/A
A.	Ground Water Extraction Wells, Pumps, and Pipelines
1.	Pumps, Wellhead Plumbing, and Electrical         Good condition       All required wells located         Needs O&M       N/A         Remarks:
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances            Good condition           Needs O&M             Remarks:
3.	Spare Parts and Equipment         Readily available       Good condition         Remarks:
B.	Surface Water Collection Structures, Pumps, and Pipelines Applicable N/A
1.	Collection Structures, Pumps, and Electrical       Good condition       Needs O&M       Remarks:
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances         Good condition       Needs O&M         Remarks:
3.	Spare Parts and Equipment         Readily available       Good condition       Requires upgrade       Needs to be provided         Remarks:

C.	Treatment System	Applicable	N/A	
1.	Treatment Train (Che         Metals removal         Air stripping         Filters         Additive (e.g., chela	ck components that apply) Oil/water separation Carbon absorbers	Bioremediation	
	<ul> <li>Others</li> <li>Good condition</li> <li>Sampling ports prop</li> <li>Sampling/maintenan</li> <li>Equipment properly</li> <li>Quantity of ground</li> <li>Quantity of surface</li> <li>Remarks:</li> </ul>	Needs O&M perly marked and functional nee log displayed and up to d identified water treated annually water treated annually	ate	
2.	Electrical Enclosures a	and Panels (Properly rated an Good condition	nd functional)	
3	Tonks Voults Storage	Vossols		
5.	N/A   Good     Remarks:	condition Proper se	econdary containment	Needs O&M
4.	Discharge Structure an N/A Remarks:	Description of the description o	Needs O&M	
5.	Treatment Building(s)          N/A         Chemicals and equi         Remarks:	Good condition (esp. ro pment properly stored	oof and doorways)	Needs repair
		1		
6.	Properly secured/loo All required wells loo Remarks:	np and treatment remedy) cked	Routinely sampled ds O&M	Good condition N/A
D.	Monitored Natural Att	<b>tenuation</b> Applicable	N/A	
1.	Monitoring Wells (Nat Properly secured/loc condition All requir Remarks: <u>Repaint well</u> missing or nonfunctioni	tural attenuation remedy) cked  Functioning  Rou ed wells located identification markings, repl ng padlocks, sample wells in	utinely sampled (Semi-an I Needs O&M lace illegible or missing v accordance with approve	nually) Good N/A varning signs, replace ed O&M Plan.

## X. OTHER REMEDIES

If there are remedies applied at the site that are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

# XI. OVERALL OBSERVATIONS

### A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).

Based on the data review, the Site inspection, and the interviews, it appears that the remedy selected in the Record of Decision (ROD) is functioning as intended, however, not all recommendations identified during the previous review have been implemented. Remedy components defined in the ROD are complete except for ongoing natural flushing of the shallow groundwater. As a result of the statistical analysis performed during the current review period, it was found that there are no wells that show statistically significant increases in monitored parameters where exceedances of action levels are found. In addition, with the exception of wells GW-28 and GW-30, no volatile organic compounds have been detected above action levels since 2006 in the remainder of Site wells. The metals beryllium, lead, and nickel are more widespread in Site wells; however, there are a number of wells (GW-7, GW-21, GW-25, GW-33, GW-35) where no exceedances above action levels have been found since 2006.

### B. Adequacy of O&M

Physical site maintenance appeared to be adequate at the time of the site investigation on 2 March 2016.

## C. Early Indicators of Potential Remedy Failure

None identified during the site inspection.

## D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

Opportunities exist to reduce costs of monitoring at the Site through reduction in the frequency of sampling for wells where volatile organic compounds and/or metals have not historically been detected above action levels. In wells where sampling has ceased, and with EPA's consensus, plugging and abandonment of select monitoring wells may reduce costs in maintaining access to the wells (i.e. mowing, less subcontractor time on Site).

#### **INSPECTION TEAM ROSTER**

Name	Organization	Title
RAJI JOSIAM	USERA-R6	RPM
Lam Tran	TCEQ	pm
April Ballweg	EA Engineering	PM
	0.00	
· · · · · · · · · · · · · · · · · · ·		

**APPENDIX I** 

SITE INSPECTION PHOTOGRAPHS

(This page intentionally left blank)



Photograph No. 1 Description: Main entrance to Site. Date: 3/2/2016

Site: Sikes Disposal Pits

Direction: North



Photograph No. 2Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-18; heavy sediment buildup observed within fenced<br/>area and at gate assumed to be the result of flooding in the area.Date: 3/2/2016Direction: Northeast



Photograph No. 3 Description: Signage for GW-18; phone numbers illegible. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: Northeast



Photograph No. 4Site: Sikes Disposal PitsDescription: Close up of GW-18 well casing; heavy rust at edge and on hinges;<br/>however still functional; concrete monitoring pad covered with sediment buildup and<br/>vegetation.Date: 3/2/2016Direction: Down



Photograph No. 5 Site: Sikes Disposal Pits Description: Shallow monitoring well GW-23; small amount of barbed wire dislocated from posts observed during visit.



Photograph No. 6Site: Sikes Disposal PitsDescription: Sign on GW-23 fence; yellow warning sign in background to the right.Date: 3/2/2016Direction: N/A (front gate)



Photograph No. 7Site: Sikes Disposal PitsDescription: Overview of deep monitoring well GW-07 with signs.Date: 3/2/2016Direction: South



Photograph No. 8 Description: Opened well casing for GW-07. Date: 3/2/2016

Site: Sikes Disposal Pits



Photograph No. 9 Description: Overview of deep monitoring well GW-21. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: West



Photograph No. 10 Description: Opened well casing for GW-21. Date: 3/2/2016 Site: Sikes Disposal Pits



Photograph No. 11 Description: Overview of shallow monitoring well GW-27. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: West



Photograph No. 12 Description: Opened well casing at GW-27. Date: 3/2/2016 Site: Sikes Disposal Pits



Photograph No. 13Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-34; missing warning sign; indications of recreational<br/>activity observed during site visit (note lawn chair by fence).Direction: NorthDate: 3/2/2016Direction: North



Photograph No. 14Site: Sikes Disposal PitsDescription: Close up of GW-34; severe rusting of well casing observed, however, functional.<br/>Date: 3/2/2016Direction: Down



Photograph No. 15Site: Sikes Disposal PitsDescription: Vicinity near shallow monitoring well GW-34.Camper trailer observed in the<br/>distance behind pine trees.



Photograph No. 16Site: Sikes Disposal PitsDescription: Vicinity near shallow monitoring well GW-34; observed multiple trash disposaldrums during site visit; appears to be a picnic area for Down South Offroad.Date: 3/2/2016Direction: East



Photograph No. 17Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-35; identification not legible due to heavy rust.Date: 3/2/2016Direction: North



Photograph No. 18Site: Sikes Disposal PitsDescription: Open well casing for GW-35; water observed inside of well casing may be the<br/>result of flooding conditions in the area but reason not determined.Date: 3/2/2016Direction: Down



Photograph No. 19Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-32; some sediment buildup observed.Date: 3/2/2016Direction: West



Photograph No. 20Site: Sikes Disposal PitsDescription: GW-32; identification fading and well casing rusting however functional.Date: 3/2/2016Direction: West



Photograph No. 21Site: Sikes Disposal PitsDescription: Shallow well GW-32; rusted hinge observed however functional.Date: 3/2/2016Direction: Down



Photograph No. 22 Description: Overview of deep monitoring well GW-33. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: West



Photograph No. 23Site: Sikes Disposal PitsDescription: GW-33 area with some buildup of soil on the concrete.Date: 3/2/2016Direction: Southwest



Photograph No. 24Site: Sikes Disposal PitsDescription: Deep monitoring well GW-33 with well casing lid removed.Date: 3/2/2016Direction: Down



Photograph No. 25 Description: View of Site access roads in good condition. Date: 3/2/2016

Site: Sikes Disposal Pits

Direction: South



Photograph No. 26 Description: Alternate view of Site access roads. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: East



Photograph No. 27Site: Sikes Disposal PitsDescription: Business at the northern end of the Site, Down South Offroad.Date: 3/2/2016Direction: East



Photograph No. 28 Description: Down South Offroad trail map. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: N/A



Photograph No. 29Site: Sikes Disposal PitsDescription: Sign for shallow well GW-15 (on left) and deep well GW-31 (on right).Date: 3/2/2016Direction: West



Photograph No. 30Site: Sikes Disposal PitsDescription: GW-15; casing observed to be rusting at edge and hinge; yellow warning<br/>sign not observed.Direction: WestDate: 3/2/2016Direction: West



Photograph No. 31Site: Sikes Disposal PitsDescription: Deep monitoring well GW-31; yellow warning sign not observed.Date: 3/2/2016Direction: West



Photograph No. 32Site: Sikes Disposal PitsDescription: GW-31 fence enclosure, fallen tree observed lying on top rail of fence along with<br/>dislocation of fencing cross bar.Direction: WestDate: 3/2/2016Direction: West



Photograph No. 33Site: Sikes Disposal PitsDescription: Deep well GW-29 (on left) and shallow well GW-28 (on right).Date: 3/2/2016Direction: Northwest



Photograph No. 34 Description: Shallow well GW-28; identification fading. Date: 3/2/2016 Site: Sikes Disposal Pits


Site: Sikes Disposal Pits Photograph No. 35 Description: Deep well GW-29; identification fading; note drum of purge water in background. Direction: South/down Date: 3/2/2016



Photograph No. 36

Site: Sikes Disposal Pits

Description: Labeled 55-gallon drum of purge water, small quantity of liquid contained within the drum at time of inspection; informed by TCEQ that disposal occurs annually. Date: 3/2/2016 Direction: Southeast



Photograph No. 37 Description: Shallow monitoring well GW-19. Date: 3/2/2016

Site: Sikes Disposal Pits

Direction: North



Photograph No. 38Site: Sikes Disposal PitsDescription: Well casing for GW-19; not locked due to damaged pad lock.Date: 3/2/2016Direction: Down



Photograph No. 39 Description: Well GW-19 identification highly visible. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: North



Photograph No. 40Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-25 located south of Beaumont Highwayand north along Gulf Pump Road/Old Houston Crosby Road.Date: 3/2/2016Direction: Southwest

Page 20 of 25



Photograph No. 41 Description: Alternate view of GW-25. Date: 3/2/2016

Site: Sikes Disposal Pits

Direction: North



Photograph No. 42 Description: Well GW-25 casing opened. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: Down



Photograph No. 43Site: Sikes Disposal PitsDescription: Shallow monitoring well GW-30, located at Love's Marina near surface ponds.Date: 3/2/2016Direction: North



Photograph No. 44 Description: Shallow monitoring well, GW-30, well casing. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: Down



Photograph No. 45 Description: East pond at Love's Marina. Date: 3/2/2016

Site: Sikes Disposal Pits

Direction: Southeast



Photograph No. 46 Description: West pond at Love's Marina. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: Southwest



Photograph No. 47 Description: Love's Marina office. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: North



Photograph No. 48 Description: Activity sign for Love's Marina. Date: 3/2/2016 Site: Sikes Disposal Pits

Direction: East



Photograph No. 49Site: Sikes Disposal PitsDescription: Based on historical document review, wells S1-116 and INT-116 determined to be<br/>sentinel wells and part of the French Limited Superfund Site monitoring well field;<br/>Thomas Honey Bees beehive structures no longer staged in the vicinity.<br/>Date: 3/2/2016Date: 3/2/2016Direction: North



Photograph No. 50Site: Sikes Disposal PitsDescription: Based on historical document review, Well-A identified during the previous five-<br/>year review determined to be GW-5 and part of the French Limited Superfund Site well field.<br/>Date: 3/2/2016Date: 3/2/2016Direction: Down

# **APPENDIX J**

# APPLICABLE OR RELEVANT AND APPROPRIATE REQUIREMENT SUMMARY

(This page intentionally left blank)

The purpose of this appendix is to review the applicable or relevant and appropriate requirements (ARAR) set for the Sikes Disposal Pits Superfund Site (Site) and to review Federal, State, or local regulations related to public health or the environment and promulgated subsequent to the Record of Decision (ROD) for changes in standards. For any changes in standards identified, the changes are evaluated to assess the appropriateness of the changed regulations on the actions to ensure protectiveness.

## Applicable or Relevant and Appropriate Requirements set by the Record of Decision

ARARs and other requirements 'to be considered' (TBC) for this site were identified in the ROD dated 9/18/1986 (EPA 1986). As a part of the Fifth Five-Year Review (FYR) for the Site, an evaluation was performed to identify and evaluate changes in these ARARs to determine whether such changes may affect the protectiveness of the selected remedy.

The ROD identified the following ARARs and TBCs as having an impact on the proposed remedy:

- 1. Resource Conservation and Recovery Act (RCRA) requirements for the design, construction, operation, and maintenance of hazardous waste facilities within the 100-year floodplain, as regulated under 40 *Code of Federal Regulations* (CFR) 264 Subpart B.
- 2. RCRA requirements for the characterization of hazardous wastes under 40 CFR 261, and RCRA requirements for manifesting and offsite transportation of hazardous wastes, as regulated under 40 CFR 262 and 40 CFR 263.
- 3. RCRA requirements applicable to groundwater protection, as regulated under 40 CFR 264 Subpart F, which state the concentrations of hazardous substances allowable in groundwater.
- 4. RCRA requirements for the construction of hazardous waste landfills, as regulated under 40 CFR 264 Subpart N.
- 5. RCRA requirements for operators of hazardous waste incinerators, as regulated under 40 CFR 264 Subpart O.
- 6. Ambient Water Quality Criteria under 40 CFR 131, and the National Primary Drinking Water Standards, expressed as Maximum Contaminant Levels (MCL) in 40 CFR 141, established under the Safe Drinking Water Act (SWDA).
- 7. Technical and substantive requirements of the National Pollutant Discharge Elimination System (NPDES), established under the Clean Water Act (CWA) and regulated by 40 CFR 122 and 125.
- 8. Occupational Safety and Health Act (OSHA) requirements for the protection of workers at hazardous waste sites, as regulated under 29 CFR 1910.
- 9. Federal Standards for Toxic Pollutant Effluent, as regulated under 40 CFR 129.
- 10. Substantive and technical requirements for the emissions of primary air pollutants during remedial actions involving waste excavation and incineration, as regulated under the Clean Air Act (CAA) and the National Ambient Air Quality Standards (NAAQS).
- 11. Department of Transportation (DOT) requirements governing the transportation of hazardous materials, as regulated under 49 CFR 171–177.
- 12. Requirements of the Texas Surface Water Quality Criteria for the protection of designated uses of surface water bodies in the State of Texas.
- 13. Texas Air Control Board regulations governing the emissions of pollutants from point sources.
- 14. Requirements of the Texas Solid Waste Act governing the transportation and disposal of wastes.
- 15. Requirements of the Executive Order on Floodplain Management, Executive Order No. 11988, to minimize impacts to floodplains during remedial action.
- 16. The U.S Environmental Protection Agency's (EPA) Groundwater Protection Strategy.

Standard, Requirement, Criteria, or Limitation	Citation	Description	Media	Status
RCRA Landfill Requirements	40 CFR 264 Subpart B	Requirements for the design, construction, operation, and maintenance of hazardous waste facilities within the 100-year floodplain	Hazardous Waste	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
RCRA Hazardous Waste Characterization	40 CFR 261	Requirements for the characterization of hazardous wastes	Hazardous Waste	No changes have been made which would affect the protectiveness of the remedy.
RCRA Manifest and Transportation	40 CFR 262 and 263	Requirements for manifesting and offsite transportation of hazardous wastes	Hazardous Waste	No changes have been made which would affect the protectiveness of the remedy.
RCRA Groundwater Protection	40 CFR 264 Subpart F	Requirements applicable to groundwater protection	Hazardous Waste	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
RCRA Landfill Requirements	40 CFR 264 Subpart N	Requirements for the construction of hazardous waste landfills	Hazardous Waste	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
RCRA Incinerators	40 CFR 264 Subpart O	Requirements for operators of hazardous waste incinerators	Hazardous Waste	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
Ambient Water Quality Criteria	40 CFR 131	Defines the water quality goals of a water body, by designating the use or uses to be made of the water and by setting criteria that protect the designated uses.	Surface Water	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
National Primary Drinking Water Standards, expressed as MCLs	40 CFR 141	Establishes the allowable levels of contaminants in groundwater.	Groundwater	No changes have been made which would affect the protectiveness of the remedy
NPDES, established under the CWA	40 CFR 122 and 125	Technical and substantive requirements of this act must be adhered to during remediation activities.	Surface Water	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
OSHA	29 CFR 1910	Requirements for the protection of workers at hazardous waste sites	Not Applicable	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.

Standard, Requirement, Criteria or Limitation	Citation	Description	Media	Status
Federal Standards for Toxic Pollutant Effluent	40 CFR 129	Requirements for owners or operators of specified facilities discharging into navigable waters.	Surface Water	No changes have been made which would affect the protectiveness of the remedy
CAA and the NAAQS	40 CFR 50	Ambient air quality to protect public health and the environment.	Air	The applicable activity is no longer occurring, however no changes have been made which would affect the protectiveness of the remedy.
DOT	49 CFR 171–177	Requirements governing the transportation of hazardous materials.	Hazardous Waste	No changes have been made which would affect the protectiveness of the remedy
Requirements of the Texas Surface Water Quality Criteria for the protection of designated uses of surface water bodies in the State of Texas	30 TAC 307	Requirements for discharges to surface water.	Surface Water	No changes have been made which would affect the protectiveness of the remedy.
Texas Air Control Board Regulations	30 TAC 101	Regulations governing the emissions of pollutants from point sources.	Air	The applicable activity is no longer occurring; however, no changes have been made which would affect the protectiveness of the remedy.
Texas Solid Waste Act Regulations	30 TAC 335	Requirements governing the transportation and disposal of wastes.	Solid Waste	No changes have been made which would affect the protectiveness of the remedy.
Floodplain Management	Executive Order No. 11988	Requirements to minimize impacts to floodplains during remedial action.	Surface Water	The applicable activity has been completed; however, no changes have been made which would affect the protectiveness of the remedy.
EPA Groundwater Protection Strategy	NA	To be considered for protection of groundwater.	Groundwater	No changes have been made which would affect the protectiveness of the remedy.

#### **Assessment of Changes in Standards**

The remedial action at the Site has been completed, and the current operations involve only operations and maintenance (O&M) activities related to ongoing groundwater and surface water sampling. No hazardous waste treatment or disposal facilities remain at the Site. Therefore, the only ARARs that still apply to the remedy are those related to the contaminated groundwater, O&M activities, and the Texas Surface Water Quality Criteria.

These ARARs include the RCRA requirements to characterize wastes at 40 CFR 261, DOT requirements for the transportation of hazardous materials at 49 CFR 171–177, RCRA requirements for allowable limits of contaminants in groundwater at 40 CFR 264 Subpart F, the Ambient Water Quality Criteria at 40 CFR 131, the MCLs at 40 CFR 141, OSHA regulations at 29 CFR 1910, and the Texas Surface Water Quality Criteria. Also, the EPA's Groundwater Protection Strategy would still apply, but because it is not a regulation or law, it is a TBC requirement for the remedy.

The RCRA requirements for the characterization of hazardous wastes and the DOT requirements for the transportation of hazardous materials apply to purge water generated during groundwater sampling activities. Since the start of O&M, based on available documentation, no water from sampling activities has been characterized as hazardous, and no significant applicable changes have been made to these regulations that affect the remedy's protectiveness. The analytical testing requirements and discharge criteria for purge water are not contained in the Field Sampling Plan (FSP) (ECS 2013) or O&M Plan (Shaw 2012). According to the FSP, purge water generated during sampling events is to "be collected in 55-gallon drums for subsequent testing and disposal" (ECS 2013). Testing requirements are not specified.

The OSHA regulations in 29 CFR 1910 are addressed through a site-specific health and safety plan for the O&M activities at the site. This plan should be updated regularly to reflect any new changes to these regulations.

The RCRA requirements for allowable levels of contaminants in groundwater and the MCLs still apply to the contaminated groundwater. Since the ROD was signed in 1986, MCLs have been promulgated or revised for many of the Site groundwater contaminants. The current MCLs, along with the ROD-specified human health criteria, are provided in Table 1. As shown in Table 1, the current MCL is lower than the ROD-specified human health criteria for cadmium, lead, thallium, benzene, chlorobenzene, 1,2-dichloroethane, ethylbenzene, toluene, 1,1,2-trichloroethane, trichloroethene, and vinyl chloride. The ROD designates the MCLs as ARARs for the Site, and the MCLs were not waived in the ROD. The 2012 O&M report (Shaw 2012b) states that action levels for contaminants of concern have been updated to reflect the lower value between the MCLs or ROD-specified human health criteria (HHC). However, a decision document has not been created to document these changes. An assessment of the MCLs, the HHCs and action levels should be conducted and a decision document should be created as appropriate.

The Texas Surface Water Quality Criteria are now called the Texas Surface Water Quality Standards. These regulations would only apply if contaminated groundwater is discharging into Jackson Bayou, the San Jacinto River, or other surface water bodies. These standards are regulated in 30 *Texas Administrative Code* (TAC) 307, and the regulations are updated regularly. These regulations were last updated in 2014. The Texas Commission on Environmental Quality (TCEQ) has also issued guidance on the calculation of surface water protective concentration levels (PCL) where no surface water quality standard has been promulgated. The guidance document, *Determining PCLs for Surface Water and*  *Sediment* (TCEQ 2007), would be a TBC for the Site when determining surface water quality criteria for contaminants in surface water where a standard is not contained in 30 TAC 307.

#### **Impact of Changes in Standards**

The standards review determined that the MCLs for several Site groundwater contaminants had not changed since the Fourth Five Year Review. In accordance with the ROD, the lower of the MCL or ROD-specified human health criteria should be used for purposes of determining when the groundwater at the Site has achieved the remedial objective of protection of human health and use of the groundwater onsite can be allowed.

### References

- Environmental Chemistry Services (ECS). 2013. Field Sampling Plan for Operations and Maintenance Activities, Sikes Disposal Pits Federal Superfund Site, Crosby, Harris County, Texas. Version 3.0. 6/21.
- Shaw Environmental, Inc. (Shaw). 2012. Operations and Maintenance Plan, Sikes Disposal Pits Superfund Site, Crosby, Texas, Site Number SUP034. 10/2.
- Texas Commission on Environmental Quality (TCEQ). 2007. *Determining PCLs for Surface Water and Sediment*. TCEQ Regulatory Guidance RG-366/TRRP-24. 12/2007.
- U.S. Environmental Protection Agency (EPA). 1986. *Record of Decision, Remedial Alternatives* Selection. 9/18.

### TABLE 1

ROD-Specified 10⁻⁵ Human Health Criteria and Current MCLs for Groundwater Contaminants Sikes Disposal Pits Superfund Site Crosby, Harris County, Texas

Contaminant ^a	ROD-Specified 10 ⁻⁵ Human Health Criteria (µg/L)	Current MCL (µg/L)	Year Current MCL Was Promulgated
Berylium	0.037	4	1994
Cadmium	10	5	1992
Chromium (total)	50	100	1992
Lead	50	15	1991
Mercury	0.14	2	1992
Nickel	13.4	Not Available	Not Available
Thallium	13	2	1994
Methyl methacrylate ^b	34,000	Not Available	Not Available
Styrene ^C	100	100	1992
Benzene	6.6	5	1989
Chlorobenzene	488	100	1989
Chloroform	1.9	80 ^d	2002
1,2-Dichloroethane	9.4	5	1989
Trans-1,2-dichlorpropene	87	Not Available	Not Available
Ethylbenzene	1,400	700	1992
1,1,2,2-Tetrachloroethane	1.7	Not Available	Not Available
Toluene	14,300	1,000	1992
1,1,2-Trichloroethane	6	5	1994
Trichloroethene/ Trichloroethylene	23	5	1989
Vinyl Chloride	20	2	1989

NOTES:

The groundwater criteria that currently apply (the lower of the human health criteria or the MCL) are bolded and shaded in gray.

 $\mu g/L$  – micrograms per liter ROD – Record of Decision

MCL – Maximum Contaminant Level

^aOnly contaminants that are monitored for are listed.

^bMethyl methacrylate was included in the O&M Plan in 6/001, but was not initially listed in the ROD.

^cStyrene was included in the O&M Plan in 12/2000, but was not initially listed in the ROD.

^dMCL for chloroform is expressed as total trihalomethanes, which also includes bromodichloromethane,