

FINAL FIVE-YEAR REVIEW REPORT

INSTALLATION RESTORATION SITE 9 OPERABLE UNIT 1 MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

September 12, 2007

Prepared by: DEPARTMENT OF THE NAVY Naval Facilities Engineering Command Southwest 1220 Pacific Highway, San Diego, California 92132-5190



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX 75 Hawthorne Street San Francisco, CA 94105

September 27, 2007

Lieutenant Colonel B. W. Soderburg Deputy AC/S Environmental Security Marine Corps Base Box 55508 Building 22165 Camp Pendleton, CA. 92055-5010

> Re: Five-Year Review, Installation Restoration Site 9, Operable Unit 1, Marine Corps Base, Camp Pendleton, California

Dear Lieutenant Colonel Soderburg:

The U.S. Environmental Protection Agency (EPA) Region 9 has received the Final Five-Year Review of Installation Restoration Site 9, Operable Unit 1, Marine Corps Base Camp Pendleton, dated September 12, 2007. We have reviewed the aforementioned document. Based on this review, EPA agrees with the findings, conclusions and recommendations provided in the Report, and concurs with the Marine Corps that the remedy in place at Camp Pendleton is protective of human health and the environment under the current land use and exposure pathways. We also concur with the determination of No Further Action at the Site.

If you have questions regarding this letter, please contact Martin Hausladen, Remedial Project Manager, at (415) 972-3007.

Sincerel

Michael M. Montgomery, Chief Federal Facilities and Site Cleanup Branch

cc: Theresa Morley, DON Tayseer Mahmoud, DTSC Brian Mc Daniel. CRWQCB John Chesnutt, EPA R9

FINAL FIVE-YEAR REVIEW REPORT

INSTALLATION RESTORATION SITE 9 OPERABLE UNIT 1 MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

September 12, 2007

Prepared by: DEPARTMENT OF THE NAVY Naval Facilities Engineering Command Southwest 1220 Pacific Highway, San Diego, California 92132-5190

APPROVED BY:

1

B. W. SODERBERG, LIEUTENANT COLONEL UNITED STATES MARINE CORPS DEPUTY AC/S, ENVIRONMENTAL SECURITY MARINE CORPS BASE CAMPPENDLETON BY DIRECTION OF THE COMMANDING OFFICER

SEPT 07

ü

DECLARATION OF ACCEPTANCE FOR THE FINAL FIVE-YEAR REVIEW REPORT FOR INSTALLATION RESTORATION SITE 9 OPERABLE UNIT 1 MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

Pursuant to the delegation of the authority in Sections 2(d) and 11(g) of Executive Order 12580, and U.S. Department of Defense Instruction 4715.7 of 22 April 1996, the U.S. Department of the Navy is the approval authority for Comprehensive Environmental Response, Compensation, and Liability Act five-year reviews conducted at sites under its jurisdiction, custody, or control.

B. W. SODERBERG, LIEUTENANT COLONEL UNITED STATES MARINE CORPS DEPUTY AC/S, ENVIRONMENTAL SECURITY MARINE CORPS BASE CAMP PENDLETON BY DIRECTION OF THE COMMANDING OFFICER

27 SEPT 07 Date

Five Year Review Report, IR Sile 9 (OL 1), MCB Camp Pendleton, California

EXECUTIVE SUMMARY

This Final Five-Year Review Report has been prepared by the United States Department of the Navy (DoN) in support of the Installation Restoration (IR) Program at Marine Corps Base (MCB) Camp Pendleton, California (MCBCP or Base), pursuant to Section 121(e) of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), 42 U.S.C. 9621(e), and the National Contingency Plan 40 Code of Federal Regulations (CFR) Part 300.430(f)(4). The IR Program was developed by the Department of Defense (DoD) to remediate contamination at military facilities caused by past use, storage, handling, and disposal of hazardous and other potential toxic substances, as required by Section 121 of CERCLA. Soil and groundwater at MCB Camp Pendleton have been impacted by such substances and are currently being remediated pursuant to the IR Program. The DoN is the lead DoD authority responsible for conducting remediation at the Base in conjunction with the United States Environmental Protection Agency (EPA), and with concurrence by the California Regional Water Quality Control Board (RWQCB), San Diego Region, and the State of California Department of Toxic Substances Control (DTSC).

This report provides the results of the CERCLA final five-year review for IR Site 9, 41 Area Stuart Mesa Stabilization Pond at MCB Camp Pendleton. IR Site 9 is part of Operable Unit 1 (OU1) at MCB Camp Pendleton. IR Site 9 is the only OU1 site that requires completion of a final five-year review as a result of site closure under the CERCLA program. All other sites under OU1 were considered No Further Action (NFA) sites at the time the Record of Decision (ROD) was signed.

In accordance with EPA guidance on completing five-year reviews, a final five-year report is prepared once a site has attained No Further Action status under CERCLA. This final report ends the requirement to produce any more five-year reviews for OU1. The remedy has been shown to be protective of both human health and the environment.

FIVE-YEAR REVIEW SUMMARY FORM - OU1

SITE IDENTIFICATION
Site name: Marine Corps Base Camp Pendleton, Site 9, 41 Area, Stuart Mesa Stabilization Pond
EPA ID: CA2170023533
Region: 09 State: CA City/County: Camp Pendleton, San Diego County
SITE STATUS
NPL status: I Final Deleted Other (specify)
Remediation status (choose all that apply): Under Construction Operating I Complete
Multiple OUs: YES INO Construction Complete date: <u>NA / / /</u>
Has the site been put into reuse? I YES NO
REVIEW STATUS
Reviewing Agency: EPA State Tribe Other Federal Agency Department of the Navy
Author Name: Theresa Morley, PE
Author Title: Remedial Project Manager Author Affiliation: Naval Facilities Engineering Command Southwest
Review period: July 2002 (date of last five-year review) to June 30, 2007
Date(s) of inspection: Site revisited June 27, 2007
Type of Review: Policy Post-SARA Pre-SARA NPL-Removal only Non-NPL Remedial Action site NPL State/Tribe-lead Regional Descretion)
Review number: 1 (first) 2 (second) 3 (third) Other (specify)
Triggering action: □ Actual RA Onsite Construction at OU □ Actual RA Start at OU # □ Construction Completion □ Previous Five-Year Review Report ☑ Other (specify) _Remedy Complete and final five-year review
Triggering action date: August 18, 2002 (EPA comments on previous Five-Year Review Report)
Due date (five years after triggering action date): August 18, 2007

FIVE-YEAR REVIEW SUMMARY FORM – OU1 (CONTINUED)

Issues:

· There are no issues remaining for this site.

Recommendations and Follow-up Actions:

There are no follow-up actions required.

Protectiveness Statement(s):

The remedial action at OU1, IR Site 9, is protective of human health and the environment. This determination is made based on the Explanation of Significant Difference (ESD) signed by the Federal Facilities Agreement (FFA) team on May 29, 2004. The ESD removed Site 9 from further groundwater monitoring since it was determined the site had met the cleanup requirements for groundwater as stipulated in the ROD. Based on the results of the five-year review, the groundwater remedy for IR Site 9 was found to have been effective in meeting the remedial action objectives.

Other Comments:

None.

TABLE OF CONTENTS

		ON OF ACCEPTANCE	
EXEC	CUTIVE	SUMMARY	II
		REVIEW SUMMARY FORM – OU1	
ACR		ABBREVIATIONS	
1.0	INTR	ODUCTION	1
	1.1	PURPOSE	1
	1.2	FIVE-YEAR REVIEW TRIGGER DATE	2
2.0	CHE	RONOLOGY	2
3.0	BAC	KGROUND	5
	3.1	PHYSICAL CHARACTERISTICS	
	3.2	LAND AND RESOURCE USE	
	3.3	INITIAL RESPONSE	
	3.4	CONTAMINANTS	6
		3.4.1 Groundwater	
4.0	REM	EDIAL ACTIONS	6
	4.1	REMEDY SELECTION	
	4.2	REMEDY IMPLEMENTATION	
	4.3	SYSTEM OPERATIONS/OPERATION AND MAINTENANCE	7
5.0	PRC	GRESS SINCE THE LAST FIVE-YEAR REVIEW	7
	5.1	PROTECTIVENESS STATEMENTS FROM LAST REVIEW	7
	5.2	STATUS OF RECOMMENDATIONS AND FOLLOW-UP ACTIONS FROM LAST REVIEW	
	5.3	RESULTS OF IMPLEMENTED ACTIONS	8
6.0	FIVE	-YEAR REVIEW PROCESS	8
7.0	FIVE	-YEAR REVIEW FINDINGS	8
	7.1	INTERVIEWS	9
	7.2	SITE INSPECTION	
	7.3	RISK INFORMATION REVIEW	9
	7.4	DATA REVIEW	9
	7.5	DOCUMENT REVIEW	10
8.0	TEC	HNICAL ASSESSMENT	10
	8.1	IS THE REMEDY FUNCTIONING AS INTENDED BY THE DECISION DOCUMENT?	10
	8.2	ARE THE ASSUMPTIONS USED AT THE TIME OF REMEDY SELECTION STIL VALID?	L
	8.3	HAS ANY OTHER INFORMATION COME TO LIGHT THAT COULD CALL INT QUESTION THE PROTECTIVENESS OF THE REMEDY?	

9.0	ISSUES
10.0	RECOMMENDATIONS AND FOLLOW-UP ACTIONS
11.0	PROTECTIVENESS STATEMENT 11
12.0	NEXT REVIEW 11
13.0	REFERENCES

.

FIGURES

Figure 1	Site Map
Figure 2	IR Site 9 Site Plan and Vicinity

APPENDICES

Appendix A	PHOTOGRAPHS
Appendix B	INTERVIEWS
Appendix C	OTHER SITES IN OU1 AND OTHER OUS

ACRONYMS/ABBREVIATIONS

CCR	California Code of Regulations
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CFR	Code of Federal Regulations
CLP	Contract Laboratory Program
DCA	dichloroethane
DCE	dichloroethene
DOD	
DoN	Department of Defense
DTCS	U.S. Department of the Navy
	Department of Toxic Substances Control
EPA	U.S. Environmental Protection Agency
ESD	Explanation of Significant Difference
FFA	Federal Facility Agreement
FS	feasibility study
GDIT	General Dynamics Information Technology
GIS	geographic information system
IR	Installation Restoration
IT	IT Corporation
MCB	Marine Corps Base
MCL	maximum contaminant level
mg/kg	milligrams per kilogram
mg/L	milligrams per liter
NAVFAC SW	Naval Facilities Engineering Command Southwest
NCP	National Oil and Hazardous Substances Pollution Contingency Plan
NEESA	Naval Energy and Environmental Support Activity
NPL	National Priorities List
OHM	OHM Remediation Services Corp.
OU	Operable Unit
PCE	tetrachloroethene
PRG	preliminary remediation goal
PWC	Public Works Center
RAO	Remedial Action Objective
RI	remedial investigation
RI/FS	remedial investigation/feasibility study
RNA	remediation by natural attenuation
ROD	Record of Decision
RWQCB	Regional Water Quality Control Board
SWDIV	Southwest Division Naval Facilities Engineering Command
SWRCB	California State Water Resources Control Board
TCE	trichloroethene
TPH	total petroleum hydrocarbons
UCL	upper confidence limit
VOC	volatile organic compound
USMC	United States Marine Corps
µg/kg	micrograms per kilogram
µg/L	micrograms per liter
1.0000000	

1.0 INTRODUCTION

The United States Department of the Navy (DON) has conducted a five-year review of the remedial actions implemented in accordance with the Record of Decision (ROD) issued for Installation Restoration (IR) Site 9, 41 Area Stuart Mesa Stabilization Pond, in the southwest portion of Marine Corps Base (MCB) Camp Pendleton (Figure 1). This review was conducted from April through June 2007. This report documents the results of this review. Analysis for the five-year review was conducted by the Naval Facilities Engineering Command Southwest Division (NAVFAC SW), with technical support from General Dynamics Information Technology (GDIT). This document was reviewed and finalized for compliance with DON *Policy for Conducting Five-Year Reviews Under the Installation Restoration Program* (DON, 2004), *DON Environmental Restoration Program Manual* (DON, 2006), and U.S Environmental Protection Agency (EPA) Comprehensive Five-Year Review Guidance (EPA, 2001).

The DON is conducting environmental restoration activities at the Base as part of the IR Program. The IR Program was established by the Department of Defense (DoD) pursuant to CERCLA Section 121 to identify, evaluate, and control the spread of contaminants from historical waste sites at military installations. The Base was placed on the National Priorities List (NPL) in 1989 (EPA No. CA2170023533) because groundwater and soils at various locations had become impacted with organic and inorganic constituents primarily as a result of past waste disposal practices related to vehicle maintenance and domestic and light commercial activities. The U.S. Department of the Navy (DON), acting on behalf of and in conjunction with the Base, has been conducting and implementing the IR Program at MCB Camp Pendleton since the early 1980s. The DON's cleanup efforts are being conducted in conjunction with the EPA, Region 9, the State of California Environmental Protection Agency's Regional Water Quality Control Board (RWQCB), San Diego Region, and the State of California Environmental Protection Agency's Department of Toxic Substances Control (DTSC) through a Federal Facility Agreement (FFA) signed in 1996 (EPA, 1990).

IR Site 9 is one of the Operable Unit (OU) 1 sites. The Record of Decision (ROD) for IR Site 9 was signed on December 12, 1995. This report documents the second five-year review conducted for IR Site 9, which is the only OU1 site that requires the completion of the final five-year review process as a result of site closure under the CERCLA program. All other sites under OU1 were determined to be No Further Action (NFA) sites at the time the Record of Decision (ROD) was signed.

1.1 PURPOSE

Consistent with Executive Order 12580, the Secretary of Defense is responsible for ensuring that five-year reviews are conducted at all qualifying DoD cleanup sites. According to the *Policy for Conducting Five-Year Reviews Under the Installation Restoration Program* (DoN, 2004), a final five-year report is prepared once a site has attained No Further Action status under CERCLA. This final report ends the requirement to produce any more five-year reviews. The remedy has been shown to be protective of both human health and the environment.

1.2 FIVE-YEAR REVIEW TRIGGER DATE

According to the National Oil and Hazardous Substances Pollution Contingency Plan (NCP), five-year review reports are to be completed and signed within five years of the trigger date for a site. The trigger date for this second IR Site 9 five-year review is August 18, 2007, five years from August 18, 2002, the date of the first five-year review.

2.0 CHRONOLOGY

MCB Camp Pendleton is the primary Marine Corps amphibious training center on the west coast. In addition to amphibious training, training for many of the various Marine Corps missions also is accomplished at MCB Camp Pendleton. Construction of MCB Camp Pendleton started in March 1942, and President Franklin D. Roosevelt dedicated the base in September 1942. Although MCB Camp Pendleton has been an important training facility since its inception in 1942, it was not designated a permanent base until October 1944. The base covers approximately 125,000 acres, almost entirely in San Diego County. The base currently supports more than 36,000 military personnel and employs approximately 4,600 civilians.

The DoN, acting on behalf of and in concert with the United States Marine Corps (USMC) and in accordance with authority in CERCLA, the NCP and Executive Order 12580, conducted and implemented the IR program at MCB Camp Pendleton since the early 1980s. The IR program is designed, in part, to evaluate and remedy, if necessary, contamination caused by hazardous substances, pollutants, or contaminants, pursuant to CERCLA. The initial list of eight IR sites at MCB Camp Pendleton was established on the basis of the results of the initial site assessment performed in 1983/1984 (Naval Energy and Environmental Support Activity [NEESA], 1984). In November 1989, MCB Camp Pendleton was added to the National Priorities List (NPL), primarily because an herbicide was detected in two drinking water production wells in a groundwater basin of the base.

IR Site 9 was identified during the site inspection process in 1988 (SWDIV, 1994). The site was used as a sewage pond for oxidation and percolation of raw sewage generated in Las Flores 41 Area in the southwestern part of MCB Camp Pendleton (Figure 1) from 1963 to 1974 or 1975. The site is southwest of Stuart Mesa Road and consists of an approximately 400- by 500-foot waste stabilization pond surrounded by engineered earthen berms (Figure 2). The waste stabilization pond reportedly was used for stockpiling soil contaminated with petroleum hydrocarbons, primarily fuel and oil. Mounds of dirt and dark stains were visible on the bottom of the waste stabilization pond, as indicated in the ROD. The visual inspection in 1988 also indicated that waste oils and other liquids may have been disposed of at the site.

Under the base IR program, the parties to the Federal Facility Agreement (FFA) assigned IR sites to groups (starting with Group A) based on potential impact to health and the environment. Those sites that posed the highest threat were addressed first (i.e., Group A sites). Along with five other sites, IR Site 9 was assigned to Group A. A remedial investigation (RI) of the Group A sites (SWDIV, 1993) was conducted between February 1992 and April 1993 and determined that IR Site 9 was the only site requiring further remedial action via a feasibility study (FS). Three additional rounds of groundwater monitoring (Phase II RI) were conducted between May 1993

and April 1994. The IR Site 9 FS was completed in 1994 (SWDIV, 1994) under the RI/FS program for OU 1. The remedial action for IR Site 9 was established through when the OU1 ROD was signed on December 12, 1995. IR Site 9 was the only site requiring further action under the OU1 ROD; no other sites addressed in the OU1 ROD required remedial action. These sites have all been determined to be No Further Action and are listed in Appendix C.

Based on the OU1 ROD, the remedy for IR Site 9 included no further action for soil and the following components for groundwater:

- Amend the Base Master Plan to restrict future access to groundwater in the immediate vicinity of IR Site 9 for the duration of the long-term monitoring or until groundwater contaminants no longer exceed cleanup goals. Also, in the unlikely event that IR Site 9 is converted to residential use, re-grading and the importation of clean fill, as well as notification of interested parties of remaining site contaminants (specifically one beryllium hit), would be required.
- Sample and analyze groundwater semiannually for 10 years to verify that dispersion and natural attenuation are occurring.
- Evaluate the effectiveness of the remedy no less often than every 5 years.
- Conduct compliance demonstration monitoring consisting of eight sampling events evenly spaced throughout a 1-year period during the eighth year of groundwater monitoring to assess the effectiveness of dispersion and natural attenuation processes.

The first post-ROD semiannual groundwater monitoring event was conducted on April 30, 1997 and continued through 2002. Eight wells were monitored for VOCs using EPA Method 8260B and various groundwater chemistry and bio-parameters, including total iron, ferrous and ferric iron, manganese, methane, ethane, ethene, nitrate, sulfate, sulfide, total organic carbon, pH, temperature, conductivity, turbidity, and dissolved oxygen. During the semiannual sampling for the second half of 2001, groundwater quality met the ROD Remedial Action Objectives (MCLs) in all monitored wells except 9W-07A.

The Navy conducted the first Five-Year Review for the site in 2002. The Five-Year Review concluded that, unlike VOC concentrations in other wells, PCE in monitoring well 9W-07A was not attenuating as predicted in the fate and transport model, and that PCE concentrations had increased over the last five years. Additional soil and groundwater data were recommended to investigate whether the waste stabilization pond was the source or if another separate source of PCE was present. The FFA team met and concluded that a letter work plan would be prepared to install one soil boring and one groundwater monitoring well to further assess the southeastern portion of the waste stabilization pond as a PCE source. The Draft Final Sampling and Analysis Plan (SAP) was submitted in November 2002 and the field work was conducted in January 2003.

Eight soil samples were collected from the soil boring and analyzed for VOCs. Neither PCE nor TCE were present above detection limits. The soil boring was converted to a temporary monitoring well (CPIR9-28) and groundwater samples were collected from this well. The well was sampled for VOCs: PCE and TCE were not detected in these samples. All soil and groundwater data were validated by a third party in accordance with Navy requirements. Results of the investigation were reported in a Technical Memorandum (Tech Memo, PWC, 2003) that concluded the pond was not the source of PCE or TCE in 9W-07A. The Tech Memo alsc

recommended discontinuing groundwater sampling at the site since RAOs had been met with the exception of well 9W-07A.

The Tech Memo also evaluated the chemical concentrations in soil and groundwater and included a baseline risk assessment. As part of the risk evaluation, it was determined that the PRG for beryllium had increased since the OU1 RI and the previously measured value was below the PRG. The risk assessment concluded that the concentrations in soil and groundwater (excluding 9W-07A) were protective of human health and the environment under a residential land use scenario. Therefore, no land use restrictions would be required. IR Site 9 soils meet the current (October 2004) EPA Region 9 Preliminary Remediation Goals for a residential use scenario.

The Tech Memo concluded that a separate point source release for well 9W-07A was not associated with Site 9 and that the PCE was bounded in groundwater by nondetect values. Therefore, the recommendations section proposed that a new site be established to investigate the source of VOCs in groundwater around well 9W-07A. The FFA team agreed with these findings and recommendation during the 72nd FFA meeting on April 17, 2003. The location of the well is now designated as IR Site 1114. The monitoring well network associated with Site 9 has been retained as part of Site 1114 for possible future monitoring needs.

An Explanation of Significant Difference (ESD) for OU 1 ROD IR Site 9 (PWC 2004) was prepared in order to acknowledge the early attainment of RAOs in IR Site 9 groundwater, document the conclusion of long-term groundwater monitoring, complete site closeout, and document the identification of Site 1114 (PWC 2004). The new site was designated as Site 1114 and is currently being monitored. The final signature on the ESD was June 28th, 2004.

Event	Date
Initial discovery of the Site and Process	1988 Site Inspection and sampling
NPL Listing of MCB Camp Pendleton	15 November 1989
Phase I RI	February 1992 through April 1993
Phase II RI (groundwater monitoring)	May 1993 through April 1994
FS	1994
ROD Signature	December 12, 1995
Remedial Action (start)	December 7, 1995
Monitoring of Remedial Action	Semiannually since April 30, 1997
First Five-Year Review	August 18, 2002
Technical Memorandum, Summary of Soil and Monitoring Well Sampling	July 8, 2003
Explanation of Significant Difference (ESD) for Site Closure	June 28th, 2004

The following is a chronology of events for IR Site 9, 41 Area Stuart Mesa Stabilization Pond:

3.0 BACKGROUND

This section presents site background information, including physical characteristics, land use, and contaminants.

3.1 PHYSICAL CHARACTERISTICS

IR Site 9 is located in the southwest portion of MCB Camp Pendleton, approximately 1 mile south of the Las Flores Creek groundwater basin and ¾ mile east of the Pacific Ocean (Figure 1). The site is located between two forks of a natural drainage arroyo on a relatively low-lying wave-cut terrace. An ephemeral stream trends north and east of the stabilization pond and drains south westward toward the Pacific Ocean. The nearest building is about 1,500 feet northeast of the site along Stuart Mesa Road.

IR Site 9 is located in marine terrace deposits, outside the Santa Margarita Basin. No production (drinking water) wells are located downgradient from IR Site 9. The nearest drinking water well is about 6,500 feet northeast of the site. The site is ½ mile upgradient of the nonbeneficial groundwater use boundary, as defined in the Comprehensive Water Quality Control Plan for the San Diego Basin (California State Water Resources Control Board [SWRCB], 1994). Interstate 5 runs approximately along the line demarcating this boundary.

3.2 LAND AND RESOURCE USE

The waste stabilization pond at IR Site 9 was operated as a sewage pond for oxidation and percolation of raw sewage generated in 41 Area from 1963 to 1974 or 1975. In 1975, a wet well and a lift station (Building 41300) were installed and raw sewage was pumped into a treatment facility in the 43 Area. The sewer line to the waste stabilization pond and the outfall pipe in the pond were left in place as an emergency overflow backup system and reportedly were used occasionally.

The waste stabilization pond, which contained water only briefly following heavy rainfall, was used for stockpiling soil contaminated with petroleum hydrocarbons, primarily fuel and oil. The area immediately northeast of the waste stabilization pond was used for disposal of mess hall grease trap wastes, a practice that began after sewage treatment operations at IR Site 9 were discontinued.

3.3 INITIAL RESPONSE

No removal action has been conducted since the site was identified in 1988. The Phase I RI and associated studies for IR Site 9 were conducted between February 1992 and April 1993. Three additional quarterly groundwater monitoring events (Phase II RI) were conducted from May 1993 through April 1994. In accordance with EPA guidance for conducting an RI under CERCLA (EPA, 1988), the nature and extent of contamination were assessed to a level sufficient to support ecological and human health risk assessments and the FS. Based on the human health risk assessment, the risk levels associated with exposures to soil and groundwater contamination at the site were determined to be within the risk management range established in the NCP (40 CFR 300.430[e][2][I][A][2]). The results of the RI ecological risk assessment indicated no significant risk to the environment for soil contamination at the site. However, groundwater contamination exceeded Federal and State maximum contaminant levels (MCLs) and, therefore,

required remedial action. Based on the level of groundwater contamination, the selected remedy was remediation by natural attenuation, which required no additional remedial construction or response.

3.4 CONTAMINANTS

This section discusses the contaminants that were previously identified at IR Site 9.

3.4.1 Groundwater

Groundwater analytical data demonstrated that an area of volatile organic contamination (TCE and PCE) was present downgradient from the former pond at IR Site 9. No contaminants were detected in the wells upgradient from the former effluent pond. Groundwater monitoring conducted semiannually from 1997 through 2002, indicated that TCE is present in wells 9W-06B and 9W-07A at concentrations below the MCL and that as noted above, PCE is present in well 9W-07A at concentrations exceeding the MCL. However, this well is now IR Site 1114 and is no longer part of IR Site 9.

4.0 REMEDIAL ACTIONS

This section discusses remedial actions at IR Site 9, including remedy selection, implementation, system operation, and progress.

4.1 REMEDY SELECTION

The remedial action selected for IR Site 9 was specified in the OU1 ROD (SWDIV, 1995). The OUI ROD was signed on December 12, 1995, by the parties to the FFA. The ROD stipulated the following remedial action:

- No action is needed for IR Site 9 soil contamination. Site soil was left in place. Also, in the unlikely event that IR Site 9 is converted to residential use, re-grading and the importation of clean fill, as well as notification of interested parties of remaining site contaminants (specifically one beryllium hit), would be required.
- The groundwater component of the selected remedy involved risk management through an amendment to the Base Master Plan restricting future access to groundwater in the immediate vicinity of the site and initiating monitoring of contaminant concentrations and migration. Monitoring consists of semiannual groundwater sampling and analysis of 12 wells for 10 years, with compliance monitoring consisting of eight sampling events to be conducted during the eighth year. Monitoring well locations are shown in Figure 2. An alternative evaluation will be performed once every 5 years to assess the effectiveness and document the progress of the alternative.

The human health risk associated with exposures to groundwater contamination at IR Site 9 was deemed acceptable within the risk management range. However, PCE and TCE concentrations exceeded State and Federal MCLs in two of the monitoring wells and, thus, required remedial action. Based on limited computer modeling performed as part of the FS process, the results indicated that natural attenuation would reduce groundwater contamination to less than the MCLs in 10 years and that the plume migration would not reach the ocean approximately ³/₄ mile west of IF. Site 9. Institutional controls would manage the potential risk posed by the site by

limiting access, restricting land and groundwater uses, and monitoring groundwater impacts during natural attenuation.

4.2 REMEDY IMPLEMENTATION

The remedy has been implemented as stated in the ROD. Groundwater monitoring activities, which had been performed semiannually, were concluded in late 2002 as a result of the Five Year Review.

4.3 SYSTEM OPERATIONS/OPERATION AND MAINTENANCE

The ROD did not require the construction of a remedial system. The selected remedy was based on natural attenuation.

5.0 PROGRESS SINCE THE LAST FIVE-YEAR REVIEW

Soil and monitoring well sampling were conducted in 2003 to address a data gap identified during the previous Five-Year Review (OHM, 2002). Results of the investigation were reported in a Technical Memorandum (PWC, 2003). Additional semiannual monitoring by PWC was also conducted through 2003 (PWC, 2001, 2002a, 2002b, and 2003). PCE concentrations have increased in monitoring well 9W-7A. However, supplemental sampling data have identified a separate source outside of the pond. This limited release and its attendant groundwater contamination at and in the vicinity of monitoring well 9W-7A are addressed as IR Site 1114. This new site is being monitored under the IR program. The monitoring well network formerly associated with Site 9 has been transferred to Site 1114 in case they need to be sampled. An Explanation of Significant Difference (ESD) for OU 1 ROD IR Site 9 (PWC 2004) was prepared in order to acknowledge the early attainment of RAOs in IR Site 9 groundwater, document the identification of a new IR Site (1114) associated with well 9W-07A (PWC 2004). IR Site 9 has been closed, which was documented in the ESD signed in May 2004.

5.1 PROTECTIVENESS STATEMENTS FROM LAST REVIEW

The following is the protectiveness statement from the last five year review that was completed in October 2002. The remedial action at OU-1 is protective of human health and the environment. This determination is made based on the information considered and evaluated in the performance of this five-year review update. Currently, there are no exposure pathways to groundwater at IR Site 9 and the groundwater meets the cleanup requirements stipulated in the ROD (with the exception of 9W-07A, which has been removed from IR Site 9 and is now called IR Site 1114. IR Site 9 soils do not require remediation for the current military land-use scenario, and ICs for the soil continue to restrict the future land uses in the vicinity of the site.

Since the last five year review it was determined that the PRG for beryllium had increased and the value from the OU1 ROD was now below the PRG. The concentrations in soil and groundwater (excluding 9W-07A) are protective of human health and the environment under a residential land use scenario. Therefore, no land use restrictions are now required. IR Site 9 soils meet the current (October 2004) EPA Region 9 Preliminary Remediation Goals for a residential use scenario. The Base Master Plan (currently being updated) will remove any reference to IR Site 9.

5.2 STATUS OF RECOMMENDATIONS AND FOLLOW-UP ACTIONS FROM LAST REVIEW

The last Five Year Review (2002) recommended three actions.

- Discontinue sampling of IR Site 9 groundwater. This has been completed with the last sampling event in 2003 that documented there were no concentrations in groundwater wells above MCLs, except for well 9W-07A. This well is now IR Site 1114 and the monitoring well network has also transferred to IR Site 1114 for possible future monitoring needs.
- The Explanation of Significant Difference should be finalized. The ESD to discontinue groundwater monitoring at IR Site 9, close the site, and establish a new IR site for well 9W-07A was signed, after agency review and concurrence, on June 28th, 2004.
- The groundwater at new IR Site 1114 should be investigated. The groundwater at IR Site 1114 was investigated in 2004 as part of the new Triad approach with the assistance and concurrence of the regulatory agencies. A soil gas survey is scheduled to be conducted at the site in late 2007.

5.3 **RESULTS OF IMPLEMENTED ACTIONS**

The results of the implemented actions have been: documented closure of IR Site 9 through a signed ESD and establishment of a new IR Site (1114) to investigate PCE in well (w-07A.

6.0 FIVE-YEAR REVIEW PROCESS

From April to June 2007, DoN Remedial Project Manager, Ms. Theresa Morley, PE, of NAVFAC SW, led this five-year review process, with the participation of the following team members:

- Ms. Chrissy Dangel, MCB Camp Pendleton Assistant Chief of Staff/Environmental Security
- Mr. James Hoyle, PG, GDIT (technical consultant, NAVFAC contractor)

Ms. Morley was supported by NAVFAC SW technical, legal, and managerial staff. Mr. Hoyle was supported by technical staff including engineers, hydrogeologists, and regulatory specialists.

7.0 FIVE-YEAR REVIEW FINDINGS

This section summarizes results from the site inspection conducted as part of the five-year review.

7.1 INTERVIEWS

Interviews were conducted with the former and current MCB Camp Pendleton Environmental Security staff tasked with managing IR Site 9. No substantive changes in site conditions have occurred that warrant additional interviews. The site is located in an undeveloped, remote area with limited access. The interviews are included in Appendix B.

7.2 SITE INSPECTION

On June 3, 2007, Mr. David Bloom, GDIT, conducted a visual site inspection. On June 28th, 2007, Ms. Dangel and Ms. Morley inspected and photographed the site. The site photographs are presented in Appendix A. The inspection results are summarized as follows:

- The site is not used for any purposes. The pond is surrounded by an earthen dike on all sides. The dike is about 8 feet tall as measured from the bottom of the pond, which is re atively flat all across.
- The former disposal areas show no sign of recent disposal activities. The impoundment is dry. The earthen berm surrounding impoundment is intact.
- Most of the site is covered with dense vegetation, with a few bare patches of soil, and shows minimal erosion damage.

No site changes were identified during the site inspection compared to previous inspections.

7.3 RISK INFORMATION REVIEW

The risk assessment performed during the 1994 RI process indicated that soil and groundwater contamination at IR Site 9 was within the NCP's risk management range. There was one measurement of beryllium (1.9 ppm) in soil that was above the PRG for a residential land use scenario. When the risk analysis was conducted in 2003, the PRG had been revised (to 150 ppm). The risk analysis determined that concentrations in soil and groundwater were protective of human health and the environment under a residential land use scenario. Therefore, no land use restrictions would be required.

Semiannual groundwater sampling conducted since 1997 has demonstrated attenuation of PCE and TCE in all wells except 9W-7A to below MCLs. Monitoring well 9W-7A has been transferred to IR Site 1114. Therefore, the risk from groundwater at IR Site 9 is within the acceptable criteria as defined by federal and state drinking water standards.

7.4 DATA REVIEW

This section presents a table of the validated analytical results for the constituents of concern from groundwater sampling at IR Site 9 after the last five-year review. The following data were samples taken from temporary well CPIR9-28 (PWC 2003).

TABLE 1 - GROUNDWATER ANALYTICAL RESULTS - TECH MEMO -JULY 2003

PWC Sample ID	Laboratory Sample ID	PCE (ug/kg)	TCE (ug/kg)
CPIR-28Well shallow	XCMXM3-0013S	1U	1U
CPIR-28W∈II shallow	XCMXM3-0014S	1U	1U

CPIR-28Well deep	XCMXM3-0017	1U	1UJ
CPIR-28Well deep	XCMXM3-0018	1U	1UJ

Notes:

U - Indicates the compound or analyte was analyzed for but was not detected at or above the stated limit

UJ - Indicates the compound or analyte was analyzed for but was not detected. The sample detection limit is an estimated value.

7.5 DOCUMENT REVIEW

This five-year review consisted of a review of all relevant documents and available data for IR Site 9, as listed below.

- 1. Data obtained from the Final Marine Corps Base Camp Pendleton, California, Record of Decision Operable Unit 1 (SWDIV, 1995)
- Data obtained from Groundwater Monitoring Reports issued since 1997 by Navy Public Works Center for SWDIV
- 3. Data obtained from Technical Memorandum Summary of Soil and Monitoring Well Sampling, July 2003 (PWC, 2003)
- Explanation of Significant Difference for the 1995 Record of Decision, IR Site 9 (SWDIV, 2004)

8.0 TECHNICAL ASSESSMENT

The technical assessment of the protectiveness of a remedy during a five-year review is primarily based on answering the following three questions:

- Is the remedy functioning as intended by the decision document?
- Are the assumptions (e.g., exposure assumptions, toxicity data, cleanup levels, RAOs) used at the time of remedy selection still valid?
- Has any other information come to light that could call into question the protectiveness of the remedy?

The following sections address each of these questions and how they relate to selected remedy impletion at IR Site 9.

8.1 IS THE REMEDY FUNCTIONING AS INTENDED BY THE DECISION DOCUMENT?

A review of the groundwater monitoring data from the 2003 Tech Memo indicates that TCE and PCE concentrations have been reduced below their respective MCLs. Therefore, the remedy is complete.

8.2 ARE THE ASSUMPTIONS USED AT THE TIME OF REMEDY SELECTION STILL VALID?

The standard risk screening concentration values have changed since the risk screening for soil contaminants at IR Site 9 were performed in 1994. For the Technical Memorandum and ESD, site soil concentrations were compared with current EPA Region 9 PRGs (October 2004). The one measurement of beryllium at 1.9 ppm that was above residential PRGs in 1994 is below the 2004 residential PRG of 150 ppm. The concentrations of contaminants compared favorably for a residential use scenario. The assumptions used at the time of remedy selection are still valid for site soils.

8.3 HAS ANY OTHER INFORMATION COME TO LIGHT THAT COULD CALL INTO QUESTION THE PROTECTIVENESS OF THE REMEDY?

No.

9.0 ISSUES

There are no issues for this site.

10.0 RECOMMENDATIONS AND FOLLOW-UP ACTIONS

There are no recommendations or follow-up actions required for this site.

11.0 PROTECTIVENESS STATEMENT

The remedial action at OU1, IR Site 9, is protective of human health and the environment. This determination is made based on the Explanation of Significant Difference (ESD) signed by the Federal Facilities Agreement (FFA) team on May 29, 2004. The ESD removed Site 9 from further groundwater monitoring since it was determined the site had met the cleanup requirements for groundwater as stipulated in the ROD. Based on the results of the five-year review, the groundwater remedy for IR Site 9 was found to have been effective in meeting the remedial action objectives.

12.0 NEXT REVIEW


This is the final five-year review report for this site and for OU1.


13.0 REFERENCES

Department of the Navy, 2004, Policy for Conducting Five-Year Reviews Under the Installation Restoration Program, May 21.

- PWC, see Southwest Division Naval Facilities Engineering Command, prepared by Navy Public Works Center.
- Southwest Division Naval Facilities Engineering Command, 1993, Draft Final RI Report for Group A Sites, Site 9 - Operable Unit 1 - Marine Corps Base Camp Pendleton, California, prepared by Jacobs Engineering Group Inc., October.
- Southwest Division Naval Facilities Engineering Command, 1995, Draft Final, Revision 1, Record of Decision for Operable Unit 1 - Site 9 and Group A Sites, Marine Corps Base Camp Pendleton, California, prepared by Jacobs Engineering Group Inc., 2 October.
- Southwest Division Naval Facilities Engineering Command, 2002a, Semiannual Groundwater Monitoring Report for the First Half of 2002. IR Site 9, 41 Area Stabilization Pond, Marine Corps Base Camp Pendleton, California, prepared by Navy Public Works Center, September.
- Southwest Division Naval Facilities Engineering Command, 2002b, Draft Final Sampling and Analysis Plan (Field Sampling Plan/Quality Assurance Project Plan) Monitoring Well Installation IR Site 9, 41 Area Waste Stabilization Pond, Marine Corps Base Camp Pendleton, California, prepared by Navy Public Works Center, November.
- Southwest Division Naval Facilities Engineering Command, 2003, Semiannual Groundwater Monitoring Report for the Second Half of 2002. IR Site 9, 41 Area Stabilization Pond, Marine Corps Base Camp Pendleton, California, prepared by Navy Public Works Center, February.
- Southwest Division Naval Facilities Engineering Command, 2003, Technical Memorandum, Summary of Soil and Monitoring Well Sampling, IR Site 9, Marine Corps Base Camp Pendleton, California, prepared by Navy Public Works Center, July.
- Southwest Division Naval Facilities Engineering Command, 2004, Explanation of Significant Difference for Operable Unit 1 Record of Decision, Installation Restoration Site 9, Stuart Mesa Stabilization Pond, Marine Corps Base Camp Pendleton, May 10.
- OHM, 2002, 5-Year Review for IR Site 9, Stuart Mesa Stabilization Pond, MCB Camp Pendleton, California, April.
- U.S. Environmental Protection Agency, 2001, *Final, Comprehensive Five-Year Review Guidance*, EPA/540/R-01-007, OSWER Directive 9355.7-03B-P, Office of Emergency and Remedial Response, Washington, DC, June.
- U.S. Environmental Protection Agency, 2004. Region IX Preliminary Remediation Goals (PRGs). October


FIGURES






APPENDIX A PHOTOGRAPHS

Five-Year Review Report, IR Site 9 (OU1), MCB Camp Pendleton, California



VIEWS TO NORTHEAST AND SOUTHEAST FROM WESTERN EDGE OF SITE



Five-Year Review Report, IR Site 9 (OU1), MCB Camp Pendleton, California

APPENDIX B INTERVIEWS

Five-Year Review Report, IR Site 9 (OU1), MCB Camp Pendleton, California

÷

Site Inspection Checklist

	I. SITE INF	ORMATION		
Site na	ime: Sife 9 - 41 Area Waste Stabilization	Date of inspection:	6-20-0	7
Locati	on and Region: MCB camp Pendleton	EPAID: CA2		_
	y, office, or company leading the five-year	Weather/temperatu Partly Sur	ire:	
Remed	G Access controls G G	U Monitored natural atter Groundwater containm Vertical barrier walls	0 nuation ent	
Attach	iments: G Inspection team roster attached	G Site map attac	hed	
	II. INTERVIEWS	(Check all that apply)		
(Prev)	Name Name Name Name Name S by phone Phone blems, suggestions; G Report attached	no	manager	<u>6-20-07</u> Date
2. 08	M staff	Title		
	erviewed G at site G at office G by phone Phone blems, suggestions; G Report attached	no		
3.	Local regulatory authorities and response ag office, police department, office of public health deeds, or other city and county offices, etc.) Fil Agency	or environmental heat		
	Name Problems; suggestions; G Report attached	Title	Date	Phone no.
	Agency Contact			
	Name Problems: suggestions; G Report attached	Title	Date	Phone no.
	Agency			
	Contact			s

	Name Problems; suggestions; G Report attached	Title	Date	Phone no.
k,	Other interviews (optional) G Report attach	ed.		
_				
-				
_				
_	III. ON-SITE DOCUMENTS & RE	CORDS VERIFIED (C	heck all that app	ly)
l.	G As-built drawings	G Readily available G Readily available G Readily available	G Up to date G Up to date G Up to date	
5	Site-Specific Health and Safety Plan G Contingency plan/emergency response plan Remarks		G Up to date G Up to date	G N/A
	O&M and OSHA Training Records Remarks	G Readily available	G Up to date	QN/A)
	G Effluent discharge G Waste disposal, POTW G Readily	G Readily available G Readily available y available G Up to	and a second	
	G Other permits Remarks	G Readily available	G Up to date	GN/A)
5.	Gas Generation Records G Readil Remarks	y available G Up to	o date & N/A	0
	Settlement Monument Records Remarks	G Readily available	G Up to date	G N/A
7.	Groundwater Monitoring Records	G Readily available	G Up to date	G N/A

Five-year Review Report - 2

	Remarks	Records	G Readily available	G Up to date G N/A
-	Discharge Complian	ce Records	-	
	G Air		G Readily available	G Up to date G N/A
	G Water (effluent)		G Readily available	G Up to date GN/A
	Remarks			~
	Daily Access/Securit Remarks	y Logs	G Readily available	G Up to date G N/A
-			IV. O&M COSTS	
	O&M Organization			
	G State in-house		G Contractor for State	
	G PRP in-house		G Contractor for PRP	
	Con to Commission		G Contractor for Federal Faci	lity
	G Federal Facility in- G Other O&M Cost Records G Readily available G Funding mechanism Original O&M cost e	G Up to	date) rplace	
	G Other O&M Cost Records G Readily available G Funding mechanism Original O&M cost es	G Up to Vagreement in stimate otal annual co	date rplace MIA G Breakdow ost by year for review period i	wn attached
	G Other O&M Cost Records G Readily available G Funding mechanism Original O&M cost es T From To Date From To	G Up to Vagreement fr stimate otal annual co Date	date) rptace MIAG Breakdow ost by year for review period i G Total cost G	wn attached if available
	G Other G Other G Readily available G Funding mechanism Original O&M cost ex- To Date From To Date From To Date From To	G Up to vagreement fr stimate otal annual co Date Date	date rptace MIAG Breakdow ost by year for review period i G G G G G G G G	wn attached if available Breakdown attached
	G Other O&M Cost Records G Readily available G Funding mechanism Original O&M cost ex Diginal O&M cost ex To Date From To Date From To Date From To Date	G Up to vagreement fr stimate otal annual co Date Date Date	date rptace G Breakdow ost by year for review period i G Total cost G Total cost G Total cost G Total cost G	wn attached if available Breakdown attached Breakdown attached
	G Other O&M Cost Records G Readily available G Funding mechanism Original O&M cost ex Discrete FromTo Date FromTo Date FromTo Date	G Up to Vagreement fractionate Total annual co Date Date Date Date Date	date rptace M(AG Breakdow ost by year for review period i G _	wn attached if available Breakdown attached Breakdown attached Breakdown attached

1.	Fencing damaged Remarks G Location shown on site map G Gates secured G N/A
B. O	ther Access Restrictions
1.	Signs and other security measures G Location shown on site map G N/A Remarks_Signs were removed when the site was closed
C. In	stitutional Controls (ICs)
1.	Implementation and enforcement Site conditions imply ICs not properly implemented G Yes Site conditions imply ICs not being fully enforced G Yes G N/A G N/A
	Frequency
	Contact Name Title Date Phone no.
	Reporting is up-to-dateG YesG NoReports are verified by the lead agencyG YesG No
	Specific requirements in deed or decision documents have been met (G Yes) G No G N/A Violations have been reported Other problems or suggestions: G Report attached
2.	Adequacy G ICs are adequate G ICs are inadequate Remarks
D. G	eneral
١.	Vandalism/trespassing G Location shown on site map G No vandalism evident Remarks
2.	Land use changes on site G N/A Remarks
3.	Land use changes off size G N/A Remarks
	VL GENERAL SITE CONDITIONS
A. F	oads G Applicable G N/A
1.	Roads damaged G Location shown on site map G Roads adequateG N/A Remarks

Five-year Review Report - 4

. 0	ther Site Conditions		
	Remarks		
	VII. LAN	OFILL COVERS G Applicable	S N/A
A. L	andfill Surface		
1.	Settlement (Low spots)	G Location shown on site map	G Settlement not evident
	Areal extent	Depth	
	Remarks		
_			
2.	Cracks	G Location shown on site map	
		Is Depths	
	Remarks		
3.	Erosion	G Location shown on site map	G Erosion not evident
	Areal extent		e Erosion not evident
	Remarks		
4.	Holes	G Location shown on site map	G Holes not evident
	Areal extent	Depth	
	Remarks		
5.	Vegetative Cover G Gra	ss G Cover properly establi	ished G No signs of stress
	G Trees/Shrubs (indicate size and	f locations on a diagram)	ě
	Remarks		
6.	Alternative Cover (armored ro	ck, concrete, etc.) G N/A	
	Remarks		
7.	Bulges	G Location shown on site map	G Bulges not evident
	Areal extent	Height	THE REAL PROPERTY AND INCOME.
	Remarks		
e e	Watherson	a Warmatan I	
8.	Wet Areas/Water Damage G Wet areas	G Wet areas/water damage not ev G Location shown on site map	Areal extent
	G Ponding	G Location shown on site map	Areal extent
	G Seeps	G Location shown on site map	Areal extent
	G Soft subgrade	G Location shown on site map	Areal extent

	Remarks			
).	Slope Instability G Areal extent Remarks		e map G No	evidence of slope instability
3. B	enches 3 Appl (Horizontally constructed in order to slow down the channel.)	icable G N/A mounds of earth placed across a st velocity of surface runoff and inte	teep landfill sic crept and conv	de slope to interrupt the slope rey the runoff to a lined
Ľ,	Flows Bypass Beach Remarks	G Location shown on sit	te map	G N/A or okay
2.	Bench Breached Remarks	G Location shown on sit		G N/A or okay
3.	Bench Overtopped Remarks	G Location shown on sit	te map	G N/A or okay
с. L		on control mats, riprap, grout bags Il allow the runoff water collected		
ι.	Settlement Areal extent	G Location shown on site map	G No evide	nce of settlement
-	Settlement Areal extent Remarks Material Degradation Material type	G Location shown on site map	G No evide	
1.	Settlement Areal extent Remarks Material Degradation Material type Remarks Erosion Areal extent	G Location shown on site map Depth G Location shown on site map Areal extent G Location shown on site map	G No evide G No evide	
3.	Settlement Areal extent Remarks Material Degradation Material type Remarks Erosion Areal extent Remarks Undercutting Areal extent	G Location shown on site map Depth G Location shown on site map Areal extent G Location shown on site map Depth	G No evide	nce of degradation
2.	Settlement Areal extent Remarks Material Degradation Material type Remarks Erosion Areal extent Remarks Undercutting Areal extent Remarks Obstructions Type_ G Location shown on site	G Location shown on site map G Location shown on site map Areal extent G Location shown on site map Depth G Location shown on site map Depth G No	G No evide G No evide G No evide obstructions	nce of erosion

	G Vegetation in channels does not obstru G Location shown on site map Remarks	uct flow Areal extent
D. C	over Penetrations G Applicable G N	//A
1.	Gas Vents G Active G Pa G Properly secured/locked G Functionin G Evidence of leakage at penetration G N/A Remarks	
2.	Gas Monitoring Probes G Properly secured/locked G Functionin G Evidence of leakage at penetration Remarks	g G Routinely sampled G Good condition G Needs Maintenance G N/A
3.	Monitoring Wells (within surface area G Properly secured/locked G Functionin G Evidence of leakage at penetration Remarks	g G Routinely sampled G Good condition G Needs Maintenance G N/A
4.	Leachate Extraction Wells G Properly secured/locked G Functionin G Evidence of leakage at penetration Remarks	G Needs Maintenance G N/A
5.	Settlement Monuments G L Remarks	ocated G Routinely surveyed G N/A
E. G	Gas Collection and Treatment G Ap	pplicable G N/A
1.	Gas Treatment Facilities G Flaring G Thermal destruction G Good condition G Needs Maintenance Remarks	
2.	Gas Collection Wells, Manifolds and G Good condition G Needs Maintenance Remarks	
3.	Gas Monitoring Facilities (e.g., gas m G Good condition G Needs Maintenance Remarks	nonitoring of adjacent homes or buildings) G N/A
F. C	Cover Drainage Layer G A	Applicable G N/A
i.	Outlet Pipes Inspected G F	Functioning G N/A

	Remarks			
2.	Outlet Rock Inspected Remarks		tioning	g N/A
G. D	etention/Sedimentation Por	ids G Appl	icable G	N/A
1.	Siltation Areal extent G Siltation not evident Remarks			
2.	Erosion Areal e G Erosion not evident	xtent	Depth_	
3.	Outlet Works Remarks	G Functioning	g N/A	
4.	Dam Remarks	G Functioning	g N/A	
H. R	etaining Walls	G Applicable	G N/A	
L	Deformations Horizontal displacement_ Rotational displacement_ Remarks			p G Deformation not evident
2.	Degradation Remarks			p G Degradation not evident
1. Pe	rimeter Ditches/Off-Site Di	scharge	G Applicab	le G N/A
ſ.	Siltation G Loca Areal extent Remarks	tion shown on site Depth_		
2.	Vegetative Growth G Vegetation does not im Areal extent Remarks		vn on site ma	p GN/A
3,	Erosion Areal extent Remarks	G Location show Depth	vn on site ma	
4.	Discharge Structure Remarks	G Functioning	g N/A	

	VIII. V	ERTICAL BARRIER WALLS G Applic	able GN/A	
1.		G Location shown on site map G Settl	ement not evident	
2.	G Performance not mor Frequency Head differential	ring Type of monitoring	hing	
С. Т	reatment System	G Applicable G N/A		
1.	G Metals removal G Air stripping G Filters			
	G Sampling/maintenan G Equipment properly G Quantity of groundw G Quantity of surface	G Needs Maintenance erly marked and functional ce log displayed and up to date identified vater treated annually water treated annually		
2.	G N/A G G	and Panels (properly rated and functional) bod condition G Needs Maintenance		
3.	Tanks, Vaults, Storage Vessels G N/A G Good condition G Proper secondary containment G Needs Maintenance Remarks			
4.	Discharge Structure and Appurtenances G N/A G Good condition G Needs Maintenance Remarks			
5.	G N/A G G	Treatment Building(s) G N/A G Good condition (esp. roof and doorways) G Chemicals and equipment properly stored		
6.		imp and treatment remedy) cked G Functioning G Routinely sampled ocated G Needs Maintenance	G Good condition G N/A	

	Remarks
D. Me	onitoring Data
1.	Monitoring Data G Is routinely submitted on time G Is of acceptable quality
2.	Monitoring data suggests: G Groundwater plume is effectively contained G Contaminant concentrations are declining
D. M	onitored Natural Attenuation
Į,	Monitoring Wells (natural attenuation remedy) G Properly secured/locked G Functioning G Routinely sampled G Good condition G All required wells located G Needs Maintenance G N/A Remarks G N/A
	X. OTHER REMEDIES
2	If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.
	XI. OVERALL OBSERVATIONS
A.	Implementation of the Remedy
	Describe issues and observations relating to whether the remedy is effective and functioning as designed Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.). <u>Site is closed with no land use restrictions</u> <u>There is no nisk</u> .
B,	Adequacy of O&M
	Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.

2	Early Indicators of Potential Remedy Problems
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.
D.	Opportunities for Optimization
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy. N/A

٦

r

Site Inspection Checklist

I. SITE	INFORMATION			
Site name: Site 9-41 Area Waste Stabiliza	Date of inspection	: 6/27/1	07	
Location and Region: MCB Camp Pendleton	EPAID: CA 2	EPA ID: CA 2170023533		
Agency, office, or company leading the five-year review:	The second se			
Remedy Includes: (Check all that apply) G Landfill cover/containment G Access controls G Institutional controls G Groundwater pump and treatment G Surface water collection and treatment G Other SITE IS CLOSE		ment		
Attachments: G Inspection team roster attached	G Site map atta	iched		
II. INTERVIE	EWS (Check all that apply	7)		
1. O&M site manager <u>CHR155Y DANUEL</u> Name Interviewed G at site G at office G by phone H Problems, suggestions; G Report attached	Title	-	Date	
2. O&M staff		_		
Name Interviewed G at site G at office G by phone B Problems, suggestions; G Report attached	Title Phone no.	Date		
Local regulatory authorities and response office, police department, office of public deeds, or other city and county offices, etc Agency	health or environmental h) Fill in all that apply. 			
Agency				
Name Problems; suggestions; G Report attached	Title	Date	Phone no.	
Agency	_	4		

	Name Problems; suggestions; G Report attached	Title	Date	Phone no.
				_
	Other interviews (optional) G Report attac	ched.		
	III. ON-SITE DOCUMENTS & F	ECORDS VERIFIED (C	heck all that appl	y)
E.	G O&M manual	G Readily available	G Up to date	e N/A
	G As-built drawings	G Readily available	G Up to date	G N/A
	G Maintenance logs Remarks	G Readily available	G Up to date	G-N/A
2	Site-Specific Health and Safety Plan	G Readily available	G Up to date	G N/A-
	G Contingency plan/emergency response p Remarks	lan G Readily available	G Up to date	G-N/A-
3.	O&M and OSHA Training Records	G Readily available	G Up to date	G N/A-
	Remarks			
4.	Permits and Service Agreements			
	G Air discharge permit	G Readily available	G Up to date	G-N/A
	G Effluent discharge G Waste disposal, POTW G Read	G Readily available fily available G Up t	G Up to date o date G N/A	G-N/A
	G Other permits	G Readily available	G Up to date	G-N/A-
	Remarks	Le propone principalit	1997 - 1 100 1997 -	CHRISTING.
5.	Gas Generation Records G Read	fily available G Up t	o date G N/A	
	Remarks			_
6,	Settlement Monument Records	G Readily available	G Up to date	G N/A -
	Remarks			
7.	Groundwater Monitoring Records Remarks	G Readily available	G Up to date	G N/A

	Remarks			ecords	G Readily available	G Up to date	G N/A
D	Discharge Compliance Records G Air G Water (effluent)		Records			1	
-				G Readily available	G Up to date	GNA	
				G Readily available	G Up to date	G N/A	
R	Remarks	. <u> </u>					
		ccess/Sec			G Readily available	G Up to date	G N/A
					IV. O&M COSTS		
G G	O&M Organization G State in-house G Contractor for State G PRP in-house G Contractor for PRP G Federal Facility in-house G Contractor for Federal Facility G Other G Contractor for Federal Facility						
G	3 Readil 3 Fundii		ble anism/a	G Up to da greement in p nate N	blace	own attached	
G G C	3 Readil 3 Fundir Original	ly availab ng mecha	ble anism/aj ost estir Tot	greement in p nateN	blace G Breakdo t by year for review period	if available	
G G C	3 Readil 3 Fundir Original From	ly availab ng mecha	ble anism/a; ost estir Tot _ To	greement in p nateN	Diace G Breakdo t by year for review period G Total cost	if available Breakdown attached	
G G C	3 Readil 3 Fundir Original	y availat ng mecha O&M co Date	ble anism/aj ost estir Tot	greement in p nate N al annual cos Date	Diace G Breakdo t by year for review period Total cost G	if available	
G G C F F	3 Readil 3 Fundir Original From	y availal ng mecha O&M co	ble anism/a; ost estir Tot _ To	greement in p nate N al annual cos	Diace G Breakdo t by year for review period Total cost Total cost G	if available Breakdown attached	I
G G C F F F	3 Readil 3 Fundin Original From From From	y availat ng mecha O&M co Date	ble anism/a ost estir Tot _ To _ To _ To	greement in p nate N al annual cos Date	Delace G Breakdo t by year for review period Total cost Total cost G Total cost G Total cost	if available Breakdown attached Breakdown attached Breakdown attached	1
G G C F F F	3 Readil 3 Fundin Original From From	y availat ng mecha O&M co Date Date Date	ble anism/a; ost estir Tot _ To _ To	greement in p nate N al annual cos Date Date Date	G Breakdo t by year for review period Total cost Total cost Total cost	if available Breakdown attached Breakdown attached	1
G G C F F F F	3 Readil 3 Fundin Original From From From	y availat ng mecha O&M co Date Date	ble anism/a, ost estir Tot To To To To	greement in p nate N al annual cos Date Date	Delace G Breakdo t by year for review period Total cost Total cost Total cost G Total cost G Total cost G Total cost G G G G G G G G G G G G G	if available Breakdown attached Breakdown attached Breakdown attached Breakdown attached	1 1 1
G G C F F F F	3 Readil 3 Fundin Original From From From	y availat ng mecha O&M co Date Date Date	ble anism/a ost estir Tot _ To _ To _ To	greement in p nate N al annual cos Date Date Date	Delace G Breakdo t by year for review period Total cost Total cost Total cost G Total cost G Total cost G Total cost G G G G G G G G G G G G G	if available Breakdown attached Breakdown attached Breakdown attached	1 1 1

1.	Fencing damaged Remarks	G Location shown on site map	G Gates secured		g N/A
B. C	other Access Restrictions				
1.	Signs and other security Remarks	1-11-	n on site map		
C. I	nstitutional Controls (ICs)				
1.	Implementation and end Site conditions imply ICs Site conditions imply ICs	not properly implemented	G Yes G Yes	G NO G NO	g N/A g N/A
	Frequency Responsible party/agency	self-reporting, drive by) STE			
	Contact Name		Da	te	Phone no.
	Reporting is up-to-date Reports are verified by th	e lead agency	G Yes G Yes	G No G No	G N/A G N/A
	Violations have been rep	deed or decision documents have bee orted stions: G Report attached	en met – G -Yes G-Yes	G No G No	g N/A g N/A-
2.	Adequacy Remarks	G ICs are adequate G ICs ar	re inadequate		G -N/A -
D. (General				
1.	Vandalism/trespassing Remarks	G Location shown on site map	G No vandalism	evident	
2.	Land use changes on sit Remarks	e G-N/A-			
3.	Land use changes off si Remarks	teg N/A			
		VI. GENERAL SITE CONDIT	TIONS		
A. 1	Roads G Applicable	G-N/A			
I., .	Roads damaged Remarks	G Location shown on site map	G Roads adequa	teG N/A	

Five-year Review Report - 4

3. 0	ther Site Conditions					
-	Remarks					
	· · · · · · · · · · · · · · · · · · ·					
	VII. LAN	DFILL COVERS G Applicable G	3 N/A			
A. L	andfill Surface					
1.	Settlement (Low spots) Areal extent	G Location shown on site map Depth	G Settlement not evident			
	Remarks					
2.	Cracks	G Location shown on site map				
		ns Depths				
3.	Erosion	G Location shown on site map	G Erosion not evident			
	Areal extent	Depth				
	Remarks					
4.	Holes	G Location shown on site map	G Holes not evident			
	Areal extent	Depth				
	Remarks		665.65			
5.	Vegetative Cover G Gr	ass G Cover properly establi	ished G No signs of stress			
0.	•	Vegetative Cover G Grass G Cover properly established G No signs of stress G Trees/Shrubs (indicate size and locations on a diagram) G No signs of stress G No signs of stress				
	Remarks					
6.	Alternative Cover (armored re	ock, concrete, etc.) G N/A				
	Remarks					
7.	Bulges	G Location shown on site map	G Bulges not evident			
1.	Areal extent	Height	G Bulges not evident			
	Remarks					
0	Wat Amaga/Watan Daman	C Wat areas/upter domose and	vident			
8.	Wet Areas/Water Damage G Wet areas	G Wet areas/water damage not ev G Location shown on site map	Areal extent			
	G Ponding	G Location shown on site map	Areal extent			
	G Seeps	G Location shown on site map	Areal extent			
	G Soft subgrade	G Location shown on site map	Areal extent			

	Remarks			
9.	Slope Instability G Areal extent Remarks	Slides G Location shown on sit	te map G No evidence of slope insta	bility
B. B	enches G Appl (Horizontally constructed in order to slow down the channel.)	mounds of earth placed across a s	teep landfill side slope to interrupt the crept and convey the runoff to a lined	e slope i
1.	Flows Bypass Bench Remarks	G Location shown on sit	G N/A or okay	
2.	Bench Breached Remarks	G Location shown on sit	e map G N/A or okay	_
3.	Bench Overtopped Remarks	G Location shown on si	te map G N/A or okay	
C. L		on control mats, riprap, grout bags Il allow the runoff water collected	, or gabions that descend down the sto by the benches to move off of the lan	
1.	Settlement Areal extent Remarks	G Location shown on site map Depth	G No evidence of settlement	
2.	Material Degradation Material type Remarks	G Location shown on site map Areal extent	G No evidence of degradation	
3.	Erosion Areal extent Remarks	G Location shown on site map Depth	G No evidence of erosion	
4.	Undercutting Areal extent Remarks	G Location shown on site map Depth	G No evidence of undercutting	
5.	Obstructions Type_ G Location shown on site Size Remarks		obstructions ent	
6.	Excessive Vegetative G G No evidence of excess			

	G Vegetation in channels does not obstruct f G Location shown on site map Remarks	Areal extent
D. C	Cover Penetrations G Applicable G N/A	
î.		G Routinely sampled G Good condition G Needs Maintenance
2.	Gas Monitoring Probes G Properly secured/locked G Functioning G Evidence of leakage at penetration Remarks	G Routinely sampled G Good condition G Needs Maintenance G N/A
3.	Monitoring Wells (within surface area of la G Properly secured/locked G Functioning G Evidence of leakage at penetration Remarks	G Routinely sampled G Good condition
4.	Leachate Extraction Wells G Properly secured/locked G Functioning G Evidence of leakage at penetration Remarks	G Needs Maintenance G N/A
5.	Settlement Monuments G Locate Remarks	
E. G	Gas Collection and Treatment G Applic	able G N/A
t.	Gas Treatment Facilities G Flaring G Thermal destruction G Good condition G Needs Maintenance Remarks	G Collection for reuse
2.	Gas Collection Wells, Manifolds and Pipi G Good condition G Needs Maintenance Remarks	ing
3.	Gas Monitoring Facilities (e.g., gas monito G Good condition G Needs Maintenance Remarks	oring of adjacent homes or buildings) G N/A
F. C	Cover Drainage Layer G Appli	icable G N/A
1.	Outlet Pipes Inspected G Funct	tioning G N/A

	Remarks		
2.	Outlet Rock Inspected Remarks	G Functioning	g N/A
G. D	etention/Sedimentation Por	ids G Applicable G N/A	6
1.	Siltation Areal extent G Siltation not evident Remarks	Depth	G N/A
2.	Erosion Areal e: G Erosion not evident Remarks_	ktent Depth	
3.	Outlet Works Remarks	G Functioning G N/A	
4,	Dam Remarks	G Functioning G N/A	
H. R	etaining Walls	G Applicable G N/A	
I.	Deformations Horizontal displacement_ Rotational displacement_ Remarks	G Location shown on site map Vertical displa	
2.	Degradation Remarks	G Location shown on site map	G Degradation not evident
I. Pe	rimeter Ditches/Off-Site Di	scharge G Applicable	g N/A
1.	Siltation G Loca Areal extent Remarks	tion shown on site map G Siltation Depth	1 not evident
2.	Vegetative Growth G Vegetation does not im Areal extent Remarks		g N/A
3.	Erosion Areal extent Remarks	G Location shown on site map Depth	G Erosion not evident
4.	Discharge Structure Femarks	G Functioning G N/A	

	Remarks		
2.	Outlet Rock Inspected Remarks	G Functioning	g N/A
G. D	etention/Sedimentation Por	ds G Applicable	g N/A
1.	Siltation Areal extent G Siltation not evident Remarks	Depth	G N/A
2.	Erosion Areal e G Erosion not evident Remarks	xtent De	pth
3.	Outlet Works Remarks		
4.	Dam Remarks	G Functioning G N/A	
H. F	tetaining Walls	G Applicable G N/A	
1.	Deformations Horizontal displacement Rotational displacement Remarks	G Location shown on site Vertica	map G Deformation not evident l displacement
2.	Degradation Remarks	G Location shown on site	map G Degradation not evident
I. Pe	erimeter Ditches/Off-Site Di	ischarge G Appl	icable G N/A
1.	Siltation G Loca Areal extent Remarks		
2.	Vegetative Growth G Vegetation does not in Areal extent Remarks		: map G N/A
3.	Erosion Areal extent Remarks	G Location shown on site Depth	
4.	Discharge Structure Remarks	G Functioning G N/A	

1.	VIII. V	VERTICAL BARRIER WALLS G Applic	able G-N/A
	Settlement Areal extent Remarks		lement not evident
2.	G Performance not mo Frequency Head differential	oring Type of monitoring onitoredG Evidence of breac	hing
с. т	reatment System	G Applicable G N/A	
1.	G Metals removal G Air stripping G Filters	G Oil/water separation G Bioremediation G Carbon adsorbers	
1410	G Sampling/maintenau G Equipment properly G Quantity of groundy G Quantity of surface Remarks	s and Panels (properly rated and functional)	
2.			
2.	Remarks		
	Remarks Tanks, Vaults, Stora		G Needs Maintenance
	Remarks Tanks, Vaults, Stora G N/A G G Remarks Discharge Structure	ige Vessels	G Needs Maintenance
3.	Remarks Tanks, Vaults, Stora G N/A G G Remarks Discharge Structure G N/A G G Remarks Treatment Building G N/A G G	ige Vessels food condition G Proper secondary containment and Appurtenances food condition G Needs Maintenance	G Needs Maintenance G Needs repair

	Remarks		
D. M	onitoring Data		
I.	Monitoring Data G Is routinely submitted on time G Is of acceptable quality		
2.	Monitoring data suggests: G Groundwater plume is effectively contained G Contaminant concentrations are declining		
D. M	onitored Natural Attenuation		
1.	Monitoring Wells (natural attenuation remedy) G Properly secured/locked G Functioning G Routinely sampled G Good condition G All required wells located G Needs Maintenance G N/A Remarks G N/A		
	X. OTHER REMEDIES		
	If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.		
	XI. OVERALL OBSERVATIONS		
А.	Implementation of the Remedy		
D	minimize infiltration and gas emission, etc.). SITE CLOSED- NO LUCS		
В.	Adequacy of O&M		
	Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.		

C.	Early Indicators of Potential Remedy Problems		
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.		
D.	Opportunities for Optimization		
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy		

APPENDIX C OTHER SITES IN OU1 AND OTHER OUS

Five-Year Review Report. IR Site 9 (OU1), MCB Camp Pendleton, California

The five-year reviews for Camp Pendleton have not been consolidated into one report. Since this is the final five-year review for OU1, the OU3 five-year review report was not added for the sake of clarity. Rather, that five-year review will be submitted in 2009 when the OU3 five-year review is due. No five-year reviews are required for OU2 and OU4 as all of the sites in those OUs have been closed with no land use restrictions. Once the OU5 ROD is signed, that OU will be included in the OU3 Five Year Review due in 2009.

The following is a list of the other sites in the OU1 ROD besides Site 9. All of the sites have been closed with unrestricted land use.

Site 4 - Marine Corps Air Station (MCAS) Drainage Ditch

Site 4A - Marine Corps Air Station (MCAS) Concrete-Lined Surface Impoundment

Site 24 – 26 Area Morale, Welfare and Recreation (MWR) Maintenance Facility

Five-Year Review Report, IR Site 9 (OU1), MCB Camp Pendleton, California