REMEDIAL ACTION REPORT

For

OPERABLE UNIT 1 – REMEDIAL ACTION PHASE 2 FORMER KIL-TONE COMPANY SUPERFUND SITE VINELAND, NEW JERSEY PROPERTY ID: 014 – 527 E. Cherry Street

CONTRACT NO.: W912DQ-16-D-3003 Task Order: W912DQ-18-F-3031

PREPARED FOR:

USACE – Kansas City DISTRICT 601 East 12th Street Kansas City, MO 64106



Prepared by:



2749 Lockport Road Niagara Falls, New York 14305

October 2020

TABLE OF CONTENTS

Section	1	Page
1. IN	TRODUCTION	1-1
1.1. 1.2. 1.3. 1.4. 1.5.	REMEDIAL ACTION REPORT OBJECTIVESSITE DESCRIPTIONSITE HISTORYUSACE AND EPA PROJECT MANAGEMENTREMEDIATION GOALS.	1-2 1-3 1-4
2. RE	EMEDIAL CONSTRUCTION ACTIVITIES	2-7
2.1.	Investigative/Design History of OU-1	2-7
2.	1.1. Site Geology and Hydrogeology	2-7
2.	1.2. Site Characterization Summary & Results	2-7
2.	1.3. ROD Findings	2-9
2.2. 2.3. 2.4.		2-11
3. PF	ROPERTY SPECIFIC SUMMARY REPORTS	3-14
3.1.	PROPERTY ID 014 REMEDIATION	3-14
3.	1.1. Property ID 014 Pre-excavation Sampling	3-14
3.	1.2. Property ID 014 Investigation Sampling	3-15
4. C	ONTACT INFORMATION	4-31
5 RF	FFERENCES	5-32



LIST OF FIGURES

Figure	Page
Figure 1- Site Map	1-6
Figure 3.1.1 Property ID 014 Pre-Excavation Sample Locations	3-15



LIST OF TABLES

Table	Page
	_
Table 3.1.1 Property ID 014 Pre-excavation Sample Results	3-14
Table 3.1.2 Property ID 014 Pre-excavation Investigation Sample Results	3-17
Table 4.1 Key Project Contacts	4-31



APPENDICES

Appendix A Signed Access & Restoration Agreement Forms

Appendix B Design Drawings



LIST OF ACRONYMS & ABBREVIATIONS

bgs below ground surface

CCIA Cumberland County Improvement Authority

CERCLA Comprehensive Environmental Response, Compensation and Liability Act of 1980

CQCSM Contractor Quality Control Systems Manager

CY Cubic yard

DGA Dense graded aggregate

EPA U.S. Environmental Protection Agency

FKTC Former Kil-Tone Company
HDPE High Density Polyethylene

µg/L Microgram per Liter

mg/kg Milligram per kilogram

NJDEP New Jersey Department of Environmental Protection

NPL National Priorities List

OU Operable Unit

PAL Project Action Limit PCB Polychlorinated biphenyl

PM Project Manager

PPE Personal protective equipment

QA Quality assurance

QAPP Quality Assurance Project Plan

QC Quality control

RAR Remedial Action Report

RDCSRS Residential Direct Contact Soil Remediation Standards

RI Remedial Investigation

RI/FS Remedial Investigation/Feasibility Study

ROD Record of Decision

RPM Remedial Project Manager

SES Sevenson Environmental Services, Inc.

SSHO Site Safety and Health Officer SVOC Semi volatile organic compounds

TAL Target Analyte List

USDA United State Department of Agriculture

USACE U.S. Army Corps of Engineers

USEPA United States Environmental Protection Agency

VOC Volatile organic compounds



1. INTRODUCTION

This Remedial Action Report (RAR) is being submitted by Sevenson Environmental Services, Inc. (SES) for the soils remediation component of Operable Unit 1- Phase 2 at the Former Kil-Tone Company (FKTC) Superfund site located in Vineland, New Jersey. The work was performed under Pre-Placed Remedial Action Contract (PRAC) W912DQ-16-D-3003 Task Order (TO) W912DQ-18-F-3031.

U.S. Army Corps of Engineers (USACE), Kansas City District provided technical support to the U.S. Environmental Protection Agency (EPA) during soils remediation of OU1-Phase 2 at the FKTC site. The final Remedial Design Analysis Report, contract drawings, and Specifications for Soils Remediation were completed by USACE Kansas City District on March 7, 2018. Field oversite and contract administration was provided by USACE, Philadelphia District. SES performed the remedial construction in accordance with the project design documents developed by USACE. All work was performed in accordance with site-specific project plans prepared by SES. Each plan was submitted to USACE for approval prior to commencement of specific field activities.

This contract addressed the remediation of OU-1, Phase II, site soils based on the remedial action selected in the Record of Decision (ROD) dated September 2016 for OU-1 soils:

- Excavation of an estimated 21,000 cubic yards of soil contaminated primarily with arsenic and lead from approximately 57 residential properties in the vicinity of the former Kil-Tone Company property
- Off-site disposal of excavated contaminated soil, and backfilling of excavated areas with clean fill
- Restoration of the affected properties

Representatives from EPA, USACE, and SES attended a pre-construction conference conducted at the site in August 2018. SES mobilized to the site for this Task Order in November 2018. Excavation activities started on February 13, 2019 and were substantially completed in March 2020. Remedial action construction started in December 2018 and was completed in May of 2020. On May 12, 2020, upon correction of all construction deficiencies and submittal of outstanding project documents, representatives of USACE and SES attended a final inspection. Attendance was kept minimal due to the ongoing COVID-19 pandemic.

1.1. REMEDIAL ACTION REPORT OBJECTIVES

The objectives of this report are summarized below:

• Provide a summary of pertinent background information including site description, history, and discussion of the OU.



- Present a detailed chronology of events for the remedial action effort.
- Present an extended summary of the project performance and construction quality control standards instituted by SES to ensure the successful completion of the remedial action.
- Present a summary of property specific remedial action activities completed over the course of the project.
- Present a summary of lessons learned.
- Present a summary of the project final inspection.
- Present a summary of the project costs.

1.2. SITE DESCRIPTION

The former Kil-Tone property encompasses approximately 4.08 acres at 527 East Chestnut Avenue in a mixed residential and commercial area. The FKTC property was used for pesticide manufacturing from the late 1910's until the 1930's. Contaminated soil has been identified on the property as well as surrounding residential and commercial properties. Surrounding soil, sediment, surface water and groundwater downgradient from the FKTC property have all been impacted from the FKTC. The property is bordered to the north by East Chestnut Avenue, to the east by S. 6th St., to the south by Paul St., and to the west by South East Boulevard, followed by railroad tracks. The surrounding area is both commercial and residential.

Residential properties in the area range in lot size from the smallest being .05 acres with larger lots ranging around .5 acres. Home construction dates range from 1890 to the newest being constructed as late as 1999. The majority of the properties contain single family dwellings although there are approximately 10 homes that are of duplex construction with two housing units sharing a common central wall. Most yards associated with the properties have a lawn, landscaping and impervious surfaces such as driveways, sidewalks, and patios. There are several commercial properties comingled amongst the residential properties including a fuel distribution facility, transmission service company, a salon, a restaurant and a market. In addition, there are also a few vacant lots and uninhabited properties within the residential properties.

A storm sewer located in the northwestern corner of the FKTC property receives storm water from the entire 4 acre property and discharges into the head of the Tarkiln Branch located just across South East Boulevard about 400 feet west of the property. The Tarkiln Branch is a tributary of the Parvin Branch which flows into the Maurice River which eventually flows into Union Lake. The Maurice River is located about 3.5 miles from the FKTC site while Union Lake is almost 10 miles.



1.3. SITE HISTORY

The Kil-Tone Company began operations at the property located at East Chestnut Avenue in Vineland, NJ around 1916. Kil-Tone manufactured the pesticide lead arsenate. In the mid-1920's, Kil-Tone was acquired by John Lucas & Company forming the Lucas Kil-Tone Company. The Lucas Kil-Tone Company absorbed the FKTC pesticide operations and continued manufacturing arsenic-based pesticides on the property. Around 1930, John Lucas & Company was acquired by the Sherwin Williams Company. Lucas Kil-Tone operated as a subsidiary of Sherwin Williams until they ceased operations at the property in the 1930's. Sanborn maps from 1919 to 1925 were used to identify the original site buildings used by the former Kil-Tone Company to manufacture pesticides. Buildings identified on the Sanborn maps included an acid plant, tank room, engine room, and manufacturing building for grinding, mixing, pressing and storage. A laboratory was constructed after 1919 on the southwest corner of the property.

Lead arsenate is a pentavalent form of inorganic arsenic, which exists normally as white crystals with no discernable odor, contains about 22% arsenic and is slightly soluble in cold water. Inorganic arsenicals are known to be acutely toxic. Lead arsenate was the most used of the arsenical insecticides. Information obtained from the Vineland Chamber of Commerce and the New Jersey Experiment Stations that dates between 1917 and 1926 indicates that specific products manufactured by the FKTC included Green Cross Dry Powdered Arsenate of Lead, Green Cross Standard Arsenate of Lead (paste), Green Cross Sulpho-arsenate Powder, Green Cross Sulphur and Arsenate of Lead Mixture, Modified Kil-Tone, Improved Kil-Tone, Fruit Kil-Tone, Bordeaux Mixture, Dry Powdered Arsenate of Zinc, and Beetle Mort. Based on the timeframe during which the FKTC operated, these products were regulated under the Insecticide Act of 1910. In September 1932, the US Department of Agriculture (USDA) issued a Notice of Judgement under the insecticide Act against the Lucas Kil-Tone Company for the adulteration and misbranding of Bordo (lead arsenate) and Green Cross Nico-Tone. In this judgement, the Lucas Kil-Tone Company pleaded guilty and paid a \$490 fine. This action involved shipments of Bordo Lead Arsenate and Green Cross Nico-Tone that contained ingredients (for example calcium arsenate) that were not declared on the label and greater percentages of arsenic in water soluble form than declared on the label. In 1929 and 1930, Lucas kil-Tone was also issued a Notice of Judgement for adulteration and misbranding of Green Cross Beetle Mort. The products contained ingredients that were inconsistent with the label including, a greater amount of water soluble arsenic expressed as metallic. Lucas Kil-Tone continued to operate at the property until about 1933. Since Lucas Kil-Tone ceased operations, the property has undergone several property transfers. In 1949 and 1968 Sanborn maps indicate that the Uddo Taormina Company Food Products occupied the property and the configurations of the buildings had changed. Since that time, several entities have



REMEDIAL ACTION REPORT - SECTION 1

operated on the property. The property is now owned by Urban Manufacturing, LLC, which purchased the property in 2008. Urban Sign & Crane, Inc. is the current tenant, and its operation includes the fabrication and installation of commercial signage.

The LERCO Company property is located directly across East Chestnut Avenue from the FKTC property. A fuel distribution facility operated on the LERCO property since the 1930's but is no longer in use. In 1989, a release of petroleum hydrocarbons was reported to NJDEP during the removal of a 20.000 gallon underground storage tank (UST) at the LERCO property. Since 1989, LERCO has performed remedial investigation activities on this property which included removal of several UST's, above ground storage tanks, light non-aqueous phase liquid remediation, and soil/groundwater sampling. Soil and groundwater sampling performed on the LERCO property identified high concentrations of benzene, toluene, ethylbenzene and xylenes, as well as arsenic and lead. Arsenic was identified in concentrations up to 20,500 milligrams per kilogram (mg/kg) and lead up to 28,700 mg/kg. The soil exceedances were mainly detected between 1.5 to 2 feet and 4.5 to 5 feet below ground surface (bgs) soil sampling intervals along the western and southern property boundaries. Since the initial investigation, several soil sampling events have been conducted at the LERCO property by environmental consulting companies including Aqua-Tex and RT Environmental. RT Environmental indicated that the metal compounds identified were not associated with the LERCO site operations. RT Environmental also stated that the historical operations on the LERCO site support that it has always been operated as a fueling station, with no evidence they would have generated arsenic or lead wastes. The presence of arsenic in conjunction with lead, indicate that it is likely that some portion of the lead contamination may not be petroleumrelated.

In August 2014, NJDEP initiated a site investigation to determine if the lead and arsenic contamination could be attributed to the historic operations at the FKTC property. The NJDEP investigation found arsenic on the FKTC property at concentrations as high as 740 mg/kg in the top six inches of soil and at concentrations as high as 5,800 mg/kg at depths 3.5 to 4 bgs. Groundwater samples collected from the temporary well points on the FKTC property showed arsenic concentrations from 8.1 micrograms per liter (μ g/L) to 14,000 μ g/L. This discovery prompted NJDEP to refer the site to EPA on November 14, 2014. The site was proposed to the National Priorities List (NPL) on September 30, 2015 and was added to the NPL on April 5, 2016.

1.4. USACE AND EPA PROJECT MANAGEMENT

USACE Kansas City District was responsible for the project design and contracting support. USACE Philadelphia District was responsible for



construction oversight. USACE provided full-time on-site technical representatives throughout the duration of the project. USACE representatives were responsible for ensuring the project was executed in accordance with design documents and site-specific plans. USACE on-site representatives maintained a direct line of communication with SES's project management team and EPA Region II Remedial Project Manager (RPM). Weekly project meetings were held at the site throughout the duration of the field activities. Health and safety, work progress, field observations, problems and conflicts, schedule, submittals, quality control, changes, and community relations were discussed during these meetings.

Key project personnel included:

Caroline Kwan	EPA Region II - Remedial Project Manager
Dan Patel	EPA Region II - Remedial Project Manager
Steve Creighton	USACE – Philadelphia District – CO Representative
Ian Stewart	USACE – Philadelphia District-Project Engineer
Terry Mower	USACE – Philadelphia District – Construction
<u> </u>	D

Representative

1.5. REMEDIATION GOALS

In accordance with the ROD, the EPA has adopted the following remediation goals for OU1 of the site, all of which are consistent with New Jersey Residential Direct Contact Soil Remediation Standards (RDCSRS).

Constituent in Soil	Cleanup Goal (mg/kg
Lead	400*
Arsenic	19
Dieldrin	0.04
Heptachlor epoxide	0.007
Benzo(a)pyrene	0.2
Benzo(a)anthracene	0.6
Benzo(b)flouranthene	0.6

^{*}The action limit for lead was 400 mg/kg for any single point, however, the average across the surface of each individual property had a cleanup goal of less than or equal to 200 mg/kg.



Figure 1- Site Map



1-6

2. REMEDIAL CONSTRUCTION ACTIVITIES

OU-1 Phase II remedial construction activities started in December 2018 and were completed in May 2020. A summary of the historical investigative & design steps, followed by the construction activities completed at the FKTC Superfund site during the soil remediation phase is presented below.

2.1. INVESTIGATIVE/DESIGN HISTORY OF OU-1

2.1.1. SITE GEOLOGY AND HYDROGEOLOGY

The topography of the site area is generally flat. The United States Department of Agriculture, Soil Conservation Service, Soil Survey of Cumberland County, New Jersey states that the site is located on Downer and Auro loamy sands. The Downer loamy sands are formed from fluviomarine deposits, located on river basins or hills. The Auro loamy sands occur with low hills and ancient stream terraces. The permeability is relatively slow to moderate for these soil associations. Parent material is described as loamy and gravelly alluvium. Much of the area is covered by houses, streets, driveways, buildings, parking lots and urban construction. During sampling activities, the soil types observed at the background and the residential areas included coarse sands, coarse sandy loams, coarse loamy sands, coarse sandy clays, coarse loamy sand and sand. In addition, background and residential soil samples collected during the residential soil sampling events were analyzed for grain size. The grain size analysis indicated that the background and residential soil samples are primarily sand. The percentage of sand in the background soil samples ranged from 61.4 percent to 63.9 percent. The percentage of sand in the residential soil samples ranged from 54.4 percent to 85 percent. The grain size analysis indicated that the background and residential soil samples also contained silt, clay, and colloids. During sampling activities, fill material was routinely encountered in some of the soil borings. The fill material included concrete, red brick, coarse sand, coarse black sand, coarse orange and orange black sand with asphalt, brick and rock shards, plastic, terra cotta, dark brown soil fill, various types of variegated dark brown soil and fill, coal fragments, coal ash, silt, small shards of coal, porcelain, slag and trash.

2.1.2. SITE CHARACTERIZATION SUMMARY & RESULTS

The preliminary sampling that was initiated in January 2015 was used to help delineate the nature and extent of contamination. To date, thousands of environmental samples have been collected from soil, sediment, groundwater and surface water. Sampling has occurred on publically



REMEDIAL ACTION REPORT - SECTION 2

owned and commercial/residential properties in the vicinity of the FKTC property.


Soil samples collected from residential properties were analyzed for metals, VOC's, SVOC's, including PAH's, pesticides, and PCB's. The analytical results for residential soil samples were compared to NJDEP's RDCSRS. Based on the residential sampling data, lead and arsenic were detected most frequently and at the greatest concentrations above New Jersey RDCSRS of 400 mg/kg and 19 mg/kg, respectively. Soil samples had concentrations of arsenic and lead up to 1,000 mg/kg for arsenic and 5,700 mg/kg for lead. All VOC's were detected at levels below both NJDEP RDCSRS's and EPA risk-based levels. All metals other than lead and arsenic, all SVOC's, with the exception of three PAH's, and all but two pesticides were also detected below these two benchmarks. All analytical data are available in the RI and RI addendum reports in the administrative record.

The pesticides found at the residential properties at concentrations above their RDCSRS (and their respective standard) are dieldrin (.04 mg/kg) and heptachlor epoxide (0.07 mg/kg). Maximum concentrations were found to be .49 mg/kg for dieldrin and .38 mg/kg for heptachlor epoxide. The PAH's found at concentrations above their RDCSRS (and their respective standards) are benzo(a)pyrene (0.2 mg/kg), benzo(a)anthracene (0.6 mg/kg), and benzo(b)fluoranthene (0.6 mg/kg); these were detected at concentrations as high as .81 mg/kg, 2.1 mg/kg, and 2.2 mg/kg, respectively. These pesticides and PAH's were found less frequently than arsenic and lead at the residential properties at concentrations above RDCSRS.

Contamination is primarily found in shallow soil on residential properties, though some areas of deeper contamination were identified. Shallow soil is generally defined as the 0-2 foot depth interval, and the maximum depth of soil sampling was 6 feet. The estimated volume of soil to be addressed is approximately 21,000 cubic yards, though this volume may increase during planning and/or implementation of the remedial action if additional contamination associated with the site is found.

Contaminated soil on the residential properties is likely the result of surface water runoff and air dispersion from the FKTC property. A likely secondary cause for contamination of remedial properties would also include the use of excavated fill material from the FKTP as backfill material on nearby properties.

The RI report for OU1 of the site was finalized in July 2016.



2.1.3. ROD FINDINGS

In September 2016, the USEPA issued a ROD for OU-1. Based upon the requirements of CERCLA, the results of the site investigations, the detailed analysis of the alternatives, and public comments, EPA's selected remedy to address contaminated soil at the residential properties is remediation of the OU-1 contaminated Site soils. The response action selected in the ROD dated September 2016 for OU-1 soils includes:

- -Excavation of an estimated 21,000 cubic yards of soil contaminated primarily with arsenic and lead from approximately 57 residential properties in the vicinity of the FKTC property, off-site disposal of contaminated soil and backfilling with clean fill; and
- -Restoration of the affected properties

2.2. SITE SUBCONTRACTORS

SES began subcontractor selection by preparing an Invitation for Bid (IFB) for any items Sevenson would be utilizing a subcontractor for. Below are the listed subcontractors and description of work for the Kil-Tone OU1-Phase II remediation.

- Aliano Brothers-Vineland, NJ
 - Performed masonry work for the site including the garage construction at property ID 003 as well as the crawl space foundation construction for property ID 001.
 - Constructed all retaining walls on-site for property IDs 001, 003, and 004
- ATC Group Services, LLC-Burlington, NJ
 - o ATC performed all compaction testing for the site along with on-site concrete testing and off-site compressive strength testing.
 - ATC also provided SES with proctors for backfill use on both the DGA and common backfill.
- B&B Drilling- Stanhope, NJ
 - B&B Drilling performed all mechanical core sampling for the project, mainly for property IDs 014 and 035 investigative sampling
- Capitol Environmental- Newark, DE
 - Capital performed all management for off-site disposal activates. They handled coordination with the Cumberland County Landfill and trucking associated with it.
 - Capital was also responsible for all aggregate deliveries to the site (DGA, #57 Stone)
- Chem-Tech- Clifton, NJ
 - Provided site analytical for all soil waste Characterization as well las analytical for clean source material



- Provided all analytical for confirmation sampling PAHs and Pesticides
- Dun Rite Aggregate & Sand- Vineland, NJ
 - o Provided common backfill and topsoil for the site
- East Coast Liner- Toms River, NJ
 - o Installation of the 60 Mil HDPE liner used under the stockpile pad
- EB Fence- Sicklerville, NJ
 - All fence restoration completed on-site including chain-link, stockade and vinyl fence. This also included all installation of gates on-site
- Ehrlick Pest Control- Vineland, NJ
 - o Conducted all rodent eradication before demolition of structures
- Eurofins- Savannah GA
 - o Provided metals analytical support for the project
 - o Provided wastewater characterization analytical for the project
- Giordanos Recycling- Vineland, NJ
 - o Provided all demolition and construction debris removal for the project
- Master Locators- Glen Mills, PA
 - Conducted all Ground Penetrating Radar (GPR) for the site and provided findings on easy to identify drawings
- McVac Environmental- Laurence Harbor, NJ
 - Performed all vac truck remediation for under the crawl space of Property ID 001
- Mountainview Layout- Rockaway, NJ
 - Conducted all survey activities on-site including but not limited to; grade layout, excavation layout, as-built drawings, depth of excavation drawings and all topo surveys
- Pac Van- Indianapolis, IN
 - Site trailers
- Remington & Vernick Engineers- Haddonfield, NJ
 - Provided all engineering oversite for items such as retaining wall,
 CMU garage and deck designs. Additionally provided engineering for the support system of the crawl space at property ID 001
- Ricky Slade- Bridgeton, NJ
 - o Provided all concrete restoration for the site
 - o Provided all asphalt restoration for the site
- Rogers Cipollono Electric- Atco, NJ
 - Licensed electrician who provided all electrical installations or disconnects for the site
- Seismic Survey Incorporated- Frederick, MD
 - o Provided all vibration and crack gauge monitoring for the project
 - Provided all pre-con photos of properties both interior and exterior if allowable
- Stella Contracting, Inc.- Elmer, NJ
 - o Provided all clearing & grubbing activities for the site



- Stoltzfus Structures- Atglen, PA
 - Provided all garage and shed structure replacements for the site as needed
- Tony Campana Plumbing- Vineland, NJ
 - Licensed plumber who provided all plumbing repairs and installations for the site
- Tri-County Security- Vineland, NJ
 - Security company utilized for site security during non-working hours
- Turf Construction- Vineland, NJ
 - Provided all landscaping needs which included sod placement, hydro seeding, tree and shrub planting and all mulching.
 - o Provided lawn maintenance under a 90 day maintenance period

2.3. DUST CONTROL/AIR MONITORING

Real time PM10 perimeter air monitoring was performed during intrusive remediation activities for dust and particulate matter less than 10 microns (PM10) in size using a TSI Dust Trak II Model 8530 Aerosol Monitors (DTs). Monitors were located around the perimeter of each excavation area which included, at a minimum, one unit downwind, one unit upwind and a unit on either side of the area being excavated.. The DTs measured fugitive dust emissions for PM10 particulates in real time. Monitor locations were based on wind direction and the configuration of the properties. The DTs were housed in enclosures equipped with Netronix telemetry transmitters (Thiamis-1000) capable of broadcasting data to the "cloud". The collected data was reviewed by the SSHO and summarized in the Daily Health and Safety Report.

In addition, the telemetry system was set up to alert the SSHO if the PM10 fugitive dust emission reached .075 mg/m³. The telemetry system sent out an alert via text message and email to the Netronix telemetry system users, when an action level exceedance occurred. The DTs were calibrated annually by the manufacturer. Prior to each use, the DTs were zeroed using a zero-dust filter attached to the inlet.

Throughout the OU1 remedial action, best engineering practices (including air monitoring, dust control and erosion control) were used to ensure the safety of the surrounding community during construction. Water sprayed from on-site installed hydrants or hose bibs located at residence homes, was the primary method for dust suppression to limit migrating from the site during excavation/demolition. Other actions taken to minimize dust being generated included:

- Minimizing concurrent operations;
- Applying water on and sweeping haul roads;



- Wetting and misting equipment and structures;
- Spraying mist on buckets during material handling and dumping;
- Placing polyethylene on the ground surface where trucks are loaded, and material loaded into trucks was not be dropped from heights above the truck body;
- Hauling materials in properly covered containers;
- Covering stockpiled materials;
- Reducing the active work area surface and limiting the number of concurrent operations; and
- Regular washing of construction equipment.

2.4. SOIL SAMPLING AND ANALYSIS

Two distinct types of sampling were performed for the remediation of the properties. Pre-excavation sampling was conducted to aid in the remediation design, to establish boundaries between contaminated soils and non-contaminated soils. These sample results were utilized to establish boundaries before excavation. Confirmation sampling was conducted along the established excavation boundaries to confirm results below the Project Action Limits (PAL), delineating the extent of the contamination area. A majority of confirmation samples were also conducted prior to excavation to limit any areas where secondary excavation would be needed once an area was already backfilled. With both sample types, if a sample was found to be above the PAL, additional sampling was conducted until a sample was analyzed with results below the PAL. Any sidewall sample with results above the PAL were generally resampled with a 5' step-out until results below the PAL were achieved. Bottom samples with results above the PAL were generally resampled in 1' increments until results below the PAL were achieved.

Although most pre-excavation soil sampling took place prior to mobilization as part of the USACE/NWK-managed effort, additional pre-excavation samples were needed to better define the excavation areas and make the drawings compliant with NJDEP regulations. Additional samples were added to meet the NJDEP requirement for one sidewall sample at least every 30 linear feet as well as at least one bottom sample every 900 square feet. Sidewall samples were not required for any excavation depth changes of less than 1 foot. Field duplicate samples were also taken every 20 samples to ensure laboratory conformity. These same standards also held true for all confirmation sampling on the site. All pre-excavation samples were analyzed for lead and arsenic.

Additionally, investigative pre-excavation samples were also needed for property ID's 014 and 035. Property 035 investigation yielded eventual clean bottom



REMEDIAL ACTION REPORT - SECTION 2

samples so remediation of the property could be achieved. Property 014 started with an initial round of sampling which identified contamination deeper than 16' around the dwelling. Additionally, extremely high amounts of arsenic and lead were found with a maximum of 13,000 mg/kg of arsenic and 31,000 mg/kg of lead were identified on property ID 014 (527 E Cherry St) in boring B081, approximately 6' bgs. This warranted 2 additional pre-excavation sampling rounds for property 014 which also included coring through the foundation of the house in the basement. Although results weren't near the maximum found prior, several areas under the building remained contaminated well above clean-up criteria. Eventually property ID 014 was removed from SES scope of work and pushed to a future phase of work.

Due to the contamination found on property ID 014, 2 additional rounds of pre-excavation sampling were also conducted on property IDs 029 and 084. Additional contaminated areas were identified which expanded the remediation for the properties. Additional quantities are listed in the property specific write-ups located in Section 3 of the RAR. A total of 1,009 pre-excavation samples were taken during OU1-Phase II of the Kil-Tone Superfund Site

A majority of post excavation sampling and analysis of soils (confirmation samples) were performed prior to excavation as described in the USACE-approved Sampling and Analysis Plan. Confirmation samples began to show several areas where PAH's were present, changing the way confirmation sampling was conducted. Per RFI #0013, SES was granted the approval to take confirmation samples in-situ, allowing identification areas of secondary excavation before the area was excavated. This in turn allowed SES to develop excavation lenses to include secondary excavation areas, expediting excavation and backfill operations within the residential remediation. All confirmation sampling included analysis for site specific PAH and pesticide COC's. Per EPA direction, any PAH or pesticide COC discovered 24" or deeper below ground surface without additional arsenic or lead contamination above the PAL's, remediation was not nesecarry as it posed no danger to human health at that depth.

Additionally, any exterior sidewall sample was also analyzed for lead and arsenic for record purposes. A total of 600 confirmation samples were taken during OU1-Phase II of the Kil-Tone superfund Site. All samples were collected and analyzed prior to the start of excavation.



3. PROPERTY SPECIFIC SUMMARY REPORTS

Section 3 covers all property specific summaries of work completed.

3.1. PROPERTY ID 014 REMEDIATION

This section provides a summary of the remedial action activities conducted at Property ID 014, located at 527 East Cherry St. (Block 4116, Lot 7). Due to pre-excavation sampling analysis of the property, it was determined that remedial action for the property would be moved to a future phase.

3.1.1. PROPERTY ID 014 PRE-EXCAVATION SAMPLING

Additional pre-excavation samples were needed to accommodate NJDEP regulations and collected from property 014 prior to excavation on December 17, 2018 with an additional secondary sample collected on February 4, 2019. Bottom and interior sidewall samples were collected from the predefined excavation lenses. All pre-excavation soil samples were analyzed for both arsenic and lead in accordance with the approved site QAPP.

Pre-excavation sample results for Property ID 014 are summarized in Table 3.1.1 below. Two interior sidewall samples were analyzed with one sample exceeding PALs. A secondary interior sidewall sample was collected and analyzed with results exceeding the PALs. At this point, it had been determined the property would be moved to a future phase, no additional samples were collected at this time. A total of five bottom samples were taken all of which were below PALs. Pre-excavation sample locations are shown in Figure 3.1.1.

Table 3.1.1 Property ID 014 Pre-excavation Sample Results

Table 3.1.1 Property	ID 014116-ex	cavation sampi	e Results						
Table 3.1.1 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION SAMPLE RESULTS		PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B047-121718	12/17/2018	36"	N/A	N/A	N/A	N/A	N/A	5.3	13
PRE-014-B048-121718	12/17/2018	48"	N/A	N/A	N/A	N/A	N/A	1.4 J	5
PRE-014-B049-121718	12/17/2018	24"	N/A	N/A	N/A	N/A	N/A	4.5	260
PRE-014-B050-121718	12/17/2018	24"	N/A	N/A	N/A	N/A	N/A	19	22
PRE-014-B051-121718	12/17/2018	36"	N/A	N/A	N/A	N/A	N/A	3.9	68
PRE-014-SW057-121718	12/17/2018	36"-48"	N/A	N/A	N/A	N/A	N/A	29	27




Table 3.1.1 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION SAMPLE RESULTS		PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-SW057-020419-1 ²	2/4/2019	36"-48"	N/A	N/A	N/A	N/A	N/A	81	110
PRE-014-SW058-121718 12/17/2018		24"-48"	N/A	N/A	N/A	N/A	N/A	1.9	9.5

NOTES:

Bold Italicized results indicate an exceedance to Project Action Limits (PALs)

Figure 3.1.1 Property ID 014 Pre-Excavation Sample Locations



3.1.2. PROPERTY ID 014 INVESTIGATION SAMPLING

Per contract drawings, additional investigation samples needed to be collected from around the house to determine excavation depths. Initially, a total of 24 boring locations were provided, to be sampled at 12" intervals or until the water table was reached. Arsenic levels analyzed from the

Sevenson Environmental Services, Inc.

¹ NJAC 7:26D Soil Remediation Criteria for Residential Direct Contact

² No further samples at this time, property moved to future phase

All sample results reported in mg/kg mg/kg = milligram(s) per kilogram

U - Result not detected

J - Parameter not detected; quantitation is an estimation

N/A - Non-applicable

OU1- PHASE 2 REMEDIAL ACTION Former Kil-Tone Superfund Site Vineland, New Jersey REMEDIAL ACTION REPORT - SECTION 3

sampling event reached as high as 13,000 mg/kg while lead was 31,000 mg/kg, respectively.

A second mobilization for core sampling was made at the direction of USACE. An additional 18 boring locations were provided, to be sampled at 12" intervals or until the water table was reached. This also included six core samples through the basement floor. A majority of the sample locations resulted in some level of contamination with the highest concentration of arsenic at 9,500 mg/kg while lead had a high concentration of 12,000 mg/kg. All investigation core samples can be found below in table 3.1.2 with all sample locations shown in Figure 3.1.1, above.



OU1- PHASE 2 REMEDIAL ACTION Former Kil-Tone Superfund Site Vineland, New Jersey REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 Property ID 014 Pre-excavation Investigation Sample Results									
Table 3.1.2 - Kil-Tone Superfund Site-O	U1-Phase II	ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PROPERTY ID 014			antin acene	nuoranthene	pyrene		еролие		
PRE-EXCAVATION INVESTIGATION SA RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B068-121818-1	12/18/2018	12"	N/A	N/A	N/A	N/A	N/A	44	170
PRE-014-B068-121818-2	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	5.2	45
PRE-014-B068-121818-3	12/18/2018	36"	N/A	N/A	N/A	N/A	N/A	3	7.1
PRE-014-B068-121818-4	12/18/2018	48"	N/A	N/A	N/A	N/A	N/A	9	98
PRE-014-B068-121818-5	12/18/2018	60"	N/A	N/A	N/A	N/A	N/A	16	100
PRE-014-B068-121818-6	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	39	44
PRE-014-B068-121818-7	12/18/2018	84"	N/A	N/A	N/A	N/A	N/A	510	6.7
PRE-014-B068-121818-8	12/18/2018	96"	N/A	N/A	N/A	N/A	N/A	150	5.3
PRE-014-B068-121818-9	12/18/2018	108"	N/A	N/A	N/A	N/A	N/A	25	5.7
PRE-014-B068-121818-10	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	500	11
PRE-014-B068-121818-11	12/18/2018	132"	N/A	N/A	N/A	N/A	N/A	33	2.8
PRE-014-B068-121818-12	12/18/2018	144"	N/A	N/A	N/A	N/A	N/A	60	2.9
PRE-014-B068-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	190	2.1
PRE-014-B068-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	56	3.7
PRE-014-B068-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	11	6.4
PRE-014-B068-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	1.6	5.9
PRE-014-B069-121818-1	12/18/2018	12"	N/A	N/A	N/A	N/A	N/A	25	180
PRE-014-B069-121818-2	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	130	150
PRE-014-B069-121818-2-1*	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	130	130
PRE-014-B069-121818-3	12/18/2018	36"	N/A	N/A	N/A	N/A	N/A	7	8.6
PRE-014-B069-121818-4	12/18/2018	48"	N/A	N/A	N/A	N/A	N/A	6.4	11
PRE-014-B069-121818-5	12/18/2018	60"	N/A	N/A	N/A	N/A	N/A	1.8	18
PRE-014-B069-121818-6	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	350	240
PRE-014-B069-121818-7	12/18/2018	84"	N/A	N/A	N/A	N/A	N/A	190	7.5
PRE-014-B069-121818-8	12/18/2018	96"	N/A	N/A	N/A	N/A	N/A	190	3.5
PRE-014-B069-121818-9	12/18/2018	108"	N/A	N/A	N/A	N/A	N/A	220	2.1
PRE-014-B069-121818-10	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	87	1.2
PRE-014-B069-121818-11	12/18/2018	132"	N/A	N/A	N/A	N/A	N/A	52	1.8
PRE-014-B069-121818-12	12/18/2018	144"	N/A	N/A	N/A	N/A	N/A	310	6
PRE-014-B069-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	71	3.3
PRE-014-B069-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	4.3	4.8
PRE-014-B069-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	2.4	5.5
PRE-014-B069-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	3.7	2
PRE-014-B070-121818-1	12/18/2018	12"	N/A	N/A	N/A	N/A	N/A	580	740
PRE-014-B070-121818-2	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	14	12
PRE-014-B070-121818-3	12/18/2018	36"	N/A	N/A	N/A	N/A	N/A	1.3	4.6
PRE-014-B070-121818-4	12/18/2018	48"	N/A	N/A	N/A	N/A	N/A	7.8	15
PRE-014-B070-121818-5	12/18/2018	60"	N/A	N/A	N/A	N/A	N/A	1.5	11
PRE-014-B070-121818-6	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	110	180
PRE-014-B070-121818-7	12/18/2018	84"	N/A	N/A	N/A	N/A	N/A	9500	3600

REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S	AMPLE	DAI - / /I - \1					•		
RESULTS	Т	PALs (mg/kg) ¹	0.6 mg/kg	0.6 mg/kg	0.2 mg/kg	0.04 mg/kg	0.07 mg/kg	19 mg/kg	400 mg/kg
SAMPLE ID	DATE	DEPTH	1116/116	1116/116	1116/116	1116/116	1116/116	1116/116	1116/116
PRE-014-B070-121818-8	12/18/2018	96"	N/A	N/A	N/A	N/A	N/A	320	5.1
PRE-014-B070-121818-9	12/18/2018	108"	N/A	N/A	N/A	N/A	N/A	330	6.3
PRE-014-B070-121818-10	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	89	3.3
PRE-014-B070-121818-10- 1*	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	160	1.8
PRE-014-B070-121818-11	12/18/2018	132"	N/A	N/A	N/A	N/A	N/A	85	1.3
PRE-014-B070-121818-12	12/18/2018	144"	N/A	N/A	N/A	N/A	N/A	75	1.9
PRE-014-B070-020519-14	12/18/2018	168"	N/A	N/A	N/A	N/A	N/A	95	2.7
PRE-014-B070-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	160	4.3
PRE-014-B070-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	170	6.5
PRE-014-B071-121818-1	12/18/2018	12"	N/A	N/A	N/A	N/A	N/A	42	89
PRE-014-B071-121818-2	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	2.7	25
PRE-014-B071-121818-3	12/18/2018	36"	N/A	N/A	N/A	N/A	N/A	5.3	45
PRE-014-B071-121818-4	12/18/2018	48"	N/A	N/A	N/A	N/A	N/A	5.7	490
PRE-014-B071-121818-5	12/18/2018	60"	N/A	N/A	N/A	N/A	N/A	4.3	33
PRE-014-B071-121818-6	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	13	37
PRE-014-B071-121818-7	12/18/2018	84"	N/A	N/A	N/A	N/A	N/A	1100	8.9
PRE-014-B071-121818-8	12/18/2018	96"	N/A	N/A	N/A	N/A	N/A	170	5.5
PRE-014-B071-121818-9	12/18/2018	108"	N/A	N/A	N/A	N/A	N/A	210	38
PRE-014-B071-121818-10	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	89	61
PRE-014-B071-121818-11	12/18/2018	132"	N/A	N/A	N/A	N/A	N/A	110	3.8
PRE-014-B071-121818-12	12/18/2018	144"	N/A	N/A	N/A	N/A	N/A	55	1.6
PRE-014-B071-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	140	3
PRE-014-B071-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	120	3.7
PRE-014-B071-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	130	4.6
PRE-014-B071-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	130	3
PRE-014-B072-121818-1	12/18/2018	12"	N/A	N/A	N/A	N/A	N/A	14	45
PRE-014-B072-121818-2	12/18/2018	24"	N/A	N/A	N/A	N/A	N/A	14	55
PRE-014-B072-121818-3	12/18/2018	36"	N/A	N/A	N/A	N/A	N/A	6.8	22
PRE-014-B072-121818-4	12/18/2018	48"	N/A	N/A	N/A	N/A	N/A	4.4	12
PRE-014-B072-121818-5	12/18/2018	60"	N/A	N/A	N/A	N/A	N/A	74	1300
PRE-014-B072-121818-6	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	360	110
PRE-014-B072-121818-6-1*	12/18/2018	72"	N/A	N/A	N/A	N/A	N/A	360	60
PRE-014-B072-121818-7	12/18/2018	84"	N/A	N/A	N/A	N/A	N/A	200	4.3
PRE-014-B072-121818-8	12/18/2018	96"	N/A	N/A	N/A	N/A	N/A	7.1	5.8
PRE-014-B072-121818-9	12/18/2018	108"	N/A	N/A	N/A	N/A	N/A	16	39
PRE-014-B072-121818-10	12/18/2018	120"	N/A	N/A	N/A	N/A	N/A	21	1.4
PRE-014-B072-121818-11	12/18/2018	132"	N/A	N/A	N/A	N/A	N/A	37	1.6
PRE-014-B072-121818-12	12/18/2018	144"	N/A	N/A	N/A	N/A	N/A	72	2.9
PRE-014-B072-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	98	3.9
PRE-014-B072-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	5.8	3.8



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O PROPERTY ID 014	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B072-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	13	4.8
PRE-014-B072-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	5.6	8.4
PRE-014-B073-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	150	220
PRE-014-B073-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	28	84
PRE-014-B073-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	370	1100
PRE-014-B073-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	330	1100
PRE-014-B073-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	210	9.3
PRE-014-B073-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	130	37
PRE-014-B073-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	670	6.5
PRE-014-B073-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	41	4.9
PRE-014-B073-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	40	3.3
PRE-014-B073-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	18	1.6
PRE-014-B073-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	15	30
PRE-014-B073-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	67	3.3
PRE-014-B073-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	160	3.3
PRE-014-B073-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	150	8.9
PRE-014-B073-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	94	4.2
PRE-014-B073-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	33	5.3
PRE-014-B074-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	21	36
PRE-014-B074-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	5.4	140
PRE-014-B074-121918-2-1*	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	6.6	150
PRE-014-B074-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	4.3	18
PRE-014-B074-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	16	15
PRE-014-B074-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	1200	2000
PRE-014-B074-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	210	33
PRE-014-B074-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	52	4
PRE-014-B074-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	21	5
PRE-014-B074-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	41	8
PRE-014-B074-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	2.5	.93 J
PRE-014-B074-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	3.2	1.1
PRE-014-B074-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	75	4.9
PRE-014-B074-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	55	4.7
PRE-014-B074-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	1.9	3.2
PRE-014-B074-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	1.9	5.2
PRE-014-B074-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	2.9	4.7
PRE-014-B075-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	22	110
PRE-014-B075-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	15	150
PRE-014-B075-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	16	73
PRE-014-B075-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	72	57
PRE-014-B075-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	7.2	18



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O	U1-Phase II	ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S	AMPLE	DAI - / /I - \1			10		•		
RESULTS	<u> </u>	PALs (mg/kg) ¹	0.6 mg/kg	0.6 mg/kg	0.2 mg/kg	0.04 mg/kg	0.07 mg/kg	19 mg/kg	400 mg/kg
SAMPLE ID	DATE	DEPTH	IIIg/ Ng	IIIg/ Ng	IIIg/ Ng	IIIg/ Ng	1116/116	IIIg/ Ng	IIIg/ Ng
PRE-014-B075-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	47	9.7
PRE-014-B075-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	38	11
PRE-014-B075-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	28	2.2
PRE-014-B075-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	72	29
PRE-014-B075-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	15	3.7
PRE-014-B075-121918-10- 1*	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	12	4.3
PRE-014-B075-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	64	3.5
PRE-014-B075-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	110	2.6
PRE-014-B075-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	230	3.6
PRE-014-B075-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	200	5.7
PRE-014-B075-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	110	4.1
PRE-014-B075-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	91	4.2
PRE-014-B076-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	7.4	25
PRE-014-B076-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	93	390
PRE-014-B076-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	75	89
PRE-014-B076-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	4.7	63
PRE-014-B076-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	7	7.3
PRE-014-B076-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	4.7	120
PRE-014-B076-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	1.9 U	4.7
PRE-014-B076-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	1.8
PRE-014-B076-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.6
PRE-014-B076-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	1.2 J	7.1
PRE-014-B076-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	60	1
PRE-014-B076-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	8.7	4.5
PRE-014-B077-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	15	120
PRE-014-B077-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	11	18
PRE-014-B077-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	2.3	7.3
PRE-014-B077-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	7	12
PRE-014-B077-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	42	60
PRE-014-B077-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	800	66
PRE-014-B077-121918-6-1*	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	1000	170
PRE-014-B077-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	370	7.3
PRE-014-B077-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	270	5.4
PRE-014-B077-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	130	2.3
PRE-014-B077-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	52	1.4
PRE-014-B077-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	150	3.5
PRE-014-B077-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	170	2.9
PRE-014-B077-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	3	5
PRE-014-B078-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	18	150
PRE-014-B078-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	6.3	11



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O PROPERTY ID 014	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B078-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	4.5	28
PRE-014-B078-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	4.2	13
PRE-014-B078-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	5.9	13
PRE-014-B078-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	1100	25
PRE-014-B078-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	350	3.9
PRE-014-B078-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	110	1.4
PRE-014-B078-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	100	1.1
PRE-014-B078-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	50	.96 J
PRE-014-B078-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	47	2.8
PRE-014-B078-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	130	4.1
PRE-014-B078-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	25	8.3
PRE-014-B078-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	13	5.9
PRE-014-B078-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	8.7	9.7
PRE-014-B078-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	3.1	4.2
PRE-014-B079-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	43	98
PRE-014-B079-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	5.8	16
PRE-014-B079-121918-2-1*	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	6.5	17
PRE-014-B079-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	7.9	19
PRE-014-B079-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	23	53
PRE-014-B079-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	13	45
PRE-014-B079-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	220	17
PRE-014-B079-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	8.7	5.2
PRE-014-B079-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	.94 J	0.34
PRE-014-B079-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.5
PRE-014-B079-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	8.6	3.2
PRE-014-B079-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	55	2.8
PRE-014-B079-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	39	3.9
PRE-014-B079-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	96	3.7
PRE-014-B079-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	4.6	7.5
PRE-014-B079-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	5	4.9
PRE-014-B079-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	5.1	7.8
PRE-014-B080-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	12	76
PRE-014-B080-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	4.4	8.3
PRE-014-B080-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	5.4	8.9
PRE-014-B080-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	4.4	59
PRE-014-B080-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	3.3	12
PRE-014-B080-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	140	47
PRE-014-B080-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	3.1	6.4
PRE-014-B080-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	1.5 J	1.4
PRE-014-B080-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	2	4.2



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O	U1-Phase II	ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION SA	AMPLE	PALs (mg/kg) ¹	0.6	0.5		2.24		40	100
SAMPLE ID	DATE	DEPTH	0.6 mg/kg	0.6 mg/kg	0.2 mg/kg	0.04 mg/kg	0.07 mg/kg	19 mg/kg	400 mg/kg
				21/2	21/2	21/2	21/4		0.4
PRE-014-B080-121918-10 PRE-014-B080-121918-10-	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	27	2.1
1*	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	7.2	0.95
PRE-014-B080-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	53	1.8
PRE-014-B080-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	2.7	7
PRE-014-B081-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	41	160
PRE-014-B081-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	7.2	61
PRE-014-B081-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	7.2	9.6
PRE-014-B081-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	7.9	29
PRE-014-B081-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	6.3	28
PRE-014-B081-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	13000	31000
PRE-014-B081-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	98	19
PRE-014-B081-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	22	3.2
PRE-014-B081-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	170	8.8
PRE-014-B081-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	180	3.8
PRE-014-B081-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	27	3.8
PRE-014-B081-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	2.1	5.1
PRE-014-B082-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	6.6	28
PRE-014-B082-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	3.7	19
PRE-014-B082-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	370	850
PRE-014-B082-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	8.2	61
PRE-014-B082-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	16	63
PRE-014-B082-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	440	150
PRE-014-B082-121918-6-1*	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	340	53
PRE-014-B082-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	83	10
PRE-014-B082-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	340	130
PRE-014-B082-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	24	4.2
PRE-014-B082-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	4.3	5.9
PRE-014-B082-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	1.8	1.6
PRE-014-B082-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	1.4	2.3
PRE-014-B083-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	62	170
PRE-014-B083-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	21	56
PRE-014-B083-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	28	170
PRE-014-B083-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	14	26
PRE-014-B083-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	1.6	16
PRE-014-B083-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	11	39
PRE-014-B083-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	2.5	16
PRE-014-B083-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	1.1 J	7.9
PRE-014-B083-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	1.5 J	11
PRE-014-B083-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	2.1 U	6.1
PRE-014-B083-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	1.3 J	4



REMEDIAL ACTION REPORT - SECTION 3

. ,	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S	AMPLE	DAI - / /\1					•		
RESULTS		PALs (mg/kg) ¹	0.6 mg/kg	0.6 mg/kg	0.2 mg/kg	0.04 mg/kg	0.07 mg/kg	19 mg/kg	400 mg/kg
SAMPLE ID	DATE	DEPTH	6/6	6/6	6/6	6/8	6/6	6/6	6/6
PRE-014-B083-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	2.8	4.8
PRE-014-B084-121918-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	19	93
PRE-014-B084-121918-2	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	8.3	79
PRE-014-B084-121918-2-1*	12/19/2018	24"	N/A	N/A	N/A	N/A	N/A	6	130
PRE-014-B084-121918-3	12/19/2018	36"	N/A	N/A	N/A	N/A	N/A	7.7	150
PRE-014-B084-121918-4	12/19/2018	48"	N/A	N/A	N/A	N/A	N/A	1.6	22
PRE-014-B084-121918-5	12/19/2018	60"	N/A	N/A	N/A	N/A	N/A	2	28
PRE-014-B084-121918-6	12/19/2018	72"	N/A	N/A	N/A	N/A	N/A	47	59
PRE-014-B084-121918-7	12/19/2018	84"	N/A	N/A	N/A	N/A	N/A	3	41
PRE-014-B084-121918-8	12/19/2018	96"	N/A	N/A	N/A	N/A	N/A	1.3 J	18
PRE-014-B084-121918-9	12/19/2018	108"	N/A	N/A	N/A	N/A	N/A	1.8 U	2
PRE-014-B084-121918-10	12/19/2018	120"	N/A	N/A	N/A	N/A	N/A	1 J	7
PRE-014-B084-121918-11	12/19/2018	132"	N/A	N/A	N/A	N/A	N/A	1.9 U	5.9
PRE-014-B084-121918-12	12/19/2018	144"	N/A	N/A	N/A	N/A	N/A	1.9 U	5.7
PRE-014-B085-010719-1	12/19/2018	12"	N/A	N/A	N/A	N/A	N/A	7.6	17
PRE-014-B085-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	7.7	88
PRE-014-B085-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	22	52
PRE-014-B085-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	18	40
PRE-014-B085-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	4100	2000
PRE-014-B085-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	2200	22
PRE-014-B085-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	470	5
PRE-014-B085-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	370	3.5
PRE-014-B085-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	180	32
PRE-014-B085-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	92	1.4
PRE-014-B085-010719-10- 1*	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	87	1.2
PRE-014-B085-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	140	7.4
PRE-014-B085-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	96	1.2
PRE-014-B085-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	250	2.5
PRE-014-B085-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	220	3.8
PRE-014-B085-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	220	4.7
PRE-014-B085-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	130	3.9
PRE-014-B086-010719-1	1/7/2019	12"	N/A	N/A	N/A	N/A	N/A	4.3	9.8
PRE-014-B086-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	6	170
PRE-014-B086-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	11	160
PRE-014-B086-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	15	130
PRE-014-B086-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	55	450
PRE-014-B086-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	37	42
PRE-014-B086-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.4
PRE-014-B086-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	2 U	2.9
PRE-014-B086-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	2	2



REMEDIAL ACTION REPORT - SECTION 3

• •	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S. RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B086-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	4.5	1.7
PRE-014-B086-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	21	1.6
PRE-014-B086-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	260	4.7
PRE-014-B086-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	260	5.2
PRE-014-B086-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	100	2.9
PRE-014-B086-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	260	4.1
PRE-014-B086-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	170	5.1
PRE-014-B087-010719-1	1/7/2019	12"	N/A	N/A	N/A	N/A	N/A	2.9	26
PRE-014-B087-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	6.2	9.6
PRE-014-B087-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	71	520
PRE-014-B087-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	130	2700
PRE-014-B087-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	27	130
PRE-014-B087-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	1.3 J	8.5
PRE-014-B087-010719-6-1*	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	9.6	54
PRE-014-B087-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	1.8 U	3.3
PRE-014-B087-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	1.8
PRE-014-B087-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	.7 J
PRE-014-B087-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	2 U	1.3
PRE-014-B087-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	84	2.3
PRE-014-B087-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	420	4.9
PRE-014-B087-020519-13	2/5/2019	156"	N/A	N/A	N/A	N/A	N/A	92	4.8
PRE-014-B087-020519-14	2/5/2019	168"	N/A	N/A	N/A	N/A	N/A	96	1.8
PRE-014-B087-020519-15	2/5/2019	180"	N/A	N/A	N/A	N/A	N/A	83	3.2
PRE-014-B087-020519-16	2/5/2019	192"	N/A	N/A	N/A	N/A	N/A	64	2.9
PRE-014-B088-010719-1	1/7/2019	12"	N/A	N/A	N/A	N/A	N/A	14	110
PRE-014-B088-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	36	1200
PRE-014-B088-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	99	180
PRE-014-B088-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	390	500
PRE-014-B088-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	10	62
PRE-014-B088-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	0.94 J	6.8
PRE-014-B088-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	1.3 J	6.1
PRE-014-B088-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	.84 J	5.5
PRE-014-B088-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.3
PRE-014-B088-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	2 U	3.2
PRE-014-B088-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	3.1	3.3
PRE-014-B088-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.1
PRE-014-B089-010719-1	1/7/2019	12"	N/A	N/A	N/A	N/A	N/A	7.5	100
PRE-014-B089-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	6.8	130
PRE-014-B089-010719-2-1*	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	9.8	190
PRE-014-B089-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	7.2	71



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
RESULTS SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B089-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	29	200
PRE-014-B089-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	17	47
PRE-014-B089-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	23	55
PRE-014-B089-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	3.9	6.7
PRE-014-B089-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	3.3
PRE-014-B089-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	1.8 U	2.5
PRE-014-B089-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	2 U	.8 J
PRE-014-B089-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	2.6	4.1
PRE-014-B089-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	4.6	4.4
PRE-014-B090-010719-1	1/7/2019	12"	N/A	N/A	N/A	N/A	N/A	15	76
PRE-014-B090-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	19	5000
PRE-014-B090-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	36	150
PRE-014-B090-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	48	520
PRE-014-B090-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	4.7	390
PRE-014-B090-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	6.1	42
PRE-014-B090-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	2 U	4.7
PRE-014-B090-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	3.3
PRE-014-B090-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	2 U	1.3
PRE-014-B090-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	2 U	.91 J
PRE-014-B090-010719-10-	1/7/2019	120"	N/A N/A	N/A	N/A	N/A	N/A	1.9 U	.91 J
1*			•	-	-				
PRE-014-B090-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	1.7	8.2
PRE-014-B090-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	2.2	5
PRE-014-B091-010719-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	5.1	30
PRE-014-B091-010719-2	1/7/2019	24"	N/A	N/A	N/A	N/A	N/A	6.9	18
PRE-014-B091-010719-3	1/7/2019	36"	N/A	N/A	N/A	N/A	N/A	2.6 U	2.3
PRE-014-B091-010719-4	1/7/2019	48"	N/A	N/A	N/A	N/A	N/A	46	990
PRE-014-B091-010719-5	1/7/2019	60"	N/A	N/A	N/A	N/A	N/A	98	92
PRE-014-B091-010719-6	1/7/2019	72"	N/A	N/A	N/A	N/A	N/A	7.9	3.3
PRE-014-B091-010719-7	1/7/2019	84"	N/A	N/A	N/A	N/A	N/A	1.2 J	5.1
PRE-014-B091-010719-8	1/7/2019	96"	N/A	N/A	N/A	N/A	N/A	0.96 J	4.7
PRE-014-B091-010719-9	1/7/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	0.97
PRE-014-B091-010719-10	1/7/2019	120"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.1
PRE-014-B091-010719-11	1/7/2019	132"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.1
PRE-014-B091-010719-12	1/7/2019	144"	N/A	N/A	N/A	N/A	N/A	1.7 J	2.6
PRE-014-B121-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	14	94
PRE-014-B121-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	21	260
PRE-014-B121-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	45	190
PRE-014-B121-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	7.2	42
PRE-014-B121-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	3.8	140
PRE-014-B121-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	5.1	56



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O PROPERTY ID 014	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B121-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.6
PRE-014-B121-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	2.1	3.7
PRE-014-B121-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	2.7	8.2
PRE-014-B121-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	1.2 J	2.1
PRE-014-B121-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	2	1.6
PRE-014-B121-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	2.3	2.6
PRE-014-B122-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	12	63
PRE-014-B122-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	7.7	51
PRE-014-B122-061019-2-1*	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	11	43
PRE-014-B122-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	3.8	62
PRE-014-B122-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	6.1	38
PRE-014-B122-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	9	61
PRE-014-B122-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	20	7.6
PRE-014-B122-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	2.1	3.6
PRE-014-B122-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	1 J	3.1
PRE-014-B122-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	1.8 J	5.8
PRE-014-B122-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	.95 J	2.8
PRE-014-B122-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	1.4	2.3
PRE-014-B122-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	1.8 J	2.8
PRE-014-B123-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	4.8	3.7
PRE-014-B123-061019-1-1*	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	6.9	16
PRE-014-B123-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	45	39
PRE-014-B123-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	14	230
PRE-014-B123-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	8.1	500
PRE-014-B123-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	35	56
PRE-014-B123-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	1.2 J	12
PRE-014-B123-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	1.8 U	3.2
PRE-014-B123-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	2.2
PRE-014-B123-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.7
PRE-014-B123-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.3
PRE-014-B123-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	30	.95 J
PRE-014-B123-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	97	3.1
PRE-014-B124-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	8.6	120
PRE-014-B124-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	12	120
PRE-014-B124-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	14	110
PRE-014-B124-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	13	120
PRE-014-B124-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	11	120
PRE-014-B124-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	1.8 U	6.3
PRE-014-B124-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	1.4 J	5.6
PRE-014-B124-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	2



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		ANALYTE	Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B124-061019-8-1*	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	.77 J	1.7
PRE-014-B124-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	12	17
PRE-014-B124-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	.89 J	2.8
PRE-014-B124-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	5.5	2.8
PRE-014-B124-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	1.9 J	4.8
PRE-014-B125-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	6.6	87
PRE-014-B125-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	7.2	48
PRE-014-B125-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	48	1600
PRE-014-B125-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	40	2800
PRE-014-B125-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	100	500
PRE-014-B125-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	7.1	64
PRE-014-B125-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	.79 J	5.1
PRE-014-B125-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	2.7
PRE-014-B125-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.9
PRE-014-B125-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	.78 J	2.9
PRE-014-B125-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	1.7 J	4
PRE-014-B125-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	.76 J	3.7
PRE-014-B126-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	11	120
PRE-014-B126-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	6	66
PRE-014-B126-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	11	110
PRE-014-B126-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	8.6	47
PRE-014-B126-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	6.2	41
PRE-014-B126-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	2.2	37
PRE-014-B126-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	0.91	3.5
PRE-014-B126-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	0.73 J	3.1
PRE-014-B126-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	2 U	1.3
PRE-014-B126-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	2 U	1.2
PRE-014-B126-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	1.8 J	2.5
PRE-014-B126-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	1.6 J	4.4
PRE-014-B127-061019-1	6/10/2019	12"	N/A	N/A	N/A	N/A	N/A	51	490
PRE-014-B127-061019-2	6/10/2019	24"	N/A	N/A	N/A	N/A	N/A	20	200
PRE-014-B127-061019-3	6/10/2019	36"	N/A	N/A	N/A	N/A	N/A	28	130
PRE-014-B127-061019-4	6/10/2019	48"	N/A	N/A	N/A	N/A	N/A	46	230
PRE-014-B127-061019-5	6/10/2019	60"	N/A	N/A	N/A	N/A	N/A	32	12000
PRE-014-B127-061019-6	6/10/2019	72"	N/A	N/A	N/A	N/A	N/A	1.8 U	83
PRE-014-B127-061019-7	6/10/2019	84"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.6
PRE-014-B127-061019-8	6/10/2019	96"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.5
PRE-014-B127-061019-9	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	2 U	25
PRE-014-B127-061019-9-1*	6/10/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.3
PRE-014-B127-061019-10	6/10/2019	120"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.3



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O PROPERTY ID 014	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B127-061019-11	6/10/2019	132"	N/A	N/A	N/A	N/A	N/A	1.3 J	2.7
PRE-014-B127-061019-12	6/10/2019	144"	N/A	N/A	N/A	N/A	N/A	2.5	4.5
PRE-014-B128-061119-1	6/11/2019	12"	N/A	N/A	N/A	N/A	N/A	44	140
PRE-014-B128-061119-2	6/11/2019	24"	N/A	N/A	N/A	N/A	N/A	49	47
PRE-014-B128-061119-3	6/11/2019	36"	N/A	N/A	N/A	N/A	N/A	29	730
PRE-014-B128-061119-4	6/11/2019	48"	N/A	N/A	N/A	N/A	N/A	5.4	81
PRE-014-B128-061119-5	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	7.3	140
PRE-014-B128-061119-6	6/11/2019	72"	N/A	N/A	N/A	N/A	N/A	.9 J	5.1
PRE-014-B128-061119-7	6/11/2019	84"	N/A	N/A	N/A	N/A	N/A	1.8 U	2.7
PRE-014-B128-061119-8	6/11/2019	96"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.8
PRE-014-B128-061119-9	6/11/2019	108"	N/A	N/A	N/A	N/A	N/A	1.9 U	1.8
PRE-014-B128-061119-10	6/11/2019	120"	N/A	N/A	N/A	N/A	N/A	1.8 U	3.9
PRE-014-B128-061119-11	6/11/2019	132"	N/A	N/A	N/A	N/A	N/A	2 U	0.61
PRE-014-B128-061119-12	6/11/2019	144"	N/A	N/A	N/A	N/A	N/A	1.4 J	3.5
PRE-014-B129-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	20	80
PRE-014-B129-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	72	26
PRE-014-B129-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	3.4	4
PRE-014-B129-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	5.9	3.1
PRE-014-B129-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	2.7	1.7
PRE-014-B129-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	4.5	1.5
PRE-014-B129-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	9.2	1
PRE-014-B130-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	3.8	32
PRE-014-B130-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	9500	4300
PRE-014-B130-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	230	37
PRE-014-B130-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	150	4
PRE-014-B130-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	52	4.1
PRE-014-B130-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	5.8	3
PRE-014-B130-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	1.4 J	2.9
PRE-014-B131-061119-1	6/11/2019	12"	N/A	N/A	N/A	N/A	N/A	20	190
PRE-014-B131-061119-2	6/11/2019	24"	N/A	N/A	N/A	N/A	N/A	24	120
PRE-014-B131-061119-3	6/11/2019	36"	N/A	N/A	N/A	N/A	N/A	7.3	43
PRE-014-B131-061119-4	6/11/2019	48"	N/A	N/A	N/A	N/A	N/A	9.2	94
PRE-014-B131-061119-5	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	400	54
PRE-014-B131-061119-5-1*	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	410	81
PRE-014-B131-061119-6	6/11/2019	72"	N/A	N/A	N/A	N/A	N/A	210	7.6
PRE-014-B131-061119-7	6/11/2019	84"	N/A	N/A	N/A	N/A	N/A	300	11
PRE-014-B131-061119-8	6/11/2019	96"	N/A	N/A	N/A	N/A	N/A	110	6.3
PRE-014-B131-061119-9	6/11/2019	108"	N/A	N/A	N/A	N/A	N/A	56	3.6
PRE-014-B132-061119-1	6/11/2019	12"	N/A	N/A	N/A	N/A	N/A	250	260
PRE-014-B132-061119-2	6/11/2019	24"	N/A	N/A	N/A	N/A	N/A	380	52



REMEDIAL ACTION REPORT - SECTION 3

Table 3.1.2 - Kil-Tone Superfund Site-O PROPERTY ID 014	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B132-061119-3	6/11/2019	36"	N/A	N/A	N/A	N/A	N/A	170	6.1
PRE-014-B132-061119-4	6/11/2019	48"	N/A	N/A	N/A	N/A	N/A	66	2.1
PRE-014-B132-061119-5	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	72	2.1
PRE-014-B132-061119-6	6/11/2019	72"	N/A	N/A	N/A	N/A	N/A	17	0.9
PRE-014-B132-061119-7	6/11/2019	84"	N/A	N/A	N/A	N/A	N/A	90	1.1
PRE-014-B132-061119-8	6/11/2019	96"	N/A	N/A	N/A	N/A	N/A	130	1.6
PRE-014-B133-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	26	640
PRE-014-B133-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	380	76
PRE-014-B133-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	49	9.9
PRE-014-B133-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	1.9 U	2.6
PRE-014-B133-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	2 U	1.9
PRE-014-B133-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	2 U	3.9
PRE-014-B133-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.1
PRE-014-B133-061219-7-1*	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	13	2.9
PRE-014-B134-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	9.2	120
PRE-014-B134-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	7.4	79
PRE-014-B134-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	4.9	28
PRE-014-B134-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	4.8	37
PRE-014-B134-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	3.5	120
PRE-014-B134-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	13	36
PRE-014-B134-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	170	9.8
PRE-014-B134-061219-8	6/12/2019	96"	N/A	N/A	N/A	N/A	N/A	1.4 J	2.4
PRE-014-B134-061219-9	6/12/2019	108"	N/A	N/A	N/A	N/A	N/A	7.5	13
PRE-014-B135-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	3.3	25
PRE-014-B135-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	180	340
PRE-014-B135-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	130	8.1
PRE-014-B135-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	.86 J	3.3
PRE-014-B135-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	47	8.5
PRE-014-B135-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	140	3.1
PRE-014-B135-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	45	3.2
PRE-014-B135-061219-8	6/12/2019	96"	N/A	N/A	N/A	N/A	N/A	43	3.1
PRE-014-B136-061219-1	6/12/2019	12"	N/A	N/A	N/A	N/A	N/A	3.1	23
PRE-014-B136-061219-2	6/12/2019	24"	N/A	N/A	N/A	N/A	N/A	23	44
PRE-014-B136-061219-3	6/12/2019	36"	N/A	N/A	N/A	N/A	N/A	2 U	6.3
PRE-014-B136-061219-4	6/12/2019	48"	N/A	N/A	N/A	N/A	N/A	2.1 U	6.4
PRE-014-B136-061219-5	6/12/2019	60"	N/A	N/A	N/A	N/A	N/A	.9 J	5.1
PRE-014-B136-061219-6	6/12/2019	72"	N/A	N/A	N/A	N/A	N/A	.96 J	5.2
PRE-014-B136-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	1.5 J	4.9
PRE-014-B136-061219-7	6/12/2019	84"	N/A	N/A	N/A	N/A	N/A	1 J	4.2
PRE-014-B136-061219-8	6/12/2019	96"	N/A	N/A	N/A	N/A	N/A	2.1 U	3.6



REMEDIAL ACTION REPORT - SECTION 3

. ,	Table 3.1.2 - Kil-Tone Superfund Site-OU1-Phase II PROPERTY ID 014		Benzo(a) anthracene	Benzo(b) fluoranthene	Benzo(a) pyrene	Dieldrin	Heptachlor epoxide	Arsenic	Lead
PRE-EXCAVATION INVESTIGATION S RESULTS	AMPLE	PALs (mg/kg) ¹	0.6	0.6	0.2	0.04	0.07	19	400
SAMPLE ID	DATE	DEPTH	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
PRE-014-B137-061119-1	6/11/2019	12"	N/A	N/A	N/A	N/A	N/A	20	120
PRE-014-B137-061119-2	6/11/2019	24"	N/A	N/A	N/A	N/A	N/A	23	140
PRE-014-B137-061119-3	6/11/2019	36"	N/A	N/A	N/A	N/A	N/A	2.9	34
PRE-014-B137-061119-4	6/11/2019	48"	N/A	N/A	N/A	N/A	N/A	1.8 J	12
PRE-014-B137-061119-5	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	10	59
PRE-014-B137-061119-6	6/11/2019	72"	N/A	N/A	N/A	N/A	N/A	38	0.86
PRE-014-B137-061119-7	6/11/2019	84"	N/A	N/A	N/A	N/A	N/A	3.3	19
PRE-014-B137-061119-8	6/11/2019	96"	N/A	N/A	N/A	N/A	N/A	1.8 U	1.5
PRE-014-B137-061119-9	6/11/2019	108"	N/A	N/A	N/A	N/A	N/A	.86 J	4.2
PRE-014-B137-061119-10	6/11/2019	120"	N/A	N/A	N/A	N/A	N/A	1.9 U	3.3
PRE-014-B138-061119-1	6/11/2019	12"	N/A	N/A	N/A	N/A	N/A	26	130
PRE-014-B138-061119-2	6/11/2019	24"	N/A	N/A	N/A	N/A	N/A	23	130
PRE-014-B138-061119-3	6/11/2019	36"	N/A	N/A	N/A	N/A	N/A	20	150
PRE-014-B138-061119-4	6/11/2019	48"	N/A	N/A	N/A	N/A	N/A	2.8	29
PRE-014-B138-061119-5	6/11/2019	60"	N/A	N/A	N/A	N/A	N/A	15	240
PRE-014-B138-061119-6	6/11/2019	72"	N/A	N/A	N/A	N/A	N/A	3.5	13
PRE-014-B138-061119-7	6/11/2019	84"	N/A	N/A	N/A	N/A	N/A	1.8 U	4.6
PRE-014-B138-061119-8	6/11/2019	96"	N/A	N/A	N/A	N/A	N/A	1.9 U	2
PRE-014-B138-061119-9	6/11/2019	108"	N/A	N/A	N/A	N/A	N/A	.9 J	3.5
PRE-014-B138-061119-10	6/11/2019	120"	N/A	N/A	N/A	N/A	N/A	4.5	6
PRE-014-B138-061119-11	6/11/2019	132"	N/A	N/A	N/A	N/A	N/A	1.1 J	5.3
PRE-014-B138-061119-12	6/11/2019	144"	N/A	N/A	N/A	N/A	N/A	6.5	5.9
PRE-014-B138-061119-12- 1* NOTES:	6/11/2019	144"	N/A	N/A	N/A	N/A	N/A	11	3.9

¹ NJAC 7:26D Soil Remediation Criteria for Residential Direct Contact

All sample results reported in mg/kg

mg/kg = milligram(s) per kilogram U - Result not detected

J - Parameter not detected; quantitation is an estimation

N/A - Non-applicable

Bold Italicized results indicate an exceedance to Project Action Limits (PALs)

*Indicates duplicate sample



3-30 October 2020

4. CONTACT INFORMATION

Table 4.1 summarizes the key project personnel contacts.

Table 4.1 Key Project Contacts

Name	Title	Organization	Address
Caroline Kwan	Project Manager	EPA	290 Broadway, 18 th Floor
			New York, NY 10007-1866
Dan Patel	Project Manager	EPA	290 Broadway, 18 th Floor
			New York, NY 10007-1866
Steve Creighton	CO	USACE	1405 N Mill Road Vineland,
	Representative		NJ 08360
Ian Stewart	Project Engineer	USACE	1405 N Mill Road Vineland,
			NJ 08360
Terry Mower	Construction	USACE	1405 N Mill Road Vineland,
	Representative		NJ 08360
Jesse Albert	Project Manager	SES	2749 Lockport Road Niagara
			Fall, NY 14305
Perry Novak	Site	SES	2749 Lockport Road Niagara
	Superintendent		Fall, NY 14305
Eric Delellis	Site CQCSM	SES	2749 Lockport Road Niagara
			Fall, NY 14305
Mira Juengling	Site SSHO	SES	2749 Lockport Road Niagara
			Fall, NY 14305



October 2020 4-31

5. REFERENCES

USEPA September 2016, Record of Decision for OU1

Sevenson Environmental Services, Inc. Site Specific Work Plans:

- Site Safety and Health Plan (including Activity Hazard Analysis Plan)
- Accident Prevention Plan
- Environmental Protection Plan
- Perimeter Air Monitoring Plan
- Sampling and Analysis Plan
- Contractor Quality Control Plan
- Temporary Site Facility Layout Plan
- Security Plan
- Excavation and Handling Plan
- Traffic Control and Transportation Plan
- Waste Management Plan
- Soil Erosion and Sediment Control Plan
- Dewatering Work Plan
- Dust Control Plan
- Spill Prevention and Control Plan
- Excavation and Support Plan
- Quality Assurance Plan (QAPP)



Appendix A Signed Access Form

CONSENT FOR ACCESS Former Kil-Tone Company Superfund Site


Property Owner(s)	Frodicio	+ Mildred Pames
Address of Property:	527 E Cherr	45+ Vineland NJ
remedial action for the F	operty listed above. I ormer Kil-Tone Com ized by the Superfund	pany Superfund Site under its response and enforcement diaw, also known as the Comprehensive Environmental
Lalso understand that EP the Former Kil-Tone Cor		y property to conduct response activities in connection with e.
access to my property in	order to perform rem f soil samples; 2) the	and authorized representatives of EPA to enter and have redial activities including, but not limited to, the following excavation of contaminated soil; 3) off-site disposal of d areas with clean fill.
federal and state agencie	s, and their agents. I	clude contractors and/or subcontractors hired by EPA, other also understand and agree that the above-mentioned it reasonable times as mutually scheduled.
		may require some disturbance to the property and EPA will. Areas of disturbance will be restored to prior conditions
I understand that EPA re comprehensive general li		to maintain comprehensive vehicle liability insurance and
		tarily and without threats or promises of any kind. By my authorized to grant such access.
By: Milchallar Name	na	11 (1 (18) Date
Main Contact Telephone	Number	856-332-5398 Best time to call:
Tenant Name (if applical	ble)	Tenant Contact Telephone Number (if applicable)

APPENDIX

Appendix B <u>Design Drawings</u>


KIL-TONE OU-1 SUPERFUND SITE PHASE 2 VINELAND, NEW JERSEY

PROPERTY ID NOS. 001, 003, 004, 006, 007, 008, 009, 010, 011, 012, 013, 014, 015, 016, 023, 025, 026, 027, 028, 029, 032, 034, 035, 072, 073, 074, 084









SITE LOCATION MAP

APPROXIMATE SCALE IN FEET

1000 2000 300

February 2018

VICINITY MAP

	DESIGN PHASE 2
SIGNATURES AFFIXED BELOW INDICATE OFFICIAL RECOMMENDATION AND APPROVAL OF DRAWINGS IN THIS SET AS INDEXED ON THIS PLATE	, 13.
APPROVAL RECOMMENDED: 3-2-2018	OU-1 REMEDIAL
CHIEF, ENVIRONMENTAL ENGINEERING BRANCH DATE	Ш
APPROVED: 3/7/18	L
CHIEF, ENGINEERING DIVISION, P.E. DATE	
THIS PROJECT WAS DESIGNED BY THE KANSAS CITY DISTRICT OF THE U.S. ARMY JORPS OF ENGINEERS. THE INITIALS OR SIGNATURES AND REGISTRATION DESIGNATIONS OF INDIVIDUALS THAT APPEAR ON THESE PROJECT DOCUMENTS ARE WITHIN THE SCOPE OF THEIR EMPLOYMENT AS REQUIRED BY ER 1110-1-8152.	L

GENERAL NOTES

- CONTRACTOR SHALL PROTECT EXISTING FEATURES NOT DESIGNATED TO BE REMOVED AND RESTORE FROM DAMAGE. AT THE DIRECTION OF THE COR. CONTRACTOR SHALL REPLACE OR REPAIR ANY DAMAGED FEATURE.
- THE CONTRACTOR SHALL INVENTORY AND CLEAR EACH OWNER'S PROPERTY FROM WITHIN THE WORK AREA AND SAFELY STORE ON-SITE. FOLLOWING THE COMPLETION OF THE WORK, THE CONTRACTOR SHALL RETURN ITEMS TO THEIR ORIGINAL LOCATIONS. CONTRACTOR SHALL REPAIR OR REPLACE ANY ITEMS DAMAGED DURING STORAGE OR RELOCATION OF EACH OWNER'S PROPERTY. THE CONTRACTOR SHALL COORDINATE TEMPORARY OFF-SITE STORAGE OF OWNER'S PROPERTY WITH COR, IF NECESSARY.
- 3 CONTRACTOR SHALL REMOVE PORTIONS OF THE EXISTING FENCE TO ACCOMMODATE THE EXCAVATION ACTIVITIES CONTRACTOR SHALL REMOVE FENCE, POSTS, GATES, AND APPURTENANCES. CLEAN AND STOCKPILE MATERIALS FOR REUSE OR REPLACE WITH EQUIVALENT IN ACCORDANCE WITH LOCAL CODES AS PART OF THE SITE RESTORATION. CONTRACTOR SHALL INSTALL TEMPORARY FENCING UNTIL PERMANENT FENCING IS REINSTALLED.
- CONTRACTOR SHALL PERFORM SOIL EROSION AND SEDIMENT CONTROL IN ACCORDANCE WITH SECTION 01356A.
- 5. PROPERTY BOUNDARIES ON THESE MAPS ARE CONSIDERED APPROXIMATE.
- 6. THE HORIZONTAL DATUM COORDINATE SYSTEM IS THE NEW JERSEY STATE PLANE COORDINATE SYSTEM, NORTH AMERICAN DATUM OF 1983, CT
- 7. BASE MAPPING AND BORING LOCATIONS WERE PROVIDED BY TETRATECH. PROPERTY BOUNDARIES WERE SURVEYED IN 2017.

EXCAVATION NOTES

- CONTRACTOR SHALL ESTABLISH ON-SITE SURVEY CONTROL TO ACCURATELY RESTORE THE SITE TO THE ORIGINAL GRADES, ELEVATIONS, AND
 CONDITIONS. AT THE CONCLUSION OF THE WORK, CONTRACTOR SHALL DEVELOP A DETAILED FINAL AS-BUILT DRAWING. THIS DRAWING WILL BE USED IN CONJUNCTION WITH THE EXISTING SITE SURVEY TO DETERMINE WORK QUANTITIES.
- CONTRACTOR SHALL PROVIDE TEMPORARY ACCESS TO AND FROM THE SITE TO EFFECTIVELY PERFORM THE WORK, CONTRACTOR SHALL PROTECT CURBS ADJACENT TO PROJECT SITE. CONTRACTOR SHALL CLEAN ACCESS WAYS AS NEEDED DURING AND AT THE CONCLUSION OF THE WORK. UNLESS OTHERWISE NOTED, ANY CURB OR CONCRETE DAMAGED SHALL BE REPLACED BY THE CONTRACTOR AT THE DIRECTION OF THE COR. CONTRACTOR SHALL COORDINATE ACCESS WITH THE PROPERTY OWNERS PRIOR TO MOBILIZATION
- EXCAVATIONS ADJACENT TO ALL BUILDING FOUNDATION AND CRAWL SPACES SHALL BE PERFORMED IN ACCORDANCE WITH THE TYPICAL EXCAVATION SECTION FOOTING DETAIL SHOWN ON DRAWING TD-1. IF THE EXCAVATION EXTENDS BELOW THE FOOTING OR INTO THE CRAWL SPACE. THE CONTRACTOR SHALL NOTIFY THE COR AND THE EXCAVATION SHALL PROGRESS AS DIRECTED BY THE COR.
- CONTRACTOR SHALL COLLECT, TREAT AND DISPOSE OF GROUNDWATER AND SURFACE WATER THAT ACCUMULATES IN EXCAVATION AREAS IN ACCORDANCE WITH SECTION 02310. GROUNDWATER IS ANTICIPATED TO BE BELOW THE EXCAVATION LIMITS. NO DEWATERING IS ANTICIPATED DURING
- 5. CONTRACTOR SHALL PROVIDE ALL SHORING, SHEETING, AND BRACING NECESSARY TO CONDUCT THE WORK SAFELY AND PREVENT DAMAGE TO ADJACENT UTILITIES AND STRUCTURES
- INSPECT BASEMENT WALLS AND REPORT STRUCTURAL DEFECTS OR CRACKS. PROVIDE INFORMATION TO DOCUMENT AND MONITOR MOVEMENT OF STRUCTURAL CRACKS EXCEEDING 1/8" DURING DEMOLITION AND CONSTRUCTION
- COORDINATES FOR THE LAYOUT OF THE EXCAVATION AREAS CAN BE OBTAINED FROM THE BASE MAP FILES AND WILL BE PROVIDED TO THE SELECTED

RESTORATION NOTES

- CONTRACTOR SHALL RESTORE ALL DISTURBED AND EXCAVATED AREAS TO PRE-CONSTRUCTION GRADES AND ELEVATIONS UNLESS OTHERWISE NOTED OR SPECIFIED
- CONTRACTOR SHALL REINSTALL, OR REPLACE WITH EQUIVALENT, CHAIN LINK OR WOOD PANEL FENCE TO THEIR ORIGINAL LOCATIONS AND IN ACCORDANCE WITH LOCAL CODES. POSTS SHALL BE RESET AT ORIGINAL LOCATIONS IN CONCRETE FOR POST SUPPORT. ANY DAMAGED MATERIALS SHALL BE REPLACED AS DIRECTED BY THE COR.
- 3. CONTRACTOR SHALL REINSTALL, OR REPLACE ALL FEATURES TEMPORARILY REMOVED FROM THE LIMITS OF CONSTRUCTION.
- 4. CONTRACTOR SHALL RESTORE ADJACENT PROPERTIES DISTURBED DURING THE WORK TO PRE-CONSTRUCTION CONDITIONS.
- 5. CONTRACTOR SHALL REMOVE EROSION CONTROL MEASURES AND CLEAN SITE FOLLOWING RESTORATION.
- 6. CONTRACTOR SHALL REPLACE TREES REMOVED DURING REMEDIATION ACTIVITIES.
- PROTECT ALL TREES. TREES SHALL ONLY BE REMOVED AT THE DIRECTION OF THE COR. PROVIDE A SUBMITTAL FROM A NEW JERSEY CERTIFIED TREE EXPERT, THE SUBMITTAL SHALL REPORT THE CONDITION OF ALL TREES ON THE PROPERTY, REPORT SHALL ADDRESS LIKELIHOOD OF TREE SURVIVAL/ OUTCOME BASED ON CURRENT CONDITION AND THE IMPACT OF EXPECTED EXCAVATION DEPTH SURROUNDING THE TREE. ADDRESS THE STABILITY OF THE TREE BASED ON WIND LOAD AND EXCAVATION DEPTH. PROVIDE RECOMMENDATION FOR REMOVAL AND REPLANTING NEW TREE BASED ON PROXIMITY TO STRUCTURES SCHEDULED FOR DEMOLITION AND RECONSTRUCTION.
- DEMOLISH AND REPLACE OR MOVE AND REINSTALL FEATURES OUTSIDE THE FOOTPRINT OF THE HOUSE (GARAGES, SHEDS, PLAY SETS, ETC.) IN ACCORDANCE WITH THE APPROVED DEMOLITION PLAN AND AT THE DIRECTION OF THE COR
- EXCAVATION NEAR UTILITY POLES SHALL BE COORDINATED WITH UTILITY FOR BRACING REQUIREMENTS AND ANY OTHER REQUIREMENTS.
- 10. RESTORE IN KIND IN ACCORDANCE WITH THE APPROVED RESTORATION PLAN AT THE DIRECTION OF THE COR. SEE PROPERTY INVENTORY REPORTS ATTACHED TO DRAWINGS FOR INVENTORY OF ITEMS AT EACH PROPERTY

LEGEND (10 SCALE)

SOIL SAMPLE LOCATION (AS, PB) CONCENTRATIONS (ppm) @ DEPTH (19, 400) @ 0-6" 158.82 CHOILFHD

CONCRETE MONUMENT FOUND ⊙158.06 CAPPED REBAR FND. CAPPED REBAR FOUND ⊙158.39 REBAR FND. REBAR FOUND **≜**158.46 0.H.FND DRILL HOLE FOUND O158.57 IRON PIPE FOUND O158.7 FEN.PST.PROPCOR OLD FENCE POST ≜173.34 X-CUT FND. 30080 X-MARK FOUND **▲173.49** MAG NAIL FND. 30050 MAG NAIL FOUND ₾ 173.52 MAG NAIL SET 30051

MAG NAIL SET -∰tαwo ιτ GROUND LIGHT LIGHT POLE

C8 20 x36 GATE=158.82 CATCH BASIN 20"x36" (CURB) ● 153,72 FLOORDRAN FLOOR DRAIN

0175.69 GAS VALVE SANITARY CLEANOUT SAN MH RM-159.90' SANITARY MANHOLE **⊗**POST POST (WOOD/METAL) □ ROOF DRAIN NJ/SPOUT ROOF DRAIN WITH DOWN SPOUT

(T) RM=158.05" TELEPHONE MANHOLE -Ò-TRAF.SIGNAL POLE

TRAFFIC SIGNAL SUPPORT POLE POWER POLE UTILITY POLE WITH LIGHT **GUY ANCHOR ₫** 158.82 FIRE HYDRAN

WATER METER WATER VALVE SHRUB WITH SIZE



PINE TREE WITH SIZE

TREE STUMP



DECIDLIOUS TREE WITH SIZE

HEDGE LINE

CONCRETE WALK/PAD/PAVEMENT SANITARY SEWER LINE GAS LINE

WATER LINE ______

OVERHEAD ELECTRIC UNDERGROUND ELECTRIC OVERHEAD COMMUNICATION UNKNOWNLINE FENCE

U.S. Army Corp of Engineers KANSAS CITY DISTRIC

SHEET ID

G-02

DRAWING INDEX			
SHEET NAME	DRAWING TITLE		
G-01	COVER SHEET		
G-02	DRAWING INDEX AND NOTES		
G-03	SITE PLAN		
G-04	SITE PLAN - NORTH		
G-05	SITE PLAN - SOUTH		
G-06A	PROPERTY 001 EXISTING CONDITIONS / BORING PLAN		
G-06B	PROPERTY 001 EXCAVATION PLAN		
G-07A	PROPERTY 003 EXISTING CONDITIONS / BORING PLAN		
G-07B	PROPERTY 003 EXCAVATION PLAN		
G-08A	PROPERTY 004 EXISTING CONDITIONS / BORING PLAN		
G-08B	PROPERTY 004 EXCAVATION PLAN		
G-09A	PROPERTY 006 EXISTING CONDITIONS / BORING PLAN		
G-09B	PROPERTY 006 EXCAVATION PLAN		
G-10A	PROPERTY 007 EXISTING CONDITIONS / BORING PLAN		
G-10B	PROPERTY 007 EXCAVATION PLAN		
G-11A	PROPERTY 008 EXISTING CONDITIONS / BORING PLAN		
G-11B	PROPERTY 008 EXCAVATION PLAN		
G-12A	PROPERTY 009 EXISTING CONDITIONS / BORING PLAN		
G-12B	PROPERTY 009 EXCAVATION PLAN		
G-13A	PROPERTY 010 EXISTING CONDITIONS / BORING PLAN		
G-13B	PROPERTY 010 EXCAVATION PLAN		
G-14A	PROPERTY 011 EXISTING CONDITIONS / BORING PLAN		
G-14B	PROPERTY 011 EXCAVATION PLAN		
G-15A	PROPERTY 012 EXISTING CONDITIONS / BORING PLAN		
G-15B	PROPERTY 012 EXCAVATION PLAN		
G-16A	PROPERTY 013 EXISTING CONDITIONS / BORING PLAN		
G-16B	PROPERTY 013 EXCAVATION PLAN		
G-17A	PROPERTY 014 EXISTING CONDITIONS / BORING PLAN		
G-17B	PROPERTY 014 PLAN FOR SUPPLEMENTAL SAMPLING		
G-17C	PROPERTY 014 EXCAVATION PLAN		
G-18A	PROPERTY 015 EXISTING CONDITIONS / BORING PLAN		
G-18B	PROPERTY 015 EXCAVATION PLAN		
G-19A	PROPERTY 016 EXISTING CONDITIONS / BORING PLAN		
G-19B	PROPERTY 016 EXCAVATION PLAN		
G-20A	PROPERTY 023 EXISTING CONDITIONS / BORING PLAN		
G-20B	PROPERTY 023 EXCAVATION PLAN		
G-21A	PROPERTY 025 EXISTING CONDITIONS / BORING PLAN		
G-21B	PROPERTY 025 EXCAVATION PLAN		
G-22A	PROPERTY 026 EXISTING CONDITIONS / BORING PLAN		
G-22B	PROPERTY 026 EXCAVATION PLAN		
G-23A	PROPERTY 027 EXISTING CONDITIONS / BORING PLAN		
C 22D	DDODEDTY 007 EVO AVATION DI ANI		

PROPERTY 027 EXCAVATION PLAN

PROPERTY 028 EXCAVATION PLAN

PROPERTY 029 EXCAVATION PLAN

PROPERTY 032 EXCAVATION PLAN

PROPERTY 034 EXCAVATION PLAN

PROPERTY 035 EXCAVATION PLAN

PROPERTY 073 EXCAVATION PLAN

PROPERTY 074 EXCAVATION PLAN

PROPERTY 084 EXCAVATION PLAN

TYPICAL DETAILS

TYPICAL DETAILS

PROPERTY 028 EXISTING CONDITIONS / BORING PLAN

PROPERTY 029 EXISTING CONDITIONS / BORING PLAN

PROPERTY 032 EXISTING CONDITIONS / BORING PLAN

PROPERTY 034 EXISTING CONDITIONS / BORING PLAN

PROPERTY 035 EXISTING CONDITIONS / BORING PLAN

PROPERTY 035 PLAN FOR SUPPLEMENTAL SAMPLING

PROPERTY 072 EXISTING CONDITIONS / BORING PLAN

PROPERTY 073 EXISTING CONDITIONS / BORING PLAN

PROPERTY 074 EXISTING CONDITIONS / BORING PLAN

PROPERTY 084 EXISTING CONDITIONS / BORING PLAN

72 EXCAVATION PLAN

G-24A

G-24B

G-28A

G-28C

G-29A

G-30A


G-31A


G-31B


G-32A


G-32B

G-35









EXISTING GROUND SURFACE (ELEVATION VARIES) INTERIOR EXTERIOR TYPICAL BLOCK WALL - 1" NJDOT I-5 TOP COURSE MATERIAL TO BE EXCAVATED - 3" NJDOT I-2 BASE COURSE TYPICAL FOOTING -- 4" DGA STONE EXCAVATION LIMITS -EXCAVATE AT 45" -EXISTING SUBGRADE TYPICAL EXCAVATION SECTION AT TYPICAL DRIVEWAY RESTORATION DETAIL FOOTING DETAIL NOT TO SCALE NOT TO SCALE NOTES: 1. DETAIL ASSUMES STANDARD FOOTING, CONSTRUCTION LAYOUT WILL VARY IN FIELD 2. CONTRACTOR SHALL NOT EXCAVATE BELOW THE LIMITS SHOWN WITHOUT PRIOR APPROVAL FROM THE CONTRACTING OFFICER.

OU-1 REMEDIAL DESIGN PHASE KIL-TONE SUPERFUND SITE VINELAND, NJ

SHEET ID

G-33

