

**A Site Inspection
of
Chem Solv Inc.
EPA No. DE-63
Emergency and Remedial Response Information System
Grant No. X-003282-01-0**

**Presented to: Mr. E. Skernolis, Acting Chief, Site
Investigation & Support Section,
U. S. EPA, Region III**

**Prepared by: Delaware Department of Natural Resources
and Environmental Control, Solid Waste Branch**

Andrew Bullen, ERRIS Investigator

Robert Pickert, ERRIS Coordinator

AR100491

A-1

If the page filmed in this frame is not as readable or legible as this label, it is due to substandard color or condition of the original page.

SITE INSPECTION REPORT CONTENTS

- ORIGINAL
7/20/80
- I. Introduction
 - Summary
 - Conclusions and Recommendations
 - II. Background
 - Permits & Regulatory History
 - Site Use and Ownership History
 - Site Location and Layout
 - Summary Trip Report
 - Remedial Action
 - III. Environmental Setting
 - Topography
 - Surface Waters
 - Groundwater
 - Geology and Soils
 - Land Use
 - Population Distribution
 - Water Supply
 - Critical Environments
 - Climate and Meteorology
 - IV. Site Photographs and Sketches
 - V. Waste Characteristic
 - Waste Quantities
 - Waste Disposal Methods and Location
 - Waste Types
 - VI. Laboratory Data
 - Summary of Laboratory Results
 - Quality Assurance Review
 - VII. Toxicological/Chemical Characteristics
 - VIII. Data
 - IX. Site Inspection Report Form
 - X. References
 - XI. Appendices
 - A. "Hydrologic Conditions and the Potential for Contamination of Water Supplies at Chem-Solv, Cheswold, Delaware," DNREC
 - B. Monitoring Well Borings
 - C. Maps
 - D. Correspondence

AR100492