Louis R. Tomson
Chairman

Nancy E. Carey
Board Member

John R. Riedman
Board Member

John R. Platt
Executive Director

70694

Canal Operations

Matthew P. Behrmann
Director

Office of Canal Maintenance
and Operations

John M. King, P.E.
Director

Phone (518) 471-5010
TDD/TTY 1-800-253-6244
Fax (518) 471-5023

New York State Canal Corporation

200 Southern Boulevard
Post Office Box 189
Albany, New York 12201-0189

September 29, 2000

John J. Szeligowski
TAMS
655 Third Avenue
New York, NY 10017

Dear Mr. Szeligowski:

This responds to your request yesterday, in which you asked for another copy of the 1999 dredge chart for the Champlain Canal. Also enclosed are a few maps that show the pool elevation of the Champlain Canal.

I hope that the enclosed information meets your needs, should you have any questions, please feel free to contact me at 518/471-5011.

Sincerely yours,

JOHN R. DERGOSITS, P.E.
Canal Environmental Engineer

Enclosures

CC: D. Tomchuck – USEPA, NY

403323

The New York State Canal Corporation is a subsidiary of the New York State Thruway Authority

1999 NAVIGATION SEASON

STATE OF NEW YORK
DEPARTMENT OF TRANSPORTATION
WATERWAYS MAINTENANCE SUBDIVISION
REGION NO. 1   ALBANY, N.Y.

DREDGING CHART
SECTION NO. 1 - CHAMPLAIN CANAL

ENT SPOIL AREAS   HORIZ. SCALE 1"=1000'

IBLE SPOIL AREAS

ING AREAS

VATION NEEDED

VATION ACCOMPLISHED

C.Y.

19 99 NAVIGATION SEASON

STATE OF NEW YORK
DEPARTMENT OF TRANSPORTATION
WATERWAYS MAINTENANCE SUBDIVISION
REGION NO. 1   ALBANY, N.Y.

DREDGING CHART
SECTION NO. 1 - CHAMPLAIN CANAL

S POIL AREAS   HORIZ. SCALE   1"= 1000'

E SPOIL AREAS

AREAS

ION NEEDED

ION ACCOMPLISHED

EST. CAP. 20,000 C.Y.

AERIAL CABLE

AERIAL CABLE

403325

19 99 NAVIGATION SEASON

STATE OF NEW YORK
DEPARTMENT OF TRANSPORTATION
WATERWAYS MAINTENANCE SUBDIVISION
REGION NO. I   ALBANY, N.Y.

DREDGING CHART
SECTION NO. I CHAMPLAIN CANAL

SENT SPOIL AREAS   HORIZ. SCALE   I"= 1000'

SIBLE SPOIL AREAS

PING AREAS

VATION NEEDED

VATION ACCOMPLISHED

403326