Land Quality

Environmental Cleanup

Environmental Cleanup Site Information (ECSI) Database
Site Summary Report - Details for Site ID 2375, Portland Container Repair Corp.

This report shows data entered as of December 21, 2015 at 3:18:00 PM

This report contains site details, organized into the following sections: 1) Site Photos (appears only if the site has photos); 2) General Site Information; 3) Site Characteristics; 4) Substance Contamination Information; 5) Investigative, Remedial and Administrative Actions; and 6) Site Environmental Controls (i.e., institutional or engineering controls; appears only if DEQ has applied one or more such controls to the site). A key to certain acronyms and terms used in the report appears at the bottom of the page.

Note: DEQ may have posted online documents related to this site. If so, they would be available for viewing or downloading on ECSI Summary Page

Go to DEQ's Facility Profiler to see a site map as well is information on what other DEQ programs may be active at this site.

General Site Information

Site ID: 2375	Site Name: Portland Container Repair Corp.	CERCLIS No:	
Address:	9449 N Burgard Way Portland 97203		
	County: Multnomah	Region: Northwest	
Other location information:			
Investigation Status:	Suspect site requiring further investigation		
	Brownfield Site: No NPL Site: No	Orphan Site: No	Study Area: No
Property:	Twnshp/Range/Sect: 2N , 1W , 35	Tax Lots: 4,5,6,7, 8	
	Latitude: 45.6133 deg. Longitude: -122.7734 deg.	Site Size: Approx. 18.5 acres	
Other Site Names:	Burgard Industrial Park Portland Harbor Sediment Study Schnitzer Investment Corp.		

Site Characteristics

General Site Description:	
Site History:	
Contamination Information:	Weston sampling results from the Portland Harbor Sediment Study revealed total organotins, copper, zinc, and antimony in river sediments adjacent to the site.
Manner and Time of Release:	
Hazardous	

Substances/Waste Types:	
Pathways:	
Environmental/Health Threats:	
Status of Investigative or Remedial Action:	(6/15/99 JMW/SAP) Based on initial sampling results from a river sediment quality study, the Portland Container Repair facility has been identified as a potential source of contamination to the Portland Harbor. A Site Assessment Review Notice was sent on March 2, 1999. A response from the Portland Container Repair Corp was received on March 22, 1999. A site screening is scheduled (level II priority). (2/1/00 JMW/SAP) Site information combined in Schnitzer Steel Strategy Recommendation - SEE ECSI #2355.
Data Sources:	Portland Harbor Sediment Investigation Report, prepared by Roy F. Weston, Inc. for US EPA, 5/98.

Substance Contamination Information

Substance	Media Contaminated	Concentration Level	Date Recorded
No information is available			

Investigative, Remedial and Administrative Actions

Action	Start Date	Compl. Date	Resp. Staff	Lead Pgm
REMEDIAL INVESTIGATION (Primary Action)	03/02/2000		Michael Romero	VCS

Key to Certain Acronyms and Terms in this Report:

CERCLIS No.: The U.S. EPA's Hazardous Waste Site identification number, shown only if EPA has been involved at the site.
Region: DEQ divides the state into three regions, Eastern, Northwest, and Western; the regional office shown is responsible for site investigation/cleanup.
NPL Site: Is this site on EPA's National Priority List (i.e., a federal Superfund site)? (Y/N).
Orphan Site: Has DEQ's Orphan Program been active at this site? (Y/N). The Orphan Program uses state funds to clean up high-priority sites where owners and operators responsible for the contamination are absent, or are unable or unwilling to use their own resources for cleanup.
Study Area: Is this site a Study Area? (Y/N). Study Areas are groupings of individual ECSI sites that may be contributing to a larger, area-wide problem. ECSI assigns unique Site ID numbers to both individual sites and to Study Areas.
Pathways: A description of human or environmental resources that site contamination could affect.
Lead Pgm: This column refers to the Cleanup Program affiliation of the DEQ employee responsible for the action shown. SAS or SAP = Site Assessment; VCS or VCP = Voluntary Cleanup; ICP = Independent Cleanup; SRS or SRP = Site Response (enforcement cleanup); ORP = Orphan Program.

You may be able to obtain more information about this site by contacting Michael Romero at the Northwest regional office or via email at romero.mike@deq.state.or.us. If this does not work, you may contact Gil Wistar at (503) 229-5512, or via email at wistar.gil@deq.state.or.us or contact the Northwest regional office.

[print version]

For more information about **ECSI** call Gil Wistar at 503-229-5512 or email.

For more information about **DEQ's Land Quality programs**, visit the DEQ contact page.

Oregon Department of Environmental Quality
Headquarters: 811 SW Sixth Ave., Portland, OR 97204-1390
Phone: 503-229-5696 or toll free in Oregon 1-800-452-4011
Oregon Telecommunications Relay Service: 1-800-735-2900 FAX: 503-229-6124

The Oregon Department of Environmental Quality is a regulatory agency authorized to protect Oregon's environment by the State of Oregon and the Environmental Protection Agency.