Land Quality

Environmental Cleanup

Environmental Cleanup Site Information (ECSI) Database
Site Summary Report - Details for Site ID 69, Wilhelm Trucking

This report shows data entered as of December 21, 2015 at 3:30:57 PM

This report contains site details, organized into the following sections: 1) Site Photos (appears only if the site has photos); 2) General Site Information; 3) Site Characteristics; 4) Substance Contamination Information; 5) Investigative, Remedial and Administrative Actions; and 6) Site Environmental Controls (i.e., institutional or engineering controls; appears only if DEQ has applied one or more such controls to the site). A key to certain acronyms and terms used in the report appears at the bottom of the page.

Note: DEQ may have posted online documents related to this site. If so, they would be available for viewing or downloading on ECSI Summary Page

Go to DEQ's Facility Profiler to see a site map as well is information on what other DEQ programs may be active at this site.

General Site Information

Site ID: 69	Site Name: Wilhelm Trucking		CERCLIS No: 980639439
Address:	3250 NW St. Helens Rd. Portland 97210		
	County: Multnomah		Region: Northwest
Other location information:	Old address for site is 3074 NW St. Helens Rd.		
Investigation Status:	Suspect site requiring further investigation		
	Brownfield Site: No	NPL Site: No	Orphan Site: No / Study Area: No
Property:	Twnshp/Range/Sect: 1N , 1E , 29		Tax Lots: 34 (now T.L. 800)
	Latitude: 45.5447 deg.	Longitude: -122.7218 deg.	Site Size: 1 acre
Other Site Names:	National Lead Co. NL Industries Industrial Craters Magnus Co.		

Site Characteristics

General Site Description:	
Site History:	
Contamination Information:	Magnus Co. (from 1930-1936) and National Lead Company (from 1936-1967) operated a bearing rehabilitation plant at the site. Furnaces were used to melt lead from the bearings. Cracks in the building's concrete floor were filled with lead. Also, lead dust settled on structural beams within the building. Some lead dust may have settled outside the building on unpaved areas.

Manner and Time of Release:	Lead melting operations; time of release: 1930-1967.
Hazardous Substances/Waste Types:	lead
Pathways:	Workers at the business that currently uses the site (Industrial Craters, Inc.) may be exposed to lead-containing dust that has settled inside the building.
Environmental/Health Threats:	
Status of Investigative or Remedial Action:	Further DEQ information or investigation needed. (3/25/93 DRobinson/EPA) Based on a review by EPA's contractor, PRC Environmental Management, no further investigation is anticipated under the Federal Superfund program. PRC recommended the mitigaton of soil contamination on-site, to reduce the threat through the soil and air pathways.
Data Sources:	

Substance Contamination Information

Substance	Media Contaminated	Concentration Level	Date Recorded
LEAD	Other	280 ppm	
LEAD	Soil	39 ppm	

Investigative, Remedial and Administrative Actions

Action	Start Date	Compl. Date	Resp. Staff	Lead Pgm
Source Control Decision (Primary Action)	06/09/2008		James Orr	VCP

Key to Certain Acronyms and Terms in this Report:

CERCLIS No.: The U.S. EPA's Hazardous Waste Site identification number, shown only if EPA has been involved at the site.
Region: DEQ divides the state into three regions, Eastern, Northwest, and Western; the regional office shown is responsible for site investigation/cleanup.
NPL Site: Is this site on EPA's National Priority List (i.e., a federal Superfund site)? (Y/N).
Orphan Site: Has DEQ's Orphan Program been active at this site? (Y/N). The Orphan Program uses state funds to clean up high-priority sites where owners and operators responsible for the contamination are absent, or are unable or unwilling to use their own resources for cleanup.
Study Area: Is this site a Study Area? (Y/N). Study Areas are groupings of individual ECSI sites that may be contributing to a larger, area-wide problem. ECSI assigns unique Site ID numbers to both individual sites and to Study Areas.
Pathways: A description of human or environmental resources that site contamination could affect.
Lead Pgm: This column refers to the Cleanup Program affiliation of the DEQ employee responsible for the action shown. SAS or SAP = Site Assessment; VCS or VCP = Voluntary Cleanup; ICP = Independent Cleanup; SRS or SRP = Site Response (enforcement cleanup); ORP = Orphan Program.

You may be able to obtain more information about this site by contacting James Orr at the Northwest regional office or via email at orr.jim@deq.state.or.us. If this does not work, you may contact Gil Wistar at (503) 229-5512, or via email at wistar.gil@deq.state.or.us or contact the Northwest regional office.

[print version]

For more information about **ECSI** call Gil Wistar at 503-229-5512 or email.

For more information about **DEQ's Land Quality programs**, visit the DEQ contact page.

Oregon Department of Environmental Quality
Headquarters: 811 SW Sixth Ave., Portland, OR 97204-1390
Phone: 503-229-5696 or toll free in Oregon 1-800-452-4011
Oregon Telecommunications Relay Service: 1-800-735-2900 FAX: 503-229-6124

The Oregon Department of Environmental Quality is a regulatory agency authorized to protect Oregon's environment by the State of Oregon and the Environmental Protection Agency.

DEQ Web site privacy notice