ONGOING POLLUTION CONTROLS.

The Plan must address the issue of ongoing pollutants being dumped in the harbor and upriver. Re-contamination must not be allowed'.

(b) (6)

(b) (6)

Portland, OR 97203

17 AUG 2016 PM 6

RECEIVED
OREGON OPERATIONS OFFICE

AUG 19 2016

EPA-REGION 10

US. EPA.
805 SW BROADWAY Suite 500
PORTLAND OR 97205.

ATT: HARBOR COMMENTS.

recycled
© 2015 USPS