

SITE: Durham Meadows

BREAK: G.2

OWNER: 574808

www.enpro.com

www.tsdf.com

www.hazardouswaste.com


www.enpro.com

www.hazardouswaste.com

www.enpro.com

www.tsdf.com

www.hazardouswaste.com

NON HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CTD05131631333276		Manifest Document No.		2. Page 1 of 1	
3. Generator's Name and Mailing Address US EPA Region 1 / Precision Plating Superfund Site 5 Post Office Square, Suite 100 Boston MA 02109-3912				A. Non-Hazardous Manifest Document Number NH2001 33276			
4. Generator's Phone (617) 918-1389				B. S.G.I. (Gen. Site Address) 1050 Hartford Turnpike Vernon Rockville CT 06086			
5. Transporter 1 Company Name ENPRO SERVICES, INC.		6. US EPA ID Number MAD980670004		C. S.T.I. (Lic. Plate #) ME		D. Transporter's Phone 978-465-1595	
7. Transporter 2 Company Name		8. US EPA ID Number		E. S.T.I. (Lic. Plate #)		F. Transporter's Phone	
9. Designated Facility Name and Site Address ENPRO SERVICES OF MAINE, INC. 106 MAIN STREET SOUTH PORTLAND ME 04106				10. US EPA ID Number ME019051069		G. State Facility's ID SAME	
				H. Facility's Phone 207-799-0850			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers		13. Total Quantity	
a. NON DOT, NON RCRA REGULATED MATERIAL				No. Type		14. Unit Wt/Vol	
				I. Waste No.		State	
				015 DM 09000		NONE	
						NONE	
						State	
						State	
						State	
						State	
						State	
J. Additional Descriptions for Materials Listed Above (S) Precision - B Drill Cuttings;				K. Handling Codes for Wastes Listed Above			
a. ME-1214-06148		b.		Interim Final		Interim Final	
				a. ADR		b. HY1	
c.		d.		c.		d.	
15. Special Handling Instructions and Additional Information ENPRO CONTACT: ENPRO SERVICES, INC. - 24 HOURS - (800) 966-1102							
						Point of Departure: ENPRO JOB# 1303-14	
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, and all applicable state laws and regulations.							
Printed/Typed Name Daniel Warren TRC Agent for USEPA				Signature <i>[Signature]</i> TRC Agent for USEPA		Month Day Year 11/21/14	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name William P Mabee				Signature <i>[Signature]</i>		Month Day Year 11/21/14	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
						 SDMS DocID 574808	
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name William S. Pello				Signature <i>[Signature]</i>		Month Day Year 11/21/14	

ORIGINAL-RETURN TO GENERATOR

INSTRUCTIONS

IMPORTANT: READ ALL INSTRUCTIONS BEFORE COMPLETING THIS FORM ALL 5 COPIES MUST BE TOTALLY LEGIBLE

COPY DISTRIBUTION

- COPY 1: DESTINATION STATE COMPLETED COPY: Mailed by HWF:** This original stays with the shipment from generation to completion by the HWF. When the manifest is completed the HWF must mail this copy to the State where his facility is located.
- COPY 2: GENERATOR STATE COMPLETED COPY: Mailed by HWF:** When the HWF has completed his section of the manifest, he mails this copy to the State where the waste was generated.
- COPY 3: GENERATOR COMPLETED COPY: Mailed by HWF:** When the HWF has completed his section of the manifest, he mails this copy back to the Generator of the waste, who must retain it on site for his records.
- COPY 4: HWF COPY: Retained by HWF:** When the HWF has completed his portion of the manifest, he keeps this copy on site for his records.
- COPY 5: TRANSPORTER: Retained by the Transporter:** When the transporter has completed his section of the manifest, and transfers the waste to the HWF, he keeps this copy for his records.

GENERATOR SECTION

- Item 1: GENERATOR'S ID AND MANIFEST DOCUMENT NO. —** Enter the US EPA 12 digit identification number. Then enter a UNIQUE 5 digit number you assign to this manifest. Use of serially increasing numbers (eg. 00001, 00002 etc.) is recommended.
- Item 2: Page 1 OF —** Enter the total number of pages used to complete this manifest, i.e., the first form plus the number of Continuation Sheets, if any.
- Item A: MANIFEST DOCUMENT NUMBER —** Preprinted number.
- Item 3: GENERATOR'S NAME AND MAILING ADDRESS —** Enter the name (as notified to EPA) & mailing address of the Generator.
- Item 4: GENERATOR'S PHONE NUMBER —** Enter a telephone number with the area code where an authorized agent of the Generator can be reached in an emergency.
- Item B: STATE GENERATOR'S ID (S.G.I.) —** The State Generator ID is the STREET ADDRESS of the Generator's pick-up location. If the mailing address and the street address are the same, enter "same" in this block.
- Item 5: TRANSPORTER 1 COMPANY NAME —** Enter the company name (as notified by EPA) of the first transporter who will transport the waste.
- Item 6: US EPA ID NUMBER —** Enter the U.S. EPA ID 12 digit identification number of the first transporter identified in Item 5.
- Item C: STATE TRANSPORTER'S ID (S.T.I.) —** Enter the State of registration & the license plate number of the waste-carrying portion of the vehicle being used to transport the waste.
- Item D: TRANSPORTER'S PHONE —** Enter a telephone number with area code where an authorized agent of the transporter can be contacted.
- Item 7: TRANSPORTER 2 COMPANY NAME —** If applicable, enter the company name (as notified to EPA) of the 2nd transporter who will transport the waste. If more than 2 transporters will be used, use a Maine Manifest Continuation Sheet & list the transporters in the order they will be transporting the waste.
- Item 8: US EPA ID NUMBER —** If applicable, the U.S. EPA 12 digit identification number of the 2nd transporter identified in item 7.
- Item E: STATE TRAN ID (S.T.I.) —** If applicable, enter the 2nd transporter's State of registration & license plate number for the waste-carrying portion of the vehicle being used to make the pick-up.
- Item F: TRANSPORTER'S PHONE —** If applicable, enter the 2nd transporter's telephone number with area code where an authorized agent of the transporter can be contacted.
- Item 9: DESIGNATED FACILITY NAME & SITE ADDRESS —** Enter the company name (as notified to EPA) of the HWF designated to receive the waste listed on this manifest. The address must be the site address, which may differ from the mailing address.
- Item 10: US EPA ID NUMBER —** Enter the U.S. EPA 12 digit identification number of the designated HWF identified in item 9.
- Item G: STATE FACILITY'S ID —** Enter mailing address if different from site address.
- Item H: FACILITY PHONE —** Enter a telephone number with area code for the HWF designated to receive the waste listed on the manifest.
- Item 11: US DOT DESCRIPTION —** ALL of the following information must be entered: The correct US DOT (Dept. of Transportation) name for the waste as identified in 49 CFR Parts 171-177 (usually found in Column 2 of Section 172.101), the assigned DOT Hazard Class (usually in Column 3) & the 4 digit UN/NA ID Number (Column 3A) (Example: Waste Acetone, **flammable liquid**, UN-1090).
- Item 12: CONTAINERS (NO & TYPE) —** Enter the number of containers for each waste and the appropriate abbreviations from TABLE 1 (below) for the type of container used.

TABLE 1 — CONTAINER TYPE

DM = Metal Drums, barrels, kegs	TP = Tanks, portable	CM = Metal boxes, cartons, cases (incl. roll-offs)
DW = Wooden drums, barrels, kegs	TT = Cargo Tanks (tank trucks)	CW = Wooden boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	TC = Tank Cars	CF = Fiber or plastic boxes, cartons, cases
CY = Cylinders	DT = Dump Trucks	BA = Burlap cloth, paper/plastic bags

- Item 13: TOTAL QUANTITY —** Enter the total quantity of waste described on each line, relative to the units used in ITEM 14.
- Item 14: UNIT (Wt./Vol.) —** Enter the appropriate abbreviation from Table II (below) for the unit of measure used in determining the total quantity of waste described on each line. DO NOT use fractions.

TABLE II — UNITS OF MEASURE

G = Gallons (liquids only)	L = Liter (liquids only)	Y = Cubic Yards
P = Pounds	K = Kilograms	N = Cubic Meters
T = Tons	M = Metric Tons (1,000 kg)	

- Item I: NO. —** Enter the 4 digit State waste code. If both the Destination and Generator States have assigned codes, use the Destination State code. If there is no EPA/State code, enter "NONE" - Do NOT leave blank.
- Item J: ADDITIONAL DESCRIPTIONS FOR MATERIALS LISTED ABOVE —** Enter description (chemical names, constituent percentages, etc.) for any waste which has a US DOT shipping name ending in N.O.S. If you entered a STATE-DESIGNATED WASTE CODE in Item I, provide description or note any EPA Hazard Codes: Ignitable (I), Corrosive (C), Reactive (R), EP Toxic (E), Acute Hazardous (H), Toxic (T). Enter specific gravity if other than 1.0 and physical state of waste. Any additional desired waste description may be entered here.
- Item 15: SPECIAL HANDLING INSTRUCTIONS & ADDITIONAL INFORMATION —** Use this space to indicate special transportation, packaging or disposal, or Bill of Lading information. If an alternate facility is designated, note it here. For INTERNATIONAL SHIPMENTS, the Generator must enter here the point of departure from the U.S. through which the waste must travel before entering a foreign country (City & State). This space may also be used for emergency response numbers, and other information the Generator wishes to include about the shipment.
- Item K: HANDLING CODES (HWF COMPLETES) —** HWF completes this section—see "Designated Facility Section" - (below)
- Item 16: GENERATORS CERTIFICATION —** The Generator must read, sign (by hand) & date the Certification (with date of transfer to transporter). If a mode other than high is used, the word "highway" should be lined out & the appropriate mode (rail, water or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g. "and rail") in the space below.

TRANSPORTER SECTION

- Item 17: TRANSPORTER 1 ACKNOWLEDGEMENT —** Print or type the name of the person accepting the waste on behalf of the 1st transporter. That person must acknowledge acceptance of the waste described on the manifest by signing & entering the date of receipt.
- Item 18: TRANSPORTER 2 ACKNOWLEDGEMENT —** If applicable, follow instructions for Item 17 for Transporter 2.

DESIGNATED FACILITY (HWF) SECTION

- Item K: HANDLING CODES (HWF COMPLETES) —** Enter the final Handling Code as described in 40 CFR 464 Appendix I, Table 2 for each waste listed in Item 11. For example, D81-Landfill or T07-Rotary Kiln Incinerator.
- Item 19: DISCREPANCY INDICATION SPACE —** The authorized representative of the designated facility's owner or operator must note in this space any significant discrepancy between the waste described on the manifest & the waste actually received at the facility. Any rejected materials should be listed here, along with an indication of the disposition of the rejected materials.
- Item 20: FACILITY OWNER OR OPERATOR CERTIFICATION: —** Print or type the name of the person accepting the waste on behalf of the owner or operator of the designated HWF. That person must acknowledge acceptance of the waste described on the manifest by signing (by hand) & entering the date of receipt. The signature of the authorized HWF agent indicates acceptance (except for items specified in Item 19) & agreement with the statements on this manifest.

NOTE: FOR INTERSTATE SHIPMENTS (between different states) YOU MAY BE REQUIRED TO COMPLY WITH THE MANIFESTING REQUIREMENTS OF BOTH THE DESTINATION & GENERATOR STATES REGARDING THE COMPLETION OF SPECIFIC INFORMATION INCLUDED IN LETTERED ITEMS A-L. You may wish to contact State agencies for more information on this subject.

REMINDER: ALL 5 COPIES OF THIS FORM MUST BE LEGIBLE