



# Morrill Construction Co., Inc.

840 SOUTH KINGSHIGHWAY  
CAPE GIRARDEAU, MO. 63701

Site: MEW  
ID #: MJD9807657B  
Break: 5.7  
Other: ADDENDUM II

205222

Phone: (314) 334-4828

September 14, 1990

United States Environmental Protection Agency  
Region VII  
726 Minnesota Ave  
Kansas City, Kansas 66101

RECEIVED  
SEP 17 1990  
REML SECTION

ATTN: Ms. Hattie Thomas

Ref: Missouri Electrical Works Superfund Site



2046566

Dear Ms. Thomas;

Morrill Construction Company is very concerned about the proposed clean-up operation to be performed here at the M.E.W. site. It has already begun to interrupt the work flow here at our business property. Below is a list of concerns we would appreciate you addressing as soon as possible.

- 1) Who will be the responsible party contractor or firm responsible for the different phases or alternatives of clean-up being proposed?
  - 2) What exactly would be the proposed schedule and procedure in which it would take place?
  - 3) How long would the different phases take? (months, years, follow-up, etc?)
  - 4) What kind of labor, material, equipment and possible sub-contracting would be utilized?
  - 5) What kind of hours and what times during the day would this work be performed?
  - 6) What kind of work clothes, protective clothing, etc would be worn during these hours?
  - 7) Who will handle the inspection of the party responsible for the clean-up on a day to day basis as the work progresses?
  - 8) Who will be responsible for the monitoring for the contaminated area's as the work progresses?
- \*\* If the on-site incineration of the contaminated soils is selected, the following questions are of concern:
- 1) We would ask for a detailed explanation of what the incineration method involves.
  - 2) How will it be completed? (all at once, phases, small amount at a time, etc?)
  - 3) Will the contaminated material be stockpiled on site, excavated and hauled off all at once, or what?

MEW Admin record  
AR108753

September 14, 1990

U.S. Environmental Protection Agency  
Region VII  
726 Minnesota Ave  
Kansas City, Kansas 66101

Attn: Ms. Hattie Thomas


- 4) What about the emisions from the incineration process?
- 5) What hours of the day would the "burning" take place?
- 6) What happens to the residue left over from the inceneration process?
- 7) What type of fill material would be used back in its place, where would it come from, would the site be sodded back and finish landscaped when the excavation is complete?
- 8) What about our employees, both field and office, possible health hazards as the work is being performed, before, during and after?

Being commercial, Industrial and manufacturing contractors ourselves there are many other questions in our minds. These questions will be asked when we see which direction the E.P.A. is headed with this clean-up operation.

Thank you for listening to these questions. We anxiously await your reply.

Concerened Adjoining Property Owner to M.E.W.,

Morrill Construction Co.Inc.



C.J.M. -/President

CM/tl