



United States Environmental Protection Agency – Region 1

Off-Site Rule Compliance Request Form

Date: (mm/dd/yy) 11/18/14	Supporting Documentation Attached? (yes/no) Yes
---	---

RECEIVING FACILITY INFORMATION:		
1	Name of Facility receiving CERCLA waste:	Liquid Environmental Solutions (formerly NewStream LLC)
2	Address of Facility:	527 Pleasant St., Building 11D
3	City:	Attleboro
4	State:	MA
5	Zip Code:	02703-9604
6	EPA/State Facility ID: (e.g. Haz. Waste/Municipal Waste ID)	MAC0005808
7	Other Pertinent ID Numbers: (e.g. License #, permit #)	
8	Phone Number (if available):	508-236-6001
9	Contact Name (if available):	Mr. Rick Derby, Operations Manager
10	FAX Number (if available):	508-236-6004
11	E-mail address (if available):	

GENERATING FACILITY INFORMATION:		
12	CERCLA Site Name:	Creese & Cook Tannery (Former) Superfund Site
13	CERCLA Site Address:	33 Water Street
14	City:	Danvers
15	State:	Massachusetts
16	Zip Code:	01923
17	CERCLA Site ID: (i.e. alpha-numeric)	MAD001031574
18	EPA CERCLA ID #:	
19	Waste Media: (e.g., Soil, Water, Air, etc.)	Water (Investigation Derived Wastes)
20	CERCLA Waste Contaminates: (e.g. tce, pcb, lead)	See comment section below
21	Amount of CERCLA Waste: (e.g. gallons, pounds, tons, ft ³ , yd ³)	
22	EPA representative making waste determination: (e.g. OSC, RPM & Tel.#)	Diane Baxter - Nobis Engineering - 978-703-6025 Derrick Golden – EPA - 617-918-1448

Comments:

Waste Characterization: Non-RCRA IDW Groundwater based on no TCLP exceedances of VOCs, SVOCs, or metals; no exceedance of criteria for ignitability, corrosivity, reactivity; and no detection of PCBs. See waste characterization report attached.

CERCLA waste contaminants present in samples collected from monitoring wells for site characterization were limited mainly to metals, with sporadic low-concentration detections of chlorinated VOCs and dioxins/furans.

For more information on the Off-Site Rule, please contact the appropriate Regional Off-Site Contact (ROC) listed at <http://www.epa.gov/waste/hazard/wastetypes/wasteid/offsite/index.htm>

	Regional Off-Site Contacts (listed as of April 8, 2014)	
Region # U.S. & DC,PR,VI	Contact Name	Telephone #
1 CT,MA,ME,NH,RI,VT	Donald MacLeod (macleod.donald@epa.gov)	617.918.1405
2 NY,NJ,PR,VI	Beckett Grealish (Region2_OSR@epa.gov)	732.321.4341
3 DC,DE,MD,PA,VA,WV	Gary Morton (morton.gary@epa.gov)	215.814.3159
4 AL,FL,GA,KY,MS,NC,SC,TN	Paula Whiting (whiting.paula@epa.gov)	404.562.9277
5 IL,IN,MI,MN,OH,WI	William Damico (damico.william@epa.gov)	312.353.8207
6 AR,LA,NM,OK,TX	Wilkin (Ron) Shannon (shannon.wilkin@epa.gov)	214.665.2282
7 IA,KS,MO,NE	Nicole Moran (moran.nicole@epa.gov)	913.551.7641
8 CO,MT,ND,SD,UT,WY	Terry Brown (brown.terry@epa.gov)	303.312.6419
9 AZ,CA,HI,NV	Kandice Bellamy (bellamy.kandice@epa.gov)	415.972.3304
10 AK,ID,OR,WA	Kevin Schanilec (schanilec.kevin@epa.gov) Ofelia Erickson (erickson.ofelia@epa.gov)	206.553.1061 206.553.2583