

U.S. ENVIRONMENTAL PROTECTION AGENCY  
REGION I

MEMORANDUM

Superfund Records Center

SITE: Shpack Landfill

BREAK: 7.5

OTHER: 583702

Date: August 25, 2015

Subject: Shpack Landfill Superfund Site, Norton/Attleboro Massachusetts  
Final Remedial Construction and Demonstration of Compliance Report

From: Melissa Taylor, Remedial Project Manager  
Massachusetts Superfund Section

Thru: Bob Cianciarulo, Chief  
Massachusetts Superfund Section


To: Bryan Olson, Chief  
Remediation & Restoration Branch I

Please find attached the Final Remedial Construction and Demonstration of Compliance Report (April 22, 2015) for the Shpack Landfill Superfund Site. The Final Remedial Construction and Demonstration of Compliance Report also serves as the Remedial Action Report for the Site. The Report certifies that the Remedial Action activities have been performed at the Site in accordance with the requirements of the Consent Decree and documents that the performance standards for the remedy required in the Consent Decree have been achieved. This report was prepared by Environmental Resources Management on behalf of the Performing Defendants under EPA oversight.

The Report provides: a Site background; a description of the Remedial Action requirements; a description of construction quality control and health and safety measures; and a description of remedy implementation; including the Peckham Street water supply pipeline project, excavation activities, waste management and disposal, and wetland and site restoration.

The remedy involved excavating and off-site disposal of contaminated soil and sediments in areas of the Site that were in exceedance of chemical cleanup standards; installation of a public water supply line to within 500 feet of the site; and wetlands restoration in accordance with the requirements of the ROD. The remedy required extensive stormwater management and excavation dewatering, including the use of pumps to convey water to pre-treatment settling areas and infiltration basins located on site. In addition, after remedial activities were completed, the public roadway (i.e., Peckham Street and Union Road) adjacent to the Site experienced flooding; therefore, a roadway storm management system was constructed to restore the pre-remediation connection between the public roadway and the on-site wetlands. The construction activities (including addressing punch-list items) were completed in July 2014. The final inspection was conducted in September 2014.

EPA has determined that the remedial action at the Site is complete and complies with all federal and state regulatory requirements. I recommend that you sign this memorandum to indicate EPA's acceptance of this as documentation of Remedial Action completion.



Bryan Olson, Chief  
Remediation and Restoration I Branch



SDMS DocID

583702