



Aerial images courtesy of Salvatore A. Boccuti


03/04/2009







Park Parcel (July 2008)



Reservoir and Pile Parcels (August 2008)




Phase I Before Removal Activities




Phase I Before Removal Activities













Phase I After Removal Activities



Phase I After Removal Activities



Phase II Before Removal Activities



Phase II Before Removal Activities





Phase II Before Removal Activities











Phase II After Removal Activities




Phase II After Removal Activities



Phase II After Tropical Storm Lee



Phase II After Tropical Storm Lee







Rose Valley Creek at Maple Avenue Swing Gate after storm Lee cleanup. The swing gate opens slowly as pressure from the water builds up.










Phase II After Reconstruction




Phase III Before Removal Activities







Phase III After Removal Activities



Phase III After Removal Activities



Phase III After Removal Activities




Phases II and III After Removal Activities



Exposed Area – Pile Property




Tannery Run (Phase IV) During Removal Activities



Phase IV During Removal Activities



Phase IV During Removal Activities




Phase IV – Open Section



Phase IV – Open Section












Phase IV During Removal Activities




Phase IV After Removal Action



Phase V During Removal Action



Phase V During Removal Action



Phase V After Removal Action



Phase V After Removal Action




Pile During Removal Action



Pile During Removal Action







Alley by the Park



Curb Installation Along the Alley



Alley by the Park



