

AECOM 303 E. Wacker Drive, Suite 900 Chicago, Illinois 60601 312-938-0300 tel 312-938-1109 fax

US EPA RECORDS CENTER REGION 5



May 1, 2012

Mr. Narendra Prasad People's Gas Light & Coke Co. Environmental Services Department 130 East Randolph, 22nd Floor Chicago, IL 60601

RE: Radiological Survey of Right-of-Way Utility Excavation

Permit No.: 252580634

Permit Address: 401 East 26th Street AECOM Project No. 60157647

Dear Mr. Prasad:

Pursuant to conditions specified in a permit (see attached) issued by the City of Chicago, radiation monitoring was required to be performed at the above referenced site. AECOM Technical Services, Inc. (AECOM) provided the required radiation surveillance on April 27, 2012 for the installation of an anode on existing gas service piping.

Surveying was performed for the soil removed from an 18-inch vacuum excavated borehole at South Martin Luther King Drive and East 26th Street (see sketch) to a depth of 7-feet below ground surface required for installation of the anode protection on the existing gas service piping. For this excavation a vacuum truck was used to remove the soil, therefore the probe had to be lowered into the borehole at 12 to 15-inch intervals.

A cleanup criterion has not been approved for this area by the USEPA. Therefore, the USEPA has requested that the field instrument threshold for potentially radiologically contaminated material conservatively be set at approximately twice the field instrumentation background. Gamma radiation count measurements for the project were made using Ludlum Model 2221 survey meter and a shielded 2 x 2 inch Nal probe (Model 44-10). To perform the screening the shielded probe required a longer (25-foot) cable. The field instrumentation gamma background for the surrounding area outside the excavation based on multiple measurements using a shield and a 25-foot cable was approximately 934 counts per minute (cpm). Thus, twice this field instrumentation background, or 1,868 cpm, was considered as the conservative indicator of potential contamination.

The excavation/borehole monitoring revealed no gamma counts above twice the field instrument background. The field gamma measurements within the borehole ranged from a minimum of 1,200 cpm to a maximum of 1,550 cpm shielded. Thus, there was no indication of the presence of radiologically contaminated material and/or an exceedance of twice the project specific field instrument background.

As part of the permit conditions this letter has been forwarded to:

Chicago Department of Public Health Attention: Ms. Rahmat Begum 333 South State Street, Rm. 200 Chicago, Illinois 60604 Radiological Survey of Right-of-Way Utility Excavation

Permit No.: 252580634

Page 2

Please contact us with any questions you have regarding this letter or the reported results.

Regards,

Joshua J. Rowe Project Scientist II

Jashua & Rome

Steven C. Kornder, Ph.D. Senior Project Geoscientist

Rahmat Begum, Chicago Department of Public Health Verneta Simon, USEPA

Attachments: Permit

Sketch



DEPARTMENT OF PUBLIC HEALTH CITY OF CHICAGO

FORM NO. CDPH.ROW.03

Notice is hereby given that the site you have requested a permit for is recorded with the City of Chicago Department of Public Health (CDPH) as potentially having environmental contamination on the site and adjacent right-of way. This environmental contamination could present a threat to human health and safety in connection with work performed at the site, or in the adjacent right-of-way, if proper safeguards are not employed.

A file containing detailed information regarding the aforementioned environmental contamination is available for review at CDPH at 33 N. LaSalle St., Suite LL-120, Chicago, Illinois 60602 during normal business hours (8:30AM-4:30PM, Monday through Friday). Contact (312) 744-3152 for an appointment. This file must be reviewed and the remainder of this form completed before the permit can be issued if the ground is exposed or excavated. Please note that for some locations, additional health and safety procedures may be required by law.

ground is exposed or excavated. Please note that for some locations, additional health and safety procedures may be required by law.
Please complete the following: I have reviewed and understand the documents, maintained by CDPH, regarding environmental contamination of the site and adjacent right-of-way. Further, I will ensure that all work at the subject site and adjacent right-of-way, and any monitoring required including but not limited to radiation monitoring, will be performed in a manner that is protective of human health and the environment and in compliance with all applicable local, state, and federal laws, rules, and regulations, especially those pertaining to worker safety and waste management. I will ensure that the results of any radiation monitoring and/or surveying conducted shall be provided to the CDPH and the United States Environmental Protection Agency within two (2) weeks of their completion. If any elevated levels of radioactive material are detected, I will immediately contact the United States Environmental Protection Agency at (800) 424-8802. Applicant Name (print): Applicant Name (print): Signature: Signature: Signature:
Site Address and Work Location (Describe exact site location and attach map): 401 & 26th 1.
Work in street, sedewalk, parkway
Nature of Work: Openation
Company Name, Address, Phone No.: Jeoples Sus, 130 & Sandolph (3/2) 240-4692
General / Prime Contractor Name, Address, Phone No.: Rushel Mulson, 130E. Pandslph (773) 395- Include subcontractor information if applicable) Safety Officer / Phone No. 6 Demonstrated (773) 962-4830
Radiation Contractor / Phone No. (if applicable) AECOM, Suc, Steve Kornder (847) 279-2440
Check if City Department Work Department Name:
CDOT Permit No.: 2525 80434
Today's Date: 1/18/12 Expected Start Date: 1811 CDPH Approval / Date Kahniatumer Breau
Please return this completed form to the Chicago Department of Transportation, Division of Infrastructure Management, Public Way Perint 8 / 20 Diffice, City Hall – Room 905, 121 N. LaSalle St., Chicago, Illinois 60602 during normal business hours (8:30 AM - 4:30 PM, Monday through Priday)
For CDPH Use Only

-		
Л		4
-	_ \ \	7
_		_

JOB TITLE 401 E 26th St - Integrys

JOB NO. 60157647 CALCULATION NO.

ORIGINATOR Josh Rowe DATE 4127112

REVIEWER DATE

SCALE NOT to SCALE SHEET NO. 1 OF

A	
, N	
	8
	26 th St
~	J Medium (X) [344
D AL	
MLK Drve	10 ft Core hole I3ft
depth counts per minute	Sideralk 11A
74" 1300 36" 1400	
48" 1500 60" 1550	& background Locations
72" 1350 84" 1200	
. 1200	Side walk
not to scale	44

Grid: 6x6 = 2 cm