

Stan A. Huber Consultants, Inc.

Health Physics and Radiation Safety Services

200 North Cedar Road - New Lenox, Illinois 60451-1751 - (800) 383-0468 or (815) 485-6161 - FAX (815) 485-4433 - Email sahci@sahci.com - Home Page www.sahci.com

May 12, 2020

958184

Mike Lanenga SET Environmental 450 Sumac Road Wheeling, Illinois 60090

RE: Thorium Monitoring – City of Chicago Department of Water Management

CDOT Permit: 1233456 - 311 E. Ohio St.

.

Dear Mr. Lanenga:

Stan A. Huber Consultants, Inc (SAHCI) was hired by your firm to provide radiation monitoring during the excavation for repair of a storm sewer discharge pipe at 311 E. Ohio St. in Chicago, Illinois. The monitoring was performed by Brian Schmidt, SAHCI Health Physics Technician, on April 28, 2020. All activities were conducted under the guidance of document *SET General Procedure for Thorium Monitoring*.

<u>Instrumentation</u>

Surface gamma scans were performed using a Ludlum Model 2221 Scaler / Ratemeter (serial no. 132844) with attached Ludlum Model 44-10 2"x2" Nal Detector (w/ 6" collimated lead shield). The instrument was calibrated on August 6, 2019. The US Environmental Protection Agency (USEPA) action level of 7.1 picocuries per gram (pCi/g) total thorium for this instrument is 7,299 counts per minute (cpm).

The average background count rate for these locations was measured at 1,947 cpm.

Soil Gamma Scans

Gamma surface scans were performed using the Ludlum Model 2221 Scaler / Ratemeter described above. Survey data was collected by entering the excavation and recording the highest count rate for the floor and walls to an excavation depth of 4 feet below ground surface. Material excavated from 4 feet to 8.5 feet below ground surface was surveyed in the excavator bucket as it was removed. All asphalt, concrete, and soil were loaded directly into a truck for disposal.

The maximum gamma count rate for each lift was recorded on the attached Radiation Survey Form. The count rates in the excavation ranged from 2,100 cpm to 4,100 cpm. No count rates were found at any time that exceeded the threshold limit of 7,299 cpm.

Additional Monitoring

Since no count rates were identified above the 7.1 pCi/gram threshold limit, no additional soil sampling, air monitoring, or personnel monitoring were performed.

I will be providing a copy of this report to both the City of Chicago Department of Public Health and US Environmental Protection Agency, as required.

Thank you for your assistance with this project. If you have any questions or need additional information, please call me at (815) 485-6161.

Sincerely,

Stan A. Huber Consultants, Inc.

Calledon .

Glenn Huber, CHP

President



Radiation Survey Form

Location/ Project ID: DWM- 311 E. On 10 St. - Sewen Beginner REPAIR - ROW RADIOLOGICAL

SOIL SURVEY Technician: BRIAN SOUMIST 4/21/2020 Serial No.: 132844 Inst Model: Lunum - 2221 Lift Elevation: __O~/oZ" Probe Type: 1"x1" Nal / 2"x2" Nal Shielded / Not Shielded Action Level: 7199 1947 cpm Background . Write grid designations in circles. Record highest counts for grid in cpm. Record 30 second counts at grid intersections (if required). Shade areas of elevated counts and record max cpm. N scale 0410 St. FAIR STREET CURB Exchation IO DEPTH CPM 0-12" -7200 2700 3600 94-101"- 2300 102-120"- 2100