

Stan A. Huber Consultants, Inc.

Health Physics and Radiation Safety Services

200 North Cedar Road - New Lenox, Illinois 60451-1751 - (800) 383-0468 or (815) 485-6161 - FAX (815) 485-4433 - Email sahci@sahci.com - Home Page www.sahci.com

January 29, 2021

Nicole Espinoza Electric Conduit Construction 3333 S. Iron St. Chicago, IL 60608

RE: Thorium Monitoring 628-632 N. Fairbanks Ct.

CDOT Permit #1400494

Dear Ms. Espinoza:

Stan A. Huber Consultants, Inc (SAHCI) was hired by your firm to provide radiation monitoring during the excavation and replacement of a utility pole at 628-632 N. Fairbanks Ct. in Chicago, Illinois. The monitoring was performed by Brian Schmidt, SAHCI Health Physics Technician, on January 20, 2021.

Instrumentation

Surface gamma scans were performed using a Ludlum Model 2221 Scaler / Ratemeter (serial no. 132844) with attached Ludlum Model 44-10 2"x2" Nal Detector (w/ 6" collimated lead shield). The instrument was last calibrated on July 28, 2020. The US Environmental Protection Agency (USEPA) action level of 7.1 picocuries per gram (pCi/g) total thorium for this instrument is 7,592 counts per minute (cpm).

The background count rate for this location was measured at 1,273 cpm.

Soil Gamma Scans

Gamma surface scans were performed using the Ludlum Model 2221 Scaler / Ratemeter described above. Survey data was collected by entering the excavation and recording the highest count rate for the floor and walls to a maximum excavation depth of 3 feet below ground surface. Soil below 3 feet was removed using a vacuum truck. Measurements were taken by lowering the detector into the hole after each 18 inches to a maximum depth of 9 feet.

The maximum gamma count rate for each lift was recorded on the attached Radiation Survey Form. The count rates in the excavation ranged from 1,400 cpm to 3,500 cpm. No count rates were found at any time that exceeded the threshold limit of 7,592 cpm.

Additional Monitoring

Since no count rates were identified above the 7.1 pCi/gram threshold limit, no additional soil sampling, air monitoring, or personnel monitoring were performed.

I will be providing a copy of this report to both the City of Chicago Department of Public Health and US Environmental Protection Agency, as required.

Thank you for your assistance with this project. If you have any questions or need additional information, please call me at (815) 485-6161.

Sincerely, Stan A. Huber Consultants, Inc.

Glenn Huber, CHP President

Page	of	
------	----	--



Radiation Survey Form						
Location/ Project ID: (ECC - ONTANIO + F	FAIRBANKS - LIGH	+ Poll			
Date: 1/20/2021		Technician: 1	MIAN SCHNIOT			
Inst Model: LVDLUA	2- 2221	Serial No. :	132844			
Probe Type: 1"x1" Nal	/ 2"x2" Na / Not Shielded	Lift Elevation: _	0-108"			
Background	cpm	Action Level: 7	592 cpm			
Write grid designations in circl at grid intersections (if required) N		
			scale)		
1	4'	D 45		— <u> </u>		
	14'	2445		<u></u>		
	START CULS I	FAIRBANUS ST				
	ONTAKIO ST.			—		
D EXCAPATION ID 0-6" 6-24" 24-42"	DEPTY CPM 1400 1800					
42-60" 60-78"	22 <i>00</i> 27 <i>00</i> 3000			—		
78-96" 96-114"	3100 3200	ı				
108-126"	3500					