

200 North Cedar Road - New Lenox, Illinois 60451-1751 - (800) 383-0468 or (815) 485-6161 - FAX (815) 485-4433 - Email sahci@sahci.com - Home Page www.sahci.com

November 22, 2021

Paul Muszynski Electric Conduit Construction 3333 S. Iron St. Chicago, IL 60608

RE: Thorium Monitoring at 194-238 E. North Water St. CDOT Permit # 1612933

Dear Mr. Muszynski:

Stan A. Huber Consultants, Inc (SAHCI) was hired by your firm to provide radiation monitoring during excavation for installation of a utility conduit at 194-238 E. North Water St. in Chicago, Illinois. The monitoring was performed by Brian Schmidt, SAHCI Health Physics Technician, on November 17, 2021.

Instrumentation

Surface gamma scans were performed using a Ludlum Model 2221 Scaler / Ratemeter (serial no. 134542) with attached Ludlum Model 44-10 2"x2" Nal Detector (w/ 6" collimated lead shield). The instrument was last calibrated on May 5, 2021. The US Environmental Protection Agency (USEPA) action level of 7.1 picocuries per gram (pCi/g) total thorium for this instrument is 7,396 counts per minute (cpm).

The background count rate for this location was measured at 1,776 cpm.

Soil Gamma Scans

Gamma surface scans were performed using the Ludlum Model 2221 Scaler / Ratemeter described above. Survey data was collected by entering the excavation and recording the highest count rate for the floor and walls to a maximum excavation depth of 4 feet below ground surface. Soil, concrete, and asphalt were loaded directly into a truck for offsite disposal.

The maximum gamma count rate for each 18-inch lift was recorded on the attached Radiation Survey Form. The count rates in the excavation ranged from 1,800 cpm to 2,500 cpm. No count rates were found at any time that exceeded the threshold limit of 7,396 cpm.

Additional Monitoring

Since no count rates were identified above the 7.1 pCi/gram threshold limit, no additional soil sampling, air monitoring, or personnel monitoring were performed.

I will be providing a copy of this report to both the City of Chicago Department of Public Health (CDPH) and USEPA, as required.

Thank you for your assistance with this project. If you have any questions or need additional information, please call me at (815) 485-6161.

Sincerely, Stan A. Huber Consultants, Inc.

Glenn Huber, CHP President

sahci.		Page of
Stan A. Huber Consultants, Inc		ion Survey Form
Location/ Project	ID: FOG - FARA SE	ERVICE INFIAM - S. WATER ST ROW RADIOLOGICAL
Data Ulnh	a21	Technician: BLIAN SUMPT
Date:/		
Inst Model:	Inlun - LLLI	Serial No. : 134542
Probe Type: 1"x	1" Nai / 2"x2" Na Ided / Not Shielded	Lift Elevation: <u>0-48</u> "
_		7,396 Action Level: <u>675%</u> GAH
Background 177		
		counts for grid in cpm. Record 30 second counts elevated counts and record max cpm.
		Ň
\bigcirc	.01	
Ť	t, Guan Si	T T T O
	3 +	- STGUAS
	4	4
S. LJAI	En ST	
5.		MANHOLE
	- 7	
	St. Curst	
	1. pi - y - 89.	9' DELISTING COLUMN
		3' 12' 2'
EXCALATES	to Derry CI	Pm O
		00 500
	1	3 00
	36-54" 25	
	48-66 21	100

1