



Appendix C

Ü^] !^•^} cca^Ái[b&Á
Ú@ç *!a çÁ

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 1: Installation of sheetpile weir/stop log structure Housatonic River Outfall (7/18/12)

Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á



Photograph 2: Installation of sheetpile weir/stop log structure Housatonic River Outfall (7/18/12)

Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á
Á



Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 3: Installation of sheetpile for soil removal activities (8/14/12)

Á



Á
Á

Photograph 4: Soil removal activities (Polygon 5) (8/16/12)



Á
Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 5: Installation of sheetpile for soil removal activities (8/16/12)



Photograph 6: Soil removal activities (Polygon 5) (8/20/12)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 7: Construction of access road on Shrub-Scrub Island (8/21/12)



Á

Photograph 8: Decommissioning monitoring wells (8/31/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 9: Decommissioned 12-inch cast iron pipe discovered in Polygon 5 (9/6/12)



Á

Photograph 10: Direct loading of excavated materials during soil removal activities (9/13/12)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 11: Installation of sheetpile for soil removal activities (9/22/12)



Á

Photograph 12: Near-shore sediment removal near Fourth Street Outfall (10/26/12)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 13: Soil/debris material handling at temporary stockpile (10/31/12)



Photograph 14: Near-shore area restoration (11/7/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 15: Installed erosion control blanket in restored Recreational Areas (11/10/12)



Photograph 16: Clearing of large trees (11/16/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 19: Near-shore area restoration (11/20/12)



Photograph 20: Removal of debris (Target 14) (12/4/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 21: Removal of debris (Target 14) (12/7/12)



Photograph 22: Clearing vegetation from Shrub-Scrub Island (12/10/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 23: Installation of geotextile fabric on Shrub-Scrub Island (12/12/12)



Photograph 24: Installation of cap and topsoil material on Shrub-Scrub Island (12/12/12)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 25: Removal of sheetpile (1/2/13)



Photograph 26: Direct loading of cleared and grubbed vegetation (1/3/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 27: Bank clearing and grubbing (1/3/13)



Photograph 28: Verification of thickness of near-shore restoration layer(s) (1/17/13)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 29: Installation of sheetpile for soil removal activities (1/28/13)



Á
Á

Photograph 30: Installation of sheetpile for soil removal activities (1/29/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 31: Delivery of super sacks of Lime Kiln Dust to Bldg.65 (2/27/13)



Photograph 32: Staged HDPE pipe for hydraulic capping activities (3/5/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 35: Fusing of HDPE Pipe in preparation for hydraulic capping activities (3/14/13)



Photograph 36: Backfill activities (Polygon 9B) (3/18/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 37: Utility management during soil removal activities (3/19/13)



Á

Photograph 38: Installation of geotextile fabric for near-shore area restoration (3/22/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 39: Staged mixing hopper associated with hydraulic capping operations (3/22/13)



Photograph 40: Installation of armor stone layer in near-shore area (3/28/13)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 41: HDPE pipe installed through PEDAs Outfall in preparation for hydraulic capping activities (3/28/13)



Photograph 42: Installation of near-shore area Gravel Habitat Layer (4/5/13)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 45: Hydraulic capping barge fully assembled (5/28/13)



Photograph 46: Hydraulic capping activities (5/30/13)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 47: Hydraulic capping activities (5/30/13)




Photograph 48: Cap material on conveyor belt to hopper (5/30/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 49: Settling pan measurement (5/31/13)



Á
Photograph 50: Preparation of walking path area (7/2/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 51: Slurry mixing operations for hydraulic capping (7/3/13)



Photograph 52: Walking path subgrade preparation (7/25/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 53: Hydraulic capping activities (8/22/13)



Photograph 54: Installation of geotextile fabric and armor stone in channel (9/19/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 55: Installation of retaining wall along walking path (9/26/13)



Photograph 56: Installation of large woody debris (10/1/13)



Á

Á

APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 57: Installation of plantings on Shrub-Scrub Island (10/17/13)



Photograph 58: Construction of pad for benches along walking path (10/21/13)



Á

Á

**APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS**

**FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS**

Photograph 59: Paving of the walking path (10/30/13)



Photograph 60: Restored Recreational Area and walking path (10/30/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 61: Paving of the walking path (10/31/13)



Photograph 62: Installation of plantings along the walking path (11/4/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 63: Installed plantings along the walking path (11/4/13)



Photograph 64: Restored private parcels (11/20/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 65: Restored private parcels (11/20/13)



Á
Photograph 66: Restored private parcels (11/20/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 67: Restored Shrub-Scrub Island (11/25/13)



Photograph 68: Restored area near the Fourth Street Outfall (11/25/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 69: Installation of sediment traps (12/2/13)



Photograph 70: Restored gravel lot in southwest corner (12/2/13)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 71: Walking path and large trees along eastern portion of lake (9/4/14)



Photograph 72: Walking path and bank vegetation in northwest portion of lake (9/4/14)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 73: Western portion of Shrub-Scrub Island (9/4/14)



Photograph 74: Eastern portion of Shrub-Scrub Island (9/4/14)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 75: View of plantings along western portion of lake (9/4/14)



Photograph 76: View of plantings along southern portion of lake (9/4/14)



APPENDIX C
REPRESENTATIVE PROJECT PHOTOGRAPHS

FINAL COMPLETION REPORT FOR THE SILVER LAKE AREA REMOVAL ACTION
GENERAL ELECTRIC COMPANY – PITTSFIELD, MASSACHUSETTS

Photograph 77: Restoration of Fourth Street Outfall Channel (10/9/14)



Photograph 78: Restored Fourth Street Outfall Channel (10/15/14)

