

## ProScience Analytical Services, Inc.

## PLM Asbestos Chain of Custody Record

LABORATORY/HEADQUARTERS  
22 Cummings Park, Woburn, MA 01801  
T:781-935-3212 F:781-932-4857

LABORATORY SERVICES  
683 North Mountain Rd., Newington, CT 06111  
T:860-953-1022 F:860-953-1030



Superfund Records Center

SITE: Parsons Paper Mill

BREAK: 2.3

OTHER: 643110  
Turn Around Time Requested

Page 1 of 1

 RUSH Same day  24 Hour  48 Hour  72 Hour  5 Days

Client: MassDEP - Western Regional Office

Address: 436 Dwight Street, Springfield, MA 01103

Project Site &amp; Number: Burned Out Mill: Sergeant &amp; Race Streets, Holyoke

Phone / FAX Number: 413-755-2210/413-784-1149

Contact: Bob Shultz

For Lab Use &gt; Batch Number

Analyzed by/date:

Relinquished by/date:

Bob Shultz 7-10-08

Received by/date:

Kathy Astone 7-11-08 9:40 AM

Samples received:

9 Analyzed:

Faxed, E-mailed, Verbal by/date:

Stop on first positive: Yes

No X

QC by/date:

AP 7/17/08

Lab ID	Field ID Sampled date	Description / Location	Analyzed by/date:												Asbestos Percentage (%)				Non Asbestos Percentage (%)								
			Visual	Optical Properties				RI	Asbestos Percentage (%)				Circle Type	Chrysotile	Amosite	Crocidolite	Tridolite	Anthophyllite	Actinolite	Fiberglass	Mineral Wool	Cellulose	Hair	Synthetic	Other	Non Fibrous	
				Color	Homogeneity	Texture	Friability	Morphology	Extinction	Sign of Elongation	Brilliance	Plauchroism	II	III	Chrysotile	Amosite	Crocidolite	Tridolite	Anthophyllite	Actinolite	Fiberglass	Mineral Wool	Cellulose	Hair	Synthetic	Other	Non Fibrous
	# 6250801S 6/25/2008	Suspect Asbestos Wire in rubble pile./Along Sergeant Street.	0	M	CONF	RF																AB					
	# 6250802S 6/25/2008	Suspect Asbestos Paper in rubble pile./Along Sergeant Street.	0	P	CONF	RF																50					
	# 6250803S 6/25/2008	Suspect Asbestos Paper in rubble pile./Along Sergeant Street.	0	P	CONF	RF																90					
	# 6250804S 6/25/2008	Suspect Asbestos Plaster in rubble pile./Along Sergeant Street.	0	G	G	GW																90					
	# 6250805S 6/25/2008	Suspect Asbestos Roofing in rubble pile./Along Sergeant Street.	0	G	G	GW																68					
	# 6250806S 6/25/2008	Suspect Asbestos Caulking in rubble pile./Along Sergeant Street.	0	G	G	GW																22					
07/17/2008 13:25	7819353212																										

Comments: Please return all samples to MassDEP under Chain of Custody.

Please analyze all layers separately.

For complete information about our services and locations please visit us at [www.proscience.net](http://www.proscience.net) or call the numbers above.

Revised on 08/2006



SEMS DocID

643110

## ProScience Analytical Services, Inc.

## PLM Asbestos Chain of Custody Record

LABORATORY/HEADQUARTERS  
22 Cummings Park, Woburn, MA 01801  
T:781-935-3212 F:781-932-4857

LABORATORY SERVICES  
683 North Mountain Rd., Newington, CT 06111  
T:860-953-1022 F:860-953-1030



RUSH

Turn Around Time Requested

Same day  24 Hour  48 Hour  72 Hour  5 Days

Client: MassDEP - Western Regional Office  
Address: 436 Dwight Street, Springfield, MA 01103  
Project Site & Number: Burned Out Mill: Sergeant & Race Streets, Holyoke  
Phone / FAX Number: 413-755-2210/413-784-1149  
Contact: Bob Shultz

For Lab Use > Batch Number

Analyzed by/date: SB7/10/08

Relinquished by/date: Bob Shultz 7-10-08

Received by/date:

Samples received: Analyzed:

Faxed, E-mailed, Verbal by/date:

No X

Stop on first positive: Yes

QC by/date: AP

Lab ID	Field ID Sampled date	Description / Location	Analyzed by/date: SB7/10/08										No Asbestos Percentage (%)												
			Visual	Optical Properties			RI	Asbestos Percentage (%)			Fiberglass			Mineral Wool	Cellulose	Hair	Synthetic	Other							
	# 6250807S	Suspect Asbestos Roofing in rubble pile./Along Sergeant Street.	SB	7/10/08	SB	7/10/08	SB	II	I	Chrysotile	Amosite	Crocidolite	Tremolite	Anthophyllite	Actinolite	Fiberglass	Mineral Wool	Cellulose	Hair	Synthetic	Other	Non Fibrous	SB	7/10/08	80
	# 6250808S	Suspect Asbestos Tar Coating in rubble pile./Along Sergeant Street.	SB	7/10/08	SB	7/10/08	SB	II	I	Chrysotile	Amosite	Crocidolite	Tremolite	Anthophyllite	Actinolite	Fiberglass	Mineral Wool	Cellulose	Hair	Synthetic	Other	Non Fibrous	SB	7/10/08	10
	#6250809S	Suspect Asbestos Component in rubble pile./Along Sergeant Street.	SB	7/10/08	SB	7/10/08	SB	II	I	Chrysotile	Amosite	Crocidolite	Tremolite	Anthophyllite	Actinolite	Fiberglass	Mineral Wool	Cellulose	Hair	Synthetic	Other	Non Fibrous	SB	7/10/08	30
		INTENTIONALLY LEFT BLANK																							
		INTENTIONALLY LEFT BLANK																							
		INTENTIONALLY LEFT BLANK																							

Comments: Please return all samples to MassDEP under Chain of Custody. Please analyze all layers separately.

For complete information about our services and locations please visit us at [www.proscience.net](http://www.proscience.net) or call the numbers above.

Revised on 08/2005