



**AECOM**  
303 East Wacker Drive, Suite 900  
Chicago, Illinois 60601

312.938.0300 tel  
312.938.1109 fax

November 17, 2010

Mr. Narendra Prasad  
Integrus Business Support, LLC  
Environmental Services Department  
130 East Randolph, 22nd Floor  
Chicago, IL 60601

EPA Region 5 Records Ctr.



381356

**Subject: Radiological Survey of Right-of-Way Utility Excavation  
Permit No 777872308  
Permit Address: 406 East Grand Avenue  
AECOM Project No 60157647**

Dear Mr. Prasad:

Pursuant to conditions specified in the permit found in Attachment A issued by the City of Chicago, radiation monitoring was required to be performed at the above referenced site. AECOM provided the required radiation surveillance on November 1, 2010 for the excavation a single one foot by one foot excavation opening to install corrosion protection materials for the gas main in the vicinity of the permitted address.

Surveying was performed for the asphalt, concrete, and soil removal for the excavations required for the installation of corrosion protection equipment for the gas main. A one foot by one foot area was saw cut into the asphalt and concrete surface, exposing the structural backfill material located below approximately 12 feet south of the North Lot Line of East Grand Avenue and 94 feet east of the East Lot Line of North McClurg Court. Documentation of the excavation location provided by INTREN can be found in Attachment B. After asphalt and concrete were removed, the installation contractor, INTREN, utilized a soil vacuum truck to remove subsurface soils to expose the main due to the minimal area of excavation. AECOM proceeded to monitor the soils in increments of approximately 15-inches to a depth of approximately 4-feet.

The monitoring revealed no indication of soils above the specified clean-up threshold established by the United States Environmental Protection Agency (USEPA) for the Streeterville area of Chicago. The USEPA threshold for Chicago's Streeterville area is 7.1 picocuries per gram (pCi/g total radium (Ra-226 + Ra-228). Gamma radiation count measurements for the project were made using Ludlum Model 2221 survey meter and an unshielded 2 x 2 Nal probe (Model 44-10) with a 20-foot long cord due to the depth of excavations. For the instrument used, the gamma count indicative of the 7.1 pCi/g threshold was 7,567 counts per minute (cpm) unshielded. The field gamma measurements within the excavation and the spoil materials generated during the excavation process did not exceed the respective threshold values previously stated and ranged from a minimum of 1,120 cpm to a maximum of 6,640 cpm. Thus, there was no indication of the presence of radiologically-impacted material and/or an exceedance of the USEPA cleanup threshold of 7.1 pCi/g total radium.


Finally, as part of the permit conditions, this letter has been forwarded to:

Chicago Department of Environment  
Attention: Ms. Rahmat Begum  
30 North LaSalle Street, 25<sup>th</sup> Floor  
Chicago, Illinois 60602

AECOM

Please contact us with any questions you have regarding this letter or the reported results.

Regards,



Bryant K. Williams  
Environmental Scientist



Steven C. Kornder, Ph.D.  
Senior Project Geochemist

cc: Rahmat Begum, Chicago Department of Environment  
Verneta Simon, USEPA

Attachment A Permit  
Attachment B Excavation Location

**Attachment A**

**Permit**



CITY OF CHICAGO DEPARTMENT OF ENVIRONMENT  
FORM NO. DOE.ROW.02

City of Chicago  
Richard M. Daley, Mayor

Department of Environment

Sadbu A. Johnston  
Commissioner

Twenty-fifth Floor  
30 North LaSalle Street  
Chicago, Illinois 60602-2575  
(312) 744-7606 (Voice)  
(312) 744-6451 (FAX)  
(312) 744-3586 (TTY)  
<http://www.cityofchicago.org>

Notice is hereby given that the site you have requested a permit for is recorded with the City of Chicago Department of Environment as potentially having environmental contamination on the site and adjacent right-of-way. This environmental contamination could present a threat to human health and safety in connection with work performed at the site, or in the adjacent right-of-way, if proper safeguards are not employed.

A file containing detailed information regarding the aforementioned environmental contamination is available for review at the Department of Environment at 30 N. LaSalle St., 25th Floor, Chicago, Illinois 60602 during normal business hours (8:30AM -4:30PM, Monday through Friday). Contact (312) 744-7606 for an appointment. This file must be reviewed and the remainder of this form completed before the permit can be issued if the ground is exposed or excavated. Please note that for some locations, additional health and safety procedures may be required by law.

Please complete the following:

I have reviewed and understand the documents, maintained by the Department of Environment, regarding environmental contamination of the site and adjacent right-of-way. Further, I will ensure that all work at the subject site and adjacent right-of-way, and any monitoring required including but not limited to radiation monitoring, will be performed in a manner that is protective of human health and the environment and in compliance with all applicable local, state, and federal laws, rules, and regulations, especially those pertaining to worker safety and waste management. I will ensure that the results of any radiation monitoring and/or surveying conducted shall be provided to the Department of Environment and the United States Environmental Protection Agency within two (2) weeks of their completion. If any elevated levels of radioactive material are detected, I will immediately contact the United States Environmental Protection Agency at (800) 424-8802.

Permit No. 777872308

Date 10/14/10

Site Address  
406-26  
E. Grand Av

Work Location (Describe exact site location and attach map)  
Street  
sidewalk  
parkway

Nature of Work  
Corrosion

Expected Start Date  
ASAP

Applicant Name (print) Maria G. Oliver

Signature Maria G. Oliver Date 10/14/10

Company Peoples Gas

Company Address / Phone No. 130 E. Randolph (312) 240-4692

Check if City Department Work  Department Name \_\_\_\_\_

General / Prime Contractor Sal Balani  
Include subcontractor information if applicable

Address 130 E. Randolph

Phone No. (773) 395-7446

Safety Officer / Phone No. Jake Collins (773) 542-7838

Radiation Contractor / Phone No. (if applicable) Steve Konder (847) 279-2500 *ALERT*

Department of Environment Approval / Date Kalimatunisa Begum 10/15/2010 *W.A. Shaw*



Please return this completed form to the City of Chicago Department of Transportation at 30 N. LaSalle St., Room 1101, Chicago, Illinois 60602 during normal business hours (8:30 AM - 4:30 PM, Monday through Friday).

For DOE Use Only



**Attachment B**

**Excavation Location**

# MAIN MAINTENANCE TICKET

ADDRESS  
**406 E. Grand Ave.**

MAIN LOCATION				LOCATION FROM INTERSECTING STREET					
FEET FROM LL	NSEW OF	NSEW LL	PROD. DIR.	FEET FROM LL	NSEW OF	NSEW LL	DIR.	INTERSECTING STREET	PROD. DIR.

12	S	N		94	E	E	N.	McClurg St	
----	---	---	--	----	---	---	----	------------	--

SIZE	KIND (CIRCLE ONE)	PRESSURE	DEPTH OF MAIN	CONDITION OF MAIN: (CIRCLE ONE)	IF MAIN CONDITION IS POOR, WAS COUPON TAKEN?
12"	<del>C - CAST IRON</del> <del>C - DUCTILE IRON</del> <u>S - STEEL COR PRO</u> <del>P - PLASTIC</del> <del>OTHER</del>	<del>LOW</del> <u>MEDIUM</u> <del>HIGH</del>	3 FT. 5 IN.	<u>GOOD</u> POOR NOT EXPOSED	YES  NO

WORK PERFORMED: (CIRCLE ONE)	ON WHAT? (CIRCLE ONE)	REASON FOR WORK (CIRCLE ONE)
<p style="text-align: center;"><u>JOB CODE</u></p> <p>26 - EXTERNAL SEALANT ..... (MILLER) 206            33 - INJECTED SEALANT ..... (PERMABOND) 436            18 - B-BOX/BASIN MAINTENANCE ..... 348            19 - TEST HOLE ..... 248            60 - MAIN REPLACEMENT (Kind for Kind) ..... 260            99 - OTHER ..... 265</p> <p style="text-align: center;"><u>MANUF. CD.</u></p> <p>3 - BAND CLAMP ..... 51-DRESSER 406            ..... 53-SMITH BLAIR</p> <p><u>CORROSION WORK</u></p> <p>51 - INSTALL TEST LEAD &amp; ANODE ..... 951            52 - INSTALL ANODE ..... <u>952</u>            54 - B-BOX MAINTENANCE ..... 954            56 - CLEAR SHORT ..... 956            59 - INSULATE/REINSULATE ..... 959            67 - OTHER CORROSION WORK ..... 967</p>	<p>35 - BELL JOINT            15 - MECHANICAL JOINT            6 - COMPRESSION COUPLING            13 - BROKEN MAIN            14 - CRACK AT TAP            31 - CORROSION HOLE IN MAIN            20 - VALVE            9 - DRIP/SYPHON  <u>99 - OTHER</u></p>	<p>1 - LEAK            3 - PUBLIC IMPROVEMENT  <u>4 - CATHODIC PROTECTION</u>            6 - THIRD PARTY DAMAGE            5 - OTHER</p>

PRESSURE TEST INFO (REQUIRED for all installed piping)									
INSTALLED PRE-TESTED PIPE: YES NO									
PRE-TESTED PIPE CONTROL NO:	<table border="1" style="width: 100%; text-align: center;"> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> </table>								
PRESSURE TEST: YES NO	PSI: _____ MINUTES: _____								

RESTORATION SIZE	OPENING DESCRIPTION
1 FT. X 1 FT.	<input checked="" type="checkbox"/> STREET <input type="checkbox"/> ALLEY <input type="checkbox"/> PKWY <input type="checkbox"/> WALK <input type="checkbox"/> INS-LL <input checked="" type="checkbox"/> ASPH <input type="checkbox"/> LAWN <input type="checkbox"/> CONC <input type="checkbox"/> DIRT
_____ FT. X _____ FT.	<input type="checkbox"/> STREET <input type="checkbox"/> ALLEY <input type="checkbox"/> PKWY <input type="checkbox"/> WALK <input type="checkbox"/> INS-LL <input type="checkbox"/> ASPH <input type="checkbox"/> LAWN <input type="checkbox"/> CONC <input type="checkbox"/> DIRT

DESCRIPTION OF WORK OR REMARKS

---



---



---



---



---

CREW REPORT		
PREPARED BY	EMPLOYEE NUMBER	DATE
J. Butler	J. Butler	11-1-2010