



Aerial photo (1984) shows historic site layout. Multiple former waste management units (WMUs) included landfills, spreading areas, pits, ponds, and trenches used for hazardous waste disposal.

Aerial photo showing site following capping of four of the five landfills in 2002 and reconsolidation of former waste management units (WMUs)





RCRA Canyon, looking south toward Pond A-5 and A-Series Pond .

Installation of RCRA cap on metals landfill as part of early action work in 2002. Caustics/Cyanide Landfill appears in background.



