APPENDIX D. COPY OF VISUAL INSPECTION LOGBOOK

08.01.19 Slip 4 Long Term Monitoring M. Yarnes
Year 7

0820 Arrive @ Slip 4
WW visual inspection team:
Mike Yarnes, Abby Hawley, Jenna Rheuben
Weather: overcast morning, becoming mostly sunny by 0930. Mid 70's to low 80's. -3.15 ft. MLLW @ 1141

0825 Health & safety meeting
- slips, trips, falls
- sediment exposure
- PPE and sun exposure

0830 Began visual inspection and filling out forms (Abby Hawley and Mike Yarnes) Jenna Rheuben began taking photos from marked locations and conducting photo marker maintenance/replacement where applicable. Took photo of cap sign near entrance; in good condition. Fallen tree partially blocking sign, may need to be removed.

Rite in the Rain

8.1.19 Slip 4 LTM YR 7 M. Yarnes

0838 Survey SE slope cap
0905 Survey SE sediment cap
0926 Survey East Sediment cap
0954 Survey North sediment cap
1006 Survey North slough
1021 Survey West sediment cap
1036 Survey Central sediment cap
1045 Survey South slough
1053 Survey Central Slough
1110 Survey NW Sediment cap
1125 Survey NW slope cap
1140 Survey NW beach
1152 Survey North slope/outfalls
1201 Survey East-Central sediment cap
1213 Survey South sediment cap
1225 Took short lunch break
1250 Survey East slope cap
1305 Survey NE slope cap
1312 Survey NE beach
1320 Cleanup supplies and boots
1330 Depart from Slip 4; completed visual monitoring effort.

Mike Yarnes

8.1.19

8.5.19 SLIP 4 LTM YR 7 J. Rheuben

1429 ARRIVE @ SLIP 4
1435 ARRIVE @ PHOTO POINT H
↳ TAKE ADDITIONAL PHOTO OF NE POCKET BEACH.

1440 DEPART SLIP 4

JR 8.5.2019

Rite in the Rain